

Essex County Resource Recovery Facility

MAJOR CONSTRUCTION PROJECTS SINCE 1993

American Ref-Fuel Carbon Silo/Auxiliary Building

POST CONSTRUCTION ASSESSMENTS

LEGEND:

Code	Code Required Assessments
Non-Code	PA Assessments that are not required by code
NYC Only	Façade Assessments required by code in NYC only
NJ Only	Assessments required by code in New Jersey only

VERTICAL TRANSPORTATION, BOILER & REFRIGERATION INVENTORY

Elevators		Escalators		Moving Walks		Boilers		Refrigeration Systems	
PA	Tenant	PA	Tenant	PA	Tenant	PA	Tenant	PA	Tenant
	2						1		

FACILITY CONDITION SURVEY PROGRAM INVENTORY

BUILDINGS	BRIDGES			TUNNELS		PIERS & WHARVES	SIGN & LIGHT STRUCTURES	LIGHT/CATENARY POLES
	VEHICULAR	PEDESTRIAN	LIGHT RAIL SYSTEM	RAIL	VEHICULAR			
14Total								

Façade

4

Structural Integrity other than Façade

14

FAÇADE ASSESSMENT SCHEDULE

BUILDING NAME	HEIGHT (Ft.)	LAST FAÇADE ASSESSMENT	NEXT FAÇADE ASSESSMENT
Refuse Bunker	115	2012	2017
Boiler Building	165	2012	2017
Turbine Bldg	80	2012	2017
Stack	279	2012	2017

MANDATED INSPECTIONS

FACILITY	DESCRIPTION	ACTION TAKEN	YEAR COMPLETED
		None required	