

## Outerbridge Crossing (OBX)

### MAJOR CONSTRUCTION PROJECTS SINCE 1993

No Significant Projects

### POST CONSTRUCTION ASSESSMENTS

<b>LEGEND:</b>	
<b>Code</b>	Code Required Assessments
<b>Non-Code</b>	PA Assessments that are not required by code
<b>NYC Only</b>	Façade Assessments required by code in NYC only
<b>NJ Only</b>	Assessments required by code in New Jersey only

### VERTICAL TRANSPORTATION, BOILER & REFRIGERATION INVENTORY

Elevators		Escalators		Moving Walks		Boilers		Refrigeration Systems	
PA	Tenant	PA	Tenant	PA	Tenant	PA	Tenant	PA	Tenant
						3			

### FACILITY CONDITION SURVEY PROGRAM INVENTORY

BUILDINGS	BRIDGES				TUNNELS		PIERS & WHARVES	SIGN & LIGHT STRUCTURES	LIGHT/CATENARY POLES
	VEHICULAR	PEDESTRIAN	LIGHT RAIL SYSTEM	RAIL	VEHICULAR	RAIL			
2	1.76 mi. 501,634 s.f.							35	109
<b>FAÇADE</b>									
0									
<b>Structural items other than Façade</b>									
2									

### FAÇADE ASSESSMENT SCHEDULE

BUILDING NAME	HEIGHT (Ft.)	LAST FAÇADE ASSESSMENT	NEXT FAÇADE ASSESSMENT
No buildings over 72 feet			

### MANDATED INSPECTIONS

FACILITY	DESCRIPTION	ACTION TAKEN	YEAR COMPLETED
OBX	Deteriorated stringer S2 & stringer S9 bearing	Repaired stringers	2006
OBX	Deteriorated support channel of catwalk	Repaired deteriorated support channel	2007
OBX	NY Approach - Deteriorated Concrete	deteriorated concrete was removed	2010
OBX	Maintenance catwalk at underside of main span at PP L16 - Deteriorated west support Channel	Close the deteriorated section of the catwalk till repairs are completed. Repair deteriorated section	2012
OBX	NY APP- Structure BIN 552306A - Deteriorated Concrete at underside of deck between Piers 2E & 3E	Remove the Cracked and delaminated concrete	2013

OBX	NY Approach - Structure Bin 552306A -Deteriorated Concrete at underside of deck between Piers 2E & 3E	Repair the Deteriorated Deck Slab	2013
-----	--	--------------------------------------	------