

Bathgate Industrial Park

MAJOR CONSTRUCTION PROJECTS SINCE 1993

Clay Park Labs: New Entrances, Offices and Storage

NYC School Construction Authority: Convert Existing Building to a High School

POST CONSTRUCTION ASSESSMENTS

LEGEND:	
Code	Code Required Assessments
Non-Code	PA Assessments that are not required by code
NYC Only	Façade Assessments required by code in NYC only
NJ Only	Assessments required by code in New Jersey only

VERTICAL TRANSPORTATION, BOILER & REFRIGERATION INVENTORY

Elevators		Escalators		Moving Walks		Boilers		Refrigeration
PA	Tenant	PA	Tenant	PA	Tenant	PA	Tenant	PA
	8						3	

FACILITY CONDITION SURVEY PROGRAM INVENTORY

BUILDINGS	BRIDGES				TUNNELS		PIERS & WHARVES	SIGN & LIGHT STRUCTURES
	VEHICULAR	PEDESTRIAN	LIGHT RAIL SYSTEM	RAIL	VEHICULAR	RAIL		
8 TOTAL								
FAÇADE								
0								
Structural Items other than Façade								
9								

FAÇADE ASSESSMENT SCHEDULE

BUILDING NAME	HEIGHT (Ft.)	LAST FAÇADE ASSESSMENT	NEXT FAÇADE ASSESSMENT
No buildings over 72 feet			

MANDATED INSPECTIONS

FACILITY	DESCRIPTION	ACTION TAKEN	YEAR COMPLETED
None required			
BIP	BLDG 2920 - First Floor Lounge - Ceiling Collapse	replace the missing ceiling tiles and the missing section of the main runner to be replaced in-kind on a routine basis	2012



tion Systems
Tenant

LIGHT/CATENARY POLES

