

**THE PORT AUTHORITY OF NEW YORK AND NEW JERSEY  
TWO MONTGOMERY STREET - 1st FLOOR  
JERSEY CITY, NJ 07302**

July 11, 2017

**ADDENDUM NO. 1**

TO PROSPECTIVE BIDDERS ON CONTRACT **LGA-124.251** – LAGUARDIA AIRPORT –  
REHABILITATION OF RUNWAY DECK STRUCTURAL ELEMENTS 3

The following changes are hereby made in the Contract Documents for the subject Contract.

This communication should be physically annexed to back cover of the book and initialled by each bidder before submitting his bid.

In case any bidder fails to conform to these instructions, his Proposal will nevertheless be construed as though this communication had been so physically annexed and initialled.

CHANGES IN THE CONTRACT BOOKLET

- Page 9 - In C. of the clause entitled "DISADVANTAGED BUSINESS ENTERPRISES PROGRAM (DBE)", delete "<http://www.njucp.net/>" and substitute therefor "<https://njucp.dbesystem.com>".
- Page 44 - Delete this entire page and physically attach in its place new page 44, which is attached hereto and made a part hereof.
- Page 46 - In the third line of the fourteenth paragraph of the clause entitled "UNIT PRICES" (beginning "In the case of Item No. 9"), delete "S0412 and S0413" and substitute therefor "S0417, S0418 and S0419".

**THE PORT AUTHORITY OF NEW YORK AND NEW JERSEY**

James Starace, P.E.  
Chief Engineer/Director

INITIALLED BY THE BIDDER:

---

I. SCHEDULE OF UNIT PRICES				
Item No.	Estimated Quantities	Items of Classified Work With Unit Prices Written	Figures	
			Unit Prices	Amounts <sup>20</sup>
8	1 EA.	PILE CAP FULL REPAIR - TYPE A, PER EACH.  _____ DOLLARS _____ CENTS		
9	1 EA.	END ANCHOR ENCASEMENT FULL REPAIR, PER EACH.  _____ DOLLARS _____ CENTS		
10	1 EA.	PILE CAP FULL REPAIR - TYPE C, PER EACH.  _____ DOLLARS _____ CENTS		
11	150 S.F.	PILE CAP SPALL REPAIRS, PER SQUARE FOOT.  _____ DOLLARS _____ CENTS		
12	220 L.F.	PILE CAP CRACK REPAIR, PER LINEAR FOOT.  _____ DOLLARS _____ CENTS		
13	340 L.F.	PRESTRESSED GIRDER CRACK REPAIR, PER LINEAR FOOT.  _____ DOLLARS _____ CENTS		
14	60 S.F.	PRESTRESSED GIRDER TYPES I OR III REPAIR - SPALL REPAIR, PER SQUARE FOOT.  _____ DOLLARS _____ CENTS		
15	9 EA.	PRESTRESSED GIRDER TYPE II REPAIR - STEEL JACKET, PER EACH.  _____ DOLLARS _____ CENTS		