

**NYNJ Rail**

**MAJOR CONSTRUCTION PROJECTS SINCE 1993**

None

**POST CONSTRUCTION ASSESSMENTS**

|                 |   |
|-----------------|---|
| <b>LEGEND:</b>  |   |
| <b>Code</b>     | Code Required Assessments                       |
| <b>Non-Code</b> | PA Assessments that are not required by code    |
| <b>NYC Only</b> | Façade Assessments required by code in NYC only |
| <b>NJ Only</b>  | Assessments required by code in New Jersey only |

**VERTICAL TRANSPORTATION, BOILER & REFRIGERATION INVENTORY (NOT APPLICABLE)**

| Elevators |        | Escalators |        | Moving Walks |        | Boilers |        | Refrigeration Systems |        |
|-----------|--------|------------|--------|--------------|--------|---------|--------|-----------------------|--------|
| PA        | Tenant | PA         | Tenant | PA           | Tenant | PA      | Tenant | PA                    | Tenant |
|           |        |            |        |              |        |         |        |                       |        |

**FACILITY CONDITION SURVEY PROGRAM INVENTORY**

| BUILDINGS                                 | BRIDGES   |            |                   |                       | TUNNELS   |      | PIERS & WHARVES | SIGN & LIGHT STRUCTURES | LIGHT/CATENARY POLES |
|---|-----------|------------|-------------------|-----------------------|-----------|------|-----------------|-------------------------|----------------------|
|   | VEHICULAR | PEDESTRIAN | LIGHT RAIL SYSTEM | RAIL TRANSFER BRIDGES | VEHICULAR | RAIL |                 |                         |                      |
|   |           |            |                   | 2                     |           |      |                 |                         |                      |
| <b>Façade</b>                             |           |            |                   |                       |           |      |                 |                         |                      |
| <b>Structural Items other than Façade</b> |           |            |                   |                       |           |      |                 |                         |                      |
|   | 3         |            |                   |                       |           |      |                 |                         |                      |

**FAÇADE ASSESSMENT SCHEDULE (NOT APPLICABLE)**

| BUILDING NAME | HEIGHT (Ft.) | LAST FAÇADE ASSESSMENT | NEXT FAÇADE ASSESSMENT |
|---------------|--------------|------------------------|------------------------|
|               |              |                        |                        |
|               |              |                        |                        |

**MANDATED INSPECTIONS**

| FACILITY  | DESCRIPTION   | ACTION TAKEN  | YEAR COMPLETED |
|-----------|---|---|----------------|
| NYNJ RAIL | Greenville Yard Float Bridge No. 11- south Fender Rack - Collision Damage   | Install new Walkway, install continuous fender wall   | 2011           |
| NYNJR     | 65th St Rail Yard - North Transfer Bridge - Deteriorated Stringer Bearings. | Repair the north and south bearing assemblies   | 2012           |
| NYNJR     | 65th Float Bridge   | South Ramp currently not in use has offset bearing and downed utility pole w/o effect on operations. Facility to determine action | 2012           |
| NYNJR     | 65Th street bridge - North Bridge - Missing Timber Guide                    | Install new timber guide  | 2013           |