
# 1979 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1979 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 21
Volume 1, Sheet 22
Volume 1, Sheet 5
Volume 1, Sheet 6

0 Feet 165 330 660

N

# 1977 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1977 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 1, Sheet 5
Volume 1, Sheet 6
Volume 1, Sheet 21
Volume 1, Sheet 22
Volume 1, Sheet 30

N

# 1969 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1969 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 1, Sheet 5
Volume 1, Sheet 6
Volume 1, Sheet 21
Volume 1, Sheet 22

0 Feet 165 330 660

N

# 1950 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1950 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 1, Sheet 5
Volume 1, Sheet 6
Volume 1, Sheet 21
Volume 1, Sheet 22

0 Feet 165 330 660

N

# 1938 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1938 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 1, Sheet 21
Volume 1, Sheet 22
Volume 1, Sheet 5
Volume 1, Sheet 6

0 Feet 165 330 660

N

# 1928 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

Site Name: Red Hook
Address: Red Hook
City, ST, ZIP: Brooklyn NY 11231
Client: STV Inc.
EDR Inquiry: 3929425.12
Order Date: 5/5/2014 1:22:01 PM
Certification # 456F-444C-84F6
Copyright: 1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 46

N

# 1922 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

Site Name: Red Hook
Address: Red Hook
City, ST, ZIP: Brooklyn NY 11231
Client: STV Inc.
EDR Inquiry: 3929425.12
Order Date: 5/5/2014 1:22:01 PM
Certification # 456F-444C-84F6
Copyright: 1922

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 38

N

# 1921 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

Site Name: Red Hook
Address: Red Hook
City, ST, ZIP: Brooklyn NY 11231
Client: STV Inc.
EDR Inquiry: 3929425.12
Order Date: 5/5/2014 1:22:01 PM
Certification # 456F-444C-84F6
Copyright: 1921

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume Atlas Maps, Sheet b-3

N

# 1915 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

| | |
|---|---|
| Site Name: | Red Hook |
| Address: | Red Hook |
| City, ST, ZIP: | Brooklyn NY 11231 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.12 |
| Order Date: | 5/5/2014 1:22:01 PM |
| Certification # | 456F-444C-84F6 |
| Copyright: | 1915 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 1, Sheet 5
Volume 1, Sheet 6
Volume 1, Sheet 21
Volume 1, Sheet 22

N

# 1904 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # 456F-444C-84F6

Site Name: Red Hook
Address: Red Hook
City, ST, ZIP: Brooklyn NY 11231
Client: STV Inc.
EDR Inquiry: 3929425.12
Order Date: 5/5/2014 1:22:01 PM
Certification # 456F-444C-84F6
Copyright: 1904

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 1, Sheet 5
Volume 1, Sheet 6
Volume 1, Sheet 21
Volume 1, Sheet 22

N

**Red Hook**
Red Hook
Brooklyn, NY 11231

Inquiry Number: 3929425.11s
May 01, 2014

# The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# TABLE OF CONTENTS


| SECTION | PAGE |
|---|---|
| Executive Summary | ES1 |
| Overview Map | 2 |
| Detail Map | 3 |
| Map Findings Summary | 4 |
| Map Findings | 8 |
| Orphan Summary | 1103 |
| Government Records Searched/Data Currency Tracking | GR-1 |

**GEOCHECK ADDENDUM**

| | |
|---|---|
| Physical Setting Source Addendum | A-1 |
| Physical Setting Source Summary | A-2 |
| Physical Setting Source Map | A-7 |
| Physical Setting Source Map Findings | A-8 |
| Physical Setting Source Records Searched | PSGR-1 |


***Thank you for your business.***
Please contact EDR at 1-800-352-0050
with any questions or comments.


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

## TARGET PROPERTY INFORMATION

### ADDRESS

RED HOOK
BROOKLYN, NY 11231

### COORDINATES

| | |
|---|---|
| Latitude (North): | 40.6886619 - 40° 41' 19.18'' |
| Longitude (West): | 74.0031317 - 74° 0' 11.27'' |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 584234.3 |
| UTM Y (Meters): | 4504463.0 |
| Elevation: | 6 ft. above sea level |

### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

| | |
|---|---|
| Target Property Map: | 40074-F1 JERSEY CITY, NJ NY |
| Most Recent Revision: | 1981 |
| East Map: | 40073-F8 BROOKLYN, NY |
| Most Recent Revision: | 1995 |

### AERIAL PHOTOGRAPHY IN THIS REPORT

| | |
|---|---|
| Portions of Photo from: | 2010, 2011 |
| Source: | USDA |

## TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

## DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

## STANDARD ENVIRONMENTAL RECORDS

### *Federal NPL site list*

NPL---------- National Priority List

# EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

***Federal Delisted NPL site list***

Delisted NPL ---------- National Priority List Deletions

***Federal CERCLIS list***

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

***Federal CERCLIS NFRAP site List***

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

***Federal RCRA CORRACTS facilities list***

CORRACTS ---------- Corrective Action Report

***Federal RCRA non-CORRACTS TSD facilities list***

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

***Federal institutional controls / engineering controls registries***

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

***State- and tribal - equivalent CERCLIS***

NY SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State
NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

***State and tribal landfill and/or solid waste disposal site lists***

NY SWF/LF ---------- Facility Register

***State and tribal leaking storage tank lists***

NY HIST LTANKS ---------- Listing of Leaking Storage Tanks
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

***State and tribal registered storage tank lists***

NY TANKS ---------- Storage Tank Faciliy Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY CBS AST ---------- Chemical Bulk Storage Database
NY MOSF AST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY CBS ---------- Chemical Bulk Storage Site Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

# EXECUTIVE SUMMARY

***State and tribal institutional control / engineering control registries***

NY ENG CONTROLS ..... Registry of Engineering Controls
NY INST CONTROL ..... Registry of Institutional Controls

***State and tribal voluntary cleanup sites***

NY VCP ..... Voluntary Cleanup Agreements
INDIAN VCP ..... Voluntary Cleanup Priority Listing

***State and tribal Brownfields sites***

NY ERP ..... Environmental Restoration Program Listing
NY BROWNFIELDS ..... Brownfields Site List

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS ..... A Listing of Brownfields Sites

***Local Lists of Landfill / Solid Waste Disposal Sites***

ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
NY SWTIRE ..... Registered Waste Tire Storage & Facility List
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands

***Local Lists of Hazardous waste / Contaminated Sites***

US CDL ..... Clandestine Drug Labs
NY DEL SHWS ..... Delisted Registry Sites
US HIST CDL ..... National Clandestine Laboratory Register

***Local Land Records***

LIENS 2 ..... CERCLA Lien Information
NY LIENS ..... Spill Liens Information

***Records of Emergency Release Reports***

NY Hist Spills ..... SPILLS Database
NY SPILLS 80 ..... SPILLS 80 data from FirstSearch

***Other Ascertainable Records***

DOT OPS ..... Incident and Accident Data
DOD ..... Department of Defense Sites
FUDS ..... Formerly Used Defense Sites
CONSENT ..... Superfund (CERCLA) Consent Decrees
ROD ..... Records Of Decision
UMTRA ..... Uranium Mill Tailings Sites
US MINES ..... Mines Master Index File

TRIS ---- Toxic Chemical Release Inventory System
TSCA ---- Toxic Substances Control Act
SSTS ---- Section 7 Tracking Systems
PADS ---- PCB Activity Database System
MLTS ---- Material Licensing Tracking System
RADINFO ---- Radiation Information Database
RAATS ---- RCRA Administrative Action Tracking System
RMP ---- Risk Management Plans
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY UIC ---- Underground Injection Control Wells
NY AIRS ---- Air Emissions Data
INDIAN RESERV ---- Indian Reservations
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
NY Financial Assurance ---- Financial Assurance Information Listing
NY COAL ASH ---- Coal Ash Disposal Site Listing
2020 COR ACTION ---- 2020 Corrective Action Program List
EPA WATCH LIST ---- EPA WATCH LIST
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
US FIN ASSUR ---- Financial Assurance Information
COAL ASH DOE ---- Steam-Electric Plant Operation Data
PRP ---- Potentially Responsible Parties

**EDR HIGH RISK HISTORICAL RECORDS**

***EDR Exclusive Records***

EDR MGP ---- EDR Proprietary Manufactured Gas Plants

**EDR RECOVERED GOVERNMENT ARCHIVES**

***Exclusive Recovered Govt. Archives***

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

**SURROUNDING SITES: SEARCH RESULTS**

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

# EXECUTIVE SUMMARY

**STANDARD ENVIRONMENTAL RECORDS**

***Federal RCRA generators list***

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/11/2014 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| NYMT - BP ASI CONTAINER | 90 COLUMBIA STREET | SSW 0 - 1/8 (0.055 mi.) | V165 | 368 |

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/11/2014 has revealed that there are 6 RCRA-SQG sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***WATCHTOWER*** | ***FURMAN STREET*** | ***NNE 0 - 1/8 (0.109 mi.)*** | ***AK285*** | ***652*** |
| ***BROOKLYN BATTERY TUNNEL*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT349*** | ***771*** |
| ***UNIVERSITY HOSPITAL OF BROOKLY*** | ***340 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***AW388*** | ***879*** |
| ***NYC BD OF ED - PUBLIC SCHOOL 2*** | ***425 HENRY ST*** | ***ESE 1/8 - 1/4 (0.189 mi.)*** | ***BA391*** | ***898*** |
| ***RANDEX CLEANERS*** | ***534 HENRY ST*** | ***SSE 1/8 - 1/4 (0.241 mi.)*** | ***BM485*** | ***1074*** |
| ***TODD SHIPYARDS CORP*** | ***FOOT OF DWIGHT ST*** | ***SSW 1/8 - 1/4 (0.246 mi.)*** | ***BL492*** | ***1097*** |

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/11/2014 has revealed that there are 11 RCRA-CESQG sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON MANHOLE: 73002 | FURMAN ST & ATLANTIC AV | NE 0 - 1/8 (0.008 mi.) | O92 | 246 |
| CON EDISON MANHOLE: 9204 | FURMAN ST & ATLANTIC AV | NE 0 - 1/8 (0.008 mi.) | O93 | 247 |
| RED HOOK CONTAINER TERMINAL | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V169 | 374 |
| ***TECHNIKOTE CORP*** | ***63 SEABRING ST*** | ***SSW 0 - 1/8 (0.109 mi.)*** | ***AL289*** | ***666*** |
| CON EDISON MANHOLE: 61249 | RICHARDS ST & SEABRING | SSW 0 - 1/8 (0.121 mi.) | AC308 | 705 |
| ***CON EDISON MANHOLE: 44577*** | ***15 SEABRING ST*** | ***SSW 1/8 - 1/4 (0.166 mi.)*** | ***AT364*** | ***826*** |
| ***CON EDISON MANHOLE: 9192*** | ***332 FURMAN ST FRONT OF*** | ***NNE 1/8 - 1/4 (0.166 mi.)*** | ***AV367*** | ***830*** |

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON MANHOLE: 1718 | HICKS ST & JORALEMON ST | NE 1/8 - 1/4 (0.204 mi.) | AY430 | 978 |
| GRACE CHURCH | 254 HICKS ST | NE 1/8 - 1/4 (0.220 mi.) | AY458 | 1031 |
| CON EDISON MANHOLE: 43937 | VERONA & RICHARDS ST | SSW 1/8 - 1/4 (0.229 mi.) | BP471 | 1053 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SHOWMAN FABRICATORS*** | ***29 IMLAY ST*** | ***0 - 1/8 (0.000 mi.)*** | ***C14*** | ***41*** |

***Federal ERNS list***

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 09/30/2013 has revealed that there are 7 ERNS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 29-50 ATLANTIC AVE. | NE 0 - 1/8 (0.014 mi.) | O101 | 257 |
| Not reported | 74 UNION STREET | SSW 0 - 1/8 (0.046 mi.) | R139 | 312 |
| Not reported | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V159 | 347 |
| Not reported | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V168 | 374 |
| Not reported | 40 CARROL STREET | S 0 - 1/8 (0.098 mi.) | W247 | 591 |
| Not reported | HENRY ST AND CONGRESS S | E 1/8 - 1/4 (0.189 mi.) | BB395 | 908 |
| Not reported | 112 ATLANTIC AVE. | ENE 1/8 - 1/4 (0.193 mi.) | BC414 | 954 |

***State and tribal leaking storage tank lists***

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/17/2014 has revealed that there are 22 NY LTANKS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| PORT AUTHORITY | 100 COLUMBIA STREET | E 0 - 1/8 (0.005 mi.) | B41 | 101 |
| Spill Number/Closed Date: 9711130 / 10/9/2002 | | | | |
| ***PORT AUTHORITY BROOKLYN PIERS*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B46*** | ***145*** |
| Spill Number/Closed Date: 9203457 / 7/9/1992 | | | | |
| Spill Number/Closed Date: 9204113 / 2/23/1993 | | | | |
| Spill Number/Closed Date: 9509127 / 2/28/2003 | | | | |
| 37 HAMILTON AVE/BKLYN | 37 HAMILTON AVENUE | SSW 0 - 1/8 (0.020 mi.) | G106 | 262 |
| Spill Number/Closed Date: 9012122 / 8/2/1993 | | | | |
| CONTINENTAL WAREHOUSE | 23RD STREET | NE 0 - 1/8 (0.038 mi.) | O134 | 301 |
| Spill Number/Closed Date: 9515551 / 3/4/1996 | | | | |
| ***RED HOOK TERMINAL*** | ***HAMILTON AVE*** | ***SSW 0 - 1/8 (0.054 mi.)*** | ***V153*** | ***337*** |
| Spill Number/Closed Date: 8908683 / 12/2/1989 | | | | |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***AMERICAN STEVEDORING INC*** | ***70 HAMILTON AVE*** | ***SSW 0 - 1/8 (0.055 mi.)*** | ***V164*** | ***354*** |
| Spill Number/Closed Date: 9705748 / 8/12/1997 | | | | |
| LONG ISLAND HOSPITAL | 363 HICKS STREET | ENE 0 - 1/8 (0.104 mi.) | AH272 | 630 |
| Spill Number/Closed Date: 0211399 / 10/17/2003 | | | | |
| Spill Number/Closed Date: 0211398 / 10/23/2006 | | | | |
| LI COLLEGE HOSP TTF | 339 HICKS ST | ENE 0 - 1/8 (0.104 mi.) | AE274 | 637 |
| Spill Number/Closed Date: 1201982 / Not Reported | | | | |
| ***WATCHTOWER BIBLE*** | ***360 FURMAN STREET*** | ***NNE 0 - 1/8 (0.109 mi.)*** | ***AK287*** | ***663*** |
| Spill Number/Closed Date: 0311887 / 5/17/2004 | | | | |
| PVT DWELLING TTF | 423 HICKS AT | E 0 - 1/8 (0.112 mi.) | AB293 | 678 |
| Spill Number/Closed Date: 1003165 / 1/12/2011 | | | | |
| ***MOBIL OIL CORP SS #EMW*** | ***304 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.140 mi.)*** | ***AO326*** | ***731*** |
| Spill Number/Closed Date: 9312498 / 5/14/2003 | | | | |
| ***TRIBOROUGH BRIDGE & TUNNEL AUT*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT352*** | ***790*** |
| Spill Number/Closed Date: 9201988 / 11/17/2003 | | | | |
| Spill Number/Closed Date: 8912103 / 10/7/1992 | | | | |
| BALL RESIDENCE | 80 CARROLL STREET | S 1/8 - 1/4 (0.166 mi.) | AP368 | 831 |
| Spill Number/Closed Date: 0311649 / 3/8/2004 | | | | |
| ***76 PRECINCT NYPD -DDC*** | ***191 UNION STREET*** | ***SSE 1/8 - 1/4 (0.191 mi.)*** | ***AU405*** | ***925*** |
| Spill Number/Closed Date: 9710102 / 5/2/2001 | | | | |
| Spill Number/Closed Date: 9710091 / 10/31/2003 | | | | |
| ***SHELL GAS*** | ***112 ATLANTIC AVE*** | ***ENE 1/8 - 1/4 (0.193 mi.)*** | ***BC410*** | ***942*** |
| Spill Number/Closed Date: 0400263 / 3/10/2005 | | | | |
| 43 GARDEN PL | 43 GARDEN PL | NE 1/8 - 1/4 (0.194 mi.) | AY416 | 961 |
| Spill Number/Closed Date: 9108876 / 11/18/1994 | | | | |
| 36 GARDEN PLACE | 36 GARDEN PLACE | NE 1/8 - 1/4 (0.198 mi.) | AY421 | 968 |
| Spill Number/Closed Date: 9504733 / 7/19/1995 | | | | |
| APARTMENT BLDG | 262 HICKS ST | NE 1/8 - 1/4 (0.200 mi.) | AY423 | 970 |
| Spill Number/Closed Date: 9614314 / 12/31/1997 | | | | |
| X | 50 GRACE COURT | NE 1/8 - 1/4 (0.217 mi.) | BN451 | 1022 |
| Spill Number/Closed Date: 0210381 / 11/21/2005 | | | | |
| WAREHOUSE | 80 RICHARDS STREET | SSW 1/8 - 1/4 (0.218 mi.) | BE452 | 1023 |
| Spill Number/Closed Date: 0310837 / 2/13/2004 | | | | |
| SACRED HEARTS | 56 STRONG PLACE | SE 1/8 - 1/4 (0.238 mi.) | 484 | 1072 |
| Spill Number/Closed Date: 9514544 / 3/25/1996 | | | | |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| RED HOOK TERMINAL | BIRTH 9A NORTH | 0 - 1/8 (0.000 mi.) | 1 | 8 |
| Spill Number/Closed Date: 9709712 / 3/4/2003 | | | | |

# EXECUTIVE SUMMARY

***State and tribal registered storage tank lists***

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 12/30/2013 has revealed that there are 27 NY UST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***DSNY BK DISTRICT 6A GARAGE*** | ***93 VAN BRUNT STREET*** | ***0 - 1/8 (0.000 mi.)*** | ***E22*** | ***51*** |
| ***NEW YORK MARINE TERMINALS / BK*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B42*** | ***102*** |
| RED HOOK CONTAINER TERMINAL | 70 HAMILTON AVENUE | SSW 0 - 1/8 (0.055 mi.) | V161 | 348 |
| ***LAB DELIVERY SERVICE INC*** | ***3644 SEABRING STREET*** | ***SSW 0 - 1/8 (0.070 mi.)*** | ***U201*** | ***459*** |
| 33 CARROLL ST | 33 CARROLL STREET | SSW 0 - 1/8 (0.072 mi.) | W203 | 471 |
| ***ABM SERVICE STATION, INC.*** | ***434 HICKS STREET*** | ***ESE 0 - 1/8 (0.081 mi.)*** | ***Y216*** | ***511*** |
| ***COLUMBIA HICKS SITE 3*** | ***414 HICKS STREET*** | ***E 0 - 1/8 (0.081 mi.)*** | ***AB220*** | ***539*** |
| ***UNIVERSITY HOSPITAL OF BROOKLY*** | ***70 ATLANTIC AVENUE*** | ***NE 0 - 1/8 (0.090 mi.)*** | ***AE236*** | ***567*** |
| UNIV. HOSPITAL OF BROOKLYN | 363 HICKS STREET | ENE 0 - 1/8 (0.104 mi.) | AH273 | 633 |
| ***PRISCILLA GOLD SEAL CORP INC*** | ***65 COMMERCE STREET*** | ***SSW 0 - 1/8 (0.119 mi.)*** | ***AC303*** | ***697*** |
| ***F.D.N.Y. ENG.CO. 202*** | ***31 RICHARDS STREET*** | ***SSW 0 - 1/8 (0.121 mi.)*** | ***AC309*** | ***706*** |
| MOBIL S/S 17-EMW | 304 COLUMBIA ST | S 1/8 - 1/4 (0.140 mi.) | AO325 | 725 |
| HUGH L. CAREY TUNNEL SERVICE B | 160 HAMILTON AVENUE | S 1/8 - 1/4 (0.156 mi.) | AT351 | 784 |
| ***24-32 JORALEMON STREET*** | ***A/K/A 10-20-30 COLUMBIA*** | ***NNE 1/8 - 1/4 (0.158 mi.)*** | ***AK357*** | ***815*** |
| RIVERSIDE BUILDINGS | 30 JORALEMON ST | NE 1/8 - 1/4 (0.162 mi.) | AQ363 | 824 |
| LONG ISLAND COLLEGE HOSPITAL D | 94 AMITY STREET | ENE 1/8 - 1/4 (0.167 mi.) | AW370 | 834 |
| 11 SEABRING STREET | 11 SEABRING STREET | SSW 1/8 - 1/4 (0.175 mi.) | AT376 | 842 |
| ***327 HENRY ST*** | ***327 HENRY ST*** | ***ENE 1/8 - 1/4 (0.190 mi.)*** | ***BC404*** | ***922*** |
| 76 PCT | 191 UNION STREET | SSE 1/8 - 1/4 (0.191 mi.) | AU406 | 933 |
| 112 ATLANTIC AVENUE LLC | 112 ATLANTIC AVENUE | ENE 1/8 - 1/4 (0.193 mi.) | BC415 | 954 |
| ***NICOBROS INC DBA J&E SERVICE*** | ***640 HICKS STREET*** | ***S 1/8 - 1/4 (0.211 mi.)*** | ***BI437*** | ***984*** |
| ***GRACE CHURCH*** | ***50 GRACE COURT*** | ***NE 1/8 - 1/4 (0.217 mi.)*** | ***BN450*** | ***1018*** |
| ***GRACE COURT OWNERS CORP.*** | ***45 GRACE COURT*** | ***NE 1/8 - 1/4 (0.218 mi.)*** | ***BJ454*** | ***1025*** |
| ***GRACE EPISCOPAL CHURCH*** | ***254 HICKS STREET*** | ***NE 1/8 - 1/4 (0.220 mi.)*** | ***AY459*** | ***1032*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SCHOENBERG SALT CO.*** | ***87 BOWNE STREET*** | ***SSW 0 - 1/8 (0.004 mi.)*** | ***H34*** | ***85*** |
| ***62 IMLAY ST. ESTATE, LLC*** | ***62/114 IMLAY STREET*** | ***SSW 0 - 1/8 (0.007 mi.)*** | ***H89*** | ***242*** |
| AMERICAN QUICK START | 225 VAN BRUNT STREET | SSW 1/8 - 1/4 (0.150 mi.) | AR335 | 752 |

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 12/30/2013 has revealed that there are 35 NY AST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***RED HOOK CONTAINER TERMINAL*** | ***FOOT OF HAMILTON AVENUE*** | ***0 - 1/8 (0.000 mi.)*** | ***10*** | ***20*** |
| ***DSNY BK DISTRICT 6A GARAGE*** | ***93 VAN BRUNT STREET*** | ***0 - 1/8 (0.000 mi.)*** | ***E22*** | ***51*** |
| COACH BUS REPAIR, INC. | 170 VAN BRUNT STREET | SSW 0 - 1/8 (0.004 mi.) | I37 | 96 |
| ***NEW YORK MARINE TERMINALS / BK*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B42*** | ***102*** |
| 129 DEGRAW ST | 129 DEGRAW STREET | SSE 0 - 1/8 (0.036 mi.) | M131 | 297 |
| JP MORGAN CHASE AND COMPANY | 79 HAMILTON AVENUE | SSW 0 - 1/8 (0.037 mi.) | Q133 | 299 |
| TIFFANY MEWS | 63 TIFFANY PLACE | SE 0 - 1/8 (0.054 mi.) | J155 | 340 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***TIFFANY MEWS LIMITED PARTNERSH*** | ***37 TIFFANY PLACE*** | ***SE 0 - 1/8 (0.054 mi.)*** | ***T157*** | ***343*** |
| 25 CARROLL ST | 25 CARROLL STREET | SSW 0 - 1/8 (0.056 mi.) | W172 | 377 |
| 96-98 BALTIC ST., LLC | 96 BALTIC STREET | ESE 0 - 1/8 (0.066 mi.) | Y195 | 441 |
| ***LAB DELIVERY SERVICE INC*** | ***3644 SEABRING STREET*** | ***SSW 0 - 1/8 (0.070 mi.)*** | ***U201*** | ***459*** |
| ***COLUMBIA HICKS SITE 3*** | ***414 HICKS STREET*** | ***E 0 - 1/8 (0.081 mi.)*** | ***AB220*** | ***539*** |
| ROBSON SALES CORP | 120 HAMILTON AVENUE | SSW 0 - 1/8 (0.090 mi.) | V233 | 563 |
| ***UNIVERSITY HOSPITAL OF BROOKLY*** | ***70 ATLANTIC AVENUE*** | ***NE 0 - 1/8 (0.090 mi.)*** | ***AE236*** | ***567*** |
| COBBLE HILL TOWERS ASSOC | 439 HICKS ST | ESE 0 - 1/8 (0.103 mi.) | Y260 | 614 |
| COBBLE HILL TOWERS CONDOMINIUM | 423 HICKS ST | E 0 - 1/8 (0.103 mi.) | AB262 | 617 |
| AUTO TECH REPAIR CENTER | 113 HAMILTON AVENUE | SSW 0 - 1/8 (0.105 mi.) | AD279 | 645 |
| ***F.D.N.Y. ENG.CO. 202*** | ***31 RICHARDS STREET*** | ***SSW 0 - 1/8 (0.121 mi.)*** | ***AC309*** | ***706*** |
| ***WILLOWTOWN APARTMENTS INC*** | ***32 WILLOW PLACE*** | ***NE 1/8 - 1/4 (0.144 mi.)*** | ***AQ329*** | ***744*** |
| ONE BROOKLYN BRIDGE PARK CONDO | 360 FURMAN STREET | NNE 1/8 - 1/4 (0.156 mi.) | AK346 | 763 |
| HUGH L. CAREY TUNNEL SERVICE B | 160 HAMILTON AVENUE | S 1/8 - 1/4 (0.156 mi.) | AT348 | 768 |
| UNIV HOSPITAL OF BROOKLYN | 97 AMITY ST | ENE 1/8 - 1/4 (0.168 mi.) | AW371 | 836 |
| ENGINE COMPANY 224 | 274 HICKS STREET | NE 1/8 - 1/4 (0.178 mi.) | AY379 | 867 |
| PUBLIC SCHOOL 29 - BROOKLYN | 425 HENRY STREET | ESE 1/8 - 1/4 (0.189 mi.) | BA389 | 895 |
| ***294 HENRY ST INC*** | ***316 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***BC396*** | ***909*** |
| ***COBBLE HILL NURSING HOME INC*** | ***380 HENRY ST*** | ***E 1/8 - 1/4 (0.189 mi.)*** | ***BB397*** | ***912*** |
| 112 ATLANTIC AVENUE LLC | 112 ATLANTIC AVENUE | ENE 1/8 - 1/4 (0.193 mi.) | BC412 | 952 |
| 2 GRACE OWNERS INC. | 2 GRACE COURT | NNE 1/8 - 1/4 (0.212 mi.) | BJ440 | 999 |
| IDEA NUIVA | 80 RICHARDS STREET | SSW 1/8 - 1/4 (0.215 mi.) | BE444 | 1009 |
| ***GRACE COURT OWNERS CORP.*** | ***45 GRACE COURT*** | ***NE 1/8 - 1/4 (0.218 mi.)*** | ***BJ454*** | ***1025*** |
| 19 GRACE OWNERS CORP. | 19 GRACE COURT | NNE 1/8 - 1/4 (0.224 mi.) | BJ466 | 1048 |
| 269 HENRY STREET | 269 HENRY STREET | ENE 1/8 - 1/4 (0.233 mi.) | BK479 | 1063 |
| ***BEGAY REALTY CO*** | ***99 JORALEMON ST*** | ***NE 1/8 - 1/4 (0.237 mi.)*** | ***481*** | ***1067*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SCHOENBERG SALT CO.*** | ***87 BOWNE STREET*** | ***SSW 0 - 1/8 (0.004 mi.)*** | ***H34*** | ***85*** |
| ***COMMERCIAL BUILDING*** | ***116/164 IMLAY STREET*** | ***SW 1/8 - 1/4 (0.143 mi.)*** | ***AF327*** | ***740*** |

***State and tribal institutional control / engineering control registries***

NY RES DECL: A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

A review of the NY RES DECL list, as provided by EDR, and dated 03/13/2014 has revealed that there are 8 NY RES DECL sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***LOT 1,TAXBLOCK 299*** | ***75 COLUMBIA STREET*** | ***ENE 0 - 1/8 (0.007 mi.)*** | ***B85*** | ***235*** |
| ***LOT 16,TAXBLOCK 299*** | ***86 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.056 mi.)*** | ***X173*** | ***379*** |
| ***LOT 18,TAXBLOCK 299*** | ***90 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.064 mi.)*** | ***X188*** | ***424*** |
| ***LOT 39,TAXBLOCK 299*** | ***79 WARREN STREET*** | ***E 0 - 1/8 (0.065 mi.)*** | ***X194*** | ***438*** |
| ***LOT 16,TAXBLOCK 304*** | ***108 WARREN STREET*** | ***E 0 - 1/8 (0.073 mi.)*** | ***X205*** | ***474*** |
| ***LOT 50,TAXBLOCK 347*** | ***29 CARROLL STREET*** | ***S 0 - 1/8 (0.074 mi.)*** | ***W207*** | ***482*** |
| ***LOT 17,TAXBLOCK 304*** | ***110 WARREN STREET*** | ***E 0 - 1/8 (0.075 mi.)*** | ***Y208*** | ***488*** |
| ***LOT 19,TAXBLOCK 299*** | ***96 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.076 mi.)*** | ***X211*** | ***502*** |

# EXECUTIVE SUMMARY

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Lists of Landfill / Solid Waste Disposal Sites***

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 12/12/2013 has revealed that there is 1 NY SWRCY site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET | 0 - 1/8 (0.000 mi.) | E20 | 50 |

***Local Lists of Registered Storage Tanks***

NY HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 12 NY HIST UST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***BROOKLYN WEST A*** | ***93 VAN BRUNT STREET*** | ***0 - 1/8 (0.000 mi.)*** | ***E25*** | ***71*** |
| ***NEW YORK MARINE TERMINALS / BK*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B42*** | ***102*** |
| CHASE BANK | 79 HAMILTON AVE | SSW 0 - 1/8 (0.037 mi.) | Q132 | 298 |
| ***LAB DELIVERY SERVICE INC*** | ***3644 SEABRING STREET*** | ***SSW 0 - 1/8 (0.070 mi.)*** | ***U201*** | ***459*** |
| ***ABM SERVICE STATION, INC.*** | ***434 HICKS STREET*** | ***ESE 0 - 1/8 (0.081 mi.)*** | ***Y216*** | ***511*** |
| ***PRISCILLA GOLD SEAL CORP INC*** | ***65 COMMERCE STREET*** | ***SSW 0 - 1/8 (0.119 mi.)*** | ***AC303*** | ***697*** |
| ***TRIBOROUGH BRIDGE & TUNNEL AUT*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT352*** | ***790*** |
| ***24-32 JORALEMON STREET*** | ***A/K/A 10-20-30 COLUMBIA*** | ***NNE 1/8 - 1/4 (0.158 mi.)*** | ***AK357*** | ***815*** |
| ***GRACE CHURCH*** | ***50 GRACE COURT*** | ***NE 1/8 - 1/4 (0.217 mi.)*** | ***BN450*** | ***1018*** |
| ***GRACE EPISCOPAL CHURCH*** | ***254 HICKS STREET*** | ***NE 1/8 - 1/4 (0.220 mi.)*** | ***AY459*** | ***1032*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SCHOENBERG SALT CO.*** | ***87 BOWNE STREET*** | ***SSW 0 - 1/8 (0.004 mi.)*** | ***H34*** | ***85*** |
| ***62 IMLAY ST. ESTATE, LLC*** | ***62/114 IMLAY STREET*** | ***SSW 0 - 1/8 (0.007 mi.)*** | ***H89*** | ***242*** |

NY HIST AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY HIST AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 15 NY HIST AST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***RED HOOK CONTAINER TERMINAL*** | ***FOOT OF HAMILTON AVENUE*** | ***0 - 1/8 (0.000 mi.)*** | ***10*** | ***20*** |
| ***BROOKLYN WEST A*** | ***93 VAN BRUNT STREET*** | ***0 - 1/8 (0.000 mi.)*** | ***E25*** | ***71*** |
| ***NEW YORK MARINE TERMINALS / BK*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B42*** | ***102*** |
| 129 DEGRAW ST | 129 DE GRAW ST | SSE 0 - 1/8 (0.036 mi.) | M129 | 296 |
| ***TIFFANY MEWS LIMITED PARTNERSH*** | ***37 TIFFANY PLACE*** | ***SE 0 - 1/8 (0.054 mi.)*** | ***T157*** | ***343*** |
| ***LAB DELIVERY SERVICE INC*** | ***3644 SEABRING STREET*** | ***SSW 0 - 1/8 (0.070 mi.)*** | ***U201*** | ***459*** |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ROBSON SALES CORP | 120 HAMILTON AVENUE | SSW 0 - 1/8 (0.090 mi.) | V234 | 566 |
| ***F.D.N.Y. ENG.CO. 202*** | ***31 RICHARDS STREET*** | ***SSW 0 - 1/8 (0.121 mi.)*** | ***AC309*** | ***706*** |
| ***WILLOWTOWN APARTMENTS INC*** | ***32 WILLOW PLACE*** | ***NE 1/8 - 1/4 (0.144 mi.)*** | ***AQ329*** | ***744*** |
| ENGINE COMPANY 224 | 274 HICKS STREET | NE 1/8 - 1/4 (0.178 mi.) | AY380 | 869 |
| ***294 HENRY ST INC*** | ***316 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***BC396*** | ***909*** |
| ***COBBLE HILL NURSING HOME INC*** | ***380 HENRY ST*** | ***E 1/8 - 1/4 (0.189 mi.)*** | ***BB397*** | ***912*** |
| ***BEGAY REALTY CO*** | ***99 JORALEMON ST*** | ***NE 1/8 - 1/4 (0.237 mi.)*** | ***481*** | ***1067*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SCHOENBERG SALT CO.*** | ***87 BOWNE STREET*** | ***SSW 0 - 1/8 (0.004 mi.)*** | ***H34*** | ***85*** |
| ***COMMERCIAL BUILDING*** | ***116/164 IMLAY STREET*** | ***SW 1/8 - 1/4 (0.143 mi.)*** | ***AF327*** | ***740*** |

***Records of Emergency Release Reports***

HMIRS: The Hazardous Materials Incident Report System contains hazardous material spill incidents reported to the Department of Transportation. The source of this database is the U.S. EPA.

A review of the HMIRS list, as provided by EDR, and dated 12/31/2013 has revealed that there is 1 HMIRS site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 336 HICKS STREET | ENE 0 - 1/8 (0.102 mi.) | AE256 | 610 |

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/17/2014 has revealed that there are 152 NY Spills sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| DRUM RUN<br>Spill Number/Closed Date: 1200169 / 4/20/2012 | 90 COLUMBIA ST @ B61 BU | 0 - 1/8 (0.000 mi.) | B4 | 14 |
| REDHOOK TERMINAL<br>Spill Number/Closed Date: 1216849 / Not Reported | 20 IMLAY ST | 0 - 1/8 (0.000 mi.) | C5 | 15 |
| 45-60 UNION STREET<br>Spill Number/Closed Date: 9408241 / 9/21/1994 | 45-60 UNION STREET | 0 - 1/8 (0.000 mi.) | E7 | 17 |
| MANHOLE #44171<br>Spill Number/Closed Date: 0501964 / 7/28/2005 | SACKETT ST/VANBRUNT ST | 0 - 1/8 (0.000 mi.) | E8 | 18 |
| MAN HOLE #57343<br>Spill Number/Closed Date: 9815413 / 3/31/1999 | IMLAY S T & SUMMIT ST | 0 - 1/8 (0.000 mi.) | C9 | 19 |
| TM #1747<br>Spill Number/Closed Date: 9912998 / 2/27/2002 | IMLAY ST/SUMMIT ST | 0 - 1/8 (0.000 mi.) | C12 | 40 |
| MANHOLE 57347<br>Spill Number/Closed Date: 9912922 / 2/27/2002 | SUMMIT ST & EMLAY | 0 - 1/8 (0.000 mi.) | C19 | 49 |
| 300 GAL OIL IN TM #1420<br>Spill Number/Closed Date: 0703565 / 7/23/2007 | DEGRAW & VANBRUNT STREE | 0 - 1/8 (0.000 mi.) | F21 | 50 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| BROOKLYN WEST A DOS -DDC<br>Spill Number/Closed Date: 9614895 / 2/18/2005<br>Spill Number/Closed Date: 9708762 / 2/1/2006 | 93 VAN BRUNT STREET | 0 - 1/8 (0.000 mi.) | E24 | 68 |
| MAN HOLE 43632<br>Spill Number/Closed Date: 0907974 / 11/30/2009 | 133 VANBRUNT ST | SSW 0 - 1/8 (0.002 mi.) | E28 | 80 |
| VAN BRUNT & CARROLL ST<br>Spill Number/Closed Date: 8603605 / 9/2/1986 | VAN BRUNT & CARROLL ST | SSW 0 - 1/8 (0.003 mi.) | G30 | 81 |
| MANHOLE #57342<br>Spill Number/Closed Date: 9815412 / 5/11/1999 | SUMMIT ST & VAN BRUNT S | SSW 0 - 1/8 (0.003 mi.) | G31 | 82 |
| GOLTENS MARINE<br>Spill Number/Closed Date: 1216530 / 3/29/2013 | 160 VAN BRUNDT ST | SSW 0 - 1/8 (0.003 mi.) | C32 | 83 |
| VAULT #TN1554<br>Spill Number/Closed Date: 9814694 / 6/6/2002<br>Spill Number/Closed Date: 9811739 / 2/14/2003<br>Spill Number/Closed Date: 9811742 / 2/14/2003 | 170 VAN BRUNT ST | SSW 0 - 1/8 (0.004 mi.) | I35 | 92 |
| COOKING OIL ON STREET<br>Spill Number/Closed Date: 0803040 / 6/16/2008 | 171 VANBRUNT ST | SSW 0 - 1/8 (0.005 mi.) | C40 | 100 |
| ***PORT AUTHORITY BROOKLYN PIERS***<br>Spill Number/Closed Date: 9708468 / 7/1/2013 | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B46*** | ***145*** |
| ROADWAY<br>Spill Number/Closed Date: 9614062 / 3/4/1997 | COLUMBIA ST/IRVING PL | SE 0 - 1/8 (0.005 mi.) | J48 | 178 |
| 169 COLUMBIA ST<br>Spill Number/Closed Date: 9614063 / 3/3/1997 | 169 COLUMBIA ST | SSE 0 - 1/8 (0.005 mi.) | D52 | 183 |
| COLUMBIA & KANE STS<br>Spill Number/Closed Date: 9408094 / 4/25/1995 | KANE & COLUMBIA STS PIE | SE 0 - 1/8 (0.005 mi.) | J53 | 184 |
| DRUM RUN<br>Spill Number/Closed Date: 1200175 / 4/20/2012 | 60 COLUMBIA STREET | ENE 0 - 1/8 (0.006 mi.) | K57 | 190 |
| ELITE CARPET & UPOLSTRY<br>Spill Number/Closed Date: 9713602 / 6/4/1998 | 147 COLUMBIA ST | SSE 0 - 1/8 (0.007 mi.) | D84 | 234 |
| SPILL NUMBER 0101741<br>Spill Number/Closed Date: 0101741 / 2/13/2003 | DEGRAW ST/COLUMBIA ST | SSE 0 - 1/8 (0.007 mi.) | M86 | 239 |
| COLUMBIA ST & ATLANTIC AV<br>Spill Number/Closed Date: 8904120 / 7/25/1989 | COLUMBIA ST & ATLANTIC | NE 0 - 1/8 (0.012 mi.) | O97 | 251 |
| DRUM RUN<br>Spill Number/Closed Date: 1101845 / 5/23/2011 | COLUMBIA ST | NE 0 - 1/8 (0.013 mi.) | O98 | 252 |
| MANHOLE 55769<br>Spill Number/Closed Date: 9909801 / 3/29/2002 | 23-52 ATLANTIC AVE | NE 0 - 1/8 (0.014 mi.) | O102 | 257 |
| GETTY 411<br>Spill Number/Closed Date: 1002438 / 6/3/2010 | 35 ATLANTIC AVE | NE 0 - 1/8 (0.016 mi.) | O103 | 258 |
| TRENCH<br>Spill Number/Closed Date: 0505704 / 10/5/2005 | VANBRUNT ST NEAR CARROL | SSW 0 - 1/8 (0.024 mi.) | G112 | 268 |
| MEDGAR EVERS COLLEGE<br>Spill Number/Closed Date: 9002752 / 6/20/1995 | 11 CARROLL STREET | SSW 0 - 1/8 (0.027 mi.) | G114 | 271 |
| ROADWAY<br>Spill Number/Closed Date: 0613408 / 3/14/2007 | BROOKLYN QUEENS EXPRESS | NE 0 - 1/8 (0.030 mi.) | P115 | 272 |
| BQE- W.BOUND ATLANTIC AVE<br>Spill Number/Closed Date: 9412790 / 1/3/1995 | BROOKLYN QUEENS EXPRESS | NE 0 - 1/8 (0.030 mi.) | P116 | 273 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| BKLYN QUNS EXPWY/ATLANTIC<br>Spill Number/Closed Date: 8910159 / 1/23/1990 | B Q EXPWY/ATLANTIC AVE | NE 0 - 1/8 (0.030 mi.) | P117 | 274 |
| ROADWAY<br>Spill Number/Closed Date: 0701741 / 5/11/2007<br>Spill Number/Closed Date: 1214603 / 1/15/2013 | BROOKLYN QUEENS EXPRESS | NE 0 - 1/8 (0.030 mi.) | P118 | 275 |
| EXIT OF ATLANTIC AVENUE<br>Spill Number/Closed Date: 9407939 / 9/15/1994 | EXIT OF ATLANTIC AVENUE | NE 0 - 1/8 (0.030 mi.) | P119 | 277 |
| BROOKLYN QUEENS EXPRESS<br>Spill Number/Closed Date: 0705598 / 8/16/2007 | ALTLANTIC AVE | NE 0 - 1/8 (0.030 mi.) | P120 | 278 |
| BQE-ATLANTIC AVE EXIT<br>Spill Number/Closed Date: 9106862 / 9/26/1991 | BROOKLYN QUEENS EXPRESS | NE 0 - 1/8 (0.030 mi.) | P121 | 279 |
| BQE @ ATLANTIC AVE.<br>Spill Number/Closed Date: 9407938 / 9/19/1994 | ENTRANCE RAMP BQE & ATL | NE 0 - 1/8 (0.030 mi.) | P122 | 280 |
| RT278 AT ATLANTIC AVE<br>Spill Number/Closed Date: 0101093 / 4/30/2001 | RT278 AT ATLANTIC AVE | NE 0 - 1/8 (0.030 mi.) | P123 | 282 |
| SPILL NUMBER 9805578<br>Spill Number/Closed Date: 9805578 / 8/5/1998 | BROOKLYN EXP/ATLANTIC A | NE 0 - 1/8 (0.030 mi.) | P124 | 283 |
| BQE - ATLANTIC AVE<br>Spill Number/Closed Date: 9412952 / 1/3/1995 | BROOKLYN QUEENS EXPRESS | NE 0 - 1/8 (0.030 mi.) | P125 | 284 |
| EAST RIVER<br>Spill Number/Closed Date: 1005329 / 8/11/2010<br>Spill Number/Closed Date: 9511518 / Not Reported | 29TH ST | NE 0 - 1/8 (0.034 mi.) | O127 | 291 |
| VOLT #3203<br>Spill Number/Closed Date: 0211543 / 4/3/2003 | HAMILTON AV OPP #2 | SSW 0 - 1/8 (0.035 mi.) | I128 | 294 |
| VS4121 NORTH SIDE<br>Spill Number/Closed Date: 9903606 / 5/18/2000 | 39TH STREET | NE 0 - 1/8 (0.039 mi.) | P135 | 303 |
| NEWTOWN CREEK & 43RD ST<br>Spill Number/Closed Date: 9508251 / 10/5/1995 | 43RD ST & NEWTOWN CREEK | NE 0 - 1/8 (0.041 mi.) | P136 | 304 |
| HEINS RES<br>Spill Number/Closed Date: 9811188 / 12/7/1998 | 74 UNION STREET | SSW 0 - 1/8 (0.046 mi.) | R138 | 311 |
| 51 SACKETT ST/BKLYN<br>Spill Number/Closed Date: 9008428 / 11/1/1990 | 51 SACKETT STREET | S 0 - 1/8 (0.049 mi.) | S140 | 312 |
| BETWEEN 2ND AV & 3RD AV<br>Spill Number/Closed Date: 9911584 / 1/12/2000 | 45TH ST BET 2ND & 3RD A | NE 0 - 1/8 (0.053 mi.) | P151 | 335 |
| RED HOOK CONTAINER<br>Spill Number/Closed Date: 9906280 / 11/12/1999 | RED HOOK CONTAINER | SSW 0 - 1/8 (0.054 mi.) | V152 | 336 |
| ***RED HOOK TERMINAL***<br>Spill Number/Closed Date: 9704119 / 7/7/1997 | ***HAMILTON AVE*** | ***SSW 0 - 1/8 (0.054 mi.)*** | ***V153*** | ***337*** |
| 89-101 HAMILTON AVENUE<br>Spill Number/Closed Date: 9712252 / 2/3/1998 | 89-101 HAMILTON AVENUE | SSW 0 - 1/8 (0.054 mi.) | Q154 | 339 |
| ***AMERICAN STEVEDORING INC***<br>Spill Number/Closed Date: 9405338 / 7/19/1994<br>Spill Number/Closed Date: 0202470 / 6/7/2002<br>Spill Number/Closed Date: 0700624 / 4/18/2007 | ***70 HAMILTON AVE*** | ***SSW 0 - 1/8 (0.055 mi.)*** | ***V164*** | ***354*** |
| RED HOOK CONTAINER<br>Spill Number/Closed Date: 1216835 / 4/1/2013 | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V170 | 375 |
| HUMBUG ON HAMBERGER<br>Spill Number/Closed Date: 8901238 / 11/6/2001 | 75 WARREN ST | E 0 - 1/8 (0.062 mi.) | X182 | 405 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| FORMER ABM SERVICE STATION<br>Spill Number/Closed Date: 0106455 / Not Reported | 434 HICKS STREET/115-11 | E 0 - 1/8 (0.076 mi.) | Y210 | 496 |
| DEGRAW<br>Spill Number/Closed Date: 0506519 / 9/29/2005 | DEGRAW/HICKS | SSE 0 - 1/8 (0.081 mi.) | AA212 | 505 |
| HICKS ST<br>Spill Number/Closed Date: 9905715 / 11/12/1999<br>Spill Number/Closed Date: 9606082 / 8/12/1996 | HICKS ST BET PRES. & CA | SSE 0 - 1/8 (0.081 mi.) | AA213 | 506 |
| AT CONGRESS ST<br>Spill Number/Closed Date: 9804952 / 7/21/1998 | SB LANE OF BQE | ENE 0 - 1/8 (0.082 mi.) | X224 | 547 |
| ON SIDE WALK<br>Spill Number/Closed Date: 0601287 / 7/5/2006 | HICKS ST & WARREN ST | E 0 - 1/8 (0.082 mi.) | AB225 | 548 |
| NYC DEP.<br>Spill Number/Closed Date: 9711191 / 11/9/2005 | 534 HICKS ST | SSE 0 - 1/8 (0.086 mi.) | AA229 | 555 |
| CON ED MANHOLE<br>Spill Number/Closed Date: 0804565 / 8/27/2008 | HICKS ST & KANE ST INTE | ESE 0 - 1/8 (0.092 mi.) | T237 | 574 |
| TENEMENT BLDG<br>Spill Number/Closed Date: 0207701 / 10/25/2002 | 509 HICKS ST | SSE 0 - 1/8 (0.099 mi.) | AA249 | 597 |
| AMITY HOSPITAL<br>Spill Number/Closed Date: 0312265 / 12/27/2004 | 336 HICKS STREET | ENE 0 - 1/8 (0.102 mi.) | AE255 | 609 |
| COBBLE HILL TOWERS APT #1E<br>Spill Number/Closed Date: 0608438 / 1/15/2009 | 423 HICKS STREET | E 0 - 1/8 (0.102 mi.) | AB257 | 610 |
| 69TH STREET<br>Spill Number/Closed Date: 9307124 / 3/31/1995 | 69TH STREET | NE 0 - 1/8 (0.103 mi.) | AE259 | 613 |
| APART<br>Spill Number/Closed Date: 0612892 / 3/9/2007 | 439 HICKS STREET | ESE 0 - 1/8 (0.103 mi.) | Y261 | 616 |
| VAULT 7211<br>Spill Number/Closed Date: 0306081 / 10/15/2003 | AMITY ST/HICKS ST | ENE 0 - 1/8 (0.103 mi.) | AH263 | 619 |
| VAULT 5526<br>Spill Number/Closed Date: 0505592 / 1/10/2006 | ATLANTIC AVE/HICKS ST | ENE 0 - 1/8 (0.103 mi.) | AE264 | 621 |
| HICK ST & ATLANTIC AVENUE<br>Spill Number/Closed Date: 9407834 / 9/13/1994 | HICKS ST & ATLANTIC AVE | ENE 0 - 1/8 (0.103 mi.) | AE265 | 622 |
| HICKS STREET AND ATLANTIC<br>Spill Number/Closed Date: 8700477 / 4/16/1987 | HICKS ST. & ATLANTIC AV | ENE 0 - 1/8 (0.103 mi.) | AE266 | 624 |
| TWO QTS ANTIFREEZE FROM TRUCK<br>Spill Number/Closed Date: 0613889 / 4/24/2007 | ALTLANTIC AVENUE & HICK | ENE 0 - 1/8 (0.104 mi.) | AE267 | 624 |
| MANHOLE 14656<br>Spill Number/Closed Date: 9905141 / 11/5/1999 | SW CORNER HICKS/ATLANTI | ENE 0 - 1/8 (0.104 mi.) | AE268 | 626 |
| SPILL NUMBER 0105297<br>Spill Number/Closed Date: 0105297 / 12/8/2003 | 113 HAMILTON AVE | SSW 0 - 1/8 (0.105 mi.) | AD277 | 644 |
| SPILL NUMBER 0001336<br>Spill Number/Closed Date: 0001336 / 7/11/2000 | 140 HAMILTON AVE | SSW 0 - 1/8 (0.105 mi.) | AI282 | 648 |
| BQE SADDLE TANK SPILL<br>Spill Number/Closed Date: 8600931 / 5/8/1986 | BROOKLYN QUEENS EXPRESS | SSE 0 - 1/8 (0.106 mi.) | AJ283 | 650 |
| 106 UNION STREET<br>Spill Number/Closed Date: 9211539 / 1/7/1993 | 106 UNION STREET | S 0 - 1/8 (0.108 mi.) | AG284 | 651 |
| ***WATCHTOWER BIBLE***<br>Spill Number/Closed Date: 0700183 / 4/12/2007 | ***360 FURMAN STREET*** | ***NNE 0 - 1/8 (0.109 mi.)*** | ***AK287*** | ***663*** |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| HAMILTON AVENUE<br>Spill Number/Closed Date: 9309547 / 11/29/1994 | HAMILTON AVENUE | SSW 0 - 1/8 (0.116 mi.) | AI297 | 691 |
| MANHOLE 1714<br>Spill Number/Closed Date: 1113303 / 3/23/2012 | HICKS ST/STATE ST | NE 0 - 1/8 (0.118 mi.) | AE300 | 695 |
| ENGINE CO. 202/LADD. CO. 10 FD<br>Spill Number/Closed Date: 9600812 / 12/9/2005 | 31 RICHARDS STREET | SSW 0 - 1/8 (0.121 mi.) | AC310 | 712 |
| PM 1419<br>Spill Number/Closed Date: 9815132 / 6/6/2002 | COLUMBIA ST & CARROLL S | S 0 - 1/8 (0.125 mi.) | AP314 | 715 |
| 174 SACKETT ST.<br>Spill Number/Closed Date: 9214467 / 2/11/2003 | 174 SACKETT ST | SSE 0 - 1/8 (0.125 mi.) | AN315 | 716 |
| 124 KANE STREET<br>Spill Number/Closed Date: 0302546 / 7/17/2003 | 124 KANE STREET | ESE 1/8 - 1/4 (0.127 mi.) | AJ318 | 718 |
| SPILL NUMBER 0306452<br>Spill Number/Closed Date: 0306452 / 10/15/2003 | HAMILTON AV & RICHARD S | SSW 1/8 - 1/4 (0.133 mi.) | AI322 | 721 |
| 55 COMMERCE ST/BKLYN<br>Spill Number/Closed Date: 8801960 / 8/7/1995 | 55 COMMERCE STREET | SSW 1/8 - 1/4 (0.135 mi.) | AL323 | 723 |
| ***MOBIL OIL CORP SS #EMW***<br>Spill Number/Closed Date: 8904339 / Not Reported<br>Spill Number/Closed Date: 0502047 / 4/26/2010<br>Spill Number/Closed Date: 0610200 / 4/26/2010 | ***304 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.140 mi.)*** | ***AO326*** | ***731*** |
| 27 CHEEVER PLACE<br>Spill Number/Closed Date: 9516629 / 3/26/1996 | 27 CHEEVER PLACE | SE 1/8 - 1/4 (0.146 mi.) | AJ330 | 747 |
| VAULT 4398<br>Spill Number/Closed Date: 9911663 / 7/17/2000 | 85TH STREET | ENE 1/8 - 1/4 (0.155 mi.) | AS343 | 761 |
| ***TRIBOROUGH BRIDGE & TUNNEL AUT***<br>Spill Number/Closed Date: 9908442 / Not Reported | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT352*** | ***790*** |
| POLE 67345<br>Spill Number/Closed Date: 0107466 / 6/13/2003 | 80 DELEVAN ST | SSW 1/8 - 1/4 (0.157 mi.) | AR353 | 810 |
| BTWN DITMAS AV/DEAD END<br>Spill Number/Closed Date: 9913824 / 2/14/2003 | 91ST ST | ENE 1/8 - 1/4 (0.160 mi.) | AS361 | 821 |
| SOUTHWEST CORNER<br>Spill Number/Closed Date: 1103205 / 1/18/2012 | JORALEMON ST AND COLUMB | NE 1/8 - 1/4 (0.166 mi.) | AQ369 | 832 |
| DRUM RUN<br>Spill Number/Closed Date: 0406978 / 11/1/2004 | HAMILTON AVE.& RAPELYE | S 1/8 - 1/4 (0.173 mi.) | AT374 | 839 |
| DRUM RUN<br>Spill Number/Closed Date: 0409284 / 12/14/2004 | HAMILTON AVE AND RAPELY | S 1/8 - 1/4 (0.173 mi.) | AT375 | 840 |
| VACANT LOT/FUTURE HOTEL<br>Spill Number/Closed Date: 0805267 / Not Reported | 11-15 SEABRING STREET | SSW 1/8 - 1/4 (0.175 mi.) | AT377 | 844 |
| UNDER ROADWAY<br>Spill Number/Closed Date: 1004881 / 8/4/2011 | 160 HAMILTON AVE NORTH/ | S 1/8 - 1/4 (0.178 mi.) | AT378 | 865 |
| MAN HOLE #17152<br>Spill Number/Closed Date: 9815102 / 4/2/1999 | HAMILTON AV & COLUMBIA | S 1/8 - 1/4 (0.186 mi.) | AT382 | 874 |
| IN MUD MANHOLE #20843<br>Spill Number/Closed Date: 9812208 / 10/17/2002 | 446 HENRY ST | SE 1/8 - 1/4 (0.187 mi.) | 384 | 876 |
| MANHOLE 20836<br>Spill Number/Closed Date: 9812207 / 10/17/2002 | HENRY ST & KANE ST | ESE 1/8 - 1/4 (0.188 mi.) | BA386 | 877 |
| ***UNIVERSITY HOSPITAL OF BROOKLY***<br>Spill Number/Closed Date: 0105976 / 9/6/2001 | ***340 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***AW388*** | ***879*** |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| MAN HOLE # 56082<br>Spill Number/Closed Date: 9811672 / 5/7/2001 | HENRY ST/CONGRESS ST | E 1/8 - 1/4 (0.189 mi.) | BB393 | 906 |
| 218163; HENRY ST AND CONGRESS<br>Spill Number/Closed Date: 0914413 / 10/22/2009 | HENRY ST AND CONGRESS S | E 1/8 - 1/4 (0.189 mi.) | BB394 | 907 |
| TWENTY GAL RELEASE AT MH 56082<br>Spill Number/Closed Date: 0701879 / 6/28/2007<br>Spill Number/Closed Date: 0900503 / 6/3/2009 | 371 HENRY STREET | E 1/8 - 1/4 (0.190 mi.) | BB402 | 919 |
| ***327 HENRY ST***<br>Spill Number/Closed Date: 0905847 / 9/16/2009 | ***327 HENRY ST*** | ***ENE 1/8 - 1/4 (0.190 mi.)*** | ***BC404*** | ***922*** |
| ***76 PRECINCT NYPD -DDC***<br>Spill Number/Closed Date: 9601482 / Not Reported<br>Spill Number/Closed Date: 9830012 / 10/31/2003 | ***191 UNION STREET*** | ***SSE 1/8 - 1/4 (0.191 mi.)*** | ***AU405*** | ***925*** |
| ***SHELL GAS***<br>Spill Number/Closed Date: 9806463 / 7/11/2002<br>Spill Number/Closed Date: 0809729 / 8/3/2010 | ***112 ATLANTIC AVE*** | ***ENE 1/8 - 1/4 (0.193 mi.)*** | ***BC410*** | ***942*** |
| ROCKAWAY BEACH<br>Spill Number/Closed Date: 9905248 / 8/27/1999<br>Spill Number/Closed Date: 0107483 / 2/13/2003 | 116TH ST | ENE 1/8 - 1/4 (0.195 mi.) | AS417 | 962 |
| VAULT #3598<br>Spill Number/Closed Date: 0009860 / 1/18/2001 | SACKETT ST & HENRY ST | SSE 1/8 - 1/4 (0.197 mi.) | AZ419 | 966 |
| CORNER OF<br>Spill Number/Closed Date: 0903068 / 8/5/2009 | SACKETT ST AND HENRY ST | SSE 1/8 - 1/4 (0.197 mi.) | AZ420 | 967 |
| TM 170<br>Spill Number/Closed Date: 0313672 / 6/9/2004 | JORALEMON ST E/0 HICKS | NE 1/8 - 1/4 (0.203 mi.) | AY427 | 974 |
| DRUM RUN<br>Spill Number/Closed Date: 0507279 / 9/29/2005 | 61 RAPELYE ST | S 1/8 - 1/4 (0.210 mi.) | BH436 | 983 |
| ***NICOBROS INC DBA J&E SERVICE***<br>Spill Number/Closed Date: 0808610 / 6/15/2012 | ***640 HICKS STREET*** | ***S 1/8 - 1/4 (0.211 mi.)*** | ***BI437*** | ***984*** |
| PIER 11 OIL STAIN & FIRE<br>Spill Number/Closed Date: 8601969 / 6/23/1986 | PIER 11,COMMERCE ST. | SSW 1/8 - 1/4 (0.213 mi.) | BL443 | 1008 |
| MH #43281<br>Spill Number/Closed Date: 9813126 / 10/18/2002 | HENRY ST & UNION ST | SSE 1/8 - 1/4 (0.216 mi.) | BM445 | 1012 |
| 42 GRACE COURT<br>Spill Number/Closed Date: 9208894 / 11/2/1992 | 42 GRACE COURT | NE 1/8 - 1/4 (0.216 mi.) | BJ446 | 1013 |
| IDEA NUOVA GLOBAL<br>Spill Number/Closed Date: 1211033 / 11/13/2012 | 80 RICHARDS ST | SSW 1/8 - 1/4 (0.216 mi.) | BE448 | 1016 |
| 283 HENRY ST/BROOKLYN<br>Spill Number/Closed Date: 8911344 / 3/1/1990 | 283 HENRY STREET | ENE 1/8 - 1/4 (0.217 mi.) | BK449 | 1017 |
| MAZZOLA BAKERY<br>Spill Number/Closed Date: 9913889 / 11/16/2005 | 192 UNION ST | SSE 1/8 - 1/4 (0.219 mi.) | BM455 | 1029 |
| CLOSED IN LOT<br>Spill Number/Closed Date: 0614015 / 4/5/2007 | 35 DELVAN STREET | SSW 1/8 - 1/4 (0.222 mi.) | BE463 | 1044 |
| DRUM RUN<br>Spill Number/Closed Date: 1000727 / 5/5/2010 | HICKS ST & SUMMIT ST | S 1/8 - 1/4 (0.223 mi.) | 464 | 1046 |
| APARTMENT BUILDING<br>Spill Number/Closed Date: 0410977 / 3/18/2005 | 19 GRACE COURT | NNE 1/8 - 1/4 (0.224 mi.) | BJ467 | 1050 |
| MANHOLE #57915<br>Spill Number/Closed Date: 9812670 / 10/17/2002 | WOODHULL ST E OF HICKS | S 1/8 - 1/4 (0.226 mi.) | BI469 | 1051 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| MANHOLE 57915<br>Spill Number/Closed Date: 0210466 / 2/26/2003 | WOODHULL ST & HICKS ST | S 1/8 - 1/4 (0.232 mi.) | BI477 | 1061 |
| HAMILTON AVE & HICKS ST<br>Spill Number/Closed Date: 9302895 / 6/3/1993 | HAMILTON AVE & HICKS ST | S 1/8 - 1/4 (0.236 mi.) | BH480 | 1066 |
| SPILL NUMBER 9900296<br>Spill Number/Closed Date: 9900296 / 4/8/1999 | 136-138 ATLANTIC AVE | ENE 1/8 - 1/4 (0.237 mi.) | BQ482 | 1070 |
| MANHOLE 20859<br>Spill Number/Closed Date: 9812900 / 10/18/2002 | HENRY STREET AT PRESIDE | SSE 1/8 - 1/4 (0.238 mi.) | BO483 | 1071 |
| COURTYARD OF APT COMPLEX<br>Spill Number/Closed Date: 1206890 / 10/31/2013 | 5 DELEVAN ST | SSW 1/8 - 1/4 (0.242 mi.) | BP488 | 1089 |
| ***TOM RUSSO'S SHOP COLLISIONVILL***<br>Spill Number/Closed Date: 0713807 / 4/7/2008 | ***204 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.244 mi.)*** | ***BF491*** | ***1091*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| PIER #7<br>Spill Number/Closed Date: 0612593 / 6/3/2013 | BROOKLYN PORT AUTHORITY | 0 - 1/8 (0.000 mi.) | A2 | 9 |
| FOOT OF ATLANTIC AVE AT<br>Spill Number/Closed Date: 9714448 / 3/30/1998 | BROOKLYN PIER #7 | 0 - 1/8 (0.000 mi.) | A3 | 13 |
| ***SHOWMAN FABRICATORS INC***<br>Spill Number/Closed Date: 1208335 / 4/4/2013 | ***29 IMLAY ST*** | ***0 - 1/8 (0.000 mi.)*** | ***C11*** | ***35*** |
| PORT AUTHORITY -BUILDING #111<br>Spill Number/Closed Date: 0612595 / Not Reported | FOOT OF HAMILTON AVE | 0 - 1/8 (0.000 mi.) | 16 | 44 |
| IN THE AREA OF NY HARBOR<br>Spill Number/Closed Date: 9904255 / 7/11/1999 | ATLANTIC AVE | NNE 0 - 1/8 (0.005 mi.) | 38 | 98 |
| MANHOLE 57960<br>Spill Number/Closed Date: 0305504 / 9/19/2003 | IMLAY ST AT BOWNE ST | SSW 0 - 1/8 (0.005 mi.) | H49 | 179 |
| VACANT BUILDING<br>Spill Number/Closed Date: 0811376 / 1/15/2010 | 62 IMLAY ST | SSW 0 - 1/8 (0.007 mi.) | H87 | 240 |
| ANCHORAGE & BUTTREMILK CH<br>Spill Number/Closed Date: 9207079 / 11/23/1994 | ANCHORAGE & BUTTERMILK | SW 0 - 1/8 (0.062 mi.) | 181 | 404 |
| EAST RIVER / BROOKLYN<br>Spill Number/Closed Date: 8602044 / 6/25/1986 | EAST RIVER | N 0 - 1/8 (0.065 mi.) | Z190 | 430 |
| EAST RIVER<br>Spill Number/Closed Date: 9408331 / 9/22/1994 | EAST RIVER- & GREEN ST | N 0 - 1/8 (0.065 mi.) | Z191 | 431 |
| 211 VAN BRUNT STREET (HURRICAN<br>Spill Number/Closed Date: 1212405 / 11/16/2012 | 211 VAN BRUNT STREET | SSW 0 - 1/8 (0.081 mi.) | U218 | 538 |
| 211 VAN BRUNT (HURRICANE SANDY<br>Spill Number/Closed Date: 1212250 / 11/14/2012 | 211 VAN BRUNT | SSW 0 - 1/8 (0.081 mi.) | U222 | 544 |
| RED HOOK MARINE TERMINAL<br>Spill Number/Closed Date: 9513092 / 8/14/1996 | CONOVER STREET | SW 0 - 1/8 (0.096 mi.) | AF240 | 583 |
| CONTAINMENT VESSEL<br>Spill Number/Closed Date: 8605954 / 12/19/1986 | REDHOOK UNIVERSAL TERMI | SW 0 - 1/8 (0.096 mi.) | AF241 | 584 |
| RED HOOK TERMINAL<br>Spill Number/Closed Date: 9306442 / 8/26/1993<br>Spill Number/Closed Date: 9213470 / 11/23/1994 | RED HOOK TERMINAL-PIER | SW 0 - 1/8 (0.096 mi.) | AF242 | 586 |
| THIMET,BKLYN TERMINAL<br>Spill Number/Closed Date: 8604187 / 9/30/1986 | REDHOOK TERMINAL | SW 0 - 1/8 (0.096 mi.) | AF243 | 587 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| BERTH 1 AND 2 AT RED HOOK<br>Spill Number/Closed Date: 8704433 / 8/28/1987 | BERTH 1 AND 2/RED HOOK | SW 0 - 1/8 (0.096 mi.) | AF244 | 589 |
| RED HOOK TERM BERTH 1 & 2<br>Spill Number/Closed Date: 9203673 / 6/29/1992 | RED HOOK TERMINALS | SW 0 - 1/8 (0.096 mi.) | AF245 | 590 |
| MANHOLE #5779<br>Spill Number/Closed Date: 0401666 / 5/17/2004 | IMLEY ST / COMMERCE ST | SSW 0 - 1/8 (0.103 mi.) | AF258 | 612 |
| INLAY STREET AT COMMERCE<br>Spill Number/Closed Date: 8701486 / 8/12/1987 | INLAY STREET @ COMMERCE | SW 1/8 - 1/4 (0.132 mi.) | AF321 | 720 |
| TRANSFORMER POLE 67175<br>Spill Number/Closed Date: 1209972 / 6/10/2013 | 240 VAN BRUNT ST | SSW 1/8 - 1/4 (0.150 mi.) | AR336 | 755 |
| ABANDONED HOUSE BASEMENT<br>Spill Number/Closed Date: 0901786 / 12/14/2010 | 251 VAN BRUNT ST | SSW 1/8 - 1/4 (0.150 mi.) | AR338 | 756 |
| SPILL NUMBER 0303652<br>Spill Number/Closed Date: 0303652 / 8/19/2003 | IMLAY ST & VERONA ST | SW 1/8 - 1/4 (0.200 mi.) | BD424 | 971 |
| OPPOSITE 253 VAN BRUNT ST<br>Spill Number/Closed Date: 9602193 / 5/16/1996 | OPPOSITE 253 VAN BRUNT | SSW 1/8 - 1/4 (0.205 mi.) | BG431 | 979 |
| RESIDENCE<br>Spill Number/Closed Date: 0513119 / 12/5/2008 | 280 VAN BRUNT ST | SSW 1/8 - 1/4 (0.213 mi.) | BG442 | 1001 |
| AERIAL XFMR ON POLE #67195 HAS<br>Spill Number/Closed Date: 0708562 / 11/27/2007 | IN FRONT OF 284 VAN BRU | SSW 1/8 - 1/4 (0.230 mi.) | BG475 | 1060 |

NY SPILLS 90: Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

A review of the NY SPILLS 90 list, as provided by EDR, and dated 12/14/2012 has revealed that there are 2 NY SPILLS 90 sites within approximately 0.25 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| 211 VAN BRUNT STREET (HURRICAN | 211 VAN BRUNT STREET | SSW 0 - 1/8 (0.081 mi.) | U217 | 537 |
| 211 VAN BRUNT (HURRICANE SANDY | 211 VAN BRUNT | SSW 0 - 1/8 (0.081 mi.) | U221 | 544 |

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/11/2014 has revealed that there are 18 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***NYC DOS BROOKLYN WEST A*** | ***93 VAN BRUNT ST*** | ***0 - 1/8 (0.000 mi.)*** | ***E23*** | ***67*** |
| ***PORT AUTHORITY BROOKLYN PIERS*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B46*** | ***145*** |
| AMERICAN STEVEDORING INC | 70 HAMILTON AVENUE | SSW 0 - 1/8 (0.055 mi.) | V162 | 352 |

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| RED HOOK CONTAINER TERMINAL | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V166 | 371 |
| ***NYSDOT CONTRACT D254611*** | ***59 ATLANTIC AVE*** | ***NE 0 - 1/8 (0.093 mi.)*** | ***AE238*** | ***575*** |
| CON EDISON MANHOLE: 4647 | 75 ATLANTIC AVE | ENE 0 - 1/8 (0.104 mi.) | AE270 | 629 |
| ***ATLANTIC STAR CLEANERS*** | ***77 ATLANTIC AVE*** | ***ENE 0 - 1/8 (0.112 mi.)*** | ***AE294*** | ***680*** |
| ***NYCDOT*** | ***KANE SACKETT & UNION ST*** | ***SSE 0 - 1/8 (0.118 mi.)*** | ***AN299*** | ***693*** |
| NYC DEP | RICHARDS ST & SEABRING | SSW 0 - 1/8 (0.121 mi.) | AC307 | 704 |
| ***BRUNO TRUCK SALES*** | ***50 COMMERCE ST*** | ***SSW 1/8 - 1/4 (0.140 mi.)*** | ***324*** | ***724*** |
| ***MOBIL OIL CORP SS #EMW*** | ***304 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.140 mi.)*** | ***AO326*** | ***731*** |
| NYCT AUTH | MANHOLE 27 WILLOW PL | NE 1/8 - 1/4 (0.149 mi.) | AQ331 | 748 |
| ***BROOKLYN MOTOR CYCLE WORKS*** | ***194 SACKETT ST*** | ***SSE 1/8 - 1/4 (0.161 mi.)*** | ***AN362*** | ***822*** |
| ***MTA NYCT WILLOW PLACE FAN PLAN*** | ***58 JORALEMON ST*** | ***NE 1/8 - 1/4 (0.182 mi.)*** | ***AY381*** | ***871*** |
| ***SHELL OIL-S&D SERV STA INC*** | ***112 ATLANTIC AVENUE*** | ***ENE 1/8 - 1/4 (0.193 mi.)*** | ***BC411*** | ***948*** |
| ***LADYZINSKI JOHN*** | ***44 GRACE CT*** | ***NE 1/8 - 1/4 (0.216 mi.)*** | ***BJ447*** | ***1014*** |
| ***NYSDOT CONTRACT D252284*** | ***373 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.229 mi.)*** | ***BF473*** | ***1056*** |
| ***TOM RUSSO'S SHOP COLLISIONVILL*** | ***204 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.244 mi.)*** | ***BF491*** | ***1091*** |

FTTS: FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 04/09/2009 has revealed that there are 2 FTTS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***GRACE CHURCH*** | ***254 HICKS ST*** | ***NE 1/8 - 1/4 (0.220 mi.)*** | ***AY457*** | ***1030*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHUEN FAI TRADING CORP*** | ***191-193 VAN BRUNT ST*** | ***SSW 0 - 1/8 (0.020 mi.)*** | ***H110*** | ***267*** |

HIST FTTS: A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there are 2 HIST FTTS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***GRACE CHURCH*** | ***254 HICKS ST*** | ***NE 1/8 - 1/4 (0.220 mi.)*** | ***AY457*** | ***1030*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHUEN FAI TRADING CORP*** | ***191-193 VAN BRUNT ST*** | ***SSW 0 - 1/8 (0.020 mi.)*** | ***H110*** | ***267*** |

# EXECUTIVE SUMMARY

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 07/20/2011 has revealed that there are 5 ICIS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| BROOKLYN BATTERY TUNNEL | 160 HAMILTON AVE BRO | S 1/8 - 1/4 (0.156 mi.) | AT347 | 767 |
| NYC BD OF ED - PUBLIC SCHOOL 2 | 425 HENRY ST BROOKLY | ESE 1/8 - 1/4 (0.189 mi.) | BA392 | 905 |
| PLASTIFORM PACKAGING INCORPORA | 42 DELEVAN ST BROOKL | SSW 1/8 - 1/4 (0.191 mi.) | BE407 | 937 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CHUEN FAI TRADING CORP | 191 VAN BRUNT STREET | SSW 0 - 1/8 (0.020 mi.) | H108 | 265 |
| WYCKOFF MEDICAL CENTER OFFICE | 267 VAN BRUNT STREET | SSW 1/8 - 1/4 (0.248 mi.) | BG493 | 1101 |

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 11/18/2013 has revealed that there are 62 FINDS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| PORT AUTHORITY-PIER 9B | SEDGWICK STREET | 0 - 1/8 (0.000 mi.) | D6 | 16 |
| 20TH CENTURY RECYCLING - 170 V | 170 VAN BRUNT STREET (A | 0 - 1/8 (0.000 mi.) | C18 | 48 |
| ***NYC DOS BROOKLYN WEST A*** | ***93 VAN BRUNT ST*** | ***0 - 1/8 (0.000 mi.)*** | ***E23*** | ***67*** |
| NYC DEP - GOWANUS FLUSHING TUN | DEGRAW ST | SSW 0 - 1/8 (0.002 mi.) | F27 | 79 |
| NYMT - BP ASI CONTAINER | 90 COLUMBIA STREET | E 0 - 1/8 (0.005 mi.) | B43 | 144 |
| PORT AUTHORITY/BROOKLYN MARINE | 90 COLUMBIA STREET | E 0 - 1/8 (0.005 mi.) | B45 | 144 |
| SOUTH BROOKLYN AUTO BODY | 67 UNION ST. | SSW 0 - 1/8 (0.011 mi.) | E95 | 250 |
| DESIGNERS WOODCRAFT INC | 129 DEGRAW STREET | SSE 0 - 1/8 (0.036 mi.) | M130 | 297 |
| RED HOOK CONTAINER TERMINAL | 70 HAMILTON AVENUE | SSW 0 - 1/8 (0.055 mi.) | V171 | 377 |
| BLOOMING IMPORT INC. | 45 BOWNE STREET | SSW 0 - 1/8 (0.073 mi.) | V204 | 473 |
| ***ATLANTIC-HICKS ST*** | ***434 HICKS STREET*** | ***ESE 0 - 1/8 (0.081 mi.)*** | ***Y214*** | ***508*** |
| DAVID HAMBERGER INC | 410 HICKS ST | E 0 - 1/8 (0.081 mi.) | X219 | 539 |
| KAMMETAL | 60 SEABRING ST | SSW 0 - 1/8 (0.085 mi.) | AC228 | 555 |
| AUTO WERK-AUTOBODY | 61 SUMMIT STREET | S 0 - 1/8 (0.089 mi.) | W232 | 563 |
| ***NYSDOT CONTRACT D254611*** | ***59 ATLANTIC AVE*** | ***NE 0 - 1/8 (0.093 mi.)*** | ***AE238*** | ***575*** |
| PEDRO'S WORK CORP | 34-43 ATLANTIC AVENUE | ENE 0 - 1/8 (0.096 mi.) | AE246 | 591 |
| 113-115 UNION STREET BUILDING | 113-115 UNION ST | S 0 - 1/8 (0.102 mi.) | AG253 | 602 |
| CON EDISON MANHOLE: 4647 | 75 ATLANTIC AVE | ENE 0 - 1/8 (0.104 mi.) | AE271 | 630 |
| SUNY DOWNSTATE MEDICAL CENTER | 339 HICKS ST | ENE 0 - 1/8 (0.104 mi.) | AE276 | 643 |
| MOBIL OIL-BKLYN TUNNEL SVCE ST | 113-115 HAMILTON AVE | SSW 0 - 1/8 (0.105 mi.) | AD278 | 645 |
| ***TECHNIKOTE CORP*** | ***63 SEABRING ST*** | ***SSW 0 - 1/8 (0.109 mi.)*** | ***AL289*** | ***666*** |
| WATCHTOWER BIBLE AND TRACT | 360 FURMAN ST | NNE 0 - 1/8 (0.111 mi.) | AK291 | 677 |
| NEW YOU LIAN TRADING INC. | 70 COMMERCE STREET | SSW 0 - 1/8 (0.111 mi.) | AL292 | 678 |
| ***ATLANTIC STAR CLEANERS*** | ***77 ATLANTIC AVE*** | ***ENE 0 - 1/8 (0.112 mi.)*** | ***AE294*** | ***680*** |
| YMCA | 130 SOUTH UNION STREET | S 0 - 1/8 (0.115 mi.) | AM295 | 690 |
| NYC DEP | RICHARDS ST & SEABRING | SSW 0 - 1/8 (0.121 mi.) | AC305 | 704 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| KINGS HARBOR VIEW-PIER 44 | 163 DEGRAW STREET | SSE 0 - 1/8 (0.123 mi.) | AA312 | 714 |
| TM1419 | CARROLL ST & COLUMBIA S | S 0 - 1/8 (0.125 mi.) | AP313 | 715 |
| ***BRUNO TRUCK SALES*** | ***50 COMMERCE ST*** | ***SSW 1/8 - 1/4 (0.140 mi.)*** | ***324*** | ***724*** |
| ***MOBIL OIL CORP SS #EMW*** | ***304 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.140 mi.)*** | ***AO326*** | ***731*** |
| NYCT AUTH | MANHOLE 27 WILLOW PL | NE 1/8 - 1/4 (0.149 mi.) | AQ332 | 749 |
| BROOKLYN BATTERY TUNNEL | 160 HAMILTON AVE | S 1/8 - 1/4 (0.156 mi.) | AT350 | 783 |
| 24 JORALEMON ST BUILDING | 24 JORALEMON ST | NNE 1/8 - 1/4 (0.160 mi.) | AQ360 | 821 |
| ***BROOKLYN MOTOR CYCLE WORKS*** | ***194 SACKETT ST*** | ***SSE 1/8 - 1/4 (0.161 mi.)*** | ***AN362*** | ***822*** |
| ***CON EDISON MANHOLE: 44577*** | ***15 SEABRING ST*** | ***SSW 1/8 - 1/4 (0.166 mi.)*** | ***AT364*** | ***826*** |
| ***CON EDISON MANHOLE: 9192*** | ***332 FURMAN ST FRONT OF*** | ***NNE 1/8 - 1/4 (0.166 mi.)*** | ***AV367*** | ***830*** |
| ***MTA NYCT WILLOW PLACE FAN PLAN*** | ***58 JORALEMON ST*** | ***NE 1/8 - 1/4 (0.182 mi.)*** | ***AY381*** | ***871*** |
| ***UNIVERSITY HOSPITAL OF BROOKLY*** | ***340 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***AW388*** | ***879*** |
| PS 29 | 425 HENRY STREET | ESE 1/8 - 1/4 (0.189 mi.) | BA390 | 897 |
| ***NYC BD OF ED - PUBLIC SCHOOL 2*** | ***425 HENRY ST*** | ***ESE 1/8 - 1/4 (0.189 mi.)*** | ***BA391*** | ***898*** |
| COBBLE HILL HEALTH CENTER | 380 HENRY ST | E 1/8 - 1/4 (0.189 mi.) | BB398 | 917 |
| ***PLASTIFORM PACKAGING INCORPORA*** | ***42 DELEVAN ST*** | ***SSW 1/8 - 1/4 (0.191 mi.)*** | ***BE409*** | ***940*** |
| ***SHELL OIL-S&D SERV STA INC*** | ***112 ATLANTIC AVENUE*** | ***ENE 1/8 - 1/4 (0.193 mi.)*** | ***BC411*** | ***948*** |
| ***LI'S DRY CLEANER*** | ***500 HENRY ST*** | ***SSE 1/8 - 1/4 (0.195 mi.)*** | ***AZ418*** | ***964*** |
| ***HENRY GREEN CLEANERS*** | ***113 PACIFIC STREET*** | ***ENE 1/8 - 1/4 (0.206 mi.)*** | ***BC432*** | ***980*** |
| ***LADYZINSKI JOHN*** | ***44 GRACE CT*** | ***NE 1/8 - 1/4 (0.216 mi.)*** | ***BJ447*** | ***1014*** |
| JOHN TURANO & SONS | 80 RICHARDS ST | SSW 1/8 - 1/4 (0.218 mi.) | BE453 | 1024 |
| GRACE CHURCH | 254 HICKS STREET | NE 1/8 - 1/4 (0.220 mi.) | AY456 | 1030 |
| CON EDISON MANHOLE: 43937 | VERONA & RICHARDS ST | SSW 1/8 - 1/4 (0.229 mi.) | BP470 | 1053 |
| ***NYSDOT CONTRACT D252284*** | ***373 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.229 mi.)*** | ***BF473*** | ***1056*** |
| RANDEX CLEANERS | 534 HENRY STREET | SSE 1/8 - 1/4 (0.241 mi.) | BM487 | 1088 |
| ***TOM RUSSO'S SHOP COLLISIONVILL*** | ***204 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.244 mi.)*** | ***BF491*** | ***1091*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SHOWMAN FABRICATORS*** | ***29 IMLAY ST*** | ***0 - 1/8 (0.000 mi.)*** | ***C14*** | ***41*** |
| EXTECH BUILDING MATERIALS | 87 BOWNE ST | SSW 0 - 1/8 (0.005 mi.) | H51 | 182 |
| MERCEDES DISTRIBUTION CENTER | 62 IMLAY ST | SSW 0 - 1/8 (0.007 mi.) | H88 | 242 |
| GLORY TRADING CORP. | 191-193 VAN BRUNT STR. | SSW 0 - 1/8 (0.020 mi.) | H109 | 266 |
| CHUEN FAI TRADING COMPANY | 191 VAN BRUNT STREET | SSW 0 - 1/8 (0.020 mi.) | H111 | 267 |
| TUFARO SVCE STA | 225 VAN BRUNT STREET | SSW 1/8 - 1/4 (0.150 mi.) | AR334 | 751 |
| SEISE BROS-252 VAN BRUNT ST | 252 VAN BRUNT ST | SSW 1/8 - 1/4 (0.152 mi.) | AR341 | 760 |
| JOEL GOLDSTEIN MERCEDES DIST C | 160 IMLAY ST | SW 1/8 - 1/4 (0.190 mi.) | BD401 | 919 |
| PREMIUM MILLWORK INC | 270 VAN BRUNT ST | SSW 1/8 - 1/4 (0.190 mi.) | AR403 | 921 |
| WYCKOFF MEDICAL CENTER OFFICE | 267 VAN BRUNT STREET | SSW 1/8 - 1/4 (0.248 mi.) | BG494 | 1102 |

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 02/28/2014 has revealed that there are 45 NY MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| NICHMEN AMERICA INC | VAN BRUNT ST & HAMILTON | SSW 0 - 1/8 (0.005 mi.) | C39 | 99 |
| ASI SITE MATERIALS | 90 COLUMBIA STREET | E 0 - 1/8 (0.005 mi.) | B44 | 144 |
| ***PORT AUTHORITY BROOKLYN PIERS*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B46*** | ***145*** |
| US COAST GUARD/RED HOOK MARINE | 70 HAMILTON AVE PIER 10 | SSW 0 - 1/8 (0.055 mi.) | V163 | 353 |
| ***AMERICAN STEVEDORING INC*** | ***70 HAMILTON AVE*** | ***SSW 0 - 1/8 (0.055 mi.)*** | ***V164*** | ***354*** |
| DAVID HAMBERGER INC | 110-112 WARREN ST | E 0 - 1/8 (0.075 mi.) | Y209 | 491 |
| CONSOLIDATED EDISON | HICK ST & KANE ST | ESE 0 - 1/8 (0.081 mi.) | T223 | 545 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***NYSDOT CONTRACT D254611*** | ***59 ATLANTIC AVE*** | ***NE 0 - 1/8 (0.093 mi.)*** | ***AE238*** | ***575*** |
| TRI COUNTY DIAGNOSTICS LABS | 25-78 ATLANTIC AVE | ENE 0 - 1/8 (0.101 mi.) | AE251 | 599 |
| CON EDISON | 75 ATLANTIC AVE | ENE 0 - 1/8 (0.104 mi.) | AE269 | 627 |
| ***WATCHTOWER BIBLE*** | ***360 FURMAN STREET*** | ***NNE 0 - 1/8 (0.109 mi.)*** | ***AK287*** | ***663*** |
| ***TECHNIKOTE CORP*** | ***63 SEABRING ST*** | ***SSW 0 - 1/8 (0.109 mi.)*** | ***AL289*** | ***666*** |
| BELL ATLANTIC-NY | 5 AV + PACIFIC ST MANHO | ENE 0 - 1/8 (0.110 mi.) | 290 | 677 |
| ***ATLANTIC STAR CLEANERS*** | ***77 ATLANTIC AVE*** | ***ENE 0 - 1/8 (0.112 mi.)*** | ***AE294*** | ***680*** |
| ***NYCDOT*** | ***KANE SACKETT & UNION ST*** | ***SSE 0 - 1/8 (0.118 mi.)*** | ***AN299*** | ***693*** |
| NYCDEP | RICHARDS ST & SEABRING | SSW 0 - 1/8 (0.121 mi.) | AC306 | 704 |
| ***MOBIL OIL CORP SS #EMW*** | ***304 COLUMBIA ST*** | ***S 1/8 - 1/4 (0.140 mi.)*** | ***AO326*** | ***731*** |
| NYCTA | 27 WILLOW PLACE | NE 1/8 - 1/4 (0.149 mi.) | AQ333 | 750 |
| ***TRIBOROUGH BRIDGE & TUNNEL AUT*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT352*** | ***790*** |
| CON EDISION | 18 WILLOW PL | NE 1/8 - 1/4 (0.158 mi.) | AQ354 | 812 |
| CON EDISON | JORALEMON ST & FURMAN S | NNE 1/8 - 1/4 (0.158 mi.) | AK355 | 812 |
| CON EDISON | 15 SEABRING ST | SSW 1/8 - 1/4 (0.166 mi.) | AT365 | 827 |
| CON EDISON | 332 FURMAN ST | NNE 1/8 - 1/4 (0.166 mi.) | AV366 | 828 |
| CONSOLIDATED EDISON | MH330-FURMAN ST | NNE 1/8 - 1/4 (0.170 mi.) | AV372 | 838 |
| ***MTA NYCT WILLOW PLACE FAN PLAN*** | ***58 JORALEMON ST*** | ***NE 1/8 - 1/4 (0.182 mi.)*** | ***AY381*** | ***871*** |
| NYCDEP | BALTIC ST & HENRY ST | ESE 1/8 - 1/4 (0.188 mi.) | BA387 | 878 |
| ***UNIVERSITY HOSPITAL OF BROOKLY*** | ***340 HENRY ST*** | ***ENE 1/8 - 1/4 (0.189 mi.)*** | ***AW388*** | ***879*** |
| ***NYC BD OF ED - PUBLIC SCHOOL 2*** | ***425 HENRY ST*** | ***ESE 1/8 - 1/4 (0.189 mi.)*** | ***BA391*** | ***898*** |
| PLASTIFORM PACKAGING INC | 42 DELEVAN ST | SSW 1/8 - 1/4 (0.191 mi.) | BE408 | 938 |
| NYNEX | COLUMBIA ST & COLES ST | S 1/8 - 1/4 (0.202 mi.) | BF425 | 972 |
| LONG ISLAND COLLEGE HOSPITAL | 112 PACIFIC ST | ENE 1/8 - 1/4 (0.203 mi.) | BC426 | 973 |
| CON EDISON | HICKS ST & JORALEMAN ST | NE 1/8 - 1/4 (0.203 mi.) | AY428 | 976 |
| ***LADYZINSKI JOHN*** | ***44 GRACE CT*** | ***NE 1/8 - 1/4 (0.216 mi.)*** | ***BJ447*** | ***1014*** |
| GRACE CHURCH | 254 HICKS ST | NE 1/8 - 1/4 (0.220 mi.) | AY460 | 1036 |
| CON EDISON | 119 PACIFIC ST | ENE 1/8 - 1/4 (0.220 mi.) | BC461 | 1040 |
| CON EDISON | 120 PACIFIC ST | ENE 1/8 - 1/4 (0.221 mi.) | BC462 | 1042 |
| CONSOLIDATED EDISON | V2218 22 DELAVAN ST | SSW 1/8 - 1/4 (0.223 mi.) | BE465 | 1047 |
| CON EDISON | 164 PRESIDENT ST | SSE 1/8 - 1/4 (0.224 mi.) | BO468 | 1051 |
| CON EDISON | VERONA ST & RICHARDS ST | SSW 1/8 - 1/4 (0.229 mi.) | BP472 | 1054 |
| CON EDISON | 228 SACKETT ST | SE 1/8 - 1/4 (0.230 mi.) | 474 | 1058 |
| ***RANDEX CLEANERS*** | ***534 HENRY ST*** | ***SSE 1/8 - 1/4 (0.241 mi.)*** | ***BM485*** | ***1074*** |
| ***TOM RUSSO'S SHOP COLLISIONVILL*** | ***204 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.244 mi.)*** | ***BF491*** | ***1091*** |
| ***TODD SHIPYARDS CORP*** | ***FOOT OF DWIGHT ST*** | ***SSW 1/8 - 1/4 (0.246 mi.)*** | ***BL492*** | ***1097*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***SHOWMAN FABRICATORS INC*** | ***29 IMLAY ST*** | ***0 - 1/8 (0.000 mi.)*** | ***C11*** | ***35*** |
| NYC DEP | SEABRING & VAN BRUNT ST | SSW 0 - 1/8 (0.054 mi.) | U156 | 342 |

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 02/28/2014 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| AMERICAN STEVEDORING INC | 70 HAMILTON AVENUE | SSW 0 - 1/8 (0.055 mi.) | V160 | 347 |

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 02/28/2014 has revealed that there are 4 NJ MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***PORT AUTHORITY BROOKLYN PIERS*** | ***90 COLUMBIA ST*** | ***E 0 - 1/8 (0.005 mi.)*** | ***B46*** | ***145*** |
| ***WATCHTOWER*** | ***FURMAN STREET*** | ***NNE 0 - 1/8 (0.109 mi.)*** | ***AK285*** | ***652*** |
| ***BROOKLYN BATTERY TUNNEL*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT349*** | ***771*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| NYCDEP | SEABRING & VAN BRUNT ST | SSW 0 - 1/8 (0.052 mi.) | U149 | 332 |

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 01/21/2014 has revealed that there are 4 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| WATCHTOWER BIBLE & TRACT(MOVED | 360 FURMAN STREET | NNE 0 - 1/8 (0.109 mi.) | AK286 | 662 |
| BERNIES/COLUMBIA TERRACE LAUND | 134 UNION STREET | S 0 - 1/8 (0.118 mi.) | AM302 | 696 |
| WATCHTOWER BIBLE & TRACT (2-61 | 336-374 FURMAN STREET | NNE 1/8 - 1/4 (0.156 mi.) | AK345 | 763 |
| ***RANDEX CLEANERS*** | ***534 HENRY ST*** | ***SSE 1/8 - 1/4 (0.241 mi.)*** | ***BM485*** | ***1074*** |

NY SPDES: New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

A review of the NY SPDES list, as provided by EDR, and dated 02/25/2014 has revealed that there is 1 NY SPDES site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***TRIBOROUGH BRIDGE & TUNNEL AUT*** | ***160 HAMILTON AVE*** | ***S 1/8 - 1/4 (0.156 mi.)*** | ***AT352*** | ***790*** |

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 03/12/2014 has revealed that there are 81 NY E DESIGNATION sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| LOT 27,TAXBLOCK 597 | 8 VAN BRUNT STREET | 0 - 1/8 (0.000 mi.) | F15 | 43 |
| LOT 3,TAXBLOCK 319 | 181 COLUMBIA STREET | SSE 0 - 1/8 (0.005 mi.) | D47 | 177 |
| LOT 4,TAXBLOCK 319 | 179 COLUMBIA STREET | SSE 0 - 1/8 (0.005 mi.) | D50 | 181 |
| LOT 10,TAXBLOCK 319 | 167 COLUMBIA STREET | SSE 0 - 1/8 (0.005 mi.) | D54 | 185 |
| LOT 11,TAXBLOCK 319 | 165 COLUMBIA STREET | SSE 0 - 1/8 (0.005 mi.) | D55 | 186 |
| LOT 16,TAXBLOCK 319 | 157 COLUMBIA STREET | SSE 0 - 1/8 (0.005 mi.) | D56 | 188 |
| LOT 12,TAXBLOCK 319 | 163 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D58 | 191 |
| LOT 14,TAXBLOCK 319 | 159A COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D59 | 192 |

# EXECUTIVE SUMMARY

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| LOT 15,TAXBLOCK 319 | 159 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D60 | 194 |
| LOT 17,TAXBLOCK 319 | 155 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D61 | 195 |
| LOT 19,TAXBLOCK 319 | 151 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D63 | 197 |
| LOT 18,TAXBLOCK 319 | 153 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D64 | 199 |
| LOT 20,TAXBLOCK 319 | 149 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D65 | 201 |
| LOT 24,TAXBLOCK 319 | 145 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D66 | 202 |
| LOT 25,TAXBLOCK 319 | 143 COLUMBIA STREET | SSE 0 - 1/8 (0.006 mi.) | D67 | 204 |
| LOT 26,TAXBLOCK 319 | 139 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J68 | 205 |
| LOT 29,TAXBLOCK 319 | 133 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J69 | 207 |
| LOT 27,TAXBLOCK 319 | 137 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J70 | 209 |
| LOT 37,TAXBLOCK 319 | 117 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J71 | 210 |
| LOT 30,TAXBLOCK 319 | 131 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J72 | 212 |
| LOT 6,TAXBLOCK 309 | 111 COLUMBIA STREET | ESE 0 - 1/8 (0.006 mi.) | L73 | 213 |
| LOT 28,TAXBLOCK 319 | 135 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J74 | 220 |
| LOT 36,TAXBLOCK 319 | 119 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J75 | 221 |
| LOT 34,TAXBLOCK 319 | 123 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J76 | 223 |
| LOT 32,TAXBLOCK 319 | 127 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J77 | 224 |
| LOT 35,TAXBLOCK 319 | 121 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J78 | 226 |
| LOT 33,TAXBLOCK 319 | 125 COLUMBIA STREET | SE 0 - 1/8 (0.006 mi.) | J79 | 228 |
| LOT 1,TAXBLOCK 319 | 185 COLUMBIA STREET | SSE 0 - 1/8 (0.007 mi.) | M80 | 229 |
| LOT 23,TAXBLOCK 319 | 147 COLUMBIA STREET | SSE 0 - 1/8 (0.007 mi.) | D82 | 231 |
| LOT 22,TAXBLOCK 319 | 147A COLUMBIA STREET | SSE 0 - 1/8 (0.007 mi.) | D83 | 233 |
| ***LOT 1,TAXBLOCK 299*** | ***75 COLUMBIA STREET*** | ***ENE 0 - 1/8 (0.007 mi.)*** | ***B85*** | ***235*** |
| LOT 6,TAXBLOCK 319 | COLUMBIA STREET | SSE 0 - 1/8 (0.013 mi.) | D99 | 253 |
| LOT 8,TAXBLOCK 319 | COLUMBIA STREET | SSE 0 - 1/8 (0.013 mi.) | D100 | 255 |
| LOT 7,TAXBLOCK 319 | COLUMBIA STREET | SSE 0 - 1/8 (0.020 mi.) | D104 | 259 |
| LOT 9,TAXBLOCK 319 | COLUMBIA STREET | SSE 0 - 1/8 (0.020 mi.) | D105 | 261 |
| LOT 5,TAXBLOCK 319 | COLUMBIA STREET | SSE 0 - 1/8 (0.020 mi.) | D107 | 264 |
| LOT 39,TAXBLOCK 319 | 90 KANE STREET | ESE 0 - 1/8 (0.027 mi.) | L113 | 269 |
| LOT 11,TAXBLOCK 299 | 74 CONGRESS STREET | ENE 0 - 1/8 (0.033 mi.) | K126 | 285 |
| LOT 19,TAXBLOCK 352 | 20 CARROLL STREET | SSW 0 - 1/8 (0.045 mi.) | G137 | 305 |
| LOT 20,TAXBLOCK 352 | 22 CARROLL STREET | SSW 0 - 1/8 (0.049 mi.) | G141 | 313 |
| LOT 54,TAXBLOCK 347 | 23 CARROLL STREET | SSW 0 - 1/8 (0.052 mi.) | G142 | 319 |
| LOT 62,TAXBLOCK 319 | 36 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | J143 | 322 |
| LOT 7501,TAXBLOCK 319 | 42 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | J144 | 324 |
| LOT 7503,TAXBLOCK 319 | 20 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | J145 | 326 |
| LOT 55,TAXBLOCK 319 | 26 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | J146 | 327 |
| LOT 49,TAXBLOCK 319 | 16 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | T147 | 329 |
| LOT 50,TAXBLOCK 319 | 18 TIFFANY PLACE | SE 0 - 1/8 (0.052 mi.) | T148 | 330 |
| LOT 42,TAXBLOCK 319 | 2 TIFFANY PLACE | ESE 0 - 1/8 (0.053 mi.) | L150 | 333 |
| ***LOT 16,TAXBLOCK 299*** | ***86 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.056 mi.)*** | ***X173*** | ***379*** |
| LOT 43,TAXBLOCK 299 | 69 WARREN STREET | E 0 - 1/8 (0.058 mi.) | X175 | 383 |
| LOT 1,TAXBLOCK 304 | 85 BALTIC STREET | ESE 0 - 1/8 (0.059 mi.) | Y176 | 389 |
| LOT 9,TAXBLOCK 309 | 86 BALTIC STREET | ESE 0 - 1/8 (0.060 mi.) | Y177 | 392 |
| LOT 10,TAXBLOCK 309 | 88 BALTIC STREET | ESE 0 - 1/8 (0.061 mi.) | Y178 | 395 |
| LOT 3,TAXBLOCK 304 | 88 WARREN STREET | E 0 - 1/8 (0.061 mi.) | X179 | 398 |
| LOT 25,TAXBLOCK 304 | 89 BALTIC STREET | ESE 0 - 1/8 (0.061 mi.) | Y180 | 401 |
| LOT 53,TAXBLOCK 352 | 45 SUMMIT STREET | SSW 0 - 1/8 (0.062 mi.) | Q183 | 407 |
| LOT 24,TAXBLOCK 304 | 91 BALTIC STREET | ESE 0 - 1/8 (0.062 mi.) | Y184 | 411 |
| LOT 11,TAXBLOCK 309 | 92 BALTIC STREET | ESE 0 - 1/8 (0.063 mi.) | Y185 | 414 |
| LOT 23,TAXBLOCK 304 | 93 BALTIC STREET | ESE 0 - 1/8 (0.064 mi.) | Y186 | 417 |
| LOT 4,TAXBLOCK 304 | 92 WARREN STREET | E 0 - 1/8 (0.064 mi.) | X187 | 421 |
| ***LOT 18,TAXBLOCK 299*** | ***90 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.064 mi.)*** | ***X188*** | ***424*** |
| LOT 12,TAXBLOCK 309 | 94 BALTIC STREET | ESE 0 - 1/8 (0.065 mi.) | Y189 | 427 |
| LOT 5,TAXBLOCK 304 | 94 WARREN STREET | E 0 - 1/8 (0.065 mi.) | X192 | 432 |
| LOT 22,TAXBLOCK 304 | 95 BALTIC STREET | ESE 0 - 1/8 (0.065 mi.) | Y193 | 435 |

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***LOT 39,TAXBLOCK 299*** | ***79 WARREN STREET*** | ***E 0 - 1/8 (0.065 mi.)*** | ***X194*** | ***438*** |
| LOT 21,TAXBLOCK 304 | 97 BALTIC STREET | ESE 0 - 1/8 (0.066 mi.) | Y196 | 444 |
| LOT 6,TAXBLOCK 304 | 96 WARREN STREET | E 0 - 1/8 (0.066 mi.) | X197 | 447 |
| LOT 20,TAXBLOCK 304 | 99 BALTIC STREET | ESE 0 - 1/8 (0.067 mi.) | Y198 | 450 |
| LOT 7,TAXBLOCK 304 | 98 WARREN STREET | E 0 - 1/8 (0.067 mi.) | X199 | 453 |
| LOT 8,TAXBLOCK 304 | 100 WARREN STREET | E 0 - 1/8 (0.069 mi.) | X200 | 456 |
| LOT 9,TAXBLOCK 304 | 102 WARREN STREET | E 0 - 1/8 (0.070 mi.) | X202 | 468 |
| ***LOT 16,TAXBLOCK 304*** | ***108 WARREN STREET*** | ***E 0 - 1/8 (0.073 mi.)*** | ***X205*** | ***474*** |
| LOT 10,TAXBLOCK 304 | 109 BALTIC STREET | ESE 0 - 1/8 (0.074 mi.) | Y206 | 477 |
| ***LOT 50,TAXBLOCK 347*** | ***29 CARROLL STREET*** | ***S 0 - 1/8 (0.074 mi.)*** | ***W207*** | ***482*** |
| ***LOT 17,TAXBLOCK 304*** | ***110 WARREN STREET*** | ***E 0 - 1/8 (0.075 mi.)*** | ***Y208*** | ***488*** |
| ***LOT 19,TAXBLOCK 299*** | ***96 CONGRESS STREET*** | ***ENE 0 - 1/8 (0.076 mi.)*** | ***X211*** | ***502*** |
| LOT 52,TAXBLOCK 352 | 55 SUMMIT STREET | SSW 0 - 1/8 (0.084 mi.) | Q227 | 549 |
| LOT 51,TAXBLOCK 352 | 57 SUMMIT STREET | S 0 - 1/8 (0.089 mi.) | AD230 | 557 |
| LOT 50,TAXBLOCK 352 | 59 SUMMIT STREET | S 0 - 1/8 (0.093 mi.) | AD239 | 577 |
| LOT 49,TAXBLOCK 352 | 61 SUMMIT STREET | S 0 - 1/8 (0.098 mi.) | AD248 | 591 |
| LOT 48,TAXBLOCK 352 | 63 SUMMIT STREET | S 0 - 1/8 (0.102 mi.) | AD254 | 603 |

LEAD SMELTERS: A listing of former lead smelter site locations.

A review of the LEAD SMELTERS list, as provided by EDR, and dated 01/29/2013 has revealed that there is 1 LEAD SMELTERS site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ATLAS WHITE METAL CO. | 77 DELEVAN | SSW 1/8 - 1/4 (0.172 mi.) | AX373 | 839 |

US AIRS: The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

A review of the US AIRS list, as provided by EDR, and dated 10/23/2013 has revealed that there are 12 US AIRS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| SOUTH BROOKLYN AUTO BODY | 67 UNION ST | SSW 0 - 1/8 (0.011 mi.) | E94 | 248 |
| AMERICAN STEVEDORING INC - RED | 70 HAMILTON AVE | SSW 0 - 1/8 (0.055 mi.) | V167 | 372 |
| ***ATLANTIC-HICKS ST*** | ***434 HICKS STREET*** | ***ESE 0 - 1/8 (0.081 mi.)*** | ***Y214*** | ***508*** |
| 113-115 UNION STREET BUILDING | 113-115 UNION ST | S 0 - 1/8 (0.102 mi.) | AG252 | 600 |
| SUNY DOWNSTATE MEDICAL CENTER | 339 HICKS ST | ENE 0 - 1/8 (0.104 mi.) | AE275 | 638 |
| 24 JORALEMON ST BUILDING | 24 JORALEMON ST | NNE 1/8 - 1/4 (0.160 mi.) | AQ359 | 819 |
| ***PLASTIFORM PACKAGING INCORPORA*** | ***42 DELEVAN ST*** | ***SSW 1/8 - 1/4 (0.191 mi.)*** | ***BE409*** | ***940*** |
| ***SHELL OIL-S&D SERV STA INC*** | ***112 ATLANTIC AVENUE*** | ***ENE 1/8 - 1/4 (0.193 mi.)*** | ***BC411*** | ***948*** |
| ***LI'S DRY CLEANER*** | ***500 HENRY ST*** | ***SSE 1/8 - 1/4 (0.195 mi.)*** | ***AZ418*** | ***964*** |
| ***HENRY GREEN CLEANERS*** | ***113 PACIFIC STREET*** | ***ENE 1/8 - 1/4 (0.206 mi.)*** | ***BC432*** | ***980*** |
| ***RANDEX CLEANERS*** | ***534 HENRY ST*** | ***SSE 1/8 - 1/4 (0.241 mi.)*** | ***BM485*** | ***1074*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| TUFARO SVCE STA | 225 VAN BRUNT ST | SSW 1/8 - 1/4 (0.150 mi.) | AR340 | 759 |

# EXECUTIVE SUMMARY

## EDR HIGH RISK HISTORICAL RECORDS

### *EDR Exclusive Records*

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 36 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 115 VAN BRUNT ST | SSW 0 - 1/8 (0.002 mi.) | E26 | 79 |
| Not reported | 129 VAN BRUNT ST | SSW 0 - 1/8 (0.003 mi.) | E29 | 81 |
| Not reported | 63 UNION ST | SSW 0 - 1/8 (0.004 mi.) | E33 | 84 |
| Not reported | 170 VAN BRUNT ST | SSW 0 - 1/8 (0.004 mi.) | I36 | 96 |
| Not reported | 70 DEGRAW ST | S 0 - 1/8 (0.007 mi.) | N81 | 231 |
| Not reported | 65 UNION ST | SSW 0 - 1/8 (0.008 mi.) | E90 | 245 |
| Not reported | 56 UNION ST | SSW 0 - 1/8 (0.008 mi.) | E91 | 246 |
| Not reported | 67 UNION ST | SSW 0 - 1/8 (0.011 mi.) | E96 | 251 |
| Not reported | 77 SACKETT ST | S 0 - 1/8 (0.054 mi.) | N158 | 347 |
| Not reported | 100 SACKETT ST | S 0 - 1/8 (0.056 mi.) | S174 | 383 |
| Not reported | 434 HICKS ST | ESE 0 - 1/8 (0.081 mi.) | Y215 | 510 |
| Not reported | 103 UNION ST | S 0 - 1/8 (0.082 mi.) | R226 | 549 |
| Not reported | 59 SUMMIT ST | S 0 - 1/8 (0.089 mi.) | W231 | 563 |
| Not reported | 120 HAMILTON AVE | SSW 0 - 1/8 (0.090 mi.) | V235 | 567 |
| Not reported | 100 UNION ST | S 0 - 1/8 (0.100 mi.) | AG250 | 599 |
| Not reported | 113 HAMILTON AVE | SSW 0 - 1/8 (0.105 mi.) | AD280 | 647 |
| Not reported | 45 SEABRING ST | SSW 0 - 1/8 (0.105 mi.) | AC281 | 648 |
| Not reported | 120 UNION ST | S 0 - 1/8 (0.109 mi.) | AG288 | 665 |
| Not reported | 9 WOODHULL ST | S 0 - 1/8 (0.120 mi.) | AO304 | 703 |
| Not reported | 547 HICKS ST | SSE 0 - 1/8 (0.123 mi.) | AN311 | 713 |
| Not reported | 288 COLUMBIA ST | S 1/8 - 1/4 (0.127 mi.) | AD317 | 718 |
| Not reported | 15 WOODHULL ST | S 1/8 - 1/4 (0.132 mi.) | AO320 | 720 |
| Not reported | 20 COLUMBIA PL | NE 1/8 - 1/4 (0.144 mi.) | AQ328 | 743 |
| Not reported | 167 UNION ST | SSE 1/8 - 1/4 (0.155 mi.) | AN344 | 763 |
| Not reported | 112 ATLANTIC AVE | ENE 1/8 - 1/4 (0.193 mi.) | BC413 | 954 |
| Not reported | 360 COLUMBIA ST | S 1/8 - 1/4 (0.204 mi.) | BF429 | 978 |
| Not reported | 14 COLES ST | S 1/8 - 1/4 (0.207 mi.) | BF434 | 982 |
| Not reported | 640 HICKS ST | S 1/8 - 1/4 (0.211 mi.) | BI438 | 998 |
| Not reported | 74 VERONA ST | SSW 1/8 - 1/4 (0.211 mi.) | AX439 | 998 |
| Not reported | 276 HENRY ST | ENE 1/8 - 1/4 (0.213 mi.) | BK441 | 1001 |
| Not reported | 2 DWIGHT ST | S 1/8 - 1/4 (0.232 mi.) | BF478 | 1062 |
| Not reported | 134 ATLANTIC AVE | ENE 1/8 - 1/4 (0.242 mi.) | BQ489 | 1090 |
| Not reported | 204 HAMILTON AVE | S 1/8 - 1/4 (0.244 mi.) | BF490 | 1091 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 232 VAN BRUNT ST | SSW 1/8 - 1/4 (0.150 mi.) | AR337 | 756 |
| Not reported | 225 VAN BRUNT ST | SSW 1/8 - 1/4 (0.150 mi.) | AR339 | 758 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 278 VAN BRUNT ST | SSW 1/8 - 1/4 (0.208 mi.) | BD435 | 983 |

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 17 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| Not reported | 147 COLUMBIA ST | SSE 0 - 1/8 (0.006 mi.) | D62 | 197 |
| Not reported | 130 UNION ST | S 0 - 1/8 (0.115 mi.) | AM296 | 690 |
| Not reported | 169 SACKETT ST | SSE 0 - 1/8 (0.117 mi.) | AN298 | 692 |
| Not reported | 134 UNION ST | S 0 - 1/8 (0.118 mi.) | AM301 | 696 |
| Not reported | 257 COLUMBIA ST | S 1/8 - 1/4 (0.125 mi.) | AP316 | 717 |
| Not reported | 289 COLUMBIA ST | S 1/8 - 1/4 (0.130 mi.) | AD319 | 719 |
| Not reported | 10 COLUMBIA PL | NE 1/8 - 1/4 (0.154 mi.) | AQ342 | 760 |
| Not reported | 6 COLUMBIA PL | NE 1/8 - 1/4 (0.158 mi.) | AQ356 | 814 |
| Not reported | 162 UNION ST | SSE 1/8 - 1/4 (0.159 mi.) | AU358 | 818 |
| Not reported | 484 HENRY ST | SE 1/8 - 1/4 (0.187 mi.) | AZ383 | 875 |
| Not reported | 416 HENRY ST | ESE 1/8 - 1/4 (0.187 mi.) | BA385 | 877 |
| Not reported | 385 HENRY ST | E 1/8 - 1/4 (0.189 mi.) | BB399 | 918 |
| Not reported | 389 HENRY ST | E 1/8 - 1/4 (0.190 mi.) | BB400 | 919 |
| Not reported | 303 HENRY ST | ENE 1/8 - 1/4 (0.199 mi.) | AS422 | 969 |
| Not reported | 113 PACIFIC ST | ENE 1/8 - 1/4 (0.206 mi.) | BC433 | 982 |
| Not reported | 226 DEGRAW ST | SE 1/8 - 1/4 (0.232 mi.) | AZ476 | 1061 |
| Not reported | 534 HENRY ST | SSE 1/8 - 1/4 (0.241 mi.) | BM486 | 1087 |

**EDR RECOVERED GOVERNMENT ARCHIVES**

***Exclusive Recovered Govt. Archives***

NY RGA LF: The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

A review of the NY RGA LF list, as provided by EDR, has revealed that there are 2 NY RGA LF sites within approximately 0.25 miles of the target property.


| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET, PO BOX | 0 - 1/8 (0.000 mi.) | E13 | 41 |
| WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET | 0 - 1/8 (0.000 mi.) | E17 | 48 |

# EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 20 records.

| Site Name | Database(s) |
|---|---|
| NYS DOT BIN 106539A | PA MANIFEST |
| BELL ATLANTIC-NY | NY MANIFEST |
| CON EDISON | NY MANIFEST |
| CON EDISON | NY MANIFEST |
| BP PRODUCTS OF NORTH AMERICA INC | NY MANIFEST |
| CONSOLIDATED EDISON | NY MANIFEST |
| CON EDISON | NY MANIFEST |
| CON EDISION - MH38210 | RCRA NonGen / NLR, NY MANIFEST |
| CON EDISION - MH 2863 | RCRA NonGen / NLR, NY MANIFEST |
| CON EDISION - V4512 | RCRA NonGen / NLR, NY MANIFEST |
| CON EDISION - V04461 | RCRA NonGen / NLR, NY MANIFEST |
| TR854 | RCRA NonGen / NLR, NY MANIFEST |
| RED HOOK MARINE TERMINAL-PIER 11 | FINDS |
| NYCDEP RED HOOK WATER POLLUTION CO | FINDS |
| US ARMY CORP-RED HOOK FLATS | FINDS |
| US ARMY CORP-RED HOOK CH | FINDS |
| EXIT 34 | NY Spills |
| KINGS HIGHWAY MOBIL | NY Spills |
| BETW/AVE X & | NY Spills |
| 205842; KINGS HWY | NY Spills |


# OVERVIEW MAP - 3929425.11s




| | | | |
|---|---|---|---|
| SITE NAME: | Red Hook | CLIENT: | STV Inc. |
| ADDRESS: | Red Hook<br>Brooklyn NY 11231 | CONTACT: | Doug Glorie |
| | | INQUIRY #: | 3929425.11s |
| LAT/LONG: | 40.6886619345085 / 74.003131736071 | DATE: | May 01, 2014 2:16 pm |

Copyright © 2014 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

# DETAIL MAP - 3929425.11s




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

| | |
|---|---|
| SITE NAME: Red Hook | CLIENT: STV Inc. |
| ADDRESS: Red Hook<br>Brooklyn NY 11231 | CONTACT: Doug Glorie |
| LAT/LONG: 40.6886619345085 / 74.003131736071 | INQUIRY #: 3929425.11s<br>DATE: May 01, 2014 2:19 pm |

Copyright © 2014 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| **STANDARD ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Federal NPL site list*** | | | | | | | | |
| NPL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| Proposed NPL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NPL LIENS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal Delisted NPL site list*** | | | | | | | | |
| Delisted NPL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal CERCLIS list*** | | | | | | | | |
| CERCLIS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FEDERAL FACILITY | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal CERCLIS NFRAP site List*** | | | | | | | | |
| CERC-NFRAP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal RCRA CORRACTS facilities list*** | | | | | | | | |
| CORRACTS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal RCRA non-CORRACTS TSD facilities list*** | | | | | | | | |
| RCRA-TSDF | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal RCRA generators list*** | | | | | | | | |
| RCRA-LQG | 0.250 | | 1 | 0 | NR | NR | NR | 1 |
| RCRA-SQG | 0.250 | | 1 | 5 | NR | NR | NR | 6 |
| RCRA-CESQG | 0.250 | | 6 | 5 | NR | NR | NR | 11 |
| ***Federal institutional controls / engineering controls registries*** | | | | | | | | |
| US ENG CONTROLS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| US INST CONTROL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| LUCIS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Federal ERNS list*** | | | | | | | | |
| ERNS | 0.250 | | 5 | 2 | NR | NR | NR | 7 |
| ***State- and tribal - equivalent CERCLIS*** | | | | | | | | |
| NY SHWS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY VAPOR REOPENED | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal landfill and/or solid waste disposal site lists*** | | | | | | | | |
| NY SWF/LF | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal leaking storage tank lists*** | | | | | | | | |
| NY LTANKS | 0.250 | | 11 | 11 | NR | NR | NR | 22 |
| NY HIST LTANKS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| INDIAN LUST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| ***State and tribal registered storage tank lists*** | | | | | | | | |
| NY TANKS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY UST | 0.250 | | 13 | 14 | NR | NR | NR | 27 |
| NY CBS UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY AST | 0.250 | | 19 | 16 | NR | NR | NR | 35 |
| NY CBS AST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF AST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY CBS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| INDIAN UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FEMA UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal institutional control / engineering control registries*** | | | | | | | | |
| NY ENG CONTROLS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY INST CONTROL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY RES DECL | 0.250 | | 8 | 0 | NR | NR | NR | 8 |
| ***State and tribal voluntary cleanup sites*** | | | | | | | | |
| NY VCP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| INDIAN VCP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal Brownfields sites*** | | | | | | | | |
| NY ERP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY BROWNFIELDS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| **ADDITIONAL ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Local Brownfield lists*** | | | | | | | | |
| US BROWNFIELDS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Local Lists of Landfill / Solid Waste Disposal Sites*** | | | | | | | | |
| ODI | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| DEBRIS REGION 9 | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY SWRCY | 0.250 | | 1 | 0 | NR | NR | NR | 1 |
| NY SWTIRE | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| INDIAN ODI | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Local Lists of Hazardous waste / Contaminated Sites*** | | | | | | | | |
| US CDL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY DEL SHWS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| US HIST CDL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Local Lists of Registered Storage Tanks*** | | | | | | | | |
| NY HIST UST | 0.250 | | 8 | 4 | NR | NR | NR | 12 |
| NY HIST AST | 0.250 | | 9 | 6 | NR | NR | NR | 15 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| ***Local Land Records*** | | | | | | | | |
| LIENS 2 | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY LIENS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***Records of Emergency Release Reports*** | | | | | | | | |
| HMIRS | 0.250 | | 1 | 0 | NR | NR | NR | 1 |
| NY Spills | 0.250 | | 99 | 53 | NR | NR | NR | 152 |
| NY Hist Spills | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY SPILLS 80 | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY SPILLS 90 | 0.250 | | 2 | 0 | NR | NR | NR | 2 |
| ***Other Ascertainable Records*** | | | | | | | | |
| RCRA NonGen / NLR | 0.250 | | 9 | 9 | NR | NR | NR | 18 |
| DOT OPS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| DOD | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FUDS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| CONSENT | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ROD | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| UMTRA | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| US MINES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| TRIS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| TSCA | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FTTS | 0.250 | | 1 | 1 | NR | NR | NR | 2 |
| HIST FTTS | 0.250 | | 1 | 1 | NR | NR | NR | 2 |
| SSTS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ICIS | 0.250 | | 1 | 4 | NR | NR | NR | 5 |
| PADS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| MLTS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| RADINFO | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FINDS | 0.250 | | 33 | 29 | NR | NR | NR | 62 |
| RAATS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| RMP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY HSWDS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY UIC | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MANIFEST | 0.250 | | 18 | 27 | NR | NR | NR | 45 |
| PA MANIFEST | 0.250 | | 1 | 0 | NR | NR | NR | 1 |
| NJ MANIFEST | 0.250 | | 3 | 1 | NR | NR | NR | 4 |
| NY DRYCLEANERS | 0.250 | | 2 | 2 | NR | NR | NR | 4 |
| NY SPDES | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| NY AIRS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY E DESIGNATION | 0.250 | | 81 | 0 | NR | NR | NR | 81 |
| INDIAN RESERV | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| SCRD DRYCLEANERS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY Financial Assurance | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY COAL ASH | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| 2020 COR ACTION | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| EPA WATCH LIST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| LEAD SMELTERS | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| COAL ASH EPA | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PCB TRANSFORMER | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| US FIN ASSUR | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| COAL ASH DOE | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PRP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| US AIRS | 0.250 | | 5 | 7 | NR | NR | NR | 12 |
| **EDR HIGH RISK HISTORICAL RECORDS** | | | | | | | | |
| ***EDR Exclusive Records*** | | | | | | | | |
| EDR MGP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| EDR US Hist Auto Stat | 0.250 | | 20 | 16 | NR | NR | NR | 36 |
| EDR US Hist Cleaners | 0.250 | | 4 | 13 | NR | NR | NR | 17 |
| **EDR RECOVERED GOVERNMENT ARCHIVES** | | | | | | | | |
| ***Exclusive Recovered Govt. Archives*** | | | | | | | | |
| NY RGA LF | 0.250 | | 2 | 0 | NR | NR | NR | 2 |
| NY RGA HWS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

**1** **RED HOOK TERMINAL** **NY LTANKS** **S102960489**
**BIRTH 9A NORTH** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 277342 |
| Spill Number/Closed Date: | 9709712 / 3/4/2003 |
| Spill Date: | 11/20/1997 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Vessel |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 11/20/1997 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Notifier: | Federal Government |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/20/1997 |
| Spill Record Last Update: | 3/4/2003 |
| Spiller Name: | JOE CICCIA |
| Spiller Company: | ZNAMYA OKTYABRYA |
| Spiller Address: | 44 KENDALL ST |
| Spiller City,St,Zip: | NEW HAVEN, CT |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 225431 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TOMASELLO CC R. AUSTIN"3-4-03: Closed Due To The Nature / Extent Of The Spill Report. |
| Remarks: | tank on vessel over flowed spill contained on the deck of the ship - us coast guard sending people to verify |

Material:

| | |
|---|---|
| Site ID: | 277342 |
| Operable Unit ID: | 1056027 |
| Operable Unit: | 01 |
| Material ID: | 328044 |
| Material Code: | 0006 |
| Material Name: | Crude Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 100 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**RED HOOK TERMINAL (Continued)** **S102960489**

Tank Test:

---

**A2** **PIER #7** **NY Spills** **S108466123**
**BROOKLYN PORT AUTHORITY** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 1 of 2 in cluster A**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0612593 |
| Facility Type: | ER |
| DER Facility ID: | 327024 |
| Site ID: | 377474 |
| DEC Region: | 2 |
| Spill Date: | 2/20/2007 |
| Spill Number/Closed Date: | 0612593 / 6/3/2013 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | vszhune |
| Referred To: | Not reported |
| Reported to Dept: | 2/20/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/20/2007 |
| Spill Record Last Update: | 1/31/2014 |
| Spiller Name: | PATRICIA PARVIS |
| Spiller Company: | PIER #7 |
| Spiller Address: | BROOKLYN PORT AUTHORITY |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | PATRICIA PARVIS |
| Contact Phone: | (845) 735-8300 |
| DEC Memo: | Sangesland spoke to Patricia Parvis - consultant for NY City.***** This spill is different from Spill # 0612595 ****Both 0612593 and 0612595 are at the Port Authority Red Hood Container Dock, but this is a 120 acre site. 0612593 deals with "Pier #7" while 0612595 deals with "Building #111"**********120 acre site (Port Authority Red Hook Container Dock) is being sold to the city. As part of this sale, the City hired HDRLMS Consultant to do a Phase 2.Patricia Parvis works for the consultant working for the city. She will finalize the report she is working on and will submit a copy to the DEC. Unknown if this is a shortterm or Longterm case, the Port Authority may deal with the tanks & contamination quickly, or they may sell the land to the city and let the city deal with the problem.2/26/07 - Raphael Ketani. I spoke to Patricia Parvis, project |

**PIER #7 (Continued)** **S108466123**

manager at HGR-LMS (845) 735-8300, ext 275. She said she is the project manager for both the #0612593 site and the #0612595 site. They are part of the same 120 acre parcel of land presently owned by the Port Authority. The parcel of land to be sold is from Pier #7 to Pier #12. She said that the NYC DEP is the lead agency. She said that spill at Pier 7 involves some gasoline USTs and the spill at Bldg. #111 involves 2 4,000 gal. gasoline USTs and 2 4,000 gal. diesel USTs. The 4,000 gal. tanks are still in service, but not the tanks at Pier 7. She said that it looks like the spill comes from the 4,000 gal. tanks, but the people filling the vehicles just drop the hoses on the ground and let what fuel is left inside run out. At the 4,000 gal. tanks, and at Pier #7, there is soil contamination. There is also groundwater contamination of 4200 ppb benzene at the 4,000 gal. tanks. The city is planning to buy the property whether the tanks are removed and the site is cleaned up or not. She said that the Draft EIS is due on March 12, 2007 to the city. There will be a phase II report, but they still have a lot of borings to do. Right now, there is a tenant on site, the stevedors, who the Port Authority people are afraid of. The tenant is supposed to leave in March 2007. I asked Mr. Parvis to send me the lab reports for the soil and water and any other documents they have produced for the site. She said she would send them to me.3/1/07 - Raphael Ketani. Ed Aldrich of the Port Authority (973) 565-7553 called to say that he was the overall manager of the 2 spills (#0612593 and #0612595) for the property that is being transfered to the City. He said that Chris Jones of the Port Authority is involved. He stated that the tenant will be put on notice (the stevedors) that they have to clean up the contamination at their site. Aside from this, the Port Authority will have to do the cleanup at Pier 7.3/6/07 - Raphael Ketani. Today, I received a soil and groundwater data analytical package from Patricia Parvis of HGR-LMS. It contained analyticals for both the Pier 7 and Bldg. 111 sites. There were exceedences of TAGM for various analytes ranging from a little more than the limit to many times the limit. 3/22/07 - Raphael Ketani. I received a letter today from Robert Pruno, Chief Environmental Engineer for the Port Authority. The letter mentioned the Pier #7 site and the Bldg. #111 site. It explained that the Pier #7 site tanks were closed in place and that the Bldg. #111 site is still an active motor fuel facility. As per their lease, American Stevedoring Inc. is responsible for their fuel tanks and the remediation. Further historical information for both facilities will be forthcoming.7/13/07 - Raphael Ketani. I contacted Mr. Eldrich. He said he is still the project manager. He said that this project fell off of his "radar screen." He said he will investigate what is happening up to now and get back to me.10/4/07 - Raphael Ketani. I tried to contact Mr. Aldrich, but could only leave a message. I contacted Ms. Parvis and the on-site supervising engineer for the Port Authority, Christopher Jones (718) 330-2971. Both told me that nothing was happening and nothing had happened since July. Mr. Jones said that the stevedors are responsible for cleaning up their fueling station at Building #111. He added that Mr. Aldrich is going to send a proposal to DEC regarding the work that needs to be done at Pier #7.Mr. Jones e-mailed me the following addresses for correspondence:Arie Van TolManagerThe Port Authority of NY & NJNew York Marine Terminals90 Columbia StreetBrooklyn, NY 11201cc: Robert P. Pruno, P.E. Chief Environmental Engineer The Port Authority of NY & NJ Engineering Department Two Gateway Center Newark, NJ 07102 10/5/07 - Raphael Ketani. Ed Aldrich of the Port Authority called and

**PIER #7 (Continued)** **S108466123**

left a voice mail. He said that they have a proposal from the consultants to do a delineation around Pier #7. It will consist of about 15 borings. A geophysical survey will also be done because there is a utility line running through the site and they found several anomalies during the last geophysical survey. The proposal should be finalized next week. They will start the investigation sometime soon after that. 10/16/07 - Raphael Ketani. I spoke to Mr. Aldrich (973) 565-7553 today. He said that the investigation/delineation plan has been approved and he will e-mail it to me. He said that he expects the geophysical work to start in about 1 week. Each boring will be hand augered the first 6" in order to avoid running into utilities. 10/19/07 - Raphael Ketani. I received the 9/14/07 Pier 7 Gasoline Spill Delineation Scope of Work from Mr. Aldrich by e-mail. I reviewed the work plan and generated some comments. They are:1) manifests for all materials generated by the boring and well installation should be submitted to DEC2) groundwater sampling should take place at least 2 weeks after well development3) the analytical results must be compared to TAGM4) water and soil testing should also be via method 8270 as there may have been historical diesel spills and leaks5) a plan should be submitted regarding the abandonment and closure of any fuel tanksI sent a letter with these 5 comments was sent to Mr. Aldrich. 11/29/07 - Raphael Ketani. I tried to contact Mr. Aldrich, but could only leave a message.1/9/08 - Raphael Ketani. I tried to contact Mr. Aldrich(973) 565-7553, but could only leave a voice mail.1/14/08 - Raphael Ketani. I spoke with Mr. Aldrich today. He said that the project is going to be handled in-house, rather than by an outside consultant. Right now, the prepatory work is taking place (marking proposed boring locations, utility mark-outs, etc.). Drilling and digging will take place in 1 week with submission of the analytical data and a report in 2 months. 4/4/08 - Raphael Ketani. I spoke to Mr. Aldrich today. He said that the samples were taken and they just received the results. He is going to look at the results very soon and send me the tables for the VOCs and SVOCs next week. Nothing else is happening at this time at the site.8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The case manager needs to make followup calls to check on the progress of the investigation and remediation. The DEC needs to receive the investigation report, the analytical resulst, and the revised PBS registration.1/19/12- Zhune visited the site and had a meeting with Mr. Aldrich and four of his associates from Port Authority. 1/19/12- Randy Austin, Veronica Zhune and Bill Glen from PANYNJ had a conference Call at 3:00pm on 01/19/12 to discuss additional work that have to be done to remediate groundwater contamination found in pizometer(PZ2-A)installed by HDR in 2007 adjacent to the 550-gallon UST abondoned in placed(South tank). The Port Authory will send the scope of work which will include the installation of four monitoring wells install on the west side of the tank. They will also investigate the high concentrations of gasoline constitutents found in a soil vapor sample collected adjacent to a historic gasoline UST(North Tank).3/23/12 - Austin - Zhune and Austin received the groundwater investigation workplan from Ed Aldrich of the PANY/NJ. I uploaded the file into eDocs, and Veronica will review the document. - end 4/22/2012- Approved the Suplemental Remedial Investigation Work Plan to install four monitoring wells downgradient the abondoned USTs. 11/20/12-Received a CD with the Suplemental Remedial Investigation Report dated October 2012.Four soil borings

**PIER #7 (Continued)** **S108466123**

were completed onsite. Eight soil samples were collected from the four soil borings. The laboratory results indicate exceedances of CP-51 cleanup levels at two borings P7MW-1(m&p-xtlenes o.41mg/kg, xylene 0.57 mg.kg) and P7-MW4 (1,2,4 trimethylbenzene, 1,3,5 trimethylbenzene 9.0 mg/kg, ethylbenzene 3.4 mg/kg, 0-xylene 5.5 mg/kg, xylene 7.65 mg/kg).No soil exceedances were observed in soil samples collected from soil borings P7-MW-2, and P7-MW-3.Groundwater samples were collected from the four monitoring wells. The results indicate exceedances of water Quality standards at wells P7-MW1(1,2,4 Trimethylbenzene 150 ug/l, 1,3,5 Trimethylbenzene, 4-isopropylbenzene 6.6 ug/l, benzene 390 ug/l, isopropylbenzene 19 ug/l, Methyl-t-buthyl ether 23 ug/l, naphthalene 81 ug/l, n-propylbenzene 35 ug/l, o-xylene 300 ug/l, toluene 110 ug/l, xylene 660 ug/l),P7-MW-3(benzene 9.4 ug/l. m&P-xylene 5.5 ug/l, n-propylbenzene7.9 ug/l, xylene 8.2 ug/l) and P7-MW-4(1,2,4 Trimethylbenzene 16 ug/l, 1,3,5 Trimethylbenzene 14ug/l, benzene 20 ug/l, ethylbenzene 37 ug/l, isopropylbenzene 6.5 ug/l, m&p-xylene 27 ug/l, napgthalene 14 ug/l, n-propylbenzene 16 ug/l, xylene 29 ug/l).-The Port Authority proposed the intallation of seven additional soil borings/monitoring wells. Four monitoring wells will be install upgradient and downgradient of the historic gasoline UST and three monitoring wells will be installed downgradient of the abondoned UST 06/03/13- Received and reviewed the confirmatory Remedial Investigation dated May 2013.Soil.Fourteen soil samples were collected from the seven soil borings. The laboratoy results indicate the presence of VOC-benzene exceeded the limit at P7-MW-7 (0.32 mg/kg.SVOC- were detected at four wells at above the acceptable limit at:P7-MW-7 1-2 benzohenanthracene 6.6 mg/kg, (benzo (a) anthracene 7,7 mg/kg, benzo (a) pyrene 7.9 mg, benzo (b) fluoranthene 9.4 mg/kg, benzo (k)fluoranthene 3.1 mg/kg, dibenzo (a.h)anthracene 1.2 mg/kg amnd indeno (1,2,3-ed) pyrene 5.3mg/kg).P7-MW-8 benzohenanthracene 3.6 mg/kg, (benzo (a) anthracene 3,9 mg/kg, benzo (a) pyrene 3.1 mg, benzo (b) fluoranthene 3.3 mg/kg, benzo (k)fluoranthene 2.0 mg/kg, dibenzo (a.h)anthracene 0.46 mg/kg amnd indeno (1,2,3-ed) pyrene 1.4 mg/kg).P7-MW-9 benzohenanthracene 3.0 mg/kg, (benzo (a) anthracene 2,7 mg/kg, benzo (a) pyrene 3.3 mg, benzo (b) fluoranthene 2.1 mg/kg, benzo (k)fluoranthene 1.8 mg/kg, 0.46 mg/kg and indeno (1,2,3-ed) pyrene 0.83 mg/kg).P7-MW-11 benzohenanthracene 4.9 mg/kg, (benzo (a) anthracene 6.5 mg/kg, benzo (a) pyrene 7.4 mg, benzo (b) fluoranthene 4.5 mg/kg, benzo (k)fluoranthene 2.8 mg/kg, 0.46 mg/kg, indeno (1,2,3-ed) pyrene 0.5 mg/k) and dibenzo (a.h)anthracene 0.46 mg/kg).Groundwater. The seven newly installed groundwater monitoring wells were sampled. The results indicate VOC-Benzene exceedances of the Ambient Water Quality Standards at three wells, P7-MW-7 (5.3 mg/kg), M7-MW-8 3.0 mg/kg, P7-MW-9 2.7 mg/kg.SVOC were detected in the seven wells above their Water Quality standards(1,2-benzophenanthracene, benzo(a)anthracene, benzo(b)anthracene, benzo(b)fluoranthene, benzo(K) fluoranthene and Indeno (1.2.3.-cd)pyrene.The results of the Pier Remedial Investigation inidcated VOCs were detected at low concentration acroos the site with exception of Well PMW-1 located 15 feet southwest of the abondeoned UST. Howerver VOC concentrations at P7-MW-1 are within the natural attenuation parameters and has been fully delineated downgradient (Three wells P7-MW-2, P7-MW-10, P7-MW-11 located 30 to 50 feet downgradient reported no VOCs). Based on the data collected during the investigations of pier 7 and the current groundwater quality no significant impact exist at the previously abandoned 550-gallon UST or historic tank location. Spill

**PIER #7 (Continued)** **S108466123**

CLosed.
Remarks: LAB RESULTS SHOWED CONTAMINATION

Material:
Site ID: 377474
Operable Unit ID: 1135007
Operable Unit: 01
Material ID: 2124897
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**A3** **FOOT OF ATLANTIC AVE AT BROOKLYN PIER #7** **NY Spills** **S103037087**
**N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 2 of 2 in cluster A**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:
Facility ID: 9714448
Facility Type: ER
DER Facility ID: 157495
Site ID: 188583
DEC Region: 2
Spill Date: 3/28/1998
Spill Number/Closed Date: 9714448 / 3/30/1998
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 3/28/1998
CID: 199
Water Affected: BUTTERMILK CHANNEL
Spill Source: Vessel
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/28/1998
Spill Record Last Update: 3/31/1998
Spiller Name: KEVIN NUGENT
Spiller Company: BOUCHARD TRANSPORTATION
Spiller Address: 77 NEWBRIDGE RD
Spiller City,St,Zip: HICKSVILLE, NY 11801-

**FOOT OF ATLANTIC AVE AT (Continued)** **S103037087**

| | |
|---|---|
| Spiller Company: | 001 |
| Contact Name: | KEVIN NUGENT |
| Contact Phone: | (516) 721-7533 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"3/30/98 phone conversation with USCG P.O. Terrel:7 gal total, 2 to water. USCG responded. Miller Environmental Group cleaned. Not reported |
| Remarks: | OPERATORS WERE BLOWING OUT A LINE TO SWITCH FROM DIESEL TO GASTHOUGHT THEY HAD IT ALL CLEAR - WHEN THEY DISCONNECTED THE AIRHOSE RED DYED DIESEL (APPROX 2 GAL) SPILLED INTO WATER |

Material:

| | |
|---|---|
| Site ID: | 188583 |
| Operable Unit ID: | 1060231 |
| Operable Unit: | 01 |
| Material ID: | 325409 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 2 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**B4** **DRUM RUN** **NY Spills** **S111835334**
**90 COLUMBIA ST @ B61 BUS STOP** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 1 of 8 in cluster B**

**Relative: Higher**

**Actual: 9 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1200169 |
| Facility Type: | ER |
| DER Facility ID: | 417203 |
| Site ID: | 462787 |
| DEC Region: | 2 |
| Spill Date: | 4/6/2012 |
| Spill Number/Closed Date: | 1200169 / 4/20/2012 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RMPIPER |
| Referred To: | Not reported |
| Reported to Dept: | 4/6/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**DRUM RUN (Continued)** **S111835334**

| | |
|---|---|
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/6/2012 |
| Spill Record Last Update: | 4/20/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | REBECCA ECONOMOS |
| Contact Phone: | (718) -33-0-2976 |
| DEC Memo: | Called into city DEP - Case #185399728 - city phone contact Janet 212-689-1520DEP Haz Mat will take a look and call back if they take it or DEC takes it.not found. spill closed. |
| Remarks: | Rebecca found a 5 gal container of liquid at the curb at the B61 bus stop. Location is approx 1 block North of 90 Columbia St, Brooklyn. No other landmarks around |

Material:

| | |
|---|---|
| Site ID: | 462787 |
| Operable Unit ID: | 1212886 |
| Operable Unit: | 01 |
| Material ID: | 2210756 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**C5** **REDHOOK TERMINAL** **NY Spills** **S113406095**
**20 IMLAY ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 1 of 10 in cluster C**

**Relative:**
**Higher**

**Actual:**
**7 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1216849 |
| Facility Type: | ER |
| DER Facility ID: | 435547 |
| Site ID: | 480255 |
| DEC Region: | 2 |
| Spill Date: | 3/29/2013 |
| Spill Number/Closed Date: | 1216849 / Not Reported |
| Spill Cause: | Human Error |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 3/29/2013 |
| CID: | Not reported |

**REDHOOK TERMINAL (Continued)** **S113406095**

| | |
|---|---|
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 3/29/2013 |
| Spill Record Last Update: | 4/1/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | HOP OIL |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | DOUG SCHRIMPF |
| Contact Phone: | (631) 774-9681 |
| DEC Memo: | Not reported |
| Remarks: | Spilled during delivery onto blacktop. Cleanup is underway. |

Material:

| | |
|---|---|
| Site ID: | 480255 |
| Operable Unit ID: | 1230046 |
| Operable Unit: | 01 |
| Material ID: | 2227889 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**D6** **PORT AUTHORITY-PIER 9B** **FINDS** **1007803394**
**SEDGWICK STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 1 of 25 in cluster D**

**Relative: Higher**

FINDS:

Registry ID: 110019659216

**Actual: 15 ft.**

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**E7** **45-60 UNION STREET** **NY Spills** **S104495755**
**45-60 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 1 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9408241 |
| Facility Type: | ER |
| DER Facility ID: | 99531 |
| Site ID: | 114087 |
| DEC Region: | 2 |
| Spill Date: | 9/21/1994 |
| Spill Number/Closed Date: | 9408241 / 9/21/1994 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 9/21/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | 9/21/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/28/1994 |
| Spill Record Last Update: | 10/28/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | VENTURA PASSION |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | BACK PRESSURE -CLEANED UP W/SPEEDY DRY |

Material:

| | |
|---|---|
| Site ID: | 114087 |
| Operable Unit ID: | 1005837 |
| Operable Unit: | 01 |
| Material ID: | 377683 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**45-60 UNION STREET (Continued)** **S104495755**

Tank Test:

---

**E8** **MANHOLE #44171** **NY Spills** **S106968026**
**SACKETT ST/VANBRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 2 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0501964 |
| Facility Type: | ER |
| DER Facility ID: | 292489 |
| Site ID: | 346231 |
| DEC Region: | 2 |
| Spill Date: | 5/17/2005 |
| Spill Number/Closed Date: | 0501964 / 7/28/2005 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | GDBREEN |
| Referred To: | Not reported |
| Reported to Dept: | 5/18/2005 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/18/2005 |
| Spill Record Last Update: | 7/28/2005 |
| Spiller Name: | ERT DESK MIKE DAUGHTERY |
| Spiller Company: | MANHOLE #44171 |
| Spiller Address: | SACKETT ST/VANBRUNT ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | ERT DESK MIKE DAUGHTERY |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 158639 5/17/05 - 1406hrs - Sal DiMauro # 44803 Splicer, UG, reports while on location for pre-inspections of 1B63 acct # C7515 found 1 gallon of unknown oil on2000 gallons water in MH44171. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample taken, marked E priority - 24 hr program - chain of custody # CC17516. Env. stop tag # 38143 placed. Structure in middle of street. Clean up pending test results. cn#196615/17/2005 22:27 HRS. -- RECEIVED PCB RESULTS <1.0 PPM, LAB SEQ # 05-04610-001.-- W.W. #17344 --5/18/2005 12:40 HRS. -- BROOKLYN ENV OPS O/S B. BROWN REPORTS HE ORDERED A TANKER FOR 7AM SHIFT DUE TO AMOUNT OF WATER IN STRUCTURE. -- W.W. #17344 --UPDATE: 18-MAY-2005 1201HRS LUGO REQUEST A #9 RED WAGON TO TAKE CARE OF BARE COPPER WIRES IN STRUCTURE. HE ALSO SEE VERY BAD CRABS THATS LOOK UNSAFE. WILL TAKE OFF 24HOUR CLOCK. CALL CIG PIROPATO 12:07 JR78448.18-MAY-2005 19:10 HRS. ENVIR. |

**MANHOLE #44171 (Continued)** **S106968026**

OPER. MECH-A D.LICHTENSTEIN EMP# 08078 REPORTS: ASTORIA TANKER REMOVED APPROX. 1300 GALS OF LIQUID FROM STRUCTURE. ENVIR. CREW THEN DBL. WASHED STRUCTURE WITH BIO-GEN 760. NO SUMP IN STRUCTURE, ENVIR. TAG# 38143 REMOVED. CLEANUP COMPLETE 100%.C.HOGAN 07511.UPDATE 5/19/2005 06:30 HRS PER # 9 OGS G.NELSON # 9 RESPONDED ON 5/18 AND FIXED THE COPPER WIRES AND RETAPED THE CRABS HOLE WAS MADE SAFE. EVESCE.Closed. 7-28-05. George Breen

Remarks: COMING OFF 24 HR CLOCK DUE TO UNSAFE CONDITION IN MANHOLE: CONED # 158639: NO TO 5 QUESTIONS:

Material:

| | |
|---|---|
| Site ID: | 346231 |
| Operable Unit ID: | 1103966 |
| Operable Unit: | 01 |
| Material ID: | 584174 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**C9** **MAN HOLE #57343** **NY Spills** **S103829509**
**IMLAY S T & SUMMIT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 2 of 10 in cluster C**

**Relative: Higher**

**Actual: 8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9815413 |
| Facility Type: | ER |
| DER Facility ID: | 153017 |
| Site ID: | 182625 |
| DEC Region: | 2 |
| Spill Date: | 3/28/1999 |
| Spill Number/Closed Date: | 9815413 / 3/31/1999 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 3/28/1999 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |

**MAN HOLE #57343 (Continued)** **S103829509**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/28/1999 |
| Spill Record Last Update: | 6/19/2000 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | MR THORTON |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"CON ED E2MIS NOTES1/2 pt. unknown oil found on top of 300 gals. water in MH 57343. No sewers or waterways affected. MH print shows no sewer connection, there is a sump in the hole, no joint regulation in hole. Sample taken and put in for a 4-6 hr turnaround. Tag #18916 installed, cleanup pending test results.3-28-99 13:05 Lab Seq# 99-03166 <1.0ppm PCB3-28-99 Cleanup complete and tag removed.Incident closed. |
| Remarks: | about 1/2 pint on 300gals of water in manhole - cleanup pending test results ref #123919 |

Material:

| | |
|---|---|
| Site ID: | 182625 |
| Operable Unit ID: | 1073435 |
| Operable Unit: | 01 |
| Material ID: | 569238 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**10** **RED HOOK CONTAINER TERMINAL** **NY AST U003178573**
**FOOT OF HAMILTON AVENUE** **NY HIST AST N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Relative: Higher**

**Actual: 6 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-603004 |
| Program Type: | PBS |
| UTM X: | 584001.625 |
| UTM Y: | 4504073 |
| Expiration Date: | 2017/05/19 |
| Site Type: | Municipality (Incl. Waste Water Treatment Plants, |

Affiliation Records:

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Mail Contact |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | JUDITH STRINGER |
| Address1: | 90 COLUMBIA STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 676-8481 |
| EMail: | J[INVALID]R@PANYNJ.GOV |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 8/20/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | On-Site Operator |
| Company Name: | RED HOOK CONTAINER TERMINAL |
| Contact Type: | Not reported |
| Contact Name: | RED HOOK CONTAINER TERMINAL, LLC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 875-0777 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 3/14/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | FRANK JORDAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 295-0995 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 3/14/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Facility Owner |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | ENVIRONMENTAL PROGRAM ANALYST |
| Contact Name: | JUDITH STRINGER |
| Address1: | 225 PARK AVENUE SOUTH |
| Address2: | Not reported |
| City: | NEW YORK |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| State: | NY |
| Zip Code: | 10003 |
| Country Code: | 001 |
| Phone: | (718) 435-7000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 8/20/2012 |

Tank Info:

| | |
|---|---|
| Tank Number: | 42197-1 |
| Tank Id: | 52548 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:

G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 01/25/2004 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/27/2004 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 42197-1R |
| Tank Id: | 178757 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 01/25/2004 |
| Capacity Gallons: | 350 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/28/2004 |
| Register: | True |
| Modified By: | CGFREEDM |
| Last Modified: | 07/12/2012 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 42197-2 |
| Tank Id: | 52549 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 01/25/2004 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/27/2004 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 42197-2R |
| Tank Id: | 178758 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 01/25/2004 |
| Capacity Gallons: | 350 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/28/2004 |
| Register: | True |
| Modified By: | CGFREEDM |
| Last Modified: | 07/12/2012 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 42197-3 |
| Tank Id: | 52550 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 01/25/2004 |
| Register: | True |
| Modified By: | NRLOMBAR |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Last Modified: 07/27/2004
Material Name: Lube Oil

Tank Number: 42197-3R
Tank Id: 178759
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/25/2004
Capacity Gallons: 350
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/28/2004
Register: True
Modified By: CGFREEDM
Last Modified: 07/12/2012
Material Name: Lube Oil

Tank Number: 42197-4
Tank Id: 52551
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/25/2004
Register: True
Modified By: NRLOMBAR
Last Modified: 07/27/2004
Material Name: Lube Oil

Tank Number: 42197-4R
Tank Id: 178760
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/25/2004
Capacity Gallons: 350
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/28/2004
Register: True
Modified By: CGFREEDM
Last Modified: 07/12/2012
Material Name: Lube Oil

Tank Number: 42197-8
Tank Id: 52554
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/27/2004 |
| Material Name: | Waste Oil/Used Oil |

| | |
|---|---|
| Tank Number: | 42197-C |
| Tank Id: | 52553 |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 01/25/2004 |
| Capacity Gallons: | 350 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/28/2004 |
| Register: | True |
| Modified By: | KAKYER |
| Last Modified: | 08/20/2012 |
| Material Name: | Waste Oil/Used Oil |

| | |
|---|---|
| Tank Number: | 42197-UO |
| Tank Id: | 52552 |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Equipment Records:
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 01/25/2004 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/28/2004 |
| Register: | True |
| Modified By: | KAKYER |
| Last Modified: | 08/20/2012 |
| Material Name: | Waste Oil/Used Oil |

| | |
|---|---|
| Tank Number: | B621307 |
| Tank Id: | 220803 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:
L00 - Piping Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 08/28/2004 |
| Capacity Gallons: | 350 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | KAKYER |
| Last Modified: | 08/20/2012 |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Material Name: Lube Oil

Tank Number: B621308
Tank Id: 220802
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/28/2004
Capacity Gallons: 350
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 08/20/2012
Material Name: Lube Oil

Tank Number: B621309
Tank Id: 220804
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

Pipe Model: Not reported
Install Date: 08/24/2004
Capacity Gallons: 350
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 08/20/2012
Material Name: Lube Oil

Tank Number: B621310
Tank Id: 220805
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/28/2004
Capacity Gallons: 350
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 08/20/2012
Material Name: Lube Oil

HIST AST:

PBS Number: 2-603004
SWIS Code: 6101
Operator: AMERICAN STEVEDORING, INC.
Facility Phone: (718) 875-0777
Facility Addr2: Not reported
Facility Type: OTHER
Emergency: FRANK GODLEWSKI
Emergency Tel: (718) 875-0777
Old PBSNO: Not reported
Date Inspected: Not reported

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | THE PORT AUTHORITY OF NY & NJ |
| Owner Address: | 1 WORLD TRADE CENTER |
| Owner City,St,Zip: | NEW YORK, NY 10048 |
| Federal ID: | Not reported |
| Owner Tel: | (212) 435-7000 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | CHRISTOPHER JONES |
| Mailing Name: | THE PORT AUTHORITY OF NY & NJ |
| Mailing Address: | 90 COLUMBIA STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11201 |
| Mailing Telephone: | (718) 330-2976 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 02/01/1999 |
| Expiration: | 05/19/2002 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 18825 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 42197-1 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 04 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-2 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 04 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-3 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 04 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-4 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 04 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-8 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | None |
| Pipe Type: | NONE |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 00 |
| Dispenser Method: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

| | |
|---|---|
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-C |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | None |
| Pipe Type: | NONE |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 00 |
| Dispenser Method: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 42197-UO |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | None |
| Pipe Type: | NONE |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | None |
| Leak Detection: | 00 |
| Overfill Protection: | 00 |
| Dispenser Method: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |

**RED HOOK CONTAINER TERMINAL (Continued)** **U003178573**

SPDES Number: Not reported
Lat/Long: Not reported

---

**C11** **SHOWMAN FABRICATORS INC** **NY MANIFEST 1009225593**
**29 IMLAY ST** **NY Spills N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 3 of 10 in cluster C**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYR000054684 |
| Country: | USA |
| Mailing Name: | SHOWMAN FABRICATORS |
| Mailing Contact: | P IOCOLANO |
| Mailing Address: | 4722 PEARSON PLACE |
| Mailing Address 2: | Not reported |
| Mailing City: | LONG ISLAND CITY |
| Mailing State: | NY |
| Mailing Zip: | 11101 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-935-9899 |

| | |
|---|---|
| Document ID: | NYC4625100 |
| Manifest Status: | Not reported |
| Trans1 State ID: | ILD984908202 |
| Trans2 State ID: | MOD095038998 |
| Generator Ship Date: | 05/14/1998 |
| Trans1 Recv Date: | 05/14/1998 |
| Trans2 Recv Date: | 05/22/1998 |
| TSD Site Recv Date: | 05/23/1998 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000054684 |
| Trans1 EPA ID: | KYD053348108 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYAM6252 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00476 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 98 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | MAD039322250 |
| Generator Ship Date: | 2011-10-07 |
| Trans1 Recv Date: | 2011-10-07 |
| Trans2 Recv Date: | 2011-10-12 |
| TSD Site Recv Date: | 2011-10-14 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |

**SHOWMAN FABRICATORS INC (Continued)** **1009225593**

| | |
|---|---|
| Generator EPA ID: | NYR000054684 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHD000816629 |
| Waste Code: | Not reported |
| Quantity: | 400.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2011 |
| Manifest Tracking Num: | 004796423FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | MAD039322250 |
| Generator Ship Date: | 2011-12-16 |
| Trans1 Recv Date: | 2011-12-16 |
| Trans2 Recv Date: | 2011-12-21 |
| TSD Site Recv Date: | 2011-12-22 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000054684 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHD000816629 |
| Waste Code: | Not reported |
| Quantity: | 500.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2011 |
| Manifest Tracking Num: | 004867569FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |

**SHOWMAN FABRICATORS INC (Continued)** **1009225593**

| | |
|---|---|
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |
| | |
| EPA ID: | NYD000054684 |
| Country: | USA |
| Mailing Name: | SHOWMAN FABRICATORS INC |
| Mailing Contact: | RICHARD IOCOLANO |
| Mailing Address: | 29 IMLAY ST |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11231 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-935-9899 |
| | |
| Document ID: | NYC4625100 |
| Manifest Status: | Not reported |
| Trans1 State ID: | ILD984908202 |
| Trans2 State ID: | MOD095038998 |
| Generator Ship Date: | 05/14/1998 |
| Trans1 Recv Date: | 05/14/1998 |
| Trans2 Recv Date: | 05/22/1998 |
| TSD Site Recv Date: | 05/23/1998 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000054684 |
| Trans1 EPA ID: | KYD053348108 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYAM6252 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00476 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 98 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | MAD039322250 |
| Generator Ship Date: | 2011-10-07 |
| Trans1 Recv Date: | 2011-10-07 |
| Trans2 Recv Date: | 2011-10-12 |
| TSD Site Recv Date: | 2011-10-14 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000054684 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHD000816629 |
| Waste Code: | Not reported |

**SHOWMAN FABRICATORS INC (Continued)** **1009225593**

| | |
|---|---|
| Quantity: | 400.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2011 |
| Manifest Tracking Num: | 004796423FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | MAD039322250 |
| Generator Ship Date: | 2011-12-16 |
| Trans1 Recv Date: | 2011-12-16 |
| Trans2 Recv Date: | 2011-12-21 |
| TSD Site Recv Date: | 2011-12-22 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000054684 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHD000816629 |
| Waste Code: | Not reported |
| Quantity: | 500.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2011 |
| Manifest Tracking Num: | 004867569FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

**SHOWMAN FABRICATORS INC (Continued)** **1009225593**

SPILLS:

| | |
|---|---|
| Facility ID: | 1208335 |
| Facility Type: | ER |
| DER Facility ID: | 425676 |
| Site ID: | 471397 |
| DEC Region: | 2 |
| Spill Date: | 11/1/2012 |
| Spill Number/Closed Date: | 1208335 / 4/4/2013 |
| Spill Cause: | Storm |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 11/1/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/1/2012 |
| Spill Record Last Update: | 4/4/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | HURRICANE SANDY |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | KHEN |
| Contact Phone: | 6467632597 |
| DEC Memo: | Hurricane Sandy related. |
| Remarks: | Diesel on roadway and sidewalk anonymous report from 311 |

Material:

| | |
|---|---|
| Site ID: | 471397 |
| Operable Unit ID: | 1221254 |
| Operable Unit: | 01 |
| Material ID: | 2219895 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**C12** **TM #1747** **NY Spills** **S104509948**
**IMLAY ST/SUMMIT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 4 of 10 in cluster C**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9912998 |
| Facility Type: | ER |
| DER Facility ID: | 251280 |
| Site ID: | 311455 |
| DEC Region: | 2 |
| Spill Date: | 2/15/2000 |
| Spill Number/Closed Date: | 9912998 / 2/27/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 2/15/2000 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/15/2000 |
| Spill Record Last Update: | 2/28/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | STEVEN ROMERO |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" |
| Remarks: | ABOVE MATERIAL DISCOVERED ONTOP OF 50 GALLONS OF WATER AT ABOVE LOCATION. AMOUNT DESCRIBED AS A SHEEN. SAMPLE TAKEN AND CLEANUPIS PENDING TEST RESULTS. NO CALL BACK REQEUSTED . CON ED #129988. |

Material:

| | |
|---|---|
| Site ID: | 311455 |
| Operable Unit ID: | 1087521 |
| Operable Unit: | 01 |
| Material ID: | 569088 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**TM #1747 (Continued)** **S104509948**

Tank Test:

---

**E13** **WILLIAMSBURGH PAPER STOCK CO.** **NY RGA LF** **S114962940**
**51 UNION STREET, PO BOX 470** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 3 of 18 in cluster E**

**Relative: Higher**

RGA LF:

| | | |
|---|---|---|
| 1999 | WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET, PO BOX 470 |

**Actual: 11 ft.**

---

**C14** **SHOWMAN FABRICATORS** **RCRA-CESQG** **1001224252**
**29 IMLAY ST** **FINDS** **NYR000054684**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 5 of 10 in cluster C**

**Relative: Lower**

**Actual: 5 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | SHOWMAN FABRICATORS |
| Facility address: | 29 IMLAY ST<br>BROOKLYN, NY 112311336 |
| EPA ID: | NYR000054684 |
| Mailing address: | IMLAY ST<br>BROOKLYN, NY 11231 |
| Contact: | RICHARD IOCOLANO |
| Contact address: | IMLAY ST<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | (718) 935-9899 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Land type: | Facility is not located on Indian land. Additional information is not known. |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | E REBELLINO & D INCATALUPO |
| Owner/operator address: | 313 BUTLER ST |

**SHOWMAN FABRICATORS (Continued)** **1001224252**

BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 858-5555
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: E REBELLINO & D INCATALUPO
Owner/operator address: 313 BUTLER ST
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 858-5555
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: SHOWMAN FABRICATORS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/11/1998
Facility name: SHOWMAN FABRICATORS
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/19/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004543138

**SHOWMAN FABRICATORS (Continued)** **1001224252**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**F15** **LOT 27,TAXBLOCK 597** **NY E DESIGNATION** **S108075254**
**8 VAN BRUNT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 1 of 3 in cluster F**

**Relative: Higher**

**Actual: 10 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 27 |
| E-No: | E-110 |
| Effective Date: | 1/30/2002 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 00DME013K |
| Ulurp Number: | 020047 ZMK |
| Zoning Map No: | 16a |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 3.02 |
| Census Block: | 1009 |
| School District: | 15 |
| City Council District: | 33 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1/R5 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | MX-5 |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1/R5/MX-5 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | PACE, PAT |
| Lot Area: | 000001725 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |

**LOT 27,TAXBLOCK 597 (Continued)** **S108075254**

| | |
|---|---|
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0025.00 |
| Lot Depth: | 0069.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000011790 |
| Total Assessed Value: | 00000011790 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.25 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3005970027 |
| Condominium Number: | 00000 |
| Census Tract 2: | 000302 |
| X Coordinate: | 0980165 |
| Y Coordinate: | 0185567 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 019 |
| Tax Map: | 30207 |
| E Designation No: | E-110 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**16** **PORT AUTHORITY -BUILDING #111** **NY Spills** **S108466125**
**FOOT OF HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0612595 |
| Facility Type: | ER |
| DER Facility ID: | 327026 |
| Site ID: | 377476 |
| DEC Region: | 2 |

**PORT AUTHORITY -BUILDING #111 (Continued)** **S108466125**

| | |
|---|---|
| Spill Date: | 2/20/2007 |
| Spill Number/Closed Date: | 0612595 / Not Reported |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | vszhune |
| Referred To: | Not reported |
| Reported to Dept: | 2/20/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 2/20/2007 |
| Spill Record Last Update: | 8/14/2013 |
| Spiller Name: | PATRICIA PARVIS |
| Spiller Company: | BUILDING #111 |
| Spiller Address: | FOOT OF HAMILTON AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | PATRICIA PARVIS |
| Contact Phone: | (845) 735-8300 |
| DEC Memo: | Sangesland spoke to Patricia Parvis - consultant for NY City.***** This spill is different from Spill # 0612593 ****Both 0612593 and 0612595 are at the Port Authority Red Hood Container Dock, but this is a 120 acre site. 0612593 deals with "Pier #7" while 0612595 deals with "Building #111"**********120 acre site (Port Authority Red Hook Container Dock) is being sold to the city. As part of this sale, the City hired HDRLMS Consultant to do a Phase 2.They found soil and ground water contamination aroundTwo 4,000 gal gasoline tanks and Two 4,000 gal diesel tanks buried on the site.Patricia Parvis works for the consultant working for the city. She will finalize the report she is working on and will submit a copy to the DEC. Unknown if this is a shortterm or Longterm case, the Port Authority may deal with the tanks & contamination quickly, or they may sell the land to the city and let the city deal with the problem.2/26/07 - Raphael Ketani. I spoke to Patricia Parvis, project manager at HGR-LMS (845) 735-8300, ext 275. She said she is the project manager for both the #0612593 site and the #0612595 site. They are part of the same 120 acre parcel of land presently owned by the Port Authority. The parcel of land to be sold is from Pier #7 to Pier #12. She said that the NYC DEP is the lead agency. She said that the spill at Pier 7 involves some gasoline USTs and the spill at Bldg. #111 involves 2 4,000 gal. gasoline USTs and 2 4,000 gal. diesel USTs. The 4,000 gal. tanks are still in service, but not the tanks at Pier 7. She said that it looks like the spill comes from the 4,000 gal. tanks, but the people filling the vehicles just drop the hoses on the ground and let what fuel is left inside run out. At the 4,000 gal. tanks, and at Pier #7, there is soil contamination. There is also groundwater contamination of 4200 ppb benzene at the 4,000 |

**PORT AUTHORITY -BUILDING #111 (Continued)** **S108466125**

gal. tanks. The city is planning to buy the property whether the tanks are removed and the site is cleaned up or not. She said that the Draft EIS is due on March 12, 2007 to the city. There will be a phase II report, but they still have a lot of borings to do. Right now, there is a tenant on site, the stevedors, who the Port Authority people are afraid of. The tenant is supposed to leave in March 2007. I asked Mr. Parvis to send me the lab reports for the soil and water and any other documents they have produced for the site. She said she would send them to me.3/1/07 - Raphael Ketani. Ed Aldrich of the Port Authority (973) 565-7553 called to say that he was the overall manager of the 2 spills (#0612593 and #0612595) for the property that is being transfered to the City. He said that Chris Jones of LMS is involved. He stated that the tenant will be put on notice (the stevedors) that they have to clean up the contamination at their site. Aside from this, the Port Authority will have to do the cleanup at Pier 7.3/6/07 - Raphael Ketani. Today, I received a soil and groundwater data analytical package from Patricia Parvis of HGR-LMS. It contained analyticals for both the Pier 7 and Bldg. 111 sites. There were exceedences of TAGM for various analytes ranging from a little more than the limit to many times the limit.3/22/07 - Raphael Ketani. I received a letter today from Robert Pruno, Chief Environmental Engineer for the Port Authority. The letter mentioned the Pier #7 site and the Bldg. #111 site. It explained that the Pier #7 site tanks were closed in place and that the Bldg. #111 site is still an active motor fuel facility. As per their lease, American Stevedoring Inc. is responsible for their fuel tanks and the remediation. Further historical information for both facilities will be forthcoming.7/13/07 - Raphael Ketani. I contacted Mr. Aldrich. He said he is still the project manager. He said that this project fell off of his "radar screen." He said he will investigate what is happening up to now and get back to me.10/4/07 - Raphael Ketani. I tried to contact Mr. Aldrich, but could only leave a message. I contacted Ms. Parvis and the on-site supervising engineer for the Port Authority, Christopher Jones (718) 330-2971. Both told me that nothing was happening and nothing had happened since July. Mr. Jones said that the stevedors are responsible for cleaning up their fueling station at Building #111. He added that Mr. Aldrich is going to send a proposal to DEC regarding the work that needs to be done at Pier #7.Mr. Jones e-mail me the Port Authority contact for correspondence: Sabato CatuciiPresident & CEOAmerican Stevedoring, Inc.Red Hook Container Terminal70 Hamilton AvenueBrooklyn, NY 11231cc: Graeme Cooper American Stevedoring, Inc. 138 Marsh Street Port Newark, NJ 07114 A standard CSL was sent to Mr. Catucii and Mr. Cooper with a copy to Christopher Jones of the Port Authority.10/18/07 - Raphael Ketani. Mr. Jones called and said that he received a copy of the letter to Mr. Catucii and Mr. Cooper. He said that the fuel tanks are registered as case #2-603004. He said that the registration expired in 5/07, but that he believes the status of the tanks is the same and the number of tanks is the same. He said the Port Authority has the responsibility to register the tanks.10/23/07 - Raphael Ketani. Graeme Cooper of American Stevedoring Inc. (ASI) called to state that the Port Authority is going to send ASI a copy of the lease agreement that either states that ASI is responsible for the cleanup or that the Port Authority is responsible. He is waiting on this document before starting any investigations. Mr. Cooper also asked for more time, about 2 weeks, to send in the documentation regarding any contamination at the site. I told him this will be alright.11/29/07 -

**PORT AUTHORITY -BUILDING #111 (Continued)** **S108466125**

Raphael Ketani. Mr. Jones of the PA called to ask whether DEC had received any documents regarding the site investigation plan. I told him that we hadn't. He said that he will contact Mr. Cooper (work (973) 522-0999, ext 213; cell (914) 441-9949) and tell him that ASI is responsible for investigating and cleaning up the site. I tried to contact Mr. Cooper, but could only leave a message.Mr. Cooper called me back. He said that his legal staff submitted some documents to the Port Authority in response to their submission of the past lease agreement. 12/31/07 - Raphael Ketani. I received a copy of a letter that R.M. Larraabee, Director, Port Commerce Department, the Port Authority of NY & NJ, had sent to Mr. Catucci of ASI. The letter requested that ASI take action to investigate and remediate the underground gasoline release. The letter also stated that DEC had determined that ASI was the responsible party and that, under the lease agreement with the PA, ASI must respond in writing by January 2, 2008 to the PA and submit a corrrective action plan.1/4/08 - Raphael Ketani. Mr. Cooper and Matt Yates, Director of Commercial and Governmental Affairs (917) 709-0461, called to update DEC as to what is in the works for investigating the site. They explained to me in a long phone conference call that ASI is starting to move foreward to obtain the services of an environmental company. I told them that some historical information will have to be collected about the site. I also stated that the fuel systems should be tested, and that soil samples, groundwater and open marine water samples must be collected. They said that they understood. I told them to sit down with the environmental company's project manager and work out a plan of action. I added that DEC needs to see the plan before work commences so that everyone can be in agreement with what is scheduled to take place and so that DEC can comment, if necessary, on the plan. They said that DEC will definitely get an investigation plan. They said that they will give me another update in about two weeks.1/18/08 - Raphael Ketani. I spoke to Paul Myer of Delta Consultants (914) 765-8806. He said he is the consultant for the site. I explained the site conditions to him. He said that he will sit down with ASI, come up with a preliminary investigation plan, and submit it to DEC. 4/4/08 - Raphael Ketani. I tried to contact Mr. Myer, but could only leave a message. 4/7/08 - Raphael Ketani. Mr. Myer (914) 469-6812 called and left a message. He said that he thought it had been agreed upon that the Port Authority would take responsibility for the investigation. He said he will check on the situation and get back to me in a couple of days.8/18/08 - Raphael Ketani. The case is being prepared for transfer due to a case realignment within the unit. The case manager needs to make followup calls to check on the progress of the investigation and remediation. The DEC needs to receive the investigation/remediation report and the revised PBS registration.09/10/09- Zhune called Mr. Cooper from ASI. he said they pushed back againts the PA. It's the PA's responsibility since they own the equipment. ASI operates the terminal but equipment belongs to the PA. The equipment are in the ground.He said call Mr. Jones from PA (718) 330-2971.09/10/09- Zhune called Mr. Jones could not get him. Left a message.03/4/13- Zhune spoke to Ed Aldrich from the Engineering Department at the Por Authority and he said they released the tenant the responsiblity to remediate the contamination. they are preparing the proposal and will send it to the Por Commerce of the Port Authority (responsible party) for aproval. Once they have approved the proposal, they will send the work plan within two weeks to the DEC for approval.08/12/13- The work plan for Building 111 was

**PORT AUTHORITY -BUILDING #111 (Continued)** **S108466125**

received and approved.
Remarks: TANK LEAK

Material:
Site ID: 377476
Operable Unit ID: 1135009
Operable Unit: 01
Material ID: 2124899
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**E17** **WILLIAMSBURGH PAPER STOCK CO.** **NY RGA LF** **S114962941**
**51 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 4 of 18 in cluster E**

**Relative: Higher**

RGA LF:

| | | |
|---|---|---|
| 2006 | WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET |
| 2005 | WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET |
| 2004 | WILLIAMSBURGH PAPER STOCK CO. | 51 UNION STREET |

**Actual: 11 ft.**

---

**C18** **20TH CENTURY RECYCLING - 170 VAN BRUNT** **FINDS** **1007779900**
**170 VAN BRUNT STREET (AT BROWNE STREET)** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 6 of 10 in cluster C**

**Relative: Higher**

FINDS:

Registry ID: 110019423621

**Actual: 6 ft.**

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**C19** **MANHOLE 57347** **NY Spills** **S104509881**
**SUMMIT ST & EMLAY** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 7 of 10 in cluster C**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9912922 |
| Facility Type: | ER |
| DER Facility ID: | 246224 |
| Site ID: | 304827 |
| DEC Region: | 2 |
| Spill Date: | 2/13/2000 |
| Spill Number/Closed Date: | 9912922 / 2/27/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 2/13/2000 |
| CID: | 199 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/13/2000 |
| Spill Record Last Update: | 2/28/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | TONY LOPEZ |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" |
| Remarks: | 1 pt of unk oil found on 30 gal of water at location - cleanup after samples come back - con ed spill 129964 |

Material:

| | |
|---|---|
| Site ID: | 304827 |
| Operable Unit ID: | 1091639 |
| Operable Unit: | 01 |
| Material ID: | 294783 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**MANHOLE 57347 (Continued)** **S104509881**

Tank Test:

---

**E20** **WILLIAMSBURGH PAPER STOCK CO.** **NY SWRCY** **S104075735**
**51 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 5 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SWRCY:

| | |
|---|---|
| Region: | 2 |
| Facility Address 2: | Not reported |
| Phone Number: | 7188758382 |
| Owner Type: | Private |
| Owner Name: | Robert Scala |
| Owner Address: | PO Box 470 |
| Owner Address 2: | Not reported |
| Owner City,St,Zip: | Brooklyn, NY 11231 |
| Owner Email: | Not reported |
| Owner Phone: | 7188758382 |
| Contact Name: | Not reported |
| Contact Address: | Not reported |
| Contact Address 2: | Not reported |
| Contact City,St,Zip: | Not reported |
| Contact Email: | Not reported |
| Contact Phone: | Not reported |
| Activity Desc: | RHRF - registration |
| Activity Number: | [24M79] |
| Active: | Yes |
| East Coordinate: | 584056 |
| North Coordinate: | 4504283 |
| Accuracy Code: | 4.3 - Utilization of Digital Orthophoto Quads |
| Regulatory Status: | Registration |
| Permit #: | 24M79R |
| Auth. Date: | Not reported |
| Expiration Date: | Not reported |
| Waste Types: | Not reported |

---

**F21** **300 GAL OIL IN TM #1420** **NY Spills** **S108638491**
**DEGRAW & VANBRUNT STREETS** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 2 of 3 in cluster F**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0703565 |
| Facility Type: | ER |
| DER Facility ID: | 332984 |
| Site ID: | 383533 |
| DEC Region: | 2 |
| Spill Date: | 6/27/2007 |
| Spill Number/Closed Date: | 0703565 / 7/23/2007 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |

**300 GAL OIL IN TM #1420 (Continued)** **S108638491**

| | |
|---|---|
| Investigator: | gdbreen |
| Referred To: | Not reported |
| Reported to Dept: | 6/27/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/27/2007 |
| Spill Record Last Update: | 7/23/2007 |
| Spiller Name: | ERTSDESK |
| Spiller Company: | CON EDISON TM #1420 |
| Spiller Address: | DEGRAW /VANBRUNT |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERTSDESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 07/23/07 - See eDocs for Con Ed report detailing cleanup and closure.206677. see eDocs |
| Remarks: | ON 500 GALLONS OF WATER : CONED# 206677 |

Material:

| | |
|---|---|
| Site ID: | 383533 |
| Operable Unit ID: | 1140875 |
| Operable Unit: | 01 |
| Material ID: | 2130987 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**E22** **DSNY BK DISTRICT 6A GARAGE** **NY UST U004062148**
**93 VAN BRUNT STREET** **NY AST N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 6 of 18 in cluster E**

**Relative: Higher**

**Actual: 11 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-455911 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2018/12/06 |
| UTM X: | 584108.48747000005 |
| UTM Y: | 4504294.12414 |

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

Site Type: Municipality (Incl. Waste Water Treatment Plants,

Affiliation Records:

Site Id: 20076
Affiliation Type: Emergency Contact
Company Name: ANGEL MANAGEMENT % PERSON & COMPANY, LLP
Contact Type: Not reported
Contact Name: BUREAU OF CLEANING &COLLECTION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 885-5051
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/21/2013

Site Id: 20076
Affiliation Type: On-Site Operator
Company Name: DSNY BK DISTRICT 6A GARAGE
Contact Type: Not reported
Contact Name: GARAGE SUPERVISOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 522-4482
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/18/2013

Site Id: 20076
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF SANITATION
Contact Type: Not reported
Contact Name: A/C G. CARANNANTE
Address1: 125 WORTH STREET
Address2: ROOM 823B
City: NEW YORK
State: NY
Zip Code: 10013
Country Code: 001
Phone: (646) 885-4856
EMail: GCARANN@DSNY.NYC.GOV
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/18/2013

Site Id: 20076
Affiliation Type: Facility Owner
Company Name: ANGEL MANAGEMENT % PERSON & COMPANY, LLP
Contact Type: DIC

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

| | |
|---|---|
| Contact Name: | JOHN C |
| Address1: | 6 EAST 39TH ST, ROOM 801 |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10016 |
| Country Code: | 001 |
| Phone: | (718) 665-1319 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 11/18/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 36357 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1996 |
| Date Tank Closed: | 06/18/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | dxliving |
| Last Modified: | 08/24/2009 |

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 36358 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1996 |
| Date Tank Closed: | 12/01/1996 |

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None

Tank Number: 003
Tank ID: 36359
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 004

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

| | |
|---|---|
| Tank ID: | 36360 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1996 |
| Date Tank Closed: | 12/01/1996 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 005 |
| Tank ID: | 36361 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1996 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None

Tank Number: 006
Tank ID: 36362
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None

Tank Number: 007
Tank ID: 36363
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1996
Date Tank Closed: 12/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Number: 013-A
Tank ID: 173826
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: dxliving
Last Modified: 09/21/2009

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Number: 014
Tank ID: 51703
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2500
Install Date: 10/23/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

| | |
|---|---|
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/18/2013 |

Equipment Records:

F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)

| | |
|---|---|
| Tank Number: | 015 |
| Tank ID: | 51704 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 2500 |
| Install Date: | 10/23/1997 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 2710 |
| Common Name of Substance: | Biodiesel |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/18/2013 |

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

Tank Number: 017
Tank ID: 230229
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 01/01/2001
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 11/18/2013

Equipment Records:

F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 018
Tank ID: 230230
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 01/01/2001
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0015
Common Name of Substance: Motor Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSBAPTIS
Last Modified: 11/18/2013

Equipment Records:

B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
C03 - Pipe Location - Aboveground/Underground Combination
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)

| | |
|---|---|
| Tank Number: | 019 |
| Tank ID: | 230231 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 1000 |
| Install Date: | 01/01/2001 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0010 |
| Common Name of Substance: | Hydraulic Oil |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/18/2013 |

Equipment Records:

F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-455911 |
| Program Type: | PBS |
| UTM X: | 584108.48747000005 |

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

UTM Y: 4504294.12414
Expiration Date: 2018/12/06
Site Type: Municipality (Incl. Waste Water Treatment Plants,

Affiliation Records:

Site Id: 20076
Affiliation Type: Emergency Contact
Company Name: ANGEL MANAGEMENT % PERSON & COMPANY, LLP
Contact Type: Not reported
Contact Name: BUREAU OF CLEANING &COLLECTION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 885-5051
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/21/2013

Site Id: 20076
Affiliation Type: On-Site Operator
Company Name: DSNY BK DISTRICT 6A GARAGE
Contact Type: Not reported
Contact Name: GARAGE SUPERVISOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 522-4482
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/18/2013

Site Id: 20076
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF SANITATION
Contact Type: Not reported
Contact Name: A/C G. CARANNANTE
Address1: 125 WORTH STREET
Address2: ROOM 823B
City: NEW YORK
State: NY
Zip Code: 10013
Country Code: 001
Phone: (646) 885-4856
EMail: GCARANN@DSNY.NYC.GOV
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/18/2013

Site Id: 20076
Affiliation Type: Facility Owner

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

| | |
|---|---|
| Company Name: | ANGEL MANAGEMENT % PERSON & COMPANY, LLP |
| Contact Type: | DIC |
| Contact Name: | JOHN C |
| Address1: | 6 EAST 39TH ST, ROOM 801 |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10016 |
| Country Code: | 001 |
| Phone: | (718) 665-1319 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 11/18/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 008 |
| Tank Id: | 36364 |
| Material Code: | 0012 |
| Common Name of Substance: | Kerosene [#1 Fuel Oil] (On-Site Consumption) |

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/16/1973 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 03/01/2001 |
| Register: | True |
| Modified By: | dxliving |
| Last Modified: | 08/24/2009 |
| Material Name: | Kerosene [#1 Fuel Oil] (On-Site Consumption) |

| | |
|---|---|
| Tank Number: | 009 |
| Tank Id: | 173782 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/16/1973 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 03/01/2001 |
| Register: | True |
| Modified By: | dxliving |
| Last Modified: | 08/24/2009 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 009-A |
| Tank Id: | 173800 |
| Material Code: | 0012 |
| Common Name of Substance: | Kerosene [#1 Fuel Oil] (On-Site Consumption) |

Equipment Records:

G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 110 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 12/01/1993 |
| Register: | True |
| Modified By: | TRANSLAT |

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

Last Modified: 03/04/2004
Material Name: Kerosene [#1 Fuel Oil] (On-Site Consumption)

Tank Number: 010
Tank Id: 36368
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/16/1973
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/01/2001
Register: True
Modified By: dxliving
Last Modified: 08/28/2009
Material Name: Lube Oil

Tank Number: 011
Tank Id: 36367
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

| | |
|---|---|
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 110 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 12/01/1993 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | Other |

| | |
|---|---|
| Tank Number: | 012 |
| Tank Id: | 36371 |
| Material Code: | 0013 |
| Common Name of Substance: | Lube Oil |

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/16/1973 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 03/01/2001 |
| Register: | True |
| Modified By: | dxliving |
| Last Modified: | 08/28/2009 |
| Material Name: | Lube Oil |

| | |
|---|---|
| Tank Number: | 013 |
| Tank Id: | 173825 |
| Material Code: | 0010 |
| Common Name of Substance: | Hydraulic Oil |

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
F00 - Pipe External Protection - None

**DSNY BK DISTRICT 6A GARAGE (Continued)** **U004062148**

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 2 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/16/1973 |
| Capacity Gallons: | 110 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 06/10/2010 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/07/2010 |
| Material Name: | Hydraulic Oil |

| | |
|---|---|
| Tank Number: | 016 |
| Tank Id: | 36372 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 250 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/01/1996 |
| Register: | True |
| Modified By: | dxliving |
| Last Modified: | 09/21/2009 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

**E23** **NYC DOS BROOKLYN WEST A** **RCRA NonGen / NLR** **1000140993**
**93 VAN BRUNT ST** **FINDS** **NYD982529729**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 7 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | NYC DOS BROOKLYN WEST A |
| Facility address: | 93 VAN BRUNT ST<br>BROOKLYN, NY 112311427 |
| EPA ID: | NYD982529729 |
| Mailing address: | WORTH ST ROOM 823<br>BUR OF C&C<br>NEW YORK, NY 10013 |
| Contact: | Not reported |
| Contact address: | WORTH ST ROOM 823<br>NEW YORK, NY 10013 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Land type: | Facility is not located on Indian land. Additional information is not known. |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | ANGEL MANAGEMENT CORP |
| Owner/operator address: | 1028 57TH ST<br>BROOKLYN, NY 11219 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 292-6200 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | ANGEL MANAGEMENT CORP |
| Owner/operator address: | 1028 57TH ST<br>BROOKLYN, NY 11219 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 292-6200 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |

**NYC DOS BROOKLYN WEST A (Continued)** **1000140993**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC DOS BROOKLYN WEST A
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NYC DOS BROOKLYN WEST A
Classification: Not a generator, verified

Date form received by agency: 12/19/1996
Facility name: NYC DOS BROOKLYN WEST A
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/26/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004421340

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

**E24** **BROOKLYN WEST A DOS -DDC** **NY Spills** **S102560497**
**93 VAN BRUNT STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**1 ft.**

**Site 8 of 18 in cluster E**

**Relative: Higher**
**Actual: 11 ft.**

SPILLS:
Facility ID: 9614895
Facility Type: ER
DER Facility ID: 270528
Site ID: 272922
DEC Region: 2
Spill Date: 3/26/1997
Spill Number/Closed Date: 9614895 / 2/18/2005
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

**BROOKLYN WEST A DOS -DDC (Continued)** **S102560497**

| | |
|---|---|
| | Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | AIIslam |
| Referred To: | Not reported |
| Reported to Dept: | 3/26/1997 |
| CID: | 369 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/26/1997 |
| Spill Record Last Update: | 2/18/2005 |
| Spiller Name: | Not reported |
| Spiller Company: | CITY OF NEW YORK |
| Spiller Address: | 30-30 THOMPSON AVE 5TH FL |
| Spiller City,St,Zip: | NEW YORK, NY |
| Spiller Company: | 001 |
| Contact Name: | TONY MARINO |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"The spill is closed to consolidate with spill # 9708762 in consultation with AZ. The site is currently under remediation by LiRo Engineers. -II (02/18/05). |
| Remarks: | SANITATION DEPT- DEMATTEIS CONSTRUCTION CORP SOIL SAMPLES WERE CONTAMINATED |

Material:

| | |
|---|---|
| Site ID: | 272922 |
| Operable Unit ID: | 1042492 |
| Operable Unit: | 01 |
| Material ID: | 339993 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 272922 |
| Operable Unit ID: | 1042492 |
| Operable Unit: | 01 |
| Material ID: | 339994 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**BROOKLYN WEST A DOS -DDC (Continued)** **S102560497**

Tank Test:

| | |
|---|---|
| Facility ID: | 9708762 |
| Facility Type: | ER |
| DER Facility ID: | 270528 |
| Site ID: | 272923 |
| DEC Region: | 2 |
| Spill Date: | 10/27/1997 |
| Spill Number/Closed Date: | 9708762 / 2/1/2006 |
| Spill Cause: | Unknown |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 10/27/1997 |
| CID: | 211 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/27/1997 |
| Spill Record Last Update: | 2/1/2006 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | JACINTA TEIJMUL |
| Contact Phone: | (516) 485-0000 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"TRANSFERRED TO I. ISLAM3/2/05- The site is currently under active remediation by LiRo Engineers. The site had another spill (#9614895) which has recently been consolidated with this spill. - II.5/13/05- Reviewed the March/05 monthly monitoring report. MPE system was in place to remediate soil and GW.The latest soil sampling results exhibit no exceedance of NYSDEC guidance values and LiRo recommends shutting down of the MPE system. The GW sampling results indicate substantial improvement with minor exceedances in 5 monitoring wells( with a max. of 300 ppb of TVOC in one well) and LiRo recommends to treat the dissolved phase contamination by installing ORC socks in wells. No Free product in any well. LiRo's recommendations are agreed upon and proposals are approved via email. - II 8/3/05- As per May/05 monthly report, the MPE system has been shut down on May 20, 2005 with DEC's approval. ORC socks installation has been scheduled for wells showing elevated VOC levels. April 2005 GW sampling results detected highest VOC concentration @ 78 ppb at one well (MW-3). Based on complied GW sampling data, and as per LiRo's recommendation, discontinuation of GW sampling at monitoring wells MW-1,MW-6, MW-7, MW-11 and MW-13 is hereby approved, while monitoring of the remaining wells will continue. LiRo's |

**BROOKLYN WEST A DOS -DDC (Continued)** **S102560497**

recommendation for changing the reporting frequency from monthly to quarterly for the site is also approved. - II 8/30/05- Reviewed the June/05 monthly report. Routine monitoring as mentioned above will continue. Copied the monthly reports for Apr., May & June/05 in the eDoc folder.- II12/5/05- Reviewed the July-Sept/05 monitoring report dt. Oct.20/05. The MPE system at the site was shutdown as per DEC's approval of the LiRo's recommendation. Subsequently, ORC socks were installed into wells showing elevated VOC concentrations. During Jul-Aug./05 GW sampling, four of the seven sampled wells were observed to exceed NYSDEC water quality criteria for VOCs, the highest TVOCs being at 88 ppb. However, overall VOC concentrations have been observed to decrease significantly since remediation efforts began at the site. No product has been observed at the site since Dec., 2002. LiRo recommends continuing with the currently existing monitoring program at the site. Filed the report in the eDoc folder.- II.2/1/06 - LIRO submitted a sensitive receptor survey. After review of the survey, no known direct exposure pathways for GW within 2000 ft. of the site. Spill Closed. - KST

Remarks: CALLER'S COMPANY IS INSTALLING FILL LINES FOR REMOTE FUEL TANKS AND FOUND SOIL CONATMINATION - CALLER IS NOT SURE THE SOURCE OF SPILL AT PRESENT TIME

Material:

| | |
|---|---|
| Site ID: | 272923 |
| Operable Unit ID: | 1051837 |
| Operable Unit: | 01 |
| Material ID: | 330711 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**E25** **BROOKLYN WEST A** **NY HIST UST U003074870**
**93 VAN BRUNT STREET** **NY HIST AST N/A**
**< 1/8** **BROOKLYN, NY 11231**
**1 ft.**

**Site 9 of 18 in cluster E**

**Relative: Higher**

**Actual: 11 ft.**

HIST UST:

| | |
|---|---|
| PBS Number: | 2-455911 |
| SPDES Number: | Not reported |
| Emergency Contact: | BUREAU OF CLEANING &COLLECTION |
| Emergency Telephone: | (212) 788-4054 |
| Operator: | NYC DEPT OF SANITATION, BCC |
| Operator Telephone: | (718) 522-4274 |
| Owner Name: | ANGEL MANAGEMENT CORP. C/O BARRY MILEA |
| Owner Address: | 1028 57TH STREET |
| Owner City,St,Zip: | NEW YORK, NY 11219 |
| Owner Telephone: | (718) 292-6200 |
| Owner Type: | Local Government |

**BROOKLYN WEST A (Continued)** **U003074870**

| | |
|---|---|
| Owner Subtype: | Not reported |
| Mailing Name: | NYC DEPT. OF SANITATION |
| Mailing Address: | 125 WORTH STREET, ROOM 823 |
| Mailing Address 2: | 8TH FLOOR |
| Mailing City,St,Zip: | NEW YORK, NY 10013 |
| Mailing Contact: | CHIEF OF FACILITIES |
| Mailing Telephone: | (212) 788-4059 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | 93 VAN BRUNT STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | OTHER |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 03/23/1999 |
| Expiration Date: | 12/06/2003 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 6100 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 003 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | DIESEL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 12/01/1996 |

**BROOKLYN WEST A (Continued)** **U003074870**

Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 005
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 550
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 12/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 006
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 550
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 12/01/1996
Test Method: Not reported
Deleted: False
Updated: True

**BROOKLYN WEST A (Continued)** **U003074870**

Lat/long: Not reported

Tank Id: 013
Tank Location: UNDERGROUND
Tank Status: Tank Converted To Non-Regulated Use
Install Date: Not reported
Capacity (gals): 275
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Vent Whistle
Dispenser: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

HIST AST:
PBS Number: 2-455911
SWIS Code: 6101
Operator: NYC DEPT OF SANITATION, BCC
Facility Phone: (718) 522-4274
Facility Addr2: 93 VAN BRUNT STREET
Facility Type: OTHER
Emergency: BUREAU OF CLEANING &COLLECTION
Emergency Tel: (212) 788-4054
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: ANGEL MANAGEMENT CORP. C/O BARRY MILEA
Owner Address: 1028 57TH STREET
Owner City,St,Zip: NEW YORK, NY 11219
Federal ID: Not reported
Owner Tel: (718) 292-6200
Owner Type: Local Government
Owner Subtype: Not reported
Mailing Contact: CHIEF OF FACILITIES
Mailing Name: NYC DEPT. OF SANITATION
Mailing Address: 125 WORTH STREET, ROOM 823
Mailing Address 2: 8TH FLOOR
Mailing City,St,Zip: NEW YORK, NY 10013
Mailing Telephone: (212) 788-4059
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

**BROOKLYN WEST A (Continued)** **U003074870**

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

| | |
|---|---|
| Certification Flag: | False |
| Certification Date: | 03/23/1999 |
| Expiration: | 12/06/2003 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 6100 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 008 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | KEROSENE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 1 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 0 |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | 6 |
| Dispenser Method: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 009 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (Gal): | 110 |
| Product Stored: | KEROSENE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |

**BROOKLYN WEST A (Continued)** **U003074870**

| | |
|---|---|
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | Not reported |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1993 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 009 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 1 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 0 |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | 6 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 010 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 1 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |

**BROOKLYN WEST A (Continued)** **U003074870**

Pipe Internal: None
Pipe External: 0
Tank Containment: None
Leak Detection: 0
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 011
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 110
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: Not reported
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1993
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 012
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 275
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None

**BROOKLYN WEST A (Continued)** **U003074870**

Pipe External: 0
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 013
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 110
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: Not reported
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1993
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 016
Tank Location: ABOVEGROUND
Tank Status: Tank Converted To Non-Regulated Use
Install Date: Not reported
Capacity (Gal): 250
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported

**BROOKLYN WEST A (Continued)** **U003074870**

| | |
|---|---|
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | Not reported |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1996 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**E26** **EDR US Hist Auto Stat** **1015168062**
**SSW** **115 VAN BRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.002 mi.**
**9 ft.** **Site 10 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | TIMELY CAR SERVICE |
| Year: | 2005 |
| Address: | 115 VAN BRUNT ST |
| Name: | TIMELY CAR SERVICE |
| Year: | 2006 |
| Address: | 115 VAN BRUNT ST |
| Name: | TIMELY CAR SERVICE |
| Year: | 2007 |
| Address: | 115 VAN BRUNT ST |
| Name: | TIMELY CAR SERVICE |
| Year: | 2008 |
| Address: | 115 VAN BRUNT ST |
| Name: | TIMELY CAR SERVICE |
| Year: | 2009 |
| Address: | 115 VAN BRUNT ST |

---

**F27** **NYC DEP - GOWANUS FLUSHING TUNNEL** **FINDS** **1007821372**
**SSW** **DEGRAW ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.002 mi.**
**13 ft.** **Site 3 of 3 in cluster F**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

FINDS:

Registry ID: 110019839335

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**E28**
**SSW**
**< 1/8**
**0.002 mi.**
**13 ft.**

**MAN HOLE 43632**
**133 VANBRUNT ST**
**BROOKLYN, NY**

**Site 11 of 18 in cluster E**

**NY Spills** **S110044083**
**N/A**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0907974 |
| Facility Type: | ER |
| DER Facility ID: | 369572 |
| Site ID: | 420544 |
| DEC Region: | 2 |
| Spill Date: | 10/15/2009 |
| Spill Number/Closed Date: | 0907974 / 11/30/2009 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | Con Ed Unassigned |
| Referred To: | Not reported |
| Reported to Dept: | 10/15/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/15/2009 |
| Spill Record Last Update: | 11/30/2009 |
| Spiller Name: | Not reported |
| Spiller Company: | CON ED |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 11/30/09 - See eDocs for Con Ed report detailing cleanup and closure. |
| Remarks: | soil bottom in man hole/clean up pending test results/con ed referance # 21839 |

Material:

| | |
|---|---|
| Site ID: | 420544 |
| Operable Unit ID: | 1176497 |
| Operable Unit: | 01 |
| Material ID: | 2169188 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0.1000000000000 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**MAN HOLE 43632 (Continued)** **S110044083**

Tank Test:

---

**E29**
**SSW**
**< 1/8**
**0.003 mi.**
**16 ft.**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

**129 VAN BRUNT ST** **EDR US Hist Auto Stat** **1015198887**
**BROOKLYN, NY 11231** **N/A**

**Site 12 of 18 in cluster E**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | MARATHON HOSIERY CO |
| Year: | 2009 |
| Address: | 129 VAN BRUNT ST |

---

**G30**
**SSW**
**< 1/8**
**0.003 mi.**
**16 ft.**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

**VAN BRUNT & CARROLL ST** **NY Spills** **S102144067**
**VAN BRUNT & CARROLL ST** **N/A**
**BROOKLYN, NY**

**Site 1 of 8 in cluster G**

SPILLS:

| | |
|---|---|
| Facility ID: | 8603605 |
| Facility Type: | ER |
| DER Facility ID: | 198721 |
| Site ID: | 241757 |
| DEC Region: | 2 |
| Spill Date: | 9/2/1986 |
| Spill Number/Closed Date: | 8603605 / 9/2/1986 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 9/2/1986 |
| CID: | Not reported |
| Water Affected: | NONE |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | 9/2/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/9/1986 |
| Spill Record Last Update: | 9/29/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | UNK |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***UPDATE***, ZZ |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | NYC OEM & NYC DEP OVERPACK & REMOVE |

**VAN BRUNT & CARROLL ST (Continued)** **S102144067**

Material:

| | |
|---|---|
| Site ID: | 241757 |
| Operable Unit ID: | 900854 |
| Operable Unit: | 01 |
| Material ID: | 476432 |
| Material Code: | 0116A |
| Material Name: | PYRIDINE |
| Case No.: | 00110861 |
| Material FA: | Hazardous Material |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | 20 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**G31** **MANHOLE #57342** **NY Spills** **S103829508**
**SSW** **SUMMIT ST & VAN BRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.003 mi.**
**18 ft.** **Site 2 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9815412 |
| Facility Type: | ER |
| DER Facility ID: | 147989 |
| Site ID: | 176086 |
| DEC Region: | 2 |
| Spill Date: | 3/28/1999 |
| Spill Number/Closed Date: | 9815412 / 5/11/1999 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 3/28/1999 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/28/1999 |
| Spill Record Last Update: | 6/19/2000 |
| Spiller Name: | UNKNOWN |
| Spiller Company: | UNKNOWN |
| Spiller Address: | UNKNOWN |
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |

**MANHOLE #57342 (Continued)** **S103829508**

Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"CON ED E2MIS NOTESUndiaperable sheen found on top 200 gals, of water in MH 57342. No sewers or waterways affected. There is a joint regulator in MH but unable to tell if it is leaking. Unable to tell if MH has sump due to mud on the floor. Sample taken and put in for a 4-6 hr priority. Cleanup pending test results. Tag #21460 placed. Checked MH print ot see if MH has sump... not connected to sewer.3-28-99 13:15 Lab Seq# 99-03165 <1.0ppm PCB3-28-99 Cleanup complete and tag removed.Incident closed.
Remarks: sheen of unk oil on 200 gal of water in manhole - contained in manhole - samples have been taken clean up pending test results

Material:
Site ID: 176086
Operable Unit ID: 1073433
Operable Unit: 01
Material ID: 308519
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**C32** **GOLTENS MARINE** **NY Spills** **S113405810**
**SSW** **160 VAN BRUNDT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.003 mi.**
**18 ft.** **Site 8 of 10 in cluster C**

**Relative: Higher**

**Actual: 9 ft.**

SPILLS:
Facility ID: 1216530
Facility Type: ER
DER Facility ID: 435214
Site ID: 479914
DEC Region: 2
Spill Date: 2/26/2013
Spill Number/Closed Date: 1216530 / 3/29/2013
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/19/2013
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False

**GOLTENS MARINE (Continued)** **S113405810**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/19/2013 |
| Spill Record Last Update: | 3/29/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | GOLTENS WORLDWIDE MANAGEMENT CORP |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | MARK T RUTKOWSKI |
| Contact Phone: | (732) 223-2030 |
| DEC Memo: | Brinkerhoff did a tank pull. Tank was wrapped in cement. Tank had holes, cement was stained. After tank was pulled, cement bed was broken and removed, soil end points were clean. Spill closed. |
| Remarks: | Tank 2 had holes - cleanup done - no impact |

Material:

| | |
|---|---|
| Site ID: | 479914 |
| Operable Unit ID: | 1229632 |
| Operable Unit: | 01 |
| Material ID: | 2227414 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**E33** **EDR US Hist Auto Stat** **1015583405**
**SSW** **63 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.004 mi.**
**19 ft.** **Site 13 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | CON Y SIN AUTO REPAIR |
| Year: | 2001 |
| Address: | 63 UNION ST |

**H34** **SCHOENBERG SALT CO.** **NY UST** **U003758104**
**SSW** **87 BOWNE STREET** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11231** **NY AST**
**0.004 mi.** **NY HIST AST**
**20 ft.** **Site 1 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-604788 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 583879.51841000002 |
| UTM Y: | 4503948.8024399998 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | Facility Owner |
| Company Name: | ALLEN SCHOENBERG |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 87 BOWNE STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | Mail Contact |
| Company Name: | SCHOENBERG SALT CO. |
| Contact Type: | Not reported |
| Contact Name: | ALLEN SCHOENBERG |
| Address1: | 87 BOWNE STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | On-Site Operator |
| Company Name: | SCHOENBERG SALT CO. |
| Contact Type: | Not reported |
| Contact Name: | NONE |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**SCHOENBERG SALT CO. (Continued)** **U003758104**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | Emergency Contact |
| Company Name: | ALLEN SCHOENBERG |
| Contact Type: | Not reported |
| Contact Name: | ALLEN SCHOENBERG |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 02 |
| Tank ID: | 58886 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/2000 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

**SCHOENBERG SALT CO. (Continued)** **U003758104**

| | |
|---|---|
| Tank Number: | 03 |
| Tank ID: | 58887 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/2000 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None

HIST UST:

| | |
|---|---|
| PBS Number: | 2-604788 |
| SPDES Number: | Not reported |
| Emergency Contact: | ALLEN SCHOENBERG |
| Emergency Telephone: | (718) 237-0700 |
| Operator: | NONE |
| Operator Telephone: | (718) 237-0700 |
| Owner Name: | ALLEN SCHOENBERG |
| Owner Address: | 87 BOWNE STREET |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Owner Telephone: | (718) 237-0700 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | SCHOENBERG SALT CO. |
| Mailing Address: | 87 BOWNE STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Contact: | ALLEN SCHOENBERG |
| Mailing Telephone: | (718) 237-0700 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Facility Addr2: | Not reported |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | OTHER |

**SCHOENBERG SALT CO. (Continued)** **U003758104**

| | |
|---|---|
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | Not reported |
| Expiration Date: | 11/06/2005 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 02 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |
| Pipe Location: | Aboveground/Underground Combination |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Submersible |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 10/01/2000 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 03 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |

**SCHOENBERG SALT CO. (Continued)** **U003758104**

Pipe Location: Aboveground/Underground Combination
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Submersible
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-604788
Program Type: PBS
UTM X: 583879.51841000002
UTM Y: 4503948.8024399998
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 26657
Affiliation Type: Facility Owner
Company Name: ALLEN SCHOENBERG
Contact Type: Not reported
Contact Name: Not reported
Address1: 87 BOWNE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231
Country Code: 001
Phone: (718) 237-0700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 26657
Affiliation Type: Mail Contact
Company Name: SCHOENBERG SALT CO.
Contact Type: Not reported
Contact Name: ALLEN SCHOENBERG
Address1: 87 BOWNE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231
Country Code: 001

**SCHOENBERG SALT CO. (Continued)** **U003758104**

| | |
|---|---|
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | On-Site Operator |
| Company Name: | SCHOENBERG SALT CO. |
| Contact Type: | Not reported |
| Contact Name: | NONE |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 26657 |
| Affiliation Type: | Emergency Contact |
| Company Name: | ALLEN SCHOENBERG |
| Contact Type: | Not reported |
| Contact Name: | ALLEN SCHOENBERG |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 237-0700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 01 |
| Tank Id: | 58885 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

**SCHOENBERG SALT CO. (Continued)** **U003758104**

| | |
|---|---|
| | B00 - Tank External Protection - None |
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - In Place |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 10/01/2000 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-604788 |
| SWIS Code: | 6101 |
| Operator: | NONE |
| Facility Phone: | (718) 237-0700 |
| Facility Addr2: | Not reported |
| Facility Type: | OTHER |
| Emergency: | ALLEN SCHOENBERG |
| Emergency Tel: | (718) 237-0700 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | ALLEN SCHOENBERG |
| Owner Address: | 87 BOWNE STREET |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 237-0700 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | ALLEN SCHOENBERG |
| Mailing Name: | SCHOENBERG SALT CO. |
| Mailing Address: | 87 BOWNE STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Telephone: | (718) 237-0700 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Certification Flag: | False |
| Certification Date: | Not reported |
| Expiration: | 11/06/2005 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |

**SCHOENBERG SALT CO. (Continued)** **U003758104**

Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 01
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 0
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 0
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Submersible
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/2000
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

---

**I35** **VAULT #TN1554** **NY Spills** **S103828886**
**SSW** **170 VAN BRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.004 mi.**
**20 ft.** **Site 1 of 4 in cluster I**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:
Facility ID: 9814694
Facility Type: ER
DER Facility ID: 210544
Site ID: 64760
DEC Region: 2
Spill Date: 3/10/1999
Spill Number/Closed Date: 9814694 / 6/6/2002
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 3/10/1999
CID: 257
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported

**VAULT #TN1554 (Continued)** **S103828886**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/10/1999 |
| Spill Record Last Update: | 6/6/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | JOE DEVOTI |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"Con Ed e2mis #123548:09:25 3/10/99 R.CILENTO #44214 SPLICER I&A NETWORKS REPORTED FINDING UNDIAPERABLE OIL SHEEN APP. 3/4 GAL.OIL ON 500 GAL. WATERIN TM1554 ON WALK F/O 170 VAN BRUNT ST.NO SEWERS OR WATERWAYS AFFECTED. NO SUMP PUMP IN HOLE. FOUND WHILE GOING TO DOSCHED WORK. PRESSURE TEST TAKEN CAME OUT O.K. OIL SAMPLE TAKEN PUT IN FOR 4-6 HRS. TURNAROUND PLUS INSTALLED E.S.TAG#08477 WAS INSTALLED. CLEAN UP PENDING OIL SAMPLE RESULTS.3-10-99 5:35HRS LAB SEQ# 99-02526 <1.0PPM. UPDATE :14-MAR-1999 1100HRS CLEAN UP COMPLETE USING SLIX AT THIS TIME TAG PULLED. |
| Remarks: | on 500 gals on water a sheen sample taken cleanup pending resultsref #123548 |

Material:

| | |
|---|---|
| Site ID: | 64760 |
| Operable Unit ID: | 1072282 |
| Operable Unit: | 01 |
| Material ID: | 311374 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9811739 |
| Facility Type: | ER |
| DER Facility ID: | 210544 |
| Site ID: | 257128 |
| DEC Region: | 2 |
| Spill Date: | 12/17/1998 |
| Spill Number/Closed Date: | 9811739 / 2/14/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |

**VAULT #TN1554 (Continued)** **S103828886**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 12/17/1998 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/17/1998 |
| Spill Record Last Update: | 2/19/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | FRANK MASSERIA |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"E2MIS 12200912/17/98-1418HRS--HEARNS REPORTS FOUND UNDIAPERABLE SHEEN ON 1000 GALLONS OF WATER,IN TM-1554,SAMPLE TAKEN TAG # 11571PLACED NO SEWERS OR WATERWAYS EFFECTED --- RECORDS SHOW 36PPM NOT PRESURE TESTED DUE TO WATER .UNIT CONDEMEDEXCESSIVE RUST--G DONATONE-----UPDATE:12/18/98-00:35HRS-LAB RESULTS-SEQ#98-14071-<1.00 PPMupdate********** 3-4-99 1430 HRS J. LOPORI REPORTS, UNIT WAS REMOVED AND THE CLEANUP IS COMPLETED WITH SLIX & TAGREMOVED. INCIDENT IS CLOSED. TJ - 50495 |
| Remarks: | ABOVE MATERIAL DISCOVERED IN ABOVE LOCATION. TESTING BEING DONEON MATERIAL. NO CALL BACK REQUESTED. CON ED #122009. |

Material:

| | |
|---|---|
| Site ID: | 257128 |
| Operable Unit ID: | 1072537 |
| Operable Unit: | 01 |
| Material ID: | 312025 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9811742 |
| Facility Type: | ER |
| DER Facility ID: | 210544 |
| Site ID: | 64759 |
| DEC Region: | 2 |
| Spill Date: | 12/17/1998 |

**VAULT #TN1554 (Continued)** **S103828886**

| | |
|---|---|
| Spill Number/Closed Date: | 9811742 / 2/14/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 12/17/1998 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/17/1998 |
| Spill Record Last Update: | 2/19/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNK SOURCE |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"12201217-DEC-1998 1458HRS HEARN O/S EQUIPT GRP #50839 REPORTS FOUND UNDIAPERABLE SHEEN OF OIL ON 600 GALLONS OF WATER IN MH-58457NO SEWERS OR WATERWAYS AFFECTED PRESSURE TESTED UNIT, IT HELDPRESSURE SAMPLE TAKEN AND TAG #11572 HUNG. CIG NOTIFIEDUPDATE:12/18/98-00:35HRS.-LAB RESULTS RETURNED-SEQ#98-14072-<1.00PPMJAP- - CLEAN UP COMPLETE WITH SLIX AS OF 12/30/98 1800HRS AS PER FLUSH OPERATOR D. LICHTENSTEIN #08078 ON TRUCK # 60532. STOPTAG # 11572 REMOVED. |
| Remarks: | unk diaperable oil on 600 gal of water in manhole - contained inmanhole - samples taken and will be cleaned up when its determineddwhat it is - con ed #122012 |

Material:

| | |
|---|---|
| Site ID: | 64759 |
| Operable Unit ID: | 1069007 |
| Operable Unit: | 01 |
| Material ID: | 312028 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**I36** **EDR US Hist Auto Stat** **1015265262**
**SSW** **170 VAN BRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.004 mi.**
**20 ft.** **Site 2 of 4 in cluster I**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | COACH BUS REPAIR INC |
| Year: | 2009 |
| Address: | 170 VAN BRUNT ST |
| Name: | COACH BUS REPAIR INC |
| Year: | 2010 |
| Address: | 170 VAN BRUNT ST |
| Name: | COACH BUS REPAIR INC |
| Year: | 2011 |
| Address: | 170 VAN BRUNT ST |
| Name: | COACH BUS REPAIR INC |
| Year: | 2012 |
| Address: | 170 VAN BRUNT ST |

---

**I37** **COACH BUS REPAIR, INC.** **NY AST** **A100326256**
**SSW** **170 VAN BRUNT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.004 mi.**
**20 ft.** **Site 3 of 4 in cluster I**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-611021 |
| Program Type: | PBS |
| UTM X: | 583929.09358999995 |
| UTM Y: | 4504000.5481099999 |
| Expiration Date: | 2014/02/12 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 409974 |
| Affiliation Type: | Facility Owner |
| Company Name: | AI JIN CHEN |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 170 VAN BRUNT STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 797-3606 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/12/2009 |
| Site Id: | 409974 |
| Affiliation Type: | Mail Contact |

**COACH BUS REPAIR, INC. (Continued)** **A100326256**

| | |
|---|---|
| Company Name: | COACH BUS REPAIR, INC. |
| Contact Type: | Not reported |
| Contact Name: | WINNIE/LIU |
| Address1: | 170 VAN BRUNT STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 797-3606 |
| EMail: | LIUCOACHBUS@GMAIL.COM |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/12/2009 |

| | |
|---|---|
| Site Id: | 409974 |
| Affiliation Type: | On-Site Operator |
| Company Name: | COACH BUS REPAIR, INC. |
| Contact Type: | Not reported |
| Contact Name: | MR. LIU |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (917) 662-7607 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/12/2009 |

| | |
|---|---|
| Site Id: | 409974 |
| Affiliation Type: | Emergency Contact |
| Company Name: | AI JIN CHEN |
| Contact Type: | Not reported |
| Contact Name: | WINNIE WONG |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 797-3606 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/12/2009 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 227306 |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |

**COACH BUS REPAIR, INC. (Continued)** **A100326256**

Equipment Records:

| | |
|---|---|
| | B00 - Tank External Protection - None |
| | G00 - Tank Secondary Containment - None |
| Tank Location: | 2 |
| Tank Type: | Plastic |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 12/01/2008 |
| Capacity Gallons: | 260 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 02/12/2009 |
| Material Name: | Waste Oil/Used Oil |

---

**38**
**NNE**
**< 1/8**
**0.005 mi.**
**24 ft.**

**IN THE AREA OF NY HARBOR** **NY Spills** **S104192617**
**ATLANTIC AVE** **N/A**
**BROOKLYN, NY**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9904255 |
| Facility Type: | ER |
| DER Facility ID: | 248784 |
| Site ID: | 308047 |
| DEC Region: | 2 |
| Spill Date: | 7/10/1999 |
| Spill Number/Closed Date: | 9904255 / 7/11/1999 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 7/10/1999 |
| CID: | 199 |
| Water Affected: | NEW YORK HARBOR |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/10/1999 |
| Spill Record Last Update: | 3/12/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | PO LABONTE |

**IN THE AREA OF NY HARBOR (Continued)** **S104192617**

Contact Phone: (718) 354-4120
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"SAME AS 9904263.minor spill from dock, maybe from a truck. Miller Env. called by USCG. Miller released- no work done.closed
Remarks: SHEEN ON THE WATER - UNKNOWN MATERAL - COVERES AN AREA OF 200 FT BY UNKNOWN WIDTH

Material:
Site ID: 308047
Operable Unit ID: 1083183
Operable Unit: 01
Material ID: 304144
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**C39** **NICHMEN AMERICA INC** **NY MANIFEST** **1009232182**
**SSW** **VAN BRUNT ST & HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.005 mi.**
**25 ft.** **Site 9 of 10 in cluster C**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

NY MANIFEST:
EPA ID: NYP000861302
Country: USA
Mailing Name: NICHMEN AMERICA INC
Mailing Contact: NICHMEN AMERICA INC
Mailing Address: VAN BRUNT ST & HAMILTON AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11231
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-538-0614

Document ID: NYA3085075
Manifest Status: Completed copy
Trans1 State ID: 8385RW
Trans2 State ID: Not reported
Generator Ship Date: 860902
Trans1 Recv Date: 860902
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860908
Part A Recv Date: 860919
Part B Recv Date: 860912
Generator EPA ID: NYP000861302

**NICHMEN AMERICA INC (Continued)** **1009232182**

| | |
|---|---|
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 085 |
| Waste Code: | Not reported |
| Quantity: | 00500 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 86 |

---

**C40** **COOKING OIL ON STREET** **NY Spills** **S109205297**
**SSW** **171 VANBRUNT ST** **N/A**
**< 1/8** **BROOKLYNN, NY**
**0.005 mi.**
**25 ft.** **Site 10 of 10 in cluster C**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0803040 |
| Facility Type: | ER |
| DER Facility ID: | 349043 |
| Site ID: | 399718 |
| DEC Region: | 2 |
| Spill Date: | 6/14/2008 |
| Spill Number/Closed Date: | 0803040 / 6/16/2008 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 6/14/2008 |
| CID: | 81 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/16/2008 |
| Spill Record Last Update: | 6/16/2008 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | GARSIA, STEFER |

**COOKING OIL ON STREET (Continued)** **S109205297**

Contact Phone: (212) 689-1620
DEC Memo: cooking oil spill from street vendor.closed.
Remarks: street vendors, poss cooking oil, spilling on street and sidewalk, spilling into basin.

Material:
Site ID: 399718
Operable Unit ID: 1156578
Operable Unit: 01
Material ID: 2147521
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**B41** **PORT AUTHORITY** **NY LTANKS** **S102962023**
**East** **100 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**26 ft.** **Site 2 of 8 in cluster B**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

LTANKS:
Site ID: 228103
Spill Number/Closed Date: 9711130 / 10/9/2002
Spill Date: 1/5/1998
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1/5/1998
CID: 322
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1/5/1998
Spill Record Last Update: 3/2/2005
Spiller Name: DAVID GREENFIELD
Spiller Company: WATERFRONT COMMISSION
Spiller Address: 42 BROADWAY
Spiller City,St,Zip: NEW YORK, NY 10004-1640
Spiller County: 001
Spiller Contact: Not reported

**PORT AUTHORITY (Continued)** **S102962023**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 188155
DEC Memo: This is a NYS facility - see more info in State Agency Envir. Audit notes (under facility # 4672) - end
Remarks: Caller recieved faxed results of boring from the site and theyshow contamination -only 1 borring of 4 came up hot

Material:
Site ID: 228103
Operable Unit ID: 1057627
Operable Unit: 01
Material ID: 329393
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**B42** **NEW YORK MARINE TERMINALS / BKLYN** **NY UST** **U003074668**
**East** **90 COLUMBIA ST** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11201** **NY AST**
**0.005 mi.** **NY HIST AST**
**26 ft.** **Site 3 of 8 in cluster B**

**Relative: Higher**

**Actual: 10 ft.**

UST:
Id/Status: 2-365866 / Unregulated
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584446.70079000003
UTM Y: 4504656.5085100001
Site Type: Other

Affiliation Records:
Site Id: 18598
Affiliation Type: Facility Owner
Company Name: THE PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 WORLD TRADE CENTER
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10048
Country Code: 001
Phone: (212) 466-7000
EMail: Not reported

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | Mail Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | CHRISTOPHER M. JONES |
| Address1: | 90 COLUMBIA STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 330-2976 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | On-Site Operator |
| Company Name: | NEW YORK MARINE TERMINALS / BKLYN |
| Contact Type: | Not reported |
| Contact Name: | PORT AUTH OF NY & NJ |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 330-2950 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | C. JONES |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 330-2976 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Number: | 00A |
| Tank ID: | 40895 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 3000 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 14 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

| | |
|---|---|
| Tank Number: | 00B |
| Tank ID: | 47162 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 14 |
| Date Test: | 10/01/1994 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 00C |
| Tank ID: | 47163 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 14 |
| Date Test: | 10/01/1994 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 00D |
| Tank ID: | 47164 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 1000 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 14 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm

Tank Number: 00E
Tank ID: 47165
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 10/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 01A
Tank ID: 40881
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 01B
Tank ID: 40882
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 01C
Tank ID: 40883
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 01D
Tank ID: 40884
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 01E

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank ID: | 40885 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 250 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 9999 |
| Common Name of Substance: | Other |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 01F |
| Tank ID: | 40886 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 250 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 9999 |
| Common Name of Substance: | Other |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

Tank Number: 02A
Tank ID: 40887
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 02B
Tank ID: 40888
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 02C |
| Tank ID: | 40889 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 250 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 9999 |
| Common Name of Substance: | Other |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 06A |
| Tank ID: | 163282 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 06A-A
Tank ID: 170273
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

Tank Number: 06B
Tank ID: 40902
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 07A
Tank ID: 47158
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 07B
Tank ID: 47159
Tank Status: Closed - In Place

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 11/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 50A |
| Tank ID: | 40890 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 5000 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 03 |
| Date Test: | 07/01/1992 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

G03 - Tank Secondary Containment - Vault (w/o access)

| | |
|---|---|
| Tank Number: | 53A |
| Tank ID: | 47160 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 53B |
| Tank ID: | 47161 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 56A |
| Tank ID: | 40891 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 11/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 56B |
| Tank ID: | 40892 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 11/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 56C
Tank ID: 40893
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 11/01/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 68A
Tank ID: 40897
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Number: 68B
Tank ID: 170274
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 68B-A
Tank ID: 170275
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 68C |
| Tank ID: | 40899 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Number: | 68D |
| Tank ID: | 40900 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 86B |
| Tank ID: | 40896 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 1000 |
| Install Date: | Not reported |
| Date Tank Closed: | 12/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

J03 - Dispenser - Gravity
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 86C |
| Tank ID: | 47169 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 02/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0000 |
| Common Name of Substance: | Empty |
| Tightness Test Method: | 14 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 86E |
| Tank ID: | 47171 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 11/01/1988 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 89A |
| Tank ID: | 40901 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 2500 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 09 |
| Date Test: | 04/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)

HIST UST:

| | |
|---|---|
| PBS Number: | 2-365866 |
| SPDES Number: | Not reported |
| Emergency Contact: | C. JONES |
| Emergency Telephone: | (718) 330-2976 |
| Operator: | PORT AUTH OF NY & NJ |
| Operator Telephone: | (718) 330-2950 |
| Owner Name: | THE PORT AUTHORITY OF NY & NJ |
| Owner Address: | 1 WORLD TRADE CENTER |
| Owner City,St,Zip: | NEW YORK, NY 10048 |
| Owner Telephone: | (212) 435-7000 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | THE PORT AUTHORITY OF NY & NJ |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Mailing Address: | 90 COLUMBIA STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11201 |
| Mailing Contact: | CHRISTOPHER M. JONES |
| Mailing Telephone: | (718) 330-2976 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Facility Addr2: | 90 COLUMBIA ST |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | OTHER |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 03/01/1999 |
| Expiration Date: | 08/23/2003 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 00A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 3000 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | 10/01/1995 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 10/01/1997 |
| Test Method: | Tankology [Vacutect] |
| Deleted: | False |
| Updated: | True |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Lat/long: Not reported

Tank Id: 00B
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: Diking
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: 10/01/1994
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/1997
Test Method: Tankology [Vacutect]
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 00C
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: Diking
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: 10/01/1994
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/1997
Test Method: Tankology [Vacutect]
Deleted: False
Updated: True
Lat/long: Not reported

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Id: | 00D |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 1000 |
| Product Stored: | DIESEL |
| Tank Type: | Fiberglass reinforced plastic [FRP] |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | High Level Alarm, Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | 10/01/1995 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 10/01/1997 |
| Test Method: | Tankology [Vacutect] |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 00E |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 275 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 10/01/1997 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01C |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | UNKNOWN |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01D |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01E |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 250 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 01F |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 250 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 02A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 02B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 500 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 02C |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 250 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 06A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 06A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | Not reported |
| Leak Detection: | Not reported |
| Overfill Prot: | Not reported |
| Dispenser: | Not reported |
| Date Tested: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 10/01/1988
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 06B
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 550
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Not reported
Dispenser: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 07A
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 550
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Not reported
Leak Detection: Not reported
Overfill Prot: Not reported
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1988

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 07B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | Not reported |
| Leak Detection: | Not reported |
| Overfill Prot: | Not reported |
| Dispenser: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 11/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 50A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 5000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | 07/01/1992 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 10/01/1997 |
| Test Method: | Horner EZ Check |
| Deleted: | False |
| Updated: | True |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Lat/long: Not reported

Tank Id: 53A
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Not reported
Leak Detection: Not reported
Overfill Prot: Not reported
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1988
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 53B
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Not reported
Leak Detection: Not reported
Overfill Prot: Not reported
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1988
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Id: | 56A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 11/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 56B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 11/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 56C |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Install Date: | Not reported |
| Capacity (gals): | 600 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 11/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 68A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 68B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 68B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | Not reported |
| Leak Detection: | Not reported |
| Overfill Prot: | Not reported |
| Dispenser: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 68C |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 68D |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 86B |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 1000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 12/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 86C |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | EMPTY |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | 10/01/1995 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 02/01/1999 |
| Test Method: | Tankology [Vacutect] |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 86E |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | Not reported |
| Leak Detection: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Overfill Prot: | Not reported |
| Dispenser: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 11/01/1988 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 89A |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (gals): | 2500 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | None |
| Pipe External: | Painted/Asphalt Coating |
| Second Containment: | Diking |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | 04/01/1997 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | VPLT (NDE) |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-365866 |
| Program Type: | PBS |
| UTM X: | 584446.70079000003 |
| UTM Y: | 4504656.5085100001 |
| Expiration Date: | N/A |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | Facility Owner |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 1 WORLD TRADE CENTER |
| Address2: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10048 |
| Country Code: | 001 |
| Phone: | (212) 466-7000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | Mail Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | CHRISTOPHER M. JONES |
| Address1: | 90 COLUMBIA STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 330-2976 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | On-Site Operator |
| Company Name: | NEW YORK MARINE TERMINALS / BKLYN |
| Contact Type: | Not reported |
| Contact Name: | PORT AUTH OF NY & NJ |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 330-2950 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 18598 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | C. JONES |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 330-2976 |
| EMail: | Not reported |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 86A
Tank Id: 47168
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
G99 - Tank Secondary Containment - Other

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/1996
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 86D
Tank Id: 47170
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
G99 - Tank Secondary Containment - Other

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

| | |
|---|---|
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/01/1996 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-365866 |
| SWIS Code: | 6101 |
| Operator: | PORT AUTH OF NY & NJ |
| Facility Phone: | (718) 330-2950 |
| Facility Addr2: | 90 COLUMBIA ST |
| Facility Type: | OTHER |
| Emergency: | C. JONES |
| Emergency Tel: | (718) 330-2976 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | THE PORT AUTHORITY OF NY & NJ |
| Owner Address: | 1 WORLD TRADE CENTER |
| Owner City,St,Zip: | NEW YORK, NY 10048 |
| Federal ID: | Not reported |
| Owner Tel: | (212) 435-7000 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | CHRISTOPHER M. JONES |
| Mailing Name: | THE PORT AUTHORITY OF NY & NJ |
| Mailing Address: | 90 COLUMBIA STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11201 |
| Mailing Telephone: | (718) 330-2976 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Certification Flag: | False |
| Certification Date: | 03/01/1999 |
| Expiration: | 08/23/2003 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |

**NEW YORK MARINE TERMINALS / BKLYN (Continued)** **U003074668**

Region: 2

Tank ID: 86A
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 275
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 01
Tank Containment: 47
Leak Detection: 00
Overfill Protection: 04
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 86D
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 275
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 01
Tank Containment: 47
Leak Detection: 00
Overfill Protection: 04
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

**B43** **NYMT - BP ASI CONTAINER** **FINDS** **1016022906**
**East** **90 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**26 ft.** **Site 4 of 8 in cluster B**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

FINDS:

Registry ID: 110046245014

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

---

**B44** **ASI SITE MATERIALS** **NY MANIFEST** **S112141434**
**East** **90 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN PIERS, NY 11201**
**0.005 mi.**
**26 ft.** **Site 5 of 8 in cluster B**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYR000186650 |
| Country: | USA |
| Mailing Name: | ASI SITE MATERIALS |
| Mailing Contact: | PATRICK THRASHER |
| Mailing Address: | BROOKLYN PIERS - 90 COLUMBIA ST |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 201-216-2196 |

NY MANIFEST:

No Manifest Records Available

---

**B45** **PORT AUTHORITY/BROOKLYN MARINE TERMINAL** **FINDS** **1007803401**
**East** **90 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**26 ft.** **Site 6 of 8 in cluster B**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

FINDS:

Registry ID: 110019659298

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

**PORT AUTHORITY/BROOKLYN MARINE TERMINAL (Continued)** **1007803401**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**B46** **PORT AUTHORITY BROOKLYN PIERS (NYMT)** **RCRA NonGen / NLR** **1000333148**
**East** **90 COLUMBIA ST** **NY LTANKS** **NYD980534259**
**< 1/8** **BROOKLYN, NY 11201** **NY MANIFEST**
**0.005 mi.** **NJ MANIFEST**
**26 ft.** **Site 7 of 8 in cluster B** **NY Spills**

**Relative: Higher**

**Actual: 10 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | PORT AUTHORITY BROOKLYN PIERS (NYMT) |
| Facility address: | 90 COLUMBIA ST<br>BROOKLYN, NY 11201 |
| EPA ID: | NYD980534259 |
| Mailing address: | COLUMBIA ST<br>BROOKLYN, NY 11201 |
| Contact: | RICHARD HACKER |
| Contact address: | COLUMBIA ST<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | (718) 330-2976 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | Not reported |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | Not reported |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Classification: Not a generator, verified

Date form received by agency: 03/02/2002
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Site name: PORT AUTHORITY BROOKLYHN PIERS (NYMT)
Classification: Large Quantity Generator

Date form received by agency: 05/12/1998
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Site name: BROOKLYN PORT AUTHORITY MARINE TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 02/29/1996
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Site name: BROOKLYN PORT AUTHORITY MARINE TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 12/17/1981
Facility name: PORT AUTHORITY BROOKLYN PIERS (NYMT)
Site name: BROOKLYN PA MARINE TERMINAL
Classification: Large Quantity Generator

Violation Status: No violations found

LTANKS:
Site ID: 195364
Spill Number/Closed Date: 9203457 / 7/9/1992
Spill Date: 6/20/1992
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 7/9/1992

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Cleanup Meets Standard: | True |
| SWIS: | 2401 |
| Investigator: | O'DOWD |
| Referred To: | Not reported |
| Reported to Dept: | 6/23/1992 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/29/1992 |
| Spill Record Last Update: | 12/4/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 171920 |
| DEC Memo: | Not reported |
| Remarks: | 550; VISUAL LEAK, TANKNOLOGY R & R. |

Material:

| | |
|---|---|
| Site ID: | 195364 |
| Operable Unit ID: | 967262 |
| Operable Unit: | 01 |
| Material ID: | 411249 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 195365 |
| Spill Number/Closed Date: | 9204113 / 2/23/1993 |
| Spill Date: | 7/9/1992 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | 2/23/1993 |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | KSTANG |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 7/9/1992 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/14/1992 |
| Spill Record Last Update: | 5/12/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 171920 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG" |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 195365 |
| Operable Unit ID: | 967922 |
| Operable Unit: | 01 |
| Material ID: | 411863 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 195365 |
| Spill Tank Test: | 1540214 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Unknown |

| | |
|---|---|
| Site ID: | 195366 |
| Spill Number/Closed Date: | 9509127 / 2/28/2003 |
| Spill Date: | 10/24/1995 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 10/24/1995 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/24/1995 |
| Spill Record Last Update: | 2/28/2003 |
| Spiller Name: | DORIAN |
| Spiller Company: | BROOKLYN PORT AUTH |
| Spiller Address: | 90 COLUMBIA ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 001 |
| Spiller Contact: | DORIAN |
| Spiller Phone: | (201) 216-2993 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 171920 |
| DEC Memo: | Not reported |
| Remarks: | TANK TESTED AND FAILED |

Material:

| | |
|---|---|
| Site ID: | 195366 |
| Operable Unit ID: | 1019699 |
| Operable Unit: | 01 |
| Material ID: | 360090 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD980534259 |
| Country: | USA |
| Mailing Name: | PORT AUTHORITY OF NY & NJ |
| Mailing Contact: | GUSTAVE GUSTAFSON |
| Mailing Address: | 90 COLUMBIA ST |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-330-2974 |

| | |
|---|---|
| Document ID: | NYO1522701 |
| Manifest Status: | TSDF copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 820107 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 811224 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | Not reported |
| Waste Code: | Not reported |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | 82 |

| | |
|---|---|
| Document ID: | NYO1522701 |
| Manifest Status: | Generator copy |
| Trans1 State ID: | NH002 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 811223 |
| Trans1 Recv Date: | 811223 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NHD018902874 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NHD018902874 |
| Waste Code: | B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC |
| Quantity: | 00120 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00003 |
| Units: | Y - Cubic yards* (.85 tons) |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00005 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00700 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Year: | 80-81 |

| | |
|---|---|
| Document ID: | NYO1881378 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NYJA020 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 830909 |
| Trans1 Recv Date: | 830909 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 830912 |
| Part A Recv Date: | 030920 |
| Part B Recv Date: | 030920 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NJD000692061 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHD000816629 |
| Waste Code: | B011 - PCB CONTAMINATED TRANS CONT >500 PPM |
| Quantity: | 00225 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 003 |
| Container Type: | DT - Dump trucks |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Year: | 83 |

| | |
|---|---|
| Document ID: | NYO2924496 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NYJA045 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 840910 |
| Trans1 Recv Date: | 840910 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 840910 |
| Part A Recv Date: | 840920 |
| Part B Recv Date: | 840929 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NJD991291105 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 00190 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 005 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 84 |

| | |
|---|---|
| Document ID: | PAB0938851 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | PA-AHNJSW |
| Trans2 State ID: | PA-AH |
| Generator Ship Date: | 841012 |
| Trans1 Recv Date: | 841012 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 841012 |
| Part A Recv Date: | 850308 |
| Part B Recv Date: | 841024 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NJD084044064 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD084044064 |
| Waste Code: | X726 - MISC OIL/GAS PRODUCTS (NJ ONLY) |
| Quantity: | 00100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 84 |

| | |
|---|---|
| Document ID: | NYA1464453 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PA015-TJ4 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 850319 |
| Trans1 Recv Date: | 850319 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 850320 |
| Part A Recv Date: | 850325 |
| Part B Recv Date: | 850326 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | PAD064035819 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | B011 - PCB CONTAMINATED TRANS CONT >500 PPM |
| Quantity: | 04550 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CM - Metal boxes, cases, roll-offs |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Year: | 85 |
| Document ID: | NYA3216868 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | V96685NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 861204 |
| Trans1 Recv Date: | 861204 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 861205 |
| Part A Recv Date: | 861212 |
| Part B Recv Date: | 861209 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NYD051809952 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB |
| Quantity: | 08990 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | CM - Metal boxes, cases, roll-offs |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 86 |
| Document ID: | NYA3807235 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | K65046NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 861210 |
| Trans1 Recv Date: | 861210 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 861211 |
| Part A Recv Date: | 870121 |
| Part B Recv Date: | 861216 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NYD051809952 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB |
| Quantity: | 08724 |
| Units: | P - Pounds |
| Number of Containers: | 003 |
| Container Type: | CM - Metal boxes, cases, roll-offs |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00350 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 010 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00350 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 86 |

| | |
|---|---|
| Document ID: | NJA0333746 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | NY-JA045 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 881104 |
| Trans1 Recv Date: | 881104 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 881104 |
| Part A Recv Date: | 881109 |
| Part B Recv Date: | 881220 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | NJD991291105 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 03100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 88 |

| | |
|---|---|
| Document ID: | NYA7927182 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 890301 |
| Trans1 Recv Date: | 890301 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890302 |
| Part A Recv Date: | 890316 |
| Part B Recv Date: | 890308 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | MOD095038998 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | TND980729305 |
| Waste Code: | B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB |
| Quantity: | 09000 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CM - Metal boxes, cases, roll-offs |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA7927092 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 890126 |
| Trans1 Recv Date: | 890126 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890127 |
| Part A Recv Date: | 890208 |
| Part B Recv Date: | 890213 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | MOD095038998 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | TND980729305 |
| Waste Code: | B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB |
| Quantity: | 06000 |
| Units: | P - Pounds |
| Number of Containers: | 006 |
| Container Type: | CM - Metal boxes, cases, roll-offs |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9648472 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PL7754NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 891020 |
| Trans1 Recv Date: | 891023 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 891023 |
| Part A Recv Date: | 891031 |
| Part B Recv Date: | 891027 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00172 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYB1963980 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | MO-64801 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 900207 |
| Trans1 Recv Date: | 900207 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900208 |
| Part A Recv Date: | 900406 |
| Part B Recv Date: | 900315 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

Generator EPA ID: NYD980534259
Trans1 EPA ID: MOD095038998
Trans2 EPA ID: Not reported
TSDF ID: TND980729305
Waste Code: B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity: 03100
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: L Landfill.
Specific Gravity: 100
Year: 90

Document ID: NYA9443248
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890721
Trans1 Recv Date: 890721
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890721
Part A Recv Date: 890815
Part B Recv Date: 890802
Generator EPA ID: NYD980534259
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00172
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYA9640023
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890823
Trans1 Recv Date: 890823
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890823
Part A Recv Date: 890913
Part B Recv Date: 890829
Generator EPA ID: NYD980534259
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00172
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYA9775563
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 891122
Trans1 Recv Date: 891122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 891122
Part A Recv Date: 891205
Part B Recv Date: 891204
Generator EPA ID: NYD980534259
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00172
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYB1963998
Manifest Status: Completed copy
Trans1 State ID: H10PC708
Trans2 State ID: Not reported
Generator Ship Date: 900207
Trans1 Recv Date: 900207
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900208
Part A Recv Date: 900223
Part B Recv Date: 900226
Generator EPA ID: NYD980534259
Trans1 EPA ID: ARD069748192
Trans2 EPA ID: Not reported
TSDF ID: TND980729305
Waste Code: B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity: 01915
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90

Document ID: NYC0227193
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Generator Ship Date: | 900522 |
| Trans1 Recv Date: | 900522 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900522 |
| Part A Recv Date: | 900712 |
| Part B Recv Date: | 900530 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00172 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0317081 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900607 |
| Trans1 Recv Date: | 900607 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900607 |
| Part A Recv Date: | 900730 |
| Part B Recv Date: | 900618 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00172 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0163956 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900327 |
| Trans1 Recv Date: | 900327 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900327 |
| Part A Recv Date: | 900419 |
| Part B Recv Date: | 900406 |
| Generator EPA ID: | NYD980534259 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| TSDF ID: | NYD980785760 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00172 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 90 |

Click this hyperlink while viewing on your computer to access
83 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

| | |
|---|---|
| Manifest Code: | 006015827JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 06/03/2009 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 06/03/2009 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 06/03/2009 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D008 |
| Manifest Year: | 2009 New Jersey Manifest Data |
| Quantity: | 300 |
| Unit: | P |
| Hand Code: | H111 |

| | |
|---|---|
| Manifest Code: | 005370213JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 04/24/2009 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 04/24/2009 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 05/24/2009 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2009 New Jersey Manifest Data |
| Quantity: | 25 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Waste Code: | D001 |
| Manifest Year: | 2009 New Jersey Manifest Data |
| Quantity: | 55 |
| Unit: | G |
| Hand Code: | H061 |

| | |
|---|---|
| Manifest Code: | 005972826JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 03/17/2010 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 03/17/2010 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 03/17/2010 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 110 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 007939649JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 12/20/2010 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 12/20/2010 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 12/20/2010 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 5 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Waste Code: | D001 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 5 |
| Unit: | G |
| Hand Code: | H061 |

| | |
|---|---|
| Waste Code: | D001 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 55 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Waste Code: | D039 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 5 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 005974858JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 09/09/2009 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 09/09/2009 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Date TSDF Received Waste: | 09/09/2009 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2009 New Jersey Manifest Data |
| Quantity: | 10 |
| Unit: | P |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 1.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 2.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 3.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 4.00 |
| Waste Type Code 2: | D035 |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 7.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 6.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| | |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| | |
| Waste Code: | D001 |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| | |
| Manifest Code: | 008401312JJK |
| EPA ID: | NYD980534259 |
| Date Shipped: | 7/27/2011 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NJD980772768 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | PORT AUTH NY/NJ @ BROOKLYN PIERS |
| Transporter-1 EPA Facility Name: | AUCHTER INDUSTRIAL VAC SERVICE INC |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | CLEAN EARTH OF NORTH JERSEY INC |
| QTY Units: | gallons |
| Transporter SEQ ID: | 1.00 |
| Transporter-1 Date: | 7/27/2011 |
| Waste SEQ ID: | 5.00 |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | 7/27/2011 |
| Manifest Discrepancy Type: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | Not reported |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H061 |
| Waste Code: | U226 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 5.00 |
| Unit: | gallons |
| Hand Code: | H040 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 55.00 |
| Unit: | gallons |
| Hand Code: | H141 |
| Waste Code: | D001 |
| Manifest Year: | 2011 New Jersey Manifest Data |
| Quantity: | 110.00 |
| Unit: | gallons |
| Hand Code: | H141 |

SPILLS:

| | |
|---|---|
| Facility ID: | 9708468 |
| Facility Type: | ER |
| DER Facility ID: | 171920 |
| Site ID: | 207137 |
| DEC Region: | 2 |
| Spill Date: | 10/20/1997 |
| Spill Number/Closed Date: | 9708468 / 7/1/2013 |
| Spill Cause: | Housekeeping |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

| | |
|---|---|
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 10/20/1997 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/20/1997 |
| Spill Record Last Update: | 7/1/2013 |
| Spiller Name: | CHRISTOPHER JONES |
| Spiller Company: | PORT AUTHORITY OF NY & NJ |
| Spiller Address: | 1 WORLD TRADE CENTER |
| Spiller City,St,Zip: | NEW YORK, NY 10048- |
| Spiller Company: | 001 |
| Contact Name: | CHRISTOPHER JONES |
| Contact Phone: | (718) 330-2976 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"3/11/03 - SAMUEL- File available in active unassigned spill files.4/12/04-Vought-Spill transferred from Tomasello to Rommel as per Rommel.7/27/05 TASLeft message.11/1/05 TASSent letter requesting information. Additional followup and a site visit should be performed.From TXSmith - ttransferred back to R-23/31/09 - Austin - Transferred from Needs Reassignment to Rahman for further work to remeidate and close - end01/11/13 performed site visit. tanks were closed in place. Facility rep Timothy Gard,718-330-2975, 917-533-4360, email: tgard@panynj.gov, said he would look for any available report associated with the contaminated soil removal.(sr)** Bill Glen, 973-565-7565** Port Authority.07/01/13 Remediation of this spill was performed under spill #0612593.As per limited available information provided by Port Authority, this spill 9708468 is located within the Pier 7 investigation area(spill 0612593).See the spill report 0612593.(sr) |
| Remarks: | SOIL CONTAMINATION FOUND DURING REMOVAL OF 1000 GALLON UNDERGROUND STORAGE TANK. APPROXIMATELY 30 YARDS OF SOIL AT MOST. SOIL TO BE STOCKPILED AS NECESSARY. |

Material:

| | |
|---|---|
| Site ID: | 207137 |
| Operable Unit ID: | 1051669 |
| Operable Unit: | 01 |
| Material ID: | 330441 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |

**PORT AUTHORITY BROOKLYN PIERS (NYMT) (Continued)** **1000333148**

Oxygenate: False

Tank Test:

---

**D47**
**SSE**
**< 1/8**
**0.005 mi.**
**27 ft.**

**LOT 3,TAXBLOCK 319**
**181 COLUMBIA STREET**
**BROOKLYN, NY 11231**

**NY E DESIGNATION** **S108469976**
**N/A**

**Site 2 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 3 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | MARIE MANCINI |
| Lot Area: | 000001600 |
| Total Building Floor Area: | 00000002400 |
| Commercial Floor Area: | 00000000800 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000800 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |

**LOT 3,TAXBLOCK 319 (Continued)** **S108469976**

| | |
|---|---|
| Lot Frontage: | 0020.08 |
| Lot Depth: | 0080.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000005582 |
| Total Assessed Value: | 00000016484 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000001430 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.50 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190003 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983700 |
| Y Coordinate: | 0189153 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J48** **ROADWAY** **NY Spills** **S103570363**
**SE** **COLUMBIA ST/IRVING PL** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**27 ft.** **Site 1 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9614062 |
| Facility Type: | ER |
| DER Facility ID: | 76434 |
| Site ID: | 82992 |
| DEC Region: | 2 |
| Spill Date: | 3/3/1997 |
| Spill Number/Closed Date: | 9614062 / 3/4/1997 |
| Spill Cause: | Other |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |

**ROADWAY (Continued)** **S103570363**

| | |
|---|---|
| Investigator: | ADZHITOM |
| Referred To: | Not reported |
| Reported to Dept: | 3/3/1997 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/3/1997 |
| Spill Record Last Update: | 3/7/1997 |
| Spiller Name: | ERIC JONES |
| Spiller Company: | NYC TRANSIT |
| Spiller Address: | 666 WEST 133RD ST |
| Spiller City,St,Zip: | NEWYORK, NY |
| Spiller Company: | 001 |
| Contact Name: | ERIC JONES |
| Contact Phone: | (718) 243-4581 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"SAME AS SPILL# 9614063. |
| Remarks: | DIESEL TANK FELL OUT OF PLACE AND CAUSED SPILL OF UNK AMTDIESEL FUEL ONTO ROADWAY-HAS BEEN CLEANED UP |

Material:

| | |
|---|---|
| Site ID: | 82992 |
| Operable Unit ID: | 1045495 |
| Operable Unit: | 01 |
| Material ID: | 339167 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**H49** **MANHOLE 57960** **NY Spills** **S106017451**
**SSW** **IMLAY ST AT BOWNE ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**27 ft.** **Site 2 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0305504 |
| Facility Type: | ER |
| DER Facility ID: | 179477 |
| Site ID: | 216760 |
| DEC Region: | 2 |
| Spill Date: | 8/22/2003 |

**MANHOLE 57960 (Continued)** **S106017451**

| | |
|---|---|
| Spill Number/Closed Date: | 0305504 / 9/19/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 8/23/2003 |
| CID: | 199 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/23/2003 |
| Spill Record Last Update: | 9/22/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | TOM MARCINEK |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"e2mis no. 149-975:8-22-03 09:45HRS D.BROWN (U.G) REPORTS, FOUND ONE PINT OF UNKNOWN OIL ON 25 GALLONS OF WATER IN MH 57960. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. NO SEWER CONNECTION OR SUMPS NOTICED. ONE LIQUID SAMPLE WAS TAKEN.8/22/03 16:22 HRS. -- PCB RESULTS: <1.0 PPM, LAB SEQ 03-06956.UPDATE 23-AUG-2003 06:43 HRSDUE TO SYSTEM EMERGENCY, INCIDENT #149975 WILL NOT BE MEETING THE 24 HR. CRITERIA. SPILL WILL BE RECLASSIFIED AS SPILL UNKNOWN OIL.UPDATE: 9/3/03 - 1335J. DELAROSA - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH SLIX. TAG # 29592 REMOVED. UNABLE TOCEMENT SUMP DUE TO STRUCTURE MAKING WATER. TJ - 50495 |
| Remarks: | 1 pt on 25 gal of water - unk oil -- spill taken off 24 hrremediation at 0643 - due to crew had to be pulled to work on an emergency situtation con ed spill #149975 |

Material:

| | |
|---|---|
| Site ID: | 216760 |
| Operable Unit ID: | 873944 |
| Operable Unit: | 01 |
| Material ID: | 502755 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**MANHOLE 57960 (Continued)** **S106017451**

Tank Test:

---

**D50** **LOT 4,TAXBLOCK 319** **NY E DESIGNATION** **S108469986**
**SSE** **179 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.005 mi.**
**27 ft.** **Site 3 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 4 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | B1 |
| Land Use Category: | 01 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | ASHLAND CENTER LLC |
| Lot Area: | 000001537 |
| Total Building Floor Area: | 00000003173 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0019.10 |
| Lot Depth: | 0077.60 |

**LOT 4,TAXBLOCK 319 (Continued)** **S108469986**

| | |
|---|---|
| Building Frontage: | 0019.83 |
| Building Depth: | 0040.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 0 |
| Land Assessed Value: | 00000005316 |
| Total Assessed Value: | 00000028728 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 2001 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.06 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190004 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983675 |
| Y Coordinate: | 0189184 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**H51** **EXTECH BUILDING MATERIALS** **FINDS** **1016393699**
**SSW** **87 BOWNE ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**28 ft.** **Site 3 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

FINDS:

Registry ID: 110055274965

Environmental Interest/Information System

**D52** **169 COLUMBIA ST** **NY Spills** **S102560396**
**SSE** **169 COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**28 ft.** **Site 4 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9614063 |
| Facility Type: | ER |
| DER Facility ID: | 117235 |
| Site ID: | 137034 |
| DEC Region: | 2 |
| Spill Date: | 3/3/1997 |
| Spill Number/Closed Date: | 9614063 / 3/3/1997 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | ADZHITOM |
| Referred To: | Not reported |
| Reported to Dept: | 3/3/1997 |
| CID: | 297 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/3/1997 |
| Spill Record Last Update: | 3/7/1997 |
| Spiller Name: | ERIC JONES |
| Spiller Company: | NYC TRANSIT |
| Spiller Address: | 666 WEST 133RD ST |
| Spiller City,St,Zip: | NEWYORK, NY |
| Spiller Company: | 001 |
| Contact Name: | FF CONFESSORE |
| Contact Phone: | (917) 769-0483 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"REFER TO SPILL 9614062. |
| Remarks: | A NYC TRANSIT BUS COLLIDED WITH A TRACTOR TRAILER CAUSING A RUPTURE IN THE FUEL TANK AND SPILLING THE DIESEL ONTO THE GROUND - SPILL HAS BEEN CONTAINED AND UNKNOWN AMOUNT DID GO INTO A SEWER |

Material:

| | |
|---|---|
| Site ID: | 137034 |
| Operable Unit ID: | 1041621 |
| Operable Unit: | 01 |
| Material ID: | 339168 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 50 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**169 COLUMBIA ST (Continued)** **S102560396**

Tank Test:

---

**J53** **COLUMBIA & KANE STS** **NY Spills** **S102148750**
**SE** **KANE & COLUMBIA STS PIER** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.005 mi.**
**28 ft.** **Site 2 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9408094 |
| Facility Type: | ER |
| DER Facility ID: | 180897 |
| Site ID: | 218691 |
| DEC Region: | 2 |
| Spill Date: | 9/19/1994 |
| Spill Number/Closed Date: | 9408094 / 4/25/1995 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 9/19/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 4/25/1995 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/28/1994 |
| Spill Record Last Update: | 10/21/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | PILE OF WHITE SUBSTANCE - NO ONE IS INVESTIGATING-FAX TO DEP |

Material:

| | |
|---|---|
| Site ID: | 218691 |
| Operable Unit ID: | 1002231 |
| Operable Unit: | 01 |
| Material ID: | 567134 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |

**COLUMBIA & KANE STS (Continued)** **S102148750**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**D54** **LOT 10,TAXBLOCK 319** **NY E DESIGNATION** **S108469956**
**SSE** **167 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.005 mi.**
**29 ft.** **Site 5 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 10 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | 40 TIFFANY CORP |
| Lot Area: | 000001865 |
| Total Building Floor Area: | 00000002400 |
| Commercial Floor Area: | 00000000800 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000800 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |

**LOT 10,TAXBLOCK 319 (Continued)** **S108469956**

| | |
|---|---|
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0019.92 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.92 |
| Building Depth: | 0052.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000007363 |
| Total Assessed Value: | 00000020148 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.29 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983712 |
| Y Coordinate: | 0189295 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D55** **LOT 11,TAXBLOCK 319** **NY E DESIGNATION** **S108469957**
**SSE** **165 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.005 mi.**
**29 ft.** **Site 6 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 11 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |

**LOT 11,TAXBLOCK 319 (Continued)** **S108469957**

| | |
|---|---|
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SOUTH BKLYN RENEWALAS |
| Lot Area: | 000001950 |
| Total Building Floor Area: | 00000003120 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0052.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 0 |
| Land Assessed Value: | 00000003897 |
| Total Assessed Value: | 00000019374 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000014822 |
| Year Built: | 1901 |
| Year Built Code: | E |
| Year Altered1: | 1992 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.60 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190011 |

**LOT 11,TAXBLOCK 319 (Continued)** **S108469957**

| | |
|---|---|
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983754 |
| Y Coordinate: | 0189302 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D56** **LOT 16,TAXBLOCK 319** **NY E DESIGNATION** **S108469962**
**SSE** **157 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.005 mi.**
**29 ft.** **Site 7 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 16 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | ACCARDI, DAVID J |
| Lot Area: | 000001828 |
| Total Building Floor Area: | 00000003574 |

**LOT 16,TAXBLOCK 319 (Continued)** **S108469962**

| | |
|---|---|
| Commercial Floor Area: | 00000001746 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001746 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0018.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.00 |
| Building Depth: | 0098.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000002742 |
| Total Assessed Value: | 00000038280 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1985 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.96 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190016 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983757 |
| Y Coordinate: | 0189406 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**K57** **DRUM RUN** **NY Spills** **S111835339**
**ENE** **60 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.006 mi.**
**30 ft.** **Site 1 of 2 in cluster K**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1200175 |
| Facility Type: | ER |
| DER Facility ID: | 417210 |
| Site ID: | 462793 |
| DEC Region: | 2 |
| Spill Date: | 4/6/2012 |
| Spill Number/Closed Date: | 1200175 / 4/20/2012 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RMPIPER |
| Referred To: | Not reported |
| Reported to Dept: | 4/6/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/6/2012 |
| Spill Record Last Update: | 4/20/2012 |
| Spiller Name: | ABRAM GEORGY |
| Spiller Company: | UNKNOWN |
| Spiller Address: | 60 COLUMBIA STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ABRAM GEORGY |
| Contact Phone: | (347) 768-1478 |
| DEC Memo: | drum is 1 block away from 60 Columbianot found. Spill closed. |
| Remarks: | 5 gallon drum |

Material:

| | |
|---|---|
| Site ID: | 462793 |
| Operable Unit ID: | 1212893 |
| Operable Unit: | 01 |
| Material ID: | 2210764 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**D58** **LOT 12,TAXBLOCK 319** **NY E DESIGNATION** **S108469958**
**SSE** **163 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 8 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 12 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | HOUSING PRESERVATION |
| Lot Area: | 000001991 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.42 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0052.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |

**LOT 12,TAXBLOCK 319 (Continued)** **S108469958**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022500 |
| Total Assessed Value: | 00000023400 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190012 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983727 |
| Y Coordinate: | 0189335 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D59** **LOT 14,TAXBLOCK 319** **NY E DESIGNATION** **S108469960**
**SSE** **159A COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 9 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 14 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 14,TAXBLOCK 319 (Continued)** **S108469960**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | 40 TIFFANY CORP |
| Lot Area: | 000001828 |
| Total Building Floor Area: | 00000003600 |
| Commercial Floor Area: | 00000000900 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000900 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0018.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.00 |
| Building Depth: | 0045.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000007720 |
| Total Assessed Value: | 00000034273 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 1985 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.97 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190014 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983743 |
| Y Coordinate: | 0189370 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 14,TAXBLOCK 319 (Continued)** **S108469960**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D60** **LOT 15,TAXBLOCK 319** **NY E DESIGNATION** **S108469961**
**SSE** **159 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 10 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 15 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C3 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SOUTH BKLYN RENEWALAS |
| Lot Area: | 000001828 |
| Total Building Floor Area: | 00000003600 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |

**LOT 15,TAXBLOCK 319 (Continued)** **S108469961**

| | |
|---|---|
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0018.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0018.75 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000006179 |
| Total Assessed Value: | 00000085995 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000076306 |
| Year Built: | 1900 |
| Year Built Code: | Not reported |
| Year Altered1: | 1992 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.97 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190015 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983780 |
| Y Coordinate: | 0189377 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D61** **LOT 17,TAXBLOCK 319** **NY E DESIGNATION** **S108469963**
**SSE** **155 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 11 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 17 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |

**LOT 17,TAXBLOCK 319 (Continued)** **S108469963**

| | |
|---|---|
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | O CONNELL GREGORY |
| Lot Area: | 000001828 |
| Total Building Floor Area: | 00000003600 |
| Commercial Floor Area: | 00000000900 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000900 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0018.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0018.75 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000001520 |
| Total Assessed Value: | 00000006392 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.97 |

**LOT 17,TAXBLOCK 319 (Continued)** **S108469963**

| | |
|---|---|
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190017 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983794 |
| Y Coordinate: | 0189412 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D62** **EDR US Hist Cleaners** **1014994834**
**SSE** **147 COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 12 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | HORIZON CARPET CLEANING |
| Year: | 2002 |
| Address: | 147 COLUMBIA ST |
| Name: | HORIZON CARPET CLEANING |
| Year: | 2003 |
| Address: | 147 COLUMBIA ST |
| Name: | BROADWAY CARPET CLEANING |
| Year: | 2008 |
| Address: | 147 COLUMBIA ST |

---

**D63** **LOT 19,TAXBLOCK 319** **NY E DESIGNATION** **S108469965**
**SSE** **151 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**30 ft.** **Site 13 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 19 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |

**LOT 19,TAXBLOCK 319 (Continued)** **S108469965**

| | |
|---|---|
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C3 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SOUTH BKLYN RENEWALAS |
| Lot Area: | 000001820 |
| Total Building Floor Area: | 00000003700 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0018.67 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0018.67 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000002875 |
| Total Assessed Value: | 00000034889 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000028554 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 1993 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.03 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |

**LOT 19,TAXBLOCK 319 (Continued)** **S108469965**

| | |
|---|---|
| Borough Tax Block And Lot: | 3003190019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983806 |
| Y Coordinate: | 0189446 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D64** **LOT 18,TAXBLOCK 319** **NY E DESIGNATION** **S108469964**
**SSE** **153 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**31 ft.** **Site 14 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 18 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | O CONNELL GREGORY |
| Lot Area: | 000001828 |

**LOT 18,TAXBLOCK 319 (Continued)** **S108469964**

| | |
|---|---|
| Total Building Floor Area: | 00000003600 |
| Commercial Floor Area: | 00000000900 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000900 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0018.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0018.75 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000002780 |
| Total Assessed Value: | 00000011694 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1993 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.97 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190018 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983769 |
| Y Coordinate: | 0189441 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**D65** **LOT 20,TAXBLOCK 319** **NY E DESIGNATION** **S108469967**
**SSE** **149 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**31 ft.** **Site 15 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 20 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SOUTH BKLYN RENEWALAS |
| Lot Area: | 000001976 |
| Total Building Floor Area: | 00000005200 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00007 |
| Non and Residential Units: | 00007 |
| Lot Frontage: | 0026.00 |
| Lot Depth: | 0076.00 |
| Building Frontage: | 0026.00 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 20,TAXBLOCK 319 (Continued)** **S108469967**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000008891 |
| Total Assessed Value: | 00000101970 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000065155 |
| Year Built: | 1900 |
| Year Built Code: | Not reported |
| Year Altered1: | 1993 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.63 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983783 |
| Y Coordinate: | 0189479 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D66** **LOT 24,TAXBLOCK 319** **NY E DESIGNATION** **S108469970**
**SSE** **145 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**31 ft.** **Site 16 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 24 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 24,TAXBLOCK 319 (Continued)** **S108469970**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | JACK L. IRWIN |
| Lot Area: | 000001869 |
| Total Building Floor Area: | 00000003800 |
| Commercial Floor Area: | 00000000950 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000950 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0019.17 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000008927 |
| Total Assessed Value: | 00000039985 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 1985 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.03 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190024 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983835 |
| Y Coordinate: | 0189522 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 24,TAXBLOCK 319 (Continued)** **S108469970**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D67** **LOT 25,TAXBLOCK 319** **NY E DESIGNATION** **S108469971**
**SSE** **143 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**32 ft.** **Site 17 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 25 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SOUTH BKLYN RENEWALAS |
| Lot Area: | 000001926 |
| Total Building Floor Area: | 00000004800 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |

**LOT 25,TAXBLOCK 319 (Continued)** **S108469971**

| | |
|---|---|
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00008 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0019.75 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.75 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000005507 |
| Total Assessed Value: | 00000060582 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000051005 |
| Year Built: | 1900 |
| Year Built Code: | Not reported |
| Year Altered1: | 1994 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.49 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190025 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983811 |
| Y Coordinate: | 0189552 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J68** **LOT 26,TAXBLOCK 319** **NY E DESIGNATION** **S108469972**
**SE** **139 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**32 ft.** **Site 3 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 26 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |

**LOT 26,TAXBLOCK 319 (Continued)** **S108469972**

| | |
|---|---|
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | B1 |
| Land Use Category: | 01 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | CASANOVA, SAHYLI |
| Lot Area: | 000001786 |
| Total Building Floor Area: | 00000004704 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0018.30 |
| Lot Depth: | 0097.60 |
| Building Frontage: | 0036.50 |
| Building Depth: | 0043.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 0 |
| Land Assessed Value: | 00000006912 |
| Total Assessed Value: | 00000035955 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000030473 |
| Year Built: | 2001 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.63 |

**LOT 26,TAXBLOCK 319 (Continued)** **S108469972**

| | |
|---|---|
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190026 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983851 |
| Y Coordinate: | 0189566 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J69** **LOT 29,TAXBLOCK 319** **NY E DESIGNATION** **S108469975**
**SE** **133 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**32 ft.** **Site 4 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 29 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | B1 |
| Land Use Category: | 01 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |

**LOT 29,TAXBLOCK 319 (Continued)** **S108469975**

| | |
|---|---|
| Owner Name: | ERIC STRAUSS |
| Lot Area: | 000001786 |
| Total Building Floor Area: | 00000003367 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0018.30 |
| Lot Depth: | 0097.60 |
| Building Frontage: | 0026.00 |
| Building Depth: | 0043.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 0 |
| Land Assessed Value: | 00000007140 |
| Total Assessed Value: | 00000034980 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000029270 |
| Year Built: | 2001 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.89 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190029 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983839 |
| Y Coordinate: | 0189621 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**J70** **LOT 27,TAXBLOCK 319** **NY E DESIGNATION** **S108469973**
**SE** **137 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**32 ft.** **Site 5 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 27 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | B1 |
| Land Use Category: | 01 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | DANIELLE WYNN |
| Lot Area: | 000001757 |
| Total Building Floor Area: | 00000003240 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0018.00 |
| Lot Depth: | 0097.60 |
| Building Frontage: | 0018.00 |
| Building Depth: | 0060.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 27,TAXBLOCK 319 (Continued)** **S108469973**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000006594 |
| Total Assessed Value: | 00000035955 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000029361 |
| Year Built: | 2002 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.84 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190027 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983821 |
| Y Coordinate: | 0189589 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J71** **LOT 37,TAXBLOCK 319** **NY E DESIGNATION** **S108469984**
**SE** **117 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**32 ft.** **Site 6 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 37 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 37,TAXBLOCK 319 (Continued)** **S108469984**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | O'CONNELL GREGORY |
| Lot Area: | 000001509 |
| Total Building Floor Area: | 00000002640 |
| Commercial Floor Area: | 00000000880 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000880 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0022.92 |
| Lot Depth: | 0076.08 |
| Building Frontage: | 0022.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000005077 |
| Total Assessed Value: | 00000012820 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.75 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190037 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983914 |
| Y Coordinate: | 0189769 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 37,TAXBLOCK 319 (Continued)** **S108469984**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J72** **LOT 30,TAXBLOCK 319** **NY E DESIGNATION** **S108469977**
**SE** **131 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**33 ft.** **Site 7 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 30 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GROSS DAVID |
| Lot Area: | 000002543 |
| Total Building Floor Area: | 00000006240 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |

**LOT 30,TAXBLOCK 319 (Continued)** **S108469977**

| | |
|---|---|
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00016 |
| Non and Residential Units: | 00016 |
| Lot Frontage: | 0026.08 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0026.00 |
| Building Depth: | 0053.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000014715 |
| Total Assessed Value: | 00000132300 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1910 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.45 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190030 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983843 |
| Y Coordinate: | 0189640 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**L73** **LOT 6,TAXBLOCK 309** **NY E DESIGNATION** **S108470031**
**ESE** **111 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.006 mi.**
**33 ft.** **Site 1 of 3 in cluster L**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 3 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | LUIS RIVERA |
| Lot Area: | 000002036 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.50 |
| Lot Depth: | 0079.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004406 |
| Total Assessed Value: | 00000030832 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000027856 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.49 |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090003 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983938 |
| Y Coordinate: | 0189904 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | E-36 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 3 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | LUIS RIVERA |
| Lot Area: | 000002036 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.50 |
| Lot Depth: | 0079.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004406 |
| Total Assessed Value: | 00000030832 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000027856 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.49 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090003 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983938 |
| Y Coordinate: | 0189904 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | E-36 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 6 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | NANCY JORGENSEN |
| Lot Area: | 000002350 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.50 |
| Lot Depth: | 0079.33 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006248 |
| Total Assessed Value: | 00000031014 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000026196 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.29 |
| Maximum Allowable Far: | 02.43 |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090006 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983991 |
| Y Coordinate: | 0189907 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 6 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | NANCY JORGENSEN |
| Lot Area: | 000002350 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |

**LOT 6,TAXBLOCK 309 (Continued)** **S108470031**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.50 |
| Lot Depth: | 0079.33 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006248 |
| Total Assessed Value: | 00000031014 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000026196 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.29 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090006 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983991 |
| Y Coordinate: | 0189907 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**J74** **LOT 28,TAXBLOCK 319** **NY E DESIGNATION** **S108469974**
**SE** **135 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**33 ft.** **Site 8 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 28 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | B1 |
| Land Use Category: | 01 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | SANGIRARDI, JOYCE |
| Lot Area: | 000001757 |
| Total Building Floor Area: | 00000001281 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0018.00 |
| Lot Depth: | 0097.60 |
| Building Frontage: | 0009.70 |
| Building Depth: | 0043.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 28,TAXBLOCK 319 (Continued)** **S108469974**

| | |
|---|---|
| Basement Type Grade: | 0 |
| Land Assessed Value: | 00000007860 |
| Total Assessed Value: | 00000030000 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000023570 |
| Year Built: | 2001 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.73 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190028 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983847 |
| Y Coordinate: | 0189599 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J75** **LOT 36,TAXBLOCK 319** **NY E DESIGNATION** **S108469983**
**SE** **119 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**33 ft.** **Site 9 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 36 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 36,TAXBLOCK 319 (Continued)** **S108469983**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GREGORY OCONNELL |
| Lot Area: | 000001604 |
| Total Building Floor Area: | 00000002520 |
| Commercial Floor Area: | 00000000840 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000840 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0076.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000003037 |
| Total Assessed Value: | 00000009158 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.57 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190036 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983886 |
| Y Coordinate: | 0189758 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 36,TAXBLOCK 319 (Continued)** **S108469983**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J76** **LOT 34,TAXBLOCK 319** **NY E DESIGNATION** **S108469981**
**SE** **123 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**33 ft.** **Site 10 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 34 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | 121-123 COLUNBIA ST C |
| Lot Area: | 000001602 |
| Total Building Floor Area: | 00000002520 |
| Commercial Floor Area: | 00000000840 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000840 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |

**LOT 34,TAXBLOCK 319 (Continued)** **S108469981**

| | |
|---|---|
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0076.17 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000004366 |
| Total Assessed Value: | 00000013166 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.57 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190034 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983872 |
| Y Coordinate: | 0189720 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J77** **LOT 32,TAXBLOCK 319** **NY E DESIGNATION** **S108469979**
**SE** **127 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**33 ft.** **Site 11 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 32 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |

**LOT 32,TAXBLOCK 319 (Continued)** **S108469979**

| | |
|---|---|
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C3 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | DI CASOLI ELIZABETH |
| Lot Area: | 000002048 |
| Total Building Floor Area: | 00000003360 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000002286 |
| Total Assessed Value: | 00000022662 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.64 |

**LOT 32,TAXBLOCK 319 (Continued)** **S108469979**

| | |
|---|---|
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190032 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983865 |
| Y Coordinate: | 0189678 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J78** **LOT 35,TAXBLOCK 319** **NY E DESIGNATION** **S108469982**
**SE** **121 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**34 ft.** **Site 12 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 35 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S2 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |

**LOT 35,TAXBLOCK 319 (Continued)** **S108469982**

| | |
|---|---|
| Owner Name: | 121-123 COLUMBIA STRE |
| Lot Area: | 000001606 |
| Total Building Floor Area: | 00000002520 |
| Commercial Floor Area: | 00000000840 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000840 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00002 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.08 |
| Lot Depth: | 0076.17 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0040.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000003794 |
| Total Assessed Value: | 00000011352 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.57 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190035 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983901 |
| Y Coordinate: | 0189730 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**J79** **LOT 33,TAXBLOCK 319** **NY E DESIGNATION** **S108469980**
**SE** **125 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.006 mi.**
**34 ft.** **Site 13 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 33 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | O'CONNELLL, GREGORY |
| Lot Area: | 000002048 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 33,TAXBLOCK 319 (Continued)** **S108469980**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000023850 |
| Total Assessed Value: | 00000024300 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190033 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983898 |
| Y Coordinate: | 0189688 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**M80** **LOT 1,TAXBLOCK 319** **NY E DESIGNATION** **S108469955**
**SSE** **185 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.007 mi.**
**36 ft.** **Site 1 of 5 in cluster M**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 1 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 1,TAXBLOCK 319 (Continued)** **S108469955**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CHEUNG, YICK TAK |
| Lot Area: | 000001600 |
| Total Building Floor Area: | 00000001600 |
| Commercial Floor Area: | 00000001600 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001600 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0080.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0080.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 3 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000014400 |
| Total Assessed Value: | 00000032850 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1989 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190001 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983684 |
| Y Coordinate: | 0189119 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 1,TAXBLOCK 319 (Continued)** **S108469955**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**N81** **EDR US Hist Auto Stat** **1015604183**
**South** **70 DEGRAW ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.007 mi.**
**37 ft.** **Site 1 of 2 in cluster N**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | SHAFA CAR SERVICE |
| Year: | 2004 |
| Address: | 70 DEGRAW ST |

---

**D82** **LOT 23,TAXBLOCK 319** **NY E DESIGNATION** **S108469969**
**SSE** **147 COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.007 mi.**
**37 ft.** **Site 18 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 23 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S5 |
| Land Use Category: | 04 |

**LOT 23,TAXBLOCK 319 (Continued)** **S108469969**

| | |
|---|---|
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | ZAHA T AHMAD |
| Lot Area: | 000001804 |
| Total Building Floor Area: | 00000004088 |
| Commercial Floor Area: | 00000001022 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001022 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00002 |
| Number of Floors: | 004.00 |
| Residential Units: | 00006 |
| Non and Residential Units: | 00007 |
| Lot Frontage: | 0018.50 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0019.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000007271 |
| Total Assessed Value: | 00000079560 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 1989 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.27 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190023 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983798 |
| Y Coordinate: | 0189515 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**D83** **LOT 22,TAXBLOCK 319** **NY E DESIGNATION** **S108469968**
**SSE** **147A COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.007 mi.**
**37 ft.** **Site 19 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 22 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S5 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | ZAHA AHMAD |
| Lot Area: | 000001755 |
| Total Building Floor Area: | 00000004088 |
| Commercial Floor Area: | 00000001022 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001022 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00006 |
| Non and Residential Units: | 00007 |
| Lot Frontage: | 0018.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0018.00 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 22,TAXBLOCK 319 (Continued)** **S108469968**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000007070 |
| Total Assessed Value: | 00000079560 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 1992 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.33 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190022 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983822 |
| Y Coordinate: | 0189487 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D84** **ELITE CARPET & UPOLSTRY** **NY Spills** **S103036531**
**SSE** **147 COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.007 mi.**
**37 ft.** **Site 20 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9713602 |
| Facility Type: | ER |
| DER Facility ID: | 178867 |
| Site ID: | 216029 |
| DEC Region: | 2 |
| Spill Date: | 3/3/1998 |
| Spill Number/Closed Date: | 9713602 / 6/4/1998 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MCTIBBE |
| Referred To: | Not reported |
| Reported to Dept: | 3/9/1998 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Local Agency |

**ELITE CARPET & UPOLSTRY (Continued)** **S103036531**

| | |
|---|---|
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/9/1998 |
| Spill Record Last Update: | 5/13/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | ELITE CARPET & UPOLSTRY |
| Spiller Address: | 147 COLUMBIA ST |
| Spiller City,St,Zip: | BROOKLYN, BROOKLYN HGTS., NY |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | (800) 246-9034 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"KEITH WILLIAMS SAW SOME EVIDENCE OF DUMPING. OWNER STATES THAT IT IS WASHWATER FROM FLOOR MOPPING. BACKYARD IS CONCRETE WITH LANDSCAPE EDGES. TREE IN MIDDLE OF CONCRETE ALSO HAS A LOT OF DUMPING. NO ODORS OBSERVED. OWNER THRENTEND TO KILL NEIGHBOR WHO COMPLAINED. NO ODORS BUT RESIDUES ARE OBSERVED. TIBBE INSPECTED. JUST SOAPY WATER. NYCDEP ORDERED OWNER TO STOP DUMPING IN BACKYARD AND TO REMOVE SLOP SINK FROM BACKYARD AND TO CLEAN GARBAGE FROM BACKYARD. |
| Remarks: | employees dumping unk cleaning materials in rear yard |

Material:

| | |
|---|---|
| Site ID: | 216029 |
| Operable Unit ID: | 1059567 |
| Operable Unit: | 01 |
| Material ID: | 324607 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**B85** **LOT 1,TAXBLOCK 299** **NY RES DECL** **S109155493**
**ENE** **75 COLUMBIA STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.007 mi.**
**38 ft.** **Site 8 of 8 in cluster B**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-138 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532867 |
| Borough Code: | BK |
| Tax Block: | 299 |
| Tax Lot: | 1 |
| Community District: | 306 |
| Census Tract: | 47 |

**LOT 1,TAXBLOCK 299 (Continued)** **S109155493**

| | |
|---|---|
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | ROGIS ASSOCIATES INC |
| Lot Area: | 000005400 |
| Total Building Floor Area: | 00000005400 |
| Floor Area, Commercial: | 00000005400 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000005400 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000000000 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0060.00 |
| Building, Depth: | 0090.00 |
| Building Front: | 0060.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 3 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000053550 |
| Assessed Value, Total: | 00000105750 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered 1: | 0000 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |

**LOT 1,TAXBLOCK 299 (Continued)** **S109155493**

| | |
|---|---|
| Borough, Tax Block & Lot: | 3002990001 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984128 |
| Y Coordinate: | 0190338 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 1 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | ROGIS ASSOCIATES INC |
| Lot Area: | 000005400 |
| Total Building Floor Area: | 00000005400 |
| Commercial Floor Area: | 00000005400 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000005400 |

**LOT 1,TAXBLOCK 299 (Continued)** **S109155493**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0060.00 |
| Lot Depth: | 0090.00 |
| Building Frontage: | 0060.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 3 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000053550 |
| Total Assessed Value: | 00000105750 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990001 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984128 |
| Y Coordinate: | 0190338 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**M86** **SPILL NUMBER 0101741** **NY Spills** **S105055764**
**SSE** **DEGRAW ST/COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.007 mi.**
**38 ft.** **Site 2 of 5 in cluster M**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0101741 |
| Facility Type: | ER |
| DER Facility ID: | 218046 |
| Site ID: | 267655 |
| DEC Region: | 2 |
| Spill Date: | 5/15/2001 |
| Spill Number/Closed Date: | 0101741 / 2/13/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 5/15/2001 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/15/2001 |
| Spill Record Last Update: | 2/13/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ - |
| Spiller Company: | 001 |
| Contact Name: | NEAL MCGRAW |
| Contact Phone: | (718) 624-0672 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"ADMINISTRATIVE CLOSURE - AUSTIN |
| Remarks: | CALLER STATES SEVERAL VACANT LOTS CLEARED IN ABOVE AREA AND ANUNKNOWN SUBSTANCE APPLIED TO PERHAPS KILL WEEDS. CALLER ISCONCERNED BECAUSE MATERIAL IS RUNNING OFF PROPERTY AND ONTOSIDEWALKS. CALLER IS VERY UPSET AND REQUEST IMMEDITATE CALLBACKFROM REGIONAL OFFICE. CALLER STATES HE WALKED IN MATERIAL. |

Material:

| | |
|---|---|
| Site ID: | 267655 |
| Operable Unit ID: | 838621 |
| Operable Unit: | 01 |
| Material ID: | 537447 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |

**SPILL NUMBER 0101741 (Continued)** **S105055764**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**H87** **VACANT BUILDING** **NY Spills** **S109414438**
**SSW** **62 IMLAY ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.007 mi.**
**39 ft.** **Site 4 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0811376 |
| Facility Type: | ER |
| DER Facility ID: | 358209 |
| Site ID: | 408952 |
| DEC Region: | 2 |
| Spill Date: | 1/14/2009 |
| Spill Number/Closed Date: | 0811376 / 1/15/2010 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | jbvought |
| Referred To: | Not reported |
| Reported to Dept: | 1/15/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/15/2009 |
| Spill Record Last Update: | 1/15/2010 |
| Spiller Name: | DENNIS HOVANEC |
| Spiller Company: | 62 IMLAY PARTNERS |
| Spiller Address: | 62 IMLAY ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | DENNIS HOVANEC |
| Contact Phone: | Not reported |
| DEC Memo: | Sangesland spoke to Dennis Hovanec.Property was a 100 year old warehouse.Contamination was "probably" associated with a buried fuel oil tank.CSL sent to:62 IMLAY partners LLCc/o Industry City Associates & Dennis Hovanec882 3rd Ave Brooklyn, NY 1123203/23/09-Vought-Received call from Paul Matli (Hydrotech 718-636-0800) and client wants to begin excavation and groundwater is 4' below grade. Excavation will be performed to groundwater and approval needed to collect bottom groundwater samples. No USTs onsite and no signs of tank. Vought sent copy of these notes to Matli to confirm DEC requirement of collection of bottom groundwater samples and analysis via EPA Methods 8260/8270. Future use of property will |

**VACANT BUILDING (Continued)** **S109414438**

be six story warehouse to with foundation extending to groundwater. 1/6/10-Vought-Received and reviewed Soil Removal Report from Hydrotech dated 4/30/09. Report received on 1/5/10. Excavation and removal of petroleum contaminated soil in vicinity of 12,000-gallon fuel oil UST and collection of endpoints including two sidewall soil samples and one groundwater sample from bottom of excavation. UST removal verified via performance of test pits east of the soil excavation. 19 tons of soil removed from western portion of the property. "Vicinity of site consists of commercial and manufacturing properties." UST removed in 2005 via onsite tank affadavit but no endpoint samples available but manifests indicated 22 yards of soil was removed along with UST. Tank tested in 2005 showed "passing criteria". Depth to groundwater is 4'bg. Soil was excavated from a "underground concrete trench" on the northwestern edge of the warehouse building. Excavation limited to the north by underground concrete trench and to the east by the building foundation. Excavation continued to the south and west until no further contaminted soil was indentified. "No petroleum staining was observed on the concrete walls of the underground trench or the foundation walls of the building." Endpoint samples collected form southern and western walls. Test pits at former UST location showed that UST was no longer present. Site is approximately 120' south of New York Harbor. "Visual and olfactory evidence of petroleum constituents and organic vapors of 45 ppm were identified in the bottom of the excavation. All petroleum contaminated soil encountered above the water table was removed." Test pits performed at former UST location showed "evidence of RCRA fill material" that was "down to the groundwater". Soil analyticals only show minor TAGM 4046 Required Soil Cleanup Objective exceedences for PAHs attributable to fill material. Groundwater analyticals show 5.5ppb 1,2,4-trimethylbenzene(GW1), 25ppb napthalene(GW1) and minor PAH exceedences in groundwater. Note that GW1 collected immediately downgradient of UST location (GW1 is located between former UST location and NY Harbor. In consideration of only RCRA fill material and GW being immediately downgradient of former UST location, no samples required by UST location. Vought checked PBS and registration shows closed 12,000-gallon UST. Vought called Matli and he confirmed that soil referred to with "45ppm" reading was excavated out as excavation proceeded till water table. Spill closed by Vought and NFA sent to address above with cc to Matli.

Remarks: Caller states during an excavation on the site oil was found in the soil. Cleanup is pending test bores.

Material:

| | |
|---|---|
| Site ID: | 408952 |
| Operable Unit ID: | 1165457 |
| Operable Unit: | 01 |
| Material ID: | 2156866 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**VACANT BUILDING (Continued)** **S109414438**

Tank Test:

---

**H88** **MERCEDES DISTRIBUTION CENTER** **FINDS** **1007774008**
**SSW** **62 IMLAY ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.007 mi.**
**39 ft.** **Site 5 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

FINDS:

Registry ID: 110019364560

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**H89** **62 IMLAY ST. ESTATE, LLC** **NY UST** **U003297817**
**SSW** **62/114 IMLAY STREET** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.007 mi.**
**39 ft.** **Site 6 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-603358 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 583856.71742 |
| UTM Y: | 4503963.8000100004 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 25276 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 62 IMLAY ST. ESTATE, LLC |
| Contact Type: | Not reported |
| Contact Name: | 62 IMLAY PARTNERS LLC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 965-6450 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 5/4/2009 |

| | |
|---|---|
| Site Id: | 25276 |
| Affiliation Type: | Emergency Contact |
| Company Name: | 62 IMLAY PARTNERS LLC |

**62 IMLAY ST. ESTATE, LLC (Continued)** **U003297817**

| | |
|---|---|
| Contact Type: | Not reported |
| Contact Name: | MIKE PENELLA |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 776-6251 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 5/4/2009 |

| | |
|---|---|
| Site Id: | 25276 |
| Affiliation Type: | Facility Owner |
| Company Name: | 62 IMLAY PARTNERS LLC |
| Contact Type: | SUPERVISOR |
| Contact Name: | ISREAL GOSSMAN |
| Address1: | 882 3RD AVE |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11232 |
| Country Code: | 001 |
| Phone: | (718) 965-6450 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 5/4/2009 |

| | |
|---|---|
| Site Id: | 25276 |
| Affiliation Type: | Mail Contact |
| Company Name: | HYDRO TECH ENVIRONMENTAL CORP |
| Contact Type: | Not reported |
| Contact Name: | PAUL I. MATHIS |
| Address1: | 1111 FULTON STREET |
| Address2: | 2ND FLOOR |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11204 |
| Country Code: | 001 |
| Phone: | (718) 636-0800 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 5/4/2009 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 53995 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 12000 |
| Install Date: | Not reported |
| Date Tank Closed: | 10/19/2005 |

**62 IMLAY ST. ESTATE, LLC (Continued)** **U003297817**

| | |
|---|---|
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 03 |
| Date Test: | 12/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 05/04/2009 |

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None

HIST UST:

| | |
|---|---|
| PBS Number: | 2-603358 |
| SPDES Number: | Not reported |
| Emergency Contact: | GEROGE FRANQUI |
| Emergency Telephone: | (718) 522-7111 |
| Operator: | GEORGE FRANQUI |
| Operator Telephone: | (718) 522-7111 |
| Owner Name: | MERCEDES DISTRIBUTION CORPORATION |
| Owner Address: | 62 IMLAY STREET |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Owner Telephone: | (718) 522-7111 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | MERCEDES DISTRIBUTION CORPORATION |
| Mailing Address: | 62 IMLAY STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Contact: | JOEL GOLDSTEIN |
| Mailing Telephone: | (718) 522-7111 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | 62/114 IMLAY STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | Not reported |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |

**62 IMLAY ST. ESTATE, LLC (Continued)** **U003297817**

| | |
|---|---|
| Certification Date: | 06/01/1998 |
| Expiration Date: | 03/05/2003 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 12000 |
| FAMT: | True |
| Facility Screen: | Minor Data Missing |
| Owner Screen: | No Missing Data |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (gals): | 12000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Aboveground/Underground Combination |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | 12/01/1997 |
| Next Test Date: | 12/01/2002 |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Horner EZ Check |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

---

**E90** **EDR US Hist Auto Stat** **1015590395**
**SSW** **65 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.008 mi.**
**40 ft.** **Site 14 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | N & J AUTO REPAIR SPECIALIST CORP |
| Year: | 2003 |
| Address: | 65 UNION ST |

**E91**
**SSW**
**< 1/8**
**0.008 mi.**
**42 ft.**

**56 UNION ST**
**BROOKLYN, NY 11231**

**Site 15 of 18 in cluster E**

**EDR US Hist Auto Stat** **1015553347**
**N/A**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | RALPHS AUTO REPR & COLLISION |
| Year: | 2011 |
| Address: | 56 UNION ST |
| Name: | RALPHS AUTO REPR & COLLISION |
| Year: | 2012 |
| Address: | 56 UNION ST |

---

**O92**
**NE**
**< 1/8**
**0.008 mi.**
**44 ft.**

**CON EDISON MANHOLE: 73002**
**FURMAN ST & ATLANTIC AVE NW**
**BROOKLYN, NY 11217**

**Site 1 of 9 in cluster O**

**RCRA-CESQG** **1016150096**
**NYP004287678**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 02/07/2013 |
| Facility name: | CON EDISON MANHOLE: 73002 |
| Facility address: | FURMAN ST & ATLANTIC AVE NW<br>COR<br>BROOKLYN, NY 11217 |
| EPA ID: | NYP004287678 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | ANTHONY SIGNORE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 802-3008 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |

**CON EDISON MANHOLE: 73002 (Continued)** **1016150096**

| | |
|---|---|
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

---

**O93** **CON EDISON MANHOLE: 9204** **RCRA-CESQG** **1016150091**
**NE** **FURMAN ST & ATLANTIC AVE** **NYP004287629**
**< 1/8** **BROOKLYN, NY 11217**
**0.008 mi.**
**44 ft.** **Site 2 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 02/07/2013 |
| Facility name: | CON EDISON MANHOLE: 9204 |
| Facility address: | FURMAN ST & ATLANTIC AVE<br>BROOKLYN, NY 11217 |
| EPA ID: | NYP004287629 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | ANTHONY SIGNORE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 802-3008 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |

**CON EDISON MANHOLE: 9204 (Continued)** **1016150091**

| | |
|---|---|
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

---

**E94** **SOUTH BROOKLYN AUTO BODY** **US AIRS** **1014819095**
**SSW** **67 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.011 mi.**
**60 ft.** **Site 16 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

AIRS (AFS):

Compliance and Violation Data Major Sources:

| | |
|---|---|
| EPA plant ID: | 110019097047 |
| Plant name: | SOUTH BROOKLYN AUTO BODY |
| Plant address: | 67 UNION ST<br>BROOKLYN, NY 112311416 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 7532 |
| Sic code desc: | TOP & BODY REPAIR AND PAINT SHOPS (1987) |
| North Am. industrial classf: | 811121 |
| NAIC code description: | Automotive Body, Paint, and Interior Repair and Maintenance |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL EMISSIONS ARE BELOW ALL APPLICABLE MAJOR SOURCE THRESHOLDS IF AND ONLY IF THE SOURCE COMPLIES WITH FEDERALLY ENFORCEABLE REGULATIONS OR LIMITATIONS. |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | MACT (SECTION 63 NESHAPS) |
| National action type: | NOTIFICATION RECEIVED |
| Date achieved: | 100310 |
| Penalty amount: | Not reported |
| | |
| Air program: | SIP SOURCE |
| National action type: | STATE CONDUCTED PCE/ ON-SITE |
| Date achieved: | 100406 |
| Penalty amount: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1004 |
| Air prog code hist file: | SIP SOURCE |
| | |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |

**SOUTH BROOKLYN AUTO BODY (Continued)** **1014819095**

Hist compliance date: 1004
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101

**SOUTH BROOKLYN AUTO BODY (Continued)** **1014819095**

Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

---

**E95** **SOUTH BROOKLYN AUTO BODY** **FINDS** **1016124973**
**SSW** **67 UNION ST.** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.011 mi.**
**60 ft.** **Site 17 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

FINDS:

Registry ID: 110041349467

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

**SOUTH BROOKLYN AUTO BODY (Continued)** **1016124973**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**E96** **EDR US Hist Auto Stat** **1015595999**
**SSW** **67 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.011 mi.**
**60 ft.** **Site 18 of 18 in cluster E**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | EXCLUSIVE AUTO BODY CORP |
| Year: | 2004 |
| Address: | 67 UNION ST |
| Name: | SOUTH BROOKLYN AUTO BODY INC |
| Year: | 2005 |
| Address: | 67 UNION ST |
| Name: | SOUTH BROOKLYN AUTO BODY |
| Year: | 2011 |
| Address: | 67 UNION ST |
| Name: | SOUTH BROOKLYN AUTOMOBILE BODY |
| Year: | 2012 |
| Address: | 67 UNION ST |

---

**O97** **COLUMBIA ST & ATLANTIC AV** **NY Spills** **S102145415**
**NE** **COLUMBIA ST & ATLANTIC AV** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.012 mi.**
**65 ft.** **Site 3 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8904120 |
| Facility Type: | ER |
| DER Facility ID: | 114709 |
| Site ID: | 133264 |
| DEC Region: | 2 |
| Spill Date: | 7/25/1989 |
| Spill Number/Closed Date: | 8904120 / 7/25/1989 |
| Spill Cause: | Human Error |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 7/25/1989 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | 7/25/1989 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**COLUMBIA ST & ATLANTIC AV (Continued)** **S102145415**

| | |
|---|---|
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/25/1989 |
| Spill Record Last Update: | 9/6/1989 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | TRUCK BEING TOWED, TANK PUNCTURED, TANKS RAN DRY, FIRE DEPT & NYCPD ONSCENE, SPEEDY DRY APPLIED. |

Material:

| | |
|---|---|
| Site ID: | 133264 |
| Operable Unit ID: | 931885 |
| Operable Unit: | 01 |
| Material ID: | 448184 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 300 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**O98** **DRUM RUN** **NY Spills** **S111012078**
**NE** **COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.013 mi.**
**67 ft.** **Site 4 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1101845 |
| Facility Type: | ER |
| DER Facility ID: | 403913 |
| Site ID: | 449321 |
| DEC Region: | 2 |
| Spill Date: | 5/19/2011 |
| Spill Number/Closed Date: | 1101845 / 5/23/2011 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | HRAHMED |
| Referred To: | Not reported |
| Reported to Dept: | 5/19/2011 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |

**DRUM RUN (Continued)** **S111012078**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/19/2011 |
| Spill Record Last Update: | 5/23/2011 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | UNKNOWN |
| Contact Phone: | Not reported |
| DEC Memo: | 5/23/11-HRAHMED-Three 5 gal containers were pumped out by Fenley & Nicole during DRUM RUN on 5/20/11. Approx. 3 gal of water and oil mix were pumped out. DEP and Sanitation were notified.This case is closed. Not reported |
| Remarks: | Caller reports three 5 gallon containers, one intact, two are crushed and leaking...Best location, 50 yards north of Van Voorhees Park on Columbia St. Containers are across the street from the park. This will be near the intersection of Columbia and Atlantic |

Material:

| | |
|---|---|
| Site ID: | 449321 |
| Operable Unit ID: | 1199536 |
| Operable Unit: | 01 |
| Material ID: | 2195913 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**D99** **LOT 6,TAXBLOCK 319** **NY E DESIGNATION** **S108469993**
**SSE** **COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.013 mi.**
**69 ft.** **Site 21 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 6 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |

**LOT 6,TAXBLOCK 319 (Continued)** **S108469993**

| | |
|---|---|
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | POSTGRADUATE CNTR MEN |
| Lot Area: | 000001942 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0019.92 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000022455 |
| Land Exempt Value: | 00000022455 |
| Total Exempt Value: | 00000022455 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190006 |

**LOT 6,TAXBLOCK 319 (Continued)** **S108469993**

| | |
|---|---|
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983687 |
| Y Coordinate: | 0189224 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**D100** **LOT 8,TAXBLOCK 319** **NY E DESIGNATION** **S108469997**
**SSE** **COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.013 mi.**
**71 ft.** **Site 22 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 8 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | POSTGRADUATE CNTR MEN |
| Lot Area: | 000001950 |
| Total Building Floor Area: | 00000000000 |

**LOT 8,TAXBLOCK 319 (Continued)** **S108469997**

| | |
|---|---|
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000022455 |
| Land Exempt Value: | 00000022455 |
| Total Exempt Value: | 00000022455 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190008 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983702 |
| Y Coordinate: | 0189260 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**O101** **ERNS** **2012022411**
**NE** **29-50 ATLANTIC AVE.** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.014 mi.**
**75 ft.** **Site 5 of 9 in cluster O**

**Relative:**
**Higher**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**Actual:**
**26 ft.**

---

**O102** **MANHOLE 55769** **NY Spills** **S104283947**
**NE** **23-52 ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.014 mi.**
**76 ft.** **Site 6 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9909801 |
| Facility Type: | ER |
| DER Facility ID: | 215653 |
| Site ID: | 264607 |
| DEC Region: | 2 |
| Spill Date: | 11/12/1999 |
| Spill Number/Closed Date: | 9909801 / 3/29/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 11/12/1999 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/12/1999 |
| Spill Record Last Update: | 3/29/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" |
| Remarks: | 5 OUNCES OF UNK OIL ON 50GAL OF WATER - CASE #128962 - SAMPLE TAKEN |

Material:

| | |
|---|---|
| Site ID: | 264607 |
| Operable Unit ID: | 1088493 |
| Operable Unit: | 01 |
| Material ID: | 298870 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |

**MANHOLE 55769 (Continued)** **S104283947**

Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**O103** **GETTY 411** **NY Spills** **S110488396**
**NE** **35 ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.016 mi.**
**86 ft.** **Site 7 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

SPILLS:
Facility ID: 1002438
Facility Type: ER
DER Facility ID: 390472
Site ID: 435573
DEC Region: 2
Spill Date: 6/3/2010
Spill Number/Closed Date: 1002438 / 6/3/2010
Spill Cause: Housekeeping
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 6/3/2010
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/3/2010
Spill Record Last Update: 6/3/2010
Spiller Name: Not reported
Spiller Company: GETTY 411
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: MIKE CARR
Contact Phone: (518) 786-3200
DEC Memo: minor spill - all cleaned up.
Remarks: clean up complete

Material:
Site ID: 435573
Operable Unit ID: 1186331
Operable Unit: 01
Material ID: 2181122

**GETTY 411 (Continued)** **S110488396**

| | |
|---|---|
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**D104** **LOT 7,TAXBLOCK 319** **NY E DESIGNATION** **S108469996**
**SSE** **COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.020 mi.**
**104 ft.** **Site 23 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 7 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | POSTGRADUATE CNTR MEN |
| Lot Area: | 000001958 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |

**LOT 7,TAXBLOCK 319 (Continued)** **S108469996**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.08 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000022455 |
| Land Exempt Value: | 00000022455 |
| Total Exempt Value: | 00000022455 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190007 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983726 |
| Y Coordinate: | 0189229 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**D105** **LOT 9,TAXBLOCK 319** **NY E DESIGNATION** **S108469998**
**SSE** **COLUMBIA STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.020 mi.**
**104 ft.** **Site 24 of 25 in cluster D**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 9 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | POSTGRADUATE CNTR MEN |
| Lot Area: | 000001933 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0019.83 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |

**LOT 9,TAXBLOCK 319 (Continued)** **S108469998**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000022455 |
| Land Exempt Value: | 00000022455 |
| Total Exempt Value: | 00000022455 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190009 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983739 |
| Y Coordinate: | 0189266 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**G106** **37 HAMILTON AVE/BKLYN** **NY LTANKS** **S100168241**
**SSW** **37 HAMILTON AVENUE** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.020 mi.**
**105 ft.** **Site 3 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 158094 |
| Spill Number/Closed Date: | 9012122 / 8/2/1993 |
| Spill Date: | 2/20/1991 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Gasoline Station |
| Spill Class: | Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | 8/2/1993 |
| Cleanup Meets Standard: | True |
| SWIS: | 2401 |
| Investigator: | SULLIVAN |
| Referred To: | Not reported |
| Reported to Dept: | 2/21/1991 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**37 HAMILTON AVE/BKLYN (Continued)** **S100168241**

| | |
|---|---|
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/1/1991 |
| Spill Record Last Update: | 8/2/1993 |
| Spiller Name: | Not reported |
| Spiller Company: | MOBIL |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 133653 |
| DEC Memo: | Not reported |
| Remarks: | (1) TANK & (2) TANK SYSTEMS WERE TESTED & FAILED, 2K TANK FAILED,2K & 4K TANK MANIFOLDED SYSTEM FAILED & (2) 4K TANKS MANIFOLDED FAILED, NYCFD ON SCENE, NO ACTION YET. |

Material:

| | |
|---|---|
| Site ID: | 158094 |
| Operable Unit ID: | 951966 |
| Operable Unit: | 01 |
| Material ID: | 428631 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 158094 |
| Spill Tank Test: | 1538277 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Unknown |

**D107**
**SSE**
**< 1/8**
**0.020 mi.**
**105 ft.**

**LOT 5,TAXBLOCK 319**
**COLUMBIA STREET**
**BROOKLYN, NY 11231**

**Site 25 of 25 in cluster D**

**NY E DESIGNATION** **S108469989**
**N/A**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 5 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | V1 |
| Land Use Category: | 11 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | POSTGRADUATE CNTR MEN |
| Lot Area: | 000001966 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 4 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.17 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |

**LOT 5,TAXBLOCK 319 (Continued)** **S108469989**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000022455 |
| Land Exempt Value: | 00000022455 |
| Total Exempt Value: | 00000022455 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190005 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983713 |
| Y Coordinate: | 0189192 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**H108** **CHUEN FAI TRADING CORP** **ICIS 1011620019**
**SSW** **191 VAN BRUNT STREET BROOKLYN NY 11231** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.020 mi.**
**108 ft.** **Site 7 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

ICIS:

| | |
|---|---|
| Enforcement Action ID: | 02-2002-5002 |
| FRS ID: | 110013694680 |
| Program ID: | FRS 110013694680 |
| Action Name: | CHUEN FAI TRADING COMPANY |
| Facility Name: | CHUEN FAI TRADING COMPANY |
| Facility Address: | 191 VAN BRUNT STREET BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | FIFRA 14A Action For Penalty |
| Facility County: | Kings |
| EPA Region #: | 2 |

| | |
|---|---|
| Enforcement Action ID: | 02-2002-5002 |
| FRS ID: | 110013694680 |
| Program ID: | NCDB D02#F-02-2002-5202 |
| Action Name: | CHUEN FAI TRADING COMPANY |
| Facility Name: | CHUEN FAI TRADING CORP |
| Facility Address: | 191 VAN BRUNT STREET BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |

**CHUEN FAI TRADING CORP (Continued)** **1011620019**

Enforcement Action Type: FIFRA 14A Action For Penalty
Facility County: Kings
EPA Region #: 2

Program ID: FRS 110013694680
Facility Name: CHUEN FAI TRADING COMPANY
Address: 191 VAN BRUNT STREET
Tribal Indicator: N
Fed Facility: Not reported
NAIC Code: Not reported
SIC Code: 5199
Latitude: 40.681949
Longitude: -74.007487

Program ID: NCDB D02#F-02-2002-5202
Facility Name: CHUEN FAI TRADING COMPANY
Address: 191 VAN BRUNT STREET
Tribal Indicator: N
Fed Facility: Not reported
NAIC Code: Not reported
SIC Code: 5199
Latitude: 40.681949
Longitude: -74.007487

---

**H109** **GLORY TRADING CORP.** **FINDS** **1014903426**
**SSW** **191-193 VAN BRUNT STR.** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.020 mi.**
**108 ft.** **Site 8 of 10 in cluster H**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

FINDS:

Registry ID: 110043721345

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

**H110**
**SSW**
**< 1/8**
**0.020 mi.**
**108 ft.**

**CHUEN FAI TRADING CORP**
**191-193 VAN BRUNT ST**
**BROOKLYN, NY 11231**

**Site 9 of 10 in cluster H**

**Relative: Lower**

**Actual: 5 ft.**

**FTTS** **1007273264**
**HIST FTTS** **N/A**

FTTS INSP:

| | |
|---|---|
| Inspection Number: | 199803170001 1 |
| Region: | 02 |
| Inspection Date: | 03/17/98 |
| Inspector: | F. CANABAL, EM |
| Violation occurred: | Yes |
| Investigation Type: | Section 6 PCB State Conducted |
| Investigation Reason: | Neutral Scheme, State |
| Legislation Code: | TSCA |
| Facility Function: | User |

HIST FTTS INSP:

| | |
|---|---|
| Inspection Number: | 199803170001 1 |
| Region: | 02 |
| Inspection Date: | Not reported |
| Inspector: | F. CANABAL, EM |
| Violation occurred: | Yes |
| Investigation Type: | Section 6 PCB State Conducted |
| Investigation Reason: | Neutral Scheme, State |
| Legislation Code: | TSCA |
| Facility Function: | User |

---

**H111**
**SSW**
**< 1/8**
**0.020 mi.**
**108 ft.**

**CHUEN FAI TRADING COMPANY**
**191 VAN BRUNT STREET**
**BROOKLYN, NY**

**Site 10 of 10 in cluster H**

**Relative: Lower**

**Actual: 5 ft.**

**FINDS** **1006380781**
**N/A**

FINDS:

Registry ID: 110013694680

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region

**CHUEN FAI TRADING COMPANY (Continued)** **1006380781**

that support Compliance and Enforcement programs. These include;
Incident Tracking, Compliance Assistance, and Compliance Monitoring.

---

**G112** **TRENCH** **NY Spills** **S106971100**
**SSW** **VANBRUNT ST NEAR CARROLL ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.024 mi.**
**127 ft.** **Site 4 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0505704 |
| Facility Type: | ER |
| DER Facility ID: | 297361 |
| Site ID: | 350782 |
| DEC Region: | 2 |
| Spill Date: | 8/9/2005 |
| Spill Number/Closed Date: | 0505704 / 10/5/2005 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SKARAKHA |
| Referred To: | Not reported |
| Reported to Dept: | 8/9/2005 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/9/2005 |
| Spill Record Last Update: | 10/5/2005 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN AT THIS TIME: |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | ERT DESK' |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | e2mis no 160371. AUG 09-2005 1350 HRS. E H & S REPRESENTATIVE LOU CLARK, EMPLOYEE NO 05374, REPORTS, CONSTRUCTION REP, JOHN T. OCONNELL, EMPLOYEE NO05374, WHILE ON LOCATION TO OVERSEE CONSTRUCTION IN A TRENCH LOCATED ON THE E/S VANBRUNT ST 5' N/O CARROLL ST, REPORTS FINDING APPX 1 PT OF UNKNOWN OIL FROM AN UNKNOWN SOURCE IN THE SOIL. NO FIRE OR SMOKE INVOLVED, NO INJURIES RELATED TO THE SPILL, NO SEWERS, WATERWAYS OR PRIVATE PROPERTY AFFECTED. ASTORIA CHEM LAB PERSONNEL HAVE BEEN NOTIFIED AND ARE REPORTING TO THE LOCATION TO SAMPLE THE SOIL AND TRANSPORT IT TO ASTORIA LAB FOR ANALYSIS. CREW TO UPDATE.BORCHERDINGC.see e-docs. closed. 10-5-05. GB |
| Remarks: | NO TO 5 QUESTIONS; CONED # 160371 |

Material:

| | |
|---|---|
| Site ID: | 350782 |

**TRENCH (Continued)** **S106971100**

| | |
|---|---|
| Operable Unit ID: | 1108326 |
| Operable Unit: | 01 |
| Material ID: | 2098263 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**L113** **LOT 39,TAXBLOCK 319** **NY E DESIGNATION** **S108469985**
**ESE** **90 KANE STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.027 mi.**
**142 ft.** **Site 2 of 3 in cluster L**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 39 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | C1-3 |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | C1-3/R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | KANAS, JENNIFER |
| Lot Area: | 000001771 |
| Total Building Floor Area: | 00000003108 |
| Commercial Floor Area: | 00000000000 |

**LOT 39,TAXBLOCK 319 (Continued)** **S108469985**

| | |
|---|---|
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0022.00 |
| Lot Depth: | 0080.50 |
| Building Frontage: | 0022.00 |
| Building Depth: | 0050.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000006000 |
| Total Assessed Value: | 00000038940 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000034370 |
| Year Built: | 2001 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.75 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190039 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983960 |
| Y Coordinate: | 0189746 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**G114** **MEDGAR EVERS COLLEGE** **NY Spills** **S102141577**
**SSW** **11 CARROLL STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.027 mi.**
**143 ft.** **Site 5 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**11 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9002752 |
| Facility Type: | ER |
| DER Facility ID: | 237237 |
| Site ID: | 293101 |
| DEC Region: | 2 |
| Spill Date: | 6/11/1990 |
| Spill Number/Closed Date: | 9002752 / 6/20/1995 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | FINGER |
| Referred To: | Not reported |
| Reported to Dept: | 6/11/1990 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | 6/20/1995 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/13/1990 |
| Spill Record Last Update: | 6/20/1995 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NN |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | LEAKING MANWAY-REPLACED-MANWAY STILL LEAKING FUEL INTO PIT NEXT TO TANK PRODUCT IN PIT TO CLEAN UP |

Material:

| | |
|---|---|
| Site ID: | 293101 |
| Operable Unit ID: | 942891 |
| Operable Unit: | 01 |
| Material ID: | 437492 |
| Material Code: | 0002A |
| Material Name: | #4 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 200 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**MEDGAR EVERS COLLEGE (Continued)** **S102141577**

Tank Test:

---

**P115** **ROADWAY** **NY Spills** **S108466725**
**NE** **BROOKLYN QUEENS EXPRESSWAY/ATLANTIC AVE EXIT** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 1 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0613408 |
| Facility Type: | ER |
| DER Facility ID: | 327968 |
| Site ID: | 378428 |
| DEC Region: | 2 |
| Spill Date: | 3/14/2007 |
| Spill Number/Closed Date: | 0613408 / 3/14/2007 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | smsanges |
| Referred To: | Not reported |
| Reported to Dept: | 3/14/2007 |
| CID: | 78 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/14/2007 |
| Spill Record Last Update: | 3/14/2007 |
| Spiller Name: | Not reported |
| Spiller Company: | 3 WIN INC |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | JAMAICIA, NY |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | (347) 203-6886 |
| DEC Memo: | Not reported |
| Remarks: | TRAFFIC ACCIDENT SADDLE RIPPED OPEN PRODUCT OFF LOADED AFTER SIGNIFICANT AMOUNT SPILLED ON THE ROADWAY SPEEDI DRI APLIED PRODUCT ENTERED SEWER NO RECOVERY |

Material:

| | |
|---|---|
| Site ID: | 378428 |
| Operable Unit ID: | 1135932 |
| Operable Unit: | 01 |
| Material ID: | 2125863 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 75 |

**ROADWAY (Continued)** **S108466725**

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**P116** **BQE- W.BOUND ATLANTIC AVE** **NY Spills** **S102149233**
**NE** **BROOKLYN QUEENS EXPRESSWAY - W.BOUND ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 2 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:
Facility ID: 9412790
Facility Type: ER
DER Facility ID: 162655
Site ID: 195211
DEC Region: 2
Spill Date: 12/24/1994
Spill Number/Closed Date: 9412790 / 1/3/1995
Spill Cause: Traffic Accident
Spill Class: Not reported
SWIS: 2401
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 12/24/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: 1/3/1995
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/3/1995
Spill Record Last Update: 2/24/1995
Spiller Name: Not reported
Spiller Company: RICHARD FUEL OIL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"
Remarks: TRUCK OVER TURNED

Material:
Site ID: 195211
Operable Unit ID: 1010382
Operable Unit: 01
Material ID: 375083
Material Code: 0001A
Material Name: #2 Fuel Oil

**BQE- W.BOUND ATLANTIC AVE (Continued)** **S102149233**

| | |
|---|---|
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 100 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P117** **BKLYN QUNS EXPWY/ATLANTIC** **NY Spills** **S102145646**
**NE** **B Q EXPWY/ATLANTIC AVE** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.030 mi.**
**158 ft.** **Site 3 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8910159 |
| Facility Type: | ER |
| DER Facility ID: | 83762 |
| Site ID: | 93433 |
| DEC Region: | 2 |
| Spill Date: | 1/23/1990 |
| Spill Number/Closed Date: | 8910159 / 1/23/1990 |
| Spill Cause: | Unknown |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 1/23/1990 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Other |
| Cleanup Ceased: | 1/23/1990 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/6/1990 |
| Spill Record Last Update: | 3/7/1990 |
| Spiller Name: | Not reported |
| Spiller Company: | LACARTOSA TRUCKING |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | TRUCK SPILLED 20 GALS, PETRO TANK CLEANERS CLEANED UP SPILL. |

Material:

| | |
|---|---|
| Site ID: | 93433 |
| Operable Unit ID: | 937178 |
| Operable Unit: | 01 |
| Material ID: | 443279 |

**BKLYN QUNS EXPWY/ATLANTIC (Continued)** **S102145646**

| | |
|---|---|
| Material Code: | 0003A |
| Material Name: | #6 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P118** **ROADWAY** **NY Spills** **S108637072**
**NE** **BROOKLYN QUEENS EXPRESSWAY AND ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 4 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0701741 |
| Facility Type: | ER |
| DER Facility ID: | 330713 |
| Site ID: | 381323 |
| DEC Region: | 2 |
| Spill Date: | 5/11/2007 |
| Spill Number/Closed Date: | 0701741 / 5/11/2007 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 5/11/2007 |
| CID: | 410 |
| Water Affected: | Not reported |
| Spill Source: | Tank Truck |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/11/2007 |
| Spill Record Last Update: | 5/11/2007 |
| Spiller Name: | JOHN CASSIDY |
| Spiller Company: | UNKNOWN |
| Spiller Address: | BQE AND ATLANTIC AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | JOHN CASSIDY |
| Contact Phone: | (718) 476-6288 |
| DEC Memo: | I responded to the site after getting the spill report.Spill location was on BQE west bound 200 yard before atlantic ave exit.The spilled amount reported was not realistic.A mini van was involved into a traffic accident and spilled oil.FDNY put sand on it.Spill closed. |

**ROADWAY (Continued)** **S108637072**

Remarks: NYC FD ON SCENE, CAUSE UNKNOWN AT THIS TIME IF IT WAS EQ FAILURE ON TANK TRUCK OR ACCIDENT: CLEAN UP IN PROGRESS: N

Material:

| | |
|---|---|
| Site ID: | 381323 |
| Operable Unit ID: | 1138781 |
| Operable Unit: | 01 |
| Material ID: | 2128779 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 100 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 1214603 |
| Facility Type: | ER |
| DER Facility ID: | 433154 |
| Site ID: | 477850 |
| DEC Region: | 2 |
| Spill Date: | 1/15/2013 |
| Spill Number/Closed Date: | 1214603 / 1/15/2013 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 1/15/2013 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/15/2013 |
| Spill Record Last Update: | 1/15/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | ROADWAY TRUCKING |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | SCOTT SARNELL |
| Contact Phone: | (347) 203-6886 |
| DEC Memo: | 01/15/13- Spoke with FD.Cause of the spill was traffic accident. saddle tank was emptied into drums and FD assured me that the drums will be picked up by the tow truck.No drain was impacted.(sr) |

**ROADWAY (Continued)** **S108637072**

Remarks: 5-10 gal on the ground. The saddle tanks are being pumped out. Spill is contained to the roadway. Clean up is in progress.

Material:

| | |
|---|---|
| Site ID: | 477850 |
| Operable Unit ID: | 1227648 |
| Operable Unit: | 01 |
| Material ID: | 2225091 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P119** **EXIT OF ATLANTIC AVENUE** **NY Spills** **S102148731**
**NE** **EXIT OF ATLANTIC AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 5 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9407939 |
| Facility Type: | ER |
| DER Facility ID: | 66206 |
| Site ID: | 69652 |
| DEC Region: | 2 |
| Spill Date: | 9/15/1994 |
| Spill Number/Closed Date: | 9407939 / 9/15/1994 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 9/15/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Police Department |
| Cleanup Ceased: | 9/15/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/27/1994 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |

**EXIT OF ATLANTIC AVENUE (Continued)** **S102148731**

| | |
|---|---|
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | TRUCK HAD RUPTURED FUEL LINE-NYCFD ON SCENDEPT OF SANITATION SANDED ROAD DOWN. FD FLUSHED SEWER OUT. CALL BACK IF NECESSARY |

Material:

| | |
|---|---|
| Site ID: | 69652 |
| Operable Unit ID: | 1002148 |
| Operable Unit: | 01 |
| Material ID: | 377397 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 200 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P120** **BROOKLYN QUEENS EXPRESS** **NY Spills** **S108763743**
**NE** **ALTLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 6 of 14 in cluster P**

**Relative: Higher**

**Actual: 23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0705598 |
| Facility Type: | ER |
| DER Facility ID: | 335336 |
| Site ID: | 385937 |
| DEC Region: | 2 |
| Spill Date: | 8/15/2007 |
| Spill Number/Closed Date: | 0705598 / 8/16/2007 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | smsanges |
| Referred To: | Not reported |
| Reported to Dept: | 8/15/2007 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Source: | Passenger Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/15/2007 |

**BROOKLYN QUEENS EXPRESS (Continued)** **S108763743**

| | |
|---|---|
| Spill Record Last Update: | 8/16/2007 |
| Spiller Name: | Not reported |
| Spiller Company: | NOT YET AVAILABLE |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | DISPATCHERS |
| Contact Phone: | (718) 636-1700 |
| DEC Memo: | traffic accident - FD HAZMAT on site |
| Remarks: | FIRE DEPT. ON SCENE; |

Material:

| | |
|---|---|
| Site ID: | 385937 |
| Operable Unit ID: | 1143195 |
| Operable Unit: | 01 |
| Material ID: | 2133469 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 385937 |
| Operable Unit ID: | 1143195 |
| Operable Unit: | 01 |
| Material ID: | 2133468 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P121** **BQE-ATLANTIC AVE EXIT** **NY Spills** **S102141327**
**NE** **BROOKLYN QUEENS EXPRESSWAY/ATLANTIC AVE EXIT** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 7 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9106862 |
| Facility Type: | ER |
| DER Facility ID: | 327968 |
| Site ID: | 225358 |
| DEC Region: | 2 |
| Spill Date: | 9/26/1991 |
| Spill Number/Closed Date: | 9106862 / 9/26/1991 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Not reported |

**BQE-ATLANTIC AVE EXIT (Continued)** **S102141327**

| | |
|---|---|
| SWIS: | 2401 |
| Investigator: | MCTIBBE |
| Referred To: | Not reported |
| Reported to Dept: | 9/26/1991 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | 9/26/1991 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/3/1991 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | CAN AM CONTAINER |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE" |
| Remarks: | FD & PD ON SCENE. DEP NOTIFIED. SPILL AREA CLEANED |

Material:

| | |
|---|---|
| Site ID: | 225358 |
| Operable Unit ID: | 961103 |
| Operable Unit: | 01 |
| Material ID: | 422535 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 50 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P122** **BQE @ ATLANTIC AVE.** **NY Spills** **S102662590**
**NE** **ENTRANCE RAMP BQE & ATLAN** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 8 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9407938 |
| Facility Type: | ER |
| DER Facility ID: | 263504 |
| Site ID: | 327353 |
| DEC Region: | 2 |
| Spill Date: | 9/5/1994 |

**BQE @ ATLANTIC AVE. (Continued)** **S102662590**

| | |
|---|---|
| Spill Number/Closed Date: | 9407938 / 9/19/1994 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 9/15/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/27/1948 |
| Spill Record Last Update: | 2/6/1998 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 327353 |
| Operable Unit ID: | 1002147 |
| Operable Unit: | 01 |
| Material ID: | 377396 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**P123** **RT278 AT ATLANTIC AVE** **NY Spills** **S105056950**
**NE** **RT278 AT ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 9 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0101093 |
| Facility Type: | ER |
| DER Facility ID: | 62846 |
| Site ID: | 65438 |
| DEC Region: | 2 |
| Spill Date: | 4/27/2001 |
| Spill Number/Closed Date: | 0101093 / 4/30/2001 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 4/28/2001 |
| CID: | 216 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/28/2001 |
| Spill Record Last Update: | 5/28/2002 |
| Spiller Name: | MS LEONA BOWSER |
| Spiller Company: | ROADWAY |
| Spiller Address: | 1077 GORGE BLVD |
| Spiller City,St,Zip: | AKRON, OH 44310- |
| Spiller Company: | 001 |
| Contact Name: | DON O'HARA |
| Contact Phone: | (978) 568-1922 0 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"4/30/02 TJDTraffic accident caused release of 20 gallons of Diesel Fuel onto roadway of BQE at Atlantic Avenue. Sanatation responded to sand roadway. |
| Remarks: | accident saddletank ruptured spill will be cleaned up by brooklyn sanitation dept req dec to call |

Material:

| | |
|---|---|
| Site ID: | 65438 |
| Operable Unit ID: | 839851 |
| Operable Unit: | 01 |
| Material ID: | 536798 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |

**RT278 AT ATLANTIC AVE (Continued)** **S105056950**

Oxygenate: False

Tank Test:

---

**P124** **SPILL NUMBER 9805578** **NY Spills** **S104647372**
**NE** **BROOKLYN EXP/ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 10 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9805578 |
| Facility Type: | ER |
| DER Facility ID: | 98294 |
| Site ID: | 112538 |
| DEC Region: | 2 |
| Spill Date: | 8/5/1998 |
| Spill Number/Closed Date: | 9805578 / 8/5/1998 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MCTIBBE |
| Referred To: | Not reported |
| Reported to Dept: | 8/5/1998 |
| CID: | 201 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/5/1998 |
| Spill Record Last Update: | 5/13/2002 |
| Spiller Name: | DRIVER |
| Spiller Company: | DON SMITH/ADA TRUCKING |
| Spiller Address: | 14 HARMICH RD |
| Spiller City,St,Zip: | SO PLAINFIELD, NJ 07080- |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"TOW TRUCK TOOK PRODUCT. |
| Remarks: | TRAFFIC ACCIDENT/TRUCK AND CAR/SOME OF PRODUCT WENT INTO SEWER/SPILL HAS BEEN CONTAINED/LEAK HAS BEEN STOPPED |

Material:

| | |
|---|---|
| Site ID: | 112538 |
| Operable Unit ID: | 1066759 |
| Operable Unit: | 01 |
| Material ID: | 320317 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |

**SPILL NUMBER 9805578 (Continued)** **S104647372**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | 60 |
| Units: | Gallons |
| Recovered: | 30 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**P125** **BQE - ATLANTIC AVE** **NY Spills** **S102149254**
**NE** **BROOKLYN QUEENS EXPRESSWAY -ATLANTIC AVE-NR BRIDGE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.030 mi.**
**158 ft.** **Site 11 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9412952 |
| Facility Type: | ER |
| DER Facility ID: | 67618 |
| Site ID: | 71466 |
| DEC Region: | 2 |
| Spill Date: | 12/29/1994 |
| Spill Number/Closed Date: | 9412952 / 1/3/1995 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | ADZHITOM |
| Referred To: | Not reported |
| Reported to Dept: | 12/29/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Tank Truck |
| Spill Notifier: | Police Department |
| Cleanup Ceased: | 1/3/1995 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/5/1995 |
| Spill Record Last Update: | 2/6/1995 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY" |
| Remarks: | NYCDEP CONTACTED, NYC FIRE DEPT. ON SCENE, NYC DEPT. OF PUBLIC WORKS ON SCENE. |

Material:

| | |
|---|---|
| Site ID: | 71466 |
| Operable Unit ID: | 1006580 |

**BQE - ATLANTIC AVE (Continued)** **S102149254**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 375239 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**K126** **LOT 11,TAXBLOCK 299** **NY E DESIGNATION** **S109155495**
**ENE** **74 CONGRESS STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.033 mi.**
**172 ft.** **Site 2 of 2 in cluster K**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 11 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Air Quality - #2 Fuel Oil or Natural Gas Heat and Hot Water |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | NYVEST CORP |
| Lot Area: | 000004385 |
| Total Building Floor Area: | 00000006656 |
| Commercial Floor Area: | 00000006656 |
| Office Floor Area: | 00000000000 |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000006656 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0049.58 |
| Lot Depth: | 0094.58 |
| Building Frontage: | 0049.00 |
| Building Depth: | 0060.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000034920 |
| Total Assessed Value: | 00000081000 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.52 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984231 |
| Y Coordinate: | 0190408 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 11 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | NYVEST CORP |
| Lot Area: | 000004385 |
| Total Building Floor Area: | 00000006656 |
| Commercial Floor Area: | 00000006656 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000006656 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0049.58 |
| Lot Depth: | 0094.58 |
| Building Frontage: | 0049.00 |
| Building Depth: | 0060.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000034920 |
| Total Assessed Value: | 00000081000 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.52 |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984231 |
| Y Coordinate: | 0190408 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 11 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | NYVEST CORP |
| Lot Area: | 000004385 |
| Total Building Floor Area: | 00000006656 |
| Commercial Floor Area: | 00000006656 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000006656 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0049.58 |
| Lot Depth: | 0094.58 |
| Building Frontage: | 0049.00 |
| Building Depth: | 0060.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000034920 |
| Total Assessed Value: | 00000081000 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.52 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984231 |
| Y Coordinate: | 0190408 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 11 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | NYVEST CORP |
| Lot Area: | 000004385 |
| Total Building Floor Area: | 00000006656 |
| Commercial Floor Area: | 00000006656 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000006656 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0049.58 |
| Lot Depth: | 0094.58 |
| Building Frontage: | 0049.00 |
| Building Depth: | 0060.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000034920 |
| Total Assessed Value: | 00000081000 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.52 |
| Maximum Allowable Far: | 01.00 |

**LOT 11,TAXBLOCK 299 (Continued)** **S109155495**

| | |
|---|---|
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984231 |
| Y Coordinate: | 0190408 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**O127** **EAST RIVER** **NY Spills** **S102238445**
**NE** **29TH ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.034 mi.**
**179 ft.** **Site 8 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1005329 |
| Facility Type: | ER |
| DER Facility ID: | 197859 |
| Site ID: | 438643 |
| DEC Region: | 2 |
| Spill Date: | 8/11/2010 |
| Spill Number/Closed Date: | 1005329 / 8/11/2010 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | smsanges |
| Referred To: | Not reported |
| Reported to Dept: | 8/11/2010 |
| CID: | Not reported |
| Water Affected: | GOWANAS CANAL |
| Spill Source: | Vessel |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/11/2010 |
| Spill Record Last Update: | 8/11/2010 |
| Spiller Name: | Not reported |
| Spiller Company: | TANKER |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |

**EAST RIVER (Continued)** **S102238445**

| | |
|---|---|
| Contact Name: | LUKE BERYCHOWSKI |
| Contact Phone: | (516) 790-4426 |
| DEC Memo: | Associated with 2 NRC reports from today. A floating dock from "somewhere" broke free and floated out in the Gowanas Canal. Parts have broken off and are floating. Debris includes "a few" tanks or air tanks. Coast Guard is on site with several boats collecting the pieces. Sheen is minor and has been contained by the Coast Guard booms. Cleanup is almost complete. |
| Remarks: | sheen noted around tanker - coast guard already aware - no cleanup noted |

Material:

| | |
|---|---|
| Site ID: | 438643 |
| Operable Unit ID: | 1189293 |
| Operable Unit: | 01 |
| Material ID: | 2184248 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9511518 |
| Facility Type: | ER |
| DER Facility ID: | 197859 |
| Site ID: | 240587 |
| DEC Region: | 2 |
| Spill Date: | 12/12/1995 |
| Spill Number/Closed Date: | 9511518 / Not Reported |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JMOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 12/12/1995 |
| CID: | 270 |
| Water Affected: | EAST RIVER |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 12/12/1995 |
| Spill Record Last Update: | 6/16/2010 |
| Spiller Name: | ANDY OLIVER |
| Spiller Company: | USPOWERGEN |

**EAST RIVER (Continued)** **S102238445**

| | |
|---|---|
| Spiller Address: | 18-01 20 AVENUE |
| Spiller City,St,Zip: | LONG ISLAND CITY, NY 11105 |
| Spiller Company: | 001 |
| Contact Name: | SCALDONY |
| Contact Phone: | (718) 449-1301 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"6/17/10 - changed DEC lead from Krimgold to JMOCONNE (JOC) Not reported |
| Remarks: | leak is producing 1 drop every 6 seconds |

Material:

| | |
|---|---|
| Site ID: | 240587 |
| Operable Unit ID: | 1025730 |
| Operable Unit: | 01 |
| Material ID: | 358849 |
| Material Code: | 0541A |
| Material Name: | DIELECTRIC FLUID |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9511518 |
| Facility Type: | ER |
| DER Facility ID: | 197859 |
| Site ID: | 240587 |
| DEC Region: | 2 |
| Spill Date: | 12/12/1995 |
| Spill Number/Closed Date: | 9511518 / Not Reported |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JMOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 12/12/1995 |
| CID: | 270 |
| Water Affected: | EAST RIVER |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 12/12/1995 |
| Spill Record Last Update: | 6/16/2010 |
| Spiller Name: | ANDREW PETE |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |

**EAST RIVER (Continued)** **S102238445**

Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: SCALDONY
Contact Phone: (718) 449-1301
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"6/17/10 - changed DEC lead from Krimgold to JMOCONNE (JOC) Not reported
Remarks: leak is producing 1 drop every 6 seconds

Material:
Site ID: 240587
Operable Unit ID: 1025730
Operable Unit: 01
Material ID: 358849
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**I128** **VOLT #3203** **NY Spills** **S106011622**
**SSW** **HAMILTON AV OPP #2** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.035 mi.**
**185 ft.** **Site 4 of 4 in cluster I**

**Relative: Higher**

**Actual: 9 ft.**

SPILLS:
Facility ID: 0211543
Facility Type: ER
DER Facility ID: 186721
Site ID: 226208
DEC Region: 2
Spill Date: 2/20/2003
Spill Number/Closed Date: 0211543 / 4/3/2003
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2/21/2003
CID: 201
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

**VOLT #3203 (Continued)** **S106011622**

| | |
|---|---|
| Date Entered In Computer: | 2/21/2003 |
| Spill Record Last Update: | 4/3/2003 |
| Spiller Name: | CALLER |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | MANHATTAN, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"e2mis no. 147-228:20-FEB-2003 09:08 HRSWHILE ON LOCATION VS0 FOR MAINTENANCE WORK ON FEEDER 8B90 FOUND: APPROX. 1 PT OF UNKNOWN OIL ON APPROX. 300 GAL'S OF WATER. SPILL IS CONTAINED. NO SEWERS OR WATER WAYS APPEAR TO BE AFFECTED. NO KNOWN SEWER CONNECTION PRESENT. 1 LIQ. SAMPLE TAKEN FROM SPILL.Lab Sequence Number: 03-01432-001 Date Approved: 2/20/2003Aroclor 1260 < 1.0 ppm2/20/030HRS DINEEN NETW REPORTS UNIT WAS PRSSURE TESTED AND FAILED TEST. LEAKING AROUND MAGNETIC GAUGE. UNIT TO BE REPLACED. SAMPLE TAKEN FROM UNIT FOR DRAINING OF UNIT & FINAL CLEANUP.Update - 2/21/03 0710hrsA. Glodowskis env. ops reports >50 tanker removed 1500 gallons liquid from structure. Removed all mud and dirt with vactor. Double washed structure with slix. Left tag in place pending removal of unit. No sump in structure found. This structure is water hole.Update - 2/21/03 - Structure was double washed using safety wash (slix no longer used for the cleaning of structures). H Bertorelli # 54348.UPDATE: 2/26/03 - 1145J. CUADRADO - ENV. OPS., REPORTS UNIT WAS REMOVED BY EQUIPMENT DEPT. THE CLEANUP IS COMPLETED BY DOUBLE WASHINGSTRUCTURE WITH BIO GEN 760. LIQUID WASTE REMOVED BY ASTORIA TANKER. SOLID WASTE REMOVED WITH VACTOR. NO SUMPS ORDRAINS. TAG # 26654 REMOVED. TJ - 50495Update - 2/27/03 - 0520 hrs - Updated event involved materials and event involved persons lists. |
| Remarks: | 1 PT OF UNKNOWN OIL ON 300 GLS OF WATER. CON ED #147228 |

Material:

| | |
|---|---|
| Site ID: | 226208 |
| Operable Unit ID: | 862665 |
| Operable Unit: | 01 |
| Material ID: | 511327 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**M129** **129 DEGRAW ST** **NY HIST AST** **U003385409**
**SSE** **129 DE GRAW ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.036 mi.**
**191 ft.** **Site 3 of 5 in cluster M**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

HIST AST:

| | |
|---|---|
| PBS Number: | 2-189057 |
| SWIS Code: | 6101 |
| Operator: | NELLO BOTTI |
| Facility Phone: | (718) 358-6829 |
| Facility Addr2: | 129 DEGRAW ST |
| Facility Type: | MANUFACTURING |
| Emergency: | NELLO BOTTI |
| Emergency Tel: | (718) 358-6829 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | TIFFANY PLACE SUITES, INC. |
| Owner Address: | 876 WILLIS AVENUE |
| Owner City,St,Zip: | ALBERSTON, NY 11503 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 358-6829 |
| Owner Type: | Private Resident |
| Owner Subtype: | Not reported |
| Mailing Contact: | Not reported |
| Mailing Name: | NELLO BOTTI |
| Mailing Address: | 156-05 29TH AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | FLUSHING, NY 11354 |
| Mailing Telephone: | (718) 358-6829 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 04/28/1992 |
| Expiration: | 06/05/1997 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 7500 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 401 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | 11/01/1958 |
| Capacity (Gal): | 7500 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |

**129 DEGRAW ST (Continued)** **U003385409**

| | |
|---|---|
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 5 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | 6 |
| Tank Containment: | None |
| Leak Detection: | 9 |
| Overfill Protection: | 4 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**M130** **DESIGNERS WOODCRAFT INC** **FINDS** **1007746520**
**SSE** **129 DEGRAW STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.036 mi.**
**191 ft.** **Site 4 of 5 in cluster M**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

FINDS:

Registry ID: 110019089001

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**M131** **129 DEGRAW ST** **NY AST** **A100382290**
**SSE** **129 DEGRAW STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.036 mi.**
**191 ft.** **Site 5 of 5 in cluster M**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-189057 |
| Program Type: | PBS |
| UTM X: | 584375.43603999994 |
| UTM Y: | 4504311.0254300004 |
| Expiration Date: | N/A |
| Site Type: | Utility (Other than Municipal) |

Tank Info:

Tank Number: 001

**129 DEGRAW ST (Continued)** **A100382290**

| | |
|---|---|
| Tank Id: | 6385 |
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 11/01/1958 |
| Capacity Gallons: | 7500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 10/01/1999 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | Not reported |

---

**Q132** **CHASE BANK** **NY HIST UST** **U000417751**
**SSW** **79 HAMILTON AVE** **N/A**
**< 1/8** **BKLYN, NY 11231**
**0.037 mi.**
**196 ft.** **Site 1 of 5 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

HIST UST:

| | |
|---|---|
| PBS Number: | 2-288934 |
| SPDES Number: | Not reported |
| Emergency Contact: | JACK FUCICH |
| Emergency Telephone: | (212) 552-5377 |
| Operator: | JACK FUCICH |
| Operator Telephone: | (212) 552-5377 |
| Owner Name: | CHASE BANK |
| Owner Address: | 1 CHASE PLAZA, 23RD FL. |
| Owner City,St,Zip: | NEW YORK, NY 10081 |
| Owner Telephone: | (212) 552-5377 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | CHASE BANK |
| Mailing Address: | 1 CHASE PLAZA, 23RD FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | NEW YORK, NY 10081 |
| Mailing Contact: | JACK FUCICH |
| Mailing Telephone: | (212) 552-5377 |
| Owner Mark: | Second Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | 79 HAMILTON AVE |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | OTHER |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 04/06/1999 |
| Expiration Date: | 03/23/2004 |
| Renew Flag: | False |
| Renewal Date: | Not reported |

**CHASE BANK (Continued)** **U000417751**

| | |
|---|---|
| Total Capacity: | 2200 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |
| | |
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (gals): | 2200 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | Painted/Asphalt Coating |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Vent Whistle |
| Dispenser: | Suction |
| Date Tested: | 09/01/1993 |
| Next Test Date: | 09/01/1998 |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Horner EZ Check |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

---

**Q133** **JP MORGAN CHASE AND COMPANY** **NY AST** **A100300731**
**SSW** **79 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.037 mi.**
**196 ft.** **Site 2 of 5 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-288934 |
| Program Type: | PBS |
| UTM X: | 584052.99959999998 |
| UTM Y: | 4504012.0533199999 |
| Expiration Date: | N/A |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 12992 |
| Affiliation Type: | Mail Contact |

**JP MORGAN CHASE AND COMPANY (Continued)** **A100300731**

| | |
|---|---|
| Company Name: | JP MORGAN CHASE AND COMPANY |
| Contact Type: | Not reported |
| Contact Name: | JAMES S. LISCIOTTO |
| Address1: | 575 WASHINGTON BOULEVARD |
| Address2: | FOURTH FLOOR |
| City: | JERSEY CITY |
| State: | NJ |
| Zip Code: | 07310-1680 |
| Country Code: | 001 |
| Phone: | (201) 595-5851 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 12992 |
| Affiliation Type: | Facility Owner |
| Company Name: | JP MORGAN CHASE AND COMPANY |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 575 WASHINGTON BLVD., FOURTH FLOOR |
| Address2: | Not reported |
| City: | JERSEY CITY |
| State: | NJ |
| Zip Code: | 07310-1680 |
| Country Code: | 001 |
| Phone: | (201) 595-5851 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 12992 |
| Affiliation Type: | On-Site Operator |
| Company Name: | JP MORGAN CHASE AND COMPANY |
| Contact Type: | Not reported |
| Contact Name: | JAMES S. LISCIOTTO |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (201) 595-5851 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 12992 |
| Affiliation Type: | Emergency Contact |
| Company Name: | JP MORGAN CHASE AND COMPANY |
| Contact Type: | Not reported |
| Contact Name: | JAMES S. LISCIOTTO |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |

**JP MORGAN CHASE AND COMPANY (Continued)** **A100300731**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 595-5851
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 25641
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2200
Tightness Test Method: 03
Date Test: 09/01/1993
Next Test Date: Not reported
Date Tank Closed: 12/08/2002
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

---

**O134** **CONTINENTAL WAREHOUSE** **NY LTANKS** **S102233293**
**NE** **23RD STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.038 mi.**
**198 ft.** **Site 9 of 9 in cluster O**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

LTANKS:
Site ID: 299931
Spill Number/Closed Date: 9515551 / 3/4/1996
Spill Date: 3/4/1996
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

**CONTINENTAL WAREHOUSE (Continued)** **S102233293**

| | |
|---|---|
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 3/4/1996 |
| CID: | 275 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/4/1996 |
| Spill Record Last Update: | 3/26/1996 |
| Spiller Name: | MARYBETH ACKERS |
| Spiller Company: | NEWPORT TRANSPORT |
| Spiller Address: | 1397 PROGRESS RD |
| Spiller City,St,Zip: | SUFFOLK, VA 23434- |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | (718) 499-6300 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 242638 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"SPOKE TO OPERATOR @ WAREHOUSE, SAID ONLY 6 GALLONS OF OIL IN GROUND, CLEANED UP - NYFD PUMPPED OUT TANK, WILL RECYCLE OIL - FAX CONTRACTOR LIST TO WAREHOUSE FOR PROPER DISPOSAL OF DRUMED WASTE. |
| Remarks: | foreign object punctured saddle tank - spill has been contained - firedept is on scene at this time - 150 gallon tank |

Material:

| | |
|---|---|
| Site ID: | 299931 |
| Operable Unit ID: | 1030207 |
| Operable Unit: | 01 |
| Material ID: | 355673 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 150 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**P135** **VS4121 NORTH SIDE** **NY Spills** **S103938962**
**NE** **39TH STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.039 mi.**
**204 ft.** **Site 12 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9903606 |
| Facility Type: | ER |
| DER Facility ID: | 168504 |
| Site ID: | 202567 |
| DEC Region: | 2 |
| Spill Date: | 6/29/1999 |
| Spill Number/Closed Date: | 9903606 / 5/18/2000 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | COMENALE |
| Referred To: | Not reported |
| Reported to Dept: | 6/29/1999 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/29/1999 |
| Spill Record Last Update: | 4/15/2002 |
| Spiller Name: | STEPHEN CRIBBEN |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | MANHATTAN, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | STEPHEN CRIBBEN |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Not reported |
| Remarks: | TRANSFOMER BURNING LEAKED FROM BOTTOM - CON ED #125859 |

Material:

| | |
|---|---|
| Site ID: | 202567 |
| Operable Unit ID: | 1082540 |
| Operable Unit: | 01 |
| Material ID: | 303520 |
| Material Code: | 0020A |
| Material Name: | TRANSFORMER OIL |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**P136** **NEWTOWN CREEK & 43RD ST** **NY Spills** **S102150908**
**NE** **43RD ST & NEWTOWN CREEK** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.041 mi.**
**218 ft.** **Site 13 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9508251 |
| Facility Type: | ER |
| DER Facility ID: | 182377 |
| Site ID: | 220495 |
| DEC Region: | 2 |
| Spill Date: | 10/5/1995 |
| Spill Number/Closed Date: | 9508251 / 10/5/1995 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MMMULQUE |
| Referred To: | Not reported |
| Reported to Dept: | 10/5/1995 |
| CID: | 257 |
| Water Affected: | NEWTOWN CREEK |
| Spill Source: | Unknown |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/5/1995 |
| Spill Record Last Update: | 11/10/2003 |
| Spiller Name: | IGOR KURSUSKY |
| Spiller Company: | COMPUDYNE |
| Spiller Address: | 44-22 56TH AVENUE |
| Spiller City,St,Zip: | MASPETH, NY 11385- |
| Spiller Company: | 001 |
| Contact Name: | SAME |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN" |
| Remarks: | UNKNOWN PURPLE COLOR IN WATER COAST GUARD WOULD LIKEA RESPONDER FOR ASSISTANCE |

Material:

| | |
|---|---|
| Site ID: | 220495 |
| Operable Unit ID: | 1022811 |
| Operable Unit: | 01 |
| Material ID: | 553756 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**NEWTOWN CREEK & 43RD ST (Continued)** **S102150908**

Tank Test:

---

**G137** **LOT 19,TAXBLOCK 352** **NY E DESIGNATION** **S111072703**
**SSW** **20 CARROLL STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.045 mi.**
**237 ft.** **Site 6 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 19 |
| E-No: | E-264 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 11DCP038K |
| Ulurp Number: | 110118ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - HVAC fuel limited to natural gas |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | MVM HOLDINGS LLC |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002255 |
| Commercial Floor Area: | 00000000750 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000750 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Building Frontage: | 0020.00 |
| Building Depth: | 0036.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000004074 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.13 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982836 |
| Y Coordinate: | 0188225 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 19 |
| E-No: | E-264 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 11DCP038K |
| Ulurp Number: | 110118ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | MVM HOLDINGS LLC |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002255 |
| Commercial Floor Area: | 00000000750 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000750 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0036.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000004074 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.13 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982836 |
| Y Coordinate: | 0188225 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 19 |
| E-No: | E-264 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 11DCP038K |
| Ulurp Number: | 110118ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | MVM HOLDINGS LLC |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002255 |
| Commercial Floor Area: | 00000000750 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000750 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Building Depth: | 0036.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000004074 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.13 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982836 |
| Y Coordinate: | 0188225 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 19 |
| E-No: | E-264 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 11DCP038K |
| Ulurp Number: | 110118ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S3 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | MVM HOLDINGS LLC |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002255 |
| Commercial Floor Area: | 00000000750 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000750 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00004 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0036.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000004074 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.13 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982836 |
| Y Coordinate: | 0188225 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |

**LOT 19,TAXBLOCK 352 (Continued)** **S111072703**

| | |
|---|---|
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**R138** **HEINS RES** **NY Spills** **S103575132**
**SSW** **74 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.046 mi.**
**242 ft.** **Site 1 of 3 in cluster R**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9811188 |
| Facility Type: | ER |
| DER Facility ID: | 182129 |
| Site ID: | 220189 |
| DEC Region: | 2 |
| Spill Date: | 12/5/1998 |
| Spill Number/Closed Date: | 9811188 / 12/7/1998 |
| Spill Cause: | Unknown |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MCTIBBE |
| Referred To: | Not reported |
| Reported to Dept: | 12/5/1998 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/5/1998 |
| Spill Record Last Update: | 5/20/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | MR HEINS |
| Contact Phone: | (718) 643-9517 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"FDNY ON SCENE. RESIDENT SMELLS GASOLINE COMING FROM SEWER. TOLD FDNY TO FLUSH SEWER. HOUSE CONNECTION DOES NOT HAVE A SEWER TRAP. INFORMED RESIDENT TO INSTALL ONE. REPAIR SHOP IN VICINITY. ONE TIME EVENT. |
| Remarks: | comp reports homeowner smells gasoline in res tonite |

Material:

| | |
|---|---|
| Site ID: | 220189 |

**HEINS RES (Continued)** **S103575132**

| | |
|---|---|
| Operable Unit ID: | 1072052 |
| Operable Unit: | 01 |
| Material ID: | 315037 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**R139** **ERNS** **98983**
**SSW** **74 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.046 mi.**
**242 ft.** **Site 2 of 3 in cluster R**

**Relative:**
**Higher**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**Actual:**
**12 ft.**

---

**S140** **51 SACKETT ST/BKLYN** **NY Spills** **S102146004**
**South** **51 SACKETT STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.049 mi.**
**258 ft.** **Site 1 of 2 in cluster S**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9008428 |
| Facility Type: | ER |
| DER Facility ID: | 96164 |
| Site ID: | 109605 |
| DEC Region: | 2 |
| Spill Date: | 11/1/1990 |
| Spill Number/Closed Date: | 9008428 / 11/1/1990 |
| Spill Cause: | Unknown |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | FINGER |
| Referred To: | Not reported |
| Reported to Dept: | 11/1/1990 |
| CID: | Not reported |
| Water Affected: | GOWANUS CANAL |
| Spill Source: | Unknown |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 11/1/1990 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/7/1990 |

**51 SACKETT ST/BKLYN (Continued)** **S102146004**

| | |
|---|---|
| Spill Record Last Update: | 4/15/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | USCG INVESTIGATED, DISCOVERED MOTOR OIL, UNRECOVERABLE, NO SOURCE,NO ACTION. |

Material:

| | |
|---|---|
| Site ID: | 109605 |
| Operable Unit ID: | 949072 |
| Operable Unit: | 01 |
| Material ID: | 562076 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**G141** **LOT 20,TAXBLOCK 352** **NY E DESIGNATION** **S113496595**
**SSW** **22 CARROLL STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.049 mi.**
**259 ft.** **Site 7 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 20 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S4 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SOMMA THERESA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002180 |
| Commercial Floor Area: | 00000000727 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000727 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00005 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000001428 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000001428 |
| Total Exempt Value: | 00000001690 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.09 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982845 |
| Y Coordinate: | 0188184 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 20 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S4 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SOMMA THERESA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002180 |
| Commercial Floor Area: | 00000000727 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000727 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00005 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0048.00 |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000001428 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000001428 |
| Total Exempt Value: | 00000001690 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.09 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982845 |
| Y Coordinate: | 0188184 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 20 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S4 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SOMMA THERESA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002180 |
| Commercial Floor Area: | 00000000727 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000727 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00005 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000001428 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000001428 |
| Total Exempt Value: | 00000001690 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.09 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982845 |
| Y Coordinate: | 0188184 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 20 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | S4 |
| Land Use Category: | 04 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SOMMA THERESA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000002180 |
| Commercial Floor Area: | 00000000727 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000727 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00004 |
| Non and Residential Units: | 00005 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |

**LOT 20,TAXBLOCK 352 (Continued)** **S113496595**

| | |
|---|---|
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000001428 |
| Total Assessed Value: | 00000016564 |
| Land Exempt Value: | 00000001428 |
| Total Exempt Value: | 00000001690 |
| Year Built: | 1900 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.09 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982845 |
| Y Coordinate: | 0188184 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**G142** **LOT 54,TAXBLOCK 347** **NY E DESIGNATION** **S112139030**
**SSW** **23 CARROLL STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**272 ft.** **Site 8 of 8 in cluster G**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 54 |
| E-No: | E-263 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 09DCP032K |
| Ulurp Number: | 090225ZMK |
| Zoning Map No: | 6a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |

**LOT 54,TAXBLOCK 347 (Continued)** **S112139030**

| | |
|---|---|
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARATHON HOSIERY CO I |
| Lot Area: | 000005000 |
| Total Building Floor Area: | 00000021500 |
| Commercial Floor Area: | 00000021500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000021500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 005.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000030870 |
| Total Assessed Value: | 00000172800 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0004.30 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003470054 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982901 |
| Y Coordinate: | 0188333 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |

**LOT 54,TAXBLOCK 347 (Continued)** **S112139030**

| | |
|---|---|
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 54 |
| E-No: | E-263 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 09DCP032K |
| Ulurp Number: | 090225ZMK |
| Zoning Map No: | 6a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARATHON HOSIERY CO I |
| Lot Area: | 000005000 |
| Total Building Floor Area: | 00000021500 |
| Commercial Floor Area: | 00000021500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000021500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 005.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00002 |

**LOT 54,TAXBLOCK 347 (Continued)** **S112139030**

| | |
|---|---|
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000030870 |
| Total Assessed Value: | 00000172800 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0004.30 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003470054 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982901 |
| Y Coordinate: | 0188333 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J143** **LOT 62,TAXBLOCK 319** **NY E DESIGNATION** **S108469994**
**SE** **36 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**276 ft.** **Site 14 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 62 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |

**LOT 62,TAXBLOCK 319 (Continued)** **S108469994**

| | |
|---|---|
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GREGORY OCONNELL |
| Lot Area: | 000006093 |
| Total Building Floor Area: | 00000018172 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00007 |
| Non and Residential Units: | 00007 |
| Lot Frontage: | 0062.50 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0035.00 |
| Building Depth: | 0065.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000011014 |
| Total Assessed Value: | 00000139932 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1920 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.98 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190062 |
| Condominium Number: | 00000 |

**LOT 62,TAXBLOCK 319 (Continued)** **S108469994**

| | |
|---|---|
| Census Tract 2: | 0047 |
| X Coordinate: | 0983863 |
| Y Coordinate: | 0189322 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**J144** **LOT 7501,TAXBLOCK 319** **NY E DESIGNATION** **S111073041**
**SE** **42 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**276 ft.** **Site 15 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 7501 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | R4 |
| Land Use Category: | 03 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | Not reported |
| Lot Area: | 000006031 |
| Total Building Floor Area: | 00000013791 |
| Commercial Floor Area: | 00000000000 |

**LOT 7501,TAXBLOCK 319 (Continued)** **S111073041**

| | |
|---|---|
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 006.00 |
| Residential Units: | 00012 |
| Non and Residential Units: | 00012 |
| Lot Frontage: | 0062.50 |
| Lot Depth: | 0096.50 |
| Building Frontage: | 0030.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 0 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000045453 |
| Total Assessed Value: | 00000059897 |
| Land Exempt Value: | 00000004103 |
| Total Exempt Value: | 00000004103 |
| Year Built: | 1902 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.29 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003197501 |
| Condominium Number: | 01037 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983847 |
| Y Coordinate: | 0189273 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**J145**
**SE**
**< 1/8**
**0.052 mi.**
**277 ft.**

**LOT 7503,TAXBLOCK 319**
**20 TIFFANY PLACE**
**BROOKLYN, NY**

**Site 16 of 18 in cluster J**

**NY E DESIGNATION** **S113453319**
**N/A**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 7503 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | Not reported |
| Community District: | Not reported |
| Census Tract: | Not reported |
| Census Block: | Not reported |
| School District: | Not reported |
| City Council District: | Not reported |
| Fire Company: | Not reported |
| Health Area: | Not reported |
| Police Precinct: | Not reported |
| Zone District 1: | Not reported |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | Not reported |
| All Components2: | Not reported |
| Split Boundary Indicator: | Not reported |
| Building Class: | Not reported |
| Land Use Category: | Not reported |
| Number of Easements: | Not reported |
| Owner, Type of Code: | Not reported |
| Owner Name: | Not reported |
| Lot Area: | Not reported |
| Total Building Floor Area: | Not reported |
| Commercial Floor Area: | Not reported |
| Office Floor Area: | Not reported |
| Retail Floor Area: | Not reported |
| Garage Floor Area: | Not reported |
| Storage Floor Area: | Not reported |
| Factory Floor Area: | Not reported |
| Other Floor Area: | Not reported |
| Floor Area,Total Bld Source Code: | Not reported |
| Number of Buildings: | Not reported |
| Number of Floors: | Not reported |
| Residential Units: | Not reported |
| Non and Residential Units: | Not reported |
| Lot Frontage: | Not reported |
| Lot Depth: | Not reported |
| Building Frontage: | Not reported |
| Building Depth: | Not reported |
| Proximity Code: | Not reported |
| Irregular Lot Code: | Not reported |
| Lot Type: | Not reported |

**LOT 7503,TAXBLOCK 319 (Continued)** **S113453319**

| | |
|---|---|
| Basement Type Grade: | Not reported |
| Land Assessed Value: | Not reported |
| Total Assessed Value: | Not reported |
| Land Exempt Value: | Not reported |
| Total Exempt Value: | Not reported |
| Year Built: | Not reported |
| Year Built Code: | Not reported |
| Year Altered1: | Not reported |
| Year Altered2: | Not reported |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | Not reported |
| Maximum Allowable Far: | Not reported |
| Borough Code: | Not reported |
| Borough Tax Block And Lot: | Not reported |
| Condominium Number: | Not reported |
| Census Tract 2: | Not reported |
| X Coordinate: | Not reported |
| Y Coordinate: | Not reported |
| Zoning Map: | Not reported |
| Sanborn Map: | Not reported |
| Tax Map: | Not reported |
| E Designation No: | Not reported |
| Date of RPAD Data: | Not reported |
| Date of DCAS Data: | Not reported |
| Date of Zoning Data: | Not reported |
| Date of Major Property Data: | Not reported |
| Date of Landmark Data: | Not reported |
| Date of Base Map Data: | Not reported |
| Date of Mass Appraisal Data: | Not reported |
| Date of Political and Adm Data: | Not reported |
| Pluto-Base Map Indicator: | Not reported |

---

**J146** **LOT 55,TAXBLOCK 319** **NY E DESIGNATION** **S108469992**
**SE** **26 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**277 ft.** **Site 17 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 55 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 55,TAXBLOCK 319 (Continued)** **S108469992**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | 40 TIFFANY CORP |
| Lot Area: | 000013722 |
| Total Building Floor Area: | 00000044853 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00016 |
| Non and Residential Units: | 00016 |
| Lot Frontage: | 0135.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0040.00 |
| Building Depth: | 0089.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000079200 |
| Total Assessed Value: | 00000418500 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1920 |
| Year Built Code: | E |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0003.27 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190055 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983920 |
| Y Coordinate: | 0189434 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |

**LOT 55,TAXBLOCK 319 (Continued)** **S108469992**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**T147** **LOT 49,TAXBLOCK 319** **NY E DESIGNATION** **S108469988**
**SE** **16 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**277 ft.** **Site 1 of 5 in cluster T**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 49 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | DI CASOLI ELIZABETH |
| Lot Area: | 000002535 |
| Total Building Floor Area: | 00000006250 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |

**LOT 49,TAXBLOCK 319 (Continued)** **S108469988**

| | |
|---|---|
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00008 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0026.00 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0026.00 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000003012 |
| Total Assessed Value: | 00000032383 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190049 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983960 |
| Y Coordinate: | 0189584 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**T148** **LOT 50,TAXBLOCK 319** **NY E DESIGNATION** **S108469990**
**SE** **18 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.052 mi.**
**277 ft.** **Site 2 of 5 in cluster T**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 50 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |

**LOT 50,TAXBLOCK 319 (Continued)** **S108469990**

| | |
|---|---|
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C1 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CARDINALE RICHARD |
| Lot Area: | 000002584 |
| Total Building Floor Area: | 00000006300 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00008 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0026.50 |
| Lot Depth: | 0097.50 |
| Building Frontage: | 0026.50 |
| Building Depth: | 0050.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000002949 |
| Total Assessed Value: | 00000032383 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1900 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.44 |

**LOT 50,TAXBLOCK 319 (Continued)** **S108469990**

| | |
|---|---|
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983951 |
| Y Coordinate: | 0189560 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**U149** **NYCDEP** **NJ MANIFEST** **S107909201**
**SSW** **SEABRING & VAN BRUNT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.052 mi.**
**277 ft.** **Site 1 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

NJ MANIFEST:

| | |
|---|---|
| Manifest Code: | NJA5212570 |
| EPA ID: | NYP003662426 |
| Date Shipped: | 07/18/2005 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 07/18/2005 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 07/18/2005 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |

**NYCDEP (Continued)** **S107909201**

| | |
|---|---|
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 09020535 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

---

**L150** **LOT 42,TAXBLOCK 319** **NY E DESIGNATION** **S108469987**
**ESE** **2 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.053 mi.**
**278 ft.** **Site 3 of 3 in cluster L**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 42 |
| E-No: | E-1 |
| Effective Date: | 4/28/1983 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | NA |
| Ulurp Number: | 830178 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Double Glazed Windows |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 2003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |

**LOT 42,TAXBLOCK 319 (Continued)** **S108469987**

| | |
|---|---|
| Split Boundary Indicator: | N |
| Building Class: | G6 |
| Land Use Category: | 10 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | O CONNELL GREGORY |
| Lot Area: | 000013280 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0150.17 |
| Lot Depth: | 0075.33 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000112500 |
| Total Assessed Value: | 00000117450 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003190042 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983993 |
| Y Coordinate: | 0189661 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 032 |
| Tax Map: | 30201 |
| E Designation No: | E-1 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |

**LOT 42,TAXBLOCK 319 (Continued)** **S108469987**

Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**P151** **BETWEEN 2ND AV & 3RD AV** **NY Spills** **S104508816**
**NE** **45TH ST BET 2ND & 3RD AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.053 mi.**
**280 ft.** **Site 14 of 14 in cluster P**

**Relative:**
**Higher**

**Actual:**
**24 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9911584 |
| Facility Type: | ER |
| DER Facility ID: | 103855 |
| Site ID: | 119568 |
| DEC Region: | 2 |
| Spill Date: | 1/5/2000 |
| Spill Number/Closed Date: | 9911584 / 1/12/2000 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR) |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 1/5/2000 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/5/2000 |
| Spill Record Last Update: | 2/18/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"SCHEDULE FOR DRUM RUN.NO CONTAINERS OR DRUMS FOUNDSEE SPILL #9930008 |
| Remarks: | 6 - 1GAL CONTAINERS OF UNK MATERIAL THAT IS MARKED FLAMMABLE - CONTAINERS SITTING ON SIDEWALK - DEP NOT DOING ANYTHING WITH THEM |

Material:

| | |
|---|---|
| Site ID: | 119568 |
| Operable Unit ID: | 1086196 |
| Operable Unit: | 01 |
| Material ID: | 297041 |
| Material Code: | 0063A |
| Material Name: | UNKNOWN HAZARDOUS MATERIAL |
| Case No.: | Not reported |
| Material FA: | Hazardous Material |

**BETWEEN 2ND AV & 3RD AV (Continued)** **S104508816**

Quantity: 6
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**V152** **RED HOOK CONTAINER** **NY Spills** **S104194379**
**SSW** **RED HOOK CONTAINER** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.054 mi.**
**283 ft.** **Site 1 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

SPILLS:
Facility ID: 9906280
Facility Type: ER
DER Facility ID: 186227
Site ID: 225592
DEC Region: 2
Spill Date: 8/26/1999
Spill Number/Closed Date: 9906280 / 11/12/1999
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 8/26/1999
CID: 205
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/26/1999
Spill Record Last Update: 11/17/1999
Spiller Name: CALLER
Spiller Company: RED HOOK CONTAINER
Spiller Address: RED HOOK CONTAINER
Spiller City,St,Zip: BROOKLYN, NY
Spiller Company: 001
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: coast guard reported spill from improper packaging. cleanup completed. Not reported

Material:
Site ID: 225592
Operable Unit ID: 1080727
Operable Unit: 01
Material ID: 302552

**RED HOOK CONTAINER (Continued)** **S104194379**

| | |
|---|---|
| Material Code: | 0038E |
| Material Name: | WHITE CAUSTIC |
| Case No.: | 01310732 |
| Material FA: | Hazardous Material |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**V153** **RED HOOK TERMINAL** **NY LTANKS** **S103570854**
**SSW** **HAMILTON AVE** **NY Spills** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.054 mi.**
**283 ft.** **Site 2 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 180860 |
| Spill Number/Closed Date: | 8908683 / 12/2/1989 |
| Spill Date: | 12/2/1989 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Vessel |
| Spill Class: | Not reported |
| Cleanup Ceased: | 12/2/1989 |
| Cleanup Meets Standard: | True |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 12/2/1989 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/10/1990 |
| Spill Record Last Update: | 1/25/1990 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 151700 |
| DEC Memo: | Not reported |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 180860 |
| Operable Unit ID: | 936019 |

**RED HOOK TERMINAL (Continued)** **S103570854**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 441875 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

SPILLS:

| | |
|---|---|
| Facility ID: | 9704119 |
| Facility Type: | ER |
| DER Facility ID: | 151700 |
| Site ID: | 180861 |
| DEC Region: | 2 |
| Spill Date: | 7/7/1997 |
| Spill Number/Closed Date: | 9704119 / 7/7/1997 |
| Spill Cause: | Other |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 7/7/1997 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/7/1997 |
| Spill Record Last Update: | 1/23/1998 |
| Spiller Name: | Not reported |
| Spiller Company: | PARAGON COMMERCIAL |
| Spiller Address: | 90B CENTURIAN DRIVE |
| Spiller City,St,Zip: | ONTARIO CANADA, CA |
| Spiller Company: | 001 |
| Contact Name: | JACK DONAHUE |
| Contact Phone: | (718) 875-0084 |
| DEC Memo: | Not reported |
| Remarks: | CONTAINER UNLOADED AND FOUND TO BE LEAKING - NYC FD HAZ MAT ON SCENE - DEP IS ALSO SENDING A CREW - CONTAINER IS ISOLATED |

Material:

| | |
|---|---|
| Site ID: | 180861 |
| Operable Unit ID: | 1047345 |
| Operable Unit: | 01 |

**RED HOOK TERMINAL (Continued)** **S103570854**

| | |
|---|---|
| Material ID: | 333378 |
| Material Code: | 0029C |
| Material Name: | HYDROGEN CHLORIDE |
| Case No.: | 07647010 |
| Material FA: | Hazardous Material |
| Quantity: | 1745 |
| Units: | Pounds |
| Recovered: | 1745 |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 180861 |
| Operable Unit ID: | 1047345 |
| Operable Unit: | 01 |
| Material ID: | 333379 |
| Material Code: | 0326A |
| Material Name: | ISOPROPYL ALCOHOL |
| Case No.: | 00067630 |
| Material FA: | Other |
| Quantity: | 25080 |
| Units: | Pounds |
| Recovered: | 25080 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**Q154** **89-101 HAMILTON AVENUE** **NY Spills** **S102962147**
**SSW** **89-101 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.054 mi.**
**284 ft.** **Site 3 of 5 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9712252 |
| Facility Type: | ER |
| DER Facility ID: | 163901 |
| Site ID: | 196911 |
| DEC Region: | 2 |
| Spill Date: | 2/1/1998 |
| Spill Number/Closed Date: | 9712252 / 2/3/1998 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 2/3/1998 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |

**89-101 HAMILTON AVENUE (Continued)** **S102962147**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/3/1998 |
| Spill Record Last Update: | 2/4/1998 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | ELIE SAINT JEAN |
| Contact Phone: | (718) 595-4653 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"MR. SURMING 789-0483, REFER BACK TO DEP. |
| Remarks: | UNKNOWN INFORMATION AS TO WHAT OCCURRED |

Material:

| | |
|---|---|
| Site ID: | 196911 |
| Operable Unit ID: | 1054856 |
| Operable Unit: | 01 |
| Material ID: | 326872 |
| Material Code: | 0012A |
| Material Name: | Kerosene |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**J155** **TIFFANY MEWS** **NY AST** **U003395548**
**SE** **63 TIFFANY PLACE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.054 mi.**
**286 ft.** **Site 18 of 18 in cluster J**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-600107 |
| Program Type: | PBS |
| UTM X: | 584449.76480999996 |
| UTM Y: | 4504443.5102199996 |
| Expiration Date: | 2015/03/22 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 22092 |
| Affiliation Type: | Mail Contact |
| Company Name: | C.H.T PALCE LLC |
| Contact Type: | Not reported |
| Contact Name: | PHIL GOLDSTIEN |
| Address1: | 1465A FLATBUSH AVE |
| Address2: | Not reported |
| City: | BROOKLYN |

**TIFFANY MEWS (Continued)** **U003395548**

State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 434-9440
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/17/2011

Site Id: 22092
Affiliation Type: On-Site Operator
Company Name: TIFFANY MEWS
Contact Type: Not reported
Contact Name: FRANSISCO AMIGON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 323-4952
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/17/2011

Site Id: 22092
Affiliation Type: Emergency Contact
Company Name: C.H.T PLACE LLC
Contact Type: Not reported
Contact Name: FRANSISCO AMIGON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 323-4952
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/17/2011

Site Id: 22092
Affiliation Type: Facility Owner
Company Name: C.H.T PLACE LLC
Contact Type: MGR
Contact Name: PHIL GOLDSTIEN
Address1: 1465A FLATBUSH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 434-9440
EMail: Not reported
Fax Number: Not reported

**TIFFANY MEWS (Continued)** **U003395548**

Modified By: MSBAPTIS
Date Last Modified: 5/17/2011

Tank Info:

Tank Number: 001
Tank Id: 41286
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1990
Capacity Gallons: 5000
Tightness Test Method: ZZ
Date Test: 04/01/1990
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DXLIVING
Last Modified: 03/15/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

---

**U156** **NYC DEP** **NY MANIFEST** **1009235757**
**SSW** **SEABRING & VAN BRUNT STS** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.054 mi.**
**286 ft.** **Site 2 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

NY MANIFEST:
EPA ID: NYP003662426
Country: USA
Mailing Name: NYC DEP
Mailing Contact: DENISE ATKINS
Mailing Address: 5917 JUNCTION BLVD
Mailing Address 2: Not reported
Mailing City: CORONA
Mailing State: NY
Mailing Zip: 11368
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 646-879-7312

**NYC DEP (Continued)** **1009235757**

| | |
|---|---|
| Document ID: | NJA5212570 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/18/2005 |
| Trans1 Recv Date: | 07/18/2005 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/18/2005 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP003662426 |
| Trans1 EPA ID: | S5811 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | D018 - BENZENE 0.5 MG/L TCLP |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NJA5212570 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/18/2005 |
| Trans1 Recv Date: | 07/18/2005 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/18/2005 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP003662426 |
| Trans1 EPA ID: | S5811 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | D018 - BENZENE 0.5 MG/L TCLP |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2005 |

---

**T157** **TIFFANY MEWS LIMITED PARTNERSHIP** **NY AST** **U000411809**
**SE** **37 TIFFANY PLACE** **NY HIST AST** **N/A**
**< 1/8** **BKLYN, NY 11231**
**0.054 mi.**
**287 ft.** **Site 3 of 5 in cluster T**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-600058 |

**TIFFANY MEWS LIMITED PARTNERSHIP (Continued)** **U000411809**

Program Type: PBS
UTM X: 584459.61089999997
UTM Y: 4504472.5494400002
Expiration Date: N/A
Site Type: Other

Affiliation Records:

Site Id: 22045
Affiliation Type: Mail Contact
Company Name: THE ARIANA CONDOMINIUM
Contact Type: Not reported
Contact Name: VITO MANGINI
Address1: C/O TUDOR REALTY SERVICES CORP.
Address2: 250 PARK AVENUE SOUTH
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 557-3600
EMail: Not reported
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 1/6/2005

Site Id: 22045
Affiliation Type: On-Site Operator
Company Name: THE ARIANA CONDOMINIUM
Contact Type: Not reported
Contact Name: EKURAN SEHU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 488-9872
EMail: Not reported
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 1/6/2005

Site Id: 22045
Affiliation Type: Emergency Contact
Company Name: THE ARIANA CONDOMINIUM
Contact Type: Not reported
Contact Name: VITO MANGINI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 537-3600
EMail: Not reported
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 1/6/2005

**TIFFANY MEWS LIMITED PARTNERSHIP (Continued)** **U000411809**

| | |
|---|---|
| Site Id: | 22045 |
| Affiliation Type: | Facility Owner |
| Company Name: | THE ARIANA CONDOMINIUM |
| Contact Type: | ACCOUNT EXECUTIVE |
| Contact Name: | VITO MANGINI |
| Address1: | 250 PARK AVENUE SOUTH |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10003 |
| Country Code: | 001 |
| Phone: | (212) 557-3600 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 1/6/2005 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 41204 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - In Place |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 3000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 04/03/1998 |
| Register: | True |
| Modified By: | EJCALIFA |
| Last Modified: | 01/06/2005 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-600058 |
| SWIS Code: | 6101 |
| Operator: | TIFFANY MEWS LTD PARTNERSHIP |
| Facility Phone: | (718) 522-6400 |
| Facility Addr2: | 37 TIFFANY PLACE |

**TIFFANY MEWS LIMITED PARTNERSHIP (Continued)** **U000411809**

| | |
|---|---|
| Facility Type: | OTHER |
| Emergency: | ANDREW LEIDER |
| Emergency Tel: | (718) 522-6400 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | TIFFANY MEWS LIMITED PARTNERSHIP |
| Owner Address: | 69 WARREN STREET |
| Owner City,St,Zip: | BKLYN, NY 11201 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 522-6400 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | ANDREW LEIDER |
| Mailing Name: | CUNEO-LEIDER MANAGEMENT CORP |
| Mailing Address: | 69 WARREN STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BKLYN, NY 11201 |
| Mailing Telephone: | (718) 522-6400 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 03/27/1997 |
| Expiration: | 04/19/2001 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 3000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |
| | |
| Tank ID: | 001 |
| Tank Location: | UNDERGROUND, VAULTED, WITH ACCESS |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 3000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 0 |
| Pipe Location: | Not reported |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | Diking |
| Leak Detection: | 0 |
| Overfill Protection: | 0 |

**TIFFANY MEWS LIMITED PARTNERSHIP (Continued)** **U000411809**

| | |
|---|---|
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**N158** **EDR US Hist Auto Stat** **1015629629**
**South** **77 SACKETT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.054 mi.**
**287 ft.** **Site 2 of 2 in cluster N**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | CHANGS AUTOMOBILE REPAIR |
| Year: | 2011 |
| Address: | 77 SACKETT ST |
| Name: | CHANGS AUTO REPAIR |
| Year: | 2012 |
| Address: | 77 SACKETT ST |

---

**V159** **ERNS** **2007309800**
**SSW** **70 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.055 mi.**
**291 ft.** **Site 3 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

**V160** **AMERICAN STEVEDORING INC** **PA MANIFEST** **S109244777**
**SSW** **70 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.055 mi.**
**291 ft.** **Site 4 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

PA MANIFEST:

| | |
|---|---|
| Year: | 2007 |
| Manifest Number: | 000237932FLE |
| Manifest Type: | Not reported |
| Generator EPA Id: | NYP000961250 |
| Generator Date: | 01/15/2007 |
| Mailing Address: | Not reported |
| Mailing City,St,Zip: | Not reported |
| Contact Name: | Not reported |
| Contact Phone: | 718-875-0777 |
| TSD Epa Id: | PAD067098822 |
| TSD Date: | Not reported |
| TSD Facility Name: | CYCLE CHEM INC |
| TSD Facility Address: | 550 INDUSTRIAL DRIVE |

**AMERICAN STEVEDORING INC (Continued)** **S109244777**

| | |
|---|---|
| TSD Facility City: | LEWISBERRY |
| TSD Facility State: | PA |
| Facility Telephone: | Not reported |
| Page Number: | 1 |
| Line Number: | 2 |
| Waste Number: | D001 |
| Container Number: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Waste Quantity: | 200 |
| Unit: | Pounds |
| Handling Code: | Not reported |
| TSP EPA Id: | Not reported |
| Date TSP Sig: | Not reported |

| | |
|---|---|
| Year: | 2007 |
| Manifest Number: | 000237932FLE |
| Manifest Type: | Not reported |
| Generator EPA Id: | NYP000961250 |
| Generator Date: | 01/15/2007 |
| Mailing Address: | Not reported |
| Mailing City,St,Zip: | Not reported |
| Contact Name: | Not reported |
| Contact Phone: | 718-875-0777 |
| TSD Epa Id: | PAD067098822 |
| TSD Date: | Not reported |
| TSD Facility Name: | CYCLE CHEM INC |
| TSD Facility Address: | 550 INDUSTRIAL DRIVE |
| TSD Facility City: | LEWISBERRY |
| TSD Facility State: | PA |
| Facility Telephone: | Not reported |
| Page Number: | 1 |
| Line Number: | 1 |
| Waste Number: | D001 |
| Container Number: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Waste Quantity: | 10 |
| Unit: | Gallons (liquids only) |
| Handling Code: | Not reported |
| TSP EPA Id: | Not reported |
| Date TSP Sig: | Not reported |

---

**V161** **RED HOOK CONTAINER TERMINAL** **NY UST** **U004064143**
**SSW** **70 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.055 mi.**
**291 ft.** **Site 5 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-603004 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2017/05/19 |
| UTM X: | 584001.625 |
| UTM Y: | 4504073 |
| Site Type: | Municipality (Incl. Waste Water Treatment Plants, |

Affiliation Records:

**RED HOOK CONTAINER TERMINAL (Continued)** **U004064143**

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Mail Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | JUDITH STRINGER |
| Address1: | 90 COLUMBIA STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 676-8481 |
| EMail: | J[INVALID]R@PANYNJ.GOV |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 8/20/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | On-Site Operator |
| Company Name: | RED HOOK CONTAINER TERMINAL |
| Contact Type: | Not reported |
| Contact Name: | RED HOOK CONTAINER TERMINAL, LLC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 875-0777 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 3/14/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | Not reported |
| Contact Name: | FRANK JORDAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 295-0995 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 3/14/2012 |

| | |
|---|---|
| Site Id: | 24959 |
| Affiliation Type: | Facility Owner |
| Company Name: | THE PORT AUTHORITY OF NY & NJ |
| Contact Type: | ENVIRONMENTAL PROGRAM ANALYST |
| Contact Name: | JUDITH STRINGER |
| Address1: | 225 PARK AVENUE SOUTH |

**RED HOOK CONTAINER TERMINAL (Continued)** **U004064143**

| | |
|---|---|
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10003 |
| Country Code: | 001 |
| Phone: | (718) 435-7000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 8/20/2012 |

Tank Info:

| | |
|---|---|
| Tank Number: | 11A |
| Tank ID: | 52555 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1980 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 21 |
| Date Test: | 05/08/2009 |
| Next Test Date: | 05/08/2014 |
| Pipe Model: | Not reported |
| Modified By: | BKFALVEY |
| Last Modified: | 10/19/2012 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
K01 - Spill Prevention - Catch Basin
B07 - Tank External Protection - Retrofitted Sacrificial Anode
I03 - Overfill - Automatic Shut-Off
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm

| | |
|---|---|
| Tank Number: | 11B |
| Tank ID: | 52556 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1980 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |

**RED HOOK CONTAINER TERMINAL (Continued)** **U004064143**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 05/08/2009
Next Test Date: 05/08/2014
Pipe Model: Not reported
Modified By: BKFALVEY
Last Modified: 10/19/2012

Equipment Records:

C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser

Tank Number: 11C
Tank ID: 52557
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 05/08/2009
Next Test Date: 05/08/2014
Pipe Model: Not reported
Modified By: BKFALVEY
Last Modified: 10/19/2012

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
I03 - Overfill - Automatic Shut-Off
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser

**RED HOOK CONTAINER TERMINAL (Continued)** **U004064143**

| | |
|---|---|
| Tank Number: | 11D |
| Tank ID: | 52558 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1980 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 21 |
| Date Test: | 05/08/2009 |
| Next Test Date: | 05/08/2014 |
| Pipe Model: | Not reported |
| Modified By: | BKFALVEY |
| Last Modified: | 10/19/2012 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm

---

**V162** **AMERICAN STEVEDORING INC** **RCRA NonGen / NLR** **1014395214**
**SSW** **70 HAMILTON AVENUE** **NYP000964700**
**< 1/8** **BROOKLYN, NY 11231**
**0.055 mi.**
**291 ft.** **Site 6 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 05/01/2009 |
| Facility name: | AMERICAN STEVEDORING INC |
| Facility address: | 70 HAMILTON AVENUE<br>BROOKLYN, NY 11231 |
| EPA ID: | NYP000964700 |
| Mailing address: | HAMILTON AVENUE<br>BROOKLYN, NY 11231 |
| Contact: | FRANK JORDAN |
| Contact address: | HAMILTON AVENUE<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | 718-875-0777 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

**AMERICAN STEVEDORING INC (Continued)** **1014395214**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Violation Status: No violations found

---

**V163** **US COAST GUARD/RED HOOK MARINE TERMINAL** **NY MANIFEST** **1009231934**
**SSW** **70 HAMILTON AVE PIER 10** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.055 mi.**
**291 ft.** **Site 7 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

NY MANIFEST:
- EPA ID: NYP000795781
- Country: USA
- Mailing Name: US COAST GUARD/RED HOOK MARINE TERMINAL
- Mailing Contact: US COAST GUARD/RED HOOK MARINE TERMINAL
- Mailing Address: BLDG 108 CAPTAIN OF THE PORT
- Mailing Address 2: Not reported
- Mailing City: GOVERNOR'S ISLAND
- Mailing State: NY
- Mailing Zip: 10004
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: 800-645-8265

- Document ID: CTF0380219
- Manifest Status: Completed copy
- Trans1 State ID: NJTAF7808
- Trans2 State ID: Not reported
- Generator Ship Date: 960201
- Trans1 Recv Date: 960201
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 960201
- Part A Recv Date: 960510
- Part B Recv Date: 960214
- Generator EPA ID: NYP000795781
- Trans1 EPA ID: NJD000813477
- Trans2 EPA ID: Not reported
- TSDF ID: CTD000604488
- Waste Code: D003 - NON-LISTED REACTIVE WASTES
- Quantity: 00300
- Units: P - Pounds
- Number of Containers: 005

**US COAST GUARD/RED HOOK MARINE TERMINAL (Continued)** **1009231934**

| | |
|---|---|
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 96 |

| | |
|---|---|
| Document ID: | CTF0509644 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 960127 |
| Trans1 Recv Date: | 960127 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 960127 |
| Part A Recv Date: | 960510 |
| Part B Recv Date: | 960214 |
| Generator EPA ID: | NYP000795781 |
| Trans1 EPA ID: | NJD000813477 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | CTD000604488 |
| Waste Code: | D003 - NON-LISTED REACTIVE WASTES |
| Quantity: | 05240 |
| Units: | P - Pounds |
| Number of Containers: | 131 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00600 |
| Units: | P - Pounds |
| Number of Containers: | 007 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00020 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 96 |

---

**V164** **AMERICAN STEVEDORING INC** **NY LTANKS** **S108650243**
**SSW** **70 HAMILTON AVE** **NY MANIFEST** **N/A**
**< 1/8** **BROOKLYN, NY 11231** **NY Spills**
**0.055 mi.**
**291 ft.** **Site 8 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 254290 |
| Spill Number/Closed Date: | 9705748 / 8/12/1997 |
| Spill Date: | 8/12/1997 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 8/12/1997 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Notifier: | Federal Government |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/12/1997 |
| Spill Record Last Update: | 8/13/1997 |
| Spiller Name: | FRANK JORDAN |
| Spiller Company: | RED HOOK TERMINALS |
| Spiller Address: | 70 HAMILTON AVENUE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 001 |
| Spiller Contact: | FRANK JORDAN |
| Spiller Phone: | (718) 875-0777 |
| Spiller Extention: | 238 |
| DEC Region: | 2 |
| DER Facility ID: | 208281 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT"PLEASE SEE NOTES ON BACK OF SPILL REPORT. |
| Remarks: | DISCOVERED TONGUE OIL TRANSPORT TANK LEAKING FROM TOP THIS MORNING. ONTO UNKNOWN TYPE SURFACE IN YARD. MOVED TO A SEGREGATED AREA. BEING CLEANED UP AS NECESSARY. UNKNOWN IF LEAK HAS BEEN PLUGGED AND/OR IF MATERIAL HAS BEEN TRANSFERRED. |

Material:

| | |
|---|---|
| Site ID: | 254290 |
| Operable Unit ID: | 1051917 |
| Operable Unit: | 01 |
| Material ID: | 331372 |
| Material Code: | 9999 |
| Material Name: | Other - |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000961250 |
| Country: | USA |
| Mailing Name: | american stevedoring inc |
| Mailing Contact: | american stevedoring inc |
| Mailing Address: | 70 hamilton ave |
| Mailing Address 2: | Not reported |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Mailing City: | brooklyn |
| Mailing State: | NY |
| Mailing Zip: | 11231 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-875-0777 |

| | |
|---|---|
| Document ID: | 07 |
| Manifest Status: | 000237932FLE |
| Trans1 State ID: | NYP000961250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | PAD067098822 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | NJR000011528 |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | N |
| Trans1 EPA ID: | N |
| Trans2 EPA ID: | N |
| TSDF ID: | N |
| Waste Code: | N |
| Quantity: | Not reported |
| Units: | 1 |
| Number of Containers: | DM |
| Container Type: | 200 |
| Handling Method: | P |
| Specific Gravity: | 1 |
| Waste Code: | L |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | 07 |
| Manifest Status: | 000237932FLE |
| Trans1 State ID: | NYP000961250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | PAD067098822 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | NJR000011528 |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | N |
| Trans1 EPA ID: | N |
| Trans2 EPA ID: | N |
| TSDF ID: | N |
| Waste Code: | N |
| Quantity: | Not reported |
| Units: | 1 |
| Number of Containers: | DM |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Container Type: | 10 |
| Handling Method: | G |
| Specific Gravity: | 1 |
| Waste Code: | L |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2007-01-15 |
| Trans1 Recv Date: | 2007-01-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2007-01-23 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 10.0 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2007-01-15 |
| Trans1 Recv Date: | 2007-01-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2007-01-23 |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 200.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 1/15/2007 |
| Trans1 Recv Date: | 1/15/2007 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 1/23/2007 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 200 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 1/15/2007 |
| Trans1 Recv Date: | 1/15/2007 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 1/23/2007 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 10 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-11-15 |
| Trans1 Recv Date: | 2012-11-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2012-11-15 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000195941 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MDD980555189 |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Waste Code: | Not reported |
| Quantity: | 3000.0 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 005668903FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H129 |

| | |
|---|---|
| EPA ID: | NYR000195941 |
| Country: | USA |
| Mailing Name: | RED HOOK CONTAINER TERMINAL |
| Mailing Contact: | MICHAEL STAMATIS |
| Mailing Address: | 70 HAMILTON AVE |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11231 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 908-590-0341 |

| | |
|---|---|
| Document ID: | 07 |
| Manifest Status: | 000237932FLE |
| Trans1 State ID: | NYP000961250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | PAD067098822 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | NJR000011528 |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | N |
| Trans1 EPA ID: | N |
| Trans2 EPA ID: | N |
| TSDF ID: | N |
| Waste Code: | N |
| Quantity: | Not reported |
| Units: | 1 |
| Number of Containers: | DM |
| Container Type: | 200 |
| Handling Method: | P |
| Specific Gravity: | 1 |
| Waste Code: | L |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | 07 |
| Manifest Status: | 000237932FLE |
| Trans1 State ID: | NYP000961250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | PAD067098822 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | NJR000011528 |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | N |
| Trans1 EPA ID: | N |
| Trans2 EPA ID: | N |
| TSDF ID: | N |
| Waste Code: | N |
| Quantity: | Not reported |
| Units: | 1 |
| Number of Containers: | DM |
| Container Type: | 10 |
| Handling Method: | G |
| Specific Gravity: | 1 |
| Waste Code: | L |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2007-01-15 |
| Trans1 Recv Date: | 2007-01-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2007-01-23 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 10.0 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2007-01-15 |
| Trans1 Recv Date: | 2007-01-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2007-01-23 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 200.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 1/15/2007 |
| Trans1 Recv Date: | 1/15/2007 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 1/23/2007 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 200 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR000011528 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 1/15/2007 |
| Trans1 Recv Date: | 1/15/2007 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 1/23/2007 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000961250 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD067098822 |
| Waste Code: | Not reported |
| Quantity: | 10 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1 |
| Year: | 2007 |
| Manifest Tracking Num: | 000237932FLE |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-11-15 |
| Trans1 Recv Date: | 2012-11-15 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2012-11-15 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000195941 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MDD980555189 |
| Waste Code: | Not reported |
| Quantity: | 3000.0 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 005668903FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H129 |

SPILLS:

| | |
|---|---|
| Facility ID: | 9405338 |
| Facility Type: | ER |
| DER Facility ID: | 208281 |
| Site ID: | 254289 |
| DEC Region: | 2 |
| Spill Date: | 7/19/1994 |
| Spill Number/Closed Date: | 9405338 / 7/19/1994 |
| Spill Cause: | Equipment Failure |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 7/19/1914 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | 7/19/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/14/1994 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | AMERICAN MARITIME |
| Spiller Address: | 70 HAMILTON AVENUE |
| Spiller City,St,Zip: | BROOKLYN, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | OPENING BOX BROKEN- SPILLE CONTAINED ON PAVED DRIVEWAY-CLEAN UP IS DONE. |

Material:

| | |
|---|---|
| Site ID: | 254289 |
| Operable Unit ID: | 999493 |
| Operable Unit: | 01 |
| Material ID: | 381929 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 3 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0202470 |
| Facility Type: | ER |
| DER Facility ID: | 208281 |
| Site ID: | 207699 |
| DEC Region: | 2 |
| Spill Date: | 6/7/2002 |
| Spill Number/Closed Date: | 0202470 / 6/7/2002 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

Willing Responsible Party. Corrective action taken.

| | |
|---|---|
| SWIS: | 2401 |
| Investigator: | JBVOUGHT |
| Referred To: | Not reported |
| Reported to Dept: | 6/7/2002 |
| CID: | 396 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/7/2002 |
| Spill Record Last Update: | 6/10/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | AMERICAN STEVEDORING INC |
| Spiller Address: | 70 HAMILTON AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | CARMELLA |
| Contact Phone: | (718) 628-3351 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"6/7/02 TJDFuel ank from crane was removed and Petro Fuel Oil attempted delivery. Spill of approximately 30 gallons onto asphalt. Spill cleaned by American Stevedoring Inc. pesonnel using absorbents. |
| Remarks: | petro went to fill tank on a crane and were never advised that the tank was removed until after they began filling. mill roe being contacted for clean up. |

Material:

| | |
|---|---|
| Site ID: | 207699 |
| Operable Unit ID: | 853308 |
| Operable Unit: | 01 |
| Material ID: | 520322 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 34 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0700624 |
| Facility Type: | ER |
| DER Facility ID: | 208281 |
| Site ID: | 379990 |
| DEC Region: | 2 |
| Spill Date: | 4/17/2007 |
| Spill Number/Closed Date: | 0700624 / 4/18/2007 |

**AMERICAN STEVEDORING INC (Continued)** **S108650243**

| | |
|---|---|
| Spill Cause: | Other |
| Spill Class: | Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | rmpiper |
| Referred To: | Not reported |
| Reported to Dept: | 4/17/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/17/2007 |
| Spill Record Last Update: | 4/18/2007 |
| Spiller Name: | CLINT |
| Spiller Company: | AMERICAN STEVEDORING |
| Spiller Address: | 70 HAMILTON AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | CLINT |
| Contact Phone: | (914) 447-1709 |
| DEC Memo: | dec pIPER REPSONDED TO SITE. A 6500 gal liq vessel containing Pyridine was punctured during offloading. A few gallons initially spilled though a vacuum lock contained the spill thereafter. The vessel was moved to a vacant area prior to FDNY on scene. FDNY OEM, Hazmat, Port Auth, Customs were all on scene. A perimeter was set up by FDNY Hazmat and a contain,mment pool was put under drip. No vapors were detected by PID, FID, possibly due to high wind. Leak is approx. 1/2 gallon / hour. Contractor will pump off contents to a different vessel and transport offsite. Hazmat will contact DEC if additional spill occurs. Piper to follow up regarding total amount spilled.4/18/07- DEC Piper spke w/ Pat Garrison of HNHttc. Transfer went as planned. Residual spillage was cleaned. Closed. |
| Remarks: | CASno: PYRIDINE- 4000 GALLON CONTAINER AND IS LEAKING ON BOTTOM: CAME OFF A VESSEL AND HAZMAT AND FIRE CO ENROUTE AND CLEAN UP COMPANY ALSO |

Material:

| | |
|---|---|
| Site ID: | 379990 |
| Operable Unit ID: | 1137485 |
| Operable Unit: | 01 |
| Material ID: | 2127439 |
| Material Code: | 0063A |
| Material Name: | UNKNOWN HAZARDOUS MATERIAL |
| Case No.: | Not reported |
| Material FA: | Hazardous Material |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**V165**
**SSW**
**< 1/8**
**0.055 mi.**
**291 ft.**

**NYMT - BP ASI CONTAINER**
**90 COLUMBIA STREET**
**BROOKLYN, NY 11201**

**Site 9 of 19 in cluster V**

**RCRA-LQG** **1014926877**
**NYR000186650**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

RCRA-LQG:

| | |
|---|---|
| Date form received by agency: | 03/02/2012 |
| Facility name: | NYMT - BP ASI CONTAINER |
| Facility address: | 90 COLUMBIA STREET<br>BROOKLYN, NY 11201 |
| EPA ID: | NYR000186650 |
| Mailing address: | COLUMBIA STREET<br>BROOKLYN, NY 11201 |
| Contact: | TIMOTHY GARD |
| Contact address: | COLUMBIA STREET<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | (718) 330-2975 |
| Contact email: | TGARD@PANYNJ.GOV |
| EPA Region: | 02 |
| Classification: | Large Quantity Generator |
| Description: | Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | RED HOOK CONTAINER TERMINAL LLC |
| Owner/operator address: | Not reported<br>Not reported |
| Owner/operator country: | US |
| Owner/operator telephone: | Not reported |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | 09/29/2011 |
| Owner/Op end date: | Not reported |
| | |
| Owner/operator name: | PORT AUTHORITY OF NY AND NJ |
| Owner/operator address: | COLUMBIA STREET<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 855-3618 |
| Legal status: | Municipal |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | 01/01/1956 |
| Owner/Op end date: | Not reported |
| | |
| Owner/operator name: | RED HOOK CONTAINER LLC |
| Owner/operator address: | Not reported<br>Not reported |

**NYMT - BP ASI CONTAINER (Continued)** **1014926877**

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 10/01/2011
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: COLUMBIA ST
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 330-2976
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 03/01/1956
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/03/2012
Facility name: NYMT - BP ASI CONTAINER
Site name: ASI SITE MATERIALS
Classification: Not a generator, verified

Date form received by agency: 11/16/2011
Facility name: NYMT - BP ASI CONTAINER
Site name: ASI SITE MATERIALS
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

**NYMT - BP ASI CONTAINER (Continued)** **1014926877**

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D010
Waste name: SELENIUM

Waste code: D011
Waste name: SILVER

Waste code: D012
Waste name: ENDRIN

Waste code: D018
Waste name: BENZENE

Waste code: D038
Waste name: PYRIDINE

Waste code: D039
Waste name: TETRACHLOROETHYLENE

Waste code: U196
Waste name: PYRIDINE

Waste code: U196
Waste name: PYRIDINE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 1834.8

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

**NYMT - BP ASI CONTAINER (Continued)** **1014926877**

Amount (Lbs): 1834.8

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 458.7

Waste code: D010
Waste name: SELENIUM
Amount (Lbs): 6421.8

Waste code: D011
Waste name: SILVER
Amount (Lbs): 917.4

Waste code: D012
Waste name: ENDRIN
Amount (Lbs): 458.7

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 2293.5

Waste code: D038
Waste name: PYRIDINE
Amount (Lbs): 1875.7

Waste code: D039
Waste name: TETRACHLOROETHYLENE
Amount (Lbs): 917.4

Violation Status: No violations found

---

**V166** **RED HOOK CONTAINER TERMINAL** **RCRA NonGen / NLR** **1015746535**
**SSW** **70 HAMILTON AVE** **NYP000195941**
**< 1/8** **BROOKLYN, NY 11231**
**0.055 mi.**
**291 ft.** **Site 10 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/08/2013
Facility name: RED HOOK CONTAINER TERMINAL
Facility address: 70 HAMILTON AVE
BROOKLYN, NY 112311305
EPA ID: NYP000195941
Mailing address: MARSH ST
NEWARK, NJ 00714
Contact: ERIC SEAL
Contact address: MARSH ST
NEWARK, NJ 00714
Contact country: US
Contact telephone: (973) 418-0525
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

**RED HOOK CONTAINER TERMINAL (Continued)** **1015746535**

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Historical Generators:

| | |
|---|---|
| Date form received by agency: | 11/13/2012 |
| Facility name: | RED HOOK CONTAINER TERMINAL |
| Classification: | Conditionally Exempt Small Quantity Generator |

Violation Status: No violations found

---

**V167** **AMERICAN STEVEDORING INC - RED HOOK MARI** **US AIRS** **1014813944**
**SSW** **70 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.055 mi.**
**291 ft.** **Site 11 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110040834005 |
| Plant name: | AMERICAN STEVEDORING INC - RED HOOK MARI |
| Plant address: | 70 HAMILTON AVE<br>BROOKLYN, NY 11231 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 5541 |
| Sic code desc: | GASOLINE SERVICE STATIONS |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | SIP SOURCE |

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

**AMERICAN STEVEDORING INC - RED HOOK MARI (Continued)** **1014813944**

Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

**V168**
**SSW**
**< 1/8**
**0.055 mi.**
**291 ft.**

**70 HAMILTON AVE**
**BROOKLYN, NY**

**Site 12 of 19 in cluster V**

**ERNS** **2013042436**
**N/A**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

**V169**
**SSW**
**< 1/8**
**0.055 mi.**
**291 ft.**

**RED HOOK CONTAINER TERMINAL**
**70 HAMILTON AVE**
**BROOKLYN, NY 11231**

**Site 13 of 19 in cluster V**

**RCRA-CESQG** **1014958344**
**NYR000195941**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 08/07/2012 |
| Facility name: | RED HOOK CONTAINER TERMINAL |
| Facility address: | 70 HAMILTON AVE<br>BROOKLYN, NY 11231 |
| EPA ID: | NYR000195941 |
| Mailing address: | MARSH ST<br>PORT NEWARK, NJ 07114 |
| Contact: | FRANK JORDAN |
| Contact address: | MARSH ST<br>PORT NEWARK, NJ 07114 |
| Contact country: | US |
| Contact telephone: | (973) 522-0999 |
| Contact email: | FJORDAN@REDHOOKTERMINAL.COM |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | PORT AUTHORITY OF NY AND NJ |
| Owner/operator address: | COLUMBIA ST<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 330-2972 |
| Legal status: | State |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | 01/01/1950 |
| Owner/Op end date: | Not reported |
| | |
| Owner/operator name: | RED HOOK CONTAINER TERMINAL LLC |
| Owner/operator address: | Not reported<br>Not reported |

**RED HOOK CONTAINER TERMINAL (Continued)** **1014958344**

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/01/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

---

**V170** **RED HOOK CONTAINER** **NY Spills** **S113406082**
**SSW** **70 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.055 mi.**
**291 ft.** **Site 14 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

SPILLS:
Facility ID: 1216835
Facility Type: ER
DER Facility ID: 435532
Site ID: 480241
DEC Region: 2
Spill Date: 3/29/2013
Spill Number/Closed Date: 1216835 / 4/1/2013
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 3/29/2013
CID: Not reported
Water Affected: Not reported

**RED HOOK CONTAINER (Continued)** **S113406082**

| | |
|---|---|
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/29/2013 |
| Spill Record Last Update: | 4/1/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | HOP ENERGY |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | MIKE STANTON |
| Contact Phone: | Not reported |
| DEC Memo: | 03/29/13-Hiralkumar Patel.1:00 PM:- spoke with Mike Stanton at HOP Energy. he mentioned that oil spilled as UST overfilled. oil came out of vent pipe. its diesel UST at shipping yard. Mr. Stanton asked to contact Mr. Cafiero for more information.Michael CafieroHOP EnergyPh. (917) 749-96041:02 PM:- left message for Mr. Cafiero.1:35 PM:- spoke with Mr. Cafiero. he visited site. about 5-6 gal oil spilled from vent pipe onto concrete floor where rain water was accumulated. he mentioned that the two 4,000 gal diesel tanks being used for on-site machinery. he confirmed that oily water was contained on concrete surface and no soil/sewer was impacted. cleanup crew enroute.alternate address: 20 Imlay St04/01/13-Hiralkumar Patel.11:10 AM:- visited site. its Red Hook Container Terminals located at intersection of Van Brunt St and Summit St. inspected spill area in front of mechanic shop. oil spilled from vent pipe onto concrete surface. cleanup completed. no soil or drain in spill area.case closed. |
| Remarks: | contained to paved area/clean up crew enroute |

Material:

| | |
|---|---|
| Site ID: | 480241 |
| Operable Unit ID: | 1230032 |
| Operable Unit: | 01 |
| Material ID: | 2227859 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**V171**
**SSW**
**< 1/8**
**0.055 mi.**
**291 ft.**

**RED HOOK CONTAINER TERMINAL**
**70 HAMILTON AVENUE**
**BROOKLYN, NY**

**Site 15 of 19 in cluster V**

**FINDS** **1016125924**
**N/A**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

FINDS:

Registry ID: 110042174349

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

---

**W172**
**SSW**
**< 1/8**
**0.056 mi.**
**294 ft.**

**25 CARROLL ST**
**25 CARROLL STREET**
**BROOKLYN, NY 11231**

**Site 1 of 6 in cluster W**

**NY AST** **U003393134**
**N/A**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-304174 |
| Program Type: | PBS |
| UTM X: | 584112.54879999999 |
| UTM Y: | 4504075.2580700004 |
| Expiration Date: | N/A |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 13852 |
| Affiliation Type: | Mail Contact |

**25 CARROLL ST (Continued)** **U003393134**

| | |
|---|---|
| Company Name: | 25 CARROLL ST LLC |
| Contact Type: | Not reported |
| Contact Name: | ALEX BARRETT |
| Address1: | 459 HENRY ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 360-4801 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | CGFREEDM |
| Date Last Modified: | 5/3/2010 |

| | |
|---|---|
| Site Id: | 13852 |
| Affiliation Type: | On-Site Operator |
| Company Name: | MARATHON HOSIERY CO.,INC. |
| Contact Type: | Not reported |
| Contact Name: | MARATHON HOSIERY CO |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-2926 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 13852 |
| Affiliation Type: | Emergency Contact |
| Company Name: | MARATHON HOSIERY CO.,INC. |
| Contact Type: | Not reported |
| Contact Name: | JACK WERTENTEIL |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 868-3080 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 13852 |
| Affiliation Type: | Facility Owner |
| Company Name: | 25 CARROLL LLC |
| Contact Type: | LICENSED OIL EQUIPMENT INSTALLER |
| Contact Name: | MICHAEL S. KAPLAN |
| Address1: | 459 HENRY ST |
| Address2: | Not reported |
| City: | BROOKLYN |

**25 CARROLL ST (Continued)** **U003393134**

| | |
|---|---|
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 360-4801 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | CGFREEDM |
| Date Last Modified: | 5/3/2010 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 26078 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/01/1973 |
| Capacity Gallons: | 2500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 05/10/2010 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 05/11/2010 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

---

**X173** **LOT 16,TAXBLOCK 299** **NY RES DECL** **S109155496**
**ENE** **86 CONGRESS STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.056 mi.**
**296 ft.** **Site 1 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-139 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532868 |
| Borough Code: | BK |
| Tax Block: | 299 |
| Tax Lot: | 16 |
| Community District: | 306 |
| Census Tract: | 47 |

**LOT 16,TAXBLOCK 299 (Continued)** **S109155496**

| | |
|---|---|
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | HAMBERGER CRANDCHILDR |
| Lot Area: | 000004517 |
| Total Building Floor Area: | 00000004500 |
| Floor Area, Commercial: | 00000004500 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000004500 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0050.00 |
| Building, Depth: | 0090.33 |
| Building Front: | 0050.00 |
| Building Depth: | 0090.33 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000035865 |
| Assessed Value, Total: | 00000053100 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered 1: | 0000 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |

**LOT 16,TAXBLOCK 299 (Continued)** **S109155496**

| | |
|---|---|
| Borough, Tax Block & Lot: | 3002990016 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984348 |
| Y Coordinate: | 0190366 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 16 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | HAMBERGER CRANDCHILDR |
| Lot Area: | 000004517 |
| Total Building Floor Area: | 00000004500 |
| Commercial Floor Area: | 00000004500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |

**LOT 16,TAXBLOCK 299 (Continued)** **S109155496**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000004500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0090.33 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0090.33 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000035865 |
| Total Assessed Value: | 00000053100 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990016 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984348 |
| Y Coordinate: | 0190366 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**S174** **EDR US Hist Auto Stat** **1015118534**
**South** **100 SACKETT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.056 mi.**
**298 ft.** **Site 2 of 2 in cluster S**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | CHANGS AUTO REPAIR |
| Year: | 2007 |
| Address: | 100 SACKETT ST |
| Name: | CHANGS AUTO REPAIR |
| Year: | 2010 |
| Address: | 100 SACKETT ST |

---

**X175** **LOT 43,TAXBLOCK 299** **NY E DESIGNATION** **S109155502**
**East** **69 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.058 mi.**
**307 ft.** **Site 2 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 43 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Air Quality - #2 Fuel Oil or Natural Gas Heat and Hot Water |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | O9 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SIXTY-NINE WARREN |
| Lot Area: | 000004500 |
| Total Building Floor Area: | 00000009000 |
| Commercial Floor Area: | 00000009000 |
| Office Floor Area: | 00000009000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0090.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000065250 |
| Total Assessed Value: | 00000310950 |
| Land Exempt Value: | 00000001880 |
| Total Exempt Value: | 00000235250 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1990 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990043 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984200 |
| Y Coordinate: | 0190321 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 43 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | O9 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SIXTY-NINE WARREN |
| Lot Area: | 000004500 |
| Total Building Floor Area: | 00000009000 |
| Commercial Floor Area: | 00000009000 |
| Office Floor Area: | 00000009000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0090.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000065250 |
| Total Assessed Value: | 00000310950 |
| Land Exempt Value: | 00000001880 |
| Total Exempt Value: | 00000235250 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1990 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990043 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984200 |
| Y Coordinate: | 0190321 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 43 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | O9 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SIXTY-NINE WARREN |
| Lot Area: | 000004500 |
| Total Building Floor Area: | 00000009000 |
| Commercial Floor Area: | 00000009000 |
| Office Floor Area: | 00000009000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0090.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000065250 |
| Total Assessed Value: | 00000310950 |
| Land Exempt Value: | 00000001880 |
| Total Exempt Value: | 00000235250 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1990 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990043 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984200 |
| Y Coordinate: | 0190321 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 43 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | O9 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | SIXTY-NINE WARREN |
| Lot Area: | 000004500 |
| Total Building Floor Area: | 00000009000 |
| Commercial Floor Area: | 00000009000 |
| Office Floor Area: | 00000009000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00008 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0090.00 |
| Building Frontage: | 0050.00 |
| Building Depth: | 0090.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000065250 |
| Total Assessed Value: | 00000310950 |
| Land Exempt Value: | 00000001880 |
| Total Exempt Value: | 00000235250 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1990 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0002.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990043 |
| Condominium Number: | 00000 |

**LOT 43,TAXBLOCK 299 (Continued)** **S109155502**

| | |
|---|---|
| Census Tract 2: | 0047 |
| X Coordinate: | 0984200 |
| Y Coordinate: | 0190321 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y176** **LOT 1,TAXBLOCK 304** **NY E DESIGNATION** **S108470030**
**ESE** **85 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.059 mi.**
**311 ft.** **Site 1 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 1 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | JOSEPH LARREA |
| Lot Area: | 000002544 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |

**LOT 1,TAXBLOCK 304 (Continued)** **S108470030**

| | |
|---|---|
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0022.67 |
| Lot Depth: | 0099.50 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006306 |
| Total Assessed Value: | 00000031196 |
| Land Exempt Value: | 00000002370 |
| Total Exempt Value: | 00000027260 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 1964 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.21 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040001 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984009 |
| Y Coordinate: | 0190101 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | E-36 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 1 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |

**LOT 1,TAXBLOCK 304 (Continued)** **S108470030**

| | |
|---|---|
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | JOSEPH LARREA |
| Lot Area: | 000002544 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0022.67 |
| Lot Depth: | 0099.50 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006306 |
| Total Assessed Value: | 00000031196 |
| Land Exempt Value: | 00000002370 |
| Total Exempt Value: | 00000027260 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 1964 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |

**LOT 1,TAXBLOCK 304 (Continued)** **S108470030**

| | |
|---|---|
| Built Floor Area Ratio-Far: | 0001.21 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040001 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984009 |
| Y Coordinate: | 0190101 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | E-36 |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y177** **LOT 9,TAXBLOCK 309** **NY E DESIGNATION** **S111073164**
**ESE** **86 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.060 mi.**
**316 ft.** **Site 2 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 9 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |

**LOT 9,TAXBLOCK 309 (Continued)** **S111073164**

| | |
|---|---|
| Owner, Type of Code: | Not reported |
| Owner Name: | CURTIS ERIC |
| Lot Area: | 000002350 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0024.42 |
| Lot Depth: | 0096.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006016 |
| Total Assessed Value: | 00000029865 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025279 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.29 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090009 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983973 |
| Y Coordinate: | 0190016 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 9 |

**LOT 9,TAXBLOCK 309 (Continued)** **S111073164**

| | |
|---|---|
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CURTIS ERIC |
| Lot Area: | 000002350 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0024.42 |
| Lot Depth: | 0096.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006016 |
| Total Assessed Value: | 00000029865 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025279 |
| Year Built: | 1995 |

**LOT 9,TAXBLOCK 309 (Continued)** **S111073164**

| | |
|---|---|
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.29 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090009 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983973 |
| Y Coordinate: | 0190016 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y178** **LOT 10,TAXBLOCK 309** **NY E DESIGNATION** **S111072496**
**ESE** **88 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.061 mi.**
**322 ft.** **Site 3 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 10 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |

**LOT 10,TAXBLOCK 309 (Continued)** **S111072496**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | STEVEN MOLL |
| Lot Area: | 000001975 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0094.50 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000003833 |
| Total Assessed Value: | 00000027561 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025158 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.53 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983976 |
| Y Coordinate: | 0189966 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 10,TAXBLOCK 309 (Continued)** **S111072496**

| | |
|---|---|
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 10 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | STEVEN MOLL |
| Lot Area: | 000001975 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0094.50 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |

**LOT 10,TAXBLOCK 309 (Continued)** **S111072496**

| | |
|---|---|
| Land Assessed Value: | 00000003833 |
| Total Assessed Value: | 00000027561 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025158 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.53 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0983976 |
| Y Coordinate: | 0189966 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**X179** **LOT 3,TAXBLOCK 304** **NY E DESIGNATION** **S111072804**
**East** **88 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.061 mi.**
**324 ft.** **Site 3 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 3 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |

**LOT 3,TAXBLOCK 304 (Continued)** **S111072804**

| | |
|---|---|
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | BELTRE RICARDO |
| Lot Area: | 000002540 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0028.25 |
| Lot Depth: | 0100.50 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000005784 |
| Total Assessed Value: | 00000028611 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000024257 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.22 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040003 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984065 |
| Y Coordinate: | 0190253 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |

**LOT 3,TAXBLOCK 304 (Continued)** **S111072804**

| | |
|---|---|
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 3 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | BELTRE RICARDO |
| Lot Area: | 000002540 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0028.25 |
| Lot Depth: | 0100.50 |
| Building Frontage: | 0021.33 |

**LOT 3,TAXBLOCK 304 (Continued)** **S111072804**

| | |
|---|---|
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000005784 |
| Total Assessed Value: | 00000028611 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000024257 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.22 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040003 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984065 |
| Y Coordinate: | 0190253 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y180** **LOT 25,TAXBLOCK 304** **NY E DESIGNATION** **S111072781**
**ESE** **89 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.061 mi.**
**324 ft.** **Site 4 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 25 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |

**LOT 25,TAXBLOCK 304 (Continued)** **S111072781**

| | |
|---|---|
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MIRANDA LUIS |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040025 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984057 |
| Y Coordinate: | 0190148 |

**LOT 25,TAXBLOCK 304 (Continued)** **S111072781**

| | |
|---|---|
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 25 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MIRANDA LUIS |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |

**LOT 25,TAXBLOCK 304 (Continued)** **S111072781**

| | |
|---|---|
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040025 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984057 |
| Y Coordinate: | 0190148 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**181 SW < 1/8 0.062 mi. 325 ft.**

**ANCHORAGE & BUTTREMILK CH**
**ANCHORAGE & BUTTERMILK CH**
**MANHATTAN, NY**

**NY Spills** **S102143272**
**N/A**

**Relative: Lower**

**Actual: 1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9207079 |
| Facility Type: | ER |
| DER Facility ID: | 59882 |
| Site ID: | 61610 |
| DEC Region: | 2 |
| Spill Date: | 9/18/1992 |
| Spill Number/Closed Date: | 9207079 / 11/23/1994 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. |

**ANCHORAGE & BUTTREMILK CH (Continued)** **S102143272**

Willing Responsible Party. Corrective action taken.

| | |
|---|---|
| SWIS: | 3101 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 9/18/1992 |
| CID: | Not reported |
| Water Affected: | THE NARROWS |
| Spill Source: | Vessel |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 11/23/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/22/1992 |
| Spill Record Last Update: | 11/23/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | NRC #137304 & NYCDEP NOTIFIED USCG TEAM EN ROUTE TO INVESTIGATE. |

Material:

| | |
|---|---|
| Site ID: | 61610 |
| Operable Unit ID: | 974072 |
| Operable Unit: | 01 |
| Material ID: | 407748 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**X182** **HUMBUG ON HAMBERGER** **NY Spills** **S102141893**
**East** **75 WARREN ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.062 mi.**
**329 ft.** **Site 4 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8901238 |
| Facility Type: | ER |
| DER Facility ID: | 106258 |
| Site ID: | 122570 |
| DEC Region: | 2 |
| Spill Date: | 5/8/1989 |

**HUMBUG ON HAMBERGER (Continued)** **S102141893**

| | |
|---|---|
| Spill Number/Closed Date: | 8901238 / 11/6/2001 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TOMASELLO |
| Referred To: | Not reported |
| Reported to Dept: | 5/8/1989 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | 11/6/2001 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/8/1989 |
| Spill Record Last Update: | 6/18/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | DAVID HAMBERGER MFG |
| Spiller Address: | 410 HICKS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | WASTE DUMPED IN DITCH, ALLEGEDLY BY SPILLER. DUMP SITE ACROSS STREET FROM ADDRESS. DEP ON SCENE - REQUESTED ASSISTANCE FOR LAW ENFORCEMENT BY DEC. CASE REFERRED TO ECO LOPEZ. |

Material:

| | |
|---|---|
| Site ID: | 122570 |
| Operable Unit ID: | 928232 |
| Operable Unit: | 01 |
| Material ID: | 448992 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**Q183** **LOT 53,TAXBLOCK 352** **NY E DESIGNATION** **S113496605**
**SSW** **45 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.062 mi.**
**330 ft.** **Site 4 of 5 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 53 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F1 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | LLJ REALTY CORP. |
| Lot Area: | 000015000 |
| Total Building Floor Area: | 00000007500 |
| Commercial Floor Area: | 00000007500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000007500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0150.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0068.00 |
| Building Depth: | 0094.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |

**LOT 53,TAXBLOCK 352 (Continued)** **S113496605**

| | |
|---|---|
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000094500 |
| Total Assessed Value: | 00000157050 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1979 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.50 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520053 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982881 |
| Y Coordinate: | 0188064 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 53 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |

**LOT 53,TAXBLOCK 352 (Continued)** **S113496605**

| | |
|---|---|
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F1 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | LLJ REALTY CORP. |
| Lot Area: | 000015000 |
| Total Building Floor Area: | 00000007500 |
| Commercial Floor Area: | 00000007500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000007500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0150.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0068.00 |
| Building Depth: | 0094.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000094500 |
| Total Assessed Value: | 00000157050 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1979 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.50 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520053 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982881 |
| Y Coordinate: | 0188064 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |

**LOT 53,TAXBLOCK 352 (Continued)** **S113496605**

| | |
|---|---|
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 53 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F1 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | LLJ REALTY CORP. |
| Lot Area: | 000015000 |
| Total Building Floor Area: | 00000007500 |
| Commercial Floor Area: | 00000007500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000007500 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00002 |
| Lot Frontage: | 0150.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0068.00 |
| Building Depth: | 0094.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 53,TAXBLOCK 352 (Continued)** **S113496605**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000094500 |
| Total Assessed Value: | 00000157050 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1979 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.50 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520053 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982881 |
| Y Coordinate: | 0188064 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y184** **LOT 24,TAXBLOCK 304** **NY E DESIGNATION** **S111072777**
**ESE** **91 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.062 mi.**
**330 ft.** **Site 5 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 24 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 24,TAXBLOCK 304 (Continued)** **S111072777**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | LAILA RITA CHEUNG |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025071 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040024 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984051 |
| Y Coordinate: | 0190083 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |

**LOT 24,TAXBLOCK 304 (Continued)** **S111072777**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 24 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | LAILA RITA CHEUNG |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |

**LOT 24,TAXBLOCK 304 (Continued)** **S111072777**

| | |
|---|---|
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025071 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040024 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984051 |
| Y Coordinate: | 0190083 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y185** **LOT 11,TAXBLOCK 309** **NY E DESIGNATION** **S111072540**
**ESE** **92 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.063 mi.**
**334 ft.** **Site 6 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 11 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |

**LOT 11,TAXBLOCK 309 (Continued)** **S111072540**

| | |
|---|---|
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARILYN MICHEL |
| Lot Area: | 000001940 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0093.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000003775 |
| Total Assessed Value: | 00000027541 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025196 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.56 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984015 |

**LOT 11,TAXBLOCK 309 (Continued)** **S111072540**

| | |
|---|---|
| Y Coordinate: | 0189999 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 11 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARILYN MICHEL |
| Lot Area: | 000001940 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |

**LOT 11,TAXBLOCK 309 (Continued)** **S111072540**

| | |
|---|---|
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0093.00 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000003775 |
| Total Assessed Value: | 00000027541 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025196 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.56 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090011 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984015 |
| Y Coordinate: | 0189999 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y186** **LOT 23,TAXBLOCK 304** **NY E DESIGNATION** **S111072769**
**ESE** **93 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.064 mi.**
**337 ft.** **Site 7 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 23 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |

**LOT 23,TAXBLOCK 304 (Continued)** **S111072769**

| | |
|---|---|
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | PLUTARCO JIMENEZ |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025071 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |

**LOT 23,TAXBLOCK 304 (Continued)** **S111072769**

| | |
|---|---|
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040023 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984095 |
| Y Coordinate: | 0190130 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 23 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | PLUTARCO JIMENEZ |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |

**LOT 23,TAXBLOCK 304 (Continued)** **S111072769**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025071 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040023 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984095 |
| Y Coordinate: | 0190130 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**X187** **LOT 4,TAXBLOCK 304** **NY E DESIGNATION** **S111072874**
**East** **92 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.064 mi.**
**337 ft.** **Site 5 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 4 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | RAYMOND RIVERA |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 4,TAXBLOCK 304 (Continued)** **S111072874**

| | |
|---|---|
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004454 |
| Total Assessed Value: | 00000030416 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000027392 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040004 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984067 |
| Y Coordinate: | 0190189 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 4 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |

**LOT 4,TAXBLOCK 304 (Continued)** **S111072874**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | RAYMOND RIVERA |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004454 |
| Total Assessed Value: | 00000030416 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000027392 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040004 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984067 |
| Y Coordinate: | 0190189 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 4,TAXBLOCK 304 (Continued)** **S111072874**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**X188** **LOT 18,TAXBLOCK 299** **NY RES DECL** **S109155499**
**ENE** **90 CONGRESS STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.064 mi.**
**337 ft.** **Site 6 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-139 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532868 |
| Borough Code: | BK |
| Tax Block: | 299 |
| Tax Lot: | 18 |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | DISPLAY INC |
| Lot Area: | 000002356 |
| Total Building Floor Area: | 00000002375 |
| Floor Area, Commercial: | 00000002375 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000002375 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0025.00 |
| Building, Depth: | 0095.00 |
| Building Front: | 0025.00 |

**LOT 18,TAXBLOCK 299 (Continued)** **S109155499**

| | |
|---|---|
| Building Depth: | 0095.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000021195 |
| Assessed Value, Total: | 00000035595 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered 1: | 1987 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.01 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3002990018 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984395 |
| Y Coordinate: | 0190375 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 18 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |

**LOT 18,TAXBLOCK 299 (Continued)** **S109155499**

| | |
|---|---|
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | DISPLAY INC |
| Lot Area: | 000002356 |
| Total Building Floor Area: | 00000002375 |
| Commercial Floor Area: | 00000002375 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000002375 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0025.00 |
| Lot Depth: | 0095.00 |
| Building Frontage: | 0025.00 |
| Building Depth: | 0095.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000021195 |
| Total Assessed Value: | 00000035595 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1987 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.01 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990018 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984395 |
| Y Coordinate: | 0190375 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |

**LOT 18,TAXBLOCK 299 (Continued)** **S109155499**

| | |
|---|---|
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y189** **LOT 12,TAXBLOCK 309** **NY E DESIGNATION** **S111072578**
**ESE** **94 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.065 mi.**
**342 ft.** **Site 8 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 12 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CEPEDA, DIANE |
| Lot Area: | 000002656 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |

**LOT 12,TAXBLOCK 309 (Continued)** **S111072578**

| | |
|---|---|
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.00 |
| Lot Depth: | 0091.58 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006474 |
| Total Assessed Value: | 00000030473 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025429 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.14 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090012 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984024 |
| Y Coordinate: | 0189955 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 12 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1008 |
| School District: | 15 |
| City Council District: | 39 |

**LOT 12,TAXBLOCK 309 (Continued)** **S111072578**

| | |
|---|---|
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CEPEDA, DIANE |
| Lot Area: | 000002656 |
| Total Building Floor Area: | 00000003024 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0029.00 |
| Lot Depth: | 0091.58 |
| Building Frontage: | 0021.00 |
| Building Depth: | 0048.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006474 |
| Total Assessed Value: | 00000030473 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025429 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.14 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003090012 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984024 |
| Y Coordinate: | 0189955 |

**LOT 12,TAXBLOCK 309 (Continued)** **S111072578**

| | |
|---|---|
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Z190** **EAST RIVER / BROOKLYN** **NY Spills** **S102144267**
**North** **EAST RIVER** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.065 mi.**
**342 ft.** **Site 1 of 2 in cluster Z**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8602044 |
| Facility Type: | ER |
| DER Facility ID: | 225395 |
| Site ID: | 277296 |
| DEC Region: | 2 |
| Spill Date: | 6/17/1986 |
| Spill Number/Closed Date: | 8602044 / 6/25/1986 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 6/25/1986 |
| CID: | Not reported |
| Water Affected: | EAST RIVER |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | 6/25/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/24/1987 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | NEWTOWN CREEK W.W.T.PLT. |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | BLOCKAGE AT REGULATOR |

Material:

**EAST RIVER / BROOKLYN (Continued)** **S102144267**

| | |
|---|---|
| Site ID: | 277296 |
| Operable Unit ID: | 899489 |
| Operable Unit: | 01 |
| Material ID: | 478504 |
| Material Code: | 0062A |
| Material Name: | RAW SEWAGE |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**Z191** **EAST RIVER** **NY Spills** **S102148763**
**North** **EAST RIVER- & GREEN ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.065 mi.**
**342 ft.** **Site 2 of 2 in cluster Z**

**Relative:**
**Lower**

**Actual:**
**1 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9408331 |
| Facility Type: | ER |
| DER Facility ID: | 95833 |
| Site ID: | 109061 |
| DEC Region: | 2 |
| Spill Date: | 9/22/1994 |
| Spill Number/Closed Date: | 9408331 / 9/22/1994 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 9/22/1994 |
| CID: | Not reported |
| Water Affected: | EAST RIVER |
| Spill Source: | Unknown |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 9/22/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/31/1994 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | BARBARA MC ALLISTER |
| Spiller Address: | TUG BOAT |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |

**EAST RIVER (Continued)** **S102148763**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"10/10/95: This is additional information about material spilled from the translation of the old spill file: OXYGEN CYLINDERS.

Remarks: (2) 02 TANKS FLOATING-U.S.C.G. RESPONDING. BY NEWTOWN CREEK, U.S.C.G. RECEIVED REPORT FROM THE BARGE AND HAS SENT INVESTIGATORY TEAM. NO OIL OR CHEM SPILL & FOUND AN OLD RUSTY CYLINDER

Material:

| | |
|---|---|
| Site ID: | 109061 |
| Operable Unit ID: | 1002455 |
| Operable Unit: | 01 |
| Material ID: | 377773 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**X192** **LOT 5,TAXBLOCK 304** **NY E DESIGNATION** **S111072930**
**East** **94 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.065 mi.**
**343 ft.** **Site 7 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 5 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |

**LOT 5,TAXBLOCK 304 (Continued)** **S111072930**

| | |
|---|---|
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARY CAMPO-LEWIS |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040005 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984112 |
| Y Coordinate: | 0190234 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |

**LOT 5,TAXBLOCK 304 (Continued)** **S111072930**

| | |
|---|---|
| Pluto-Base Map Indicator: | 1 |
| Tax Lot(s): | 5 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | MARY CAMPO-LEWIS |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |

**LOT 5,TAXBLOCK 304 (Continued)** **S111072930**

| | |
|---|---|
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040005 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984112 |
| Y Coordinate: | 0190234 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y193** **LOT 22,TAXBLOCK 304** **NY E DESIGNATION** **S111072762**
**ESE** **95 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.065 mi.**
**343 ft.** **Site 9 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 22 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |

**LOT 22,TAXBLOCK 304 (Continued)** **S111072762**

| | |
|---|---|
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GORDON, PETER |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040022 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984089 |
| Y Coordinate: | 0190064 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |

**LOT 22,TAXBLOCK 304 (Continued)** **S111072762**

| | |
|---|---|
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 22 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GORDON, PETER |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |

**LOT 22,TAXBLOCK 304 (Continued)** **S111072762**

| | |
|---|---|
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040022 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984089 |
| Y Coordinate: | 0190064 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**X194** **LOT 39,TAXBLOCK 299** **NY RES DECL** **S109155501**
**East** **79 WARREN STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.065 mi.**
**344 ft.** **Site 8 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-139 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532868 |
| Borough Code: | BK |
| Tax Block: | 299 |
| Tax Lot: | 39 |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |

**LOT 39,TAXBLOCK 299 (Continued)** **S109155501**

| | |
|---|---|
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | DISPLAY CITY INC |
| Lot Area: | 000002496 |
| Total Building Floor Area: | 00000002475 |
| Floor Area, Commercial: | 00000002475 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000002475 |
| Floor Area, Factory: | 00000000000 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0025.00 |
| Building, Depth: | 0099.83 |
| Building Front: | 0025.00 |
| Building Depth: | 0099.83 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000022455 |
| Assessed Value, Total: | 00000035730 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered 1: | 0000 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3002990039 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984306 |
| Y Coordinate: | 0190280 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |

**LOT 39,TAXBLOCK 299 (Continued)** **S109155501**

| | |
|---|---|
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 39 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | DISPLAY CITY INC |
| Lot Area: | 000002496 |
| Total Building Floor Area: | 00000002475 |
| Commercial Floor Area: | 00000002475 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000002475 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |

**LOT 39,TAXBLOCK 299 (Continued)** **S109155501**

| | |
|---|---|
| Lot Frontage: | 0025.00 |
| Lot Depth: | 0099.83 |
| Building Frontage: | 0025.00 |
| Building Depth: | 0099.83 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000035730 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990039 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984306 |
| Y Coordinate: | 0190280 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y195** **96-98 BALTIC ST., LLC** **NY AST** **A100292898**
**ESE** **96 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.066 mi.**
**347 ft.** **Site 10 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-609967 |
| Program Type: | PBS |
| UTM X: | 584491.90164000005 |
| UTM Y: | 4504606.7293699998 |
| Expiration Date: | 2016/03/07 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

**96-98 BALTIC ST., LLC (Continued)** **A100292898**

| | |
|---|---|
| Site Id: | 348006 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 96-98 BALTIC ST., LLC |
| Contact Type: | Not reported |
| Contact Name: | ARTURO BELTA |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (917) 440-2670 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 1/3/2007 |

| | |
|---|---|
| Site Id: | 348006 |
| Affiliation Type: | Emergency Contact |
| Company Name: | 96 BALTIC PIERS LLC |
| Contact Type: | Not reported |
| Contact Name: | ARTURO BELTA |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 440-2670 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 1/3/2007 |

| | |
|---|---|
| Site Id: | 348006 |
| Affiliation Type: | Facility Owner |
| Company Name: | 96 BALTIC PIERS LLC |
| Contact Type: | OWNER |
| Contact Name: | MEIR BOUSKILA |
| Address1: | 166 MONTAGUE STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 875-1552 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 1/4/2007 |

| | |
|---|---|
| Site Id: | 348006 |
| Affiliation Type: | Mail Contact |
| Company Name: | 96 BALTIC PIERS LLC |
| Contact Type: | OWNER |
| Contact Name: | MEIR BOUSKILA |
| Address1: | 166 MONTAGUE STREET |

**96-98 BALTIC ST., LLC (Continued)** **A100292898**

| | |
|---|---|
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 875-1552 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 1/4/2007 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 206943 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

| | |
|---|---|
| | K00 - Spill Prevention - None |
| | A00 - Tank Internal Protection - None |
| | D01 - Pipe Type - Steel/Carbon Steel/Iron |
| | J02 - Dispenser - Suction Dispenser |
| | I04 - Overfill - Product Level Gauge (A/G) |
| | C01 - Pipe Location - Aboveground |
| | E00 - Piping Secondary Containment - None |
| | F01 - Pipe External Protection - Painted/Asphalt Coating |
| | H00 - Tank Leak Detection - None |
| | G00 - Tank Secondary Containment - None |
| | I05 - Overfill - Vent Whistle |
| | B05 - Tank External Protection - Jacketed |
| | L00 - Piping Leak Detection - None |
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/19/1950 |
| Capacity Gallons: | 2000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | KXTANG |
| Last Modified: | 01/03/2007 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

**Y196** **LOT 21,TAXBLOCK 304** **NY E DESIGNATION** **S111072755**
**ESE** **97 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.066 mi.**
**349 ft.** **Site 11 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 21 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | RAYMOND FONSECA |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.41 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 21,TAXBLOCK 304 (Continued)** **S111072755**

| | |
|---|---|
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040021 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984130 |
| Y Coordinate: | 0190114 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 21 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |

**LOT 21,TAXBLOCK 304 (Continued)** **S111072755**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | RAYMOND FONSECA |
| Lot Area: | 000002090 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0099.41 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004063 |
| Total Assessed Value: | 00000027704 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023641 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.48 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040021 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984130 |
| Y Coordinate: | 0190114 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 21,TAXBLOCK 304 (Continued)** **S111072755**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**X197** **LOT 6,TAXBLOCK 304** **NY E DESIGNATION** **S111072973**
**East** **96 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.066 mi.**
**349 ft.** **Site 9 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 6 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CHARLA PURYEAR |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |

**LOT 6,TAXBLOCK 304 (Continued)** **S111072973**

| | |
|---|---|
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040006 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984107 |
| Y Coordinate: | 0190170 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 6 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |

**LOT 6,TAXBLOCK 304 (Continued)** **S111072973**

| | |
|---|---|
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CHARLA PURYEAR |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040006 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984107 |
| Y Coordinate: | 0190170 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |

**LOT 6,TAXBLOCK 304 (Continued)** **S111072973**

| | |
|---|---|
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y198** **LOT 20,TAXBLOCK 304** **NY E DESIGNATION** **S111072712**
**ESE** **99 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.067 mi.**
**356 ft.** **Site 12 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 20 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | YING AI YANG |
| Lot Area: | 000003110 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |

**LOT 20,TAXBLOCK 304 (Continued)** **S111072712**

| | |
|---|---|
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0034.25 |
| Lot Depth: | 0099.58 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006818 |
| Total Assessed Value: | 00000029792 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000024404 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984133 |
| Y Coordinate: | 0190048 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 20 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |

**LOT 20,TAXBLOCK 304 (Continued)** **S111072712**

| | |
|---|---|
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | YING AI YANG |
| Lot Area: | 000003110 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0034.25 |
| Lot Depth: | 0099.58 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000006818 |
| Total Assessed Value: | 00000029792 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000024404 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040020 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984133 |
| Y Coordinate: | 0190048 |

**LOT 20,TAXBLOCK 304 (Continued)** **S111072712**

| | |
|---|---|
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**X199** **LOT 7,TAXBLOCK 304** **NY E DESIGNATION** **S111072998**
**East** **98 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.067 mi.**
**356 ft.** **Site 10 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 7 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VICTOR TORRES |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |

**LOT 7,TAXBLOCK 304 (Continued)** **S111072998**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040007 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984150 |
| Y Coordinate: | 0190215 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 7 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |

**LOT 7,TAXBLOCK 304 (Continued)** **S111072998**

| | |
|---|---|
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VICTOR TORRES |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000025102 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |

**LOT 7,TAXBLOCK 304 (Continued)** **S111072998**

| | |
|---|---|
| Borough Tax Block And Lot: | 3003040007 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984150 |
| Y Coordinate: | 0190215 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**X200** **LOT 8,TAXBLOCK 304** **NY E DESIGNATION** **S111073148**
**East** **100 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.069 mi.**
**362 ft.** **Site 11 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 8 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | BARRANCA GASPER |
| Lot Area: | 000002105 |

**LOT 8,TAXBLOCK 304 (Continued)** **S111073148**

| | |
|---|---|
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023672 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040008 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984143 |
| Y Coordinate: | 0190157 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 8 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |

**LOT 8,TAXBLOCK 304 (Continued)** **S111073148**

| | |
|---|---|
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | BARRANCA GASPER |
| Lot Area: | 000002105 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0021.00 |
| Lot Depth: | 0100.25 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000004062 |
| Total Assessed Value: | 00000027734 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000023672 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |

**LOT 8,TAXBLOCK 304 (Continued)** **S111073148**

| | |
|---|---|
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.47 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040008 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984143 |
| Y Coordinate: | 0190157 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**U201** **LAB DELIVERY SERVICE INC** **NY UST** **U003074494**
**SSW** **3644 SEABRING STREET** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11231** **NY AST**
**0.070 mi.** **NY HIST AST**
**368 ft.** **Site 3 of 7 in cluster U**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-315923 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 593009.15685999999 |
| UTM Y: | 4497859.1483500004 |
| Site Type: | Trucking/Transportation/Fleet Operation |

Affiliation Records:

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Facility Owner |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 3644 SEABRING ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Mail Contact |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | CHARLES SKINNER |
| Address1: | 3644 SEABRING ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | On-Site Operator |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | LAB DELIVERY SERVICE INC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Emergency Contact |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | RONALD S C OTTLEY |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 978-7454 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 12915 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Capacity Gallons: | 4000 |
| Install Date: | 06/01/1981 |
| Date Tank Closed: | 02/01/1994 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | ZZ |
| Date Test: | 03/01/1991 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 12916 |
| Tank Status: | Closed Prior to Micro Conversion, 03/91 |
| Material Name: | Closed Prior to Micro Conversion, 03/91 |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
I00 - Overfill - None
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 12917 |
| Tank Status: | Closed Prior to Micro Conversion, 03/91 |
| Material Name: | Closed Prior to Micro Conversion, 03/91 |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

HIST UST:

| | |
|---|---|
| PBS Number: | 2-315923 |
| SPDES Number: | Not reported |
| Emergency Contact: | RONALD S C OTTLEY |
| Emergency Telephone: | (718) 978-7454 |
| Operator: | LAB DELIVERY SERVICE INC |
| Operator Telephone: | (718) 788-2895 |
| Owner Name: | LAB DELIVERY SERVICE INC |
| Owner Address: | 3644 SEABRING ST |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Owner Telephone: | (718) 788-2895 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | LAB DELIVERY SERVICE INC |
| Mailing Address: | 3644 SEABRING ST |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Contact: | CHARLES SKINNER |
| Mailing Telephone: | (718) 788-2895 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Facility Addr2: | 3644 SEABRING STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | TRUCKING/TRANSPORTATION |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 01/13/1993 |
| Expiration Date: | 07/10/1997 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 002 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed Before April 1, 1991 |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Submersible |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 003 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed Before April 1, 1991 |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Submersible |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-315923 |
| Program Type: | PBS |
| UTM X: | 593009.15685999999 |
| UTM Y: | 4497859.1483500004 |
| Expiration Date: | N/A |
| Site Type: | Trucking/Transportation/Fleet Operation |

Affiliation Records:

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Facility Owner |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 3644 SEABRING ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Mail Contact |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | CHARLES SKINNER |
| Address1: | 3644 SEABRING ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | On-Site Operator |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | LAB DELIVERY SERVICE INC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 788-2895 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 14464 |
| Affiliation Type: | Emergency Contact |
| Company Name: | LAB DELIVERY SERVICE INC |
| Contact Type: | Not reported |
| Contact Name: | RONALD S C OTTLEY |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 978-7454 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 004 |
| Tank Id: | 12918 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Tank Converted to Non-Regulated Use |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 275 |
| Tightness Test Method: | ZZ |
| Date Test: | 03/01/1991 |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/01/1996 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tank Number: | 005 |
| Tank Id: | 12919 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Tank Converted to Non-Regulated Use |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 275 |
| Tightness Test Method: | ZZ |
| Date Test: | 03/01/1991 |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/01/1996 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-315923 |
| SWIS Code: | 6101 |
| Operator: | LAB DELIVERY SERVICE INC |
| Facility Phone: | (718) 788-2895 |
| Facility Addr2: | 3644 SEABRING STREET |
| Facility Type: | TRUCKING/TRANSPORTATION |
| Emergency: | RONALD S C OTTLEY |
| Emergency Tel: | (718) 978-7454 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | LAB DELIVERY SERVICE INC |
| Owner Address: | 3644 SEABRING ST |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 788-2895 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | CHARLES SKINNER |
| Mailing Name: | LAB DELIVERY SERVICE INC |
| Mailing Address: | 3644 SEABRING ST |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Telephone: | (718) 788-2895 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Certification Flag: | False |
| Certification Date: | 01/13/1993 |
| Expiration: | 07/10/1997 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 004 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | Tank Converted To Non-Regulated Use |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | Not reported |
| Dispenser Method: | Gravity |
| Date Tested: | 03/01/1991 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1996 |
| Test Method: | Not reported |

**LAB DELIVERY SERVICE INC (Continued)** **U003074494**

| | |
|---|---|
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

| | |
|---|---|
| Tank ID: | 005 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | Tank Converted To Non-Regulated Use |
| Install Date: | Not reported |
| Capacity (Gal): | 275 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | Not reported |
| Dispenser Method: | Gravity |
| Date Tested: | 03/01/1991 |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1996 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**X202** **LOT 9,TAXBLOCK 304** **NY E DESIGNATION** **S111073163**
**East** **102 WARREN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.070 mi.**
**369 ft.** **Site 12 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 9 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |

**LOT 9,TAXBLOCK 304 (Continued)** **S111073163**

| | |
|---|---|
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GISELLE BAFFI |
| Lot Area: | 000003189 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0028.75 |
| Lot Depth: | 0100.42 |
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000007560 |
| Total Assessed Value: | 00000032359 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000026229 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.97 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040009 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984192 |
| Y Coordinate: | 0190199 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |

**LOT 9,TAXBLOCK 304 (Continued)** **S111073163**

| | |
|---|---|
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 9 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | R6 |
| Zone District 2: | M1-1 |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | R6 |
| All Components2: | M1-1 |
| Split Boundary Indicator: | Y |
| Building Class: | C0 |
| Land Use Category: | 02 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | GISELLE BAFFI |
| Lot Area: | 000003189 |
| Total Building Floor Area: | 00000003090 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 003.00 |
| Residential Units: | 00003 |
| Non and Residential Units: | 00003 |
| Lot Frontage: | 0028.75 |
| Lot Depth: | 0100.42 |

**LOT 9,TAXBLOCK 304 (Continued)** **S111073163**

| | |
|---|---|
| Building Frontage: | 0021.33 |
| Building Depth: | 0048.33 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 2 |
| Land Assessed Value: | 00000007560 |
| Total Assessed Value: | 00000032359 |
| Land Exempt Value: | 00000001430 |
| Total Exempt Value: | 00000026229 |
| Year Built: | 1995 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.97 |
| Maximum Allowable Far: | 02.43 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040009 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984192 |
| Y Coordinate: | 0190199 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**W203** **33 CARROLL ST** **NY UST** **U004199590**
**SSW** **33 CARROLL STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.072 mi.**
**380 ft.** **Site 2 of 6 in cluster W**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-612126 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2014/10/20 |
| UTM X: | Not reported |
| UTM Y: | Not reported |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 488529 |
| Affiliation Type: | Facility Owner |
| Company Name: | CENTER FOR NEGATIVE THINKING LLC |

**33 CARROLL ST (Continued)** **U004199590**

| | |
|---|---|
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 131 UNION STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 875-4599 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 11/7/2013 |

| | |
|---|---|
| Site Id: | 488529 |
| Affiliation Type: | Mail Contact |
| Company Name: | CENTER FOR NEGATIVE THINKING LLC |
| Contact Type: | Not reported |
| Contact Name: | HERNAN GALVIS |
| Address1: | 131 UNION STREET |
| Address2: | GROUND FLOOR |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 875-4599 |
| EMail: | HEGALVIS@GMAIL.COM |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/31/2013 |

| | |
|---|---|
| Site Id: | 488529 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 33 CARROLL STREET |
| Contact Type: | Not reported |
| Contact Name: | VACANT LAND |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | N/A |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/31/2013 |

| | |
|---|---|
| Site Id: | 488529 |
| Affiliation Type: | Emergency Contact |
| Company Name: | CENTER FOR NEGATIVE THINKING LLC |
| Contact Type: | Not reported |
| Contact Name: | HERNAN GALVIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**33 CARROLL ST (Continued)** **U004199590**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (646) 519-1261 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/31/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 250104 |
| Tank Status: | Temporarily Out of Service |
| Material Name: | Temporarily Out of Service |
| Capacity Gallons: | 3000 |
| Install Date: | 01/01/2004 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/01/2013 |

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

---

**V204** **BLOOMING IMPORT INC.** **FINDS** **1014903417**
**SSW** **45 BOWNE STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.073 mi.**
**384 ft.** **Site 16 of 19 in cluster V**

**Relative: Higher**

**Actual: 8 ft.**

FINDS:

Registry ID: 110043720337

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all

**BLOOMING IMPORT INC. (Continued)** **1014903417**

Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

---

**X205** **LOT 16,TAXBLOCK 304** **NY RES DECL** **S109155497**
**East** **108 WARREN STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.073 mi.**
**388 ft.** **Site 13 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-140 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532869 |
| Borough Code: | BK |
| Tax Block: | 304 |
| Tax Lot: | 16 |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | 410 HICKS ST CORP |
| Lot Area: | 000002496 |
| Total Building Floor Area: | 00000002475 |
| Floor Area, Commercial: | 00000002475 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000002475 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |

**LOT 16,TAXBLOCK 304 (Continued)** **S109155497**

| | |
|---|---|
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0025.00 |
| Building, Depth: | 0099.83 |
| Building Front: | 0025.00 |
| Building Depth: | 0099.83 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000022455 |
| Assessed Value, Total: | 00000037125 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1967 |
| Year Built Code: | Not reported |
| Year Altered 1: | 0000 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3003040016 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984237 |
| Y Coordinate: | 0190146 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 16 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |

**LOT 16,TAXBLOCK 304 (Continued)** **S109155497**

| | |
|---|---|
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | 410 HICKS ST CORP |
| Lot Area: | 000002496 |
| Total Building Floor Area: | 00000002475 |
| Commercial Floor Area: | 00000002475 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000002475 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0025.00 |
| Lot Depth: | 0099.83 |
| Building Frontage: | 0025.00 |
| Building Depth: | 0099.83 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000022455 |
| Total Assessed Value: | 00000037125 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1967 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.99 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040016 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984237 |

**LOT 16,TAXBLOCK 304 (Continued)** **S109155497**

| | |
|---|---|
| Y Coordinate: | 0190146 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y206** **LOT 10,TAXBLOCK 304** **NY E DESIGNATION** **S109155494**
**ESE** **109 BALTIC STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.074 mi.**
**389 ft.** **Site 13 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 10 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G7 |
| Land Use Category: | 10 |
| Number of Easements: | 0 |
| Owner, Type of Code: | C |
| Owner Name: | Not reported |
| Lot Area: | 000019130 |
| Total Building Floor Area: | 00000019130 |
| Commercial Floor Area: | 00000019130 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |

**LOT 10,TAXBLOCK 304 (Continued)** **S109155494**

| | |
|---|---|
| Garage Floor Area: | 00000019130 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0152.00 |
| Lot Depth: | 0200.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 4 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000155250 |
| Total Assessed Value: | 00000155250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984224 |
| Y Coordinate: | 0190042 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 10 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Underground Gasoline Storage Tanks* Testing Protocol |

**LOT 10,TAXBLOCK 304 (Continued)** **S109155494**

| | |
|---|---|
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G7 |
| Land Use Category: | 10 |
| Number of Easements: | 0 |
| Owner, Type of Code: | C |
| Owner Name: | Not reported |
| Lot Area: | 000019130 |
| Total Building Floor Area: | 00000019130 |
| Commercial Floor Area: | 00000019130 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000019130 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0152.00 |
| Lot Depth: | 0200.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 4 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000155250 |
| Total Assessed Value: | 00000155250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |

**LOT 10,TAXBLOCK 304 (Continued)** **S109155494**

| | |
|---|---|
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984224 |
| Y Coordinate: | 0190042 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 10 |
| E-No: | E-36 |
| Effective Date: | 8/15/1991 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 87-094K |
| Ulurp Number: | 900075 ZMK |
| Zoning Map No: | 16a,16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G7 |
| Land Use Category: | 10 |
| Number of Easements: | 0 |
| Owner, Type of Code: | C |
| Owner Name: | Not reported |
| Lot Area: | 000019130 |
| Total Building Floor Area: | 00000019130 |
| Commercial Floor Area: | 00000019130 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000019130 |

**LOT 10,TAXBLOCK 304 (Continued)** **S109155494**

| | |
|---|---|
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0152.00 |
| Lot Depth: | 0200.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 4 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000155250 |
| Total Assessed Value: | 00000155250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040010 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984224 |
| Y Coordinate: | 0190042 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

**W207** **LOT 50,TAXBLOCK 347** **NY RES DECL** **S112139028**
**South** **29 CARROLL STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.074 mi.**
**389 ft.** **Site 3 of 6 in cluster W**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-191 |
| Cp ulurp No.: | 090225 ZMK |
| Zoning Map No.: | 2010000209747 |
| Borough Code: | BK |
| Tax Block: | 347 |
| Tax Lot: | 50 |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | CENTER FOR NEGATIVE |
| Lot Area: | 000008500 |
| Total Building Floor Area: | 00000008500 |
| Floor Area, Commercial: | 00000008500 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000008500 |
| Floor Area, Factory: | 00000000000 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 001.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0085.00 |
| Building, Depth: | 0100.00 |
| Building Front: | 0085.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

| | |
|---|---|
| Assessed Value, Land: | 00000051750 |
| Assessed Value, Total: | 00000120150 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered 1: | 1997 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3003470050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982964 |
| Y Coordinate: | 0188309 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 50 |
| E-No: | E-263 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 09DCP032K |
| Ulurp Number: | 090225ZMK |
| Zoning Map No: | 6a |
| Description: | Air Quality - HVAC fuel limited to natural gas |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CENTER FOR NEGATIVE |
| Lot Area: | 000008500 |
| Total Building Floor Area: | 00000008500 |
| Commercial Floor Area: | 00000008500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000008500 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0085.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0085.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000051750 |
| Total Assessed Value: | 00000120150 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered1: | 1997 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003470050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982964 |
| Y Coordinate: | 0188309 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

| | |
|---|---|
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| Tax Lot(s): | 50 |
| E-No: | E-263 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 09DCP032K |
| Ulurp Number: | 090225ZMK |
| Zoning Map No: | 6a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CENTER FOR NEGATIVE |
| Lot Area: | 000008500 |
| Total Building Floor Area: | 00000008500 |
| Commercial Floor Area: | 00000008500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000008500 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0085.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0085.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

| | |
|---|---|
| Land Assessed Value: | 00000051750 |
| Total Assessed Value: | 00000120150 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered1: | 1997 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003470050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982964 |
| Y Coordinate: | 0188309 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 50 |
| E-No: | E-263 |
| Effective Date: | 4/29/2011 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 09DCP032K |
| Ulurp Number: | 090225ZMK |
| Zoning Map No: | 6a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 2004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

| | |
|---|---|
| Split Boundary Indicator: | N |
| Building Class: | E9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | CENTER FOR NEGATIVE |
| Lot Area: | 000008500 |
| Total Building Floor Area: | 00000008500 |
| Commercial Floor Area: | 00000008500 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000008500 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0085.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0085.00 |
| Building Depth: | 0100.00 |
| Proximity Code: | 3 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000051750 |
| Total Assessed Value: | 00000120150 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | E |
| Year Altered1: | 1997 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003470050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982964 |
| Y Coordinate: | 0188309 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |

**LOT 50,TAXBLOCK 347 (Continued)** **S112139028**

Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**Y208** **LOT 17,TAXBLOCK 304** **NY RES DECL** **S109155498**
**East** **110 WARREN STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.075 mi.**
**395 ft.** **Site 14 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-140 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532869 |
| Borough Code: | BK |
| Tax Block: | 304 |
| Tax Lot: | 17 |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | 410 HICKS ST CP |
| Lot Area: | 000015283 |
| Total Building Floor Area: | 00000015800 |
| Floor Area, Commercial: | 00000015800 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000015800 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 004.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0114.83 |
| Building, Depth: | 0099.83 |
| Building Front: | 0114.00 |
| Building Depth: | 0110.00 |

**LOT 17,TAXBLOCK 304 (Continued)** **S109155498**

| | |
|---|---|
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000121950 |
| Assessed Value, Total: | 00000191250 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1930 |
| Year Built Code: | Not reported |
| Year Altered 1: | 1958 |
| Year Altered 2: | 1958 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.03 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3003040017 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984303 |
| Y Coordinate: | 0190099 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 17 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1005 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |

**LOT 17,TAXBLOCK 304 (Continued)** **S109155498**

| | |
|---|---|
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | 410 HICKS ST CP |
| Lot Area: | 000015283 |
| Total Building Floor Area: | 00000015800 |
| Commercial Floor Area: | 00000015800 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000015800 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 004.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0114.83 |
| Lot Depth: | 0099.83 |
| Building Frontage: | 0114.00 |
| Building Depth: | 0110.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | Y |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000121950 |
| Total Assessed Value: | 00000191250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1930 |
| Year Built Code: | Not reported |
| Year Altered1: | 1958 |
| Year Altered2: | 1958 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.03 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003040017 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984303 |
| Y Coordinate: | 0190099 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |

**LOT 17,TAXBLOCK 304 (Continued)** **S109155498**

| | |
|---|---|
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**Y209** **DAVID HAMBERGER INC** **NY MANIFEST** **1009231198**
**East** **110-112 WARREN ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.075 mi.**
**395 ft.** **Site 15 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000904169 |
| Country: | USA |
| Mailing Name: | DAVID HAMBERGER INC |
| Mailing Contact: | JEROME HAMBERGER |
| Mailing Address: | 110-112 WARREN STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-852-7101 |

| | |
|---|---|
| Document ID: | NJA1162937 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920114 |
| Part A Recv Date: | 920221 |
| Part B Recv Date: | 920128 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | NJD982281016 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | D007 - CHROMIUM 5.0 MG/L TCLP |
| Quantity: | 03000 |
| Units: | P - Pounds |
| Number of Containers: | 005 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541061 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |

**DAVID HAMBERGER INC (Continued)** **1009231198**

| | |
|---|---|
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 50200 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541062 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000004169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 45760 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541063 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |

**DAVID HAMBERGER INC (Continued)** **1009231198**

| | |
|---|---|
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 51220 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541065 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | TT14841A |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 45440 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| EPA ID: | NYP000004169 |
| Country: | USA |
| Mailing Name: | DAVID HAMBERGER INC |
| Mailing Contact: | JEROME HAMBERGER |
| Mailing Address: | 110-112 WARREN STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-852-7101 |

| | |
|---|---|
| Document ID: | NJA1162937 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920114 |
| Part A Recv Date: | 920221 |
| Part B Recv Date: | 920128 |

**DAVID HAMBERGER INC (Continued)** **1009231198**

Generator EPA ID: NYP000904169
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D007 - CHROMIUM 5.0 MG/L TCLP
Quantity: 03000
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 92

Document ID: MIA2541061
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 920114
Trans1 Recv Date: 920114
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920116
Part A Recv Date: Not reported
Part B Recv Date: 920205
Generator EPA ID: NYP000904169
Trans1 EPA ID: OHD068913409
Trans2 EPA ID: Not reported
TSDF ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50200
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 92

Document ID: MIA2541062
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 920114
Trans1 Recv Date: 920114
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920116
Part A Recv Date: Not reported
Part B Recv Date: 920205
Generator EPA ID: NYP000004169
Trans1 EPA ID: OHD068913409
Trans2 EPA ID: Not reported
TSDF ID: MID000724831
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 45760
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks

**DAVID HAMBERGER INC (Continued)** **1009231198**

| | |
|---|---|
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541063 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 51220 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | MIA2541065 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | TT14841A |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920114 |
| Trans1 Recv Date: | 920114 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920116 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920205 |
| Generator EPA ID: | NYP000904169 |
| Trans1 EPA ID: | OHD068913409 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID000724831 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 45440 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 92 |

**Y210** **FORMER ABM SERVICE STATION** **NY Spills** **U002170669**
**East** **434 HICKS STREET/115-117 KANE STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.076 mi.**
**399 ft.** **Site 16 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0106455 |
| Facility Type: | ER |
| DER Facility ID: | 358922 |
| Site ID: | 128268 |
| DEC Region: | 2 |
| Spill Date: | 9/19/2001 |
| Spill Number/Closed Date: | 0106455 / Not Reported |
| Spill Cause: | Unknown |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | AAOBLIGA |
| Referred To: | QUARTERLY STATUS REPORT BY9/15/08 |
| Reported to Dept: | 9/20/2001 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Other |
| Cleanup Ceased: | 9/22/2004 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | True |
| Remediation Phase: | 5 |
| Date Entered In Computer: | 9/20/2001 |
| Spill Record Last Update: | 1/11/2012 |
| Spiller Name: | JOSEPH CUMBO |
| Spiller Company: | ABM SERVICE STATION |
| Spiller Address: | 434 HICKS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | KEVIN KLEAKA |
| Contact Phone: | (631) 269-8800 |
| DEC Memo: | DID PHASE II SITE ASSESSMENT. SAMPLES. PEGGED PID @ 2000. WILL SEND REPORT TO JENN ROMMEL. WILL BE COLLECTING GW SAMPLES ON FRIDAY. SPILL# TRANSFERRED FROM C. ENGELHARDT TO J. ROMMEL.10/22/02 JIM ROMEO FROM EAI A NJ ENVIRONMENTAL CO. WILL BE PROCEEDING WITH TANK REMOVAL AND SITE REMEDIATION PBS #2-47711710/02/01 Phase II report prepared by Impact Environmental received. 10 soil samples collected. Gasoline contaminated soils in SP-1(12-14'), SP-3(14-16'), SP-4(14-16'), SP-5(14-16'), SP-8(10-12'), SP-8(14-16'), SP-9(14-16'), SP-9(25-27'). BTEX in soil ranged from ND(SP-6, 14-16') to 765344ppb(SP-5,14-16'). MTBE ranged from ND(SP-1, 12-14') to 276000ppb(SP-5, 14-16').12 groundwater samples collected. BTEX ranged from ND(GWP-8,9,10,11) to 9177ppb(GWP-4). MTBE ranged from 8ppb(GWP-9) to 690,000ppb(GWP-8).03/28/03 Joseph Cumbo - new owner. Planning to remove tanks and build residences. I advised him to ensure that he has approval from DEC and Health Dept before beginning construction.Mailed PBS application, site facility info and list of contractors -JMR 10/10/2003-Vought-Site visit by Vought and Sun on 10/9/03. Site was boarded up with large backhoe onsite and demolition debris of what appears to be entire former service station building. |

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

No personnel on site or postings of site/construction contacts. Three gasoline dispensers in place. No visible signs of petroleum releases such as staining. No drums onsite and no petroleum vapors via olfactory and PID. No ambient exposure of contaminated soil and no excavation below grade. Inspected adjacent Gowanus Expressway for visibile signs of petroleum seepage and no impacts were found. Vought searched Property Tax records and owner of site is Vincent Cumbo (189 MacKenzie Street, Brooklyn, NY 11235). According to phone information Cumbo's phone is 718-769-0098. Joseph Cumbo 718-769-5343 son412 Court StreetBrooklyn, NY 1123110/10/03 Rommel responded to inquiry from Community Board 6, Leroy Branch,Asst District Manager 718-643-3027 ext. 204.Concerned because property is fenced, would like status on site.Left message on his voice mail, informing him of the results of DEC's inspection.10/10/03 Spoke to Joseph Cumbo 718-769-5343 (cell 917-972-2163) son of Vincent412 Court StreetBrooklyn, NY 11231They plan to finish demolition of the station building today, will submit PBS application for tank modification, excavation of tanks is planned for next week. Joe has list of contractors and will notify us when he hires one. Joseph will keep me apprised of progress. Joseph would like a FOIL application mailed to his address. Rommel10/17/03 FOIL application mailed. Spill reassigned from Rommel to Foley10/23/03 Spoke to Joseph Cumbo. Demolition is completed. Joe indicated he is cost comparing before hiring an environmental contractor from the list that Rommel supplied. He will let me know when he hires one. Requested he keep me updated. (KMF)10/27/03 Spoke with J. Cumbo. Meeting with two more consultants this week. Future use as a residential building. (KMF)12/18/03 J. Cumbo left voicemail indicating he has chosen a contractor.12/19/03 Left voicemail for J. Cumbo requesting he update the PBS information to show tanks being removed. Also, requested he speak to his consultant regarding a workplan for tank removal including a sampling plan.2/9/04 Spoke with J. Cumbo. EAI, Stefan Smith (201-395-0010, fax X0020, email stefans@eaienviro.com) is his consultant. He was told that he was taking care of everything. Will call back.2/9/04 Spoke with Stefan Smith, EAI Environmental. Anna Ciercierska is handling project. Says workplan sent to Anthony Sigona and was approved. Requested tank closure report be sent to my attention. Sigona has no record of receiving workplan.PBS 2-602145, 2-477117 should both be addressed.2/20/04 Spoke with S. Smith, EAI. Some exceedances for VOCs. Will be sending closure report shortly.3/8/04 Received EAI, Inc. UST Closure and Corrective Action Report. (Anna Ciercierska, PM (201) 395-0010). Documents closure of two 2000gal gas, seven 550gal gas and one waste oil UST. 13 grab soil samples analyzed for VOCs and SVOCs (8021/8270). Several exceedances for PAHs and volatiles. Report states that contaminant exceedances will be excavated in conjunction with pending redevelopment activities. Samples should be taken after additional excavation. Will also need groundwater investigation.3/16/04 Mailed delineation letter to Vincenzo Cumbo and EAI.3/17/04 Call from Stefan Smith, EAI. Suggested they try to coordinate construction with soil excavation (possibly down to 12'bgs) and endpoint sampling, but Geoprobe now to obtain some groundwater samples. EAI to submit proposal by 3/19/04. 3/29/04 Spoke with Stefan Smith. Refusal hit at 27'. Geotech engineer also hit refusal at 32'. Asked that he send sampling plan for final excavation(to be 14' deep). No GW samples necessary if soil returns clean.4/1/04 Spoke to Stefan Smith. During drilling of second hole, encountered groundwater. Not sure of depth. Some elevated PID

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

readings in soil. Will characterize GW. 5/11/04 Received Subsurface Investigation Report from EAI dated April 2004. Two soil borings (SB-1, SB-3) were advanced on 3/27/04 and 3/30/04. Soil samples were collected for 8260/8270 analysis, at 16-16.5'bgs. Groundwater was encountered in SB-3 and sample taken at 22'bgs. Soil samples revealed VOCs and SVOCs above cleanup objectives. The groundwater sample also revealed VOCs and SVOCs above groundwater standards. Report recommends further delineation of groundwater conditions and excavation of soils during redevelopment(and additional soil sampling).5/11/04 Requested workplan be submitted within 45days(6/25/04) for the above recommendations.6/2/04 Spoke to Stefan Smith, EAI (cell 201-892-8170). Extended deadline 2 weeks to 7/9/04. Client is considering entering BCP.6/21/04 Spoke to J. Cumbo. Stefan Smith left EAI. He will call EAI to confirm workplan is being prepared. Cumbo's are not interested in pursuing BCP due to time constraints.6/29/04 Spoke to S. Smith (718-551-2995, fax 718-875-0135) who will be keeping job under his new company, Korner. Expect to have plan in by end of the week. Plan will include construction plans. Basement and lower parking garage proposed with apartment complex.7/1/04 Faxed FOIL application to S. Smith. 7/13/04 FOIL review. S. Smith will have RAP in by next week. 7/26/04 Spoke to J. Cumbo. S. Smith has not submitted anything to date. 7/28/04 Received RAP from Korner Environmental. Proposes over-excavation of soils to the "proposed depth of excavation". 7/29/04 RAP proposes soil removal to unknown depth(assumed as depth of foundation). Groundwater at 22'bgs. RAP does not address groundwater. Have not completed delineation. Stip mailed out requiring delineation and resubmittal of RAP. DOB permit letter mailed out. Stip due 8/20/04.8/18/04 Spoke to J. Cumbo. Meeting with EAI tomorrow morning. Will be sending in formal request for an extension for signing stipulation agreement.8/19/04 Written request for 3 week extension received via fax.9/15/04 Granted extension until 9/22/04.9/16/04 Spoke to A. Ciercierska, EAI. RAP to be submitted 9/20-9/21. Source removal and GW monitoring proposed. Will be characterizing soil for disposal. Delineation proposed to be done during source removal.9/22/04 Received faxed copy of stipulation signed by Vincenzo Cumbo.9/27/04 STIP fully executed by T. Kunkel.9/29/04 Received Remedial Investigation/Corrective Action Workplan prepared by EAI, dated September 2004. Proposing excavation down to at least 16'bgs on the eastern portion and down to 10'bgs on the western portion(deeper if necessary). No institutional or engineering controls have been proposed at this point. Proposes 3 MWs.10/6/04 Conditionally approved RAP. Sidewall and bottom soil samples to be collected every 30 linear feet and analyzed for 8260/8270. Required three additional wells and monthly gauging/quarterly sampling. Results to be submitted 30days from sample collection. Also reiterated requirement for vapor barrier/sub-foundation venting system. Remedial Action Report due 1/15/05. Department to be notified 10 days prior to any field work.11/12/04 FOIL application hand-delivered by J. Cumbo.12/9/04 J. Cumbo provided information of previous owner, Antoine Marzouka - 514 Prospect Avenue, Brooklyn (718-499-6376 or 718-965-3197).1/3/05 Spoke to Steven Feinman, atty for Jonathon Pisano. He left a VM message for L. Oliva.1/12/05 Left VM for A. Marzouka at 718-965-3197 requesting callback. Other number did not have VM.1/14/05 J. Cumbo's attorney, Michael Ficchi, sent letter requesting 4 month extension (5/16/05).8/1/05 Hydrotech(Antoinette, 631-462-5866) completed excavation and are taking endpoints.8/2/05 Site visit. Met with Mrs.

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

Cumbo and Sal Schirripa(J&M Schirripa Contractors Corp., 6223 13th Ave Brooklyn NY 11219, (718-331-5181, fax 718-331-3054, cell 646-773-1184). Excavation dug to groundwater at 17'bgs. Slight sheen on surface. No odors. Spoke to Antoinette, HydroTech, who will take endpoints today. Monitoring wells to be installed this week. 8/31/05 Received Design Plans and Specifications for Vapor Barrier and Passive Ventilation System prepared by HydroTech.9/7/05 Spoke to Antoinette, HydroTech. 16 endpoints taken, 5 exceed TAGM RSCOs. GW results should be in within the next couple of days. 9/14/05 Residual soil contamination and elevated groundwater results warrant further action. Requested that HydroTech propose appropriate plan to address contamination prior to installing the vapor barrier/venting system. Site meeting planned for 9/26/05.9/26/05 Met with M. Robbins, Hydrotech, Sal Schirripa, construction contractor and Mrs. Cumbo. HydroTech will prepare a proposal for injecting ORC or RegenOx.10/13/05 Received and approved RAP prepared by HydroTech. Proposes to inject ORC slurry into both the vadose zone soil and groundwater, and install 3 additional wells(total of 8) and monitor for effectiveness. Monthly monitoring and quarterly sampling(BTEX/MTBE). Will be proceeding with vapor barrier/passive ventilation system installation and construction. Quarterly reports to follow.12/14/05 Antoinette of Hydrotech(718-636-0800) called to notify the Department of well installation and ORC injection activities which will be done 12/19, 12/20.12/21/05 Sent permit letter to Hydrotech for ORC injection.5/17/06 Requested that Hydrotech provide status and date of when to expect quarterly reports.06/13/06-Reassigned to Andersen. (Sun)7/24/06: Reviewed the update report dated 5/24/06. ORC injected surrounding MW2 at downgradient corner of property. Off-site wells installed cross-gradient of MW-2. BQE is directly downgradient of the site. TVOC 25,980 (MW2) (1/20/06), max MTBE 2580 (MW2) (1/20/06). Monthly monitoring and quarterly sampling will occurr. An approval letter was sent.10/16/06: Left a phone message for Yashodhara Saha of Hydrotech to followup on next quarterly report submission date.10/23/06: Called Yashodhara Saha, she is out of the office, she will be back tomorrow.10/24/06: Received phone message from Paul at Hydrotech. He is the new project manager. A report will be submitted next week.11/9/06: Spoke to Paul from Hydrotech (office 718-636-0800, cell 631-241-7165), report will be submitted next week.11/16/06: Reviewed the quarterly report dated 11/8/06. Wells sampled on 9/15/06. Historically high MW2 not sampled because inaccessible. MW 4 and 5 were not sampled because they were dry. Decrease in contaminant concentration in MW1. Sent email requiring dissolved oxygen be measured during monthly gauging events.11/21/06: Sent letter requiring additional of measurement of DO and pH to quarterly sampling plan.12/26/06: Letter returned to sender.3/15/07: Spoke to Paul Matli (718-636-0800) at Hydrotech. The client did not renew the contract. A vapor barrier was laid down, but the groundwater table rose and flooded the basement. Need to speak with the property owner.3/19/07: Site inspection performed. Redevelopment as a residential apartment building is almost completed. Spoke to Joseph Cumbo (718-769-5343, cell 917-972-2163) regarding overdue quarterly report. He will speak to Hydrotech and get back to me. 3/21/07: This site is an e-designated site. Sent letter indicating a quarterly report is overdue. Quarterly sampling and reporting is required, and testing of sump if there is a sump.4/30/07: Letter returned to sender. Spoke to Paul Matli at HydroTech. He refered me to the person

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

in charge of contracts. She said that a proposal was submitted to Joseph Cumbo and he did not renew the contract. 5/1/07: Spoke to Joseph Cumbo. (email: cmbo310@yahoo.com). He said he will speak to the environmental company. I emailed him the 3/21/07 letter. He confirmed that the correct mailing address is 189 McKenzie Street.5/11/07: Sampling scheduled for 5/14/07.5/14/07: Groundwater sampling conducted. 7/30/07: Left message with Paul Matli's receptionist to followup on site status.8/6/07: Spoke to Paul Matli. He will check on site status and get back to me.8/15/07: Spoke to Rachel at Hydrotech (631-462-5866). The report will be submitted soon.8/23/07: Spoke to Rachel at Hydrotech. Report will be submitted soon. Vapor barrier will be installed tomorrow.8/31/07: Case refered to legal division.9/18/07: Spoke to Rachel at Hydrotech. Report will be submitted.9/19/07: Reviewed report dated 8/13/07. Wells sampled on 5/14/07. Total VOC 7,770 ppb in MW2. Benzene 600 ppb in MW2. Depth to water 13 ft. The new condo on the property has a basement. Dissolved oxygen in MW2 is much lower than the rest of the wells. MW 4 and MW5 were damaged during construction. Sent letter requiring the installation of a soil vapor well adjacent to MW2, monitoring of air discharge from the passive venting system, and quarterly reporting. Quarterly reports are required within 6 weeks of sampling. Received email from Paul Matli of Hydrotech, two 30 mil vapor barriers will be installed instead of a 60 mil barrier.10/15/07: Letter to Vincenzo Cumbo returned to sender -
unclaimed.
---
----------10/31/07: Reassigned from Sarah Carlson to Chanda.11/8/07: Chanda received a memo of the vapor barrier installation from Paul Matli, Hydro Tech Environmental Corp., dated 11/7/07 for this site. The vapor barrier was installed under the concrete foundation and beneath the basement floor of the building. Hydro Tech Environmental, Corp. supervised the installation of vapor barriers beneath the recently developed building at the site.11/9/07: Chanda sent an email to Mr. Paul Matli, requiring that soil vapor monitoring well installation, air discharge from the passive venting system shall be measure monthly with PID, quarterly groundwater gauging, sampling and reporting must be submitted to the Department for review and approval.11/27/07: Chanda received a call from Paul Matli, Hydrotech, regarding the site visit to see the vapor barrier beneath the basement floor of the building.11/29/07: Chanda received an e-mail from Paul Matli(Hydrotech)to confirm our site visit on on December 6 at 10:00 a.m. DEC gave to consent with the schedule.12/6/07: Chanda visited the site; met with consultant Paul Matli (Hydrotech), RP, Contractor of Metrotech Construction. It is concluded that Soil Vapor Monitoring adjacent to monitoring well MW-2, Air Discharge Monitoring the passive venting system and Quarterly Groundwater monitoring are required.12/27/07: Joseph Cumbo (RP's representative), Rachel Ataman, Paul Matil(HydroTech), and Salvator Schirripa (Metrotech Construction) attends to meet in DEC office with Kartik Chanda, and Joe Sun of DEC. They discussed regarding the additional vapor barrier instalattion inside the foundation wall in the basement, soil vapor monitoring, GW monitoring, and indoor air sampling for this site. The meeting is concluded that the basement floor will be constructed after completion of the vapor barrier installation.12/31/07: Chanda sent a letter to RP (Vincenzo Cumbo) and his consultant Paul Matli (Hydro Tech) requiring, that the Quarterly Report (Soil Vapor, GW, and Air

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

Discharge) must be submitted to the Department by 2/29/08 for review.2/5/08: Chanda visited the site; met with RP (Joe Cumbo), Contractor of Metrotech Construction, regarding the witness of the installation of additional vapor barrier inside the foundation wall in the basement. The additional vapor barrier was installed inside the foundation wall in the basement but they did not put any vapor barrier surrounding the elevator pit wall. It is concluded that the basement floor will be constructed after completion of the elevator pit wall vapor barrier installation. Documentation of the installation of vapor barrier must be submitted to the DEC for review.2/28/08: Chanda received an extension request from RP(Joseph Cumbo)to submit the Quarterly report as required in the DEC's letter dated 12/31/07. The Department approves the RP request. The deadline is extended to April 14, 2008.3/4/08: Chanda sent an extension approval letter to RP (Joseph Cumbo, email: projec310@yahoo.com)) and his consultant Paul Matli (Hydro Tech) requiring that the Quarterly Report (Soil Vapor, GW, and Air Discharge) must be submitted to the Department by 4/14/08 for review.3/17/08: Chanda received a letter from Paul Matli, Hydrotech, stated that a sidewalk permit is required to install a soil vapor monitoring well at the site. Chanda sent a sidewalk permit letter via email to Paul Matli, Hydro Tech, for this site.3/25/08: Chanda received a Revised Vapor Barrier Installation Report and enclosed with this report is a specimen of the Prem-A-Barrier Wall Flashing. (see eDocs)3/26/08: Chanda has reviewed the Revised Vapor Barrier Installation Report and sent a approval letter to RP and his consultant (Hydro Tech Env.)4/1/08: Chanda received an extension request from Hydro Tech Environmental, Corp (Paul Matli) to submit soil vapor monitoring, Air Discharge Monitoring and Quarterly Sampling and monitoring reports for this spill site. He requests that the investigation report will be submitted sometimes in early June 2008.4/15/08: Chanda sent an extension approval letter to RP (Joseph Cumbo) and his consultant Paul Matli (Hydro Tech) requiring that the Quarterly Report (Soil Vapor, GW, and Air Discharge) must be submitted to the Department by 6/2/08 for review and approval.6/4/08: Chanda received a Quarterly Status Report (March 2008-May 2008)prepared by Hydro Tech Environmental dated June 2, 2008. (see eDocs)6/30/08: Chanda has reviewed the Quarterly Status Report and has the following comments:* The GW flow direction is toward the east, which is consistent with historical flow directions.*The result of GW sampling from MW-1 and MW-2 indicate elevated levels of dissolve gasolene constituents are still present beneath the southern portion of the site.* BQE is directly downgradient of the site. Total VOC is 13,230 ppb(MW2) (5/6/08), Total VOC is 2,600 ppb (MW-1)(5/6/08). These levels are relatively higher than the previous sampling event conducted during May 2007.* The soil vapor well sampling in the vicinity of MW-2 contains chlorinated solvent including PERC(PERC> 156 mcg/m3) at concentrations exceeding the NYSDOH Guidance -2003. Chanda discussed with Joe Sun regarding the findings of the Quarterly Status Report dated May 2008.7/1/08: Chanda sent a letter to RP and his consultant requiring, that additional ORC application to treat the GW at the site. Therefore, the next Quarterly Report will be submitted to DEC by 9/15/08 for review. The Quarterly Reports should include the results of monthly monitoring of the passive venting system, quarterly groundwater, and soil vapor monitoring.7/10/08: Joseph Cumbo (RP's representative), Rachel Ataman, Paul Matil(HydroTech), and Giovanni De Piello, Esq. attends to meet in DEC office with

**FORMER ABM SERVICE STATION (Continued)** **U002170669**

Kartik Chanda, and Joe Sun of DEC. They discussed regarding the additional ORC injection to treat the groundwater at the site, and soil vapor monitoring, GW monitoring, and indoor air sampling for this site. The meeting is concluded that the indoor air sampling will be conducted after completion of the building construction.8/20/08: Chanda received an email from Paul Matil (Hydrotech). The email requested that a side walk permit is required regarding the second round ORC injection at Hicks Street. (see eDocs)11/12/10 - spill re-assigned from Tibbe to Joe O'Connell.11/28/11 - Obligado - Spill re-assigned from O'Connell to Obligado.1/11/12 - Obligado - I emailed Hydrotech to inquire if approval was ever granted or if any additional work was performed.

Remarks: contaminated soil - location has been a gas station for last 50 yrs

Material:

| | |
|---|---|
| Site ID: | 128268 |
| Operable Unit ID: | 844710 |
| Operable Unit: | 01 |
| Material ID: | 531310 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**X211** **LOT 19,TAXBLOCK 299** **NY RES DECL** **S109155500**
**ENE** **96 CONGRESS STREET** **NY E DESIGNATION** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.076 mi.**
**400 ft.** **Site 14 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

RES DECL:

| | |
|---|---|
| Restrictive Decl. No.: | R-139 |
| Cp ulurp No.: | 080116 ZMK |
| Zoning Map No.: | 2007000532868 |
| Borough Code: | BK |
| Tax Block: | 299 |
| Tax Lot: | 19 |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 4000 |
| Health Center District: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercail Overlay 1: | Not reported |
| Commercial Overlay 2: | Not reported |

**LOT 19,TAXBLOCK 299 (Continued)** **S109155500**

| | |
|---|---|
| Special Purpose Dist.: | Not reported |
| Special Purpose Dist.: | Not reported |
| All Components 1: | M1-1 |
| All Components 2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Easements, Number Of: | 0 |
| Owner, Type Of Own. Code: | Not reported |
| Owner Name: | DISPLAY INC |
| Lot Area: | 000004827 |
| Total Building Floor Area: | 00000008658 |
| Floor Area, Commercial: | 00000008658 |
| Floor Area, Residential: | 00000000000 |
| Floor Area, Office: | 00000000000 |
| Floor Area, Retail: | 00000000000 |
| Floor Area, Garage: | 00000000000 |
| Floor Area, Storage: | 00000000000 |
| Floor Area, Factory: | 00000008658 |
| Floor Area, Other: | 00000000000 |
| Floor Area, Tot. Building Source Code: | 7 |
| Number Of Buildings: | 00001 |
| Number Of Floors: | 002.00 |
| Units, Residential: | 00000 |
| Units, Residential And Nonresidential: | 00001 |
| Lot, Frontage: | 0050.00 |
| Building, Depth: | 0098.08 |
| Building Front: | 0048.00 |
| Building Depth: | 0098.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type/Grade: | 5 |
| Assessed Value, Land: | 00000047700 |
| Assessed Value, Total: | 00000089550 |
| Exempt Value, Land: | 00000000000 |
| Exempt Value, Total: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered 1: | 1987 |
| Year Altered 2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.79 |
| Maximum Allowable Far: | 01.00 |
| Boro Code: | 3 |
| Borough, Tax Block & Lot: | 3002990019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984419 |
| Y Coordinate: | 0190338 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation Number: | Not reported |
| Date Of Rpad Data: | 11/2005 |
| Date Of Dcas Data: | 01/2006 |

**LOT 19,TAXBLOCK 299 (Continued)** **S109155500**

| | |
|---|---|
| Date Of Zoning Data: | 11/2005 |
| Date Of Major Property Data: | 11/2005 |
| Date Of Landmark Data: | 12/2005 |
| Date Of Base Map Data: | 01/2006 |
| Date Of Mass Appraisal Data: | 11/2005 |
| Date Of Political And Administrative: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 19 |
| E-No: | E-205 |
| Effective Date: | 4/16/2008 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 07DCP073K |
| Ulurp Number: | 080116ZMK |
| Zoning Map No: | 16c |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 47 |
| Census Block: | 1004 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E224 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | F9 |
| Land Use Category: | 06 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | DISPLAY INC |
| Lot Area: | 000004827 |
| Total Building Floor Area: | 00000008658 |
| Commercial Floor Area: | 00000008658 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000008658 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 002.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0050.00 |
| Lot Depth: | 0098.08 |
| Building Frontage: | 0048.00 |

**LOT 19,TAXBLOCK 299 (Continued)** **S109155500**

| | |
|---|---|
| Building Depth: | 0098.00 |
| Proximity Code: | 2 |
| Irregular Lot Code: | Y |
| Lot Type: | 3 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000047700 |
| Total Assessed Value: | 00000089550 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 1987 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0001.79 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3002990019 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0047 |
| X Coordinate: | 0984419 |
| Y Coordinate: | 0190338 |
| Zoning Map: | 16C |
| Sanborn Map: | 301 033 |
| Tax Map: | 30201 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**AA212** **DEGRAW** **NY Spills** **S107408522**
**SSE** **DEGRAW/HICKS** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.081 mi.**
**426 ft.** **Site 1 of 5 in cluster AA**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0506519 |
| Facility Type: | ER |
| DER Facility ID: | 299025 |
| Site ID: | 351749 |
| DEC Region: | 2 |
| Spill Date: | 8/26/2005 |
| Spill Number/Closed Date: | 0506519 / 9/29/2005 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 8/26/2005 |

**DEGRAW (Continued)** **S107408522**

| | |
|---|---|
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/26/2005 |
| Spill Record Last Update: | 2/10/2006 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | 2 PETTICOAT LA |
| Spiller City,St,Zip: | TOWN OF BRUNSWICK, NY |
| Spiller Company: | 001 |
| Contact Name: | MR WATERS |
| Contact Phone: | (646) 610-5580 |
| DEC Memo: | 09.29.05 SR// No drums found. |
| Remarks: | ONE DRUM NEEDS TO BE PICKED UP NOT LEAKING |

Material:

| | |
|---|---|
| Site ID: | 351749 |
| Operable Unit ID: | 1109254 |
| Operable Unit: | 01 |
| Material ID: | 2099245 |
| Material Code: | 0015 |
| Material Name: | Motor Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AA213** **HICKS ST** **NY Spills** **S102401910**
**SSE** **HICKS ST BET PRES. & CARR** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.081 mi.**
**426 ft.** **Site 2 of 5 in cluster AA**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9905715 |
| Facility Type: | ER |
| DER Facility ID: | 182807 |
| Site ID: | 221013 |
| DEC Region: | 2 |
| Spill Date: | 8/12/1999 |
| Spill Number/Closed Date: | 9905715 / 11/12/1999 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |

**HICKS ST (Continued)** **S102401910**

| | |
|---|---|
| Investigator: | O'DOWD |
| Referred To: | Not reported |
| Reported to Dept: | 8/12/1999 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/12/1999 |
| Spill Record Last Update: | 11/17/1999 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | CALLER |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | 2 55 GALLON DRUMS ON SIDE OF ROAD. |

Material:

| | |
|---|---|
| Site ID: | 221013 |
| Operable Unit ID: | 1084214 |
| Operable Unit: | 01 |
| Material ID: | 302005 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 110 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9606082 |
| Facility Type: | ER |
| DER Facility ID: | 229699 |
| Site ID: | 283198 |
| DEC Region: | 2 |
| Spill Date: | 8/12/1996 |
| Spill Number/Closed Date: | 9606082 / 8/12/1996 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 8/12/1996 |

**HICKS ST (Continued)** **S102401910**

| | |
|---|---|
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/12/1996 |
| Spill Record Last Update: | 8/28/1996 |
| Spiller Name: | STEVEN ROMERO |
| Spiller Company: | CON EDISON |
| Spiller Address: | 128 WEST END AVENUE |
| Spiller City,St,Zip: | NEW YORK, NY 10023 |
| Spiller Company: | 001 |
| Contact Name: | STEVEN ROMERO |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"ODOR FROM BAR-B-Q |
| Remarks: | BROKEN HYDRAULIC LINE ON REPAIR TRUCK. SOME OF THE MATERIAL DIDGO INTO A STORM SEWER BUT CREW IS ABLE TO RETRIEVE IT.NO CALL BACK REQUESTED. |

Material:

| | |
|---|---|
| Site ID: | 283198 |
| Operable Unit ID: | 1033611 |
| Operable Unit: | 01 |
| Material ID: | 348817 |
| Material Code: | 0010 |
| Material Name: | Hydraulic Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | 5 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**Y214** **ATLANTIC-HICKS ST** **FINDS** **1005820329**
**ESE** **434 HICKS STREET** **US AIRS** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.081 mi.**
**427 ft.** **Site 17 of 21 in cluster Y**

**Relative: Higher**

**Actual: 15 ft.**

FINDS:

Registry ID: 110006624368

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for

**ATLANTIC-HICKS ST (Continued)** **1005820329**

information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110005970967 |
| Plant name: | ATLANTIC-HICKS ST |
| Plant address: | 434 HICKS STREET<br>BROOKLYN, NY 11201 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 5541 |
| Sic code desc: | GASOLINE SERVICE STATIONS |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | SIP SOURCE |
| National action type: | Not reported |
| Date achieved: | 00000 |
| Penalty amount: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1104 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1202 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1301 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |

**ATLANTIC-HICKS ST (Continued)** **1005820329**

Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**Y215** **EDR US Hist Auto Stat** **1015494315**
**ESE** **434 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.081 mi.**
**427 ft.** **Site 18 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Auto Stations:
Name: ABM SERVICE STATION INCORPORATED
Year: 1999
Address: 434 HICKS ST

Name: ABM SERVICE STATION INCORPORATED
Year: 2000
Address: 434 HICKS ST

Name: ABM SERVICE STATION INC
Year: 2001

**(Continued)** **1015494315**

Address: 434 HICKS ST

Name: ABM SERVICE STATION INC
Year: 2002
Address: 434 HICKS ST

Name: ABM SERVICE STATION INC
Year: 2003
Address: 434 HICKS ST

Name: ABM SERVICE STATION INC
Year: 2004
Address: 434 HICKS ST

---

**Y216** **ABM SERVICE STATION, INC.** **NY UST** **U001840831**
**ESE** **434 HICKS STREET** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.081 mi.**
**427 ft.** **Site 19 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

UST:
Id/Status: 2-477117 / Unregulated
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584538.34846999997
UTM Y: 4504593.9355699997
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 21147
Affiliation Type: Facility Owner
Company Name: VINCENZO CUMBO
Contact Type: Not reported
Contact Name: Not reported
Address1: 189 MCKENZIE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231
Country Code: 001
Phone: (718) 855-1401
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21147
Affiliation Type: Mail Contact
Company Name: VINCENZO CUMBO
Contact Type: Not reported
Contact Name: Not reported
Address1: 189 KCKENZIE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Country Code: 001
Phone: (718) 855-1401
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21147
Affiliation Type: On-Site Operator
Company Name: ATLANTIC GAS STATION
Contact Type: Not reported
Contact Name: VINCENZO CUMBO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 855-1401
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21147
Affiliation Type: Emergency Contact
Company Name: VINCENZO CUMBO
Contact Type: Not reported
Contact Name: VINCENZO CUMBO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 855-1401
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 49328
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 2000
Install Date: 08/01/1987
Date Tank Closed: 01/15/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Date Test: 01/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

Tank Number: 001
Tank ID: 38185
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 04/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 38186
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 04/01/1989
Registered: True

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 49329
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 2000
Install Date: 08/01/1987
Date Tank Closed: 01/15/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 01/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003
Tank ID: 38187

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 04/01/1989 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 49330 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1998 |
| Date Tank Closed: | 04/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 03 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 38188
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 004
Tank ID: 49331
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 005
Tank ID: 49332
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 005
Tank ID: 38189
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 006
Tank ID: 49333
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 006
Tank ID: 38190
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 007
Tank ID: 38191
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 007
Tank ID: 49334
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 008
Tank ID: 67426
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 008
Tank ID: 49335
Tank Status: Closed - In Place
Material Name: Closed - In Place

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1998 |
| Date Tank Closed: | 04/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

| | |
|---|---|
| Tank Number: | 009 |
| Tank ID: | 67427 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Tank Number: | 010 |
| Tank ID: | 67428 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Affiliation Records:

| | |
|---|---|
| Site Id: | 24104 |
| Affiliation Type: | Facility Owner |
| Company Name: | ABM SERVICE STATION, INC. |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 434 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 625-3772 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |
| Site Id: | 24104 |
| Affiliation Type: | Mail Contact |
| Company Name: | ABM SERVICE STATION, INC. |
| Contact Type: | Not reported |
| Contact Name: | MR. KALIL BATIR |
| Address1: | 434 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Zip Code: 11201
Country Code: 001
Phone: (718) 625-3772
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24104
Affiliation Type: On-Site Operator
Company Name: ABM SERVICE STATION, INC.
Contact Type: Not reported
Contact Name: ABM SERVICE STATION, INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 625-3772
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24104
Affiliation Type: Emergency Contact
Company Name: ABM SERVICE STATION, INC.
Contact Type: Not reported
Contact Name: KALIL BATIR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-6878
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 49328
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 2000
Install Date: 08/01/1987
Date Tank Closed: 01/15/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tightness Test Method: 03
Date Test: 01/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

Tank Number: 001
Tank ID: 38185
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 04/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 38186
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 04/01/1989

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 49329
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 2000
Install Date: 08/01/1987
Date Tank Closed: 01/15/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 01/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Tank ID: | 38187 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 04/01/1989 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 49330 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1998 |
| Date Tank Closed: | 04/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 03 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 38188
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 004
Tank ID: 49331
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 005
Tank ID: 49332
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 005
Tank ID: 38189
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 006
Tank ID: 49333
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 006
Tank ID: 38190
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 007
Tank ID: 38191
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/01/1985
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 007
Tank ID: 49334
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1998
Date Tank Closed: 04/01/1999
Registered: True
Tank Location: Underground

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 008
Tank ID: 67426
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 008
Tank ID: 49335
Tank Status: Closed - In Place
Material Name: Closed - In Place

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Capacity Gallons: | 550 |
| Install Date: | 12/01/1998 |
| Date Tank Closed: | 04/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 10/01/1995 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

| | |
|---|---|
| Tank Number: | 009 |
| Tank ID: | 67427 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Tank Number: | 010 |
| Tank ID: | 67428 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None

HIST UST:

| | |
|---|---|
| PBS Number: | 2-477117 |
| SPDES Number: | Not reported |
| Emergency Contact: | SALVATORE PISANO |
| Emergency Telephone: | (718) 000-0000 |
| Operator: | SALVATORE PISANO |
| Operator Telephone: | (718) 000-0000 |
| Owner Name: | SALVATORE PISANO |
| Owner Address: | 434 HICKS STREET |
| Owner City,St,Zip: | BROOKLYN, NY 11201 |
| Owner Telephone: | (718) 000-0000 |
| Owner Type: | Not reported |
| Owner Subtype: | Not reported |
| Mailing Name: | SALVATORE PISANO |
| Mailing Address: | 434 HICKS STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11201 |
| Mailing Contact: | Not reported |
| Mailing Telephone: | (718) 000-0000 |
| Owner Mark: | First Owner |
| Facility Status: | 3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated). |
| Facility Addr2: | 434 HICKS STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | Not reported |

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 06/12/1992 |
| Expiration Date: | 08/10/1994 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | Minor Data Missing |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 2000 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | 04/01/1999 |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 002 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 2000 |
| Product Stored: | UNLEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | 04/01/1999 |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 003 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 004 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 005 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 006 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 550 |
| Product Stored: | LEADED GASOLINE |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |

**ABM SERVICE STATION, INC. (Continued)** **U001840831**

| | |
|---|---|
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 007 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Undefined |
| Install Date: | 04/01/1989 |
| Capacity (gals): | 550 |
| Product Stored: | DIESEL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Not reported |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 08/01/1995 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| Lat/long: | Not reported |

---

**U217** **211 VAN BRUNT STREET (HURRICANE SANDY)** **NY SPILLS 90** **S112395101**
**SSW** **211 VAN BRUNT STREET** **N/A**
**< 1/8** **RED HOOK, NY**
**0.081 mi.**
**428 ft.** **Site 4 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

Spills:

| | |
|---|---|
| Status: | CLOSED |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| Site ID: | 1212405 |
| Secondary ID: | 475553 |
| Cross Street: | Not reported |
| County: | KINGS |
| Longitude: | 0 |
| Latitude: | 0 |
| Elevation: | Not reported |

**U218** **211 VAN BRUNT STREET (HURRICANE SANDY)** **NY Spills** **S112807622**
**SSW** **211 VAN BRUNT STREET** **N/A**
**< 1/8** **RED HOOK, NY**
**0.081 mi.**
**428 ft.** **Site 5 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1212405 |
| Facility Type: | ER |
| DER Facility ID: | 430842 |
| Site ID: | 475553 |
| DEC Region: | 2 |
| Spill Date: | 10/29/2012 |
| Spill Number/Closed Date: | 1212405 / 11/16/2012 |
| Spill Cause: | Storm |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | Hurricane Sandy R2 |
| Referred To: | Not reported |
| Reported to Dept: | 11/16/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | DEC |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | Not reported |
| Date Entered In Computer: | 11/23/2012 |
| Spill Record Last Update: | 11/23/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | Not reported |
| Spiller Company: | Not reported |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | This spill report was created for tracking purposes related to the Department’s Hurricane Sandy emergency response efforts.DEC contractor JRG pumped out 400 gallons of fuel oil on 11/16/2012 |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 475553 |
| Operable Unit ID: | 1225386 |
| Operable Unit: | 01 |
| Material ID: | 2228925 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | 400 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**211 VAN BRUNT STREET (HURRICANE SANDY) (Continued)** **S112807622**

Tank Test:

---

**X219** **DAVID HAMBERGER INC** **FINDS** **1016401862**
**East** **410 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.081 mi.**
**428 ft.** **Site 15 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

FINDS:

Registry ID: 110055357475

Environmental Interest/Information System

---

**AB220** **COLUMBIA HICKS SITE 3** **NY UST** **U004148280**
**East** **414 HICKS STREET** **NY AST** **N/A**
**< 1/8** **BRROKLYN, NY 11201**
**0.081 mi.**
**429 ft.** **Site 1 of 5 in cluster AB**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-611205 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584540.52379000001 |
| UTM Y: | 4504678.6378499996 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | Facility Owner |
| Company Name: | COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS) |
| Contact Type: | AUTHORIZED SIGNATORY |
| Contact Name: | LISA GOMEZ |
| Address1: | 185 PALMER AVE., SUITE 203 |
| Address2: | Not reported |
| City: | LARCHMONT |
| State: | YT |
| Zip Code: | 10538 |
| Country Code: | 001 |
| Phone: | (914) 833-3000 |
| EMail: | DKENYON@LMDEVPARTNERS.COM |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 11/12/2009 |

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | Mail Contact |
| Company Name: | COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS) |
| Contact Type: | AUTHORIZED SIGNATORY |
| Contact Name: | LISA GOMEZ |
| Address1: | 185 PALMER AVE., SUITE 203 |
| Address2: | Not reported |

**COLUMBIA HICKS SITE 3 (Continued)** **U004148280**

City: LARCHMONT
State: YT
Zip Code: 10538
Country Code: 001
Phone: (914) 833-3000
EMail: DKENYON@LMDEVPARTNERS.COM
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 11/12/2009

Site Id: 421739
Affiliation Type: On-Site Operator
Company Name: COLUMBIA HICKS SITE 3
Contact Type: Not reported
Contact Name: ED LINDH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 833-3000
EMail: Not reported
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 11/12/2009

Site Id: 421739
Affiliation Type: Emergency Contact
Company Name: COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS)
Contact Type: Not reported
Contact Name: DEBBIE KENYON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 833-3000
EMail: Not reported
Fax Number: Not reported
Modified By: EJCALIFA
Date Last Modified: 11/12/2009

Tank Info:

Tank Number: 002
Tank ID: 231564
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001

**COLUMBIA HICKS SITE 3 (Continued)** **U004148280**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: EJCALIFA
Last Modified: 11/12/2009

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Number: 003
Tank ID: 231565
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: EJCALIFA
Last Modified: 11/12/2009

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None

**COLUMBIA HICKS SITE 3 (Continued)** **U004148280**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Unregulated |
| Facility Id: | 2-611205 |
| Program Type: | PBS |
| UTM X: | 584540.52379000001 |
| UTM Y: | 4504678.6378499996 |
| Expiration Date: | N/A |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | Facility Owner |
| Company Name: | COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS) |
| Contact Type: | AUTHORIZED SIGNATORY |
| Contact Name: | LISA GOMEZ |
| Address1: | 185 PALMER AVE., SUITE 203 |
| Address2: | Not reported |
| City: | LARCHMONT |
| State: | YT |
| Zip Code: | 10538 |
| Country Code: | 001 |
| Phone: | (914) 833-3000 |
| EMail: | DKENYON@LMDEVPARTNERS.COM |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 11/12/2009 |

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | Mail Contact |
| Company Name: | COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS) |
| Contact Type: | AUTHORIZED SIGNATORY |
| Contact Name: | LISA GOMEZ |
| Address1: | 185 PALMER AVE., SUITE 203 |
| Address2: | Not reported |
| City: | LARCHMONT |
| State: | YT |
| Zip Code: | 10538 |
| Country Code: | 001 |
| Phone: | (914) 833-3000 |
| EMail: | DKENYON@LMDEVPARTNERS.COM |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 11/12/2009 |

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | On-Site Operator |
| Company Name: | COLUMBIA HICKS SITE 3 |
| Contact Type: | Not reported |
| Contact Name: | ED LINDH |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |

**COLUMBIA HICKS SITE 3 (Continued)** **U004148280**

| | |
|---|---|
| Phone: | (914) 833-3000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 11/12/2009 |

| | |
|---|---|
| Site Id: | 421739 |
| Affiliation Type: | Emergency Contact |
| Company Name: | COLUMBIA HICKS AFFORDABLE LLC (MULTIPLE OWNERS) |
| Contact Type: | Not reported |
| Contact Name: | DEBBIE KENYON |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (914) 833-3000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 11/12/2009 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 231563 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 2 |
| Tank Type: | Steel Tank in Concrete |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 1080 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | EJCALIFA |
| Last Modified: | 11/12/2009 |

**COLUMBIA HICKS SITE 3 (Continued)** **U004148280**

Material Name: #2 Fuel Oil (On-Site Consumption)

---

**U221** **211 VAN BRUNT (HURRICANE SANDY)** **NY SPILLS 90** **S112394975**
**SSW** **211 VAN BRUNT** **N/A**
**< 1/8** **RED HOOK, NY 11231**
**0.081 mi.**
**430 ft.** **Site 6 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

Spills:

| | |
|---|---|
| Status: | CLOSED |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| Site ID: | 1212250 |
| Secondary ID: | 475395 |
| Cross Street: | Not reported |
| County: | KINGS |
| Longitude: | 0 |
| Latitude: | 0 |
| Elevation: | Not reported |

---

**U222** **211 VAN BRUNT (HURRICANE SANDY)** **NY Spills** **S112807480**
**SSW** **211 VAN BRUNT** **N/A**
**< 1/8** **RED HOOK, NY 11231**
**0.081 mi.**
**430 ft.** **Site 7 of 7 in cluster U**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1212250 |
| Facility Type: | ER |
| DER Facility ID: | 430680 |
| Site ID: | 475395 |
| DEC Region: | 2 |
| Spill Date: | 10/29/2012 |
| Spill Number/Closed Date: | 1212250 / 11/14/2012 |
| Spill Cause: | Storm |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | Hurricane Sandy R2 |
| Referred To: | Not reported |
| Reported to Dept: | 11/16/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | DEC |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | Not reported |
| Date Entered In Computer: | 11/20/2012 |
| Spill Record Last Update: | 11/20/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | Not reported |

**211 VAN BRUNT (HURRICANE SANDY) (Continued)** **S112807480**

Spiller Company: Not reported
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.DEC Pumped out 250Gallons on 11/14/2012
Remarks: Not reported

Material:
Site ID: 475395
Operable Unit ID: 1225230
Operable Unit: 01
Material ID: 2228904
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: 250
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**T223** **CONSOLIDATED EDISON** **NY MANIFEST** **S109155670**
**ESE** **HICK ST & KANE ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.081 mi.**
**430 ft.** **Site 4 of 5 in cluster T**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

NY MANIFEST:
EPA ID: NYP004159893
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-07-22
Trans1 Recv Date: 2008-07-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-07-24
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004159893

**CONSOLIDATED EDISON (Continued)** **S109155670**

| | |
|---|---|
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | Not reported |
| Quantity: | 100.0 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2008 |
| Manifest Tracking Num: | 001433591FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2008-07-22 |
| Trans1 Recv Date: | 2008-07-22 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2008-07-24 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004159893 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | Not reported |
| Quantity: | 100.0 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2008 |
| Manifest Tracking Num: | 001433591FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |

**CONSOLIDATED EDISON (Continued)** **S109155670**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

---

**X224** **AT CONGRESS ST** **NY Spills** **S103482875**
**ENE** **SB LANE OF BQE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.082 mi.**
**432 ft.** **Site 16 of 16 in cluster X**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9804952 |
| Facility Type: | ER |
| DER Facility ID: | 257971 |
| Site ID: | 320193 |
| DEC Region: | 2 |
| Spill Date: | 7/21/1998 |
| Spill Number/Closed Date: | 9804952 / 7/21/1998 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 7/21/1998 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/21/1998 |
| Spill Record Last Update: | 7/23/1998 |
| Spiller Name: | Not reported |
| Spiller Company: | TRACTOR TRAILER |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | CAMERA ON BRIDGE RECORDED A TRACTOR TRAILER LEAKING DIESEL - PD, FD, & DEPT OF SANITATION ON SCENE - NOTIFICATION ONLY |

Material:

| | |
|---|---|
| Site ID: | 320193 |
| Operable Unit ID: | 1062868 |
| Operable Unit: | 01 |
| Material ID: | 319713 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |

**AT CONGRESS ST (Continued)** **S103482875**

| | |
|---|---|
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AB225** **ON SIDE WALK** **NY Spills** **S107787885**
**East** **HICKS ST & WARREN ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.082 mi.**
**432 ft.** **Site 2 of 5 in cluster AB**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0601287 |
| Facility Type: | ER |
| DER Facility ID: | 313659 |
| Site ID: | 363483 |
| DEC Region: | 2 |
| Spill Date: | 5/3/2006 |
| Spill Number/Closed Date: | 0601287 / 7/5/2006 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 5/3/2006 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/3/2006 |
| Spill Record Last Update: | 7/5/2006 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | WAIMAN WONG |
| Contact Phone: | (718) 595-4783 |
| DEC Memo: | 07/05/06 Rahman- Containers not found. |
| Remarks: | 10 1-GALLON CONTAINERS LEFT ON SIDEWALK. |

Material:

| | |
|---|---|
| Site ID: | 363483 |
| Operable Unit ID: | 1121537 |
| Operable Unit: | 01 |
| Material ID: | 2111033 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |

**ON SIDE WALK (Continued)** **S107787885**

| | |
|---|---|
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**R226** **EDR US Hist Auto Stat** **1015133362**
**South** **103 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.082 mi.**
**433 ft.** **Site 3 of 3 in cluster R**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | MENDOZA AUTO SALES & AUTO RPR |
| Year: | 2001 |
| Address: | 103 UNION ST |
| Name: | MENDOZA AUTO SALES & AUTO RPR |
| Year: | 2004 |
| Address: | 103 UNION ST |

---

**Q227** **LOT 52,TAXBLOCK 352** **NY E DESIGNATION** **S113496604**
**SSW** **55 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.084 mi.**
**446 ft.** **Site 5 of 5 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 52 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | VINCENT IACONA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000020250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520052 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982961 |
| Y Coordinate: | 0188034 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 52 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | VINCENT IACONA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000020250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520052 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982961 |
| Y Coordinate: | 0188034 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 52 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | VINCENT IACONA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000020250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520052 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982961 |
| Y Coordinate: | 0188034 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 52 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | VINCENT IACONA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 52,TAXBLOCK 352 (Continued)** **S113496604**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000020250 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520052 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982961 |
| Y Coordinate: | 0188034 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**AC228** **KAMMETAL** **FINDS** **1016396155**
**SSW** **60 SEABRING ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.085 mi.**
**450 ft.** **Site 1 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**7 ft.**

FINDS:

Registry ID: 110055299788

Environmental Interest/Information System

---

**AA229** **NYC DEP.** **NY Spills** **S102962028**
**SSE** **534 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.086 mi.**
**455 ft.** **Site 3 of 5 in cluster AA**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9711191 |
| Facility Type: | ER |
| DER Facility ID: | 179592 |
| Site ID: | 216906 |

**NYC DEP. (Continued)** **S102962028**

| | |
|---|---|
| DEC Region: | 2 |
| Spill Date: | 1/6/1998 |
| Spill Number/Closed Date: | 9711191 / 11/9/2005 |
| Spill Cause: | Unknown |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JMROMMEL |
| Referred To: | Not reported |
| Reported to Dept: | 1/6/1998 |
| CID: | 369 |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/6/1998 |
| Spill Record Last Update: | 11/9/2005 |
| Spiller Name: | ALBART GORDON |
| Spiller Company: | NYC DEP. |
| Spiller Address: | 534 HICKS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | ALBART GORDON |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"04/12/04TRANSFERRED FROM TIBBE TO ROMMEL.November 09 - 2005 - Jones - Closing spill. Contacted original reporter, problem no longer there. No spilled product ever discovered during original reporting and investigation of incident. |
| Remarks: | strong odor of gasoline at the dep building located above gas station at above adress. investigation ongoing no product discovered. caller states it as an ongoing problem. |

Material:

| | |
|---|---|
| Site ID: | 216906 |
| Operable Unit ID: | 1057693 |
| Operable Unit: | 01 |
| Material ID: | 325893 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AD230** **LOT 51,TAXBLOCK 352** **NY E DESIGNATION** **S113496603**
**South** **57 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.089 mi.**
**468 ft.** **Site 1 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 51 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VITOLA ANN |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

| | |
|---|---|
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000018900 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520051 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982970 |
| Y Coordinate: | 0187998 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 51 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

| | |
|---|---|
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VITOLA ANN |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000018900 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520051 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982970 |
| Y Coordinate: | 0187998 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

| | |
|---|---|
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| Tax Lot(s): | 51 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VITOLA ANN |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000018900 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520051 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982970 |
| Y Coordinate: | 0187998 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 51 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | Z9 |
| Land Use Category: | Not reported |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | VITOLA ANN |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000000 |
| Commercial Floor Area: | 00000000000 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00000 |
| Number of Floors: | 000.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00000 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0000.00 |
| Building Depth: | 0000.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000018000 |
| Total Assessed Value: | 00000018900 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 0000 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.00 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520051 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982970 |
| Y Coordinate: | 0187998 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 51,TAXBLOCK 352 (Continued)** **S113496603**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**W231** **EDR US Hist Auto Stat** **1015563017**
**South** **59 SUMMIT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.089 mi.**
**471 ft.** **Site 4 of 6 in cluster W**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Auto Stations:
Name: C & J AUTO REPAIR SERVICE
Year: 1999
Address: 59 SUMMIT ST

---

**W232** **AUTO WERK-AUTOBODY** **FINDS** **1006536041**
**South** **61 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.089 mi.**
**471 ft.** **Site 5 of 6 in cluster W**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

FINDS:

Registry ID: 110001616252

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**V233** **ROBSON SALES CORP** **NY AST** **U004076441**
**SSW** **120 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.090 mi.**
**475 ft.** **Site 17 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-095753
Program Type: PBS

**ROBSON SALES CORP (Continued)** **U004076441**

UTM X: 583991.63719000004
UTM Y: 4503923.3368300004
Expiration Date: 2007/05/07
Site Type: Other

Affiliation Records:

Site Id: 2671
Affiliation Type: Facility Owner
Company Name: ROBSON SALES CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 120 HAMILON AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231
Country Code: 001
Phone: (718) 624-7156
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/28/2008

Site Id: 2671
Affiliation Type: Mail Contact
Company Name: ROBSON SALES CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 120 HAMILTON AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11231
Country Code: 001
Phone: (718) 624-7156
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2671
Affiliation Type: On-Site Operator
Company Name: ROBSON SALES CORP
Contact Type: Not reported
Contact Name: ROBERT SLONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 624-7156
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/28/2008

Site Id: 2671

**ROBSON SALES CORP (Continued)** **U004076441**

| | |
|---|---|
| Affiliation Type: | Emergency Contact |
| Company Name: | ROBSON SALES CORP |
| Contact Type: | Not reported |
| Contact Name: | ROBERT SLONE |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 624-7156 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/28/2008 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 4563 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

| | |
|---|---|
| | A01 - Tank Internal Protection - Epoxy Liner |
| | C00 - Pipe Location - No Piping |
| | F00 - Pipe External Protection - None |
| | I04 - Overfill - Product Level Gauge (A/G) |
| | D01 - Pipe Type - Steel/Carbon Steel/Iron |
| | J02 - Dispenser - Suction Dispenser |
| | L09 - Piping Leak Detection - Exempt Suction Piping |
| | G03 - Tank Secondary Containment - Vault (w/o access) |
| | H00 - Tank Leak Detection - None |
| | B00 - Tank External Protection - None |
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 3000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

**V234** **ROBSON SALES CORP** **NY HIST AST** **U001832480**
**SSW** **120 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.090 mi.**
**475 ft.** **Site 18 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

HIST AST:

| | |
|---|---|
| PBS Number: | 2-095753 |
| SWIS Code: | 6101 |
| Operator: | ROBERT SLONE |
| Facility Phone: | (718) 624-7156 |
| Facility Addr2: | 120 HAMILTON AVENUE |
| Facility Type: | OTHER |
| Emergency: | ROBERT SLONE |
| Emergency Tel: | (718) 323-1448 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | ROBSON SALES CORP |
| Owner Address: | 120 HAMILON AVE |
| Owner City,St,Zip: | BROOKLYN, NY 11231 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 624-7156 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | Not reported |
| Mailing Name: | ROBSON SALES CORP |
| Mailing Address: | 120 HAMILON AVE |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Telephone: | (718) 624-7156 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 08/14/1997 |
| Expiration: | 05/07/2002 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 3000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |
| | |
| Tank ID: | 001 |
| Tank Location: | UNDERGROUND, VAULTED, WITH ACCESS |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 3000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |

**ROBSON SALES CORP (Continued)** **U001832480**

| | |
|---|---|
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 1 |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | Diking |
| Leak Detection: | 0 |
| Overfill Protection: | 4 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**V235** **EDR US Hist Auto Stat** **1015178111**
**SSW** **120 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.090 mi.**
**475 ft.** **Site 19 of 19 in cluster V**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | BROOKLYN AUTO BODY |
| Year: | 2000 |
| Address: | 120 HAMILTON AVE |
| Name: | BROOKLYN AUTO BODY |
| Year: | 2001 |
| Address: | 120 HAMILTON AVE |
| Name: | MALIBU AUTO COLLISION |
| Year: | 2002 |
| Address: | 120 HAMILTON AVE |

---

**AE236** **UNIVERSITY HOSPITAL OF BROOKLYN** **NY UST** **U000418028**
**NE** **70 ATLANTIC AVENUE** **NY AST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.090 mi.**
**475 ft.** **Site 1 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-348244 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2016/05/29 |
| UTM X: | 584557.99519000005 |
| UTM Y: | 4504983.6357199997 |
| Site Type: | Hospital/Nursing Home/Health Care |

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

Affiliation Records:

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | On-Site Operator |
| Company Name: | UNIVERSITY HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | NICK KAPASSAKIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-1847 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Emergency Contact |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Contact Type: | Not reported |
| Contact Name: | CHRIS YAKUBOFF |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Facility Owner |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 450 CLARKSON AVE |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11203 |
| Country Code: | 001 |
| Phone: | (718) 270-1234 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Mail Contact |
| Company Name: | UNIVERSITY HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | EAMON QUIRKE |

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

| | |
|---|---|
| Address1: | D/B/A DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Address2: | 339 HICKS STREET |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-2999 |
| EMail: | EAMON.QUIRKE@DOWNSTATE.EDU |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 241277 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 25000 |
| Install Date: | 07/01/1983 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 21 |
| Date Test: | 05/03/2011 |
| Next Test Date: | 05/03/2016 |
| Pipe Model: | Not reported |
| Modified By: | BKFALVEY |
| Last Modified: | 04/12/2013 |

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 241278 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 25000 |
| Install Date: | 07/01/1983 |
| Date Tank Closed: | Not reported |
| Registered: | True |

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 05/09/2011
Next Test Date: 05/09/2016
Pipe Model: Not reported
Modified By: BKFALVEY
Last Modified: 04/12/2013

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I02 - Overfill - High Level Alarm
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Number: 003-A
Tank ID: 241279
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 10/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/14/2011

Equipment Records:

J02 - Dispenser - Suction Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
K01 - Spill Prevention - Catch Basin
C03 - Pipe Location - Aboveground/Underground Combination
D11 - Pipe Type - Flexible Piping
F05 - Pipe External Protection - Jacketed
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 004
Tank ID: 93643
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 3500
Install Date: 09/01/1972
Date Tank Closed: 11/24/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 02/24/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LXZIELIN
Last Modified: 10/14/2011

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

Tank Number: 004-A
Tank ID: 93639
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 3000
Install Date: 11/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/14/2011

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

J02 - Dispenser - Suction Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
K01 - Spill Prevention - Catch Basin
C03 - Pipe Location - Aboveground/Underground Combination
F05 - Pipe External Protection - Jacketed
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-348244 |
| Program Type: | PBS |
| UTM X: | 584557.99519000005 |
| UTM Y: | 4504983.6357199997 |
| Expiration Date: | 2016/05/29 |
| Site Type: | Hospital/Nursing Home/Health Care |

Affiliation Records:

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | On-Site Operator |
| Company Name: | UNIVERSITY HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | NICK KAPASSAKIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-1847 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Emergency Contact |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Contact Type: | Not reported |
| Contact Name: | CHRIS YAKUBOFF |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Facility Owner |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 450 CLARKSON AVE |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11203 |
| Country Code: | 001 |
| Phone: | (718) 270-1234 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

| | |
|---|---|
| Site Id: | 17096 |
| Affiliation Type: | Mail Contact |
| Company Name: | UNIVERSITY HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | EAMON QUIRKE |
| Address1: | D/B/A DOWNSTATE AT LICH HOLDING COMPANY, INC. |
| Address2: | 339 HICKS STREET |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-2999 |
| EMail: | EAMON.QUIRKE@DOWNSTATE.EDU |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/14/2011 |

Tank Info:

| | |
|---|---|
| Tank Number: | 005 |
| Tank Id: | 241280 |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |

**UNIVERSITY HOSPITAL OF BROOKLYN (Continued)** **U000418028**

| | |
|---|---|
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 06/01/1977 |
| Capacity Gallons: | 1500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/14/2011 |
| Material Name: | Diesel |

---

**T237** **CON ED MANHOLE** **NY Spills** **S109206421**
**ESE** **HICKS ST & KANE ST INTERS** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.092 mi.**
**484 ft.** **Site 5 of 5 in cluster T**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0804565 |
| Facility Type: | ER |
| DER Facility ID: | 350733 |
| Site ID: | 401495 |
| DEC Region: | 2 |
| Spill Date: | 7/22/2008 |
| Spill Number/Closed Date: | 0804565 / 8/27/2008 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | gdbreen |
| Referred To: | Not reported |
| Reported to Dept: | 7/22/2008 |
| CID: | 78 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/22/2008 |
| Spill Record Last Update: | 8/27/2008 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDDISON |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | ERT DESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 8/27/08 - See eDocs for Con Ed report detailing cleanup and closure. |
| Remarks: | At spill time it wasn't reportable, but at 05:54 crews cleaning manhole discovered an open drain in the bottom of the stucture. 3 quarts spilled. there is not evidence that any of the oil went into the drain. Process of doing clean up now. No to the 5 questions at |

**CON ED MANHOLE (Continued)** **S109206421**

this time.

Material:

| | |
|---|---|
| Site ID: | 401495 |
| Operable Unit ID: | 1158283 |
| Operable Unit: | 01 |
| Material ID: | 2149339 |
| Material Code: | 0541A |
| Material Name: | DIELECTRIC FLUID |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AE238** **NYSDOT CONTRACT D254611** **RCRA NonGen / NLR** **1000990237**
**NE** **59 ATLANTIC AVE** **FINDS** **NYR000001966**
**< 1/8** **BROOKLYN, NY** **NY MANIFEST**
**0.093 mi.**
**491 ft.** **Site 2 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | NYSDOT CONTRACT D254611 |
| Facility address: | 59 ATLANTIC AVE<br>BROOKLYN, NY 11201 |
| EPA ID: | NYR000001966 |
| Mailing address: | 21ST ST<br>LONG ISLAND CITY, NY 11101 |
| Contact: | JOSEPH FARO |
| Contact address: | 21ST ST<br>LONG ISLAND CITY, NY 11101 |
| Contact country: | US |
| Contact telephone: | (718) 522-4619 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | NYSDOT |
| Owner/operator address: | 47-40 21ST ST<br>LONG ISLAND CITY, NY 11101 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 482-4790 |
| Legal status: | Municipal |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | NYSDOT |
| Owner/operator address: | 47-40 21ST ST |

**NYSDOT CONTRACT D254611 (Continued)** **1000990237**

LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 482-4790
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYSDOT CONTRACT D254611
Classification: Not a generator, verified

Date form received by agency: 08/20/1998
Facility name: NYSDOT CONTRACT D254611
Site name: NYS DEPT OF TRANSPORTATION
Classification: Large Quantity Generator

Date form received by agency: 03/20/1995
Facility name: NYSDOT CONTRACT D254611
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110009484003

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000001966

**NYSDOT CONTRACT D254611 (Continued)** **1000990237**

| | |
|---|---|
| Country: | USA |
| Mailing Name: | NYSDOT - CONTRACT D254611 |
| Mailing Contact: | JOSEPH FARO |
| Mailing Address: | 47-40 21ST ST |
| Mailing Address 2: | Not reported |
| Mailing City: | LONG ISLAND CITY |
| Mailing State: | NY |
| Mailing Zip: | 11101 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-522-4619 |

| | |
|---|---|
| Document ID: | NJA2747601 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | S6993 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 970606 |
| Trans1 Recv Date: | 970606 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 970606 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 970624 |
| Generator EPA ID: | NYR000001966 |
| Trans1 EPA ID: | NJD980772768 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 22000 |
| Units: | P - Pounds |
| Number of Containers: | 044 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 97 |

---

**AD239** **LOT 50,TAXBLOCK 352** **NY E DESIGNATION** **S113496602**
**South** **59 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.093 mi.**
**492 ft.** **Site 2 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 50 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | DELFINO ANTHONY A |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1978 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982999 |
| Y Coordinate: | 0188021 |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 50 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | DELFINO ANTHONY A |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1978 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982999 |
| Y Coordinate: | 0188021 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 50 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | DELFINO ANTHONY A |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1978 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982999 |
| Y Coordinate: | 0188021 |
| Zoning Map: | 16A |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 50 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | DELFINO ANTHONY A |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |

**LOT 50,TAXBLOCK 352 (Continued)** **S113496602**

| | |
|---|---|
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1978 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520050 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0982999 |
| Y Coordinate: | 0188021 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**AF240** **RED HOOK MARINE TERMINAL** **NY Spills** **S103568927**
**SW** **CONOVER STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.096 mi.**
**505 ft.** **Site 1 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9513092 |
| Facility Type: | ER |
| DER Facility ID: | 148193 |
| Site ID: | 176319 |
| DEC Region: | 2 |
| Spill Date: | 1/19/1996 |
| Spill Number/Closed Date: | 9513092 / 8/14/1996 |
| Spill Cause: | Other |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |

**RED HOOK MARINE TERMINAL (Continued)** **S103568927**

| | |
|---|---|
| SWIS: | 2401 |
| Investigator: | GUTIERREZ |
| Referred To: | Not reported |
| Reported to Dept: | 1/19/1996 |
| CID: | 267 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | DEC |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/19/1996 |
| Spill Record Last Update: | 8/14/1996 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | JACK DONAHUE |
| Contact Phone: | (718) 875-0777 239 |
| DEC Memo: | Not reported |
| Remarks: | container failed with phosporosis pentachloridereacting with rainwater uscg may federalize clean upneed call back to po doug adams at 212-668-7920may run into alantic basin |

Material:

| | |
|---|---|
| Site ID: | 176319 |
| Operable Unit ID: | 1024082 |
| Operable Unit: | 01 |
| Material ID: | 566911 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AF241** **CONTAINMENT VESSEL** **NY Spills** **S102144293**
**SW** **REDHOOK UNIVERSAL TERMIN.** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.096 mi.**
**505 ft.** **Site 2 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8605954 |
| Facility Type: | ER |
| DER Facility ID: | 158256 |
| Site ID: | 189628 |
| DEC Region: | 2 |

**CONTAINMENT VESSEL (Continued)** **S102144293**

| | |
|---|---|
| Spill Date: | 12/18/1986 |
| Spill Number/Closed Date: | 8605954 / 12/19/1986 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 12/19/1986 |
| CID: | Not reported |
| Water Affected: | BUTTER MILK CHANNEL |
| Spill Source: | Vessel |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 12/19/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/12/1987 |
| Spill Record Last Update: | 6/1/1987 |
| Spiller Name: | Not reported |
| Spiller Company: | REDHOOK UNIVERSAL TERMIN. |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "10/10/95: This is additional information about material spilled from the translation of the old spill file: LUBRICATION OIL. |
| Remarks: | GREEK CONTAINER VESSEL - FAULTY SEAL AROUND PROPELLAR SHAFT. SHEEN ONWATER SURFACE. U.S.C.G. ON THE SCENE |

Material:

| | |
|---|---|
| Site ID: | 189628 |
| Operable Unit ID: | 903324 |
| Operable Unit: | 01 |
| Material ID: | 475095 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AF242** **RED HOOK TERMINAL** **NY Spills** **S102143841**
**SW** **RED HOOK TERMINAL-PIER II** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.096 mi.**
**505 ft.** **Site 3 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9306442 |
| Facility Type: | ER |
| DER Facility ID: | 276564 |
| Site ID: | 248988 |
| DEC Region: | 2 |
| Spill Date: | 8/25/1993 |
| Spill Number/Closed Date: | 9306442 / 8/26/1993 |
| Spill Cause: | Human Error |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 8/25/1993 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Other |
| Cleanup Ceased: | 8/26/1993 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/30/1993 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NN |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG" |
| Remarks: | CREW MEMBER DROPPED PAINT INTO WATER - WATER DILUTED PAINT NO ACTIONS TAKEN - NONE TO BE TAKEN NCB. NO ACTION FROM DEC. |

Material:

| | |
|---|---|
| Site ID: | 248988 |
| Operable Unit ID: | 987692 |
| Operable Unit: | 01 |
| Material ID: | 396311 |
| Material Code: | 0055A |
| Material Name: | PAINT |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**RED HOOK TERMINAL (Continued)** **S102143841**

Tank Test:

| | |
|---|---|
| Facility ID: | 9213470 |
| Facility Type: | ER |
| DER Facility ID: | 65252 |
| Site ID: | 68523 |
| DEC Region: | 2 |
| Spill Date: | 3/5/1993 |
| Spill Number/Closed Date: | 9213470 / 11/23/1994 |
| Spill Cause: | Human Error |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR) |
| SWIS: | 2401 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 3/5/1993 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 11/23/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/10/1993 |
| Spill Record Last Update: | 11/23/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | MOVING PALLET CONTAINING MERCURY - SOME SPILLED ON PIER - NYSHO ON SCENE - NOTIF. NYCFD - NRC CONTRACTS COMING TO CLEAN-UP - NO CALL BACK Not reported |

Material:

Tank Test:

---

**AF243** **THIMET,BKLYN TERMINAL** **NY Spills** **S102144149**
**SW** **REDHOOK TERMINAL** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.096 mi.**
**505 ft.** **Site 4 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8604187 |
| Facility Type: | ER |
| DER Facility ID: | 131511 |
| Site ID: | 155165 |

**THIMET,BKLYN TERMINAL (Continued)** **S102144149**

| | |
|---|---|
| DEC Region: | 2 |
| Spill Date: | 9/26/1986 |
| Spill Number/Closed Date: | 8604187 / 9/30/1986 |
| Spill Cause: | Unknown |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 9/29/1986 |
| CID: | Not reported |
| Water Affected: | UPPER NEW YORK HAR. |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | 9/30/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/7/1986 |
| Spill Record Last Update: | 10/10/1986 |
| Spiller Name: | Not reported |
| Spiller Company: | UNIVERSAL MARITIME SER. |
| Spiller Address: | SAME |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | 4 -55 GAL DRUMS - ONE IS LEAKING |

Material:

| | |
|---|---|
| Site ID: | 155165 |
| Operable Unit ID: | 901101 |
| Operable Unit: | 01 |
| Material ID: | 477008 |
| Material Code: | 0630A |
| Material Name: | NONENE |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 55 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AF244** **BERTH 1 AND 2 AT RED HOOK** **NY Spills** **S102144732**
**SW** **BERTH 1 AND 2/RED HOOK** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.096 mi.**
**505 ft.** **Site 5 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8704433 |
| Facility Type: | ER |
| DER Facility ID: | 229350 |
| Site ID: | 282507 |
| DEC Region: | 2 |
| Spill Date: | 8/27/1987 |
| Spill Number/Closed Date: | 8704433 / 8/28/1987 |
| Spill Cause: | Unknown |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 8/27/1987 |
| CID: | Not reported |
| Water Affected: | BUTTERMILL CHANNEL |
| Spill Source: | Vessel |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 8/28/1987 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/8/1987 |
| Spill Record Last Update: | 3/31/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | USCG EXPECTS TO SEND TEAM TO INVESTIGATE SPILL FROM UNKNOWN CRANE BARGE. |

Material:

| | |
|---|---|
| Site ID: | 282507 |
| Operable Unit ID: | 908218 |
| Operable Unit: | 01 |
| Material ID: | 467072 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**BERTH 1 AND 2 AT RED HOOK (Continued)** **S102144732**

Tank Test:

---

**AF245** **RED HOOK TERM BERTH 1 & 2** **NY Spills** **S102143046**
**SW** **RED HOOK TERMINALS** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.096 mi.**
**505 ft.** **Site 6 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9203673 |
| Facility Type: | ER |
| DER Facility ID: | 111187 |
| Site ID: | 128930 |
| DEC Region: | 2 |
| Spill Date: | 6/29/1992 |
| Spill Number/Closed Date: | 9203673 / 6/29/1992 |
| Spill Cause: | Unknown |
| Spill Class: | Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 6/29/1992 |
| CID: | Not reported |
| Water Affected: | BUTTERMILK CHANNEL |
| Spill Source: | Vessel |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 6/29/1992 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/30/1992 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | "TORMSP" YUGOSLAVIAN SHIP |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG" |
| Remarks: | USCG SUPERVISING CLEANUP BY MPC CONTRACTORS. |

Material:

| | |
|---|---|
| Site ID: | 128930 |
| Operable Unit ID: | 971071 |
| Operable Unit: | 01 |
| Material ID: | 411455 |
| Material Code: | 0003A |
| Material Name: | #6 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |

**RED HOOK TERM BERTH 1 & 2 (Continued)** **S102143046**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AE246**
**ENE**
**< 1/8**
**0.096 mi.**
**508 ft.**

**PEDRO'S WORK CORP** **FINDS** **1007795509**
**34-43 ATLANTIC AVENUE** **N/A**
**BROOKLYN, NY**

**Site 3 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

FINDS:

Registry ID: 110019580185

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**W247**
**South**
**< 1/8**
**0.098 mi.**
**515 ft.**

**40 CARROL STREET** **ERNS** **89133665**
**BROOKLYN, NY** **N/A**

**Site 6 of 6 in cluster W**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

**AD248**
**South**
**< 1/8**
**0.098 mi.**
**515 ft.**

**LOT 49,TAXBLOCK 352** **NY E DESIGNATION** **S113496601**
**61 SUMMIT STREET** **N/A**
**BROOKLYN, NY 11231**

**Site 3 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 49 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | IACONA ANNA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520049 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983007 |
| Y Coordinate: | 0187982 |
| Zoning Map: | 16A |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 49 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | IACONA ANNA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520049 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983007 |
| Y Coordinate: | 0187982 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 49 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | IACONA ANNA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520049 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983007 |
| Y Coordinate: | 0187982 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| | |
| Tax Lot(s): | 49 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | K1 |
| Land Use Category: | 05 |
| Number of Easements: | 0 |
| Owner, Type of Code: | P |
| Owner Name: | IACONA ANNA |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000001080 |
| Commercial Floor Area: | 00000001080 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000001080 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000000 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |

**LOT 49,TAXBLOCK 352 (Continued)** **S113496601**

| | |
|---|---|
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0054.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000013050 |
| Total Assessed Value: | 00000033660 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.54 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520049 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983007 |
| Y Coordinate: | 0187982 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

---

**AA249** **TENEMENT BLDG** **NY Spills** **S106008708**
**SSE** **509 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.099 mi.**
**525 ft.** **Site 4 of 5 in cluster AA**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0207701 |
| Facility Type: | ER |
| DER Facility ID: | 264457 |
| Site ID: | 328603 |
| DEC Region: | 2 |
| Spill Date: | 10/24/2002 |
| Spill Number/Closed Date: | 0207701 / 10/25/2002 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |

**TENEMENT BLDG (Continued)** **S106008708**

| | |
|---|---|
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 10/24/2002 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/24/2002 |
| Spill Record Last Update: | 11/13/2002 |
| Spiller Name: | UNKNOWN |
| Spiller Company: | UNKNOWN |
| Spiller Address: | UNKNOWN |
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | RYAN THOMPSON |
| Contact Phone: | (917) 697-7303 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"10/24/2002. J.Krimgold @ site. Construction materials (paint, paint thinners, lacquers, etc.) are stored in the basement in sealed and unsealed manufacturer labeled containers and used for the apartment renovation in the building. Non of these materials are spilled. However, a strong odor of paint and similar chemicals throughout the building. Talked to Ryan Thompson via phone and recommend to ventilate his apartment by opening windows and use fans. |
| Remarks: | CALLER STATES IT APPEARS THAT DRUMS OF UNK MATERIAL ARE BEING KEPT IN APARTMENT BLDG'S BASEMENT. THERE IS A STRONG ODOR COMINGFROM SAME. SOME OF IT MAY BE PAINT AND POLYURETHENE. |

Material:

| | |
|---|---|
| Site ID: | 328603 |
| Operable Unit ID: | 860563 |
| Operable Unit: | 01 |
| Material ID: | 514712 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AG250**
**South**
**< 1/8**
**0.100 mi.**
**530 ft.**

**100 UNION ST**
**BROOKLYN, NY 11231**

**Site 1 of 5 in cluster AG**

**EDR US Hist Auto Stat** **1015118694**
**N/A**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | AUTO REPAIR SPECIALIST |
| Year: | 2001 |
| Address: | 100 UNION ST |

---

**AE251**
**ENE**
**< 1/8**
**0.101 mi.**
**535 ft.**

**TRI COUNTY DIAGNOSTICS LABS**
**25-78 ATLANTIC AVE**
**BROOKLYN, NY 11207**

**Site 4 of 20 in cluster AE**

**NY MANIFEST** **1009232924**
**N/A**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000901306 |
| Country: | USA |
| Mailing Name: | TRI COUNTY DIAGNOSTICS LABS |
| Mailing Contact: | RIAZ HUSSEIN |
| Mailing Address: | 25-78 ATLANTIC AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11207 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 516-937-1617 |

| | |
|---|---|
| Document ID: | NJA1021295 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | S5811 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910403 |
| Trans1 Recv Date: | 910403 |
| Trans2 Recv Date: | 910404 |
| TSD Site Recv Date: | 910404 |
| Part A Recv Date: | 910415 |
| Part B Recv Date: | 910418 |
| Generator EPA ID: | NYP000901306 |
| Trans1 EPA ID: | NJD982281016 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | D009 - MERCURY 0.2 MG/L TCLP |
| Quantity: | 00041 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00032 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |

**TRI COUNTY DIAGNOSTICS LABS (Continued)** **1009232924**

| | |
|---|---|
| Waste Code: | Not reported |
| Quantity: | 00001 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00001 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NJA1021294 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | S5811 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910403 |
| Trans1 Recv Date: | 910403 |
| Trans2 Recv Date: | 910404 |
| TSD Site Recv Date: | 910404 |
| Part A Recv Date: | 910415 |
| Part B Recv Date: | 910418 |
| Generator EPA ID: | NYP000901306 |
| Trans1 EPA ID: | NJD982281016 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Waste Code: | Not reported |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 91 |

---

**AG252** **113-115 UNION STREET BUILDING** **US AIRS** **1014816930**
**South** **113-115 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.102 mi.**
**536 ft.** **Site 2 of 5 in cluster AG**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110019726126 |

**113-115 UNION STREET BUILDING (Continued)** **1014816930**

| | |
|---|---|
| Plant name: | 113-115 UNION STREET BUILDING |
| Plant address: | 113-115 UNION ST<br>BROOKLYN, NY 11231 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 6513 |
| Sic code desc: | Not reported |
| North Am. industrial classf: | 531110 |
| NAIC code description: | Lessors of Residential Buildings and Dwellings |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | Not reported |
| National action type: | Not reported |
| Date achieved: | Not reported |
| Penalty amount: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1103 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1202 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1204 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1303 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1004 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1102 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1104 |
| Air prog code hist file: | SIP SOURCE |

**113-115 UNION STREET BUILDING (Continued)** **1014816930**

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**AG253** **113-115 UNION STREET BUILDING** **FINDS** **1016122402**
**South** **113-115 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.102 mi.**
**536 ft.** **Site 3 of 5 in cluster AG**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

FINDS:

Registry ID: 110040834014

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

**AD254** **LOT 48,TAXBLOCK 352** **NY E DESIGNATION** **S113496600**
**South** **63 SUMMIT STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.102 mi.**
**539 ft.** **Site 4 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

E DESIGNATION:

| | |
|---|---|
| Tax Lot(s): | 48 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Air Quality - # 2 Fuel Oil or # 4 Fuel Oil or Natural Gas for HVAC systems |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | FORMISANO LOUIS |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000700 |
| Commercial Floor Area: | 00000000700 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000700 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0035.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

| | |
|---|---|
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000012600 |
| Total Assessed Value: | 00000016920 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.35 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520048 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983037 |
| Y Coordinate: | 0188008 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 48 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Exhaust stack location limitations |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

| | |
|---|---|
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | FORMISANO LOUIS |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000700 |
| Commercial Floor Area: | 00000000700 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000700 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0035.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000012600 |
| Total Assessed Value: | 00000016920 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.35 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520048 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983037 |
| Y Coordinate: | 0188008 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

| | |
|---|---|
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |
| Tax Lot(s): | 48 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Hazardous Materials* Phase I and Phase II Testing Protocol |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | FORMISANO LOUIS |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000700 |
| Commercial Floor Area: | 00000000700 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000700 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0035.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

| | |
|---|---|
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000012600 |
| Total Assessed Value: | 00000016920 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.35 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520048 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983037 |
| Y Coordinate: | 0188008 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |
| Date of Mass Appraisal Data: | 11/2005 |
| Date of Political and Adm Data: | 08/2005 |
| Pluto-Base Map Indicator: | 1 |

| | |
|---|---|
| Tax Lot(s): | 48 |
| E-No: | E-202 |
| Effective Date: | 10/29/2007 |
| Satisfaction Date: | Not reported |
| Ceqr Number: | 06DCP095K |
| Ulurp Number: | 060477ZMK |
| Zoning Map No: | 16a |
| Description: | Window Wall Attenuation & Alternate Ventilation |
| Borough Code: | BK |
| Community District: | 306 |
| Census Tract: | 51 |
| Census Block: | 3003 |
| School District: | 15 |
| City Council District: | 39 |
| Fire Company: | E202 |
| Health Area: | 38 |
| Police Precinct: | 076 |
| Zone District 1: | M1-1 |
| Zone District 2: | Not reported |
| Commercial Overlay1: | Not reported |
| Commercial Overlay2: | Not reported |
| Special Purpose District1: | Not reported |
| Special Purpose District2: | Not reported |
| All Components1: | M1-1 |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

| | |
|---|---|
| All Components2: | Not reported |
| Split Boundary Indicator: | N |
| Building Class: | G9 |
| Land Use Category: | 07 |
| Number of Easements: | 0 |
| Owner, Type of Code: | Not reported |
| Owner Name: | FORMISANO LOUIS |
| Lot Area: | 000002000 |
| Total Building Floor Area: | 00000000700 |
| Commercial Floor Area: | 00000000700 |
| Office Floor Area: | 00000000000 |
| Retail Floor Area: | 00000000000 |
| Garage Floor Area: | 00000000000 |
| Storage Floor Area: | 00000000000 |
| Factory Floor Area: | 00000000000 |
| Other Floor Area: | 00000000700 |
| Floor Area,Total Bld Source Code: | 7 |
| Number of Buildings: | 00001 |
| Number of Floors: | 001.00 |
| Residential Units: | 00000 |
| Non and Residential Units: | 00001 |
| Lot Frontage: | 0020.00 |
| Lot Depth: | 0100.00 |
| Building Frontage: | 0020.00 |
| Building Depth: | 0035.00 |
| Proximity Code: | 0 |
| Irregular Lot Code: | N |
| Lot Type: | 5 |
| Basement Type Grade: | 5 |
| Land Assessed Value: | 00000012600 |
| Total Assessed Value: | 00000016920 |
| Land Exempt Value: | 00000000000 |
| Total Exempt Value: | 00000000000 |
| Year Built: | 1931 |
| Year Built Code: | Not reported |
| Year Altered1: | 0000 |
| Year Altered2: | 0000 |
| Historic District Name: | Not reported |
| Landmark Name: | Not reported |
| Built Floor Area Ratio-Far: | 0000.35 |
| Maximum Allowable Far: | 01.00 |
| Borough Code: | 3 |
| Borough Tax Block And Lot: | 3003520048 |
| Condominium Number: | 00000 |
| Census Tract 2: | 0051 |
| X Coordinate: | 0983037 |
| Y Coordinate: | 0188008 |
| Zoning Map: | 16A |
| Sanborn Map: | 301 022 |
| Tax Map: | 30202 |
| E Designation No: | Not reported |
| Date of RPAD Data: | 11/2005 |
| Date of DCAS Data: | 01/2006 |
| Date of Zoning Data: | 11/2005 |
| Date of Major Property Data: | 11/2005 |
| Date of Landmark Data: | 12/2005 |
| Date of Base Map Data: | 01/2006 |

**LOT 48,TAXBLOCK 352 (Continued)** **S113496600**

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

---

**AE255** **AMITY HOSPITAL** **NY Spills** **S106125705**
**ENE** **336 HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.102 mi.**
**540 ft.** **Site 5 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0312265 |
| Facility Type: | ER |
| DER Facility ID: | 262375 |
| Site ID: | 325720 |
| DEC Region: | 2 |
| Spill Date: | 2/4/2004 |
| Spill Number/Closed Date: | 0312265 / 12/27/2004 |
| Spill Cause: | Human Error |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 2/4/2004 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/4/2004 |
| Spill Record Last Update: | 1/13/2005 |
| Spiller Name: | LAMBERT - HEAD ENGINEER |
| Spiller Company: | AMITY HOSPITAL |
| Spiller Address: | 336 HICKS STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | TONY PERETTA |
| Contact Phone: | (718) 932-9075 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"2/4/2004 Sangesland spoke to Tony Peretta at Mystic Transportion (718-932-9075 x 275). He says there was a 40 gal spill of #2 fuel oil mostly outside in dirt/snow. A small amount spilled in the basement. A.L.Eastmond was called to the site with a vac truck and a cleanup crew.Head Engineer at the facility is "Lambert" 718-780-1726Issac at Eastmond called back to say the spill is approx 100 gallons and he's calling in an excavator to the site tonight.2/4/04 TJDSite inspection. All impacts outside in courtyard. Mystic hooked up to wrong tank. Eastmond Tank Cleaners performing cleanup. Contaminated soils excavated and disposed of under manifest. Endpoint sampling required. Awaiting analytical report.12/27/04 TJDDemeo repatedly contacted by Styvesant fuel over recent weeks request closure. DeMeo told Stuvesant closure was not possible until |

**AMITY HOSPITAL (Continued)** **S106125705**

all required documents in support of closure were submiited to DEC, including: manifests and endpoint sampling data.Eastmond was directed to return to site to collect endpoint samples. A total of (4) soil samples were collected. Raw Laboratory Data Sheets submitted to DEC for review. All analytes within acceptable range. No further action required. Spill closed.

Remarks: ENGINEER DIRECTOR DRIVER TO WRONG TANK, ALMOST ALL CLEANED UP: NO SEWER

Material:

| | |
|---|---|
| Site ID: | 325720 |
| Operable Unit ID: | 879733 |
| Operable Unit: | 01 |
| Material ID: | 497490 |
| Material Code: | 0002A |
| Material Name: | #4 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 40 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AE256** **HMIRS** **2004040286**
**ENE** **336 HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.102 mi.**
**540 ft.** **Site 6 of 20 in cluster AE**

**Relative:**
**Higher**

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

**Actual:**
**33 ft.**

---

**AB257** **COBBLE HILL TOWERS APT #1E** **NY Spills** **S108295334**
**East** **423 HICKS STREET** **N/A**
**< 1/8** **NEW YORK CITY, NY**
**0.102 mi.**
**541 ft.** **Site 3 of 5 in cluster AB**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0608438 |
| Facility Type: | ER |
| DER Facility ID: | 322133 |
| Site ID: | 372405 |
| DEC Region: | 2 |
| Spill Date: | 10/23/2006 |
| Spill Number/Closed Date: | 0608438 / 1/15/2009 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JBVOUGHT |
| Referred To: | Not reported |
| Reported to Dept: | 10/23/2006 |

**COBBLE HILL TOWERS APT #1E (Continued)** **S108295334**

| | |
|---|---|
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/23/2006 |
| Spill Record Last Update: | 1/15/2009 |
| Spiller Name: | LANDLORD FRANK |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 001 |
| Contact Name: | BRAIN MICHELS |
| Contact Phone: | (917) 226-0099 |
| DEC Memo: | Sangesland left a voice message on Mr. Brian Michael's phone asking for more info and contact info for "Landlord Frank".01/15/09-Vought-Left message with Brian that due to age of spill and fact that caller only reported small puddle on floor that case would be closed. Vought called owner as per PBS and spoke to Roberta Mercury who confirmed that spill was on concrete and was cleaned using absorbent material. Spill closed by Vought. |
| Remarks: | it smells like oil and a small puddle on base ment floor; says it may just need better ventilastion in basement; not yet cleaned or contained; |

Material:

| | |
|---|---|
| Site ID: | 372405 |
| Operable Unit ID: | 1130147 |
| Operable Unit: | 01 |
| Material ID: | 2119816 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AF258** **MANHOLE #5779** **NY Spills** **S106469099**
**SSW** **IMLEY ST / COMMERCE ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**543 ft.** **Site 7 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0401666 |
| Facility Type: | ER |
| DER Facility ID: | 153144 |
| Site ID: | 182801 |
| DEC Region: | 2 |
| Spill Date: | 5/15/2004 |
| Spill Number/Closed Date: | 0401666 / 5/17/2004 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 5/16/2004 |
| CID: | 73 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/16/2004 |
| Spill Record Last Update: | 5/17/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | ERT DESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"e2mis no. 153407:FOUND APPROX 1-PINT OF UNKNOWN OIL ON 200 GALLONS WATER, IT APPEARS TO BE CONTAINED AT THIS TIME. CLEANUP PENDING TEST RESULT.LAB SEQ# 04-03752 PCB 2 PPM5/16/04 P. ROSADO, ENV. OPS., REPORTS AN EARTHEN SUMP IN THE STRUCTURE.UPDATE: 5/16/04 - 09:00P. ROSADO, ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP CEMENTED. |
| Remarks: | 1 PINT OF UNKNOWN OIL ON 200 GALS OF WATER IN MANHOLE. NO TO ALL 5 QUESTIONS.THIS SPILL IS COMING OFF THE 24 PROGRAM DUE TO THE "UNAVAILABILITY OF A TANKER".5/16 08:37 Update - Earthin sump is in the manhole. |

Material:

| | |
|---|---|
| Site ID: | 182801 |
| Operable Unit ID: | 885551 |
| Operable Unit: | 01 |
| Material ID: | 559913 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |

**MANHOLE #5779 (Continued)** **S106469099**

Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AE259** **69TH STREET** **NY Spills** **S102146982**
**NE** **69TH STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 7 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

SPILLS:
Facility ID: 9307124
Facility Type: ER
DER Facility ID: 120979
Site ID: 141712
DEC Region: 2
Spill Date: 9/11/1993
Spill Number/Closed Date: 9307124 / 3/31/1995
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 9/11/1993
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: 3/31/1995
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/26/1994
Spill Record Last Update: 3/31/1995
Spiller Name: Not reported
Spiller Company: WPCP
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"10/10/95: This is additional information about material spilled from the translation of the old spill file: 7 MILL.
Remarks: REFERED TO SPDES

Material:
Site ID: 141712
Operable Unit ID: 985578
Operable Unit: 01

**69TH STREET (Continued)** **S102146982**

| | |
|---|---|
| Material ID: | 393396 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**Y260** **COBBLE HILL TOWERS ASSOC** **NY AST** **U003388398**
**ESE** **439 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.103 mi.**
**546 ft.** **Site 20 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-275638 |
| Program Type: | PBS |
| UTM X: | 584550.96325000003 |
| UTM Y: | 4504530.7113500005 |
| Expiration Date: | 2017/07/10 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 11827 |
| Affiliation Type: | Facility Owner |
| Company Name: | COBBLE HILL TOWERS ASSOC |
| Contact Type: | GEN. PARTNER |
| Contact Name: | FRANK FARELLA |
| Address1: | 431 HICKS ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 522-1283 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 3/20/2007 |

| | |
|---|---|
| Site Id: | 11827 |
| Affiliation Type: | Mail Contact |
| Company Name: | COBBLE HILL TOWERS ASSOC |
| Contact Type: | GEN. PARTNER |
| Contact Name: | FRANK FARELLA |
| Address1: | 431 HICKS ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |

**COBBLE HILL TOWERS ASSOC (Continued)** **U003388398**

| | |
|---|---|
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 522-1283 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | EJCALIFA |
| Date Last Modified: | 3/20/2007 |

| | |
|---|---|
| Site Id: | 11827 |
| Affiliation Type: | On-Site Operator |
| Company Name: | COBBLE HILL TOWERS ASSOC |
| Contact Type: | Not reported |
| Contact Name: | COBBLE HILL TOWERS ASSOC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 858-3050 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 11827 |
| Affiliation Type: | Emergency Contact |
| Company Name: | COBBLE HILL TOWERS ASSOC |
| Contact Type: | Not reported |
| Contact Name: | ROBERTO SANTOS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (646) 235-9491 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 13880 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

**COBBLE HILL TOWERS ASSOC (Continued)** **U003388398**

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 12/01/1975 |
| Capacity Gallons: | 3000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

---

**Y261** **APART** **NY Spills** **S108466336**
**ESE** **439 HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 21 of 21 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0612892 |
| Facility Type: | ER |
| DER Facility ID: | 327396 |
| Site ID: | 377838 |
| DEC Region: | 2 |
| Spill Date: | 3/1/2007 |
| Spill Number/Closed Date: | 0612892 / 3/9/2007 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | hrpatel |
| Referred To: | Not reported |
| Reported to Dept: | 3/1/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/1/2007 |
| Spill Record Last Update: | 3/9/2007 |
| Spiller Name: | CHEDA |
| Spiller Company: | APART |
| Spiller Address: | 439 HICKS STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |

**APART (Continued)** **S108466336**

Contact Name: CHEDA
Contact Phone: (646) 235-8398
DEC Memo: As per Cheda, minor spray from broken gauge. PTC has sent authorization to be signed and awaiting signiature. Tank is a 35oo gal.03/09/07-Hiralkumar Patel. spoke with Ray Lara at PTC. they found oil stain near boiler. oil leaked from valve on boiler. oil spilled on concrete floor. no soil/drain affected.all cleaned up. case closed. Not reported
Remarks: A VALVE BROKE AT ABOVE ADDRESS AND RAY LARA ENROUTE TO CLEAN UP:

Material:
Site ID: 377838
Operable Unit ID: 1135356
Operable Unit: 01
Material ID: 2125254
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AB262** **COBBLE HILL TOWERS CONDOMINIUM** **NY AST** **U003390100**
**East** **423 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.103 mi.**
**546 ft.** **Site 4 of 5 in cluster AB**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-310425
Program Type: PBS
UTM X: 584574.93951000005
UTM Y: 4504589.3575299997
Expiration Date: 2016/10/03
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 14190
Affiliation Type: On-Site Operator
Company Name: COBBLE HILL TOWERS CONDOMINIUM
Contact Type: Not reported
Contact Name: COBBLE HILL TOWERS ASSOC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 858-3050

**COBBLE HILL TOWERS CONDOMINIUM (Continued)** **U003390100**

EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 11/14/2012

Site Id: 14190
Affiliation Type: Emergency Contact
Company Name: COBBLE HILL TOWERS CONDOMINIUM
Contact Type: Not reported
Contact Name: ROBERTO SANTOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 235-9491
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 11/14/2012

Site Id: 14190
Affiliation Type: Facility Owner
Company Name: COBBLE HILL TOWERS CONDOMINIUM
Contact Type: PROPERTY MGR
Contact Name: ED STROSSER
Address1: 417 HICKS ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 522-1283
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 11/14/2012

Site Id: 14190
Affiliation Type: Mail Contact
Company Name: COBBLE HILL TOWERS CONDO
Contact Type: Not reported
Contact Name: LISA MGMT
Address1: 423 HICKS ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 522-1283
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 11/14/2012

**COBBLE HILL TOWERS CONDOMINIUM (Continued)** **U003390100**

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 18339 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 12/01/1975 |
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

---

**AH263** **VAULT 7211** **NY Spills** **S106017951**
**ENE** **AMITY ST/HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 1 of 3 in cluster AH**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0306081 |
| Facility Type: | ER |
| DER Facility ID: | 259935 |
| Site ID: | 322659 |
| DEC Region: | 2 |
| Spill Date: | 9/9/2003 |
| Spill Number/Closed Date: | 0306081 / 10/15/2003 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required. |
| SWIS: | 2401 |
| Investigator: | SKARAKHA |
| Referred To: | Not reported |
| Reported to Dept: | 9/9/2003 |
| CID: | 246 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |

**VAULT 7211 (Continued)** **S106017951**

| | |
|---|---|
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/9/2003 |
| Spill Record Last Update: | 10/27/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | E2MIS 150254V.DINEEN #41974 BQ EQUIPMENT ON LOCATION TO REPAIR SWITCH IN V-7211 REPORTS FINDING THAT TRANSFORMER LEAKED APPROX 0 GALLONS OF DIELECTRIC FLUID ONTO DIRT IN BOTTOM OF STRUCTURE. NO SEWERS OR WATERWAYS APPEAR AFFECTED, NO FIRE OR SMOKE INVOLVED, NO INJURIES OR PRIVATE PROPERTY INVOLVED. SEES WEEP HOLES IN WALL OF STRUCTURE TO ADJOINING BUS COMPARTMENT, NO SIGNS OF OIL IN THAT STRUCTURE. HISTORICAL DATA INDICATES 10 PPM PCB. AREA MADESAFE. PLACED TAG #366.UNABLE TO SAMPLE STRUCTURE AT THIS TIME TRANSFORMER REMAINS ALIVE ON FEEDER 1B70. FEEDERTO BE DEENERGIZED ON A PRIORITY#1 DUE TO HIGH TEMP OF 80 DEGREES. HRS 9/9. ENVIROMENTAL OPS NOTIFIED. #12255 VDC.CIG M.SCHLEGEL NOTIFIED @ 0042 HRS. 9/9. #12255 VDC.UPDATE @ 00 HRS RECORDS INDICATE A SEWER. #12255 VDC.E2MIS 12-OCT-2003 10:45:17PDATE @ 0250 HRS 9/9 EPA#NYP004114831 ISSUED BY DAUGHTREY ERT. #12255 VDC.UPDATE @ 0649 HRS 9/9 LAB RESULTS RECEIVED SEQ #03-07466-001 @ 11 PPM. #12255 VDC.Update, 9/9/03, @ 0655 hours. R. Cosentino reports the following information: No pressure test performed due to visible leak located on the bottom of vault. Oilleak is soaked into dirt on floor of the structure (no water). Vault manufactured by GE dated 1965. Vault was installed in 1965. Historical analysis is 10 ppm PCBs.Oil capacity is 300 gallons One liquid sample taken to Chem Lab for new analysis. No soil sample taken. Sample was delivered by A. Walker, OS. Weep holes were found on west wall of involved vault. The adjacent structure (bus compartment) which the weep holes are connected to was checked and no visible oil was found. ERT, Mike Daughtrey visited the incident site. Equipment Group, Environmental Operations and Tanker Operations are on site. Cleanup started as 50 to 499 ppm PCBs. No environmental agencies had responded. Vinny Dineen, Splicer, was instructed to update the CC environmental desk (e2mis) with total amount of oil removed from vault. ----RAC #44505---UPDATE @ 0710 HRS 9/9 V.DINEEN REPORTS TANKER DRAINED TRANSFORMER 280 GALLONS REMOVED, CAPACITY IS 300 GALLONS. #12255 VDC.UPDATE********** 9-10-03 10:15HRS GUY PALLADINO (NETWORKS) REPORTS, THAT MR. DINEEN WAS RELEIVED BY MR. CONNELLYTO CUT TRANSFORMER SECONDARY REQUESTED BY ENV OPS DEPT SO THEY CAN DO THERE PARTIAL CLEANUP. FEEDER WAS NOT READY FORWORK ON THE 5-1 SHIFT. HE WAS PULLED OFF JOB AND MR. THORNGREN RELEIVED MR. CONNELLY AND CUT SECONDARY CABLE WHENFEEDER BECAME READY FOR WORK. S.PACE 49874.UPDATE********** 9-10-03 12:50HRS MR. FERNANDEZ REPORTS, DOUBLE WASHED STRUCUTRE WITH BIO GEN 760, REMOVED ALL9/12/03=1015HRS O.S. S.EDIP NETW REPORTS UNABLE TO REMOVE TRANSFORMER .SSC NEEDED TO LOOSEN SLAB.SHE WILL NOTIFIED SSC AND |

**VAULT 7211 (Continued)** **S106017951**

RESCHEDULE.UPDATE @1240 10/2 SELEDTSOV #19936 NETWORKS REPORTS TRANSFORMER REMOVED AT THIS TIME, TAG REMAINS IN PLACE. #12255 VDC.UPDATE: 10/2/03 - 2000D. LICHTENSTEIN - 08078 - ENV. OPS., REPORTS STRUCTURE DOUBLE WASHED WITH BIO GEN 760. SUMP FOUND CEMENTED. TAG # 36682REMOVED. TJ - 50495

Remarks: FAULTY TRANSFORMER CAUSED MATERIAL TO BE DEPOSITED INTO VAULT. CLEANUP PENDING DEENERGIZATION OF TRANSFORMER. HIST PCB OF 10/PPM

Material:

| | |
|---|---|
| Site ID: | 322659 |
| Operable Unit ID: | 872675 |
| Operable Unit: | 01 |
| Material ID: | 503319 |
| Material Code: | 0541A |
| Material Name: | DIELECTRIC FLUID |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AE264** **VAULT 5526** **NY Spills** **S106970392**
**ENE** **ATLANTIC AVE/HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 8 of 20 in cluster AE**

**Relative:** **Higher**

**Actual:** **34 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0505592 |
| Facility Type: | ER |
| DER Facility ID: | 297108 |
| Site ID: | 350633 |
| DEC Region: | 2 |
| Spill Date: | 8/3/2005 |
| Spill Number/Closed Date: | 0505592 / 1/10/2006 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SKARAKHA |
| Referred To: | Not reported |
| Reported to Dept: | 8/5/2005 |
| CID: | 409 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/5/2005 |

**VAULT 5526 (Continued)** **S106970392**

| | |
|---|---|
| Spill Record Last Update: | 1/10/2006 |
| Spiller Name: | ERT DESK MIKE DAUGHTERY |
| Spiller Company: | VAULT 5526 |
| Spiller Address: | ATLANTIC AVE/HICKS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | ERT DESK MIKE DAUGHTERY |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | e2mis no 160227W. THORNGREN REPORTS WHILE MAKING AN INSPECTION HE SMELLED OIL IN ADJACENT VAULT AND AT 08:10 HRS. HE FOUND APPROX. 1 QT UNKNOWN OIL IN DIRT OF FLOOR OF V-5526. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. ENV STOP TAG 40238 PLACED. SOIL SAMPLE WAS TAKEN (UNABLE TO GET LIQUID SAMPLE). CHAIN OF CUSTODY # EE-01967. HE WILL BE PRESSURE-TESTING TRANSFORMER TO DETERMINE IF IT IS LEAKING. CLEANUP PENDING RESULTS OF PRESSURE TEST AND PCB RESULTS FROM CHEM LAB.TRANSFORMER INFORMATION FROM ECC WAREHOUSE: Serial ID: H300859, Mfg Code: GE, KVA: 1000, Mfr Date: 03/01/1972 , Install Date: 1972.HISTORICAL PCB RESULTS: 12 PPM, Received Date: 03/10/1986, Lab Seq # 602508.8/03/2005 09:32 HRS. -- W. THORNGREN OF EQUIP GROUP REPORTS TRANSFORMER OIL LEVEL OKAY BUT PRESSURE TEST FAILED. SMALL HOLE IN TOP OF TRANSF. FOUND OIL SATURATED DIRT AROUND THROAT BUT DID NOT FIND ANY OIL LEAKING FROM TRANSF., THEREFORE HE STILL CONSIDERS SPILL TO BE UNKNOWN OIL. TRANSF. WILL BE SCHEDULED FOR REPLACEMENT. MATRIX: SOIL GRAB - LOCATION: ATLANTIC AVE 75' E/O HICKS ST - TOTAL PCB 2 ppm |
| Remarks: | 1 QUART PENDING ON DEENERGIZATION OF FEESDER.CON ED#16227 |

Material:

| | |
|---|---|
| Site ID: | 350633 |
| Operable Unit ID: | 1108191 |
| Operable Unit: | 01 |
| Material ID: | 2098123 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AE265** **HICK ST & ATLANTIC AVENUE** **NY Spills** **S102148719**
**ENE** **HICKS ST & ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 9 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9407834 |
| Facility Type: | ER |
| DER Facility ID: | 131032 |
| Site ID: | 154568 |
| DEC Region: | 2 |
| Spill Date: | 9/13/1994 |

**HICK ST & ATLANTIC AVENUE (Continued)** **S102148719**

| | |
|---|---|
| Spill Number/Closed Date: | 9407834 / 9/13/1994 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 9/13/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | 9/13/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/27/1994 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | TRUCK FUEL TANK DEVELOPED LEAK. NYC DEP NOTIFIED-NYC FD TO DRAIN. NO CALL BACK REQUIRED. |

Material:

| | |
|---|---|
| Site ID: | 154568 |
| Operable Unit ID: | 1002090 |
| Operable Unit: | 01 |
| Material ID: | 377295 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 90 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AE266** **HICKS STREET AND ATLANTIC** **NY Spills** **S102671164**
**ENE** **HICKS ST. & ATLANTIC AVE.** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.103 mi.**
**546 ft.** **Site 10 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8700477 |
| Facility Type: | ER |
| DER Facility ID: | 123745 |
| Site ID: | 145202 |
| DEC Region: | 2 |
| Spill Date: | 4/16/1987 |
| Spill Number/Closed Date: | 8700477 / 4/16/1987 |
| Spill Cause: | Other |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 4/16/1987 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Police Department |
| Cleanup Ceased: | 4/16/1987 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/21/1987 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | LONG ISLAND COLLEGE HOSP. |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "10/10/95: This is additional information about material spilled from the translation of the old spill file: NITORGEN OXIDE. |
| Remarks: | EXPLOSION - GAS RELEASED. HAZ/MAT AND DEP RESPONDING. |

Material:

Tank Test:

---

**AE267** **TWO QTS ANTIFREEZE FROM TRUCK** **NY Spills** **S108467099**
**ENE** **ALTLANTIC AVENUE & HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.104 mi.**
**547 ft.** **Site 11 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0613889 |
| Facility Type: | ER |
| DER Facility ID: | 328523 |
| Site ID: | 379023 |

**TWO QTS ANTIFREEZE FROM TRUCK (Continued)** **S108467099**

| | |
|---|---|
| DEC Region: | 2 |
| Spill Date: | 3/27/2007 |
| Spill Number/Closed Date: | 0613889 / 4/24/2007 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | gdbreen |
| Referred To: | Not reported |
| Reported to Dept: | 3/27/2007 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/27/2007 |
| Spill Record Last Update: | 4/24/2007 |
| Spiller Name: | ERTSDESK |
| Spiller Company: | CON EDISON |
| Spiller Address: | ALTLANTIC AVE/ HICKS STRE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERTSDESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 04/24/07 - See e-docs for Con Ed report detailing cleanup and closure.205102. see eDocs |
| Remarks: | NOT YET CLEANED BUT PEOPLE HAVE BEEN DISPATCHED TO EVALUATE BEST WAY TO CLEAN IT; NRC HAS BEEN NOTIFIED- 830511; 205102 |

Material:

| | |
|---|---|
| Site ID: | 379023 |
| Operable Unit ID: | 1136521 |
| Operable Unit: | 01 |
| Material ID: | 2126462 |
| Material Code: | 0043A |
| Material Name: | ANTIFREEZE |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 2 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AE268** **MANHOLE 14656** **NY Spills** **S104193385**
**ENE** **SW CORNER HICKS/ATLANTIC** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.104 mi.**
**547 ft.** **Site 12 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9905141 |
| Facility Type: | ER |
| DER Facility ID: | 162838 |
| Site ID: | 195441 |
| DEC Region: | 2 |
| Spill Date: | 7/29/1999 |
| Spill Number/Closed Date: | 9905141 / 11/5/1999 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 7/29/1999 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/29/1999 |
| Spill Record Last Update: | 6/5/2000 |
| Spiller Name: | UNKNOWN |
| Spiller Company: | UNKNOWN |
| Spiller Address: | UNKNOWN |
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | STEPHEN CRIBBIN |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"CON ED E2MIS NOTESApprox. 1 pt of unknown oil on 300 gals. of water in MH 1456, 1 sample taken.7-30-99 UpdateLab Seq# 99-07899 results <1.00ppm7-31-99Job completed & tag #21962 removed.Incident closed. |
| Remarks: | 1 PINT OF OIL ON 300 GALS OF WATER IN MANHOLE-NO SEWERS OR WATERWAYS AFFECTED. CONED #126919 |

Material:

| | |
|---|---|
| Site ID: | 195441 |
| Operable Unit ID: | 1083746 |
| Operable Unit: | 01 |
| Material ID: | 301456 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |

**MANHOLE 14656 (Continued)** **S104193385**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AE269** **CON EDISON** **NY MANIFEST** **S113496042**
**ENE** **75 ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.104 mi.**
**548 ft.** **Site 13 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004297701 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 01-Apr-2013 00:00:00 |
| Trans1 Recv Date: | 01-Apr-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05-Apr-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004297701 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 200 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002017148GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |

**CON EDISON (Continued)** **S113496042**

| | |
|---|---|
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 01-Apr-2013 00:00:00 |
| Trans1 Recv Date: | 01-Apr-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05-Apr-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004297701 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 200 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002017148GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-04-01 |
| Trans1 Recv Date: | 2013-04-01 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-04-05 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004297701 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |

**CON EDISON (Continued)** **S113496042**

| | |
|---|---|
| Quantity: | 200 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002017148GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**AE270** **CON EDISON MANHOLE: 4647** **RCRA NonGen / NLR** **1016450743**
**ENE** **75 ATLANTIC AVE** **NYP004297701**
**< 1/8** **BROOKLYN, NY 11201**
**0.104 mi.**
**548 ft.** **Site 14 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 05/01/2013 |
| Facility name: | CON EDISON MANHOLE: 4647 |
| Facility address: | 75 ATLANTIC AVE<br>BROOKLYN, NY 11201 |
| EPA ID: | NYP004297701 |
| Contact: | STEPHANIE FRASCHILLA |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 666-4527 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |

**CON EDISON MANHOLE: 4647 (Continued)** **1016450743**

Used oil transporter: No

Historical Generators:
Date form received by agency: 04/01/2013
Facility name: CON EDISON MANHOLE: 4647
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

---

**AE271** **CON EDISON MANHOLE: 4647** **FINDS** **1016439128**
**ENE** **75 ATLANTIC AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.104 mi.**
**548 ft.** **Site 15 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

FINDS:

Registry ID: 110055937198

Environmental Interest/Information System

---

**AH272** **LONG ISLAND HOSPITAL** **NY LTANKS** **S105998171**
**ENE** **363 HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.104 mi.**
**551 ft.** **Site 2 of 3 in cluster AH**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

LTANKS:
Site ID: 128632
Spill Number/Closed Date: 0211399 / 10/17/2003
Spill Date: 2/14/2003
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2/14/2003
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2/14/2003
Spill Record Last Update: 10/17/2003
Spiller Name: RALPH GAMBARDELLA
Spiller Company: LONG ISLAND HOSPITAL
Spiller Address: 363 HICKS STREET
Spiller City,St,Zip: BROOKLYN, NY 11201-
Spiller County: 001
Spiller Contact: PHIL FAZIN
Spiller Phone: (516) 375-5890

**LONG ISLAND HOSPITAL (Continued)** **S105998171**

| | |
|---|---|
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 110959 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DO/TIPPLE"ARAKHAN 2/19/03 TTF LETTER SENT.10/17/03 tipple updating//this spill # closed referred to 02-11398 |
| Remarks: | tank failed the test will evaluate and retest.2nd tank test failure |

Material:

| | |
|---|---|
| Site ID: | 128632 |
| Operable Unit ID: | 862443 |
| Operable Unit: | 01 |
| Material ID: | 511188 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 128632 |
| Spill Tank Test: | 1528032 |
| Tank Number: | 2 |
| Tank Size: | 25000 |
| Test Method: | 03 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Horner EZ Check I or II |

| | |
|---|---|
| Site ID: | 128631 |
| Spill Number/Closed Date: | 0211398 / 10/23/2006 |
| Spill Date: | 2/14/2003 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | VSZHUNE |
| Referred To: | Not reported |
| Reported to Dept: | 2/14/2003 |
| CID: | 282 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |

**LONG ISLAND HOSPITAL (Continued)** **S105998171**

| | |
|---|---|
| Date Entered In Computer: | 2/14/2003 |
| Spill Record Last Update: | 10/23/2006 |
| Spiller Name: | RALPH GAMBARDELLA |
| Spiller Company: | LONG ISLAND HOSPITAL |
| Spiller Address: | 363 HICKS STREET |
| Spiller City,St,Zip: | BROOKLYN, NY 11201- |
| Spiller County: | 001 |
| Spiller Contact: | PHIL FAZIN |
| Spiller Phone: | (516) 375-5890 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 110959 |
| DEC Memo: | 01/01/2006 Kuldeep called phil Fazin 516-375-5890 and he will call back.Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE/DO"arakhan 2/19/03 TTF LETTER SENT.10/17 03 tipple updating///// added ttf from spill # 02-11399 both tanks to be covered under this #09/8/06 This case was transfered from Albany to Region #2. Zhune spoke to Mr. Ralph Gambardella (ph: 718-780-1762). He will send results of re-test. 09/8/06 a TTF letter was sent to:363 Hicks Street Brooklyn, NY 11201Attn: Mr. Ralph Gambardella 10/6/2006 Mr. Gamberdella called me to say in two weeks report will be in.10/20/2006 Petroleun Tank Cleaners brought the report. All of the lines on each tank were replaced and each tank was retested as a system and each one passed as a system. During the removal of the old pipes, the attendant contaminated soil was placed into drums an removed from the site for legal disposal. A PID meter was utilized at the site and no futher contamination was found using the meter. There was no futher odor or any signs of oil staining. This case was closed for V.Zhune in accordance with J. Vought. |
| Remarks: | tank failed the test will uncover evaluate and retest. |

Material:

| | |
|---|---|
| Site ID: | 128631 |
| Operable Unit ID: | 862441 |
| Operable Unit: | 01 |
| Material ID: | 511187 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 128631 |
| Spill Tank Test: | 1528031 |
| Tank Number: | 1 |
| Tank Size: | 25000 |
| Test Method: | 03 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |

**LONG ISLAND HOSPITAL (Continued)** **S105998171**

Test Method: Horner EZ Check I or II

---

**AH273** **UNIV. HOSPITAL OF BROOKLYN** **NY UST** **U001839635**
**ENE** **363 HICKS STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.104 mi.**
**551 ft.** **Site 3 of 3 in cluster AH**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-348236 / Administratively Closed |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584677.79787999997 |
| UTM Y: | 4504835.6695800005 |
| Site Type: | Hospital/Nursing Home/Health Care |

Affiliation Records:

| | |
|---|---|
| Site Id: | 17095 |
| Affiliation Type: | Mail Contact |
| Company Name: | SUNY DOWNSTATE MEDICAL CTR AT LICH |
| Contact Type: | Not reported |
| Contact Name: | EAMON QUIRKE |
| Address1: | 339 HICKS ST |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-4997 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

| | |
|---|---|
| Site Id: | 17095 |
| Affiliation Type: | On-Site Operator |
| Company Name: | UNIV. HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | NICK KAPASSAKIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-1716 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

| | |
|---|---|
| Site Id: | 17095 |
| Affiliation Type: | Emergency Contact |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC |
| Contact Type: | Not reported |

**UNIV. HOSPITAL OF BROOKLYN (Continued)** **U001839635**

| | |
|---|---|
| Contact Name: | CHRIS YAKUBOFF |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

| | |
|---|---|
| Site Id: | 17095 |
| Affiliation Type: | Facility Owner |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY, INC |
| Contact Type: | OFFICER |
| Contact Name: | DEBRA D. CAREY |
| Address1: | 450 CLARKSON AVE--BOX 1281 |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11203 |
| Country Code: | 001 |
| Phone: | (718) 270-1234 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 33269 |
| Tank Status: | Administratively Closed |
| Material Name: | Administratively Closed |
| Capacity Gallons: | 25000 |
| Install Date: | 07/01/1983 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | 21 |
| Date Test: | 05/03/2011 |
| Next Test Date: | 05/03/2016 |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/14/2011 |

Equipment Records:

G00 - Tank Secondary Containment - None
I02 - Overfill - High Level Alarm
B00 - Tank External Protection - None
K00 - Spill Prevention - None

**UNIV. HOSPITAL OF BROOKLYN (Continued)** **U001839635**

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Number: 002
Tank ID: 33270
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 25000
Install Date: 07/01/1983
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 05/09/2011
Next Test Date: 05/09/2016
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/14/2011

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm

Tank Number: 003
Tank ID: 93638
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1500
Install Date: 07/01/1983
Date Tank Closed: 10/23/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008

**UNIV. HOSPITAL OF BROOKLYN (Continued)** **U001839635**

Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 02/24/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LXZIELIN
Last Modified: 10/14/2011

Equipment Records:

H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

Tank Number: 003-A
Tank ID: 93637
Tank Status: Administratively Closed
Material Name: Administratively Closed
Capacity Gallons: 1000
Install Date: 10/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/14/2011

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
D11 - Pipe Type - Flexible Piping
F05 - Pipe External Protection - Jacketed
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

**AE274** **LI COLLEGE HOSP TTF** **NY LTANKS** **S112231181**
**ENE** **339 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.104 mi.**
**551 ft.** **Site 16 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 464729 |
| Spill Number/Closed Date: | 1201982 / Not Reported |
| Spill Date: | 5/29/2012 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 5/29/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 5/29/2012 |
| Spill Record Last Update: | 8/28/2012 |
| Spiller Name: | MARLIN JOSEPH |
| Spiller Company: | LI COLLEGE HOSP |
| Spiller Address: | 363 HICKS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 999 |
| Spiller Contact: | MARLIN JOSEPH |
| Spiller Phone: | 718624-4842 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 419113 |
| DEC Memo: | Contacts: Mark at PTCNick at LI College Hospital - 718-780-1847 |
| Remarks: | tank test failure |

Material:

| | |
|---|---|
| Site ID: | 464729 |
| Operable Unit ID: | 1214766 |
| Operable Unit: | 01 |
| Material ID: | 2212831 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AE275** **SUNY DOWNSTATE MEDICAL CENTER AT LICH** **US AIRS** **1006765325**
**ENE** **339 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.104 mi.**
**551 ft.** **Site 17 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

AIRS (AFS):

Compliance and Violation Data Major Sources:

| | |
|---|---|
| EPA plant ID: | 110004395226 |
| Plant name: | SUNY DOWNSTATE MEDICAL CENTER AT LICH |
| Plant address: | 339 HICKS ST<br>BROOKLYN, NY 11201 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 8062 |
| Sic code desc: | Not reported |
| North Am. industrial classf: | 622110 |
| NAIC code description: | General Medical and Surgical Hospitals |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL EMISSIONS ARE BELOW ALL APPLICABLE MAJOR SOURCE THRESHOLDS IF AND ONLY IF THE SOURCE COMPLIES WITH FEDERALLY ENFORCEABLE REGULATIONS OR LIMITATIONS. |
| Govt facility: | SOURCE OWNED OR OPERATED BY THE STATE |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | SIP SOURCE |
| National action type: | PCE/OFF-SITE |
| Date achieved: | 060206 |
| Penalty amount: | Not reported |
| Air program: | TITLE V PERMITS |
| National action type: | PCE/OFF-SITE |
| Date achieved: | 060206 |
| Penalty amount: | Not reported |
| Air program: | SIP SOURCE |
| National action type: | STATE CONDUCTED PCE/ ON-SITE |
| Date achieved: | 060728 |
| Penalty amount: | Not reported |
| Air program: | NSR |
| National action type: | STATE CONDUCTED FCE / ON-SITE |
| Date achieved: | 060911 |
| Penalty amount: | Not reported |
| Air program: | TITLE V PERMITS |
| National action type: | STATE CONDUCTED FCE / ON-SITE |
| Date achieved: | 060911 |
| Penalty amount: | Not reported |
| Air program: | SIP SOURCE |
| National action type: | STATE CONDUCTED FCE / ON-SITE |
| Date achieved: | 060911 |
| Penalty amount: | Not reported |

**SUNY DOWNSTATE MEDICAL CENTER AT LICH (Continued)** **1006765325**

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE
Date achieved: 060912
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 060912
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE
Date achieved: 070208
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 070208
Penalty amount: Not reported

Air program: NSR
National action type: PCE/OFF-SITE
Date achieved: 070208
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE
Date achieved: 080204
Penalty amount: Not reported

Air program: NSR
National action type: PCE/OFF-SITE
Date achieved: 080204
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 080204
Penalty amount: Not reported

Air program: NSR
National action type: PCE/OFF-SITE
Date achieved: 090127
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE
Date achieved: 090127
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 090127
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE

**SUNY DOWNSTATE MEDICAL CENTER AT LICH (Continued)** **1006765325**

Date achieved: 100201
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 100201
Penalty amount: Not reported

Air program: NSR
National action type: PCE/OFF-SITE
Date achieved: 100201
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: PCE/OFF-SITE
Date achieved: 110114
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: PCE/OFF-SITE
Date achieved: 110114
Penalty amount: Not reported

Air program: NSR
National action type: PCE/OFF-SITE
Date achieved: 110114
Penalty amount: Not reported

Air program: NSR
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110531
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110531
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED PCE/ ON-SITE
Date achieved: 110531
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110728
Penalty amount: Not reported

Air program: NSR
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110728
Penalty amount: Not reported

Air program: TITLE V PERMITS
National action type: STATE CONDUCTED FCE / ON-SITE
Date achieved: 110728
Penalty amount: Not reported

**SUNY DOWNSTATE MEDICAL CENTER AT LICH (Continued)** **1006765325**

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: TITLE V PERMITS

**SUNY DOWNSTATE MEDICAL CENTER AT LICH (Continued)** **1006765325**

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

**SUNY DOWNSTATE MEDICAL CENTER AT LICH (Continued)** **1006765325**

Hist compliance date: 1201
Air prog code hist file: NSR

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: TITLE V PERMITS

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: TITLE V PERMITS

---

**AE276**
**ENE**
**< 1/8**
**0.104 mi.**
**551 ft.**

**SUNY DOWNSTATE MEDICAL CENTER AT LICH** **FINDS** **1016077679**
**339 HICKS ST** **N/A**
**BROOKLYN, NY**

**Site 18 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**34 ft.**

FINDS:

Registry ID: 110013331313

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**AD277** **SPILL NUMBER 0105297** **NY Spills** **S105140417**
**SSW** **113 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.105 mi.**
**553 ft.** **Site 5 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0105297 |
| Facility Type: | ER |
| DER Facility ID: | 107943 |
| Site ID: | 124667 |
| DEC Region: | 2 |
| Spill Date: | 8/15/2001 |
| Spill Number/Closed Date: | 0105297 / 12/8/2003 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 8/15/2001 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/15/2001 |
| Spill Record Last Update: | 12/8/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | VANDALS |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | JACKIE MALSONADO |
| Contact Phone: | (718) 403-0363 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"12/8/03 TJDProduct spilled to concrete. All material recovered. No further action required. Spill closed. |
| Remarks: | VANDALS DID DAMAGE TO THEIR TANK - THEY HAVE PETROLEUM ENROUTE FOR CLEAN UP |

Material:

| | |
|---|---|
| Site ID: | 124667 |
| Operable Unit ID: | 842204 |
| Operable Unit: | 01 |
| Material ID: | 533772 |
| Material Code: | 0015 |
| Material Name: | Motor Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**SPILL NUMBER 0105297 (Continued)** **S105140417**

Tank Test:

---

**AD278** **MOBIL OIL-BKLYN TUNNEL SVCE STA** **FINDS** **1007776130**
**SSW** **113-115 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.105 mi.**
**553 ft.** **Site 6 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

FINDS:

Registry ID: 110019385841

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**AD279** **AUTO TECH REPAIR CENTER** **NY AST** **A100301599**
**SSW** **113 HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.105 mi.**
**553 ft.** **Site 7 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-610520 |
| Program Type: | PBS |
| UTM X: | 584086.72264000005 |
| UTM Y: | 4503924.2385400003 |
| Expiration Date: | 2017/03/21 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 378734 |
| Affiliation Type: | Facility Owner |
| Company Name: | NASER MEZHER |
| Contact Type: | MANAGER |
| Contact Name: | IMAD BAKER |
| Address1: | 92 GELSTON AVE 1E |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11209 |
| Country Code: | 001 |
| Phone: | (718) 921-1272 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 1/20/2012 |

| | |
|---|---|
| Site Id: | 378734 |
| Affiliation Type: | Mail Contact |

**AUTO TECH REPAIR CENTER (Continued)** **A100301599**

| | |
|---|---|
| Company Name: | AUTO TECH REPAIR CENTER |
| Contact Type: | Not reported |
| Contact Name: | IMAD BAKER |
| Address1: | 113 HAMILTON AVENUE |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 403-0363 |
| EMail: | EMMD007@AOL.COM |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 3/21/2007 |

| | |
|---|---|
| Site Id: | 378734 |
| Affiliation Type: | On-Site Operator |
| Company Name: | AUTO TECH REPAIR CENTER |
| Contact Type: | Not reported |
| Contact Name: | IMAD BAKER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 403-0363 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 3/21/2007 |

| | |
|---|---|
| Site Id: | 378734 |
| Affiliation Type: | Emergency Contact |
| Company Name: | NASER MEZHER |
| Contact Type: | Not reported |
| Contact Name: | ELEIWI CHEIKH |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (917) 981-5052 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 3/21/2007 |

Tank Info:

| | |
|---|---|
| Tank Number: | NO 10 STEEL |
| Tank Id: | 216462 |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |

**AUTO TECH REPAIR CENTER (Continued)** **A100301599**

Equipment Records:

L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/10/2003 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 03/21/2007 |
| Material Name: | Waste Oil/Used Oil |

---

**AD280** **EDR US Hist Auto Stat** **1015163124**
**SSW** **113 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.105 mi.**
**553 ft.** **Site 8 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | ALABAS AUTO REPAIR |
| Year: | 1999 |
| Address: | 113 HAMILTON AVE |
| Name: | ALABAS AUTO REPAIR |
| Year: | 2000 |
| Address: | 113 HAMILTON AVE |
| Name: | AL ABAS AUTO REPAIR CORP |
| Year: | 2002 |
| Address: | 113 HAMILTON AVE |
| Name: | ALABAS AUTO REPAIR |
| Year: | 2003 |
| Address: | 113 HAMILTON AVE |
| Name: | ALABAS AUTO REPAIR |
| Year: | 2004 |
| Address: | 113 HAMILTON AVE |
| Name: | AUTO TECH REPAIR CENTER CORP |
| Year: | 2005 |

**(Continued)** **1015163124**

Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CENTER CORP
Year: 2007
Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CENTER CORP
Year: 2008
Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CENTER CORP
Year: 2009
Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CTR
Year: 2010
Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CENTER
Year: 2011
Address: 113 HAMILTON AVE

Name: AUTO TECH REPAIR CENTER
Year: 2012
Address: 113 HAMILTON AVE

---

**AC281** **EDR US Hist Auto Stat** **1015501482**
**SSW** **45 SEABRING ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.105 mi.**
**556 ft.** **Site 2 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

EDR Historical Auto Stations:
Name: MAGIC COLLISION INCORPORATED
Year: 2000
Address: 45 SEABRING ST

Name: MAGIC COLLISION INC
Year: 2003
Address: 45 SEABRING ST

---

**AI282** **SPILL NUMBER 0001336** **NY Spills** **S104650677**
**SSW** **140 HAMILTON AVE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.105 mi.**
**557 ft.** **Site 1 of 3 in cluster AI**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

SPILLS:
Facility ID: 0001336
Facility Type: ER
DER Facility ID: 129658
Site ID: 152751
DEC Region: 2
Spill Date: 5/3/2000
Spill Number/Closed Date: 0001336 / 7/11/2000
Spill Cause: Unknown

**SPILL NUMBER 0001336 (Continued)** **S104650677**

| | |
|---|---|
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 5/3/2000 |
| CID: | 366 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/3/2000 |
| Spill Record Last Update: | 7/11/2000 |
| Spiller Name: | JOHN CANNON |
| Spiller Company: | 140 HAMILTON AVE REALTOR |
| Spiller Address: | 184 WOODMERE BLVD |
| Spiller City,St,Zip: | HEWLETT NECK, NY 11598- |
| Spiller Company: | 001 |
| Contact Name: | 140 HAMILTON AVE REALTOR |
| Contact Phone: | (516) 569-5700 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"5/15/2000 SANGESLAND SPOKE WITH STUART BERRY AT ALLIED WASTE.HE SAID SAMPLES WERE TESTED FOR STARS AND EVERYTHING CAME BACK BELOW STARS LEVELS.SANGESLAND ASKED STUART BERRY TO SEND IN A COPY OF THE LAB REPORTS AND IF THEY ARE BELOW LIMITS, THE SPILL WOULD BE CLOSED OUT.7/11/2000 Stuart Berry submitted a report which shows 15 tons of soil were removed and manifested. End point samples were taken and appear clean.Spill Closed |
| Remarks: | Caller reporting that his company was contracted to do soil samples on property. Samples showed elevated levels of a product, possibly fuel oil. |

Material:

| | |
|---|---|
| Site ID: | 152751 |
| Operable Unit ID: | 823249 |
| Operable Unit: | 01 |
| Material ID: | 557716 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AJ283** **BQE SADDLE TANK SPILL** **NY Spills** **S102143940**
**ESE** **BROOKLYN QUEENS EXPRESSWAY** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.106 mi.**
**560 ft.** **Site 1 of 3 in cluster AJ**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8600931 |
| Facility Type: | ER |
| DER Facility ID: | 117109 |
| Site ID: | 131566 |
| DEC Region: | 2 |
| Spill Date: | 5/8/1986 |
| Spill Number/Closed Date: | 8600931 / 5/8/1986 |
| Spill Cause: | Traffic Accident |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 5/8/1986 |
| CID: | Not reported |
| Water Affected: | NONE |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | DEC |
| Cleanup Ceased: | 5/8/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/9/1986 |
| Spill Record Last Update: | 6/19/1986 |
| Spiller Name: | Not reported |
| Spiller Company: | COLT RENTAL:LEASING |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | OTHER SPILL LOCATION-KANE ST. |

Material:

| | |
|---|---|
| Site ID: | 131566 |
| Operable Unit ID: | 898591 |
| Operable Unit: | 01 |
| Material ID: | 565363 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AG284** **106 UNION STREET** **NY Spills** **S102143650**
**South** **106 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.108 mi.**
**569 ft.** **Site 4 of 5 in cluster AG**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9211539 |
| Facility Type: | ER |
| DER Facility ID: | 153907 |
| Site ID: | 183874 |
| DEC Region: | 2 |
| Spill Date: | 1/7/1993 |
| Spill Number/Closed Date: | 9211539 / 1/7/1993 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | O'DOWD |
| Referred To: | Not reported |
| Reported to Dept: | 1/7/1993 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | 1/7/1993 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/8/1993 |
| Spill Record Last Update: | 1/11/1993 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | STRONG ODOR IN CELLAR ROOM ON GROUND FLOOR-ALSO OIL NOTICED ON WATER IN BASEMENT NOTICED FOR 1WK |

Material:

| | |
|---|---|
| Site ID: | 183874 |
| Operable Unit ID: | 975826 |
| Operable Unit: | 01 |
| Material ID: | 558966 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**106 UNION STREET (Continued)** **S102143650**

Tank Test:

---

**AK285** **WATCHTOWER** **RCRA-SQG** **1000244433**
**NNE** **FURMAN STREET** **NJ MANIFEST** **NYD001256353**
**< 1/8** **BROOKLYN, NY 11201**
**0.109 mi.**
**574 ft.** **Site 1 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

RCRA-SQG:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | WATCHTOWER |
| Facility address: | FURMAN STREET<br>BROOKLYN, NY 112014505 |
| EPA ID: | NYD001256353 |
| Mailing address: | COLUMBIA HEIGHTS<br>BROOKLYN, NY 112012483 |
| Contact: | NORMAN A BREKKE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | US |
| Contact telephone: | (718) 560-5000 |
| Telephone ext.: | BREKKE |
| Contact email: | BROOKLYNREGULATORY@JW.ORG |
| EPA Region: | 02 |
| Land type: | Private |
| Classification: | Small Small Quantity Generator |
| Description: | Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | RANDALL GARRETT |
| Owner/operator address: | COLUMBIA HTS<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | Not reported |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | 02/01/2002 |
| Owner/Op end date: | Not reported |
| Owner/operator name: | WATCHTOWER |
| Owner/operator address: | COLUMBIA HTS<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | Not reported |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | 03/15/1983 |
| Owner/Op end date: | Not reported |
| Owner/operator name: | RANDALL GARRETT |
| Owner/operator address: | Not reported<br>Not reported |

**WATCHTOWER (Continued)** **1000244433**

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/01/2002
Owner/Op end date: Not reported

Owner/operator name: WATCHTOWER
Owner/operator address: COLUMBIA HEIGHTS
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/15/1983
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/01/2006
Facility name: WATCHTOWER
Classification: Small Quantity Generator

Date form received by agency: 02/28/2006
Facility name: WATCHTOWER
Classification: Small Quantity Generator

Date form received by agency: 03/09/2004
Facility name: WATCHTOWER
Classification: Small Quantity Generator

Date form received by agency: 09/14/1999
Facility name: WATCHTOWER
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: D039

**WATCHTOWER (Continued)** **1000244433**

Waste name: TETRACHLOROETHYLENE

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 08/26/1997
Date achieved compliance: 09/09/1997

**WATCHTOWER (Continued)** **1000244433**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/26/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/03/1986
Date achieved compliance: 05/23/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/02/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/13/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/01/1997
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 09/09/1997
Evaluation lead agency: State

Evaluation date: 03/03/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/23/1986
Evaluation lead agency: State

NJ MANIFEST:
Manifest Code: NJA5009437
EPA ID: NYD001256353
Date Shipped: 02/02/2004
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans1 Transported Waste: | 02/02/2004 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 02/03/2004 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 03160425 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5077154 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 05/28/2004 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 05/28/2004 |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 05/28/2004 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 06150421 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5114590 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 11/02/2004 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 11/02/2004 |
| Date Trans2 Transported Waste: | Not reported |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 11/02/2004 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 12270421 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5244355 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 02/18/2005 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 02/18/2005 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 02/18/2005 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 04270522 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5242388 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 04/18/2005 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 04/18/2005 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 04/18/2005 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 06150521 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5242389 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 04/18/2005 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 04/18/2005 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 04/18/2005 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 06150521 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5259018 |
| EPA ID: | NYD001256353 |
| Date Shipped: | 05/27/2005 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 05/27/2005 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |

**WATCHTOWER (Continued)** **1000244433**

| | |
|---|---|
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 05/27/2005 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 07130521 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

---

**AK286** **WATCHTOWER BIBLE & TRACT(MOVED TO -00191)** **NY DRYCLEANERS** **S110248295**
**NNE** **360 FURMAN STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11201**
**0.109 mi.**
**574 ft.** **Site 2 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

DRYCLEANERS:

| | |
|---|---|
| Facility ID: | 2-6101-00462 |
| Phone Number: | 718-625-3600 |
| Region: | Not reported |
| Registration Effective Date: | N/A |
| Inspection Date: | 07DEC31 |
| Install Date: | 91/01 |
| Drop Shop: | Not reported |
| Shutdown: | Y |
| Alternate Solvent: | Not reported |
| Current Business: | Not reported |

**AK287** **WATCHTOWER BIBLE** **NY LTANKS** **S108635858**
**NNE** **360 FURMAN STREET** **NY MANIFEST** **N/A**
**< 1/8** **BROOKLYN, NY 11201** **NY Spills**
**0.109 mi.**
**574 ft.** **Site 3 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 251709 |
| Spill Number/Closed Date: | 0311887 / 5/17/2004 |
| Spill Date: | 1/22/2004 |
| Spill Cause: | Tank Failure |
| Spill Source: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | MXTIPPLE |
| Referred To: | Not reported |
| Reported to Dept: | 1/22/2004 |
| CID: | 403 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/22/2004 |
| Spill Record Last Update: | 6/7/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | ANSELM PACKNETT |
| Spiller Phone: | (718) 560-5000 |
| Spiller Extention: | 22881 |
| DEC Region: | 2 |
| DER Facility ID: | 206271 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"1/23/04 tipple spoke with Anselm Packnett from Watchtower. He indicated that ATC had been retained to conduct a phase 2 investigation. There is a small amount of what appears to be #6 fuel oil slowly seeping into a sub basement at this location. Mr. Packnett indicated that he believes that there was once an underground storage tank at this address and may have been abandon many years ago. The address for correspondance is:25 Columbia HeightsBrooklyn, NY 11201contaminated soil letter sent by tipple//six weeks//4/29/04 tipple updating////site meeting revealed that contaminants remained in one phlenum adjacent to the abandon UST's..contractor will drill a test hole through the phlenum wall to determine if any residual oil lies behind the phlenum wall.soil has been removed 1-2 ft below the water table, next step will be determined by the findings of the test hole.5/17/04 no residual petroleum found in vault area, phlenum excavated to approximately 1' below water table, no product floating, possible slight staining on subaqueous soils, dewatered, 3' concrete cap poured, no further action necessary. |
| Remarks: | not a result of an ongoing process. phase 2 will be initiated to determine the nature of the amount of oil |

**WATCHTOWER BIBLE (Continued)** **S108635858**

Material:

| | |
|---|---|
| Site ID: | 251709 |
| Operable Unit ID: | 879467 |
| Operable Unit: | 01 |
| Material ID: | 497127 |
| Material Code: | 0003A |
| Material Name: | #6 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD001256353 |
| Country: | USA |
| Mailing Name: | WATCHTOWER BIBLE |
| Mailing Contact: | ERIC SANDOVAL |
| Mailing Address: | 117 ADAMS STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-560-5000 |

NY MANIFEST:

No Manifest Records Available

SPILLS:

| | |
|---|---|
| Facility ID: | 0700183 |
| Facility Type: | ER |
| DER Facility ID: | 206271 |
| Site ID: | 379479 |
| DEC Region: | 2 |
| Spill Date: | 4/5/2007 |
| Spill Number/Closed Date: | 0700183 / 4/12/2007 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | hrpatel |
| Referred To: | Not reported |
| Reported to Dept: | 4/5/2007 |
| CID: | 406 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |

**WATCHTOWER BIBLE (Continued)** **S108635858**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/5/2007 |
| Spill Record Last Update: | 4/12/2007 |
| Spiller Name: | UNKNOWN NAME |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 999 |
| Contact Name: | MALARIE GILMORE |
| Contact Phone: | (212) 689-1520 |
| DEC Memo: | anonymous call to city 311 operator04/12/07-Hiralkumar Patel. visited site. met Bill Paganotti (646-996-6183), site supervisor. small area of spill (~1-2 gal) observed on solid concrete. all cleaned up. case closed. |
| Remarks: | Hydraulic oil spill on a construction site. Unknown where the material came from and what caused it. Clean up has not begun yet. |

Material:

| | |
|---|---|
| Site ID: | 379479 |
| Operable Unit ID: | 1136960 |
| Operable Unit: | 01 |
| Material ID: | 2126901 |
| Material Code: | 0010 |
| Material Name: | Hydraulic Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AG288** **EDR US Hist Auto Stat** **1015178438**
**South** **120 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.109 mi.**
**576 ft.** **Site 5 of 5 in cluster AG**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | KNIGHTS COLLISION EXPERTS INC |
| Year: | 2001 |
| Address: | 120 UNION ST |
| Name: | KNIGHTS COLLISION EXPERTS INC |
| Year: | 2010 |
| Address: | 120 UNION ST |

**AL289** **TECHNIKOTE CORP** **RCRA-CESQG** **1000243127**
**SSW** **63 SEABRING ST** **FINDS** **NYD001338037**
**< 1/8** **BROOKLYN, NY** **NY MANIFEST**
**0.109 mi.**
**578 ft.** **Site 1 of 3 in cluster AL**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | TECHNIKOTE CORP |
| Facility address: | 63 SEABRING ST<br>BROOKLYN, NY 11231 |
| EPA ID: | NYD001338037 |
| Mailing address: | SEABRING ST<br>BROOKLYN, NY 11231 |
| Contact: | Not reported |
| Contact address: | SEABRING ST<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Land type: | Facility is not located on Indian land. Additional information is not known. |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | TECHNIKOTE CORP |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | TECHNIKOTE CORP |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

**TECHNIKOTE CORP (Continued)** **1000243127**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 01/01/2006
- Facility name: TECHNIKOTE CORP
- Classification: Conditionally Exempt Small Quantity Generator

- Date form received by agency: 07/14/1999
- Facility name: TECHNIKOTE CORP
- Classification: Small Quantity Generator

- Date form received by agency: 04/04/1989
- Facility name: TECHNIKOTE CORP
- Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
- Regulation violated: SR - 371.1(f)(7)
- Area of violation: Listing - General
- Date violation determined: 11/01/2002
- Date achieved compliance: 11/19/2002
- Violation lead agency: State
  - Enforcement action: WRITTEN INFORMAL
  - Enforcement action date: 11/12/2002
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: Not reported
  - Paid penalty amount: Not reported

Evaluation Action Summary:
- Evaluation date: 11/01/2002
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Listing - General
- Date achieved compliance: 11/19/2002
- Evaluation lead agency: State

- Evaluation date: 07/26/1999
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported

**TECHNIKOTE CORP (Continued)** **1000243127**

Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 12/17/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110004333855

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD001338037
Country: USA
Mailing Name: TECHNIKOTE
Mailing Contact: TECHNIKOTE
Mailing Address: 72 COMMERCE ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11231
Mailing Zip4: 1643
Mailing Country: USA
Mailing Phone: 718-624-6429

Document ID: NYH0471753
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 05/16/2005
Trans1 Recv Date: 05/16/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/16/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001338037
Trans1 EPA ID: 62096PA
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.

**TECHNIKOTE CORP (Continued)** **1000243127**

Specific Gravity: 01.00
Year: Not reported

Document ID: NYH0474309
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 01/25/2005
Trans1 Recv Date: 01/25/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/25/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001338037
Trans1 EPA ID: 62096PA
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYA7162632
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890614
Trans1 Recv Date: 890614
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890615
Part A Recv Date: 890621
Part B Recv Date: 890621
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 076
Year: 89

Document ID: NYA7038225
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: MV6352
Trans2 State ID: Not reported
Generator Ship Date: 890912

**TECHNIKOTE CORP (Continued)** **1000243127**

| | |
|---|---|
| Trans1 Recv Date: | 890912 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890912 |
| Part A Recv Date: | 891019 |
| Part B Recv Date: | 890919 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYB2105064 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | MV6352 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 900221 |
| Trans1 Recv Date: | 900221 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900222 |
| Part A Recv Date: | 900316 |
| Part B Recv Date: | 900309 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYB2139984 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | HM3506 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 900612 |
| Trans1 Recv Date: | 900612 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900612 |
| Part A Recv Date: | 900823 |
| Part B Recv Date: | 900918 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |

**TECHNIKOTE CORP (Continued)** **1000243127**

| | |
|---|---|
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 095 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYB2774916 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900813 |
| Trans1 Recv Date: | 900813 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900813 |
| Part A Recv Date: | 900830 |
| Part B Recv Date: | 900830 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYB2391660 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | HL4120 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910508 |
| Trans1 Recv Date: | 910508 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910508 |
| Part A Recv Date: | 910520 |
| Part B Recv Date: | 910516 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 91 |

**TECHNIKOTE CORP (Continued)** **1000243127**

| | |
|---|---|
| Document ID: | NYB2417994 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | HL4120 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910124 |
| Trans1 Recv Date: | 910124 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910124 |
| Part A Recv Date: | 910201 |
| Part B Recv Date: | 910215 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYB2640195 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | HL4120 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910917 |
| Trans1 Recv Date: | 910917 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910917 |
| Part A Recv Date: | 911002 |
| Part B Recv Date: | 910926 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYB4440807 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | HL4120 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920107 |
| Trans1 Recv Date: | 920107 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920107 |
| Part A Recv Date: | 920114 |

**TECHNIKOTE CORP (Continued)** **1000243127**

Part B Recv Date: 920117
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 076
Year: 92

Document ID: NYB4709331
Manifest Status: Completed copy
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 920320
Trans1 Recv Date: 920320
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920320
Part A Recv Date: 920327
Part B Recv Date: 920331
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 076
Year: 92

Document ID: NYB4360491
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 921013
Trans1 Recv Date: 921013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921013
Part A Recv Date: Not reported
Part B Recv Date: 921022
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002

**TECHNIKOTE CORP (Continued)** **1000243127**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 076
Year: 92

Document ID: NYB5585616
Manifest Status: Completed copy
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 920707
Trans1 Recv Date: 920707
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920707
Part A Recv Date: Not reported
Part B Recv Date: 920717
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F005 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 088
Year: 92

Document ID: NYB4322835
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 930211
Trans1 Recv Date: 930211
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930211
Part A Recv Date: 930223
Part B Recv Date: 930223
Generator EPA ID: NYD001338037
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 076
Year: 93

Document ID: NYB5177358
Manifest Status: Completed copy
Trans1 State ID: PD9938

**TECHNIKOTE CORP (Continued)** **1000243127**

| | |
|---|---|
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 931022 |
| Trans1 Recv Date: | 931022 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 931022 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 931105 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 93 |

| | |
|---|---|
| Document ID: | NYB5378328 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PD9938 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 930715 |
| Trans1 Recv Date: | 930715 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 930715 |
| Part A Recv Date: | 930730 |
| Part B Recv Date: | 930728 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 93 |

| | |
|---|---|
| Document ID: | NYB5496219 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PD9938 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 940316 |
| Trans1 Recv Date: | 940316 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 940316 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 940328 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |

**TECHNIKOTE CORP (Continued)** **1000243127**

| | |
|---|---|
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 94 |

| | |
|---|---|
| Document ID: | NYB4943187 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PD9938 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 940629 |
| Trans1 Recv Date: | 940629 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 940629 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 940711 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |
| Year: | 94 |

| | |
|---|---|
| Document ID: | NYB6707565 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PD9938 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 941102 |
| Trans1 Recv Date: | 941102 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 941102 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 941114 |
| Generator EPA ID: | NYD001338037 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00110 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 076 |

**TECHNIKOTE CORP (Continued)** **1000243127**

Year: 94

~~Click this hyperlink~~ while viewing on your computer to access
22 additional NY_MANIFEST: record(s) in the EDR Site Report.

---

**290**
**ENE**
**< 1/8**
**0.110 mi.**
**579 ft.**

**BELL ATLANTIC-NY** **NY MANIFEST** **S109064476**
**5 AV + PACIFIC ST MANHOLE** **N/A**
**BROOKLYN, NY**

**Relative:**
**Higher**

**Actual:**
**31 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000940536 |
| Country: | USA |
| Mailing Name: | BELL ATLANTIC-NY |
| Mailing Contact: | Not reported |
| Mailing Address: | Not reported |
| Mailing Address 2: | Not reported |
| Mailing City: | Not reported |
| Mailing State: | Not reported |
| Mailing Zip: | Not reported |
| Mailing Zip4: | Not reported |
| Mailing Country: | Not reported |
| Mailing Phone: | Not reported |

NY MANIFEST:

No Manifest Records Available

---

**AK291**
**NNE**
**< 1/8**
**0.111 mi.**
**584 ft.**

**WATCHTOWER BIBLE AND TRACT** **FINDS** **1016081061**
**360 FURMAN ST** **N/A**
**BROOKLYN, NY**

**Site 4 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

FINDS:

Registry ID: 110004332945

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

**WATCHTOWER BIBLE AND TRACT (Continued)** **1016081061**

corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

HAZARDOUS WASTE BIENNIAL REPORTER

---

**AL292** **NEW YOU LIAN TRADING INC.** **FINDS** **1014903421**
**SSW** **70 COMMERCE STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.111 mi.**
**588 ft.** **Site 2 of 3 in cluster AL**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

FINDS:

Registry ID: 110043720382

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

---

**AB293** **PVT DWELLING TTF** **NY LTANKS** **S110490796**
**East** **423 HICKS AT** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.112 mi.**
**589 ft.** **Site 5 of 5 in cluster AB**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 436371 |
| Spill Number/Closed Date: | 1003165 / 1/12/2011 |
| Spill Date: | 6/21/2010 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | RMPIPER |
| Referred To: | Not reported |

**PVT DWELLING TTF (Continued)** **S110490796**

| | |
|---|---|
| Reported to Dept: | 6/21/2010 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/21/2010 |
| Spill Record Last Update: | 1/12/2011 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller County: | 999 |
| Spiller Contact: | MARLON JOSEPH |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 391309 |
| DEC Memo: | spill 1002863 exists. 1003165 genrerated as result of ttf from 1002863 requirements. Sp 1002863 will be closed and consolidated into 1003165. DEC Piper performed site visit. COBBLE HILL TOWERS ASSOC. Tank was installed in1975 and have slight petroleum odors. Speedy dry was down thogh there did not appear to be a leak as the weep holes were clean. I instructed them to test tank and submit reults. Additionall work may follow.0608438 was previous spill at site that has been closed.pbs 2-310425ttf sent to CObble Hill Towers Assoc.1/12/11- DEC Piper recieved passing tightness test results after repairs to vent line were made. See edocs if warranted. closed. |
| Remarks: | 5000gal agt |

Material:

| | |
|---|---|
| Site ID: | 436371 |
| Operable Unit ID: | 1187070 |
| Operable Unit: | 01 |
| Material ID: | 2181937 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AE294** **ATLANTIC STAR CLEANERS** **RCRA NonGen / NLR** **1000153421**
**ENE** **77 ATLANTIC AVE** **FINDS** **NYD982537557**
**< 1/8** **BROOKLYN, NY 11201** **NY MANIFEST**
**0.112 mi.**
**591 ft.** **Site 19 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | ATLANTIC STAR CLEANERS |
| Facility address: | 77 ATLANTIC AVE<br>BROOKLYN, NY 112015503 |
| EPA ID: | NYD982537557 |
| Mailing address: | ATLANTIC AVE<br>BROOKLYN, NY 11201 |
| Contact: | Not reported |
| Contact address: | ATLANTIC AVE<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | OLEK BERGER |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | OLEK BERGER |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ATLANTIC STAR CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ATLANTIC STAR CLEANERS
Classification: Not a generator, verified

Date form received by agency: 04/29/1988
Facility name: ATLANTIC STAR CLEANERS
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004423570

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD982537557
Country: USA
Mailing Name: ATLANTIC STAR CLNRS
Mailing Contact: ATLANTIC STAR CLNRS
Mailing Address: 77 ATLANTIC AVE-OLEK BERGER
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-624-6028

Document ID: NYA9007479
Manifest Status: Completed copy
Trans1 State ID: NYPP4503
Trans2 State ID: Not reported
Generator Ship Date: 880826
Trans1 Recv Date: 880826
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880826
Part A Recv Date: 880902
Part B Recv Date: 880901

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

Generator EPA ID: NYD982537557
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA9082618
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: LP3931
Trans2 State ID: Not reported
Generator Ship Date: 880916
Trans1 Recv Date: 880916
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880916
Part A Recv Date: 881024
Part B Recv Date: 880927
Generator EPA ID: NYD982537557
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA8961085
Manifest Status: Completed copy
Trans1 State ID: LP3931
Trans2 State ID: Not reported
Generator Ship Date: 880720
Trans1 Recv Date: 880720
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880720
Part A Recv Date: 880728
Part B Recv Date: 880728
Generator EPA ID: NYD982537557
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA9167319
Manifest Status: Completed copy
Trans1 State ID: LP3931
Trans2 State ID: Not reported
Generator Ship Date: 881213
Trans1 Recv Date: 881213
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881213
Part A Recv Date: 881219
Part B Recv Date: 881221
Generator EPA ID: NYD982537557
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA9123838
Manifest Status: Completed copy
Trans1 State ID: LP3931
Trans2 State ID: Not reported
Generator Ship Date: 881108
Trans1 Recv Date: 881108
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881108
Part A Recv Date: 881122
Part B Recv Date: 881116
Generator EPA ID: NYD982537557
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA9346206
Manifest Status: Completed copy
Trans1 State ID: AY9381(NY
Trans2 State ID: Not reported

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Generator Ship Date: | 890228 |
| Trans1 Recv Date: | 890228 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890228 |
| Part A Recv Date: | 890303 |
| Part B Recv Date: | 890308 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9394031 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | LP3931NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890321 |
| Trans1 Recv Date: | 890321 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890321 |
| Part A Recv Date: | 890323 |
| Part B Recv Date: | 890328 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9299373 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | LP3931(NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890201 |
| Trans1 Recv Date: | 890201 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890201 |
| Part A Recv Date: | 890208 |
| Part B Recv Date: | 890208 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9586438 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 890718 |
| Trans1 Recv Date: | 890718 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890718 |
| Part A Recv Date: | 890907 |
| Part B Recv Date: | 890725 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9430986 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AY9381NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890501 |
| Trans1 Recv Date: | 890501 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890501 |
| Part A Recv Date: | 890504 |
| Part B Recv Date: | 890509 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Document ID: | NYA9634318 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 890817 |
| Trans1 Recv Date: | 890817 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890817 |
| Part A Recv Date: | 890822 |
| Part B Recv Date: | 890828 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9670105 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AY9381NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 891011 |
| Trans1 Recv Date: | 891011 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 891011 |
| Part A Recv Date: | 891013 |
| Part B Recv Date: | 891016 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9714846 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | AY9381NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890914 |
| Trans1 Recv Date: | 890914 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890914 |
| Part A Recv Date: | 891012 |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Part B Recv Date: | 890920 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYC0036707 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900111 |
| Trans1 Recv Date: | 900111 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900111 |
| Part A Recv Date: | 900214 |
| Part B Recv Date: | 900117 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0078827 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900130 |
| Trans1 Recv Date: | 900130 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900130 |
| Part A Recv Date: | 900214 |
| Part B Recv Date: | 900207 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYA9834568 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 891213 |
| Trans1 Recv Date: | 891213 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 891213 |
| Part A Recv Date: | 891228 |
| Part B Recv Date: | 891221 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYA9826176 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AY9381NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 891113 |
| Trans1 Recv Date: | 891113 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 891113 |
| Part A Recv Date: | 891120 |
| Part B Recv Date: | 891122 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | CF - Fiber or plastic boxes, cartons |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 89 |

| | |
|---|---|
| Document ID: | NYC0138824 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900226 |
| Trans1 Recv Date: | 900226 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900226 |
| Part A Recv Date: | 900507 |
| Part B Recv Date: | 900308 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0235787 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900426 |
| Trans1 Recv Date: | 900426 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900426 |
| Part A Recv Date: | 900809 |
| Part B Recv Date: | 900508 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0180459 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900403 |
| Trans1 Recv Date: | 900403 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900403 |
| Part A Recv Date: | 900514 |
| Part B Recv Date: | 900416 |
| Generator EPA ID: | NYD982537557 |
| Trans1 EPA ID: | ILD051060408 |

**ATLANTIC STAR CLEANERS (Continued)** **1000153421**

| | |
|---|---|
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 90 |

Click this hyperlink while viewing on your computer to access
14 additional NY_MANIFEST: record(s) in the EDR Site Report.

---

**AM295** **YMCA** **FINDS** **1008220869**
**South** **130 SOUTH UNION STREET** **N/A**
**< 1/8** **BROOKLYN,, NY**
**0.115 mi.**
**606 ft.** **Site 1 of 4 in cluster AM**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

FINDS:

Registry ID: 110020926630

Environmental Interest/Information System
US EPA Air Quality System (AQS) contains ambient air pollution data collected by EPA, State, Local, and Tribal air pollution control agencies from thousands of monitoring stations.

---

**AM296** **EDR US Hist Cleaners** **1014986821**
**South** **130 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.115 mi.**
**606 ft.** **Site 2 of 4 in cluster AM**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | LA CLEANERS & TAILOR |
| Year: | 2010 |
| Address: | 130 UNION ST |
| Name: | LA CLEANERS & TAILOR |
| Year: | 2011 |
| Address: | 130 UNION ST |
| Name: | LA CLEANERS & TAILOR |
| Year: | 2012 |
| Address: | 130 UNION ST |

**AI297** **HAMILTON AVENUE** **NY Spills** **S102147262**
**SSW** **HAMILTON AVENUE** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.116 mi.**
**612 ft.** **Site 2 of 3 in cluster AI**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9309547 |
| Facility Type: | ER |
| DER Facility ID: | 144198 |
| Site ID: | 171352 |
| DEC Region: | 2 |
| Spill Date: | 11/6/1993 |
| Spill Number/Closed Date: | 9309547 / 11/29/1994 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 0301 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 11/6/1993 |
| CID: | Not reported |
| Water Affected: | KILL VAN KULL |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | 11/29/1994 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/9/1993 |
| Spill Record Last Update: | 11/29/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | DEP |
| Spiller Address: | 84 AVE B |
| Spiller City,St,Zip: | KINGS COUNTY, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | AUTOMOVILE GATE REGULATOR MALFUNCTIONED GATE STUCK CLOSED AND RESULTED IN SPILL. THE GATE HAS BEEN REPAIRED AND NO CALL BACK NECESSARY. REFER SPDES. |

Material:

| | |
|---|---|
| Site ID: | 171352 |
| Operable Unit ID: | 991094 |
| Operable Unit: | 01 |
| Material ID: | 392201 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**HAMILTON AVENUE (Continued)** **S102147262**

Tank Test:

---

**AN298** **EDR US Hist Cleaners** **1015002875**
**SSE** **169 SACKETT ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.117 mi.**
**618 ft.** **Site 1 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | WASHING WELL 7 |
| Year: | 1999 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL 7 |
| Year: | 2000 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2001 |
| Address: | 169 SACKETT ST |
| Name: | CHOIS LAUNDROMAT |
| Year: | 2003 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2005 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2006 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2007 |
| Address: | 169 SACKETT ST |
| Name: | CHOIS LAUNDROMAT |
| Year: | 2007 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2008 |
| Address: | 169 SACKETT ST |
| Name: | CHOIS LAUNDROMAT |
| Year: | 2008 |
| Address: | 169 SACKETT ST |
| Name: | WASHING WELL |
| Year: | 2009 |
| Address: | 169 SACKETT ST |
| Name: | CHOIS LAUNDROMAT |
| Year: | 2009 |
| Address: | 169 SACKETT ST |

**(Continued)** **1015002875**

Name: SACKETT LAUNDROMAT INC
Year: 2010
Address: 169 SACKETT ST

---

**AN299** **NYCDOT** **RCRA NonGen / NLR** **1000889996**
**SSE** **KANE SACKETT & UNION STS** **NY MANIFEST** **NY0000204487**
**< 1/8** **BROOKLYN, NY 11201**
**0.118 mi.**
**621 ft.** **Site 2 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: NYCDOT
Facility address: KANE SACKETT & UNION STS
OVER BQE
BROOKLYN, NY 11201
EPA ID: NY0000204487
Mailing address: RECTOR ST - 5TH FLOOR
NEW YORK, NY 10006
Contact: ALOK SARKAR
Contact address: RECTOR ST - 5TH FLOOR
NEW YORK, NY 10006
Contact country: US
Contact telephone: (212) 788-1806
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCDOT
Owner/operator address: 2 RECTOR ST - 5TH FLOOR
NEW YORK, NY 10006
Owner/operator country: US
Owner/operator telephone: (212) 788-1806
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCDOT
Owner/operator address: 2 RECTOR ST - 5TH FLOOR
NEW YORK, NY 10006
Owner/operator country: US
Owner/operator telephone: (212) 788-1806
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

**NYCDOT (Continued)** **1000889996**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCDOT
Classification: Not a generator, verified

Date form received by agency: 04/14/1994
Facility name: NYCDOT
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NY0000204487
Country: USA
Mailing Name: NYCDOT
Mailing Contact: ALEX BEZCHASTRON
Mailing Address: 2 RECTOR ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10006
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-788-2091

Document ID: NYG0433152
Manifest Status: Not reported
Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 05/08/1998
Trans1 Recv Date: 05/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/13/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000204487
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: PC4340
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02400
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

**NYCDOT (Continued)** **1000889996**

Year: 98

---

**AE300** **MANHOLE 1714** **NY Spills** **S111738013**
**NE** **HICKS ST/STATE ST** **N/A**
**< 1/8** **BROOKYLN, NY**
**0.118 mi.**
**622 ft.** **Site 20 of 20 in cluster AE**

**Relative:**
**Higher**

**Actual:**
**39 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1113303 |
| Facility Type: | ER |
| DER Facility ID: | 415741 |
| Site ID: | 461286 |
| DEC Region: | 2 |
| Spill Date: | 2/23/2012 |
| Spill Number/Closed Date: | 1113303 / 3/23/2012 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RWAUSTIN |
| Referred To: | Not reported |
| Reported to Dept: | 2/23/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/23/2012 |
| Spill Record Last Update: | 3/23/2012 |
| Spiller Name: | ERT |
| Spiller Company: | CON ED |
| Spiller Address: | HICKS ST/STATE ST |
| Spiller City,St,Zip: | BROOKYLN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | 2125808383 |
| DEC Memo: | 3/23/12 - Austin - Material presumed to be ACM was found in manhole - Con Ed contained and cleaned up the spill - See eDocs files for further details - Spill closed - end |
| Remarks: | 2 or more pounds released from a degraded cable. material is in manhole |

Material:

| | |
|---|---|
| Site ID: | 461286 |
| Operable Unit ID: | 1211378 |
| Operable Unit: | 01 |
| Material ID: | 2209160 |
| Material Code: | 0026A |
| Material Name: | ASBESTOS |
| Case No.: | 01332214 |
| Material FA: | Hazardous Material |
| Quantity: | 2 |

**MANHOLE 1714 (Continued)** **S111738013**

Units: Pounds
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AM301** **EDR US Hist Cleaners** **1014989244**
**South** **134 UNION ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.118 mi.**
**622 ft.** **Site 3 of 4 in cluster AM**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

EDR Historical Cleaners:

Name: BERNIES LAUNDROMAT
Year: 2005
Address: 134 UNION ST

Name: BERNIES LAUNDROMAT
Year: 2006
Address: 134 UNION ST

Name: BERNIES LAUNDROMAT
Year: 2007
Address: 134 UNION ST

Name: BERNIES LAUNDROMAT
Year: 2008
Address: 134 UNION ST

Name: UNION STREET SUPER WASH CTR
Year: 2010
Address: 134 UNION ST

Name: UNION STREET SUPER WASH CENTER
Year: 2011
Address: 134 UNION ST

Name: UNION STREET SUPER WASH CENTER
Year: 2012
Address: 134 UNION ST

---

**AM302** **BERNIES/COLUMBIA TERRACE LAUNDRY** **NY DRYCLEANERS** **S110246016**
**South** **134 UNION STREET** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.118 mi.**
**622 ft.** **Site 4 of 4 in cluster AM**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

DRYCLEANERS:

Facility ID: WET LAUNDRY?
Phone Number: Not reported
Region: 2
Registration Effective Date: N/A
Inspection Date: Not reported
Install Date: Not reported

**BERNIES/COLUMBIA TERRACE LAUNDRY (Continued)** **S110246016**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Y
Current Business: WET LAUNDRY?

---

**AC303** **PRISCILLA GOLD SEAL CORP INC** **NY UST** **U000412024**
**SSW** **65 COMMERCE STREET** **NY HIST UST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.119 mi.**
**630 ft.** **Site 3 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

UST:
Id/Status: 2-600305 / Unregulated
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 583884.50564999995
UTM Y: 4503732.8521999996
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 22288
Affiliation Type: On-Site Operator
Company Name: PRISCILLA GOLD SEAL CORP INC
Contact Type: Not reported
Contact Name: C. TAGLIANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 852-2500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22288
Affiliation Type: Emergency Contact
Company Name: PRISCILLA GOLD SEAL CORP INC
Contact Type: Not reported
Contact Name: C. TAGLIANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 852-2500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22288
Affiliation Type: Facility Owner

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

| | |
|---|---|
| Company Name: | PRISCILLA GOLD SEAL CORP INC |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 65 COMMERCE STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 852-2500 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22288 |
| Affiliation Type: | Mail Contact |
| Company Name: | PRISCILLA GOLD SEAL CORP |
| Contact Type: | Not reported |
| Contact Name: | LARRY KRUYSMAN |
| Address1: | 65 COMMERCE STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 852-2500 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 42110 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | Not reported |
| Date Tank Closed: | 03/01/1994 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 42111 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 1100 |
| Install Date: | Not reported |
| Date Tank Closed: | 03/01/1994 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Concrete |
| Material Code: | 9999 |
| Common Name of Substance: | Other |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 42112 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 1050 |
| Install Date: | Not reported |
| Date Tank Closed: | 03/01/1994 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 48212
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

HIST UST:
PBS Number: 2-600305
SPDES Number: Not reported
Emergency Contact: C. TAGLIANI
Emergency Telephone: (718) 852-2500
Operator: C. TAGLIANI
Operator Telephone: (718) 852-2500
Owner Name: PRISCILLA GOLD SEAL CORP INC
Owner Address: 65 COMMERCE STREET
Owner City,St,Zip: BROOKLYN, NY 11231
Owner Telephone: (718) 852-2500
Owner Type: Corporate/Commercial
Owner Subtype: Not reported

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

| | |
|---|---|
| Mailing Name: | PRISCILLA GOLD SEAL CORP |
| Mailing Address: | 65 COMMERCE STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11231 |
| Mailing Contact: | LARRY KRUYSMAN |
| Mailing Telephone: | (718) 852-2500 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Facility Addr2: | 65 COMMERCE STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | TRUCKING/TRANSPORTATION |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 10/09/1991 |
| Expiration Date: | 09/05/1996 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 0 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | 0 |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 550 |
| Product Stored: | DIESEL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 03/01/1994 |
| Test Method: | Not reported |
| Deleted: | False |

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

| | |
|---|---|
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 002 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 1100 |
| Product Stored: | UNKNOWN |
| Tank Type: | Stainless steel alloy |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 03/01/1994 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

| | |
|---|---|
| Tank Id: | 003 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 1050 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |
| Pipe Location: | Underground |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Vent Whistle |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | 03/01/1994 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

**PRISCILLA GOLD SEAL CORP INC (Continued)** **U000412024**

| | |
|---|---|
| Tank Id: | 004 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | Not reported |
| Capacity (gals): | 1000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |
| Pipe Location: | Underground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | None |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | 04/01/1994 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

---

**AO304** **EDR US Hist Auto Stat** **1015665944**
**South** **9 WOODHULL ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.120 mi.**
**633 ft.** **Site 1 of 4 in cluster AO**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | AUTO CONCEPTS TOWING INC |
| Year: | 2002 |
| Address: | 9 WOODHULL ST |
| Name: | AUTO CONCEPTS TOWING INC |
| Year: | 2003 |
| Address: | 9 WOODHULL ST |
| Name: | AUTO CONCEPTS TOWING INC |
| Year: | 2004 |
| Address: | 9 WOODHULL ST |
| Name: | MASPETH AUTOMOTIVE INC |
| Year: | 2005 |
| Address: | 9 WOODHULL ST |

**AC305** **NYC DEP** **FINDS** **1014814416**
**SSW** **RICHARDS ST & SEABRING ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.121 mi.**
**639 ft.** **Site 4 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

FINDS:

Registry ID: 110042432025

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

**AC306** **NYCDEP** **NY MANIFEST** **S108232129**
**SSW** **RICHARDS ST & SEABRING ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.121 mi.**
**639 ft.** **Site 5 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP003663010 |
| Country: | USA |
| Mailing Name: | NYCDEP |
| Mailing Contact: | N/S |
| Mailing Address: | 96-05 HORACE HARDING 1ST FL |
| Mailing Address 2: | Not reported |
| Mailing City: | CORONA |
| Mailing State: | NY |
| Mailing Zip: | 11368 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 917-682-3267 |

NY MANIFEST:
No Manifest Records Available

---

**AC307** **NYC DEP** **RCRA NonGen / NLR** **1014395408**
**SSW** **RICHARDS ST & SEABRING ST** **NYP003663010**
**< 1/8** **BROOKLYN, NY 11231**
**0.121 mi.**
**639 ft.** **Site 6 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 08/08/2006 |
| Facility name: | NYC DEP |
| Facility address: | RICHARDS ST & SEABRING ST<br>BROOKLYN, NY 11231 |
| EPA ID: | NYP003663010 |
| Mailing address: | JUNCTION BLVD<br>FLUSHING, NY 11373 |
| Contact: | JOANNE NURSE |
| Contact address: | JUNCTION BLVD |

**NYC DEP (Continued)** **1014395408**

FLUSHING, NY 11373
Contact country: US
Contact telephone: (718) 595-4675
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

---

**AC308** **CON EDISON MANHOLE: 61249** **RCRA-CESQG** **1016149182**
**SSW** **RICHARDS ST & SEABRING ST SW** **NYP004278420**
**< 1/8** **BROOKLYN, NY 11201**
**0.121 mi.**
**639 ft.** **Site 7 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

RCRA-CESQG:
Date form received by agency: 11/16/2012
Facility name: CON EDISON MANHOLE: 61249
Facility address: RICHARDS ST & SEABRING ST SW
COR
BROOKLYN, NY 11201
EPA ID: NYP004278420
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MABLE MUI
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 321-4602
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

**CON EDISON MANHOLE: 61249 (Continued)** **1016149182**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

---

**AC309** **F.D.N.Y. ENG.CO. 202** **NY UST** **U003764764**
**SSW** **31 RICHARDS STREET** **NY AST** **N/A**
**< 1/8** **BROOKLYN, NY 11231** **NY HIST AST**
**0.121 mi.**
**640 ft.** **Site 8 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-600495 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2014/07/21 |
| UTM X: | 583993.93666000001 |
| UTM Y: | 4503748.0177100003 |
| Site Type: | Municipality (Incl. Waste Water Treatment Plants, |

Affiliation Records:

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Emergency Contact |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | EOC/NOTIFICATION DESK |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 999-2094 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 8/23/2012 |

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Mail Contact |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | ASST COMMR JOSEPH M. MASTROPIETRO |
| Address1: | 48-34 35TH STREET |
| Address2: | Not reported |
| City: | LONG ISLAND CITY, |
| State: | NY |
| Zip Code: | 11101 |
| Country Code: | 001 |
| Phone: | (718) 784-6510 |
| EMail: | MASTROY@FDNY.NYC.GOV |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/16/2009 |

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | On-Site Operator |
| Company Name: | F.D.N.Y. ENG.CO. 202 |
| Contact Type: | Not reported |
| Contact Name: | COMPANY OFFICER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 965-8202 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Facility Owner |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 9 METRO-TECH |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201-3857 |
| Country Code: | 001 |
| Phone: | (718) 999-7900 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/4/2010 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 42845 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

| | |
|---|---|
| Capacity Gallons: | 550 |
| Install Date: | 03/01/1997 |
| Date Tank Closed: | 03/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 60029 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 1000 |
| Install Date: | 03/01/1997 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/08/2013 |

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-600495 |
| Program Type: | PBS |
| UTM X: | 583993.93666000001 |
| UTM Y: | 4503748.0177100003 |
| Expiration Date: | 2014/07/21 |
| Site Type: | Municipality (Incl. Waste Water Treatment Plants, |

Affiliation Records:

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Emergency Contact |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | EOC/NOTIFICATION DESK |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 999-2094 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 8/23/2012 |

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Mail Contact |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | ASST COMMR JOSEPH M. MASTROPIETRO |
| Address1: | 48-34 35TH STREET |
| Address2: | Not reported |
| City: | LONG ISLAND CITY, |
| State: | NY |
| Zip Code: | 11101 |
| Country Code: | 001 |
| Phone: | (718) 784-6510 |
| EMail: | MASTROY@FDNY.NYC.GOV |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/16/2009 |

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | On-Site Operator |
| Company Name: | F.D.N.Y. ENG.CO. 202 |
| Contact Type: | Not reported |
| Contact Name: | COMPANY OFFICER |
| Address1: | Not reported |

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

| | |
|---|---|
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 965-8202 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22476 |
| Affiliation Type: | Facility Owner |
| Company Name: | FIRE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 9 METRO-TECH |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201-3857 |
| Country Code: | 001 |
| Phone: | (718) 999-7900 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 2/4/2010 |

Tank Info:

| | |
|---|---|
| Tank Number: | 002 |
| Tank Id: | 42846 |
| Material Code: | ZZZZ |
| Common Name of Substance: | Invalid Material - Please Fix |

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | ZZ |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 2500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 02/01/2001 |
| Register: | True |

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

| | |
|---|---|
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | Invalid Material - Please Fix |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-600495 |
| SWIS Code: | 6101 |
| Operator: | COMPANY OFFICER |
| Facility Phone: | (718) 965-8202 |
| Facility Addr2: | 31 RICHARDS STREET |
| Facility Type: | OTHER |
| Emergency: | EOC/NOTIFICATION DESK |
| Emergency Tel: | (718) 999-2094 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | FIRE DEPARTMENT |
| Owner Address: | 9 METRO-TECH |
| Owner City,St,Zip: | BROOKLYN, NY 11201-3857 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 999-2094 |
| Owner Type: | Local Government |
| Owner Subtype: | Not reported |
| Mailing Contact: | DIRECTOR;BLDG. MAIN. DIV. |
| Mailing Name: | FIRE DEPARTMENT |
| Mailing Address: | 48-34 35TH STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | LONG ISLAND CITY,, N.Y. 11101 |
| Mailing Telephone: | (718) 784-6510 |
| Owner Mark: | First Owner |
| Facility Status: | 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14. |
| Certification Flag: | False |
| Certification Date: | 11/06/1997 |
| Expiration: | 12/20/2001 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 1000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 002 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | Closed-Removed |
| Install Date: | Not reported |
| Capacity (Gal): | 2500 |
| Product Stored: | Not reported |
| Tank Type: | Not reported |

**F.D.N.Y. ENG.CO. 202 (Continued)** **U003764764**

| | |
|---|---|
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | Not reported |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | Not reported |
| Leak Detection: | Not reported |
| Overfill Protection: | Not reported |
| Dispenser Method: | Not reported |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Major Data Missing (which is on the certificate) |
| Date Closed: | 02/01/2001 |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**AC310** **ENGINE CO. 202/LADD. CO. 10 FDNY -DDC** **NY Spills** **S102239742**
**SSW** **31 RICHARDS STREET** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.121 mi.**
**640 ft.** **Site 9 of 9 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9600812 |
| Facility Type: | ER |
| DER Facility ID: | 176036 |
| Site ID: | 212485 |
| DEC Region: | 2 |
| Spill Date: | 4/17/1996 |
| Spill Number/Closed Date: | 9600812 / 12/9/2005 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | ADZHITOM |
| Referred To: | Not reported |
| Reported to Dept: | 4/17/1996 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/17/1996 |
| Spill Record Last Update: | 12/14/2005 |
| Spiller Name: | LT ROBERT WHEELER |
| Spiller Company: | ENGINE CO 202 |
| Spiller Address: | 31 RICHARDS ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |

**ENGINE CO. 202/LADD. CO. 10 FDNY -DDC (Continued)** **S102239742**

| | |
|---|---|
| Contact Name: | LT ROBERT WHEELER |
| Contact Phone: | (718) 965-8202 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"5-24-2005 I have reviewed a Monitoring Report for the remedial system received on April 27, 2005. The report presented remedial system performance monitoring data. The report stated that based on the site monitoring data, soil VOC levels are now below NYSDEC TAGM #4046 soil cleanup values and air influent testing showed little remaining contamination. LiRo recommended shutting down the SVE system and continuing groundwater sampling. The Department concured with this proposal.A letter was issued. AZ 12/09/05 I have reviewed a Monitoring Report for the site dated October 28, 2005. The report presented groundwater monitoring data. Previous investigations have shown that the SVE system effectively remediated soil. The current report stated that based on the site monitoring data, LiRo recommended closing this spill. All free product has been eliminated and groundwater sampling results indicate no significant residual impact to groundwater. NFA letter was issued on 12/06/2005. AZ |
| Remarks: | contaminated soil around storage tank |

Material:

| | |
|---|---|
| Site ID: | 212485 |
| Operable Unit ID: | 1028530 |
| Operable Unit: | 01 |
| Material ID: | 556536 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AN311** **EDR US Hist Auto Stat** **1015548672**
**SSE** **547 HICKS ST** **N/A**
**< 1/8** **BROOKLYN, NY 11231**
**0.123 mi.**
**649 ft.** **Site 3 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | ALFA OF BROOKLYN MOTORS INC |
| Year: | 2001 |
| Address: | 547 HICKS ST |
| Name: | ALFA OF BROOKLYN MOTORS INC |
| Year: | 2002 |
| Address: | 547 HICKS ST |
| Name: | ALFA OF BROOKLYN MOTORS INC |
| Year: | 2003 |
| Address: | 547 HICKS ST |
| Name: | ALFA OF BROOKLYN MOTORS INC |

**(Continued)** **1015548672**

Year: 2005
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2006
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2007
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2008
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2009
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2010
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2011
Address: 547 HICKS ST

Name: ALFA OF BROOKLYN MOTORS INC
Year: 2012
Address: 547 HICKS ST

---

**AA312**
**SSE**
**< 1/8**
**0.123 mi.**
**651 ft.**

**KINGS HARBOR VIEW-PIER 44** **FINDS** **1007802511**
**163 DEGRAW STREET** **N/A**
**BROOKLYN, NY**

**Site 5 of 5 in cluster AA**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

FINDS:

Registry ID: 110019650386

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**AP313** **TM1419** **FINDS** **1007252895**
**South** **CARROLL ST & COLUMBIA ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.125 mi.**
**659 ft.** **Site 1 of 4 in cluster AP**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

FINDS:

Registry ID: 110017256976

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

**AP314** **PM 1419** **NY Spills** **S103829266**
**South** **COLUMBIA ST & CARROLL ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.125 mi.**
**659 ft.** **Site 2 of 4 in cluster AP**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9815132 |
| Facility Type: | ER |
| DER Facility ID: | 242259 |
| Site ID: | 299457 |
| DEC Region: | 2 |
| Spill Date: | 3/22/1999 |
| Spill Number/Closed Date: | 9815132 / 6/6/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 3/22/1999 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/22/1999 |
| Spill Record Last Update: | 9/29/2004 |
| Spiller Name: | UNKNOWN |
| Spiller Company: | UNKNOWN |
| Spiller Address: | UNKNOWN |
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was |

**PM 1419 (Continued)** **S103829266**

"ENGELHARDT"Con Ed e2mis #123763:A.MARCHIONE#14459 LEAD MECHANIC CABLE GANG REPORTS AN UNDIAPERABLE SHEEN IN TM1419 COLUMBIA ST & CARROLL ST.NO SEWERS OR WATERWAYS AFFECTED SAMPLE TAKEN-MARKED FOR 4-6HOUR TURNAROUND & E.S.TAG#14371 PLACED. NO PARKING 8-11 TUESDAY & FRIDAY.update 3-22-99 CHEM RESULTS 99-02916 < 1 PPM UPDATE: 3/22/99 - 1345N. DREVITCH - 75896 - ENV. OPS., REPORTS <1.0 PPM CLEANUP COMPLETE WITH SLIX . TAG WAS NOT FOUND. STRUCTURE WAS VERIFIED ONM&S PLATE. INCIDENT IS CLOSED.

Remarks: sheen on 100 gal of water in a transformer manhole - con ed 123763clean up pending test results

Material:

| | |
|---|---|
| Site ID: | 299457 |
| Operable Unit ID: | 1072995 |
| Operable Unit: | 01 |
| Material ID: | 308254 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AN315** **174 SACKETT ST.** **NY Spills** **S102146323**
**SSE** **174 SACKETT ST** **N/A**
**< 1/8** **BROOKLYN, NY**
**0.125 mi.**
**659 ft.** **Site 4 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9214467 |
| Facility Type: | ER |
| DER Facility ID: | 230709 |
| Site ID: | 284515 |
| DEC Region: | 2 |
| Spill Date: | 3/31/1993 |
| Spill Number/Closed Date: | 9214467 / 2/11/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SULLIVAN |
| Referred To: | Not reported |
| Reported to Dept: | 3/31/1993 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**174 SACKETT ST. (Continued)** **S102146323**

| | |
|---|---|
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/1/1993 |
| Spill Record Last Update: | 3/12/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | FIRST NOTICED LAST JUNE. NOW IS RECURRING WITH NEW SPRING RUNOFF. |

Material:

| | |
|---|---|
| Site ID: | 284515 |
| Operable Unit ID: | 978537 |
| Operable Unit: | 01 |
| Material ID: | 400673 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AP316**
**South**
**1/8-1/4**
**0.125 mi.**
**662 ft.**

**257 COLUMBIA ST** **EDR US Hist Cleaners** **1015029404**
**BROOKLYN, NY 11231** **N/A**

**Site 3 of 4 in cluster AP**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | RITAS DRY CLEANERS |
| Year: | 2001 |
| Address: | 257 COLUMBIA ST |
| Name: | RITAS DRY CLEANERS |
| Year: | 2002 |
| Address: | 257 COLUMBIA ST |
| Name: | RITAS DRY CLEANERS |
| Year: | 2003 |
| Address: | 257 COLUMBIA ST |
| Name: | RITAS DRY CLEANERS |
| Year: | 2004 |
| Address: | 257 COLUMBIA ST |
| Name: | RITAS DRY CLEANERS |
| Year: | 2006 |
| Address: | 257 COLUMBIA ST |

**(Continued)** **1015029404**

Name: RITAS DRY CLEANERS
Year: 2007
Address: 257 COLUMBIA ST

Name: RITAS DRY CLEANERS
Year: 2008
Address: 257 COLUMBIA ST

Name: RITAS DRY CLEANERS
Year: 2009
Address: 257 COLUMBIA ST

Name: RITAS DRY CLEANERS
Year: 2010
Address: 257 COLUMBIA ST

Name: RITAS DRY CLEANERS
Year: 2011
Address: 257 COLUMBIA ST

Name: RITAS DRY CLEANERS
Year: 2012
Address: 257 COLUMBIA ST

---

**AD317** **EDR US Hist Auto Stat** **1015390802**
**South** **288 COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.127 mi.**
**669 ft.** **Site 9 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

EDR Historical Auto Stations:
Name: GB AUTO TOWING INC
Year: 2006
Address: 288 COLUMBIA ST

---

**AJ318** **124 KANE STREET** **NY Spills** **S106014852**
**ESE** **124 KANE STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.127 mi.**
**673 ft.** **Site 2 of 3 in cluster AJ**

**Relative:**
**Higher**

**Actual:**
**20 ft.**

SPILLS:
Facility ID: 0302546
Facility Type: ER
DER Facility ID: 81946
Site ID: 89731
DEC Region: 2
Spill Date: 6/9/2003
Spill Number/Closed Date: 0302546 / 7/17/2003
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 6/10/2003

**124 KANE STREET (Continued)** **S106014852**

| | |
|---|---|
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/10/2003 |
| Spill Record Last Update: | 7/17/2003 |
| Spiller Name: | JOANN FUTTILE |
| Spiller Company: | METRO FUEL |
| Spiller Address: | 500 KINGSLANG AVENUE |
| Spiller City,St,Zip: | BROOKLYN, NY 11222- |
| Spiller Company: | 001 |
| Contact Name: | JOANN FUTTILE |
| Contact Phone: | (718) 383-1400 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"Sangesland DDOTipple made site visit6/11/03 TIPPLE FOUND METRO DOING CLEANUP/ INQUIRED OF PART 364 TRANSPORT PERMIT, METRO DID NOT KNOW ANYTHING ABOUT THIS PERMIT/ PTC TO FINISH THE CLEANUP AND DISPOSAL/ MANIFESTS TO FOLLOW.7/17/03 manifest arrives/nfa// |
| Remarks: | MADE DELIVERY TO WRONG HOUSE DRAIN THERE ALSO |

Material:

| | |
|---|---|
| Site ID: | 89731 |
| Operable Unit ID: | 869368 |
| Operable Unit: | 01 |
| Material ID: | 507018 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 76 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AD319** **EDR US Hist Cleaners** **1015035072**
**South** **289 COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.130 mi.**
**684 ft.** **Site 10 of 10 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | PIMENTEL DRY CLEANERS |
| Year: | 2011 |
| Address: | 289 COLUMBIA ST |
| Name: | PIMENTEL DRY CLEANERS |
| Year: | 2012 |
| Address: | 289 COLUMBIA ST |

**AO320** **EDR US Hist Auto Stat** **1015236283**
**South** **15 WOODHULL ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.132 mi.**
**697 ft.** **Site 2 of 4 in cluster AO**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

EDR Historical Auto Stations:
Name: HAPPY HORSE TIRE & RBR RCYCLNG
Year: 2003
Address: 15 WOODHULL ST

---

**AF321** **INLAY STREET AT COMMERCE** **NY Spills** **S102144549**
**SW** **INLAY STREET @ COMMERCE** **N/A**
**1/8-1/4** **NEW YORK CITY, NY**
**0.132 mi.**
**699 ft.** **Site 8 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8701486 |
| Facility Type: | ER |
| DER Facility ID: | 64565 |
| Site ID: | 67606 |
| DEC Region: | 2 |
| Spill Date: | 5/21/1987 |
| Spill Number/Closed Date: | 8701486 / 8/12/1987 |
| Spill Cause: | Deliberate |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 5/21/1987 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Tank Truck |
| Spill Notifier: | DEC |
| Cleanup Ceased: | 8/12/1987 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/26/1987 |
| Spill Record Last Update: | 8/12/1987 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported |
| Remarks: | SEMI-TANK TRAILER ABANDONNED ON STREET; OIL SEEPING OUT OF PIPELINE. |

Material:

| | |
|---|---|
| Site ID: | 67606 |
| Operable Unit ID: | 907953 |
| Operable Unit: | 01 |
| Material ID: | 471413 |
| Material Code: | 0066A |

**INLAY STREET AT COMMERCE (Continued)** **S102144549**

| | |
|---|---|
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AI322** **SPILL NUMBER 0306452** **NY Spills** **S106018222**
**SSW** **HAMILTON AV & RICHARD ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.133 mi.**
**703 ft.** **Site 3 of 3 in cluster AI**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0306452 |
| Facility Type: | ER |
| DER Facility ID: | 132983 |
| Site ID: | 157237 |
| DEC Region: | 2 |
| Spill Date: | 9/18/2003 |
| Spill Number/Closed Date: | 0306452 / 10/15/2003 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required. |
| SWIS: | 2401 |
| Investigator: | SKARAKHA |
| Referred To: | Not reported |
| Reported to Dept: | 9/18/2003 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/18/2003 |
| Spill Record Last Update: | 10/27/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | 9-18-03 10:10HRS 14757 (NET) REPORTS, FOUND UNKNOWN AND UNDIAPERABLE SHEEN ON 0 GALLONS OF WATER IN V 5261. AT THISTIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED. NO INJURIES WERE RELATED TO SPILL AND NO WEATHER CONDITIONS CONTRIBUTED TO HAZARD OF SPILL. OIL WAS DISCOVERED |

**SPILL NUMBER 0306452 (Continued)** **S106018222**

WHILE ON INSPECTIONS FOR FEEDER 1B5. (INSTALLING OIL MINDER) ENV STOP TAG 34844 WAS PLACED, AND THE STANDING WATER THAT IS PRESENT HAS NO MOVEMENT. SEWER CONNECTION NOTICED AND FOUND SUMP PUMP DISCONNECTED.ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORTY AND CLEANUP PENDING LAB SAMPLE. PRESSURE TESTED TRANSFORMER AND PASSED. ALSO STATED HE FOUND SLIGHT LEAK ON PRIMARY CABLE BUT CANNOT VERITFY IF THAT IS SAME OIL FOUND IN PIT. REQUESTED #9 CREW TO INSPECT CABLE. S. PACE 49874.UPDATE**********9-18-03 10:50HRS JOB WILL BE TAKEN O DEPT SUPV. REPORTS CABLE NOT LEAKING AT THIS TIME, BOND ON PRIMARY NEEDS PER-REPAIR. C.HOGAN 075119/19/03=0213 LAB RESULT .MATRIX: OIL GRABLOCATION: HAMILTON AVE + RICHARD'S STSTRUCTURE: VAULT 5261 FEEDER ID:Environmental Detailed Incident ReportQC ID: 03-200309060116TEST DESCRIPTION RESULT UNIT METHODAroclor 1242 < 1.0 ppm EPA 608/8082Aroclor 1254 90.9 ppm EPA 608/8082Aroclor 1248 < 1.0 ppm EPA 608/8082Aroclor 1260 < 1.0 ppm EPA 608/8082TOTAL PCB 91 ppmEPA#004-115-101 TANKER ORDERED FOR AM.UPDATE @ 1215 HRS 9/19 E.WILLIAMS ENVIROMENTAL SUPERVISOR REPORTS STRUCTURE DOUBLE WASHED WITH BIO GEN 760,ENVIROMENTAL TAG REMOVED. SUMP PUMP IN STRUCTURE OPPERATIONAL & REMAINS ACTIVE. CLEANUP COMPLETED. #12255 VDC.On 9/19/03 Environmental Operations crew Mech. A. Lugo, Mech. Carson, and G.U.W. Ryan was assigned to clean up VS 5261 with 91ppm PCB?s located N/S Hamilton Ave 100? E/O Van Brunt St on the walk. One drum of debris and 50 gallons of liquid was removed from the structure. There was a cemented sump with a working pump installed. The structure was double washed with 10 gallons of 760 Biogen; Environmental stop tag #34844 was removed the job is 100%completed.barrell returned to 3rd ave yard on 1-trip rule.?GENE?Update - 9/19/03 @ 1450 hrs - updated event involved materials and event involved persons lists. Additionally, changed organization from Networks to FlushOperations. H Bertorelli # 54348.

Remarks: vault 5261 - sheen on 20 gal of water - leaking from a cable - ref #150386

Material:

| | |
|---|---|
| Site ID: | 157237 |
| Operable Unit ID: | 875211 |
| Operable Unit: | 01 |
| Material ID: | 503676 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AL323** **55 COMMERCE ST/BKLYN** **NY Spills** **S102142304**
**SSW** **55 COMMERCE STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.135 mi.**
**713 ft.** **Site 3 of 3 in cluster AL**

**Relative:**
**Higher**

**Actual:**
**7 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8801960 |
| Facility Type: | ER |
| DER Facility ID: | 82116 |
| Site ID: | 91092 |
| DEC Region: | 2 |
| Spill Date: | 6/2/1988 |
| Spill Number/Closed Date: | 8801960 / 8/7/1995 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KORMANIK |
| Referred To: | Not reported |
| Reported to Dept: | 6/2/1988 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | 8/7/1995 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/2/1988 |
| Spill Record Last Update: | 3/25/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | JOB CHEMICALS |
| Spiller Address: | 55 COMMERCE STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | CHEMICAL COMPANY OPERATING STACK WITHOUT PERMIT, STACK HAS UNPERMITTEDGAS FLAME, RUNNIGN PERIODICALLY DURING BATCH REACTION, LIQUID WAX FOR CAR WASH. |

Material:

| | |
|---|---|
| Site ID: | 91092 |
| Operable Unit ID: | 919126 |
| Operable Unit: | 01 |
| Material ID: | 461091 |
| Material Code: | 1576A |
| Material Name: | REACTION VAPOR |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | -1 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**55 COMMERCE ST/BKLYN (Continued)** **S102142304**

Tank Test:

---

**324**
**SSW**
**1/8-1/4**
**0.140 mi.**
**738 ft.**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

**BRUNO TRUCK SALES** **RCRA NonGen / NLR** **1001215535**
**50 COMMERCE ST** **FINDS** **NYR000046789**
**BROOKLYN, NY**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | BRUNO TRUCK SALES |
| Facility address: | 50 COMMERCE ST<br>BROOKLYN, NY 112311643 |
| EPA ID: | NYR000046789 |
| Mailing address: | COMMERCE ST<br>BROOKLYN, NY 11231 |
| Contact: | Not reported |
| Contact address: | COMMERCE ST<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | BRUNO TRUCK SALES |
| Owner/operator address: | 50 COMMERCE ST<br>BROOKLYN, NY 11231 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 243-2980 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | BRUNO TRUCK SALES |
| Owner/operator address: | 50 COMMERCE ST<br>BROOKLYN, NY 11231 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 243-2980 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |

**BRUNO TRUCK SALES (Continued)** **1001215535**

| | |
|---|---|
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Historical Generators:

| | |
|---|---|
| Date form received by agency: | 01/01/2006 |
| Facility name: | BRUNO TRUCK SALES |
| Classification: | Not a generator, verified |
| Date form received by agency: | 07/08/1999 |
| Facility name: | BRUNO TRUCK SALES |
| Classification: | Not a generator, verified |
| Date form received by agency: | 11/03/1997 |
| Facility name: | BRUNO TRUCK SALES |
| Classification: | Small Quantity Generator |
| Violation Status: | No violations found |

FINDS:

Registry ID: 110004538493

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

**AO325** **MOBIL S/S 17-EMW** **NY UST** **U001838910**
**South** **304 COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.140 mi.**
**740 ft.** **Site 3 of 4 in cluster AO**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-157252 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584171.58600999997 |
| UTM Y: | 4503879.61986 |
| Site Type: | Retail Gasoline Sales |

Affiliation Records:

| | |
|---|---|
| Site Id: | 5196 |
| Affiliation Type: | On-Site Operator |
| Company Name: | MOBIL S/S 17-EMW |
| Contact Type: | Not reported |

**MOBIL S/S 17-EMW (Continued)** **U001838910**

| | |
|---|---|
| Contact Name: | JIM DOWSE |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 875-2900 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 5196 |
| Affiliation Type: | Emergency Contact |
| Company Name: | MOBIL OIL CORP |
| Contact Type: | Not reported |
| Contact Name: | MOBIL OIL CORP. |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (800) 662-4567 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 5196 |
| Affiliation Type: | Mail Contact |
| Company Name: | MOBIL OIL CORP |
| Contact Type: | Not reported |
| Contact Name: | E.D. SARABIA / EARTH |
| Address1: | 3225 GALLOWS RD. |
| Address2: | Not reported |
| City: | FAIRFAX |
| State: | VA |
| Zip Code: | 22037 |
| Country Code: | 001 |
| Phone: | (703) 849-5866 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 5196 |
| Affiliation Type: | Facility Owner |
| Company Name: | MOBIL OIL CORP |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 3225 GALLOWS RD. |
| Address2: | Not reported |
| City: | FAIRFAX |
| State: | VA |
| Zip Code: | 22037 |

**MOBIL S/S 17-EMW (Continued)** **U001838910**

| | |
|---|---|
| Country Code: | 001 |
| Phone: | (703) 849-5862 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | CGFREEDM |
| Date Last Modified: | 12/14/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 27540 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1979 |
| Date Tank Closed: | 04/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 27541 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1979 |
| Date Tank Closed: | 04/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |

**MOBIL S/S 17-EMW (Continued)** **U001838910**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 27542
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1971
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

Tank Number: 011
Tank ID: 27543
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1989
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology

**MOBIL S/S 17-EMW (Continued)** **U001838910**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F03 - Pipe External Protection - Original Impressed Current
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
H04 - Tank Leak Detection - Groundwater Well
B04 - Tank External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 012
Tank ID: 27544
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1989
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 06/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F03 - Pipe External Protection - Original Impressed Current
I01 - Overfill - Float Vent Valve
H04 - Tank Leak Detection - Groundwater Well
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 013
Tank ID: 27545

**MOBIL S/S 17-EMW (Continued)** **U001838910**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1989
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 06/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F03 - Pipe External Protection - Original Impressed Current
I01 - Overfill - Float Vent Valve
H04 - Tank Leak Detection - Groundwater Well
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 014
Tank ID: 27546
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 09/01/1989
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D00 - Pipe Type - No Piping
I01 - Overfill - Float Vent Valve

**MOBIL S/S 17-EMW (Continued)** **U001838910**

H04 - Tank Leak Detection - Groundwater Well
B04 - Tank External Protection - Fiberglass
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

| | |
|---|---|
| Tank Number: | 015 |
| Tank ID: | 50675 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 1000 |
| Install Date: | 09/01/1989 |
| Date Tank Closed: | 04/01/1997 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)

---

**AO326** **MOBIL OIL CORP SS #EMW** **RCRA NonGen / NLR** **1000553836**
**South** **304 COLUMBIA ST** **FINDS** **NYD986962702**
**1/8-1/4** **BROOKLYN, NY 11231** **NY LTANKS**
**0.140 mi.** **NY MANIFEST**
**740 ft.** **Site 4 of 4 in cluster AO** **NY Spills**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | MOBIL OIL CORP SS #EMW |
| Facility address: | 304 COLUMBIA ST<br>BROOKLYN, NY 112311311 |
| EPA ID: | NYD986962702 |
| Mailing address: | GALLOWS RD - MKTG ENVIRON<br>FAIRFAX, NY 220370001 |
| Contact: | Not reported |
| Contact address: | GALLOWS RD - MKTG ENVIRON<br>FAIRFAX, NY 220370001 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MOBIL OIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: US
Owner/operator telephone: (703) 849-3330
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MOBIL OIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: US
Owner/operator telephone: (703) 849-3330
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MOBIL OIL CORP SS #EMW
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: MOBIL OIL CORP SS #EMW
Classification: Not a generator, verified

Date form received by agency: 04/10/1991
Facility name: MOBIL OIL CORP SS #EMW
Classification: Small Quantity Generator

Violation Status: No violations found

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

FINDS:

Registry ID: 110001573333

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:

| | |
|---|---|
| Site ID: | 59312 |
| Spill Number/Closed Date: | 9312498 / 5/14/2003 |
| Spill Date: | 1/24/1994 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Gasoline Station |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | MDMACCAB |
| Referred To: | Not reported |
| Reported to Dept: | 1/24/1994 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/26/1994 |
| Spill Record Last Update: | 6/1/2005 |
| Spiller Name: | MIKE MEOLA |
| Spiller Company: | EXXONMOBIL CORPORATION |
| Spiller Address: | 464 DOUGHTY BLVD. |
| Spiller City,St,Zip: | INWOOD, NY 11096 |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 57380 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MACCABE"This spill site has been transferred from DEC Sigona to RemedialBureau B, on August 4, 2003.This spill site cleanup has been consolidated under Spill No.8904339.Reassigned from Tomasello to Sigona on 10/30/00.03/29/95: SEE SPILL NUMBER 8904339. 10/10/95: This is additional information about material spilled from the translation of the old spill file: SPECIAL.DEC's (Sigona) comments- regarding a Subsurface Investigation Report from Groundwater & Environmental Services (GES), dated December 2, 2003, and amended Proposed Monitoring Well & Soil Boring Map, dated February 14, 2003. The DEC |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

conducted a site visit on February 10, 2003 with ExxonMobil representatives to evaluate the results of the investigation and proposed locations for on-site and off-site borings and monitoring wells necessary to de-lineate the vertical and horizontal extent of petroleum contamination.

Remarks: TO REMOVE PRODUCT & INVEST FOR LEAK.

Material:

| | |
|---|---|
| Site ID: | 59312 |
| Operable Unit ID: | 994495 |
| Operable Unit: | 01 |
| Material ID: | 387928 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 59312 |
| Spill Tank Test: | 1542387 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Unknown |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD986962702 |
| Country: | USA |
| Mailing Name: | MOBIL OIL CORP SS #EMW |
| Mailing Contact: | ROSEANN FAVARO |
| Mailing Address: | 3225 GALLOWS RD - MKTG |
| Mailing Address 2: | Not reported |
| Mailing City: | FAIRFAX |
| Mailing State: | VA |
| Mailing Zip: | 22037 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 703-849-3330 |

| | |
|---|---|
| Document ID: | NYB8433612 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | PD1011NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 970430 |
| Trans1 Recv Date: | 970430 |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

| | |
|---|---|
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 970430 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 970522 |
| Generator EPA ID: | NYD986962702 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00165 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 003 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 97 |

SPILLS:

| | |
|---|---|
| Facility ID: | 8904339 |
| Facility Type: | ER |
| DER Facility ID: | 57380 |
| Site ID: | 59311 |
| DEC Region: | 2 |
| Spill Date: | 8/1/1989 |
| Spill Number/Closed Date: | 8904339 / Not Reported |
| Spill Cause: | Housekeeping |
| Spill Class: | Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MDMACCAB |
| Referred To: | P2 |
| Reported to Dept: | 8/1/1989 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 4 |
| Date Entered In Computer: | 8/3/1989 |
| Spill Record Last Update: | 2/7/2014 |
| Spiller Name: | MIKE MEOLA |
| Spiller Company: | EXXONMOBIL CORPORATION |
| Spiller Address: | 3225 GALLOWS ROAD |
| Spiller City,St,Zip: | FAIRFAX, VA 22037- |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | This spill site cleanup has been consolidated under Spill No. 8904339.Reassigned from Tomasello to Sigona on 10/30/00. DEC's comments regarding a letter from Groundwater & Environmental Services (GES), dated February 21, 2002 which provides a proposed plan to install four (4) soil borings along Hamilton Avenue. The letter indicates that soil and groundwater samples will be collected from |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

the soil borings to attempt to delineate the extent of free and dissolved petroleum contamination at off-site locations.On February 19, 2002, the DEC's legal and technical staff discussed the site history for 304 Columbia Street with ExxonMobil's legal and technical representatives. It is my understanding that it was agreed that a full site characterization and delineation of the free and dissolved plume would be proposed. The plan submitted by GES is incomplete and only provides a limited investigation of the possible extent of soil and groundwater contamination. The DEC requests a more thorough site investigation and off-site delineation of the source contamination, vertical and horizontal extent of the plume, and evaluation of possible receptors. Moreover, the DEC requires a development of a corrective action plan based on a performance based evaluation of various remedial alternatives. A letter to Joanne Wallach at ExxonMobil was sent certified mail return receipt on March 1, 2002.DEC's (Sigona) comments- regarding a Subsurface Investigation Report from Groundwater & Environmental Services (GES), dated December 2, 2003, and amended Proposed Monitoring Well & Soil Boring Map, dated February 14, 2003. The DEC conducted a site visit on February 10, 2003 with ExxonMobil representatives to evaluate the results of the investigation and proposed locations for on-site and off-site borings and monitoring wells necessary to delineate the vertical and horizontal extent of petroleum contamination. 4/27/10 - M. MacCabe - The March quarterly report states that additional chemox injections can't be done at this time due to a half-foot increase in the water table elevation. Due to the presence of LPH in three wells at up to 0.7 feet deep, surfactant injections are planned.6/23/10 - Surfactant injection was conducted on June 21.9/27/10 - A second surfactant injection and recovery was conducted in late July / early August. Future groundwater sampling will evaluate the effectiveness of the second surfactant injection action.12/24/10 - The periodic review report was received. There is no significant change in groundwater contaminant concentrations. Chemical oxidant injections were conducted in early December.3/1/11 - A site status update report was received with groundwater data obtained before the December 2010 chemox injections. The data indicate a reduction in contaminant concentrations in some wells.5/26/11 - A quarterly site status update report was received. Quarterly groundwater monitoring data show some decrease in BTEX concentrations in some wells. A third surfactant / chemox injection is proposed.8/30/11 - The quarterly site status update report was received. Of the fourteen groundwater monitoring wells gaged and sampled during the June, 2011 sampling event, four contained liquid-phase hydrocarbon (LPH) up to 1.5 feet deep. BTEX concentrations increased in seven wells and were generally consistent in the remaining wells sampled. A third in-situ chemical oxidation (ISCO) injection event was conducted in mid August.12/20/11 - The quarterly site status update report was received. The third in-situ chemical oxidation (ISCO) injection event was conducted in mid August. The post-ISCO groundwater sampling conducted in September showed a reduction in contaminant concentrations in some of the monitoring wells.1/24/12 - Effective January 1, 2012, the consultant working for ExxonMobil on this project changed from Kleinfelder to Groundwater and Environmental Services (GES). 2/29/12 - Staff met with representatives of ExxonMobil and GES on February 28 to discuss another remedial approach. The chemox injections have not been effective in reducing contaminant concentration in groundwater. GES theorizes that a source remains in soil immediately down gradient

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

from the former location of the USTs. GES proposes excavation of that area. However, the area to be excavated is in the public right of way (under the sidewalk) and in an area with many utilities including a high-pressure gas line. Staff recommended evaluating a "plan B" because the proposed excavation may not be feasible or may be prohibited by NYC entities.4/9/12 - The quarterly site status update report was received with sampling data from December 2011. The data show no changes in contaminant concentrations in groundwater.5/25/12 - The quarterly site status update report was received with sampling data from March 2012. The data show no changes in contaminant concentrations in groundwater. Utility mark-outs were conducted in preparation of soil borings in preparation of an excavation remedy along the Hamilton Avenue sidewalk.6/19/12 - A figure with proposed soil boring locations was presented. The soil boring activity will be conducted in July to delineate the extent of soil contamination prior to source excavation activities.7/26/12 - Soil borings were conducted in July to delineate the extent of soil contamination prior to planned source excavation activities. The results are pending7/31/12 - The quarterly site status update report was received. No notable changes in groundwater contaminant concentrations was observed.10/23/12 - The quarterly site status update report was received. No notable changes in groundwater contaminant concentrations was observed. A report summarizing the findings of the July off-site soil delineation investigation was received. The consultant plans to excavate impacted soil in a narrow area between the site boundary and the street.12/19/12 - The Site Conceptual Model and Remedial Alternatives Analysis was received and is under review. The document recommends excavation in an area under the sidewalk immediately down gradient from the site where contaminants were deposited groundwater flow from the site. 02/22/13 - The quarterly site status update report was received. Generally, no notable changes in groundwater contaminant concentrations was observed.4/12/13 - The quarterly site status update report was received. No notable changes in groundwater contaminant concentrations was observed. The proposed excavation remedy was nixed because contractors are concerned about subsurface utilities and the potential for undermining the sidewalk and street because the scope includes excavating soil from below the water table. 7/16/13 - The quarterly site status update report was received. No notable changes in groundwater contaminant concentrations was observed.10/25/13 - The quarterly site status update report was received. No notable changes in groundwater contaminant concentrations was observed. Two new monitoring wells were constructed on the west-central portion of the Site in September. The first surfactant injections were conducted in early October.01/31/14 - The quarterly site status update report was received. A second round of sufactant injections was conducted and were followed up with extractions. During the first event conducted in October of 2013, a total of 750 gallons of surfactant solution were injected into six monitoring wells. Approximately 24-48 hours later, a total of 1,022 gallons of fluids were extracted from the same monitoring wells. The second event was conducted in November of 2013 wherein a total of 500 gallons of surfactant solution were injected into four monitoring wells and a 1,008 gallons of fluids were extracted from the same monitoring wells. Two more surfactant injection events are planned.

Remarks: UPDATING STATION, REPLACING STEEL TANKS WITH FIBERGLASS TANKS, DISCOVERED CONTAMINATED SOIL & WATER UPON EXCAVATION, WILL

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

INVESTIGATE& CLEAN UP.

Material:

| | |
|---|---|
| Site ID: | 59311 |
| Operable Unit ID: | 929621 |
| Operable Unit: | 01 |
| Material ID: | 448389 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0502047 |
| Facility Type: | ER |
| DER Facility ID: | 57380 |
| Site ID: | 346330 |
| DEC Region: | 2 |
| Spill Date: | 5/19/2005 |
| Spill Number/Closed Date: | 0502047 / 4/26/2010 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MDMACCAB |
| Referred To: | Not reported |
| Reported to Dept: | 5/19/2005 |
| CID: | 409 |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/19/2005 |
| Spill Record Last Update: | 4/26/2010 |
| Spiller Name: | CHRISTINE CAMARDELLA |
| Spiller Company: | FORMER SERVICE STATION |
| Spiller Address: | 304 COLUMBIA STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | CHRISTINE CAMARDELLA |
| Contact Phone: | (631) 285-6684 |
| DEC Memo: | Consolidated with 8904339 on 4/6/10 by MacCabe. 4/26/10 - closed out spill based on 4/6/10 consolidation - J. Aversa |
| Remarks: | The spill was cleaned up with a vacuum truck. Michael MacCabe told them to call in the spill. |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

Material:

| | |
|---|---|
| Site ID: | 346330 |
| Operable Unit ID: | 1104061 |
| Operable Unit: | 01 |
| Material ID: | 584268 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0610200 |
| Facility Type: | ER |
| DER Facility ID: | 57380 |
| Site ID: | 374592 |
| DEC Region: | 2 |
| Spill Date: | 12/7/2006 |
| Spill Number/Closed Date: | 0610200 / 4/26/2010 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MDMACCAB |
| Referred To: | Not reported |
| Reported to Dept: | 12/7/2006 |
| CID: | 406 |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/7/2006 |
| Spill Record Last Update: | 4/26/2010 |
| Spiller Name: | CHRISTINE CAMARDELLA |
| Spiller Company: | FORMER MOBILE GAS STATION |
| Spiller Address: | 304 COLUMBIA ST. |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | CHRISTINE CAMARDELLA |
| Contact Phone: | (631) 218-0612 |
| DEC Memo: | DEC Piper spoke w/ Christine. As per conversation, spill is historic. Ther was 9' of product in the well as per the interface probe. The well was bailed dry. Piper spoke w. Michael MacCabe in CO, he is PM for open spills 8904339 and others at site. Spill was reasssigned to MacCabe as per MacCabe.Consolidated with spill 8904339 on 4/6/10 by |

**MOBIL OIL CORP SS #EMW (Continued)** **1000553836**

MacCabe. 4/26/10: closed out spill based on 4/6/10 consolidation - J. Aversa

Remarks: Impacted soil for 8 feet down in a monitoring well. Unknown if groundwater was affected. Geologic Services will be doing the remediation on this spill. Michael McCabe is working the Existing spill numbers #8904339 and # 0502047 for this location.

Material:

| | |
|---|---|
| Site ID: | 374592 |
| Operable Unit ID: | 1132263 |
| Operable Unit: | 01 |
| Material ID: | 2121994 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AF327** **COMMERCIAL BUILDING** **NY AST U003397119**
**SW** **116/164 IMLAY STREET** **NY HIST AST N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.143 mi.**
**755 ft.** **Site 9 of 9 in cluster AF**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-603357 |
| Program Type: | PBS |
| UTM X: | 583749.96129999997 |
| UTM Y: | 4503846.0216199998 |
| Expiration Date: | 2003/03/05 |
| Site Type: | Unknown |

Affiliation Records:

| | |
|---|---|
| Site Id: | 25275 |
| Affiliation Type: | Facility Owner |
| Company Name: | MERCEDES DISTRIBUTION CORPORATION |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 62 IMLAY STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 522-7111 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |

**COMMERCIAL BUILDING (Continued)** **U003397119**

| | |
|---|---|
| Date Last Modified: | 3/4/2004 |
| Site Id: | 25275 |
| Affiliation Type: | Mail Contact |
| Company Name: | MERCEDES DISTRIBUTION CORPORATION |
| Contact Type: | Not reported |
| Contact Name: | JOEL GOLDSTEIN |
| Address1: | 62 IMLAY STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 522-7111 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |
| Site Id: | 25275 |
| Affiliation Type: | On-Site Operator |
| Company Name: | COMMERCIAL BUILDING |
| Contact Type: | Not reported |
| Contact Name: | GEORGE FRANQUI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 522-7111 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |
| Site Id: | 25275 |
| Affiliation Type: | Emergency Contact |
| Company Name: | MERCEDES DISTRIBUTION CORPORATION |
| Contact Type: | Not reported |
| Contact Name: | GEORGE FRANQUI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 522-7111 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 53994 |

**COMMERCIAL BUILDING (Continued)** **U003397119**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
D00 - Pipe Type - No Piping
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-603357
SWIS Code: 6101
Operator: GEORGE FRANQUI
Facility Phone: (718) 522-7111
Facility Addr2: 116/164 IMLARY STREET
Facility Type: Not reported
Emergency: GEORGE FRANQUI
Emergency Tel: (718) 522-7111
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MERCEDES DISTRIBUTION CORPORATION
Owner Address: 62 IMLAY STREET
Owner City,St,Zip: BROOKLYN, NY 11231
Federal ID: Not reported
Owner Tel: (718) 522-7111
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: JOEL GOLDSTEIN
Mailing Name: MERCEDES DISTRIBUTION CORPORATION
Mailing Address: 62 IMLAY STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11231
Mailing Telephone: (718) 522-7111
Owner Mark: First Owner

**COMMERCIAL BUILDING (Continued)** **U003397119**

| | |
|---|---|
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 03/11/1998 |
| Expiration: | 03/05/2003 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 20000 |
| FAMT: | True |
| Facility Screen: | Minor Data Missing |
| Owner Screen: | No Missing Data |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 001 |
| Tank Location: | ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 20000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 01 |
| Pipe Location: | Aboveground |
| Pipe Type: | NONE |
| Pipe Internal: | None |
| Pipe External: | 00 |
| Tank Containment: | Diking |
| Leak Detection: | 05 |
| Overfill Protection: | 06 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**AQ328** **EDR US Hist Auto Stat** **1015300105**
**NE** **20 COLUMBIA PL** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.144 mi.**
**760 ft.** **Site 1 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**31 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | COLUMBIA LIMO & CAR SERVICE |
| Year: | 2011 |
| Address: | 20 COLUMBIA PL |

**(Continued)** **1015300105**

Name: COLUMBIA LIMO & CAR SERVICE
Year: 2012
Address: 20 COLUMBIA PL

---

**AQ329** **WILLOWTOWN APARTMENTS INC** **NY AST** **U003391697**
**NE** **32 WILLOW PLACE** **NY HIST AST** **N/A**
**1/8-1/4** **BROOKLYN HEIGHTS, NY 11201**
**0.144 mi.**
**760 ft.** **Site 2 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-361372 |
| Program Type: | PBS |
| UTM X: | 584703.14621000004 |
| UTM Y: | 4505139.1651999997 |
| Expiration Date: | 2018/02/03 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 18240 |
| Affiliation Type: | Facility Owner |
| Company Name: | WILLOWTOWN APARTMENTS INC |
| Contact Type: | TREASURER |
| Contact Name: | ELIZABETH LEBER |
| Address1: | 32 WILLOW PLACE |
| Address2: | Not reported |
| City: | BROOKLYN HEIGHTS |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (917) 841-5156 |
| EMail: | ELEBER@BBBARCH.COM |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 2/1/2013 |

| | |
|---|---|
| Site Id: | 18240 |
| Affiliation Type: | Mail Contact |
| Company Name: | WILLOWTOWN APARTMENTS INC |
| Contact Type: | TREASURER |
| Contact Name: | ELIZABETH LEBER |
| Address1: | 32 WILLOW PLACE |
| Address2: | Not reported |
| City: | BROOKLYN HEIGHTS |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (917) 841-5156 |
| EMail: | ELEBER@BBBARCH.COM |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 2/1/2013 |

| | |
|---|---|
| Site Id: | 18240 |
| Affiliation Type: | On-Site Operator |

**WILLOWTOWN APARTMENTS INC (Continued)** **U003391697**

| | |
|---|---|
| Company Name: | WILLOWTOWN APARTMENTS INC |
| Contact Type: | Not reported |
| Contact Name: | ELIZABETH LEBER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 841-5156 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 2/1/2013 |

| | |
|---|---|
| Site Id: | 18240 |
| Affiliation Type: | Emergency Contact |
| Company Name: | WILLOWTOWN APARTMENTS INC |
| Contact Type: | Not reported |
| Contact Name: | ELIZABETH LEBER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 841-5156 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 2/1/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 22114 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |

**WILLOWTOWN APARTMENTS INC (Continued)** **U003391697**

| | |
|---|---|
| Install Date: | 07/02/1962 |
| Capacity Gallons: | 2000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |
| Last Modified: | 02/01/2013 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-361372 |
| SWIS Code: | 6101 |
| Operator: | STAN SMALL |
| Facility Phone: | (718) 852-1260 |
| Facility Addr2: | 32 WILLOW PLACE |
| Facility Type: | APARTMENT BUILDING |
| Emergency: | STAN SMALL |
| Emergency Tel: | (718) 852-1260 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | WILLOWTOWN APARTMENTS INC |
| Owner Address: | 32 WILLOW PLACE |
| Owner City,St,Zip: | BROOKLYN HEIGHTS, NY 11201 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 852-1260 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | STAN SMALL |
| Mailing Name: | WILLOWTOWN APARTMENTS INC |
| Mailing Address: | 32 WILLOW PLACE |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN HEIGHTS, NY 11201 |
| Mailing Telephone: | (718) 858-8418 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 01/16/1998 |
| Expiration: | 02/03/2003 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 2000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

**WILLOWTOWN APARTMENTS INC (Continued)** **U003391697**

| | |
|---|---|
| Tank ID: | 001 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 2000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | GALVANIZED STEEL |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | Not reported |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**AJ330** **27 CHEEVER PLACE** **NY Spills** **S102239542**
**SE** **27 CHEEVER PLACE** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.146 mi.**
**771 ft.** **Site 3 of 3 in cluster AJ**

**Relative:**
**Higher**

**Actual:**
**23 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9516629 |
| Facility Type: | ER |
| DER Facility ID: | 163014 |
| Site ID: | 195664 |
| DEC Region: | 2 |
| Spill Date: | 3/26/1996 |
| Spill Number/Closed Date: | 9516629 / 3/26/1996 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMMARTIN |
| Referred To: | Not reported |
| Reported to Dept: | 3/26/1996 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |

**27 CHEEVER PLACE (Continued)** **S102239542**

| | |
|---|---|
| Date Entered In Computer: | 3/26/1996 |
| Spill Record Last Update: | 4/3/1996 |
| Spiller Name: | ROSE BONABENTURA |
| Spiller Company: | ROSE BONABENTURA |
| Spiller Address: | 27 CHEEVER PLACE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | JEAN BERGENN |
| Contact Phone: | (718) 545-4500 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" |
| Remarks: | LEAK FROM OIL PUMP |

Material:

| | |
|---|---|
| Site ID: | 195664 |
| Operable Unit ID: | 1027588 |
| Operable Unit: | 01 |
| Material ID: | 353141 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AQ331** **NYCT AUTH** **RCRA NonGen / NLR** **1014395148**
**NE** **MANHOLE 27 WILLOW PL** **NYP000173898**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.149 mi.**
**788 ft.** **Site 3 of 12 in cluster AQ**

**Relative: Higher**

**Actual: 35 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/20/2010 |
| Facility name: | NYCT AUTH |
| Facility address: | MANHOLE 27 WILLOW PL<br>BROOKLYN, NY 11201 |
| EPA ID: | NYP000173898 |
| Mailing address: | BROADWAY RM A 27<br>NEW YORK, NY 10004 |
| Contact: | SHERRY BULKLEY |
| Contact address: | BROADWAY RM A 27<br>NEW YORK, NY 10004 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Handler Activities Summary:
U.S. importer of hazardous waste: No

**NYCT AUTH (Continued)** **1014395148**

| | |
|---|---|
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Universal Waste Summary:

| | |
|---|---|
| Waste type: | Batteries |
| Accumulated waste on-site: | No |
| Generated waste on-site: | Not reported |
| Waste type: | Lamps |
| Accumulated waste on-site: | No |
| Generated waste on-site: | Not reported |
| Waste type: | Pesticides |
| Accumulated waste on-site: | No |
| Generated waste on-site: | Not reported |
| Waste type: | Thermostats |
| Accumulated waste on-site: | No |
| Generated waste on-site: | Not reported |

Hazardous Waste Summary:

| | |
|---|---|
| Waste code: | D007 |
| Waste name: | CHROMIUM |
| Waste code: | B007 |
| Waste name: | B007 |
| Violation Status: | No violations found |

---

**AQ332** **NYCT AUTH** **FINDS** **1014819184**
**NE** **MANHOLE 27 WILLOW PL** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.149 mi.**
**788 ft.** **Site 4 of 12 in cluster AQ**

**Relative: Higher**

**Actual: 35 ft.**

FINDS:

Registry ID: 110041645413

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**AQ333** **NYCTA** **NY MANIFEST** **S110306106**
**NE** **27 WILLOW PLACE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.149 mi.**
**788 ft.** **Site 5 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000965855 |
| Country: | USA |
| Mailing Name: | NYCTA |
| Mailing Contact: | S BULKLEY |
| Mailing Address: | 2 BROADWAY ROOM A27.72 |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10004 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 646-252-5774 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2010-01-20 |
| Trans1 Recv Date: | 2010-01-20 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2010-01-25 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000965855 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | Not reported |
| Quantity: | 2600.0 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2010 |
| Manifest Tracking Num: | 001084874GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | Y |
| Discr Type Ind: | Y |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**NYCTA (Continued)** **S110306106**

| | |
|---|---|
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2010-01-20 |
| Trans1 Recv Date: | 2010-01-20 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2010-01-25 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP000965855 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | Not reported |
| Quantity: | 2600.0 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 1.0 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2010 |
| Manifest Tracking Num: | 001084874GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | Y |
| Discr Type Ind: | Y |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**AR334** **TUFARO SVCE STA** **FINDS** **1016067038**
**SSW** **225 VAN BRUNT STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.150 mi.**
**793 ft.** **Site 1 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

FINDS:

Registry ID: 110019263562

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking

**TUFARO SVCE STA (Continued)** **1016067038**

environmental facility information found across the State.

---

**AR335** **AMERICAN QUICK START** **NY UST** **U003127187**
**SSW** **225 VAN BRUNT STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.150 mi.**
**793 ft.** **Site 2 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-602750 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2016/08/20 |
| UTM X: | 583788.65251000004 |
| UTM Y: | 4503769.8891399996 |
| Site Type: | Retail Gasoline Sales |

Affiliation Records:

| | |
|---|---|
| Site Id: | 24706 |
| Affiliation Type: | On-Site Operator |
| Company Name: | AMERICAN QUICK START |
| Contact Type: | Not reported |
| Contact Name: | AMERICAN QUICK START |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NY |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 403-0600 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/4/2007 |

| | |
|---|---|
| Site Id: | 24706 |
| Affiliation Type: | Emergency Contact |
| Company Name: | JOSEPH TUFARO |
| Contact Type: | Not reported |
| Contact Name: | JOE TUFARO |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 237-9200 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/4/2007 |

| | |
|---|---|
| Site Id: | 24706 |
| Affiliation Type: | Facility Owner |
| Company Name: | 225-229 LLC INC |
| Contact Type: | Not reported |

**AMERICAN QUICK START (Continued)** **U003127187**

| | |
|---|---|
| Contact Name: | Not reported |
| Address1: | 225 VAN BRUNT STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 237-9200 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/31/2013 |

| | |
|---|---|
| Site Id: | 24706 |
| Affiliation Type: | Mail Contact |
| Company Name: | LISA MARIE TUFARO-LEONE |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 225 VAN BRUNT STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 237-9200 |
| EMail: | TUFBUS@AOL.COM |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/31/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 51382 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 08/01/1982 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |

| | |
|---|---|
| Tightness Test Method: | 21 |
| Date Test: | 09/17/2013 |
| Next Test Date: | 09/17/2018 |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/31/2013 |

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None

**AMERICAN QUICK START (Continued)** **U003127187**

D01 - Pipe Type - Steel/Carbon Steel/Iron
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 51383 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 08/01/1982 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 21 |
| Date Test: | 09/17/2013 |
| Next Test Date: | 09/17/2018 |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/31/2013 |

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 51384 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 08/01/1982 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

**AMERICAN QUICK START (Continued)** **U003127187**

Tightness Test Method: 21
Date Test: 09/17/2013
Next Test Date: 09/17/2018
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/31/2013

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm

---

**AR336** **TRANSFORMER POLE 67175** **NY Spills** **S112230014**
**SSW** **240 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.150 mi.**
**793 ft.** **Site 3 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:

Facility ID: 1209972
Facility Type: ER
DER Facility ID: 427295
Site ID: 473047
DEC Region: 2
Spill Date: 11/10/2012
Spill Number/Closed Date: 1209972 / 6/10/2013
Spill Cause: Storm
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 11/10/2012
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/10/2012
Spill Record Last Update: 6/10/2013
Spiller Name: CON ED
Spiller Company: CON ED
Spiller Address: 240 VAN BRUNT ST
Spiller City,St,Zip: BROOKLYN, NY

**TRANSFORMER POLE 67175 (Continued)** **S112230014**

Spiller Company: 999
Contact Name: CON ED
Contact Phone: (212) 580-6763
DEC Memo: 6/10/13 - Austin - 2 gal. dielectric fluid spill from a pole transformer, onto pavement - Con Ed contained and cleaned up the spill, and replaced the leaking transformer - See eDocs fiels for further information - Spill closed - end
Remarks: Spilled to blacktop and sidewalk. Cleanup pending.

Material:
Site ID: 473047
Operable Unit ID: 1222896
Operable Unit: 01
Material ID: 2221636
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AR337** **EDR US Hist Auto Stat** **1015347068**
**SSW** **232 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.150 mi.**
**793 ft.** **Site 4 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

EDR Historical Auto Stations:
Name: EMILIOS AUTO REPAIR CORP
Year: 2010
Address: 232 VAN BRUNT ST

Name: EMILIOS AUTO REPAIR CORP
Year: 2011
Address: 232 VAN BRUNT ST

---

**AR338** **ABANDONED HOUSE BASEMENT** **NY Spills** **S109582844**
**SSW** **251 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.150 mi.**
**793 ft.** **Site 5 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:
Facility ID: 0901786
Facility Type: ER
DER Facility ID: 362918
Site ID: 413799
DEC Region: 2
Spill Date: 5/13/2009
Spill Number/Closed Date: 0901786 / 12/14/2010

**ABANDONED HOUSE BASEMENT (Continued)** **S109582844**

| | |
|---|---|
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 5/13/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/13/2009 |
| Spill Record Last Update: | 12/14/2010 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | Not reported |
| Spiller Company: | Not reported |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Alex Castro is an inspector with city DEP. He was called to check on a potential "illegal waste water discharge" coming from 249 Van Brunt St. which is owned by Michael Chiriselison (718-422-7703). When Mr Castro got to 249 Van Brunt, he was told the water/oil mix was coming from the basement of 251 Van Brunt St. which is either abandoned or in foreclosure (empty house).Both basements need to be inspected and problem needs to be identified.********Empty House Owner Identified**********Owner: HH Realty Equities LLCC/O IDEA NUOVA INC302 FIFTH AVENUENEW YORK, NEW YORK, 1000105/18/09 Performed site visit today,inspected basement at 249 Van Brunt, which gets the oily water inflow when it rains, as per owner Mr. Michael Chiriselison.There was no odor of petroleum in the basement during my inspection.As per Michael, it is coming from 251 Van Brunt.251 Van Brunt is a three family vacant house.It has two fill port and two vent pipe that indicate presence of fuel tank on the property.There is a real estate sign-"Kalmon Dolgin"(718.388.7700) on the house. I left a messege for them.(sr)06/10/09 Left few messeges to Real State Agent Mr. Bob @(718)388-7700, no call back received. Spill clean up letter was sent toRaguel Espinosa251 van Brunt StreetBrooklyn, NY 11231HH Realty Equities LLCC/O Idea Nuova Inc302 Fifth AvenueNew York, NY 10001 (sr)12/14/10 Complaint could not be verified.Inspection could not be done due to failure of identifying the property owner.Prospective owner: Solomon Accad,(212)643-0680.Mr. Solomon never returned my call to confirm that he owns the property.Case closed. |
| Remarks: | Alex Castro is an inspector with city DEP. He was called to check on a potential "illegal waste water discharge" at this address and he smelled oil in the water. |

Material:

| | |
|---|---|
| Site ID: | 413799 |
| Operable Unit ID: | 1170207 |

**ABANDONED HOUSE BASEMENT (Continued)** **S109582844**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 2161927 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AR339** **EDR US Hist Auto Stat** **1015339780**
**SSW** **225 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.150 mi.**
**793 ft.** **Site 6 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | N B QUICK START SVCE STATION |
| Year: | 1999 |
| Address: | 225 VAN BRUNT ST |
| Name: | N B QUICK START SVCE STATION |
| Year: | 2000 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS INC |
| Year: | 2006 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS INC |
| Year: | 2007 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS INC |
| Year: | 2009 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS INC |
| Year: | 2010 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS |
| Year: | 2011 |
| Address: | 225 VAN BRUNT ST |
| Name: | AMERICAN QUICK START & GAS |
| Year: | 2012 |
| Address: | 225 VAN BRUNT ST |

**AR340** **TUFARO SVCE STA** **US AIRS** **1007763933**
**SSW** **225 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.150 mi.**
**793 ft.** **Site 7 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110019826312 |
| Plant name: | TUFARO SVCE STA |
| Plant address: | 225 VAN BRUNT ST<br>BROOKLYN, NY 11231 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 5541 |
| Sic code desc: | GASOLINE SERVICE STATIONS |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1004 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1102 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1201 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1203 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1302 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1103 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |

**TUFARO SVCE STA (Continued)** **1007763933**

Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**AR341** **SEISE BROS-252 VAN BRUNT ST** **FINDS** **1007772819**
**SSW** **252 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.152 mi.**
**802 ft.** **Site 8 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

FINDS:

Registry ID: 110019352644

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**AQ342** **EDR US Hist Cleaners** **1014965821**
**NE** **10 COLUMBIA PL** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.154 mi.**
**814 ft.** **Site 6 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

EDR Historical Cleaners:
Name: SUDS & DUDS LAUNDRY INC
Year: 2004
Address: 10 COLUMBIA PL

Name: SUDS & DUDS LAUNDRY INC

**(Continued)** **1014965821**

Year: 2005
Address: 10 COLUMBIA PL

Name: SUDS & DUDS LAUNDRY INC
Year: 2006
Address: 10 COLUMBIA PL

Name: SUDS & DUDS LAUNDRY INC
Year: 2007
Address: 10 COLUMBIA PL

Name: SUDS & DUDS LAUNDRY INC
Year: 2008
Address: 10 COLUMBIA PL

---

**AS343** **VAULT 4398** **NY Spills** **S104508867**
**ENE** **85TH STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.155 mi.**
**816 ft.** **Site 1 of 4 in cluster AS**

**Relative:**
**Higher**

**Actual:**
**47 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9911663 |
| Facility Type: | ER |
| DER Facility ID: | 122625 |
| Site ID: | 143820 |
| DEC Region: | 2 |
| Spill Date: | 1/6/2000 |
| Spill Number/Closed Date: | 9911663 / 7/17/2000 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 1/6/2000 |
| CID: | 389 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/6/2000 |
| Spill Record Last Update: | 7/24/2000 |
| Spiller Name: | CALLER |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PL |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"CON ED E2MIS NOTES 1-06-00A transformer was found leaking transformer oil, approx. 8 gals. onto dirt( about 20sq. ft) from |

**VAULT 4398 (Continued)** **S104508867**

secondart bushing. Transformer in on FDR 8b86. FDR cannot b etaken off at this time to make repairs to trandformer due to two 8b ( 8b83 & 8b84) FDRs already out. Found sump with pump, disconnected pump but no oil was found in sump. Appears to be contained, no sewers or waterways affected. Sump protected, balonies and diapers placed around transformer to contian oil. THe leak is a slight drip.
Historical data shows transformer to be 4ppm. On 2-03-99 sample was taken of trnasormer oil (Lab Seq# 99-01061) results were <1ppm. Did not resample.1-07-00Mike Kessler from ERT reports that it was determined after conversation with Ron Cosentino that a new sample was required. Sample to be taken today and sent to Chem Lab.1-11-00As per conversation between J.Campanile, B. Chohen, R. Cosentino, M. Saladino & R. James; a transformer does not have to be resampled if a sample was taken on or after 9-27-98 and the transformer was not retrofilled. The sample taken on 1-07-00 wa snot sent to Astoria and the transformer will be treated as <50ppm.5-01-00 <1.0ppm cleanup completed by double washing structure with slix. NO liquid waste, solid waste removed by vactor. Transformer was replaced. No leaking equipment, sump was cleaned and oil sensitive pump is unpligged and protected.Incident closed.6-14-00Inquiry from Jane O'ConnellUpdate 7-12-00Response to DEC request...Capacity of transformer? - 410 gals.How much oil drained? - 290 gals.Replacement date? - 5-01-00Final cleanup date? - 5-01-00How? - Double washing with slix, there was no liquid waste, solid waste was removed by vector.Was there a soil or cement pump? - Cement pump which was disconected adn found to be oil free but was also cleanedSewer connection? - YesWas trap checked for oil - Yes was oil free.

Remarks: caller reporting a spill of material due to a faulty secondary bushing diapers were laided down coned#129517 no callback necessary

Material:

| | |
|---|---|
| Site ID: | 143820 |
| Operable Unit ID: | 1090365 |
| Operable Unit: | 01 |
| Material ID: | 297115 |
| Material Code: | 0541A |
| Material Name: | DIELECTRIC FLUID |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 8 |
| Units: | Gallons |
| Recovered: | 8 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AN344** **EDR US Hist Auto Stat** **1015262213**
**SSE** **167 UNION ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.155 mi.**
**817 ft.** **Site 5 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**29 ft.**

EDR Historical Auto Stations:
Name: RST AUTO REPAIR SHOP
Year: 2003
Address: 167 UNION ST

---

**AK345** **WATCHTOWER BIBLE & TRACT (2-6101-00202)** **NY DRYCLEANERS** **S110248294**
**NNE** **336-374 FURMAN STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.156 mi.**
**822 ft.** **Site 5 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

DRYCLEANERS:
Facility ID: DELETED
Phone Number: Not reported
Region: 2
Registration Effective Date: AFS
Inspection Date: 03OCT23
Install Date: Not reported
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: BAD ADDRESS

---

**AK346** **ONE BROOKLYN BRIDGE PARK CONDOMINIUM** **NY AST** **U003393808**
**NNE** **360 FURMAN STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.156 mi.**
**822 ft.** **Site 6 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**17 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-345415
Program Type: PBS
UTM X: 596104.94004999998
UTM Y: 4503129.5158500001
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 16847
Affiliation Type: Emergency Contact
Company Name: 360 BROOKLYN INVESTORS, LLC. C/O SPANDREL PROPERTY
Contact Type: Not reported
Contact Name: KEN GELMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 747-2198

**ONE BROOKLYN BRIDGE PARK CONDOMINIUM (Continued)** **U003393808**

| | |
|---|---|
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | BVCAMPBE |
| Date Last Modified: | 5/25/2010 |
| | |
| Site Id: | 16847 |
| Affiliation Type: | On-Site Operator |
| Company Name: | ONE BROOKLYN BRIDGE PARK CONDOMINIUM |
| Contact Type: | Not reported |
| Contact Name: | BOGDAN DOMANOWSKI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 596-6736 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/4/2013 |
| | |
| Site Id: | 16847 |
| Affiliation Type: | Mail Contact |
| Company Name: | SPRANDEL PROPERTY SERVICES INC. |
| Contact Type: | Not reported |
| Contact Name: | KEN GELMAN |
| Address1: | 434 BROADWAY |
| Address2: | 5TH FLOOR |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10013 |
| Country Code: | 001 |
| Phone: | (646) 747-2200 |
| EMail: | KGELMAN@SPANDRELGROUP.COM |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/8/2013 |
| | |
| Site Id: | 16847 |
| Affiliation Type: | Facility Owner |
| Company Name: | ONE BROOKLYN BRIDGE CONDOMINIUM % SPRANDEL PROP |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 434 BROADWAY |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10013 |
| Country Code: | 001 |
| Phone: | (646) 747-2198 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/8/2013 |

**ONE BROOKLYN BRIDGE PARK CONDOMINIUM (Continued)** **U003393808**

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 32774 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/01/1901 |
| Capacity Gallons: | 20000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/20/2013 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/04/2013 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tank Number: | 002 |
| Tank Id: | 32775 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
H99 - Tank Leak Detection - Other
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/01/1901 |
| Capacity Gallons: | 20000 |

**ONE BROOKLYN BRIDGE PARK CONDOMINIUM (Continued)** **U003393808**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/20/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 10/04/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 003
Tank Id: 32776
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 07/01/1901
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/20/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 10/08/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 004
Tank Id: 32777
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped

**ONE BROOKLYN BRIDGE PARK CONDOMINIUM (Continued)** **U003393808**

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | 07/01/1901 |
| Capacity Gallons: | 20000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 08/20/2013 |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/08/2013 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

---

**AT347** **BROOKLYN BATTERY TUNNEL** **ICIS 1011610684**
**South** **160 HAMILTON AVE BROOKLYN NY 11231** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.156 mi.**
**824 ft.** **Site 1 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

ICIS:

| | |
|---|---|
| Enforcement Action ID: | 02-2008-0824 |
| FRS ID: | 110025314327 |
| Program ID: | FRS 110025314327 |
| Action Name: | BROOKLYN BATTERY TUNNEL (MTA) |
| Facility Name: | BROOKLYN BATTERY TUNNEL |
| Facility Address: | 160 HAMILTON AVE BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | RCRA 9006 AO For Comp And/Or Pen (UST) |
| Facility County: | Kings |
| EPA Region #: | 2 |

| | |
|---|---|
| Enforcement Action ID: | 02-2008-0824 |
| FRS ID: | 110025314327 |
| Program ID: | RCRAINFO NYD982796385 |
| Action Name: | BROOKLYN BATTERY TUNNEL (MTA) |
| Facility Name: | TBTA - BROOKLYN BATTERY TUNNEL |
| Facility Address: | 160 HAMILTON AVE BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | RCRA 9006 AO For Comp And/Or Pen (UST) |
| Facility County: | Kings |
| EPA Region #: | 2 |

| | |
|---|---|
| Enforcement Action ID: | 02-2008-0824 |
| FRS ID: | 110025314327 |
| Program ID: | BR NYD982796385 |
| Action Name: | BROOKLYN BATTERY TUNNEL (MTA) |
| Facility Name: | BROOKLYN BATTERY TUNNEL |
| Facility Address: | 160 HAMILTON AVE BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | RCRA 9006 AO For Comp And/Or Pen (UST) |
| Facility County: | Kings |
| EPA Region #: | 2 |

**BROOKLYN BATTERY TUNNEL (Continued)** **1011610684**

Program ID: BR NYD982796385
Facility Name: BROOKLYN BATTERY TUNNEL
Address: 160 HAMILTON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported
Latitude: 40.680585
Longitude: -74.005228

Program ID: FRS 110025314327
Facility Name: BROOKLYN BATTERY TUNNEL
Address: 160 HAMILTON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported
Latitude: 40.680585
Longitude: -74.005228

Program ID: RCRAINFO NYD982796385
Facility Name: BROOKLYN BATTERY TUNNEL
Address: 160 HAMILTON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported
Latitude: 40.680585
Longitude: -74.005228

---

**AT348** **HUGH L. CAREY TUNNEL SERVICE BLDG.** **NY AST** **A100293379**
**South** **160 HAMILTON AVENUE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.156 mi.**
**824 ft.** **Site 2 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-454540
Program Type: PBS
UTM X: 584081.90951000003
UTM Y: 4503734.7618699996
Expiration Date: 2018/12/06
Site Type: Other

Affiliation Records:
Site Id: 19955
Affiliation Type: Mail Contact
Company Name: MTA BRIDGES AND TUNNELS (TBTA)
Contact Type: Not reported
Contact Name: ANDREW P. PETROVICH, CHIEF H&S OFCR
Address1: HEALTH & SAFETY DEPARTMENT
Address2: 2 BROADWAY, 23RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10004

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **A100293379**

| | |
|---|---|
| Country Code: | 001 |
| Phone: | (646) 252-7062 |
| EMail: | APETROVI@MTABT.ORG |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/18/2013 |

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | Facility Owner |
| Company Name: | MTA BRIDGES & TUNNELS (TBTA) |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 2 BROADWAY, 23RD FLOOR, H&S DEPT. |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10004 |
| Country Code: | 001 |
| Phone: | (646) 252-7062 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 7/3/2013 |

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | On-Site Operator |
| Company Name: | HUGH L. CAREY TUNNEL SERVICE BLDG. |
| Contact Type: | Not reported |
| Contact Name: | GENERAL MGR |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 797-6901 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/18/2013 |

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | Emergency Contact |
| Company Name: | MTA BRIDGES & TUNNELS (TBTA) |
| Contact Type: | Not reported |
| Contact Name: | ANDREW P. PETROVICH |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (646) 252-7062 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 7/3/2013 |

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **A100293379**

Tank Info:

| | |
|---|---|
| Tank Number: | 10 |
| Tank Id: | 65815 |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |

Equipment Records:

F99 - Pipe External Protection - Other
L00 - Piping Leak Detection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
H99 - Tank Leak Detection - Other
J00 - Dispenser - None
B99 - Tank External Protection - Other
D08 - Pipe Type - Equivalent Technology
E01 - Piping Secondary Containment - Diking (Aboveground)

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Other |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/01/2002 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 05/11/2010 |
| Material Name: | Waste Oil/Used Oil |

| | |
|---|---|
| Tank Number: | 12 |
| Tank Id: | 214650 |
| Material Code: | 9999 |
| Common Name of Substance: | Other |

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J00 - Dispenser - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **A100293379**

| | |
|---|---|
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 11/01/2006 |
| Capacity Gallons: | 1000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/03/2013 |
| Material Name: | Diesel |

| | |
|---|---|
| Tank Number: | 9 |
| Tank Id: | 65814 |
| Material Code: | 9999 |
| Common Name of Substance: | Other |

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
E01 - Piping Secondary Containment - Diking (Aboveground)

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/01/1999 |
| Capacity Gallons: | 550 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/03/2013 |
| Material Name: | Diesel |

---

**AT349** **BROOKLYN BATTERY TUNNEL** **RCRA-SQG** **1000141523**
**South** **160 HAMILTON AVE** **NJ MANIFEST** **NYD982796385**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.156 mi.**
**824 ft.** **Site 3 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

RCRA-SQG:

| | |
|---|---|
| Date form received by agency: | 12/11/2007 |
| Facility name: | BROOKLYN BATTERY TUNNEL |
| Facility address: | 160 HAMILTON AVE |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

BROOKLYN, NY 112311345
EPA ID: NYD982796385
Mailing address: MTA BRGS & TUNLS R MOSES BLDG
RANDALLS ISLAND ATT: H&S
NEW YORK, NY 100355199
Contact: GEORGE BASSIL
Contact address: MTA BRGS & TUNLS R MOSES BLDG RANDALLS ISLAND ATT: H&S
NEW YORK, NY 100355199
Contact country: US
Contact telephone: (212) 360-4165
Contact email: GBASSIL@MTABT.ORG
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: TRIBOROUGH BRIDGE & TUNNEL AUTH (TBTA)
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 05/25/1950
Owner/Op end date: Not reported

Owner/operator name: MTA BRIDGES & TUNNELS (TBTA)
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 05/25/1950
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

Historical Generators:
Date form received by agency: 12/10/2007
Facility name: BROOKLYN BATTERY TUNNEL
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Facility name: BROOKLYN BATTERY TUNNEL
Classification: Small Quantity Generator

Date form received by agency: 02/26/2004
Facility name: BROOKLYN BATTERY TUNNEL
Classification: Large Quantity Generator

Date form received by agency: 04/13/1995
Facility name: BROOKLYN BATTERY TUNNEL
Site name: TBTA - BROOKLYN BATTERY TUNNEL
Classification: Not a generator, verified

Date form received by agency: 10/04/1989
Facility name: BROOKLYN BATTERY TUNNEL
Site name: TBTA - BROOKLYN BATTERY TUNNEL
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D008
Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

NJ MANIFEST:
Manifest Code: 003536989JJK
EPA ID: NYD982796385
Date Shipped: 02/24/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 02/24/2009
Date Trans2 Transported Waste: Not reported

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 02/24/2009 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2009 New Jersey Manifest Data |
| Quantity: | 80 |
| Unit: | G |
| Hand Code: | H061 |

| | |
|---|---|
| Manifest Code: | 000201851WAS |
| EPA ID: | NYD982796385 |
| Date Shipped: | 11/23/2010 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NYD046765574 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 11/23/2010 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 11/23/2010 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D008 |
| Manifest Year: | 2010 New Jersey Manifest Data |
| Quantity: | 2400 |
| Unit: | P |
| Hand Code: | H111 |

| | |
|---|---|
| Manifest Code: | 001033074JJK |
| EPA ID: | NYD982796385 |
| Date Shipped: | 05/14/2008 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD986938645 |
| Transporter 2 EPA ID: | NY0000291823 |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 05/14/2008 |
| Date Trans2 Transported Waste: | 05/14/2008 |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 05/14/2008 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D008 |
| Manifest Year: | 2008 New Jersey Manifest Data |
| Quantity: | 5500 |
| Unit: | P |
| Hand Code: | H111 |

| | |
|---|---|
| Manifest Code: | 003536603JJK |
| EPA ID: | NYD982796385 |
| Date Shipped: | 09/18/2008 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 09/18/2008 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 09/18/2008 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2008 New Jersey Manifest Data |
| Quantity: | 400 |
| Unit: | P |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | NJA5286912 |
| EPA ID: | NYD982796385 |
| Date Shipped: | 01/17/2006 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NYD046765574 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 01/17/2006 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 01/17/2006 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 02280621 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5286971 |
| EPA ID: | NYD982796385 |
| Date Shipped: | 03/08/2006 |
| TSDF EPA ID: | NJD991291105 |
| Transporter EPA ID: | NYD046765574 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 03/08/2006 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 03/09/2006 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 05040621 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5009615 |
| EPA ID: | NYD982796385 |
| Date Shipped: | 02/17/2004 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 02/17/2004 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 02/17/2004 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 03180425 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | NJA5077680 |
| EPA ID: | NYD982796385 |
| Date Shipped: | 03/04/2004 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 03/04/2004 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 03/04/2004 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 03300425 |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | Not reported |
| Manifest Year: | Not reported |
| Quantity: | Not reported |
| Unit: | Not reported |
| Hand Code: | Not reported |

| | |
|---|---|
| Manifest Code: | 000892076JJK |
| EPA ID: | NYD982796385 |
| Date Shipped: | 12/23/2008 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 12/23/2008 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Date TSDF Received Waste: | 12/23/2008 |
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D001 |
| Manifest Year: | 2008 New Jersey Manifest Data |
| Quantity: | 55 |
| Unit: | G |
| Hand Code: | H141 |

| | |
|---|---|
| Manifest Code: | 001033521JJK |
| EPA ID: | NYD982796385 |
| Date Shipped: | 07/11/2007 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NJ0000027193 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 07/11/2007 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 07/11/2007 |

**BROOKLYN BATTERY TUNNEL (Continued)** **1000141523**

| | |
|---|---|
| Tranporter 1 Decal: | Not reported |
| Tranporter 2 Decal: | Not reported |
| Generator EPA Facility Name: | Not reported |
| Transporter-1 EPA Facility Name: | Not reported |
| Transporter-2 EPA Facility Name: | Not reported |
| Transporter-3 EPA Facility Name: | Not reported |
| Transporter-4 EPA Facility Name: | Not reported |
| Transporter-5 EPA Facility Name: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Reference Manifest Number: | Not reported |
| Was Load Rejected (Y/N): | No |
| Reason Load Was Rejected: | Not reported |
| Waste Code: | D002 |
| Manifest Year: | 2007 New Jersey Manifest Data |
| Quantity: | 220 |
| Unit: | G |
| Hand Code: | H11 |

---

**AT350** **BROOKLYN BATTERY TUNNEL** **FINDS** **1009606517**
**South** **160 HAMILTON AVE** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.156 mi.**
**824 ft.** **Site 4 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

FINDS:

Registry ID: 110025314327

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**BROOKLYN BATTERY TUNNEL (Continued)** **1009606517**

HAZARDOUS WASTE BIENNIAL REPORTER

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

---

**AT351** **HUGH L. CAREY TUNNEL SERVICE BLDG.** **NY UST** **U004062139**
**South** **160 HAMILTON AVENUE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.156 mi.**
**824 ft.** **Site 5 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-454540 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2018/12/06 |
| UTM X: | 584081.90951000003 |
| UTM Y: | 4503734.7618699996 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | Mail Contact |
| Company Name: | MTA BRIDGES AND TUNNELS (TBTA) |
| Contact Type: | Not reported |
| Contact Name: | ANDREW P. PETROVICH, CHIEF H&S OFCR |
| Address1: | HEALTH & SAFETY DEPARTMENT |
| Address2: | 2 BROADWAY, 23RD FLOOR |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10004 |
| Country Code: | 001 |
| Phone: | (646) 252-7062 |
| EMail: | APETROVI@MTABT.ORG |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/18/2013 |

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | Facility Owner |
| Company Name: | MTA BRIDGES & TUNNELS (TBTA) |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 2 BROADWAY, 23RD FLOOR, H&S DEPT. |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10004 |
| Country Code: | 001 |
| Phone: | (646) 252-7062 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 7/3/2013 |

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | On-Site Operator |
| Company Name: | HUGH L. CAREY TUNNEL SERVICE BLDG. |
| Contact Type: | Not reported |
| Contact Name: | GENERAL MGR |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 797-6901 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 10/18/2013 |

| | |
|---|---|
| Site Id: | 19955 |
| Affiliation Type: | Emergency Contact |
| Company Name: | MTA BRIDGES & TUNNELS (TBTA) |
| Contact Type: | Not reported |
| Contact Name: | ANDREW P. PETROVICH |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (646) 252-7062 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 7/3/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 1 |
| Tank ID: | 65806 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 01/01/1950 |
| Date Tank Closed: | 12/01/1998 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

C02 - Pipe Location - Underground/On-ground
G07 - Tank Secondary Containment - Excavation Liner
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Number: 11
Tank ID: 211326
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 02/03/2006
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: 0
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 05/11/2010

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
D11 - Pipe Type - Flexible Piping
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B09 - Tank External Protection - Urethane
C03 - Pipe Location - Aboveground/Underground Combination
I01 - Overfill - Float Vent Valve
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 2
Tank ID: 65807
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 01/01/1950
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G07 - Tank Secondary Containment - Excavation Liner

Tank Number: 3
Tank ID: 65808
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: 01/01/1950
Date Tank Closed: 03/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 4
Tank ID: 65809
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

| | |
|---|---|
| Install Date: | 01/01/1950 |
| Date Tank Closed: | 01/01/2000 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G07 - Tank Secondary Containment - Excavation Liner
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

| | |
|---|---|
| Tank Number: | 5 |
| Tank ID: | 65810 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 550 |
| Install Date: | 01/01/1950 |
| Date Tank Closed: | 07/01/1991 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G07 - Tank Secondary Containment - Excavation Liner
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

| | |
|---|---|
| Tank Number: | 6 |
| Tank ID: | 65811 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 1000 |
| Install Date: | 01/01/1990 |
| Date Tank Closed: | 12/01/1998 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None

| | |
|---|---|
| Tank Number: | 7 |
| Tank ID: | 65812 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 2500 |
| Install Date: | 11/01/1999 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 05/11/2010 |

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
J02 - Dispenser - Suction Dispenser

**HUGH L. CAREY TUNNEL SERVICE BLDG. (Continued)** **U004062139**

L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

| | |
|---|---|
| Tank Number: | 8 |
| Tank ID: | 65813 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 2500 |
| Install Date: | 11/01/1999 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 2710 |
| Common Name of Substance: | Biodiesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 07/03/2013 |

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

---

**AT352** **TRIBOROUGH BRIDGE & TUNNEL AUTH** **NY LTANKS** **U001840232**
**South** **160 HAMILTON AVE** **NY HIST UST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231** **NY MANIFEST**
**0.156 mi.** **NY Spills**
**824 ft.** **Site 6 of 14 in cluster AT** **NY SPDES**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 327587 |
| Spill Number/Closed Date: | 9201988 / 11/17/2003 |
| Spill Date: | 7/15/1991 |
| Spill Cause: | Tank Failure |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Spill Source: | Non Major Facility > 1,100 gal |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 1/13/1992 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/20/1992 |
| Spill Record Last Update: | 6/24/2004 |
| Spiller Name: | GEORGE BASIL |
| Spiller Company: | MTA BRIDGES & TUNNELS |
| Spiller Address: | RANDALLS ISLAND |
| Spiller City,St,Zip: | NEW YORK, NY 10035- |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 263708 |
| DEC Memo: | Not reported |
| Remarks: | ONE 550 EMPTIED & CLOSED IN PLACE |

Material:

| | |
|---|---|
| Site ID: | 327587 |
| Operable Unit ID: | 966084 |
| Operable Unit: | 01 |
| Material ID: | 413268 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 327586 |
| Spill Number/Closed Date: | 8912103 / 10/7/1992 |
| Spill Date: | 3/21/1990 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Non Major Facility > 1,100 gal |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Cleanup Ceased: | 10/7/1992 |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 3/21/1990 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/23/1990 |
| Spill Record Last Update: | 6/24/2004 |
| Spiller Name: | GEORGE BASIL |
| Spiller Company: | MTA BRIDGES & TUNNELS |
| Spiller Address: | RANDALLS ISLAND |
| Spiller City,St,Zip: | NEW YORK, NY 10035- |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 263708 |
| DEC Memo: | Not reported |
| Remarks: | (1) 550 GALLON FAILED PETRO TITE, 2ND TANK WAS A 5K TANK WHICH FAILED A HORNER EZY CHECK WITH A GROSS LEAK. |

Material:

| | |
|---|---|
| Site ID: | 327586 |
| Operable Unit ID: | 938940 |
| Operable Unit: | 01 |
| Material ID: | 441579 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 327586 |
| Spill Tank Test: | 1536876 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Unknown |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

HIST UST:

| | |
|---|---|
| PBS Number: | 2-454540 |
| SPDES Number: | Not reported |
| Emergency Contact: | BOBBIE ATHEY |
| Emergency Telephone: | (212) 468-8451 |
| Operator: | EDWARD WALLACE |
| Operator Telephone: | (718) 797-6901 |
| Owner Name: | TRIBOROUGH BRIDGE & TUNNEL AUTHORITY |
| Owner Address: | 10 COLUMBUS CIRCLE, 18TH FLOOR |
| Owner City,St,Zip: | NEW YORK, NY 10019 |
| Owner Telephone: | (212) 468-8450 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | 50 |
| Mailing Name: | MTS BRIDGES AND TUNNELS |
| Mailing Address: | 10 COLUMBUS CIRCLE |
| Mailing Address 2: | 18TH FLOOR |
| Mailing City,St,Zip: | NEW YORK, NY 10019 |
| Mailing Contact: | CHIEF HEALTH & SAFETY OFF |
| Mailing Telephone: | (212) 468-8451 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | Not reported |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | OTHER |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 07/21/2000 |
| Expiration Date: | 12/06/2003 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 5000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 005 |
| Tank Location: | UNDERGROUND |
| Tank Status: | Closed-In Place |
| Install Date: | 12/01/1950 |
| Capacity (gals): | 550 |
| Product Stored: | UNKNOWN |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | Painted/Asphalt Coating |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Pipe Location: | Underground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | Painted/Asphalt Coating |
| Second Containment: | Vault (w/o access) |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD982796385 |
| Country: | USA |
| Mailing Name: | TRIBOROUGH BRIDGE & TUNNEL AUTH |
| Mailing Contact: | N/S |
| Mailing Address: | 2 BROADWAY |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10004 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-797-6070 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD046765574 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-04-18 |
| Trans1 Recv Date: | 2012-04-18 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2012-04-19 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 200.0 |
| Units: | P - Pounds |
| Number of Containers: | 2.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 000457352WAS |
| Import Ind: | N |
| Export Ind: | N |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H111 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-12-06 |
| Trans1 Recv Date: | 2012-12-06 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-01-03 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 200.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 009182390JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H111 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-12-06 |
| Trans1 Recv Date: | 2012-12-06 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-01-03 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 100.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 009182390JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H111 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD046765574 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2012-04-18 |
| Trans1 Recv Date: | 2012-04-18 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2012-04-19 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 200.0 |
| Units: | P - Pounds |
| Number of Containers: | 2.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 000457352WAS |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR986628162
Trans2 State ID: Not reported
Generator Ship Date: 2012-10-11
Trans1 Recv Date: 2012-10-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-10-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982796385
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 800.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 000457831WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 27-Jun-2013 00:00:00
Trans1 Recv Date: 27-Jun-2013 00:00:00
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02-Jul-2013 00:00:00
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982796385
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: MID980991566
Waste Code: Not reported
Quantity: 100

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181790JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 27-Jun-2013 00:00:00 |
| Trans1 Recv Date: | 27-Jun-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 150 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181790JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR000134957 |
| Trans2 State ID: | NJD054126164 |
| Generator Ship Date: | 09-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 09-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 16-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 04-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 75 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181858JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR000134957 |
| Trans2 State ID: | NJD054126164 |
| Generator Ship Date: | 09-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 09-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 16-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 04-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 75 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Manifest Tracking Num: | 009181858JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR986628162 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 14-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 14-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 14-Jan-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 1200 |
| Units: | P - Pounds |
| Number of Containers: | 3 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000517772WAS |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR986628162 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 26-Feb-2013 00:00:00 |
| Trans1 Recv Date: | 26-Feb-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| TSD Site Recv Date: | 26-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 1500 |
| Units: | P - Pounds |
| Number of Containers: | 3 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000517818WAS |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 27-Jun-2013 00:00:00 |
| Trans1 Recv Date: | 27-Jun-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181790JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 27-Jun-2013 00:00:00 |
| Trans1 Recv Date: | 27-Jun-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 150 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181790JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR000134957 |
| Trans2 State ID: | NJD054126164 |
| Generator Ship Date: | 09-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 09-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 16-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 04-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 75 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181858JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR000134957 |
| Trans2 State ID: | NJD054126164 |
| Generator Ship Date: | 09-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 09-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 16-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 04-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 75 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181858JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJ0000027193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 06-Dec-2013 00:00:00 |
| Trans1 Recv Date: | 06-Dec-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 06-Dec-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002200046 |
| Waste Code: | Not reported |
| Quantity: | 330 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 6 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 008922401JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H061 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR986628162 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 14-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 14-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 14-Jan-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 1200 |
| Units: | P - Pounds |
| Number of Containers: | 3 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Year: | 2013 |
| Manifest Tracking Num: | 000517772WAS |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJR986628162 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 26-Feb-2013 00:00:00 |
| Trans1 Recv Date: | 26-Feb-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 26-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 1500 |
| Units: | P - Pounds |
| Number of Containers: | 3 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000517818WAS |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR000134957 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 2014-01-09 |
| Trans1 Recv Date: | 2014-01-09 |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Trans2 Recv Date: | 2014-01-10 |
| TSD Site Recv Date: | 2014-01-21 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD085690592 |
| Waste Code: | Not reported |
| Quantity: | 300 |
| Units: | P - Pounds |
| Number of Containers: | 4 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2014 |
| Manifest Tracking Num: | 011979948JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD054126164 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-06-27 |
| Trans1 Recv Date: | 2013-06-27 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-07-02 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982796385 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | MID980991566 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 009181790JJK |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Click this hyperlink while viewing on your computer to access
6 additional NY_MANIFEST: record(s) in the EDR Site Report.

SPILLS:
Facility ID: 9908442
Facility Type: ER
DER Facility ID: 263708
Site ID: 99569
DEC Region: 2
Spill Date: 10/12/1999
Spill Number/Closed Date: 9908442 / Not Reported
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: RJFENG
Referred To: LETTER FOR RESUBMITTAL
Reported to Dept: 10/12/1999
CID: 312
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 10/12/1999
Spill Record Last Update: 6/5/2012
Spiller Name: GEORGE BASIL
Spiller Company: MTA BRIDGES & TUNNELS
Spiller Address: RANDALLS ISLAND
Spiller City,St,Zip: NEW YORK, NY 10035-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"REASSIGNED from DEC Tomasello to Sigona on 1/4/2001This spill site cleanup has been consolidated under Spill No. 9908442.A site investigation work plan was submitted to DEC for review and approval on November 7, 2003. DEC’s comments regarding a proposed Work Plan for Site Investigation by BEM Systems, Inc., dated November 5, 2003, along with a letter from BEM, dated March 22, 2004. Based on the results of our site visit and PBS inspection on June 16, 2003, and evaluation of the proposal by BEM, the DEC accepts MTA Bridges and Tunnel’s Work Plan to perform further investigatory actions to address any of the DEC’s concerns related to the prior heating and used oil spill investigations at this site.However, the DEC requests

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

that MTA Bridges and Tunnels also collect a follow-up groundwater sample after properly developing Monitoring Well No. MW-1, and provide an NYSDOH certified laboratory analysis of the sample using EPA Test Methods 8260 and 8270. At this point, the DEC is tracking this spill site under the most current spill case included in BEM's Work Plan under Spill No. 9908442. This represents the results of the soil sampling around the excavation for the new gasoline and diesel tank was reported as a new gasoline spill case under 9908442. 07/23/04spoke to George Bassil, MTA Bridges and Tunnels 212-360-4165.Geoprobe word scheduled for 8/3/04. Rommel.03/30/05: Transferred from Rommel to Tibbe.11/12/10 - spill re-assigned from Tibbe to Joe O'Connell2/7/2012 - changed Lead DEC from Joe O'Connell to JFeng.

Remarks: GASOLINE CONTAMINATION FOUND IN THE SOIL AT THE PARKING LOT

Material:

| | |
|---|---|
| Site ID: | 99569 |
| Operable Unit ID: | 1082728 |
| Operable Unit: | 01 |
| Material ID: | 297554 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 99569 |
| Operable Unit ID: | 1082728 |
| Operable Unit: | 01 |
| Material ID: | 297555 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 99569 |
| Operable Unit ID: | 1082728 |
| Operable Unit: | 01 |
| Material ID: | 297556 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

SPDES:

| | |
|---|---|
| Permit Number: | NY0005461 |
| State-Region: | 02 |
| Expiration Date: | 12/31/2011 |
| Current Major Minor Status: | Minor |
| Primary Facility SIC Code: | 4785 |
| State Water Body Name: | EAST R |
| Limit Set Status Flag: | Active |
| Total Actual Average Flow(MGD): | .002000 |
| Total App Design Flow(MGD): | Not reported |
| UDF1: | Not reported |
| Lat/Long: | 40.692111 / -74.012083 |
| DMR Cognizant Official: | BJ ATHEY, CHIEF HEALTH/SAFETY |
| UDF2: | 001702 |
| UDF3: | I |
| FIPS County Code: | NY047 |
| | |
| Non-Gov Permit Affiliation Type Desc: | DMR Mailing Address |
| Non-Gov Permit Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Permit Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Permit Supplemental Location: | 160 HAMILTON AVENUE |
| Non-Gov Permit City: | BROOKLYN |
| Non-Gov Permit State Code: | NY |
| Non-Gov Permit Zip Code: | 11231 |
| Non-Gov Facility Affiliation Type Desc: | Mailing Address |
| Non-Gov Facility Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Facility Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Facility Supplemental Location: | 160 HAMILTON AVENUE |
| Non-Gov Facility City: | BROOKLYN |
| Non-Gov Facility State Code: | NY |
| Non-Gov Facility Zip Code: | 11231 |
| State Water Body: | 02030201010 |
| | |
| UDF2: | 001702 |
| UDF3: | I |
| FIPS County Code: | NY047 |
| | |
| Non-Gov Permit Affiliation Type Desc: | DMR Mailing Address |
| Non-Gov Permit Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Permit Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Permit Supplemental Location: | 160 HAMILTON AVENUE |
| Non-Gov Permit City: | BROOKLYN |
| Non-Gov Permit State Code: | NY |
| Non-Gov Permit Zip Code: | 11231 |
| Non-Gov Facility Affiliation Type Desc: | Owner |
| Non-Gov Facility Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Facility Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Facility Supplemental Location: | PO BOX 35 |
| Non-Gov Facility City: | NEW YORK |
| Non-Gov Facility State Code: | NY |
| Non-Gov Facility Zip Code: | 100350035 |
| State Water Body: | 02030201010 |
| | |
| UDF2: | 001702 |
| UDF3: | I |
| FIPS County Code: | NY047 |

**TRIBOROUGH BRIDGE & TUNNEL AUTH (Continued)** **U001840232**

| | |
|---|---|
| Non-Gov Permit Affiliation Type Desc: | Permittee |
| Non-Gov Permit Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Permit Street Address: | PO BOX 35 |
| Non-Gov Permit Supplemental Location: | Not reported |
| Non-Gov Permit City: | NEW YORK |
| Non-Gov Permit State Code: | NY |
| Non-Gov Permit Zip Code: | 100350035 |
| Non-Gov Facility Affiliation Type Desc: | Mailing Address |
| Non-Gov Facility Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Facility Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Facility Supplemental Location: | 160 HAMILTON AVENUE |
| Non-Gov Facility City: | BROOKLYN |
| Non-Gov Facility State Code: | NY |
| Non-Gov Facility Zip Code: | 11231 |
| State Water Body: | 02030201010 |
| | |
| UDF2: | 001702 |
| UDF3: | I |
| FIPS County Code: | NY047 |
| | |
| Non-Gov Permit Affiliation Type Desc: | Permittee |
| Non-Gov Permit Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Permit Street Address: | PO BOX 35 |
| Non-Gov Permit Supplemental Location: | Not reported |
| Non-Gov Permit City: | NEW YORK |
| Non-Gov Permit State Code: | NY |
| Non-Gov Permit Zip Code: | 100350035 |
| Non-Gov Facility Affiliation Type Desc: | Owner |
| Non-Gov Facility Org Formal Name: | MTA BRIDGES AND TUNNELS |
| Non-Gov Facility Street Address: | BROOKLYN BATTERY TUNNEL |
| Non-Gov Facility Supplemental Location: | PO BOX 35 |
| Non-Gov Facility City: | NEW YORK |
| Non-Gov Facility State Code: | NY |
| Non-Gov Facility Zip Code: | 100350035 |
| State Water Body: | 02030201010 |

---

**AR353** **POLE 67345** **NY Spills** **S105235602**
**SSW** **80 DELEVAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.157 mi.**
**830 ft.** **Site 9 of 10 in cluster AR**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0107466 |
| Facility Type: | ER |
| DER Facility ID: | 209179 |
| Site ID: | 255377 |
| DEC Region: | 2 |
| Spill Date: | 10/20/2001 |
| Spill Number/Closed Date: | 0107466 / 6/13/2003 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 10/21/2001 |
| CID: | 246 |
| Water Affected: | Not reported |

**POLE 67345 (Continued)** **S105235602**

| | |
|---|---|
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/21/2001 |
| Spill Record Last Update: | 6/16/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"E2MIS 13986010/20/01 2358hrs - Mark Rotundi # 65057 OS, #9, reports he responded to fire dept ticket for transformer fire and found oh transformer serial # 1359A86 burnt itself out once deenergerized. Sprayed 3 oz 0 pcb oil onto 4 flags of concrete. Diapers and bolognies placed. Area has been secured. No private propertyaffected. No sewers or waterways affected. Transformer is being bagged and OH will be notified to remove/replace transformer. Sample # BK301910 results are0ppm.R. Hutchinson, OS, env. ops notified and will respond to location with flush crew to perform cleanup.E. Cortes was notified @0023hrs.CIG P. McGuire notified @ 0011hrs 10/21/01.cn#1966110/21/01=0340HRS=IOCCO REPORTS CLEANUP COMPLETED AT THIS TIME, HE USED SLIX AND DIAPERS.....LAB RESULT RECEIVED 10/22/01 - 1735. 01-10213. <1.0 PM. TJ - 50495UPDATE: 11/05/01 @ 0800 HRS. -- AL MORTENSEN FROM THE OVER HEAD REPORTS THE DEFECTIVE TRANSFORMER WAS REPLACED ON 10/21/01.R.M.D. 08584. |
| Remarks: | transformer fire caused 3 oz of material to be deposited on sidewalk. cleanup is in process |

Material:

| | |
|---|---|
| Site ID: | 255377 |
| Operable Unit ID: | 845647 |
| Operable Unit: | 01 |
| Material ID: | 532286 |
| Material Code: | 0020A |
| Material Name: | TRANSFORMER OIL |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AQ354**
**NE**
**1/8-1/4**
**0.158 mi.**
**835 ft.**

**CON EDISION**
**18 WILLOW PL**
**BROOKLYN, NY 11201**

**Site 7 of 12 in cluster AQ**

**NY MANIFEST** **S116297104**
**N/A**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004486585 |
| Country: | USA |
| Mailing Name: | Not reported |
| Mailing Contact: | Not reported |
| Mailing Address: | Not reported |
| Mailing Address 2: | Not reported |
| Mailing City: | Not reported |
| Mailing State: | Not reported |
| Mailing Zip: | Not reported |
| Mailing Zip4: | Not reported |
| Mailing Country: | Not reported |
| Mailing Phone: | Not reported |

NY MANIFEST:

No Manifest Records Available

---

**AK355**
**NNE**
**1/8-1/4**
**0.158 mi.**
**835 ft.**

**CON EDISON**
**JORALEMON ST & FURMAN ST**
**BROOKLYN, NY 11201**

**Site 7 of 8 in cluster AK**

**NY MANIFEST** **S113920190**
**N/A**

**Relative:**
**Higher**

**Actual:**
**15 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004362646 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 18-Sep-2013 00:00:00 |
| Trans1 Recv Date: | 18-Sep-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 23-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004362646 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |

**CON EDISON (Continued)** **S113920190**

| | |
|---|---|
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002291115GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 18-Sep-2013 00:00:00 |
| Trans1 Recv Date: | 18-Sep-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 23-Sep-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004362646 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002291115GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

**CON EDISON (Continued)** **S113920190**

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-09-18 |
| Trans1 Recv Date: | 2013-09-18 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-09-23 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004362646 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002291115GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

---

**AQ356** **EDR US Hist Cleaners** **1015078603**
**NE** **6 COLUMBIA PL** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.158 mi.**
**836 ft.** **Site 8 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**29 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | HEIGHTS DROP OFF CENTER AND LAUNDROMAT INCORPORATED |
| Year: | 2000 |
| Address: | 6 COLUMBIA PL |
| Name: | HEIGHTS DRP OFF CENTER LAUNDROMAT |
| Year: | 2005 |
| Address: | 6 COLUMBIA PL |
| Name: | HEIGHTS DRP OFF CENTER LAUNDROMAT |
| Year: | 2008 |
| Address: | 6 COLUMBIA PL |
| Name: | HEIGHTS DRP OFF CENTER LAUNDROMAT |
| Year: | 2009 |
| Address: | 6 COLUMBIA PL |

**(Continued)** **1015078603**

Name: HEIGHTS DROPOFF CENTER & LAUNDROM
Year: 2011
Address: 6 COLUMBIA PL

Name: HEIGHTS DROPOFF CENTER & LAUNDROM
Year: 2012
Address: 6 COLUMBIA PL

---

**AK357** **24-32 JORALEMON STREET** **NY UST** **U003128226**
**NNE** **A/K/A 10-20-30 COLUMBIA PL.** **NY HIST UST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.158 mi.**
**836 ft.** **Site 8 of 8 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

UST:
Id/Status: 2-600817 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 2018/03/18
UTM X: 584609.50477999996
UTM Y: 4505221.2548900004
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 22789
Affiliation Type: Mail Contact
Company Name: JORALEMON REALTY NY LLC
Contact Type: Not reported
Contact Name: MEIR BOUSKILA
Address1: PO BOX 1920
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10116
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 3/13/2013

Site Id: 22789
Affiliation Type: On-Site Operator
Company Name: 24-32 JORALEMON STREET
Contact Type: Not reported
Contact Name: THOMAS MUNIZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 529-3652
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 3/13/2013

**24-32 JORALEMON STREET (Continued)** **U003128226**

| | |
|---|---|
| Site Id: | 22789 |
| Affiliation Type: | Emergency Contact |
| Company Name: | JORALEMON REALTY NY, LLC |
| Contact Type: | Not reported |
| Contact Name: | EDDIE LJESNJANIN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (646) 296-0591 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 3/13/2013 |

| | |
|---|---|
| Site Id: | 22789 |
| Affiliation Type: | Facility Owner |
| Company Name: | JORALEMON REALTY NY, LLC |
| Contact Type: | AGENT |
| Contact Name: | MEIR BOUSKILA |
| Address1: | PO BOX 1920 |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10116 |
| Country Code: | 001 |
| Phone: | (212) 564-2111 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 3/13/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 43938 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 10000 |
| Install Date: | 08/12/1914 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | 21 |
| Date Test: | 02/04/2008 |
| Next Test Date: | 02/04/2013 |
| Pipe Model: | Not reported |
| Modified By: | KAKYER |
| Last Modified: | 03/13/2013 |

Equipment Records:

**24-32 JORALEMON STREET (Continued)** **U003128226**

B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

HIST UST:

| | |
|---|---|
| PBS Number: | 2-600817 |
| SPDES Number: | Not reported |
| Emergency Contact: | IRVING LANGER |
| Emergency Telephone: | (718) 434-9440 |
| Operator: | SUPERINTENDENT |
| Operator Telephone: | (718) 243-1513 |
| Owner Name: | IRVING LANGER |
| Owner Address: | 1465A FLATBUSH AVENUE |
| Owner City,St,Zip: | BROOKLYN, NY 11210 |
| Owner Telephone: | (718) 434-9440 |
| Owner Type: | Private Resident |
| Owner Subtype: | Not reported |
| Mailing Name: | RIVERSIDE APARTMENTS COMPANY |
| Mailing Address: | 1465A FLATBUSH AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11210 |
| Mailing Contact: | IRVING LANGER |
| Mailing Telephone: | (718) 434-9440 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | 20 JORALEMON STREET |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | APARTMENT BUILDING |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 07/17/1997 |
| Expiration Date: | 07/29/2002 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 10000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |

**24-32 JORALEMON STREET (Continued)** **U003128226**

| | |
|---|---|
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (gals): | 10000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |
| Pipe Location: | Aboveground/Underground Combination |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Gravity |
| Date Tested: | Not reported |
| Next Test Date: | 12/27/1987 |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

---

**AU358** **EDR US Hist Cleaners** **1015000950**
**SSE** **162 UNION ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.159 mi.**
**837 ft.** **Site 1 of 3 in cluster AU**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | SUDS & DUDS INC |
| Year: | 2003 |
| Address: | 162 UNION ST |
| Name: | SUDS & DUDS INC |
| Year: | 2004 |
| Address: | 162 UNION ST |
| Name: | LAUNDROMAT |
| Year: | 2006 |
| Address: | 162 UNION ST |
| Name: | LAUNDROMAT |
| Year: | 2007 |
| Address: | 162 UNION ST |
| Name: | LAUNDROMAT |
| Year: | 2008 |
| Address: | 162 UNION ST |
| Name: | LAUNDROMAT |

**(Continued)** **1015000950**

Year: 2009
Address: 162 UNION ST

Name: SUDS & DUDS
Year: 2010
Address: 162 UNION ST

Name: SUDS & DUDS LAUNDROMAT
Year: 2011
Address: 162 UNION ST

Name: SUDS & DUDS LAUNDROMAT
Year: 2012
Address: 162 UNION ST

---

**AQ359** **24 JORALEMON ST BUILDING** **US AIRS** **1006379924**
**NNE** **24 JORALEMON ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.160 mi.**
**844 ft.** **Site 9 of 12 in cluster AQ**

**Relative: Higher**

**Actual: 43 ft.**

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110013328103 |
| Plant name: | 24 JORALEMON ST BUILDING |
| Plant address: | 24 JORALEMON ST<br>BROOKLYN, NY 11201 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 6513 |
| Sic code desc: | Not reported |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | Not reported |
| National action type: | Not reported |
| Date achieved: | Not reported |
| Penalty amount: | Not reported |
| Air program: | Not reported |
| National action type: | Not reported |
| Date achieved: | Not reported |
| Penalty amount: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |

**24 JORALEMON ST BUILDING (Continued)** **1006379924**

Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

**AQ360** **24 JORALEMON ST BUILDING** **FINDS** **1016077571**
**NNE** **24 JORALEMON ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.160 mi.**
**844 ft.** **Site 10 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**43 ft.**

FINDS:

Registry ID: 110013313690

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

---

**AS361** **BTWN DITMAS AV/DEAD END** **NY Spills** **S104510602**
**ENE** **91ST ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.160 mi.**
**845 ft.** **Site 2 of 4 in cluster AS**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9913824 |
| Facility Type: | ER |
| DER Facility ID: | 227407 |
| Site ID: | 280092 |
| DEC Region: | 2 |
| Spill Date: | 3/8/2000 |
| Spill Number/Closed Date: | 9913824 / 2/14/2003 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR) |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 3/8/2000 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/8/2000 |
| Spill Record Last Update: | 2/14/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |

**BTWN DITMAS AV/DEAD END (Continued)** **S104510602**

| | |
|---|---|
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"ADMINISTRATIVE CLOSURE - AUSTIN |
| Remarks: | 7 - 55GAL DRUMS FOUND ABANDONED - NOT LEAKING - DEP NOT DOING ANYTHING WITH THEM |

Material:

| | |
|---|---|
| Site ID: | 280092 |
| Operable Unit ID: | 1092208 |
| Operable Unit: | 01 |
| Material ID: | 292112 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AN362** **BROOKLYN MOTOR CYCLE WORKS** **RCRA NonGen / NLR** **1000555897**
**SSE** **194 SACKETT ST** **FINDS** **NYD986984441**
**1/8-1/4** **BROOKLYN, NY**
**0.161 mi.**
**849 ft.** **Site 6 of 6 in cluster AN**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | BROOKLYN MOTOR CYCLE WORKS |
| Facility address: | 194 SACKETT ST<br>BROOKLYN, NY 112313016 |
| EPA ID: | NYD986984441 |
| Mailing address: | SACKETT ST<br>BROOKLYN, NY 11231 |
| Contact: | Not reported |
| Contact address: | SACKETT ST<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Land type: | Private |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | STEVE BARRANCA |
| Owner/operator address: | UNKNOWN<br>UNKNOWN, NY 99999 |
| Owner/operator country: | US |

**BROOKLYN MOTOR CYCLE WORKS (Continued)** **1000555897**

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: STEVE BARRANCA
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: BROOKLYN MOTOR CYCLE WORKS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: BROOKLYN MOTOR CYCLE WORKS
Classification: Not a generator, verified

Date form received by agency: 11/04/1991
Facility name: BROOKLYN MOTOR CYCLE WORKS
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/26/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

**BROOKLYN MOTOR CYCLE WORKS (Continued)** **1000555897**

Registry ID: 110004481711

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

---

**AQ363** **RIVERSIDE BUILDINGS** **NY UST** **U001837938**
**NE** **30 JORALEMON ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.162 mi.**
**857 ft.** **Site 11 of 12 in cluster AQ**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

UST:
Id/Status: 2-196401 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 2002/10/15
UTM X: 584635.57921
UTM Y: 4505213.8396500004
Site Type: Unknown

Affiliation Records:
Site Id: 6405
Affiliation Type: Facility Owner
Company Name: IMPROVED DWELLINGS CO
Contact Type: Not reported
Contact Name: Not reported
Address1: 111 REAT NECK ROAD
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 487-4940
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6405
Affiliation Type: Mail Contact
Company Name: RIVERSIDE BUILDINGS
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 30 JORALEMON STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11021
Country Code: 001
Phone: (718) 625-1425
EMail: Not reported

**RIVERSIDE BUILDINGS (Continued)** **U001837938**

| | |
|---|---|
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 6405 |
| Affiliation Type: | On-Site Operator |
| Company Name: | RIVERSIDE BUILDINGS |
| Contact Type: | Not reported |
| Contact Name: | THE PENSON CORP |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 625-1425 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 6405 |
| Affiliation Type: | Emergency Contact |
| Company Name: | IMPROVED DWELLINGS CO |
| Contact Type: | Not reported |
| Contact Name: | JEFFREY C GOLD |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 278-3005 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 23508 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 10000 |
| Install Date: | 10/01/1985 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | 03 |
| Date Test: | 07/01/1996 |
| Next Test Date: | 07/01/2001 |
| Pipe Model: | Not reported |

**RIVERSIDE BUILDINGS (Continued)** **U001837938**

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

---

**AT364** **CON EDISON MANHOLE: 44577** **RCRA-CESQG** **1016149154**
**SSW** **15 SEABRING ST** **FINDS** **NYP004278123**
**1/8-1/4** **BROOKLYN, NY**
**0.166 mi.**
**874 ft.** **Site 7 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 11/14/2012 |
| Facility name: | CON EDISON MANHOLE: 44577 |
| Facility address: | 15 SEABRING ST<br>BROOKLYN, NY 11206 |
| EPA ID: | NYP004278123 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | ROMULO QUIJIJE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 802-5196 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |

**CON EDISON MANHOLE: 44577 (Continued)** **1016149154**

| | |
|---|---|
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

FINDS:

Registry ID: 110055432900

Environmental Interest/Information System

---

**AT365** **CON EDISON** **NY MANIFEST** **S112817832**
**SSW** **15 SEABRING ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.166 mi.**
**874 ft.** **Site 8 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004278123 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 2012-11-14 |
| Trans1 Recv Date: | 2012-11-14 |
| Trans2 Recv Date: | 2012-11-20 |
| TSD Site Recv Date: | 2012-11-20 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004278123 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50.0 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1.0 |

**CON EDISON (Continued)** **S112817832**

| | |
|---|---|
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 001674378GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**AV366** **CON EDISON** **NY MANIFEST** **S113494829**
**NNE** **332 FURMAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 12201**
**0.166 mi.**
**877 ft.** **Site 1 of 3 in cluster AV**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004285201 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 24-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 24-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 28-Jan-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285201 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |

**CON EDISON (Continued)** **S113494829**

| | |
|---|---|
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001674960GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 24-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 24-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 28-Jan-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285201 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001674960GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-01-24 |

**CON EDISON (Continued)** **S113494829**

| | |
|---|---|
| Trans1 Recv Date: | 2013-01-24 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-01-28 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285201 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001674960GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**AV367** **CON EDISON MANHOLE: 9192** **RCRA-CESQG** **1016149854**
**NNE** **332 FURMAN ST FRONT OF** **FINDS** **NYP004285201**
**1/8-1/4** **BROOKLYN, NY**
**0.166 mi.**
**877 ft.** **Site 2 of 3 in cluster AV**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 01/24/2013 |
| Facility name: | CON EDISON MANHOLE: 9192 |
| Facility address: | 332 FURMAN ST FRONT OF<br>BROOKLYN, NY 11201 |
| EPA ID: | NYP004285201 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | ANTHONY SIGNORE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 802-3008 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any |

**CON EDISON MANHOLE: 9192 (Continued)** **1016149854**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

FINDS:

Registry ID: 110055467677

Environmental Interest/Information System

---

**AP368** **BALL RESIDENCE** **NY LTANKS** **S106123981**
**South** **80 CARROLL STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.166 mi.**
**878 ft.** **Site 4 of 4 in cluster AP**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 157556 |
| Spill Number/Closed Date: | 0311649 / 3/8/2004 |
| Spill Date: | 1/15/2004 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 1/15/2004 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |

**BALL RESIDENCE (Continued)** **S106123981**

| | |
|---|---|
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/15/2004 |
| Spill Record Last Update: | 4/21/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller County: | 999 |
| Spiller Contact: | ENRICA BALL |
| Spiller Phone: | (718) 834-0890 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 133225 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"1/21/04 tipple updating/// Demeo responded//Tradewinds retained to conduct cleanup. Tradewinds on site 1/15/043/8/04 TJDClosure report including manifests submitted by Tradewinds. No further action required. Spill closed. |
| Remarks: | homeowner phoned oil co. and said they had about 30 gallons of oil in basem ent on dirt floor. fire co. was on scene. INSURANCE CO WILL CONTACT CLEAN UP CO.; NO SIGN OF LEAK OR OVERFILL FROM DRIVER, BELIEVES IT IS HOMEOWNERS PROBLEM. |

Material:

| | |
|---|---|
| Site ID: | 157556 |
| Operable Unit ID: | 879259 |
| Operable Unit: | 01 |
| Material ID: | 496902 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 30 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AQ369** **SOUTHWEST CORNER** **NY Spills** **S111065055**
**NE** **JORALEMON ST AND COLUMBIA PL** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.166 mi.**
**879 ft.** **Site 12 of 12 in cluster AQ**

**Relative: Higher**

**Actual: 28 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1103205 |
| Facility Type: | ER |
| DER Facility ID: | 405321 |
| Site ID: | 450762 |
| DEC Region: | 2 |
| Spill Date: | 6/22/2011 |
| Spill Number/Closed Date: | 1103205 / 1/18/2012 |

**SOUTHWEST CORNER (Continued)** **S111065055**

| | |
|---|---|
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RWAUSTIN |
| Referred To: | Not reported |
| Reported to Dept: | 6/22/2011 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/22/2011 |
| Spill Record Last Update: | 1/18/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 1/18/12 - Austin - Oil (1 pint) came out of a duct into a Con Ed vault - Con Ed contained and cleaned up the spill - No source or other evidence was found for the oil's origin - See eDocs files for further info - Spill closed - end |
| Remarks: | manhole # 9247 - oil coming in from duct - investigation ongoing and cleanup pending |

Material:

| | |
|---|---|
| Site ID: | 450762 |
| Operable Unit ID: | 1200962 |
| Operable Unit: | 01 |
| Material ID: | 2197438 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0.25 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AW370** **LONG ISLAND COLLEGE HOSPITAL DR. RES.** **NY UST** **U004053218**
**ENE** **94 AMITY STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.167 mi.**
**881 ft.** **Site 1 of 3 in cluster AW**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-610226 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584723.93451000005 |
| UTM Y: | 4504772.0715199998 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 364792 |
| Affiliation Type: | Facility Owner |
| Company Name: | LONG ISLAND COLLEGE HOSPITAL |
| Contact Type: | CHIEF ENGINEER |
| Contact Name: | RALPH GAMBARELLA |
| Address1: | 339 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 6/1/2006 |

| | |
|---|---|
| Site Id: | 364792 |
| Affiliation Type: | Mail Contact |
| Company Name: | LONG ISLAND COLLEGE HOSPITAL |
| Contact Type: | Not reported |
| Contact Name: | ENGINEERING DEPT. |
| Address1: | 339 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 6/1/2006 |

| | |
|---|---|
| Site Id: | 364792 |
| Affiliation Type: | On-Site Operator |
| Company Name: | LONG ISLAND COLLEGE HOSPITAL DR. RES. |
| Contact Type: | Not reported |
| Contact Name: | DEAN TORNER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**LONG ISLAND COLLEGE HOSPITAL DR. RES. (Continued)** **U004053218**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-7764 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 6/1/2006 |

| | |
|---|---|
| Site Id: | 364792 |
| Affiliation Type: | Emergency Contact |
| Company Name: | LONG ISLAND COLLEGE HOSPITAL |
| Contact Type: | Not reported |
| Contact Name: | HOSPITAL OPER. |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-1000 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KXTANG |
| Date Last Modified: | 6/1/2006 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 212071 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 5000 |
| Install Date: | 01/31/1964 |
| Date Tank Closed: | 03/01/2006 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0003 |
| Common Name of Substance: | #6 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | KXTANG |
| Last Modified: | 06/01/2006 |

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

**LONG ISLAND COLLEGE HOSPITAL DR. RES. (Continued)** **U004053218**

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None

---

**AW371** **UNIV HOSPITAL OF BROOKLYN** **NY AST** **A100320118**
**ENE** **97 AMITY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.168 mi.**
**888 ft.** **Site 2 of 3 in cluster AW**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Administratively Closed |
| Facility Id: | 2-348228 |
| Program Type: | PBS |
| UTM X: | 584802.07556000003 |
| UTM Y: | 4504777.3559699999 |
| Expiration Date: | N/A |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 17094 |
| Affiliation Type: | Mail Contact |
| Company Name: | UNIV HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | EAMON QUIRKE |
| Address1: | C/O SUNY DOWNSTATE MEDICAL CTR OF LICH |
| Address2: | 339 HICKS STREET |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 780-4997 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

| | |
|---|---|
| Site Id: | 17094 |
| Affiliation Type: | On-Site Operator |
| Company Name: | UNIV HOSPITAL OF BROOKLYN |
| Contact Type: | Not reported |
| Contact Name: | NICK KAPASSAKIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 780-1847 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 6/28/2011 |

| | |
|---|---|
| Site Id: | 17094 |
| Affiliation Type: | Emergency Contact |

**UNIV HOSPITAL OF BROOKLYN (Continued)** **A100320118**

| | |
|---|---|
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY,INC |
| Contact Type: | Not reported |
| Contact Name: | CHRIS YAKUBOFF |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 780-1126 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/20/2011 |

| | |
|---|---|
| Site Id: | 17094 |
| Affiliation Type: | Facility Owner |
| Company Name: | DOWNSTATE AT LICH HOLDING COMPANY,INC |
| Contact Type: | OFFICER |
| Contact Name: | DEBRA CAREY |
| Address1: | 450 CLARKSON AVE-BOX |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11203 |
| Country Code: | 001 |
| Phone: | (718) 270-1234 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/20/2011 |

Tank Info:

| | |
|---|---|
| Tank Number: | 005 |
| Tank Id: | 33268 |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
E01 - Piping Secondary Containment - Diking (Aboveground)
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Administratively Closed |

**UNIV HOSPITAL OF BROOKLYN (Continued)** **A100320118**

| | |
|---|---|
| Pipe Model: | Not reported |
| Install Date: | 06/01/1977 |
| Capacity Gallons: | 1500 |
| Tightness Test Method: | 03 |
| Date Test: | 03/01/1993 |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | NRLOMBAR |
| Last Modified: | 10/14/2011 |
| Material Name: | Diesel |

---

**AV372** **CONSOLIDATED EDISON** **NY MANIFEST** **1009240220**
**NNE** **MH330-FURMAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.170 mi.**
**897 ft.** **Site 3 of 3 in cluster AV**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004072120 |
| Country: | USA |
| Mailing Name: | CONSOLIDATED EDISON |
| Mailing Contact: | FRANKLIN MURRAY |
| Mailing Address: | 4 IRVING PLACE RM 828 |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-2808 |

| | |
|---|---|
| Document ID: | CTF0810619 |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD039322250 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 01/26/2001 |
| Trans1 Recv Date: | 01/26/2001 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 01/30/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004072120 |
| Trans1 EPA ID: | CTD000604488 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | 51440MA |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 00001 |
| Units: | Y - Cubic yards* (.85 tons) |
| Number of Containers: | 001 |
| Container Type: | DT - Dump trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 2001 |

**AX373** **ATLAS WHITE METAL CO.** **LEAD SMELTERS** **1014201494**
**SSW** **77 DELEVAN** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.172 mi.**
**906 ft.** **Site 1 of 2 in cluster AX**

**Relative:**
**Higher**

**Actual:**
**6 ft.**

Lead Smelter Sites:

| | |
|---|---|
| Site number: | 231 |
| Street map and/or aerial photo: | Y |
| Sanborn fire ins map ref.: | Brooklyn 1904-8 v.1 # 21 |
| Comments: | SMD1950, 1963 |
| DJS match to SMD 48-49: | Not reported |

---

**AT374** **DRUM RUN** **NY Spills** **S106699548**
**South** **HAMILTON AVE.& RAPELYE ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.173 mi.**
**912 ft.** **Site 9 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0406978 |
| Facility Type: | ER |
| DER Facility ID: | 60236 |
| Site ID: | 62095 |
| DEC Region: | 2 |
| Spill Date: | 9/23/2004 |
| Spill Number/Closed Date: | 0406978 / 11/1/2004 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 9/23/2004 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | DEC |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/23/2004 |
| Spill Record Last Update: | 11/1/2004 |
| Spiller Name: | OFFICER TZITZIKALAKIS |
| Spiller Company: | Not reported |
| Spiller Address: | HAMELTON AVE. AND RAPELYE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | OFFICER TZITZIKALAKIS |
| Contact Phone: | (718) 797-6910 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"Drum Run - near entry to Brooklyn/Battery Tunnel11/1/04 TJDDrum emptied as part of Drum Run on 10/29/04. Two addtional drums at location contain solids which were not removed. Spill closed |
| Remarks: | FOUND 3 55 GALLON ABANDONED DRUMS AND THEY APPEAR DAMP AND ONE HAS A SMALL LEAK. THERE SEEMS TO ALSO BE SOME SEDIMENTS MIXED IN WITH THE WASTE OIL AND WATER. |

**DRUM RUN (Continued)** **S106699548**

Material:
- Site ID: 62095
- Operable Unit ID: 889570
- Operable Unit: 01
- Material ID: 555092
- Material Code: 0022
- Material Name: Waste Oil/Used Oil
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: 0
- Units: Pounds
- Recovered: No
- Resource Affected: Not reported
- Oxygenate: False
- Site ID: 62095
- Operable Unit ID: 889570
- Operable Unit: 01
- Material ID: 555091
- Material Code: 0022
- Material Name: Waste Oil/Used Oil
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: 0
- Units: Not reported
- Recovered: No
- Resource Affected: Not reported
- Oxygenate: False

Tank Test:

---

**AT375** **DRUM RUN** **NY Spills** **S106720686**
**South** **HAMILTON AVE AND RAPELYE CORNER** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.173 mi.**
**912 ft.** **Site 10 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:
- Facility ID: 0409284
- Facility Type: ER
- DER Facility ID: 269096
- Site ID: 333858
- DEC Region: 2
- Spill Date: 11/18/2004
- Spill Number/Closed Date: 0409284 / 12/14/2004
- Spill Cause: Abandoned Drums
- Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
- SWIS: 2401
- Investigator: TJDEMEO
- Referred To: Not reported
- Reported to Dept: 11/18/2004
- CID: 408
- Water Affected: Not reported
- Spill Source: Unknown
- Spill Notifier: Affected Persons

**DRUM RUN (Continued)** **S106720686**

| | |
|---|---|
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/18/2004 |
| Spill Record Last Update: | 12/14/2004 |
| Spiller Name: | SAMANTHA COHEN |
| Spiller Company: | CORNER OF |
| Spiller Address: | HAMILTON AVE AND RAPELYE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | SAMANTHA COHEN |
| Contact Phone: | (718) 643-3027 |
| DEC Memo: | 12/14/2004 TJDLocation visited during drum run on 12/10/04, three drums were located. These drums were previously reported (0406978) and found to contain mostly solids during drum run on 10/29/04. A minimal amount of waste oil was removed during the 10/29 drum run and NYC sanatation was notified to remove the drums, a specific reference to the solids in drums was noted in faxed listing to NYC DOS on 11/1/04. Following the new spill report by Community Board #6 the site was revisited with Royal Environmental on 12/10 and it was determined there were no changes, drums still present with solids, NYC DOS did not pick up the drums following DEC notification.RSE (Austin) contacted Community Board to inform them of drum run process. Sangesland contacted DOS to request pick-up of drums. No further action required by DEC. Spill closed. |
| Remarks: | 3 DRUMS OF UNKNOWN OIL : |

Material:

| | |
|---|---|
| Site ID: | 333858 |
| Operable Unit ID: | 1096002 |
| Operable Unit: | 01 |
| Material ID: | 576004 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AT376** **11 SEABRING STREET** **NY UST** **U004125668**
**SSW** **11 SEABRING STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.175 mi.**
**925 ft.** **Site 11 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-610907 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584029.21030999999 |
| UTM Y: | 4503708.3417199999 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 402709 |
| Affiliation Type: | Facility Owner |
| Company Name: | DEBORAH CANNON/358 COLUMBIA REALTY CORP. |
| Contact Type: | PRESIDENT |
| Contact Name: | DEBORAH CANNON |
| Address1: | 7 VALENTINE FARM COURT |
| Address2: | Not reported |
| City: | OLD BROOKVILLE |
| State: | NY |
| Zip Code: | 11545 |
| Country Code: | 001 |
| Phone: | (516) 569-5700 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/2/2008 |

| | |
|---|---|
| Site Id: | 402709 |
| Affiliation Type: | Mail Contact |
| Company Name: | HYDROTECH ENVIRONMENTAL CORP. |
| Contact Type: | Not reported |
| Contact Name: | MS. YASH SAHA |
| Address1: | 111 FULTON STREET |
| Address2: | 2ND FLOOR |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11238 |
| Country Code: | 001 |
| Phone: | (718) 636-0800 |
| EMail: | YSAHA@HYDROTECHENVIRONMENTAL.COM |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/2/2008 |

| | |
|---|---|
| Site Id: | 402709 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 11 SEABRING STREET |
| Contact Type: | Not reported |
| Contact Name: | MIKE ALTMAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**11 SEABRING STREET (Continued)** **U004125668**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (212) 245-5950 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 8/14/2008 |

| | |
|---|---|
| Site Id: | 402709 |
| Affiliation Type: | Emergency Contact |
| Company Name: | DEBORAH CANNON C/O COLUMBIA REALTY CORP |
| Contact Type: | Not reported |
| Contact Name: | MIKE ALTMAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (646) 660-1536 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 8/14/2008 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 224624 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 5000 |
| Install Date: | Not reported |
| Date Tank Closed: | 08/06/2008 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | msbaptis |
| Last Modified: | 08/14/2008 |

Equipment Records:

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

**11 SEABRING STREET (Continued)** **U004125668**

L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 224955 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 10000 |
| Install Date: | Not reported |
| Date Tank Closed: | 08/11/2008 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 09/02/2008 |

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

---

**AT377** **VACANT LOT/FUTURE HOTEL** **NY Spills** **S109206934**
**SSW** **11-15 SEABRING STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.175 mi.**
**925 ft.** **Site 12 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0805267 |
| Facility Type: | ER |
| DER Facility ID: | 351531 |
| Site ID: | 402330 |
| DEC Region: | 2 |
| Spill Date: | 8/5/2008 |
| Spill Number/Closed Date: | 0805267 / Not Reported |
| Spill Cause: | Equipment Failure |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | JAKOLLEE |
| Referred To: | APPRVD ABSRBNT SOCKS & ANNUAL GW SMPLNG |

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

| | |
|---|---|
| Reported to Dept: | 8/6/2008 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 8/6/2008 |
| Spill Record Last Update: | 1/16/2014 |
| Spiller Name: | RACHEL ATAMAN |
| Spiller Company: | VACANT LOT |
| Spiller Address: | 11-15 SEABRING STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | RACHEL ATAMAN |
| Contact Phone: | (631) 462-5866 |
| DEC Memo: | 08/06/08-Vought-Duty desk officer. Called and spoke with Rachel Ataman (Hydrotech 631-462-5866) and 5000-gallon fuel oil UST was removed and UST had hole in the bottom and contaminated soil was noted. Upon return to next day excavation was filled with groundwater that was impacted with free product. Product was vacuumed out last night by vacuum truck and reappeared again this morning. Site will be used for construction of four-story hotel. Site is not E designated. DEC Patel will perform site visit at 2pm and will meet Rajib from Hydrotech onsite (cell 631-241-7401).visited site. met Jacob Pollack from Renotal construction corp. 5000 gal UST was removed from site. tank was located immediately north of site entrance. found contaminated soil and free product on groundwater. two more test pits found on-site and no product found on water. found fill material in each test pits. odors at the site. as per Rajib Moral from Hydrotech, tank was full and product was either #2 oil or diesel. found little dark oil on water (like #4 oil). as per Mr. Pollack, there will be four story hotel in the middle of the site and parking around it. there will driveway in front of hotel, in area where tank was. site will be excavated to 4.4 ft depth in area where hotel foundation will be. groundwater found at approx. 9 ft bg. asked Rajib to submit earlier Phase I and Phase II reports. asked Rajib to remove product and contaminated water and to install recovery pit at tank location.11 to 23 Seabring Street358 Columbia Realty Corp **property owner**Deborah Cannon, Jack Cannon184 Woodmere Blvd SWoodmere, NY 11598-1848Ph: 516-569-5700Jacob Pollack **developer & construction company**Renotal Construction Corp.Ph. (212) 268-8488 (O); (646) 842-1657 (C)Fax (212) 268-8489; email: jacob@renotal.netNDOLA Holding LLC **leasee and future hotel owner**Khandu Patel Ph. (917) 501-7219 (C)Rajib MoralHydro Tech Environmental Corp.Ph. (718) 636-0800 (O); (631) 241-7401 (C)Fax (718) 636-0900; email: rmoral@htecorp.info08/08/08-Hiralkumar Patel. sent email to Mr. Moral requiring submission of previous reports.08/08/08-Vought-DEC requires: 1)submission of PBS registration for 5000-gallon fuel oil UST and gasoline UST 2)implemenation of interim remedial measures (regular product recovery) 3)delineation of soil and groundwater contamination 4)installation of vapor barrier/moisture barrier or SSDS 5)collection of endpoint samples 6)investigation of remote fill |

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

port and location of dispenser islands 7)cc to Renotal and Hydrotech.08/11/08-Vought-Sent out CSL with above requirements to Columbia Realty Corp and NDOLA Holdings with one month due date and cc to Renotal and Hydrotech. Vought called NDOLA and spoke to Khundu Patel for address: Mr. Khandu PatelNDOLA Holdings LLC1030 North 7th StreetNew Hyde Park, NY 11040Fax:(212)633-895208/18/08-Vought-Received call from Debra Cannon (Ph:516-569-5700) who is property owner. Debra indicated that in accordance with her lease signed with Khundu she has assumed all responsibility. Debra will send in copy of lease. She filled out PBS application in early August and are on the way. Received email from Yash Saha (Hydrotech) that contaminated soil was removed from site today,the tanks have been registered and the 10000 gal tank is being cleaned and cut. Received letter from Yasha with update that PBS Application has been submitted for 5000-gallon and 10,000-gallon fuel oil USTs, USTs were removed, 947 tons of soil were removed, first VEFR was on 8/14 and one inch of product present on groundwater, oil sheen present in 10,000-gallon UST pit, and replacement of booms and pads on a daily basis. Vought sent email reply requesting date of submission of RAP with complete delineation results of soil and groundwater contamination.09/04/8-Vought-File review to date by Vought:Email from Hydrotech Saha to DEC Vought-8/19/08. Investigation workplan will be submitted by end of the week and when results are in RAP will be submitted.Letter from Hydrotech Saha to DEC Vought-8/25/08. 2nd EFR event performed on 8/21/08. Depth to GW is 4'bg and "a very thin product film was observed in an isolated spot of the pit". Next EFR event scheduled for 8/28/08. Boom and pads are being replaced every two days as well.Email from Hydrotech Saha to DEC Vought-8/28/08. "...both weekly reports documents the large 10000-gallon excavation pit with little and no subsequent sheen at all. My client needs to drive piles in for construction and will not be able to do so with a large open pit". Request for DEC recommendations.Subsurface Investigation Proposal (Hydrotech Saha)-9/3/08. Proposal for installation of five wells. Site was foundry and former drycleaning facility.09/04/08-Vought-Called Hydrotech Saha, informed him that DEC would not make recommendations or approve backfill as this was purview of consultant and should be based on endpoint samples including soil sidewalls and bottom groundwater and results of delineation. Vought also informed him of full list analysis requirements as site was former drycleaner. Vought sent letter approving of 9/3/08 scope of work pending inclusion of full list analysis on soil and groundwater samples and noting outstanding requirements from letter dated 8/11/08. Vought called Hydrotech Saha (631-433-5048) and spoke to her and summarized DEC requirements and she agreed to additions and she also stated that PBS registration for both tanks was submitted.DEC requires: 1)submission of PBS registration for 5000-gallon fuel oil UST and gasoline UST 2)implemenation of interim remedial measures (regular product recovery) 3)delineation of soil and groundwater contamination 4)installation of vapor barrier/moisture barrier or SSDS 5)collection of endpoint samples 6)investigation of remote fill port and location of dispenser islands 7)cc to Renotal and Hydrotech 8)FULL LIST analysis as site is drycleaner. 11/3/08-Vought-Received and reviewed Tank Closure Report dated 9/22/08 and received on 11/3/08 from HydroTech Yash Saha. Report was prepared for:Talman Capital Partners, LLC37 East 28th Street, Suite 508New York, NY 10016Site is being excavated for development and was formerly occupied by 1-story

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

kitchen cabinet warehouse and site was formerly used as a storage lot for construction materials used for Brooklyn Battery Tunnel since 1980. Site was also formerly used as a laundry facililty in 1900's. GPR survey was performed; two anomolies were found and 10 soil borings were installed (two borings at each anomoly and six in a grid pattern throughout site). Groundwater at 8'bg and free product was detected in marco soil samples from around UST area. Removal of one 5000-gallon #2 fuel oil UST and one 10,000-gallon # 2 fuel oil UST that were located next to each other in the northwest portion of the site. "Evidence of holes was noted in the USTs and minimum corrosion was identified". A total of 947.90 tons of contaminated soil was removed and separate dimensions of excavations pits were noted as well. Free product noted in 5000-gallon UST pit. Weekly VEFR events performed for two weeks until no product or sheen was mnoted in pits. Five sidewall samples collected from 5000-gallon pit (four soil sidewalls and one bottom groundwater) and eight samples collected from 10000-gallon pit (six soil sidewall samples and two bottom groundwater samples). PID readings were 0ppm on all endpoint samples. Soil endpoint analyticals show non-detect for SVOCs but some elevated SVOCs (such as 20,000ppb benzo(b)fluoranthene(EP1) and other elevated PAHS in all samples suggesting coal ash or fill source. "Fill material, specifically brick fragments and stones were identified within the sidewalls)." Report recommends submission to DEC for recommendations.11/3/08-Vought-Received and reviewed Groundwater Investigation Report dated 10/29/08 and received on 11/3/08 from HydroTech Yash Saha. Report was prepared for:Talman Capital Partners, LLC37 East 28th Street, Suite 508New York, NY 10016Install'n of 5 monitoring wells. LNAPL present in well MW2(3.5'Free product)(southwestern boundary of site) and MW3(.65' free product)(south of UST excavation). Site is currently under development. Wells installed were 2" geoprobe wells and groundwater at depth of 8'bg. Fill material beneath the site "consists of construction debris including stones, pebbles, and brick/glass fragments. "Gray clayey sand with and olfactory evidence of petroleum contamination and organic vapors at .0.ppm was noted from 6 to 12 feet in SP-1. Gray clayey sand with evidence of product and organic vapors at 0.0ppm was noted from 10 to 12 feet in SP-2". Petroleum odors and evidence of product were also noted in SP-3(6-10'bg), SP-4(8-12'bg), SP-5(6-12'bg). Groundwater flow to the southwest after well installation. Groundwater samples analyzed for full list. Soil analyticals show: 18000ppb 1,2-dichlorobenzene(SP2 10-12'bg), 17000ppb napthalene(SP2 10-12'bg), 15,000ppb dibenzofuran(SP2 10-12'bg), 150000ppb phenanthrene(SP2 10-12'bg), 82000ppb fluoranthene(SP2 10-12'bg), 34000ppb chrysene(SP2 10-12'bg). Groundwater analyticals show: 63ppb chlorobenzene(MW2), 8.2ppb xylene(MW2), 15ppb 1,24-trimethylbenzene(MW2), 180ppb 1,2-dichlorobenzene(MW2), 18ppb napthalene(MW2). Vought discussed dichlorobenzene with DEC O'Connell who confirmed that it is a chlorinated solvent however is not used in drycleaners. Report recommends submission of report to DEC, install'n of down-gradient well and collection of addt'l groundwater samples to delineate chlorinated solvent contamination to groundwater. Report also recommends installation of a vapor barrier and SSDS system. Vought received email from HydroTech Saha requesting site visit to discuss RAP. Vought called Saha and stated that RAP could not be discussed prior to delineation and that delineation must be performed and then site visit would be scheduled.DEC requires developer letter with

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

requirements of: 1)downgradient delineation 2)submission and approval of RAP prior to development 3)installation of vapor/moisture barrier and SSD due to presence of chlorinated solvents 4)implementation of IRM product recovery 5)surrounding area site plan 6)sensitive receptor survey 7)possible transfer to DEC Petroleum Remediation Unit or Haz Waste Remediation Unit(Krimgold).11/05/08-Vought-Sent letter with above requirements.11/08/08-Vought-Received call from and spoke to Jack Cannon and Debra is wife. Jack and Debra in communication with developer. Vought summarized current site status with Jack and site will be a future hotel. Hotel will not take entire footprint of property. Parking on both sides and rear of property. Cannon will contact developer to get copies of reports. Vought to consider STIPULATION AGREEMENT on site.11/21/08-Vought-Received email from Saha that EFR event will take place tomorrow and will be followed by the delineation in about 2 to 3 week's time and a workplan will be submitted prior to mobilization. Weekly VEFR events to take place.12/04/08-Vought-Received email from Hydro Tech Saha that "We still haven't been able to get on Site to perform an EFR. We were scheduled to do it this Wed, however, the developer is driving piles inand its not safe for us to be on Site. We have to reschedule this fortentatively next week. I will keep you informed." Due to develoment of site without submission of RAP and delineation Vought sending out do not develop letter to all city agencies. Vought called Hydro Tech Saha and informed him of letter. Saha agreed that developer not being cooperative with investigation and proceeding with development despite DEC requirements. Vought called and and spoke to Debra Cannon of lack of cooperation with RP and she will contact her legal rep for further advice. Vought called NDOLA Holdings Michael Altman (Talman Capital's 212-245-5950 Alternate Phone 646-660-1536)and required that he submit a signed written statement that developement will not proceed until a RAP is approved. If no statement is received then developer letter will be sent out requesting permit revocation. Vought called and spoke to Hydro Tech Saha and she has received call from Altman and will be onsite Monday to perform work. Saha (631-433-5048) will return call to Vought when onsite Monday and will also submit a status/work proposal letter to DEC.12/05/08-Vought-Received letter via email from Hydro Tech Saha dated 12/4/08. "The property owners 358 Columbia Realty Corp and NDOLA Holdings LLC and developer HY Point Project & Development, LLC (represented by Mr. Mike Altman) would like to reiterate to NYSDEC that all efforts will be taken to address onsite and offsite contamination associated with this Spill case. Following work will be performed effective December 8, 2008: "...performance of weekly EFR, offsite GW investigation (rpt to be submitted to DEC by 1/2/09), submittal of vapor barrier and SSDS design and submission of RAP by 1/2/99. 'The responsible parties understand that until further notice from the NYSDEC, no concrete pour or other relevant aspects of the construction will be performed. However, piles may be driven and installed during this time. In addition, no soil will be disturbed". Vought received message from Hydro Tech Ataman and returned call and approved of above letter. Vought called developer and spoke to new manager assigned to case who is Daniel Lawlor (cell:646-842-0781). Lawlor recently spoke to Ataman, agreed to no further development. No DOB notification sent to date due to recent agreement by developer of no new development as per letter received 12/4/08. Vought received message from Jack Cannon that he was onsite yesterday. Vought returned call and spoke to Debra Cannon and her husband spoke with

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

builder. Debra will return call to DEC on 1/2/08 to confirm report receipt. Vought received call from and spoke to Hydro Tech Ataman who requested to begin soil excavation for building. Vought replied that due to the unknown presence of possible soil contamination in the building footprint that excavation could begin without submission of RAP if developer agreed to remove all soil down to the water table and hence ensure complete source removal and hotel location directly over former UST pads.12/11/08-Vought-Email from Saha and first EFR event performed on 12/11/08. Request for sidewalk authorization letter.12/15/08-Vought-Email from Saha of first weekly EFR letter. Next VEFR scheduled for 12/17/08. EFR report included dated 12/11/08. Wells MW3 and MW destroyed by Pile driving. 5.64 feet of free product in MW2.12/17/08-Vought-Received site plans from Daniel Lawlor (Renotal) to show where he was intending to do additional soil excavation. Proposal includes Hydrotech onsite with PID during excavation and stockpiling of contaminated soils on poly sheeting. 12/18/08-Vought-Received and reviewed Vapor Barrier System Design Specifications dated 12/18/08 from Hydro Tech. Site development plan includes four story hotel with cellar. Top of the cellar slab will be 3.68'bg and thickness of slab will be 8". Proposal to install vapor barrier of 46-mil low permeability Preprufe liner and active SSDS with fan and vent on roof. Proposal for "vapor mitigation testing" to be performed upon completion of all construction to account for HVAC system. 12/23/08-Vought-EFR letter from Hydrotech dated 12/23/08. EFR dates from 12/15-12/22. 4.75' free product found in well MW2.12/30/08-Vought-DEC requires:1)Downgradient delineation-report to be submitted by 1/2/09.2)Submission and approval of RAP for soil/groundwater/soil vapor prior to development including excavation for foundation. Approval or disapproval of contractors request to begin limited excavation without submission of RAP.3)DEC review and approval of vapor barrier proposal dated 12/18/08 including active SSD due to presence of chlorinated solvents.4)Continuation of biweekly IRM product recovery, possible switch to weekly due to 5.64' free product.5)Surrounding area site plan 6)Sensitive receptor survey 7)Possible transfer to DEC Petroleum Remediation Unit or Haz Waste Remediation Unit(Krimgold).1/2/09-Vought-Received call from and spoke to Debra Cannon who inquired if DEC received delineation results by today (as per Hydro Techs prior committment). No results received to date by DEC and Cannon to follow up with Hydro Tech and return call.02/03/09-Vought-Meeting with DEC Austin, DEC Krimgold, DEC Brevdo, DEC Tibbe and spill transferred to Petroleum Remediation Unit Jospeph Maisonave. File transferred to Masionave and Vought called Hydro Tech Ataman and provided her contact info for DEC Maisonave.2/3/09 DEC lead transferred from J. Vought to J.A. Maisonave. - JAM2/9/09 Met with R. Ataman from Hydrotech and construction supervisor at DEC Region 2 office. I sent an email on 2/4/09, and requested more wells be installed to fully delineate free product plume and dissolved phase contamination. Four monitoring wells will be installed around existing well MW-2. EFR events will then continue on a weekly basis until further notice. A modified RAP will be submitted with results from the well installation. - JAM2/24/09 Met with Rachel Ataman from HydroTech and D. Lawlor, the construction supervisor this morning at Region 2 offices. She delivered a copy of the "Revised Remedial Action Plan" and the "EFR Letter - 01/30/2009 to 02/16/2009."I reviewed the Revised RAP and EFR letter. On Februart 12, 2009 HydroTech installed 6 additional monitoring wells (MW-9 through MW-14) around existing well MW-2 to

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

delineate the free product plume. All the wells were immediately gauged and product was discovered in wells MW-2, MW-10 and MW-14. Product was removed and wells MW-9 through MW-14 were sampled for lab analysis of VOCs and SVOCs. Some VOCs were detected above TOGS in wells MW-11, MW-12 and MW-14. Minor SVOCs were discovered in all 6 wells.The Revised RAP proposes:1.Excavate all contaminated soil on-site until clean soil is encountered or to the extent feasible.2.Install a vapor barrier and sub-slab depressurization system for the proposed building.3.Perform weekly enhanced fluid recovery events on all groundwater monitoring wells in which free product is present.4.Continue to perform monthly gauging and quarterly sampling of all accessible groundwater monitoring wells.I sent a letter approving the Revised RAP with the following comments:1.Any wells destroyed during construction activities must be reinstalled.2.If free-product or dissolved-phase groundwater contamination persists in any wells, then a remedy to address that contamination should be proposed.The approval letter is uploaded to eDocs. - JAM3/17/09 Reviewed the EFR Letter for period February 26 to March 6, 2009 submitted by HydroTech dated March 13, 2009. On March 6, 2009 all accessible wells were gauged for product and EFR with a vac truck was perfromed on wells that contained product.Product thickness in wells MW-2, MW-7, MW-8, MW-10, and MW-14 was calculated to beapproximately 0.26 feet, 0.02 feet, 0.25 feet, 0.09 feet, and 0.20 feet, respectively. Approximately 40.0 combined gallons of free product/water was removed from those wells.Product was observed in downgradient wells MW-7 and MW-8. I called Rachel Attaman at HydroTech today and advised her that hydraulic control should be established to prevent off-site migration. The EFR letter is uploaded to eDocs. - JAM4/2/09 Visited site today to witness soil excavation for building foundation. Free product was observed on puddles of water in excavation. When digging in those areas, grossly contaminated soil was exposed and free product was entering from sidewalls. I recommended soil be excavated until clean soil is encountered. Excavation will continue tomorrow and contaminated soil will be live loaded and disposed off-site. - JAM4/7/09 Excavation was postponed until 4/7/09 due to weather. Several trucks of contaminated soil was live-loaded and disposed off-site. Oil-saturated soil was observed on sidewalls and product was floating on top of water in excavation. I requested water be removed, however a vac truck was not available and excavation was backfilled leaving contaminated soil and groundwater in place. The general contractor, Dan Lawlor, requested a meeting with Jon Kolleeny and myself, which will be held tomorrow at DEC Region 2 office. - JAM4/9/09 On April 8, 2009, a meeting was held at the DEC Region 2 office with the following in attendence:Joseph Maisonave, NYSDECJonathan Kolleeny, NYSDECJeffrey Vought, NYSDECKhandu Patel, NDOLA Holding, LLCDan Lawlor, Renotal ConstructionRonnie Tal, Renotal ConstructionRachal Attaman, Hydro Tech Environmental, Inc.Yash Saha, Hydro Tech Environmental, Inc.An agreement was made that Mr. Khandu Patel would sign a Stipulation Agreement and accept responsibility of cleaning up this spill. Remedial plan includes excavating soil, starting from the west end of the building, and if contaminated soil is encountered, the excavation would continue until clean soil is encountered or to a maximum depth of 2 feet below the water table. A supplemental remedial plan will have to be developed to recover free product observed in the wells on the northwestern portion of the site. A system will be installed to establish hydraulic control and prevent further off-site migration of

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

free product. - JAM4/9/09 A Stipulation Agreement was sent to NDOLA Holding, LLC with a Corrective Action Plan. Mr. Khandu Patel signed the Stip and hand-delivered it to the Region 2 office today. The Stip was then sent to Lou Oliva at DEC Office of General Council for RD Signature. - JAM4/10/09 Stipulation Agreement was signed by Regional Director and is effective as of April 10, 2009. A deliverables in the CAP will be due relative to this effective date. The signed Stip with CAP and cover letter are uploaded to eDocs. - JAM4/10/09 Received via email latest EFR rpt for period 3/30 to 4/7/2009. Product was observed in wells MW-2, MW-8, MW-10 and MW-14 at thicknesses of approx. 0.18 ft, 0.22 ft, 0.01 ft and 0.03 ft, respectively. Next EFR event is scheduled for 4/14/09. Letter uploaded to eDocs. Hydrotech also submitted all past EFR letters dating back to December 11, 2008. - JAM4/13/09 Received a Remadial Action Plan Addendum (RAPA) from HydroTech Env. dated April 10, 2009. The RAPA proposes:1. Implement the RAP as approved by the NYSDEC on February 24, 2009.2. Have a vaccum truck on-site to remove groundwater and free product from the excavation.3. collect a total of 28 end-point soil samples from 6 grids and analyze by EPA Methods 8260 and 8270, including chlorinated compounds.The NYSDEC issued a letter approving the RAPA today with the following comments:1. If contaminated soil is observed extending beyond the building footprint, the excavation of contaminated soil should continue to the extent feasible.2. As stated in the RAP approved on February 24, 2009, any wells destroyed during construction activities should be reinstalled for post-excavation monitoring.The letter and the RAPA are uploaded to eDocs. - JAM4/13/09 Visited the site today to observe excavation activities. the west-end was excavated to about 1 foot below the water table and about 3 feet wide. No contaminated was observed. The central portion of the site was then excavated begining from the west end and moving east. contaminated soil was encountered as they moved east and free product was witnessed on top of the water entering the excavation. The construction crews staged contaminated soil and scheduled trucks to dispose of the soil tomorrow. - JAM4/21/09 Visited site on 4/15 thru 4/17, 4/20 and 4/21. Site activities include excavation of contaminated soil in building footprint to a max depth of 2 ft below water table. On 4/21, contaminated soil was excavated from North wall of building up to sidewalk and grossly contaminated soil was observed extending below sidewalk towards Seabring St. Likely source was fill port which was at street curb. An investigation in sidewalk should be performed to delineate and a remedial proposal should be submitted. - JAM4/23/09 Spoke to R. Attaman, HydroTech and D. Lawlor, Renotal, about advancing soil borings in the sidewalk along Seabring Street to delineate contamination near the fill port. I issued a letter to Hydro Tech to aid in getting a sidewalk permit. The soil borings are scheduled for Monday, April 27, 2009. - JAM4/23/09 Reviewed the EFR Letter for period 4/9 to 4/14. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.05 feet, 0.08 feet, 0.05 feet, 0.20 feet and 0.11 feet, respectively. The next EFR event is schedule for 4/21/09. Letter uploaded to eDocs. - JAM4/24/09 Received via email a Product Delineation Work Plan submitted by HydroTech dated April 24, 2009. Work plan proposes installing 8 soil borings near fill port in sidewalk along Seabring Street. Soil will be continuously screened and two soil samples will be collected and analyzed for VOCs, SVOCs and Chlorinated compounds; one sample from interval with highest PID reading and the other from interval directly above water table.I

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

wrote an approval letter and issued today. Both the work plan and my approval letter are uploaded to eDocs. Fieldwork expected to begin on Monday, April 27, 2009. - JAM4/27/09 Visited the site to observed the geoprove investigation in the street. Several borings showed product in the 6-8 foot interval. These borings were along the property line adjacent to the sidewalk. The boring directly adjacent to the fill port did not appear to have product. Soil samples were collected for lab analysis from the 6-8 foot interval. - JAM4/30/09 Received a letter from HydrTech summarizing end-point soil sample results EP-1 thgrough EP=10. The results show some SVOCs above TAGM 4046 Recommended Soil Cleanup Objectives. Since the concentrations are relatively low and are indicative of fill material, I approved, via email, backfilling the site up until the middle of grid B.A meeting was scheduled at the site between HydroTech and DEC for Monday 5/4/09. - JAM5/2/09 Reviewed EFR Letter for period 4/15 to 4/24. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.01 feet, 0.01 feet, 0.16 feet, 0.01 feet and 0.27 feet, respectively. The next EFR event is schedule for 5/1/09. - JAM5/4/09 Had a meeting at the site. In attendence were representatives from DEC, HydroTech, Renotal, and NDOLA. We discussed the downgradient product plume and requested a proposal be submitted. Proposal should include a Feasibility Study which compares several methods to recover free product in on- and off-site monitoring wells.We also discussed further action in the building foorprint. A proposal to address free-product under the sidewalk will be submitted. - JAM5/8/09 Reviewed the "Sidewalk Soil Sampling Results" submitted by HydroTech dated May 5, 2009. Eight soil probes were advanced near the fill port in the sidewalk along Seabring Street. One soil samples was collected from each boring for laboratory analysis. "Gross Petroleum Stains" were observed in borings SB-9 through SB-11 in the 6-8 foot depth interval; however, laboratory results only showed some SVOCs that exceeded TAGM.HydroTech proposes excavating in the sidewalk to remove all grossly contaminated soil and collecting 4 end-point soil samples from the excavation. Report is uploaded to eDocs.I wrote a letter today approving this recommendation with the following comments:1.If grossly contaminated soil is observed to extend beyond the proposed extent of sidewalk excavation, NYSDEC recommends that the excavation continue to the extent feasible.2.A vacuum truck should be on site to recover any floating product on the water table.The rest of the site will be excavated as per the approved RAP and RAP Addendum. The letter is uploaded to eDocs. - JAM5/9/09 Reviewed EFR Letter for period 4/25 to 5/1. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.50 feet, 0.02 feet, 0.10 feet, 0.04 feet and 0.15 feet, respectively. Next EFR event is schedule for 5/8/09. - JAM5/14/09 Visited the site from 5/11 through 5/13 to observe excavation of contaminated soil in the sidewalk along Seabring Street. Monday, 5/11, the concrete sidewalk and the first 5 feet of clean soil were removed and staged on-site. No vac truck. Tuesday, 5/12, One dump truck was filled with product saturated soil and the excavation extended down to about 1 foot below the water table. The truck was rejected from the disposal facility because there was too much free-phase oil. The vac truck was on-site removing product floating on the water table. Wednesday, 5/13, one lined, roll-off container was filled with very wet and very product-saturated soil. The roll-off was fined for being overweight and did not come back. The vacuum truck was on-site all day removing

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

floating product. Contaminated soil was staged on-site, on poly so that it could dry out and be loaded into dump trucks.Spoke to on-site personnel: vac truck was on-site all day removing floating product. Excavation will continue to Northwest toward firehouse tomorrow. Two dump trucks are scheduled to remove staged material and to be live loaded with material taken from beneath sidewalk. Spoke to Yash Saha about installing wells along Commerce Street. Three wells will be installed around MW-7 and MW-8 to delineate the product plume. Another well will be installed on-site to perform a slug test. - JAM5/15/09 Reviewed EFR Letter for period 5/2 to 5/8. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.08 feet, 0.01 feet, 0.01 feet, 0.08 feet and 0.04 feet, respectively. Next EFR event is schedule for 5/15/09. - JAM5/21/09 Visited the site from 5/18 through 5/21 to observe excavation of contaminated soil beneath the sidewalk along Seabring Street. Two trucks loads of contaminated soil was removed from the site on Monday 5/18. A vac truck was on-site recovering floating product.Tuesday, 5/19, the excavation continued. I went to speak with Jon Bakalexis (property owner at 28 Commerce Street) to request access to his site for drilling product recovery wells. He was not there and I left my card. The NW end of the site was being backfilled with stone.Wednesday, 5/20, the excavation continued and vac truck was on-site recovering floating product. The holes beneath the sidewalk along Seabring Street were backfilled and sloped to stabilize the sidewalk. Three wells were installed along Commerce Street. I spoke with Mr. Bakalexis and he agreed to give access to his property to drill product recovery wells. He requested to see a workplan beforehand.Thursday, 5/21, The excavation has reached the access gate towards the on-site trailor. Six truck-loads of very contaminated soil were removed and two vac trucks were on-site today recovering floating product.The excavation will continue tomorrow. - JAM5/26/09 Reviewed EFR Letter for period 5/9 to 5/15. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.18 feet, 0.01 feet, 0.03 feet, 0.13 feet and 0.10 feet, respectively. Next EFR event is schedule for 5/22/09. - JAM5/29/09 Visited site to witness end of excavation. All grossly contaminated soil has been removed. Rest of building footprint will be excavated to final grade for slab. I sent an email to Khandu Patel stating that building construction can begin. A summary rpt should be submitted by HydroTech which documents remediation to date. A proposal to remediate product in down-gradient wells still needs to be submitted. - JAM5/29/09 Reviewed the EFR Letter for period 5/9 to 5/15. Product was observed in wells MW-2, MW-8, MW-10 and MW-16 with a product thickness of approximately 0.61 feet, 0.30 feet, 0.60 feet and 0.05 feet, respectively. The next EFR event is schedule for 5/29/09. - JAM6/4/09 Spoke to R. Ataman at HydroTech today. A slug test will be conducted on Monday, June 8. Results from the test will be used to develop a remedial proposal that addresses product in the down-gradiet wells. That proposal should be submitted within 3 weeks. - JAM6/5/09 Reviewed the Down-gradient Monitoring Well Investigation Report submitted by HydroTech dated June 4, 2009. Three permanent monitoring wells, MW-15 through MW-17, were installed on May 20th and 21st. No product was observed in wells MW-15 and MW-17 and a product sheen was observed in well MW-16. No soil or groundwater samples were collected for lab analysis. The report is uploaded to eDocs.Reviewed EFR Letter for period 5/23 to 5/29 dated 5/29/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

thickness of approximately 0.51 ft, 0.02 ft, 0.11 ft, 0.29 ft, and 0.07 ft, respectively. Next EFR event is schedule for 6/5/09. - JAM6/16/09 Reviewed the EFR Letter for period 5/30 to 6/5 dated 6/5/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.60 feet, 0.09 feet, 0.06 feet, 0.15 feet and 0.03 feet, respectively. A product sheen was observed in MW-16. The next EFR event is schedule for 6/12/09. - JAM6/18/09 Reviewed the EFR Letter for period 6/6 to 6/12 dated 6/15/09. Wells MW-2 and MW-10 were damaged due to ongoing construction activities during June 6th, 2009 to June 12th, 2009. The top of MW-2's casing is approximately 1 foot below surface grade and the top of MW-10's casing is at surface grade. HydroTech is still able to gauge these wells. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.05 feet, 0.01 feet, 0.53 feet, 0.10 feet and 0.25 feet, respectively. The next EFR event is schedule for 6/19/09. - JAM7/13/09 Reviewed the EFR Letter for period 6/13 to 6/19 dated 6/19/09. Product was observed in wells MW-2, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.45 feet, 0.02 feet, 0.68 feet and 1.50 feet, respectively. A product sheen was observed in MW-7. The next EFR event is schedule for 6/26/09.Reviewed EFR Letter for period 6/20 to 6/26 dated 6/26/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approximately 0.14 feet, 0.01 feet, 0.35 feet, 0.18 feet and 0.11 feet, respectively. Next EFR event is schedule for 7/2/09.On 7/8, I received an email update from Timothy Lo at HydroTech stating the following:"This email is to provide you with an update regarding the work planapproval by the adjacent property owner (Mr. John Bakalexis) of 11-15Seabring Street. As of this date, Mr. Bakalexis has not yet reviewedHydro Tech's Work Plan proposal to install additional monitoring wellsat his property. He requests for more time to review the work plan andto remove the materials present in the back of the property for HydroTech to perform the monitoring well installations."Awaiting approval from Mr. Bakalexis. - JAM7/23/08 Reviewed EFR Letter for period 6/27 to 7/2 dated 7/2/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approx 0.26 ft, 0.01 ft, 0.31 ft, 0.05 ft and 0.13 ft, respectively. Next EFR event is schedule for 7/10/09.Reviewed EFR Letter for period 7/3 to 7/10 dated 7/10/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approx 0.46 ft, 0.01 ft, 0.08 ft, 0.18 ft and 0.35 ft, respectively. Next EFR event is schedule for 7/17/09.Reviewed EFR Letter for period 7/11 to 7/17 dated 7/17/09. Product was observed in wells MW-2, MW-8, MW-10 and MW-14 with a product thickness of approx 0.46 ft, 0.05 ft, 0.10 ft, 0.35 ft and 0.04 ft, respectively. Next EFR event is schedule for 7/24/09. - JAM7/31/09 Reviewed EFR Letter for period 7/18 to 7/24 dated 7/24/09. Product was observed in wells MW-2, MW-7, MW-8, MW-10 and MW-14 with a product thickness of approx 0.02 ft, 0.01 ft, 0.40 ft, 0.29 ft and 0.03 ft, respectively. Next EFR event is schedule for 7/31/09. - JAM8/12/09 Reviewed the EFR Letter for period 7/25 to 7/31 dated 7/31/09. MW-6 and MW-12 were destroyed due to ongoing construction activities during July 25th, 2009 to July 31st, 2009. Product was observed in wells MW-2, MW-7, MW-8, and MW-10 with a product thickness of approximately 0.06 feet, 0.01 feet, 0.08 feet, and 0.01 feet, respectively. The next EFR event is schedule for 8/7/09.Reviewed the EFR Letter for period 8/1 to 8/7 dated 8/7/09. As of August 7th, 2009, the 15-mil vapor barrier has been installed in

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

the footprint of the building. The concrete for the foundation will be poured in the following week. Product was observed in wells MW-2, MW-7, MW-8, and MW-10 with a product thickness of approximately 0.03 feet, 0.15 feet, 2.00 feet, and 0.22 feet, respectively. Due to the product thickness identified in MW-8, a new well will be proposed to delineate MW-8. Additional information can be found in the August 7th, 2009 letter. The next EFR event is schedule for 8/14/09. - JAM8/13/09 Called Khandu Patel and left a message to discuss future work. - JAM8/19/09 Spoke to Khandu Patel today. I requested that HydroTech contact the property owner at 28 Commerce Street and get his approval to install wells on his property. The work plan was submitted via email on June 8, 2009 and the Remedial Feasibility Study Report was submitted via email on July 20, 2009.When the property owner at 28 Commerce Street approves drilling wells on his property then I will issue a letter approving the work plan.I wrote an email to Yash Saha at HydroTech requesting that she resubmit the Soil Excavation Report. The Report was submitted via email on July 15, 2009. - JAM8/19/09 Sent email to Khandu Patel:"In light of recent increase in product levels in well MW-8, as per latest EFR event, DEC requests that vacuum enhanced fluid recovery with a vaccum truck be performed on all wells that contain free product. Vacuum truck will have more of an effect on area surrounding wells and may expedite recovery. Also in latest EFR letter, HydroTech proposed installing another well, however, location of that well was not indicated on map. Please advise HydroTech to include location of additional well in next EFR letter." - JAM8/28/09 Reviewed the EFR Letter for period 8/8 to 8/14 dated 8/14/09. MW-11 was destroyed due to ongoing construction activities during August 8th, 2009 to August 14th, 2009. Product was observed in wells MW-2, MW-8, MW-10, and MW-14 with a product thickness of approximately 1.52 feet, 0.70 feet, 1.98 feet, and 0.10 feet, respectively.Reviewed the EFR Letter for period 8/15 to 8/21 dated 8/21/09. MW-10 was buried under construction materials during the EFR event and could not be sampled. Product was observed in wells MW-2, MW-7, and MW-8 with a product thickness of approximately 0.02 feet, 0.10 feet, and 0.10 feet, respectively.The first EFR with a vacuum truck occurred today. HydroTech said they evacuatied each well with product until all fluids were gone. They said they spent about 1 minute on each well. I called HydroTech to discuss this approach as it is not the same as the approach they had proposed. Mustafa El Sehamy from HydroTech said that on future events they will spend more time on each well and focus on removing (skimming) the product off the top of the water table. This approach is supposed to create a mounding effect around the well and will have influence on the surrounding area.I also spoke to K. Patel today and advised him to present an access agreement to the property owners at 28 Commerce Street. I sent him a follow up email with the address for the current property owners. - JAM9/8/09 Reviewed the EFR Letter for period 8/22 to 8/28 dated 8/28/09. Wells MW-1, MW-2, MW-7 through MW-9, and MW-14 through MW-17 were gauged for product on 8/28/09. Product was observed in wells MW-2, MW-8 and MW-10 with a product thickness of approximately 0.15 feet, 0.15 feet and 0.25 feet, respectively. A product sheen was observed in well MW-7. This was the first round of product recovery using a vacuum truck. Approximately 22.0 combined gallons of free product/water was removed via vac truck. I advised HydroTech to perform product recovery for a longer duration on each well. Another VEFR event was performed on September 4, 2009. Awaiting results. - JAM9/11/09 Reviewed the EFR Letter for

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

period 8/29 to 9/4 dated 9/4/09. Wells MW-1, MW-2, MW-7, MW-8, and MW-14 through MW-17 were gauged for product on 9/4/09. Product was observed in wells MW-2, MW-7, MW-8 and MW-10 with a product thickness of approximately 0.25 feet, 0.21 feet, 0.64 feet and 0.55 feet, respectively. Approximately 60.0 combined gallons of free product/water was removed via vac truck. Each well was pumped for 5 minutes, allowed to recharge for 5 minutes and repeated, for a total of 20 minutes. Another VEFR event was performed on September 11, 2009. - JAM9/18/09 Reviewed the EFR Letter for period 9/5 to 9/11 dated 9/11/09. Wells MW-1, MW-2, MW-7, MW-8, MW-9, and MW-14 through MW-17 were gauged for product on 9/11/09. Product was observed in wells MW-2, MW-7, MW-8 and MW-10 with thicknesses of approx. 0.04 feet, 0.01 feet, 0.15 feet and 0.05 feet, respectively. Approximately 159 gallons of product/water mixture was removed via vac truck (55 gallons of free product). HydroTech's approach this time was each well pumped for 5 minutes, allowed to recharge for 5 minutes and repeated, for a total of 40 minutes.I visited site to observe next round of VEFR today. This approach seems to be reducing product levels in wells. VEFR will continue for as long as product is being recovered. - JAM9/25/09 Reviewed the EFR Letter for period 9/12 to 9/18 dated 9/18/09. Wells MW-1, MW-2, MW-7, MW-8, MW-9, MW-10 and MW-14 through MW-17 were gauged for product on 9/11/09. Product was observed in wells MW-2, MW-8 and MW-10 with thicknesses of approx. 0.03 feet, 0.05 feet, and 0.01 feet, respectively. Approximately 203 gallons of product/water mixture was removed via vac truck (55 gallons of free product). HydroTech pumped each well for 5 minutes, allowed to recharge for 5 minutes and repeated, for a total of 40 minutes.The next EFR event is scheduled for 9/25/09. - JAM10/2/09 Reviewed the EFR Letter for period 9/19 to 9/25 dated 9/25/09. Wells MW-2, MW-7, MW-8, MW-9, and MW-14 through MW-17 were gauged for product on 9/25/09. Well MW-1 was destroyed due to construction activities during this period. Product was observed in wells MW-2, MW-7, MW-8 and MW-10 with thicknesses of approx. 0.03ft, 0.01ft, 0.02ft, and 0.02ft, respectively. Well MW-14 contained a sheen. Approx. 133-gallons of product/water was removed via vac truck.The next EFR even is scheduled for 10/2/09. - JAM10/6/09 Reviewed a "Product Delineation Work Plan" submitted by HydroTech and dated August 18, 2009. The work plan proposes installing 2 monitoring wells along Commerce Street adjacent to existing monitoring well MW-17.I issued an apporval letter today. Work plan and approval letter are uploaded to eDocs. - JAM10/16/09 Reviewed the EFR Letter for period 9/26 to 10/2 dated 10/2/09 and submitted 10/14/09. Wells MW-2, MW-7, MW-8, MW-9, and MW-14 through MW-17 were gauged for product on 10/2/09. Product was observed in wells MW-2, MW-7, MW-8 and MW-10 with thicknesses of approx. 0.07ft, 0.01ft, 0.05ft, and 0.02ft, respectively. Well MW-14 contained a sheen. Approx. 81-gallons of product/water was removed via vac truck.Reviewed the EFR Letter for period 10/3 to 10/9 dated 10/9/09 and submitted on 10/15/09. Wells MW-2, MW-7, MW-8, MW-9, and MW-14 through MW-17 were gauged for product on 10/9/09. Product was observed in wells MW-2, MW-7, MW-8 and MW-10 with thicknesses of approx. 0.07ft, 0.02ft, 0.06ft, and 0.01ft, respectively. The product thickness from the last monitoring event to this one has: remained constant in MW-2, increased in MW-7, increased in MW-8, decreased in MW-10, and decreased in MW-14. Approx. 55-gallons of product/water was removed via vac truck. - JAM12/8/09 Reviewed EFR Letter for period 10/10 to 10/16 dated 10/16/09 submitted on 11/2. Wells MW-2, MW-7, MW-8, MW-9, MW-10 and

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

MW-14 thru MW-17 were gauged for product on 10/16/09. Product thickness in MW-2, MW-8 and MW-10 was calculated to be approx 0.03 ft, 0.11 ft, and 0.01 ft, respectively. A sheen was observed in well MW-7. Approx 124 gals of product/water mixture was removed from 4 wells with a vac truck.Reviewed the EFR Letter for period 10/17 to 10/23 dated 10/23 and submitted on 11/2/09. Wells MW-2, MW-10, and MW-14 were destroyed due to ongoing construction activities during 10/17 to 10/23. Wells MW-7, MW-8, MW-9, and MW-15 through MW-17 were gauged for product on 10/23. The product thickness in MW-7, MW-8 and MW-16 was calculated to be approximately 0.01 feet, 0.33 feet, and 0.13 feet, respectively. Approximately 54 gallons of product/water mixture was remoced from the 3 wells with a vac truck.Reviewed the EFR Letter for period 10/24 to 10/30 dated 10/30 and submitted on 11/2/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-17 were gauged for product on 10/30. The product thickness in MW-8 and MW-16 was calculated to be approximately 0.13 feet and 0.39 feet, respectively. A product sheen was detected in MW-7 Approximately 55 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 10/31 to 11/6 dated 11/6 and submitted 11/19/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-17 were gauged for product on 11/6. The product Thickness in MW-8 and MW-16 was calculated to be approximately 0.03 feet and 0.68 feet, respectively. A product sheen was detected in MW-7. Approximately 59 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 11/7 to 11/13 dated 11/13 and submitted 11/19/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-17 were gauged for product on 11/13. The product thickness in MW-7, MW-8 and MW-16 was calculated to be approximately 0.01 feet, 0.03 feet and 0.56 feet, respectively. Approximately 104 gallons of product/water mixture was removed from the 3 wells with a vac truck.I received an email from Rachel Ataman on 11/23/09 notifying that product levels in MW-16 have increased to 0.73 on the 11/20/09 EFR event. My email response is as follows:"Have the additional monitoring wells been installed as per the approved work plan? I sent an approval letter on October 6, 2009. I think you should propose a more aggressive remedial strategy. You also should contact the property owner next door to 28 Commerce Street and see if he will allow wells to be installed on his site. I need to see something in the near future since downgradient properties are impacted."Also any wells that have historically contained product that have been destroyed due to construction activities should be reinstalled and product recovery should continue. - JAM1/5/10 Reviewed the EFR Letter for period 11/14 to 11/20 dated 11/20 (#43) and submitted 12/9/09. The proposed DG monitoring wells, MW-18 and MW-19, were installed on November 3, 2009. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 11/20. The product thickness in MW-7, MW-8 and MW-16 was calculated to be approximately 0.02 feet, 0.06 feet and 0.73 feet, respectively. Approximately 101 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 11/21 to 11/25 dated 11/25 (#44) and submitted 12/9/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 11/25. The product thickness in MW-7, MW-8 and MW-16 was calculated to be approximately 0.01 feet, 0.04 feet and 0.76 feet, respectively. Approximately 54 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 11/26 to 12/4 dated 12/4 (#45) and submitted 12/9/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

product on 11/25. The product thickness in MW-8 and MW-16 was calculated to be approximately 0.07 feet and 0.77 feet, respectively. A sheen was observed in well MW-7. Approximately 53 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 12/4 to 12/11 dated 12/11 (#46) and submitted 12/18/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 11/25. The product thickness in MW-8 and MW-16 was calculated to be approximately 0.04 feet and 0.75 feet, respectively. A sheen was observed in well MW-7. Approximately 106 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letter for period 12/11 to 12/18 dated 12/18 (#47) and submitted 12/24/09. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 11/25. The product thickness in MW-8 and MW-16 was calculated to be approximately 0.02 feet and 0.34 feet, respectively. A sheen was observed in well MW-7. Approximately 53 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed EFR Letter for period 12/21 to 12/25 (*dates were wrong on the actual letter) dated 12/22 (#48) and submitted 12/24/09. Wells MW-7, MW-8, MW-9, and MW-15 thru MW-19 were gauged for product on 11/25. Product thickness in MW-8 and MW-16 was calculated to be approx 0.03 feet and 0.25 feet, respectively. A sheen was observed in well MW-7. Approx 84 gallons of product/water mixture was removed from 3 wells with a vac truck. - JAM2/8/10 Reviewed the EFR Letter for period 12/19 to 12/30 dated 12/30 (#49) and submitted 1/5/10. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 12/30. The product thickness in MW-8 and MW-16 was calculated to be approximately 0.02 feet and 0.10 feet, respectively. A sheen was observed in well MW-7. Approximately 105 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letters #50 and #51 for period 12/31/09 to 1/8/10 dated 1/8/10 and submitted 1/11/10. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 1/6/10 and 1/8/10. During the 1/6/10 gauging event, product thickness in MW-8 and MW-16 was calculated to be approximately 0.02 feet and 0.19 feet, respectively. During the 1/8/10 gauging event, product thickness in MW-8 and MW-16 was calculated to be approximately 0.02 feet and 0.08 feet, respectively. A sheen was observed in well MW-7 during both gauging events. During the 1/6/10 event, approximately 13 gallons of product/water mixture was removed from the 3 wells with a pump. During the 1/8/10 event, approximately 74 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letters #52 and #53 for period 1/9/10 to 1/15/10 dated and submitted 1/15/10. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 1/13/10 and 1/15/10. During the 1/13/10 gauging event, product thickness in MW-8 and MW-16 was calculated to be approximately 0.01 feet and 0.21 feet, respectively. During the 1/15/10 gauging event, product thickness in MW-8 and MW-16 was calculated to be approximately 0.02 feet and 0.23 feet, respectively. A sheen was observed in well MW-7 during both gauging events. During the 1/13/10 event, approximately 11 gallons of product/water mixture was removed from the 3 wells with a pump. During the 1/15/10 event, approximately 104 gallons of product/water mixture was removed from the 3 wells with a vac truck.Reviewed the EFR Letters #54 and #55 for period 1/16/10 to 1/20/10 dated and submitted 1/20/10. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 1/19/10 and 1/20/10. During the 1/19/10 gauging event, product thickness in MW-8 and MW-16 was calculated to

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

be approximately 0.01 feet and 0.23 feet, respectively. During the 1/20/10 gauging event, product thickness in MW-8 and MW-16 was calculated to be approximately 0.01 feet and 0.10 feet, respectively. A sheen was observed in well MW-7 during both gauging events. During the 1/19/10 event, approximately 10 gallons of product/water mixture was removed from the 3 wells with a pump. During the 1/20/10 event, approximately 88 gallons of product/water mixture was removed from the 3 wells with a vac truck. - JAM2/11/10 Reviewed an Investigation Work Plan dated January 6, 2010, submitted by HydroTech via email on January 13, 2010. The WP proposes: installing two additional wells along Commerce Street, to the west of existing wells MW-16 and MW-19; reinstalling wells MW-2 and MW-10, which were destroyed during construction.I issued a letter today approving the work plan with the following requirement: an additional well should be reinstalled to replace well MW-14, which was also destroyed during construction. I also require that quarterly groundwater gauging and sampling resume and that reports be submitted quarterly. I also requested several items be included in all future reports (see letter). This work plan and my letter are uploaded to eDocs. - JAM4/6/10 Reviewed EFR Letter (#56 & #57) dated 1/28/10 for period 1/21/2010 to 1/28/2010 submitted via email on 2/5/2010. During this period wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 1/27 and 1/28. The product thickness in MW-8 and MW-16 during the 1/27 gauging event was approximately 0.01 feet and 0.19 feet, respectively. The product thickness in MW-8 and MW-16 during the 1/28 gauging event was approximately 0.01 feet and 0.23 feet, respectively. Well MW-7 contained a sheen. During the 1/27 event, approximately 11.0 combined gallons of free product/water was removed from MW-7, MW-8 and MW-16 using a pump. During the 1/28 event, approximately 125.0 combined gallons of free product/water was removed from MW-7, MW-8, and MW-16 via a 2,200-gallon vacuum truck. - JAMReviewed EFR Letter (#58 & #59) dated 2/5/10 for period 1/29/2010 to 2/5/2010 submitted via email on 2/5/2010. During this period wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 2/3 and 2/5. The product thickness in MW-8 and MW-16 during the 2/3 gauging event was approximately 0.01 feet and 0.25 feet, respectively. The product thickness in MW-8 and MW-16 during the 2/5 gauging event was approximately 0.01 feet and 0.34 feet, respectively. Well MW-7 contained a sheen. During the 2/3 event, approximately 12.0 combined gallons of free product/water was removed from MW-7, MW-8 and MW-16 using a pump. During the 2/5 event, approximately 108.0 combined gallons of free product/water was removed from MW-7, MW-8, and MW-16 via a 2,200-gallon vacuum truck. - JAMReviewed EFR Letter (#60 & #61) dated 2/12/10 for period 2/6/2010 to 2/12/2010 submitted via email on 2/12/2010. During this period wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 2/9 and 2/12. The product thickness in MW-8 and MW-16 during the 2/9 gauging event was approximately 0.01 feet and 0.28 feet, respectively. The product thickness in MW-8 and MW-16 during the 2/12 gauging event was approximately 0.01 feet and 0.28 feet, respectively. Well MW-7 contained a sheen. During the 2/9 event, approximately 12.0 combined gallons of free product/water was removed from MW-7, MW-8 and MW-16 using a pump. During the 2/12 event, approximately 162.0 combined gallons of free product/water was removed from MW-7, MW-8, and MW-16 via a 2,200-gallon vacuum truck. - JAMReviewed EFR Letter (#62 & #63) dated 2/18/10 for period 2/13/2010 to 2/18/2010 submitted via email on 2/25/2010. During this period wells MW-7, MW-8, MW-9, and MW-15

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

through MW-19 were gauged for product on 2/16 and 2/18. The product thickness in MW-8 and MW-16 during the 2/16 gauging event was approximately 0.01 feet and 0.29 feet, respectively. The product thickness in MW-16 during the 2/18 gauging event was approximately 0.37 feet and MW-8 contained a sheen. Well MW-7 contained a sheen in both events. During the 2/16 event, approximately 12.0 combined gallons of free product/water was removed from MW-7, MW-8 and MW-16 using a pump. During the 2/18 event, approximately 122.0 combined gallons of free product/water was removed from MW-7, MW-8, and MW-16 via a 2,200-gallon vacuum truck. - JAMReviewed EFR Letter (#64 & #65) dated 2/25/10 for period 2/19/2010 to 2/25/2010 submitted via email on 2/25/2010. During this period wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 2/23 and 2/25. The product thickness in MW-16 during the 2/23 gauging event was approximately 0.29 feet and MW-8 contained a sheen. The product thickness in MW-8 and MW-16 during the 2/25 gauging event was approximately 0.01 feet and 0.22 feet, respectively. Well MW-7 contained a sheen in both events. During the 2/23 event, approximately 12.0 combined gallons of free product/water was removed from MW-7, MW-8 and MW-16 using a pump. During the 2/25 event, approximately 132.0 combined gallons of free product/water was removed from MW-7, MW-8, and MW-16 via a 2,200-gallon vacuum truck. -JAM5/17/10 Reviewed EFR Letter (#66 & #67) dated 3/5/10 for period 2/25/10 to 5/5/10 submitted via email on 3/8/10. Wells MW-7, MW-8, MW-9, and MW-15 through MW-19 were gauged for product on 3/1 and 3/5. Product thickness in MW-8 and MW-16 on 3/1 was approx 0.01 ft and 0.22 ft, respectively. Product thickness in MW-8 and MW-16 on 3/5 was approx 0.01 ft and 0.33 ft, respectively. Product was not detected in well MW-7 during both events. Approx 11.0 combined gals of free product/water were removed from MW-8 and MW-16 on 3/1 using a pump. Approx 109.0 gals were removed from MW-8 and MW-16 on 3/5 using a vacuum truck. - JAMReviewed EFR Letter (#68) dated 3/12/10 for period 3/6/10 to 3/12/10 submitted via email on 3/12/10. All accessable wells were gauged for product on 3/9. The proposed on- and off-site monitoring wells were installed on March 4th and 5th, 2010. The product thickness in MW-8 and MW-16 was approximately 0.01 ft and 0.27 ft, respectively. Approximately 14.0 combined gallons of free product/water were removed from MW-8 and MW-16 on 3/1 using a pump. The vacuum truck was not available this week because of a last minute emergency. No vac trucks were available and the VEFR will be performed the next week. - JAM5/8/10 Reviewed several weekly EFR Letters (#69 through #75). Starting on 3/20 thru 3/26 period, weekly EFR events were reduced to once/week. Free product was recovered from wells MW-8, MW-16 and MW-21 using a vacuum truck. Starting on 4/16 product recovery event (#74), free product has not been detected in well MW-21 and VEFR was not performed on this well.Reviewed EFR Letter (#76) dated 5/7/10 for period 4/23/10 to 5/7/10 submitted via email on 5/14/10. All accessable wells were gauged for product on 5/7. The product thickness in MW-8 and MW-16 was approximately 0.01 ft and 0.02 ft, respectively. Approximately 65.0 gallons of free product/water were removed from MW-8 and MW-16 on 5/7 using a vac truck. The free product recovery events will be reduced from once per week to once every two weeks. - JAM5/19/10 Reviewed Quarterly Sampling Rpt for period Jan-March 2010 by Hydro Tech dated 3/22/10 and submitted on 4/30/10. Rpt summarizes install'n of 2 off-site mon wells and reinstall'n of 3 on-site mon wells that were destroyed during construction. Soil samples were collected during install'n and

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

GW samples were collected from all wells in March 2010. Free product has been observed in 4 mon wells, both on- and off-site, which has been recovered using vacuum truck on weekly basis. Approx 54, 208, 754 & 15 gallons of free product/water were recovered during this monitoring period from wells MW-7, MW-8, MW-16 and MW-21, resp. Soil samples show several VOCs and SVOCs exceeding their RSCOs. Total VOCs in soil ranged from 17 ug/kg in SP-16 at 4-6 fbg to 66,510 ug/kg in SP-20 at 6-8 fbg. Total SVOCs ranged from ND in SP-16 to 247,260 ug/kg in SP-18. GW samples show several VOCs and SVOCs exceeding their stds. Total VOCs in GW ranged from 4 ug/L in MW-20 to 640 ug/L in MW-10A. Hydro Tech states that chlorinated compounds were detected above regulatory standards in soil samples from smear zone in southwest part of Site. Organic vapors and visual/olfactory evidence of contam were noted during screening of soil in southwestern area. No VOCs or SVOCs were detected in soil samples collected along Commerce Street. GW results from wells in both southwestern part of site and along Commerce St. show levels of petroleum and chlorinated compounds above GW stds.Hydro Tech recommends continuing weekly EFR events and quarterly GW sampling. Next qrtly sampling expected in June 2010. Rpt uploaded to eDocs. - JAM11/10/10: This spill case transferred from J. Maisonave to J. Kolleeny. On 11/8/10, received email from Timothy Lo of Hydro Tech: "My understanding is Joseph Maisonave is currently on a leave of absence. He was case manager for this spill. Hydro Tech has forwarded 3 quarterly monitoring rpts to him, but he has not responded back with any comments or recommendations. Hydro Tech would like to request written correspondence regarding future actions/requirements regarding current status of spill so that Hydro Tech can help expedite closure. Currently, our only form of remediation is bi-monthly EFR events and quarterly sampling rpts. However, product & dissolved compounds are still present. We do not want to pursue a different avenue of remediation without DEC guidance/approval/requirements." I sent email reply: "I will be taking over this spill project from Joseph, at least temporarily. I quickly looked over Hydro Tech's 3rd Quarter 2010 Monitoring Rpt, and noted that rpt's recommendations are to continue with current remedial approach of bi-monthly EFR events and quarterly GW sampling. If you do not feel this approach is appropriate/adequate, and will not lead to spill closure in timely manner, Hydro Tech should evaluate feasibility of various other remedial options and submit rpt summarizing this evaluation, with recommendation for revised remedial approach if appropriate. Feel free to call me to discuss, if you have any questions." - J. Kolleeny12/08/10: On 11/16/10, received email from Timothy Lo of Hydro Tech with attached Project Status Update letter dated 11/16/10 (in eDocs). Letter states that measurable product only remains in 3 off-site wells, with thicknesses up to 0.31 ft, which is greatly reduced since start of project, and that dissolved-phase GW contam is "low," with worst well having 1,411 ug/L total VOCs (on-site well). Based on these data, Hydro Tech requests spill closure. I sent letter (in eDocs) by email to Khandu Patel (RP), cc's to Timothy Lo and Rachel Ataman of Hydro Tech, stating spill cannot be closed while there is measurable product and significant dissolved-phase contam in wells (which 1,411 ug/L qualifies as). Stated that product recovery and GW monitoring must continue, and that addt'l GW remediation may be warranted. Advised that proposal to address remaining impacts be developed as supplement to RAP, to expedite moving spill case towards closure. - J. Kolleeny01/21/11: Reviewed 4th Quarter 2010 Sampling

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

Rpt by HydroTech, dated 1/7/11 (in eDocs). Rpt states that well gauging in December 2010 showed 0.01 ft of product in MW-8, 0.38 ft in MW-16, and a sheen in MW-21. GW sampling in Dec. 2010 showed 635 ug/L total VOCs in well MW-14A (down from 685 ug/L in Sept. 2010), 516 ug/L tVOCs in MW-10A (down from 644 ug/L in Sept. 2010), and 406 ug/L in MW-2A (down from 1,411 ug/L in Sept. 2010), 3 on-site wells clustered in southwest part of site. Rpt states that semi-monthly EFR and quarterly GW sampling should continue, with next GW event in March 2011. - J. Kolleeny04/30/12: Reviewed Quarterly Status Rpt for Oct.-Dec. 2011 by Hydro Tech, dated 2/10/12 (in eDocs). Sent email to Mark Robbins of Hydro Tech, cc's to Rachel Ataman of Hydro Tech and Khandu Patel (RP): "Hi Mark, I've looked over Quarterly Status Rpt for Oct-Dec 2011 for this site, prepared by Hydro Tech Envt'l, Corp., dated 2/10/12. I'd like to request following changes to this rpt and to future quarterly rpts: 1. Please rearrange GW data table (Table 1) into two separate tables, one table with old "STARS" list of fuel oil related compounds (attached), and separate table for "other compounds detected" (i.e., chlorinated compounds detected). Both tables should include lines for total VOCs and Total SVOCs. 2. Please add a table with current and past historical GW data for petroleum-related compounds for all wells. (If you have past data for chlorinated compounds, you could also add a table with historical data for other compounds detected.) Having historical data for each well available along with latest data makes it easier for me to see trends in contaminant levels at site. 3. Please include a discussion of possible sources of chlorinated compounds detected in GW. 4. Please include a section with recommendations for future work, even if recommendation is just for continued quarterly GW monitoring and continued EFR events to recover free product. However, considering that product levels in down-gradient wells seem to have decreased, it might be a good idea to install petroleum-absorbent socks in wells with product in between EFR events (if this is not already being done), so this could be an appropriate recommendation to include. (Of course, you don't need to receive DEC approval to implement recommendations like continued monitoring, EFR events and install'n of socks.) Please let me know if it's possible to make these changes to Feb. 2012 rpt and re-submit a revised version of rpt, and please implement these changes for future rpts going forward. Please feel free to call to discuss any of these requirements or if you have other questions or comments." - J. Kolleeny06/20/12: On 6/14/12, received revised Quarterly Status Rpt: Oct. - Dec. 2011 by Hydro Tech Envt'l, dated 6/5/12 (in eDocs). Rpt presents recent and historical well gauging and sampling results. Data indicate that measurable product persists in several off-site wells, and low levels of dissolved VOCs exceeding GW standards are present in several on-site wells. Based on data, Hydro Tech recommends continuing EFR events on impacted off-site wells, and quarterly GW sampling of on-site wells to monitor contaminant levels. I sent approval letter (in eDocs) to Khandu Patel (RP), cc's to Paul Matli & Rachel Ataman of Hydro Tech, stating that EFR events should continue on off-site wells until measurable product is not detected in any of wells for 3 consecutive months of gauging events. At that point, DEC requires that wells be sampled for dissolved contam prior to petitioning for spill closure. - J. Kolleeny 08/15/12: Reviewed Status Rpt - January-July 2012 by Hydro Tech Envt'l, dated 8/7/12. Rpt presents Monitoring & Bailing Rpt data sheets, showing depths to product and GW before and after performing EFR, from Jan. through July 2012 (9 events total). Data

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

continue to show product in one-to-three down-gradient off-site wells, but product thicknesses decreased significantly over course of rpt period, with only 0.01 ft of product detected in MW-7, MW-8 and MW-15 during last event on 7/11/12. I sent email to Mark Robbins of Hydro Tech: "Mark, I've reviewed Status Rpt for Jan. thru July 2012 pertaining to this spill site. Rpt presents data on depths to product and water measured in on- and off-site monitoring wells before and after performing enhanced fluid recovery, for nine EFR events. I'd like to ask that future status rpts include a site plan showing wells in question, and also including data on quantities of product/total fluids recovered (if feasible) plus copies of any waste manifests for disposal of recovered fluids. Also, please include a CD with a pdf file of rpt along with hard copies of future rpts. Please feel free to contact me if you have any questions." - JK01/22/13: I received an email from Paul Matli of Hydro Tech: "Jonathan - Attached, please find monthly EFR rpts prepared for this spill Site during October, November and December 2012. EFR activities will continue during January 2013. Moving forward and following our last Quarterly Status Rpt dated June 5, 2012, I appreciate if you can advise if this spill can be closed and whether you will have other requirements to close it." I sent email response: "Paul, I'm a little confused by your request. I think my June 20, 2012 letter (attached) responding to June 5, 2012 Quarterly Status Rpt was very clear in approving Hydro Tech's recommendations to continue EFR events and perform quarterly GW monitoring, and in stating that when no measurable LNAPL has been detected for 3 consecutive months, a final round of dissolved-phase GW sampling should be performed. To best of my knowledge, no quarterly GW sampling has been performed since December 2011 (more than a year ago). Also, EFR reports you attached show measurable free product in four wells in December 2012 (including 1.07 feet of product in MW-16), so conditions for spill closure have not been met.Can you please revise EFR rpts to enter product thicknesses in "P.T. (Before)" and "P.T. (After)" columns of Monitoring & Bailing Rpt sheets, and to include a site plan showing on- and off-site wells? Also, a round of GW samples should be collected as soon as possible, and another quarterly status rpt should be prepared and submitted. I would prefer if EFR rpts could be incorporated into quarterly status rpts (and if quarterly status rpts could be submitted every quarter), to cut down on number of rpts. If you believe it's appropriate to reduce frequency of sampling wells for dissolved-phase contamination (e.g., from quarterly to semi-annual), you should recommend that in next quarterly status rpt. Please let me know if you have any questions or wish to discuss these issues further." - J. Kolleeny01/25/13: On 1/24/13, received email reply from Paul Matli of Hydro Tech: "Jonathan - I apologize for any confusion. I just took over project tho I helped revise last QSR submitted to you. At this point, I will advise client of your requirements to pursue a GW investigation at property. In rpt we will incorporate EFR rpts and also consider your last recommendation below to pursue semi-annual status rpts." On 1/25/13, I sent email reply: "Paul, Just to be clear, I am requiring that quarterly GW sampling be performed at site, as proposed by Hydro Tech and approved by DEC. (That is not same as saying that I am requiring that your client pursue a GW investigation.) Also, I did not actually recommend semi-annual status rpts, I suggested that if Hydro Tech believes it is appropriate to reduce frequency of GW sampling, Hydro Tech should propose such a reduction, and as an example I listed going from

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

quarterly to semi-annual sampling. Other options could include going to annual GW sampling, or if results of next sampling event show no significant dissolved-phase GW contamination, Hydro Tech might choose to recommend suspending GW sampling until product recovery has been completed, at which point a full round of GW samples should be collected in support of spill closure. Again, these are not my recommendations; I'm asking Hydro Tech to evaluate situation at site and make an appropriate recommendation regarding GW sampling, on behalf of your client. Please let me know if you have any questions or wish to discuss this further." - JK05/14/13: Reviewed GW Invest Rpt by Hydro Tech, dated 4/5/13, received pdf by email on 4/26/13 (in eDocs) and received hard copy on 5/6/13. Rpt notes that 11 EFR events between October 2012 and Feb. 2013 have reduced product thicknesses in off-site wells to ~0.02 ft. Results of March 2013 GW sampling show moderately low levels of dissolved VOCs persist in several on-site wells. Rpt recommends installing absorbent socks in off-site wells with product, and sampling all monitoring wells for dissolved-phase contam on annual basis. I contacted Paul Matli of Hydro Tech on 5/13/13, asked if product levels have remained stable or increased since rpt was submitted. On 5/14/13, he sent April 2013 EFR rpt (in eDocs as brief), showing max thickness was 0.03 ft. I sent letter (in eDocs) to RP Khandu Patel, cc's to Paul Matli & Rachel Ataman of Hydro Tech, approving recommendations but stating that absorbent socks in wells with product should be examined quarterly, replaced as needed, and removed on semi-annual basis (at minimum) and wells allowed to come to equilibrium, at which point product thickness should be measured and if thicknesses persist at current levels or increase, more aggressive product recovery methods should be used to eliminate measurable product to extent feasible and move spill more expeditiously toward closure. Also commented that if gauging of wells currently impacted with product shows no measurable product in a well, well should be sampled for dissolved contam during annual sampling events. - JK09/27/13: Reviewed Status Rpt - June 2013 to August 2013, dated 9/16/13, by HydroTech Envt'l (in eDocs). Rpt received 9/18/13 via email from Paul Matli of HydroTech. Gauging of five wells known to have free product impacts was performed in June and August 2013, as required. In June, only well MW-16 had product, at 0.12 ft. In August, 0.01 ft of product was found in MW-7, MW-8, MW-15 and MW-16. No measurable product was observed in MW-21 during rpt period. Absorbent socks in wells were removed and replaced in Aug.; used socks were placed into 55-gal drum for off-site disposal. - J. Kolleeny01/14/14: Reviewed Status Rpt for Sept. to Nov. 2013, dated 12/01/13 (received by email from Paul Matli of HydroTech on 12/23/13), prepared by HydroTech Envt'l (in eDocs). Results of gauging of 5 off-site wells which have historically had free product showed no measurable product in Nov. 2013, "as evidenced by absence of staining on removed absorbent socks..." Used socks were put in 55-gal drum and new socks installed. I contacted Paul Matli, asked when wells were last sampled for dissolved contam, he said March 2013. I suggested that socks be removed from wells a week or two before they plan to conduct annual sampling to ensure product does not recharge into wells. He said that they plan to gauge wells again in Feb., so they will remove socks and not replace them in preparation for GW sampling in March 2014; although if product does show up in wells, they will re-install socks and try to do dissolved sampling in June 2014. I also stated that site plan in rpt should be revised to show current condtions (with completed hotel bldg, and on-

**VACANT LOT/FUTURE HOTEL (Continued)** **S109206934**

as well as off-site wells). - J. Kolleeny01/15/14: Received email from Paul Matli of HydroTech Envt'l as follow-up to our phone conversation: "Jonathan - as per yesterday's conversation, we will be removing absorbent pads from 5 down-gradient monitoring wells, which historically contained measurable levels of LNAPL on a quarterly schedule during middle of February. We will then wait 2 weeks and then sample all wells present at site during March for dissolved-phase contamination in order to provide supporting data to close spill at this site." I sent email reply: "Paul, That's great, thanks. As we also discussed, if it turns out that after removing absorbent pads and waiting 2 weeks, LNAPL returns to any of wells, absorbent pad(s) should be replaced in affected well(s), and you can try same procedure again next quarter. When it is confirmed that measurable LNAPL is not recharging into any of wells, then all wells should be sampled for dissolved-phase contamination in support of spill closure." - J. Kolleeny

Remarks: HOLES IN TANK AND CONTAMINATED SOIL

Material:

| | |
|---|---|
| Site ID: | 402330 |
| Operable Unit ID: | 1159096 |
| Operable Unit: | 01 |
| Material ID: | 2150207 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 402330 |
| Spill Tank Test: | 2486618 |
| Tank Number: | Not reported |
| Tank Size: | 5000 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified: | 8/6/2008 |
| Test Method: | Unknown |

---

**AT378** **UNDER ROADWAY** **NY Spills** **S110490345**
**South** **160 HAMILTON AVE NORTH/ COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.178 mi.**
**939 ft.** **Site 13 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1004881 |
| Facility Type: | ER |
| DER Facility ID: | 393160 |
| Site ID: | 438172 |
| DEC Region: | 2 |

**UNDER ROADWAY (Continued)** **S110490345**

| | |
|---|---|
| Spill Date: | 7/30/2010 |
| Spill Number/Closed Date: | 1004881 / 8/4/2011 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RMPIPER |
| Referred To: | Not reported |
| Reported to Dept: | 7/30/2010 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/30/2010 |
| Spill Record Last Update: | 8/4/2011 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | MOLLY OCCONNOR |
| Contact Phone: | (785) 550-8620 |
| DEC Memo: | 7/30/10 - Raphael Ketani. While drilling a soil boring today through pavement, contaminated soil and groundwater were discovered. According to John Purdy, the project manager from Gannett Fleming (212) 967-9833, the drilling crew was installing a geotechnical soil boring and taking split spoon samples when they noticed that the soil under the roadway had petroleum odors. They continued to drill down until they reached the water table, about 10 feet below grade. Once there, they also noticed petroleum odors. The drilling was being done for the loading on a retaining wall. The site is somewhat near the water and is on the west side of Brooklyn near the Brooklyn Battery Tunnel. The source is unknown.The project is for the Triborough Bridge and Tunnel Authority (TBTA). The contact at the TBTA is Earl Walcott (718) 797-6917, 160 Hamilton Avenue, Brklyn, 11231. The site is about a block away from this office. I sent a CSL.work completed withihn scope of work. Cont soil removed and disposed of. Based on work to date, location and unknown RP, this spill is closed. |
| Remarks: | contamination found while drilling in roadway/side walk/samples have been taken |

Material:

| | |
|---|---|
| Site ID: | 438172 |
| Operable Unit ID: | 1188837 |
| Operable Unit: | 01 |
| Material ID: | 2183768 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |

**UNDER ROADWAY (Continued)** **S110490345**

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AY379** **ENGINE COMPANY 224** **NY AST** **A100175164**
**NE** **274 HICKS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.178 mi.**
**942 ft.** **Site 1 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-600507
Program Type: PBS
UTM X: 584786.06172999996
UTM Y: 4505135.9025800005
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 22488
Affiliation Type: Emergency Contact
Company Name: NYC FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: EOC/NOTIFICATION DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/1/2011

Site Id: 22488
Affiliation Type: Facility Owner
Company Name: NYC FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: Not reported
Address1: 9 METROTECH
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201-3857
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/8/2013

**ENGINE COMPANY 224 (Continued)** **A100175164**

| | |
|---|---|
| Site Id: | 22488 |
| Affiliation Type: | Mail Contact |
| Company Name: | FDNY BUILDING MAINTENANCE DIVISION |
| Contact Type: | Not reported |
| Contact Name: | DIRECTOR OF BLDG. MAINT. |
| Address1: | 48-34 35H STREET |
| Address2: | Not reported |
| City: | LONG ISLAND CITY |
| State: | NY |
| Zip Code: | 11101 |
| Country Code: | 001 |
| Phone: | (718) 784-6510 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22488 |
| Affiliation Type: | On-Site Operator |
| Company Name: | ENGINE COMPANY 224 |
| Contact Type: | Not reported |
| Contact Name: | COMPANY OFFICER |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 965-8224 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 42869 |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other
G99 - Tank Secondary Containment - Other

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 11/01/1971 |

**ENGINE COMPANY 224 (Continued)** **A100175164**

| | |
|---|---|
| Capacity Gallons: | 550 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | Diesel |

| | |
|---|---|
| Tank Number: | 002 |
| Tank Id: | 42870 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 2000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | 02/01/2003 |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

---

**AY380** **ENGINE COMPANY 224** **NY HIST AST** **S107782647**
**NE** **274 HICKS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.178 mi.**
**942 ft.** **Site 2 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

HIST AST:

| | |
|---|---|
| PBS Number: | 2-600507 |
| SWIS Code: | 6101 |
| Operator: | COMPANY OFFICER |
| Facility Phone: | (718) 965-8224 |
| Facility Addr2: | 274 HICKS STREET |
| Facility Type: | OTHER |
| Emergency: | EOC/NOTIFICATION DESK |
| Emergency Tel: | (718) 999-2094 |
| Old PBSNO: | Not reported |

**ENGINE COMPANY 224 (Continued)** **S107782647**

| | |
|---|---|
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | FIRE DEPARTMENT |
| Owner Address: | 9 METROTECH |
| Owner City,St,Zip: | BROOKLYN, NY 11201-3857 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 999-2094 |
| Owner Type: | Local Government |
| Owner Subtype: | Not reported |
| Mailing Contact: | DIRECTOR |
| Mailing Name: | BUILDINGS MAINTENANCE DIVISION |
| Mailing Address: | FIRE DEPARTMENT |
| Mailing Address 2: | 48-34 35TH STREET |
| Mailing City,St,Zip: | LONG ISLAND CITY, NY 11101 |
| Mailing Telephone: | (718) 784-6510 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 11/23/2001 |
| Expiration: | 12/23/2006 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 2550 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 002 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 2000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | 0 |
| Tank External: | 0 |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | 0 |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | 6 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | No Missing Data |

**ENGINE COMPANY 224 (Continued)** **S107782647**

| | |
|---|---|
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**AY381** **MTA NYCT WILLOW PLACE FAN PLANT** **RCRA NonGen / NLR** **1001818200**
**NE** **58 JORALEMON ST** **FINDS** **NYR000077073**
**1/8-1/4** **BROOKLYN, NY** **NY MANIFEST**
**0.182 mi.**
**963 ft.** **Site 3 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**45 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | MTA NYCT WILLOW PLACE FAN PLANT |
| Facility address: | 58 JORALEMON ST<br>BROOKLYN, NY 11201 |
| EPA ID: | NYR000077073 |
| Mailing address: | COLUMBUS CIR 25TH FLOOR<br>NEW YORK, NY 10019 |
| Contact: | WILLIAM JEHLE |
| Contact address: | COLUMBUS CIR 25TH FLOOR<br>NEW YORK, NY 10019 |
| Contact country: | US |
| Contact telephone: | (212) 307-6010 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | MTA NEW YORK CITY TRANSIT |
| Owner/operator address: | 10 COLUMBUS CIR 25TH FLOOR<br>NEW YORK, NY 10019 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 307-6010 |
| Legal status: | Municipal |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | MTA NEW YORK CITY TRANSIT |
| Owner/operator address: | 10 COLUMBUS CIR 25TH FLOOR<br>NEW YORK, NY 10019 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 307-6010 |
| Legal status: | Municipal |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |

**MTA NYCT WILLOW PLACE FAN PLANT (Continued)** **1001818200**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT WILLOW PLACE FAN PLANT
Classification: Not a generator, verified

Date form received by agency: 09/27/1999
Facility name: MTA NYCT WILLOW PLACE FAN PLANT
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004556631

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000077073
Country: USA
Mailing Name: NYCTA
Mailing Contact: JOSEPH LEWIS
Mailing Address: 2 BROADWAY 3RD FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 646-252-3500

Document ID: NJA2932493
Manifest Status: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 01/12/2000
Trans1 Recv Date: 01/12/2000

**MTA NYCT WILLOW PLACE FAN PLANT (Continued)** **1001818200**

Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/17/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077073
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSDF ID: 50059
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00520
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYG1946079
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 04/20/2001
Trans1 Recv Date: 04/20/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/27/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077073
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: NYNJ11304
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00035
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG3206484
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 12/05/2001
Trans1 Recv Date: 12/05/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/13/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077073
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 0440375ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP

**MTA NYCT WILLOW PLACE FAN PLANT (Continued)** **1001818200**

| | |
|---|---|
| Quantity: | 00030 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 2001 |

| | |
|---|---|
| Document ID: | NYG3388158 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 06/12/2002 |
| Trans1 Recv Date: | 06/12/2002 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 06/18/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000077073 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | 68235AKNY |
| Waste Code: | B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB |
| Quantity: | 00040 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2002 |

---

**AT382** **MAN HOLE #17152** **NY Spills** **S103829238**
**South** **HAMILTON AV & COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.186 mi.**
**982 ft.** **Site 14 of 14 in cluster AT**

**Relative:**
**Higher**

**Actual:**
**18 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9815102 |
| Facility Type: | ER |
| DER Facility ID: | 89450 |
| Site ID: | 100819 |
| DEC Region: | 2 |
| Spill Date: | 3/21/1999 |
| Spill Number/Closed Date: | 9815102 / 4/2/1999 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 3/21/1999 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |

**MAN HOLE #17152 (Continued)** **S103829238**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/21/1999 |
| Spill Record Last Update: | 6/19/2000 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | WILLIAM MURPHY |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"CON ED E2MIS NOTESUnknown undiaperable sheen found in MH 17152.No sewers or waterways affected, took sample and place tag #12497There are feeders & a joint regulator in structure.3-21-99 2035 hrs. Lab Seq# 99-02874 3ppm3-22-99 1650 hrs.Cleanup complete.Incident closed. |
| Remarks: | a sheen on 2 glas of water in manhole cleanup pending test resultsref #123752 |

Material:

| | |
|---|---|
| Site ID: | 100819 |
| Operable Unit ID: | 1076128 |
| Operable Unit: | 01 |
| Material ID: | 308224 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AZ383** **EDR US Hist Cleaners** **1015066312**
**SE** **484 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.187 mi.**
**986 ft.** **Site 1 of 5 in cluster AZ**

**Relative:**
**Higher**

**Actual:**
**32 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | THRIVING CLEANERS |
| Year: | 1999 |
| Address: | 484 HENRY ST |
| Name: | THRIVING CLEANERS |
| Year: | 2000 |
| Address: | 484 HENRY ST |
| Name: | SMART CLEANER |
| Year: | 2006 |

**(Continued)** **1015066312**

Address: 484 HENRY ST

---

**384**
**SE**
**1/8-1/4**
**0.187 mi.**
**988 ft.**

**IN MUD MANHOLE #20843**
**446 HENRY ST**
**BROOKLYN, NY**

**NY Spills** **S103576024**
**N/A**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9812208 |
| Facility Type: | ER |
| DER Facility ID: | 103093 |
| Site ID: | 118636 |
| DEC Region: | 2 |
| Spill Date: | 1/3/1999 |
| Spill Number/Closed Date: | 9812208 / 10/17/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 1/3/1999 |
| CID: | 255 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/3/1999 |
| Spill Record Last Update: | 10/17/2002 |
| Spiller Name: | TONY CONSTANTINE |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | TONY CONSTANTINE |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"e2mis no. 122-202:1-3-99-00:05HRS-B/PLUMMER #16942, FIELD OPER., F.O.D. AT SITE LOCATING FAULT ON FDR 1B66-FD APPROX 1 PT OF UNKNOWN OIL ON APPROX 2-3" OF MUD IN MH 20843-F/O 446 HENRY ST. FOUND BLOWN 3W-1/W JOINT, PAPER CABLE-SPILL IS CONTAINED-NO SEWERS OR WATERWAYS AFFECTED-NO JOINT REGULATOR IN M/H-NO SUMP OR PUMPS IN M/H-TOOK SAMPLE WITH 4-6 HOUR TURNAROUND-PLACE ENV TAG 06870.1000HRS--RESULTS RETURNED FROM CHEM LAB <1PPM LAB SEQ#-99-00004.UPDATE 03-JAN-1999 1400HRS CLEAN UP COMPLETE WITH SLIX TAG #06870 REMOVED.BLOWN JOINT REPLACED, INCIDENT IS CLOSED. |
| Remarks: | 1 pint unknown oil in 3 inches of mud |

Material:

| | |
|---|---|
| Site ID: | 118636 |
| Operable Unit ID: | 1069469 |
| Operable Unit: | 01 |

**IN MUD MANHOLE #20843 (Continued)** **S103576024**

| | |
|---|---|
| Material ID: | 312491 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BA385** **EDR US Hist Cleaners** **1015058045**
**ESE** **416 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.187 mi.**
**988 ft.** **Site 1 of 7 in cluster BA**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | BONAFIDE LAUNDROMAT |
| Year: | 2001 |
| Address: | 416 HENRY ST |
| Name: | BONAFIDE LAUNDROMAT |
| Year: | 2002 |
| Address: | 416 HENRY ST |

---

**BA386** **MANHOLE 20836** **NY Spills** **S103576023**
**ESE** **HENRY ST & KANE ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.188 mi.**
**993 ft.** **Site 2 of 7 in cluster BA**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9812207 |
| Facility Type: | ER |
| DER Facility ID: | 183463 |
| Site ID: | 221820 |
| DEC Region: | 2 |
| Spill Date: | 1/2/1998 |
| Spill Number/Closed Date: | 9812207 / 10/17/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 1/3/1999 |
| CID: | 195 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |

**MANHOLE 20836 (Continued)** **S103576023**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/3/1999 |
| Spill Record Last Update: | 10/17/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller Company: | 001 |
| Contact Name: | RICHARD ROACH |
| Contact Phone: | (212) 580-6764 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"DEC responder notes:1/9/99: spoke with Dave Perez (ERT) - manhole has 3-c paper-impregnated lead cable. Samples collected - results <1 ppm PCB. No sewers or waterways affected. Clean up completed 1230 hrs on 1/3/99. No sump. (JHO)e2mis no. 122-201:01-02-99 23:55HRS- B. PLUMMER-#16942- FIELD OPERATOR-F.O.D-AT SITE LOCATING FAULT ON 1B66 REPORTS FOUND APPROX 3 PINTS OFUNKNOWN OIL IN MH 20836-S/W/C HENRY ST & KANE ST. 3C PAPER CABLE IN M/H-SPILL IS CONTAINED AND NO SEWERS OR WATERWAYSAFFECTED-NO SUMP OR PUMPS IN M/H. NO JOINT REGULATOR IN M/HTOOKSAMPLE WITH A 4-6 HR. TURNAROUND AND PLACED ENV TAG# 06912.1000HRS-SAMPLE RETURNED FROM CHEM LAB <1PPM.UPDATE 03-JAN-1999 1230HRS CLEAN UP COMPLETE, USING SLIX. TAG REMOVED.#06912.NO LEAKING COMPANY EQUIPMENT, INCIDENT IS CLOSED. |
| Remarks: | 3 PINTS OF UNKNOWN OIL IN MANHOLE AT INTERSECTION. CON ED NUMBER 122201. MATERIAL WILL BE TESTED. |

Material:

| | |
|---|---|
| Site ID: | 221820 |
| Operable Unit ID: | 1072809 |
| Operable Unit: | 01 |
| Material ID: | 312490 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BA387** **NYCDEP** **NY MANIFEST** **1009235716**
**ESE** **BALTIC ST & HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN HEIGHTS, NY**
**0.188 mi.**
**995 ft.** **Site 3 of 7 in cluster BA**

**Relative:**
**Higher**

**Actual:**
**24 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP003661956 |
| Country: | USA |
| Mailing Name: | NYCDEP |
| Mailing Contact: | CHRIS HAAS |

**NYCDEP (Continued)** **1009235716**

| | |
|---|---|
| Mailing Address: | 96-05 HORACE HARDING EXPWY |
| Mailing Address 2: | Not reported |
| Mailing City: | CORONA |
| Mailing State: | NY |
| Mailing Zip: | 11368 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-595-6291 |

| | |
|---|---|
| Document ID: | NYG4289373 |
| Manifest Status: | Not reported |
| Trans1 State ID: | 68699AV |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/27/2004 |
| Trans1 Recv Date: | 05/27/2004 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/27/2004 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP003661956 |
| Trans1 EPA ID: | NYD049178296 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049178 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2004 |

---

**AW388** **UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C** **RCRA-SQG** **1000231926**
**ENE** **340 HENRY ST** **FINDS** **NYD982279614**
**1/8-1/4** **BROOKLYN, NY 11201** **NY MANIFEST**
**0.189 mi.** **NY Spills**
**996 ft.** **Site 3 of 3 in cluster AW**

**Relative:**
**Higher**

**Actual:**
**39 ft.**

RCRA-SQG:

| | |
|---|---|
| Date form received by agency: | 06/29/2011 |
| Facility name: | UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL CENTER AT LICH |
| Facility address: | 340 HENRY ST<br>BROOKLYN, NY 11201 |
| EPA ID: | NYD982279614 |
| Mailing address: | HICKS ST<br>BROOKLYN, NY 11201 |
| Contact: | NOEL AROCHO |
| Contact address: | HICKS ST<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | (718) 780-1725 |
| Contact email: | NOEL.AROCHO@DOWNSTATE.EDU |
| EPA Region: | 02 |
| Classification: | Small Small Quantity Generator |
| Description: | Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | DOWNSTATE AT LICH HOLDILNG COMPANY INC |
| Owner/operator address: | CLARKSON AVE - BOX 1281<br>BROOKLYN, NY 11203 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 270-1234 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | 05/29/2011 |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | UNIVERSITY HOSPITAL OF BROOKLYN |
| Owner/operator address: | Not reported<br>Not reported |
| Owner/operator country: | US |
| Owner/operator telephone: | Not reported |
| Legal status: | State |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | 05/29/2011 |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Historical Generators:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL CENTER AT LICH |
| Site name: | LONG ISLAND COLLEGE HOSPITAL |
| Classification: | Small Quantity Generator |

| | |
|---|---|
| Date form received by agency: | 01/01/2006 |
| Facility name: | UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL CENTER AT LICH |
| Site name: | LONG ISLAND COLLEGE HOSPITAL |
| Classification: | Conditionally Exempt Small Quantity Generator |

Date form received by agency: 07/08/1999

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued) 1000231926**

Facility name: UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL CENTER AT LICH
Site name: LONG ISLAND COLLEGE HOSPITAL
Classification: Not a generator, verified

Date form received by agency: 11/20/1987
Facility name: UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL CENTER AT LICH
Site name: LONG ISLAND COLLEGE HOSPITAL
Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: U010
Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

Waste code: U035
Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Waste code: U059
Waste name: DAUNOMYCIN

Waste code: U122
Waste name: FORMALDEHYDE

Waste code: U150
Waste name: MELPHALAN

Waste code: U188
Waste name: PHENOL

Waste code: U206
Waste name: GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-, D-

Waste code: U237
Waste name: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]-

Violation Status: No violations found

FINDS:

Registry ID: 110008026377

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD982279614
Country: USA
Mailing Name: LONG ISLAND COLLLEGE HOSPITAL
Mailing Contact: WILLIAM ALLISON
Mailing Address: 340 HENRY STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-780-4611

Document ID: NYG5054607
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/25/2005
Trans1 Recv Date: 04/25/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/28/2005
Part A Recv Date: Not reported

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NY52559JT |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00200 |
| Units: | P - Pounds |
| Number of Containers: | 005 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00040 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | Not reported |
| Specific Gravity: | 01.00 |
| Waste Code: | Not reported |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYG5395446 |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD985286988 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/21/2005 |
| Trans1 Recv Date: | 12/21/2005 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/22/2005 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | 62758JSAY |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00300 |
| Units: | P - Pounds |
| Number of Containers: | 005 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYG5397012 |
| Manifest Status: | Not reported |
| Trans1 State ID: | MAD985286988 |
| Trans2 State ID: | Not reported |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Generator Ship Date: | 08/22/2005 |
| Trans1 Recv Date: | 08/22/2005 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 08/24/2005 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NY62758JS |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00240 |
| Units: | P - Pounds |
| Number of Containers: | 006 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00040 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | Not reported |
| Specific Gravity: | 01.00 |
| Waste Code: | Not reported |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYA6253668 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 871125 |
| Trans1 Recv Date: | 871125 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 871125 |
| Part A Recv Date: | 880121 |
| Part B Recv Date: | 871209 |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD049178296 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049178296 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 00040 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 87 |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Document ID: | NYB7649748 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | PD9938 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 960403 |
| Trans1 Recv Date: | 960403 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 960403 |
| Part A Recv Date: | 960412 |
| Part B Recv Date: | 960412 |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD082785429 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD082785429 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00385 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 007 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 96 |

| | |
|---|---|
| Document ID: | NYG1419174 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/28/1998 |
| Trans1 Recv Date: | 10/28/1998 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 11/03/1998 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | 68235AKNY |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00025 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 005 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 98 |

| | |
|---|---|
| Document ID: | NYG1419327 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 09/24/1998 |
| Trans1 Recv Date: | 09/24/1998 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 09/29/1998 |
| Part A Recv Date: | Not reported |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | P01010NY |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00210 |
| Units: | P - Pounds |
| Number of Containers: | 003 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00018 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 98 |

| | |
|---|---|
| Document ID: | NYG1419336 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/02/1998 |
| Trans1 Recv Date: | 12/02/1998 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/04/1998 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PD1010NY |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00015 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00045 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 002 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | U121 - TRICHLOROMONOFLUOROMETHANE |
| Quantity: | 00030 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 01.00 |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Year: 98

Document ID: NYG1056285
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 10/28/1998
Trans1 Recv Date: 10/28/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/03/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 68235AKNY
Waste Code: P105 - SODIUM AZIDE
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00003
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYG1056294
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 10/28/1998
Trans1 Recv Date: 10/28/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/03/1998
Part A Recv Date: Not reported

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 68235AKNY
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00003
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NYG1416285
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 08/07/1998
Trans1 Recv Date: 08/07/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/10/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00245
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYG1710216
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 12/17/1999
Trans1 Recv Date: 12/17/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NY68235AK
Waste Code: U188 - PHENOL
Quantity: 00085
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00006
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U007 - ACRYLAMIDE
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00001
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99

Document ID: NYG1710225
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 12/17/1999
Trans1 Recv Date: 12/17/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NY68235AK
Waste Code: U002 - ACETONE
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00060

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: U122 - FORMALDEHYDE
Quantity: 00090
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99

Document ID: NYG1709118
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 11/22/1999
Trans1 Recv Date: 11/22/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/23/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00085
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00007
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: U188 - PHENOL
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Waste Code: | U007 - ACRYLAMIDE |
| Quantity: | 00001 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 99 |

| | |
|---|---|
| Document ID: | NYG1709127 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/17/1999 |
| Trans1 Recv Date: | 12/17/1999 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/22/1999 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NY68235AK |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00002 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D009 - MERCURY 0.2 MG/L TCLP |
| Quantity: | 00001 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 01.00 |
| Waste Code: | D009 - MERCURY 0.2 MG/L TCLP |
| Quantity: | 00001 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 01.00 |
| Year: | 99 |

| | |
|---|---|
| Document ID: | NYG2261376 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 03/03/2000 |
| Trans1 Recv Date: | 03/03/2000 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/07/2000 |
| Part A Recv Date: | Not reported |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 68235AK
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00025
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYG2611728
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 09/28/2000
Trans1 Recv Date: 09/28/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/29/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 68235AK
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NYG1814733
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 11/16/2000
Trans1 Recv Date: 11/16/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/21/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982279614

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYPD1011 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00105 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 006 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00080 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00050 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00030 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2000 |

| | |
|---|---|
| Document ID: | NYG2262222 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 03/23/2000 |
| Trans1 Recv Date: | 03/23/2000 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/24/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYPD1010 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00040 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 008 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2000 |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued)** **1000231926**

| | |
|---|---|
| Document ID: | NYG2570265 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 06/19/2000 |
| Trans1 Recv Date: | 06/19/2000 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 06/20/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982279614 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PD1011NY |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00030 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 006 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2000 |

Click this hyperlink while viewing on your computer to access
349 additional NY_MANIFEST: record(s) in the EDR Site Report.

SPILLS:

| | |
|---|---|
| Facility ID: | 0105976 |
| Facility Type: | ER |
| DER Facility ID: | 133793 |
| Site ID: | 158293 |
| DEC Region: | 2 |
| Spill Date: | 9/4/2001 |
| Spill Number/Closed Date: | 0105976 / 9/6/2001 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 9/4/2001 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/4/2001 |
| Spill Record Last Update: | 5/15/2002 |
| Spiller Name: | MS. IARA |
| Spiller Company: | L.I. COLLEGE HOSPITAL |
| Spiller Address: | 340 HENRY ST |
| Spiller City,St,Zip: | BROOKLYN, NY |

**UNIVERSITY HOSPITAL OF BROOKLYN DBA SUNY DOWNSTATE MEDICAL C (Continued) 1000231926**

Spiller Company: 001
Contact Name: MS. IARA
Contact Phone: (718) 780-1935
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"All cleaned up by the spiller.
Remarks: UNK INFORMATION - FORMALENT IS THE CHEMICAL - JACOB KRIMGOLD ADVISED

Material:
Site ID: 158293
Operable Unit ID: 844420
Operable Unit: 01
Material ID: 530862
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**BA389 PUBLIC SCHOOL 29 - BROOKLYN NY AST U003397275**
**ESE 425 HENRY STREET N/A**
**1/8-1/4 BROOKLYN, NY 11201**
**0.189 mi.**
**999 ft. Site 4 of 7 in cluster BA**

**Relative: Higher**

**Actual: 25 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603587
Program Type: PBS
UTM X: 584687.16246999998
UTM Y: 4504461.33727
Expiration Date: 2018/07/30
Site Type: School

Affiliation Records:
Site Id: 25501
Affiliation Type: On-Site Operator
Company Name: PUBLIC SCHOOL 29 - BROOKLYN
Contact Type: Not reported
Contact Name: PLANT OPERATIONS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 349-5400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

**PUBLIC SCHOOL 29 - BROOKLYN (Continued)** **U003397275**

Date Last Modified: 3/4/2004

Site Id: 25501
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: MUNENDRA SHARMA
Address1: 44-36 VERNON BOULEVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/30/2013

Site Id: 25501
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY DEPT OF EDUCATION
Contact Type: Not reported
Contact Name: SCHOOL SAFETY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 979-3300
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 7/8/2008

Site Id: 25501
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: MUNENDRA SHARMA
Address1: FIELD OPERATIONS-FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: MSHARMA@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/16/2013

Tank Info:

Tank Number: 001
Tank Id: 54882

**PUBLIC SCHOOL 29 - BROOKLYN (Continued)** **U003397275**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/1997
Capacity Gallons: 8000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 07/30/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

---

**BA390** **PS 29** **FINDS** **1007800353**
**ESE** **425 HENRY STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.189 mi.**
**999 ft.** **Site 5 of 7 in cluster BA**

**Relative: Higher**

**Actual: 25 ft.**

FINDS:

Registry ID: 110019628722

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BA391** **NYC BD OF ED - PUBLIC SCHOOL 29 K** **RCRA-SQG** **1000550765**
**ESE** **425 HENRY ST** **FINDS** **NYD986882447**
**1/8-1/4** **BROOKLYN, NY 11201** **NY MANIFEST**
**0.189 mi.**
**999 ft.** **Site 6 of 7 in cluster BA**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

RCRA-SQG:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | NYC BD OF ED - PUBLIC SCHOOL 29 K |
| Facility address: | 425 HENRY ST<br>BROOKLYN, NY 11201 |
| EPA ID: | NYD986882447 |
| Mailing address: | HENRY ST<br>BROOKLYN, NY 11201 |
| Contact: | SEAN CLYNE |
| Contact address: | HENRY ST<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | (718) 472-8504 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Small Small Quantity Generator |
| Description: | Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | NYC BD OF ED |
| Owner/operator address: | 110 LIVINGSTON ST<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 935-5010 |
| Legal status: | Municipal |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | 08/22/2000 |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | NYC BD OF ED |
| Owner/operator address: | 110 LIVINGSTON ST<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 935-5010 |
| Legal status: | Municipal |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | 08/22/2000 |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | NYC SCA |
| Owner/operator address: | 30-30 THOMSON AVE<br>LONG ISLAND CITY, NY 11101 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 472-8511 |
| Legal status: | Municipal |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Classification: Small Quantity Generator

Date form received by agency: 08/23/2000
Facility name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Classification: Small Quantity Generator

Date form received by agency: 07/08/1999
Facility name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110004439000

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include;

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

Incident Tracking, Compliance Assistance, and Compliance Monitoring.

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD986882447 |
| Country: | USA |
| Mailing Name: | P S 29 K |
| Mailing Contact: | MICHAEL MOSKOWITZ |
| Mailing Address: | 425 HENRY ST |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | 6010 |
| Mailing Country: | USA |
| Mailing Phone: | 212-727-7676 |

| | |
|---|---|
| Document ID: | NYG5222196 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD049178296 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/03/2005 |
| Trans1 Recv Date: | 05/03/2005 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/03/2005 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | 68699ANNY |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049178296 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00240 |
| Units: | P - Pounds |
| Number of Containers: | 004 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYB6853968 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NYP85193 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 950915 |
| Trans1 Recv Date: | 950915 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 950915 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 950929 |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD077444263 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

| | |
|---|---|
| Quantity: | 00500 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 95 |

| | |
|---|---|
| Document ID: | NYB9515007 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NY0000291823 |
| Trans2 State ID: | PAD146714878 |
| Generator Ship Date: | 05/10/2001 |
| Trans1 Recv Date: | 05/10/2001 |
| Trans2 Recv Date: | 05/10/2001 |
| TSD Site Recv Date: | 05/11/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | NYD049836679 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | 1A375 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 01000 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 2001 |

| | |
|---|---|
| Document ID: | NYG3162618 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD077444263 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/17/2001 |
| Trans1 Recv Date: | 10/17/2001 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 10/18/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | NYD077444263 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PD1011NY |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00120 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 008 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Waste Code: | D001 - NON-LISTED IGNITABLE WASTES |
| Quantity: | 00030 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG5222196
Manifest Status: Not reported
Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 05/03/2005
Trans1 Recv Date: 05/03/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/03/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986882447
Trans1 EPA ID: 68699ANNY
Trans2 EPA ID: Not reported
TSDF ID: NYD049178296
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00240
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD986938645
Trans2 State ID: PAD146714878
Generator Ship Date: 2012-07-23
Trans1 Recv Date: 2012-08-23
Trans2 Recv Date: 2012-08-31
TSD Site Recv Date: 2012-09-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986882447
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 001593930GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

| | |
|---|---|
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H132 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD986938645 |
| Trans2 State ID: | PAD146714878 |
| Generator Ship Date: | 2012-07-23 |
| Trans1 Recv Date: | 2012-08-23 |
| Trans2 Recv Date: | 2012-08-31 |
| TSD Site Recv Date: | 2012-09-04 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | Not reported |
| Quantity: | 50.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 001593930GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H132 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD986938645 |
| Trans2 State ID: | PAD146714878 |
| Generator Ship Date: | 2012-07-23 |
| Trans1 Recv Date: | 2012-08-23 |
| Trans2 Recv Date: | 2012-08-31 |
| TSD Site Recv Date: | 2012-09-04 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

| | |
|---|---|
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | Not reported |
| Quantity: | 50.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 001593930GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H132 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD986938645 |
| Trans2 State ID: | PAD146714878 |
| Generator Ship Date: | 2012-07-23 |
| Trans1 Recv Date: | 2012-08-23 |
| Trans2 Recv Date: | 2012-08-31 |
| TSD Site Recv Date: | 2012-09-04 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986882447 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | Not reported |
| Quantity: | 50.0 |
| Units: | P - Pounds |
| Number of Containers: | 1.0 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1.0 |
| Year: | 2012 |
| Manifest Tracking Num: | 001593930GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |

**NYC BD OF ED - PUBLIC SCHOOL 29 K (Continued)** **1000550765**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H132

---

**BA392**
**ESE**
**1/8-1/4**
**0.189 mi.**
**999 ft.**

**NYC BD OF ED - PUBLIC SCHOOL 29 K** **ICIS 1011565091**
**425 HENRY ST BROOKLYN NY 11201** **N/A**
**BROOKLYN, NY 11201**

**Site 7 of 7 in cluster BA**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

ICIS:

Enforcement Action ID: 02-1988-0588
FRS ID: 110004439000
Program ID: RCRAINFO NYD986882447
Action Name: NYC BOARD OF EDUCATION
Facility Name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Facility Address: 425 HENRY ST BROOKLYN NY 11201
BROOKLYN, New York 11201
Enforcement Action Type: Civil Judicial Action
Facility County: Kings
EPA Region #: 2

Enforcement Action ID: 02-1988-0588
FRS ID: 110004439000
Program ID: FRS 110004439000
Action Name: NYC BOARD OF EDUCATION
Facility Name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Facility Address: 425 HENRY ST BROOKLYN NY 11201
BROOKLYN, New York 11201
Enforcement Action Type: Civil Judicial Action
Facility County: Kings
EPA Region #: 2

Program ID: FRS 110004439000
Facility Name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Address: 425 HENRY ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 8211
Latitude: 40.686923
Longitude: -73.998054

Program ID: RCRAINFO NYD986882447
Facility Name: NYC BD OF ED - PUBLIC SCHOOL 29 K
Address: 425 HENRY ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 8211
Latitude: 40.686923
Longitude: -73.998054

**BB393** **MAN HOLE # 56082** **NY Spills** **S103575530**
**East** **HENRY ST/CONGRESS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.189 mi.**
**999 ft.** **Site 1 of 8 in cluster BB**

**Relative:**
**Higher**

**Actual:**
**31 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9811672 |
| Facility Type: | ER |
| DER Facility ID: | 254851 |
| Site ID: | 316122 |
| DEC Region: | 2 |
| Spill Date: | 12/16/1998 |
| Spill Number/Closed Date: | 9811672 / 5/7/2001 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 12/16/1998 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/16/1998 |
| Spill Record Last Update: | 6/18/2001 |
| Spiller Name: | FRANK MASSERIA |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | MANHATTAN, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"DEC INSPECTOR'S NOTES5gals. of unknown material in MH in sump. MH connected to sewers samples taken; sewer capped off from previous incident;treated as 50-499. DEP inspected sewer and left.12-16-98 16:00 ERT WallaceReport of 5gals. of oil in MH 2 pieces of equipment in MH leaking joint regulator cable, sampled joint regulator, going to sample oil. Verified oil in elbow of sewer connection. Looked at ... sewer with DEP Keith Williams, no oil flow in sewers, asked for results of samplingCleanup started as 50-499ppm PCB12-18-98 Con Ed ERT Perez (15:15hrs),1ppm PCBsSays oil in 1degree cables is usually PCBs but 2 degree cables non PCBCON ED E2MIS REPORT 12-16-98Found 5gals. of unknown oil in MH56082 in the sump. Sample taken and tag was hung(#12065)It is not known if there is a sewer connection.Cleanup will begin immediately as 50-499ppmUpdate 1352hrs.On engineering report it states this MH is connected to sewer and on previous incident #101785 rport says that the sewer was capped off.1527hrs.Oil is leaking from 3c joint also from joint regulator.1608hrs.Small amount of oil leaked into sewer pipes. Sample was taken from oil regulator tank we still need a sample from |

**MAN HOLE # 56082 (Continued)** **S103575530**

cable.2030hrs.MH double washed and second sample taken from additional leaking feeder cable inside of duct.12-17-98 0200hrs.Sample results from cable <1.00ppm(Seq#98-14030)lab Seq#98-14068 <1.00ppm9-14-00 UpdateStructure cleaned by double washing with slix. Liquid waste removed by tanker. Solid waste removed by vactor. There is oil dripping from a duct that contains a cut and capped 3c cable. Tag remains pending removal of 3c cable in duct and rewashing of structure with steamer.1-13-01 UpdateRemoved 12' arcproofing.2-12-01 Cleanup completed sump found cemented and stop tag removed.2-15-01 0925hrs.Cleanup completed by double washing structure with slix. Liquids were removed by tanker and solids by vactor. No leaking company equipment, incident closed.

Remarks: nrc #467803 con ed #121990 5 gals of unk if material has entered sewer caller is checking now sample has been taking clean up pending results

Material:

| | |
|---|---|
| Site ID: | 316122 |
| Operable Unit ID: | 1068949 |
| Operable Unit: | 01 |
| Material ID: | 311959 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BB394** **218163; HENRY ST AND CONGRESS ST** **NY Spills** **S110307349**
**East** **HENRY ST AND CONGRESS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.189 mi.**
**999 ft.** **Site 2 of 8 in cluster BB**

**Relative:**
**Higher**

**Actual:**
**31 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0914413 |
| Facility Type: | ER |
| DER Facility ID: | 388198 |
| Site ID: | 433268 |
| DEC Region: | 2 |
| Spill Date: | 8/24/2009 |
| Spill Number/Closed Date: | 0914413 / 10/22/2009 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | DMPOKRZY |
| Referred To: | Not reported |
| Reported to Dept: | 12/31/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |

**218163; HENRY ST AND CONGRESS ST (Continued)** **S110307349**

| | |
|---|---|
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/16/2010 |
| Spill Record Last Update: | 4/16/2010 |
| Spiller Name: | ERT DESK |
| Spiller Company: | CON EDISON |
| Spiller Address: | 5030 BROADWAY |
| Spiller City,St,Zip: | New York, NY |
| Spiller Company: | 001 |
| Contact Name: | ERT DESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | Not reported |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 433268 |
| Operable Unit ID: | 1184179 |
| Operable Unit: | 01 |
| Material ID: | 2178382 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 4 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BB395** **ERNS 98467803**
**East** **HENRY ST AND CONGRESS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.189 mi.**
**999 ft.** **Site 3 of 8 in cluster BB**

**Relative:**
**Higher**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

**Actual:**
**31 ft.**

**BC396** **294 HENRY ST INC** **NY AST** **U003383930**
**ENE** **316 HENRY ST** **NY HIST AST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.189 mi.**
**999 ft.** **Site 1 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**46 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-069809 |
| Program Type: | PBS |
| UTM X: | 584827.00569000002 |
| UTM Y: | 4504857.2886199998 |
| Expiration Date: | 2017/01/14 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 1509 |
| Affiliation Type: | Facility Owner |
| Company Name: | HERNINIA SULLIVAN PRES |
| Contact Type: | PRESIDENT |
| Contact Name: | HERNINIA SULLIVAN |
| Address1: | 294 HENRY STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 855-9168 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | KAKYER |
| Date Last Modified: | 11/7/2006 |

| | |
|---|---|
| Site Id: | 1509 |
| Affiliation Type: | Mail Contact |
| Company Name: | 294 HENRY ST INC |
| Contact Type: | Not reported |
| Contact Name: | HERNINIA SULLIVAN-PRES. |
| Address1: | 294 HENRY STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 855-9168 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 1509 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 294 HENRY ST INC |
| Contact Type: | Not reported |
| Contact Name: | ECONOMY FUEL |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |

**294 HENRY ST INC (Continued)** **U003383930**

| | |
|---|---|
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-9168 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 1509 |
| Affiliation Type: | Emergency Contact |
| Company Name: | HERNINIA SULLIVAN PRES |
| Contact Type: | Not reported |
| Contact Name: | ECONOMY FUEL |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 342-7141 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 292 |
| Tank Id: | 2583 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

E99 - Piping Secondary Containment - Other
G03 - Tank Secondary Containment - Vault (w/o access)
H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/31/1930 |
| Capacity Gallons: | 1500 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |

**294 HENRY ST INC (Continued)** **U003383930**

| | |
|---|---|
| Register: | True |
| Modified By: | KAKYER |
| Last Modified: | 11/07/2006 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-069809 |
| SWIS Code: | 6101 |
| Operator: | ECONOMY FUEL |
| Facility Phone: | (718) 855-9168 |
| Facility Addr2: | 316 HENRY STREET |
| Facility Type: | Not reported |
| Emergency: | ECONOMY FUEL |
| Emergency Tel: | (718) 342-7141 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | HERNINIA SULLIVAN PRES |
| Owner Address: | 294 HENRY STREET |
| Owner City,St,Zip: | BROOKLYN, NY 11201 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 855-9168 |
| Owner Type: | Not reported |
| Owner Subtype: | Not reported |
| Mailing Contact: | HERNINIA SULLIVAN-PRES. |
| Mailing Name: | 294 HENRY ST INC |
| Mailing Address: | 294 HENRY STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN,, NY 11201 |
| Mailing Telephone: | (718) 855-9168 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 11/05/2001 |
| Expiration: | 01/14/2007 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 1500 |
| FAMT: | True |
| Facility Screen: | Minor Data Missing |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank ID: | 292 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | 12/01/1961 |
| Capacity (Gal): | 1500 |

**294 HENRY ST INC (Continued)** **U003383930**

| | |
|---|---|
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | Diking |
| Leak Detection: | 4 |
| Overfill Protection: | 4 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**BB397** **COBBLE HILL NURSING HOME INC** **NY AST** **U003384667**
**East** **380 HENRY ST** **NY HIST AST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.189 mi.**
**1000 ft.** **Site 4 of 8 in cluster BB**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-094161 |
| Program Type: | PBS |
| UTM X: | 584733.05865000002 |
| UTM Y: | 4504595.14463 |
| Expiration Date: | 2017/05/07 |
| Site Type: | Other |

Affiliation Records:

| | |
|---|---|
| Site Id: | 2536 |
| Affiliation Type: | Mail Contact |
| Company Name: | COBBLE HILL HEALTH CENTER, INC. |
| Contact Type: | Not reported |
| Contact Name: | DONNY TUCHMAN |
| Address1: | 380 HENRY STREET |
| Address2: | ADM OFFICE |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 855-6789 |
| EMail: | DTUCHMAN@COBBLEHILL.ORG |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 8/8/2012 |

| | |
|---|---|
| Site Id: | 2536 |

**COBBLE HILL NURSING HOME INC (Continued)** **U003384667**

| | |
|---|---|
| Affiliation Type: | Facility Owner |
| Company Name: | COBBLE HILL HEALTH CENTER, INC. |
| Contact Type: | ASSOC. ADM |
| Contact Name: | DONNY TUCHMAN |
| Address1: | 380 HENRY STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 12201 |
| Country Code: | 001 |
| Phone: | (718) 855-6789 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 2/27/2007 |

| | |
|---|---|
| Site Id: | 2536 |
| Affiliation Type: | On-Site Operator |
| Company Name: | COBBLE HILL HEALTH CENTER, INC. |
| Contact Type: | Not reported |
| Contact Name: | COBBLE HILL HEALTH CENTER, INC |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-6789 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 2536 |
| Affiliation Type: | Emergency Contact |
| Company Name: | COBBLE HILL HEALTH CENTER, INC. |
| Contact Type: | Not reported |
| Contact Name: | DONNY TUCHMAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-6789 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 0004 |
| Tank Id: | 245113 |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |

**COBBLE HILL NURSING HOME INC (Continued)** **U003384667**

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
I03 - Overfill - Automatic Shut-Off
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 3 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 04/20/2012 |
| Capacity Gallons: | 275 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |
| Last Modified: | 08/08/2012 |
| Material Name: | Diesel |

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 4172 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J00 - Dispenser - None
L00 - Piping Leak Detection - None

| | |
|---|---|
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/29/1932 |
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |

**COBBLE HILL NURSING HOME INC (Continued)** **U003384667**

Last Modified: 08/08/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 245111
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/29/1932
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 08/08/2012
Material Name: Diesel

Tank Number: 003
Tank Id: 245112
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F04 - Pipe External Protection - Fiberglass
D01 - Pipe Type - Steel/Carbon Steel/Iron
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None

**COBBLE HILL NURSING HOME INC (Continued)** **U003384667**

| | |
|---|---|
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 04/20/2012 |
| Capacity Gallons: | 2000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |
| Last Modified: | 08/08/2012 |
| Material Name: | Diesel |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-094161 |
| SWIS Code: | 6101 |
| Operator: | COBBLE HILL NURSING HOME INC |
| Facility Phone: | (718) 855-6789 |
| Facility Addr2: | 380 HENRY ST |
| Facility Type: | OTHER |
| Emergency: | ADOLF WIEDER |
| Emergency Tel: | (718) 855-6789 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | COBBLE HILL NURSING HOME |
| Owner Address: | 380 HENRY STREET |
| Owner City,St,Zip: | BROOKLYN, NY 12201 |
| Federal ID: | Not reported |
| Owner Tel: | (718) 855-6789 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | ADOLF WIEDER |
| Mailing Name: | COBBLE HILL NURSING HOME |
| Mailing Address: | 380 HENRY STREET |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BROOKLYN, NY 11201 |
| Mailing Telephone: | (718) 855-6789 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 06/04/1997 |
| Expiration: | 05/07/2002 |
| Renew Flag: | False |
| Renew Date: | Not reported |
| Total Capacity: | 5000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |

**COBBLE HILL NURSING HOME INC (Continued)** **U003384667**

| | |
|---|---|
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |
| Tank ID: | 001 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 5000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Aboveground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | 4 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**BB398** **COBBLE HILL HEALTH CENTER** **FINDS** **1010683220**
**East** **380 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.189 mi.**
**1000 ft.** **Site 5 of 8 in cluster BB**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

FINDS:

Registry ID: 110033110620

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BB399** **EDR US Hist Cleaners** **1015052362**
**East** **385 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.189 mi.**
**1000 ft.** **Site 6 of 8 in cluster BB**

**Relative:**
**Higher**

**Actual:**
**27 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | ROSAS LAUNDROMAT |
| Year: | 1999 |
| Address: | 385 HENRY ST |
| Name: | ROSAS LAUNDROMAT |
| Year: | 2001 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2001 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2002 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2003 |
| Address: | 385 HENRY ST |
| Name: | ROSAS LAUNDROMAT |
| Year: | 2004 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2005 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2006 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2007 |
| Address: | 385 HENRY ST |
| Name: | YOUNGS LAUNDROMAT |
| Year: | 2008 |
| Address: | 385 HENRY ST |
| Name: | ROSAS LAUNDROMAT |
| Year: | 2011 |
| Address: | 385 HENRY ST |
| Name: | ROSAS LAUNDROMAT |
| Year: | 2012 |
| Address: | 385 HENRY ST |

**BB400**
**East**
**1/8-1/4**
**0.190 mi.**
**1001 ft.**

**389 HENRY ST**
**BROOKLYN, NY 11201**

**Site 7 of 8 in cluster BB**

**EDR US Hist Cleaners** **1015052688**
**N/A**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | EMINENCE CLEANERS |
| Year: | 2010 |
| Address: | 389 HENRY ST |
| Name: | EMINENCE CLEANER |
| Year: | 2011 |
| Address: | 389 HENRY ST |
| Name: | EMINENCE CLEANER |
| Year: | 2012 |
| Address: | 389 HENRY ST |

---

**BD401**
**SW**
**1/8-1/4**
**0.190 mi.**
**1003 ft.**

**JOEL GOLDSTEIN MERCEDES DIST CENTER**
**160 IMLAY ST**
**BROOKLYN, NY**

**Site 1 of 3 in cluster BD**

**FINDS** **1007810512**
**N/A**

**Relative:**
**Lower**

**Actual:**
**2 ft.**

FINDS:

Registry ID: 110019730512

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

**BB402**
**East**
**1/8-1/4**
**0.190 mi.**
**1003 ft.**

**TWENTY GAL RELEASE AT MH 56082**
**371 HENRY STREET**
**BROOKLYN, NY**

**Site 8 of 8 in cluster BB**

**NY Spills** **S109581874**
**N/A**

**Relative:**
**Higher**

**Actual:**
**31 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0701879 |
| Facility Type: | ER |
| DER Facility ID: | 330872 |
| Site ID: | 381484 |
| DEC Region: | 2 |
| Spill Date: | 5/15/2007 |
| Spill Number/Closed Date: | 0701879 / 6/28/2007 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | gdbreen |
| Referred To: | Not reported |
| Reported to Dept: | 5/15/2007 |
| CID: | 444 |
| Water Affected: | Not reported |

**TWENTY GAL RELEASE AT MH 56082 (Continued)** **S109581874**

| | |
|---|---|
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/15/2007 |
| Spill Record Last Update: | 6/28/2007 |
| Spiller Name: | ERTSDESK |
| Spiller Company: | CON EDISON |
| Spiller Address: | 371 HENRY STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERTSDESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 06/28/07 - See eDocs for Con Ed report detailing cleanup and closure.205891. see eDocs |
| Remarks: | in manhole- looks like it is coming from a duct, still investigating : will be testing: coned # 205891 |

Material:

| | |
|---|---|
| Site ID: | 381484 |
| Operable Unit ID: | 1138938 |
| Operable Unit: | 01 |
| Material ID: | 2128942 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0900503 |
| Facility Type: | ER |
| DER Facility ID: | 361625 |
| Site ID: | 412444 |
| DEC Region: | 2 |
| Spill Date: | 4/14/2009 |
| Spill Number/Closed Date: | 0900503 / 6/3/2009 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | Con Ed Unassigned |
| Referred To: | Not reported |
| Reported to Dept: | 4/14/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |

**TWENTY GAL RELEASE AT MH 56082 (Continued)** **S109581874**

| | |
|---|---|
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/14/2009 |
| Spill Record Last Update: | 6/3/2009 |
| Spiller Name: | ERT |
| Spiller Company: | CON ED |
| Spiller Address: | 371 HENRY ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 06/03/09 - See eDocs for Con Ed report detailing cleanup and closure. |
| Remarks: | 1 QUART OF UNK PETROLEUM IN THE MANHOLE CLEAN UP IS PENDING. |

Material:

| | |
|---|---|
| Site ID: | 412444 |
| Operable Unit ID: | 1168914 |
| Operable Unit: | 01 |
| Material ID: | 2160545 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AR403** **PREMIUM MILLWORK INC** **FINDS** **1007801910**
**SSW** **270 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.190 mi.**
**1004 ft.** **Site 10 of 10 in cluster AR**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

FINDS:

Registry ID: 110019644367

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BC404** **327 HENRY ST** **NY UST** **U003128212**
**ENE** **327 HENRY ST** **NY Spills** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.190 mi.**
**1004 ft.** **Site 2 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**46 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-600624 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584824.74364999996 |
| UTM Y: | 4504849.9385000002 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 22604 |
| Affiliation Type: | Facility Owner |
| Company Name: | ZOLTAN DEVELOPMENT CORP. |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 218 ROCKAWAY TURNPIKE, ROOM 726 |
| Address2: | Not reported |
| City: | CEDARHURST |
| State: | NY |
| Zip Code: | 11516 |
| Country Code: | 001 |
| Phone: | (516) 371-1875 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22604 |
| Affiliation Type: | Mail Contact |
| Company Name: | ZOLTAN DEVELOPMENT CORP. |
| Contact Type: | Not reported |
| Contact Name: | EDWARD H. HONIG |
| Address1: | 218 ROCKAWAY TURNPIKE |
| Address2: | ROOM 726 |
| City: | CEDARHURST |
| State: | NY |
| Zip Code: | 11516 |
| Country Code: | 001 |
| Phone: | (516) 371-1875 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22604 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 327 HENRY ST |
| Contact Type: | Not reported |
| Contact Name: | NORMAN MARKMAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**327 HENRY ST (Continued)** **U003128212**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 596-0941 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 22604 |
| Affiliation Type: | Emergency Contact |
| Company Name: | ZOLTAN DEVELOPMENT CORP. |
| Contact Type: | Not reported |
| Contact Name: | HARVEY MARKMAN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-8418 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 43119 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 1500 |
| Install Date: | 12/01/1955 |
| Date Tank Closed: | 05/09/2000 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | 21 |
| Date Test: | 05/03/2000 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

**327 HENRY ST (Continued)** **U003128212**

SPILLS:

| | |
|---|---|
| Facility ID: | 0905847 |
| Facility Type: | ER |
| DER Facility ID: | 367258 |
| Site ID: | 418140 |
| DEC Region: | 2 |
| Spill Date: | 8/19/2009 |
| Spill Number/Closed Date: | 0905847 / 9/16/2009 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RWAUSTIN |
| Referred To: | Not reported |
| Reported to Dept: | 8/19/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/19/2009 |
| Spill Record Last Update: | 9/16/2009 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 9/16/09 - Austin - Spill contained and cleaned up - see EMIS in eDocs file - closed - end |
| Remarks: | 35 gallons of antifreeze contained to the box. clean up is pending CON ED REF #218098 |

Material:

| | |
|---|---|
| Site ID: | 418140 |
| Operable Unit ID: | 1174328 |
| Operable Unit: | 01 |
| Material ID: | 2166657 |
| Material Code: | 0043A |
| Material Name: | ANTIFREEZE |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 35 |
| Units: | Gallons |
| Recovered: | 35 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**AU405** **76 PRECINCT NYPD -DDC** **NY LTANKS** **S102239868**
**SSE** **191 UNION STREET** **NY Spills** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.191 mi.**
**1006 ft.** **Site 2 of 3 in cluster AU**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 99979 |
| Spill Number/Closed Date: | 9710102 / 5/2/2001 |
| Spill Date: | 12/2/1997 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 12/2/1997 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/2/1997 |
| Spill Record Last Update: | 12/22/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | NYC |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller County: | 999 |
| Spiller Contact: | TYREE ORGANIZATION |
| Spiller Phone: | (516) 249-3150 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 128289 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"THIS IS SAME SPILL AS #9710091 - SEE COMMENTS UNDER THAT SPILL NUMBER. |
| Remarks: | tank top failure. SAME SPILL AS 9710091. |

Material:

| | |
|---|---|
| Site ID: | 99979 |
| Operable Unit ID: | 1053139 |
| Operable Unit: | 01 |
| Material ID: | 560971 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

Tank Test:

| | |
|---|---|
| Site ID: | 99979 |
| Spill Tank Test: | 1545500 |
| Tank Number: | 001 |
| Tank Size: | 6000 |
| Test Method: | 20 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | USTest 2000/P/LL plus USTest 2000/U |

| | |
|---|---|
| Site ID: | 99978 |
| Spill Number/Closed Date: | 9710091 / 10/31/2003 |
| Spill Date: | 12/2/1997 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Known release that creates potential for fire or hazard. (Highly Improbable) |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 12/2/1997 |
| CID: | 369 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/2/1997 |
| Spill Record Last Update: | 12/22/2004 |
| Spiller Name: | SAME |
| Spiller Company: | NYC POLICE DEPT |
| Spiller Address: | 830 4TH AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 001 |
| Spiller Contact: | SERGY PILDYSN |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 128289 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"FLOATING PRODUCT PLUME EXISTS AT THE SITE. ISRP IS BEING PREPARED BY RECON. A. ZHITOMIRSKY OF DEC INSTRUCTED S. PILDYSH OF RECON TO EMPTY THE TANK WITHIN 48 HRS. |
| Remarks: | TANK FAILED TIGHTNESS TEST-ASKING FOR IMMEDIATE CALLBACK IN REGARTDS TO FURTHER INSTRUCTIONS. Same as spill # 9601482. |

Material:

| | |
|---|---|
| Site ID: | 99978 |
| Operable Unit ID: | 1056467 |
| Operable Unit: | 01 |

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

| | |
|---|---|
| Material ID: | 563758 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 99978 |
| Spill Tank Test: | 1545498 |
| Tank Number: | 1 |
| Tank Size: | 6000 |
| Test Method: | 00 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Unknown |

SPILLS:

| | |
|---|---|
| Facility ID: | 9601482 |
| Facility Type: | ER |
| DER Facility ID: | 128289 |
| Site ID: | 99977 |
| DEC Region: | 2 |
| Spill Date: | 4/29/1996 |
| Spill Number/Closed Date: | 9601482 / Not Reported |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | ADZHITOM |
| Referred To: | INSTALLATION OF ONE ADDITIONAL VACUUM MONITORING P |
| Reported to Dept: | 4/29/1996 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 5 |
| Date Entered In Computer: | 4/29/1996 |
| Spill Record Last Update: | 11/7/2013 |
| Spiller Name: | Not reported |
| Spiller Company: | NYPD |
| Spiller Address: | 1 POLICE PLAZA |
| Spiller City,St,Zip: | NY, NY |
| Spiller Company: | 001 |

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"TRANSFERRED FROM Y.KRIMGOLD.7-22-2005 Reviewed Quarterly Monitoring Report received on May 20, 2005. According to the report gw extraction and treatment system must contnue to operate due to the presence of free product and elevated dissolved phase gw contaminant concentrations. The Department concurred. AZ10-12-2005 The site has free phase.AZ 10/31/2005 Reviewed Quarterly Report dated September 2005. SVE system is operated. Free phase is present. AZ4/17/2006 Reviewed Quarterly Report received in November 2005. SVE system is removing elevated contaminant concentrations from the vadose zone according to URS. Free and dissolved phases are present in groundwater. According to URS, SVE and groundwater recovery systems must continue to operate. AZ11/30/2006 Contacted Andy Leddins (Greyhawk). Pump and Treat system is installed at the site. Greyhawk took over the system on April 1, 2006. URS turned off the system sometime before April1, 2006, but it's unknown when. According to the report Greyhawk took over the site from URS on January 1, 2006. The depression system is not lowering the water table. They tried to start it in April and May of 2006 but unsuccessfully. Operators will pull out the pumps trying to evaluate/repair the system. Reviewed Quarterly Report received on November 20, 2006. MW-02 previously exhibited significant gw contamination but during last sampling event was dry. MW-01R had 0.01 foot of product. MW-08 through MW-11 could not be found. MW-03 and MW-07 were under parked cars. Pump and Treat system breakdown log was not included in the report. I called Brian Morrissey Roux Ass. @631-232-2600(Roux). The system was not operating since March 31, 2006. I requested the following: MW-2 should be reinstalled, all wells should be located and sampled. If wells are not found they should re-installed. The system should be repaired. Air Sparging should not be considered if the free phase is present. AZ12/02/2004 E-mail from Brian Morissey: "The responsibility for the management of the remedial system at 76th Precinct was transferred from URS to Greyhawk/Roux on April 1, 2006. It was reported that the system was temporarily shut down on March 23, 2006 due to highly restricted flow rates. Greyhawk negotiated with EnviroTrac to operate the system. EnviroTrac began O&M services at the site on May 5, 2006. The GWET system was not operational upon start up. EnviroTrac attempted system restarts without success. The SVE system has operated without alarms or shutdown since start-up, according to the information provided by EnviroTrac."3/30/2007 E-mail from Greyhawk:Date of Shutdown - March 29 2007. Reason for shutdown - Diagnosis and reprogramming PLC. Corrective Action - Extract Program and reloadEstimated Duration of Downtime - Approximately 2 weeks. Comments - During preparations to begin Change Order to replace liquid level sensors, system engineer diagnosed the problem resided in the PLC. The EOS PLC module was pulled and brought back to the Sub-contractor shop to have the original program installed. AZ6/27/2007 An e-mail was sent to DEC/DDC/Greyhawk:Brian,I have reviewed Quarterly Report for the above site submitted to DEC on March 23, 2007. The GWET system was off-line during the reporting period. Groundwater contamination remains in monitoring wells MW-02 (2,560 ppb) and MW-01R (33, 790 ppb).Request to re-install MW-2, repair the system and locate or re-install all wells was previously made by DEC on November 30, 2006.The GWET system should be re-started without delay and the pumping rates increased. Confirmatory soil

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

sampling plan is approved. Frequency of the groundwater gauging could be changed to quarterly. MW-02 should be re-installed. Wells which were not found should be located or re-installed. Well MW-06 (next to the removed gasoline tanks) was not sampled. If there is no particular reason for not sampling this well it should be sampled. AZ1-22-2008 Reviewed January - June 2007 Report. MW-02 has 3,715 ppb total VOCs. MW-01R decreased dramatically from 33,790 total VOCs in October 13, 2006 TO 63 ppb on April 5, 2007. However, Roux regards this decrease as suspicious. Monitoring well MW-16 should be added to the sampling program as well as MW-06. Confirmed these proposals in phone conversation with B. Morrissey. AZ10-14-2008 Reviewed July 2007 - March 2008 Report submitted on July 3, 2008. New soil borings were advanced in September 2007. High residual VOC soil contamination remains at the water table up to a few feet below the water table in the western part of the site between monitoring wells MW-01R and MW-02 (up to 418,990 ppb). GWT is at 30 bls at the site. SVE-01, the only existing on site SVE well, is not located close enough to the area of residual soil contamination to remediate it. Because residual contaminated soil occurs below the water table, for soil remediation via SVE, the water table needs to be depressed. The concentration of VOC in soil is too high for in situ enhanced bioremediation to be effective. An e-mal was sent to Roux/Greyhawk/DDC/V.B.:"I have reviewed Quarterly Report (July 2007 - March 2008) for the above site submitted on July 3, 2008. Report submittal was significantly delayed. New soil borings were advanced in September 2007. High residual VOC soil contamination remains at the water table and a few feet below the water table in the western part of the site between monitoring wells MW-01R and MW-02 (up to 418,990 ppb). SVE-01, the only existing on site SVE well, is not located close enough to the area of residual soil contamination to remediate it. Because residual contaminated soil occurs below the water table, soil remediation via SVE would be possible only if the water table is depressed. The concentration of VOC in soil is too high for in situ enhanced bioremediation to be effective. Roux recommended shutting down the SVE system and converting the groundwater extraction wells to SVE or MPE My recommendations are as follows: The existing groundwater extraction wells should remain active to address existing groundwater contamination and depress the groundwater table to enable SVE system to perform. Additional groundwater extraction wells should be installed in the area of the existing soil contamination to further depress water table. Additional SVE wells should be installed in the contaminated area. An implementation schedule for this work should be submitted to DEC."AZ 8-6-09 E-mail sent to DDC/Roux/V. Brevdo:"I have reviewed Quarterly Monitoring Report covering the period of April 2008 through January 2009. and dated March 19, 2009. The report stated that residual soil and groundwater contamination remains in the western part of the site and needs to be remediated. VOC contamination remains in soil at the water table up to a few feet below the water table around MW-01R and MW-02. The water table needs to be depressed via groundwater extraction for soil remediation via SVE to be possible. SVE-01, the only SVE well, is not located close enough to the area of soil contamination to remediate it. The concentration of VOC in soil is too high for in situ bioremediation to be effective.MW-01R exhibited 26,070 ppb of the total VOC. Roux recommended system modifications including installation of additional extraction wells focusing in the western portion of the site.These recommendations are approved. However, SVE system should not be shut

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

down, but modified instead. SVE wells should be installed int the western part of the site."AZ9-16-2010 An e-mail was sent to S. Frank, V. Brevdo and F. Ashkani: "I have reviewed Quarterly Report for 76th Precinct dated July 27, 2010. The report stated that no off-site contamination was found. The SVE/GWET system was modified by Roux. LiRo can discontinue sampling of wells MW-08, MW-09 and MW-10. These wells must be secured and their covers must be tight. LiRo should insure the tightens of the well covers. All other existing wells should be redeveloped and sampled on a quarterly basis. Wells MW-02 and MW-01R should be sampled." AZ4-25-2011 Reviewed quarterly monitoring report for the period of August--October 2010 received on January 31, 2011. In November 2009 Roux advanced RXSB-09. 346,800 ppb of total VOC was detected in this well. 11 wells were re-developed.MW-13 was damaged. Gw was observed at 24'-35'. Total VOC concentrations ranged from 26,362 ppb in MW-01R to 30,099 ppb in MW-02. SVE and GWET systems are operational.An e-mail was sent to DDC/LiRo/VB: "I have reviewed quarterly monitoring report for the period of August--October 2010 received on January 31, 2011. Heavy soil and groundwater contamination are encountered at the site. Additional site investigation proposed by LiRo is approved. Wells MW-01 and MW-13 should be repaired or re-installed. A tank inventory should be compiled. USTs, which are closed in place, should be excavated, if feasible. Hot spot soil excavation should be performed, if feasible. Monitoring of wells MW-12, MW-14 and MW-18 could be discontinued. Well covers should be secured and made tight." AZ9-7-2011 Reviewed quarterly monitoring report for the period of November 2010--January 2011, and dated April 1, 2011. Contacted S. Frank and discussed the site. Work Plan approved by DEC in April 2011, has not been implemented yet. Total VOC concentrations have decreased in groundwater. AZ11-4-2011 Reviewed quarterly monitoring report for the period of Feb 2011--Apr. 2011 and dated July 27,2011. The additional investigation approved by DEC has not been implemented yet.. It will be completed in summer 2011. Well MW-13 has not being repaired yet. It will be repaired during the site investigation. Tank inventory requested by DEC will be completed during next monitoring period. The status of 6,000 gal #2 fuel UST must be confirmed and excavation considered. DEC requested re-securing well covers. It will be done during next monitoring event. AZ3-6-2012 Reviewed QMR dated December 15, 2011. Six soil borings were advanced in August 2011. PID readings and petroleum odor were recorded at the the depth of 29'-40' bgs. Four samples reported VOCs above SCLs and ranging from 65,890 ppb to 1,224,000 ppb at or just below gw table. Groundwater contamination is up to 9,106 ppb. Well covers were secured. LiRo determined that 6,000 gal tank was removed. The following e-mail was sent to S. Frank/F. Ashkan and V. Brevdo:"Dear Steve,I have reviewed QMR dated December 15, 2011. The report proposed installation of one additional monitoring point within ROI of well SVE-02. This proposal is approved. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. Sincerely,Alexander ZhitomirskyEngineering Geologist 2NYSDEC Region 2Division of Environmental Remediation"AZ6-14-2012 An e-mail was sent to S. Frank, F. Ashkan, V. Brevdo:"Dear Steve, I have reviewed a Monitoring Report for the period of October 2011 - January 2012. Two remedial systems are being operated at the site: Groundwater Extraction Treatment (GWET) system and Soil Vapor Extraction (SVE) system. Heavy residual soil contamination ranging from 65,890 ppb to 1,224,000 ppb total VOC is preset at the site. The initial sampling of monitoring well

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

LMW-01, installed at DEC's request, reported a total VOC concentration of 5,213 ppb. Free phase is encountered in one well. LiRo will continue operation of the modified SVE system and GWET system. As part of an analysis to determine if design and modifications can be implemented (lowering the depth of groundwater extraction points) to create a cone of depression, LiRo will complete an assessment of the existing recovery wells to determine bladder pimp elevations and determine what modifications can be completed. Also, one additional vacuum monitoring point near well SVE-02 will be installed i the third quarter of 2012. I concur with the LiRo's proposal to remove wells MW-11 and MW-15 from the sampling program. sampling in monitoring wells. All other wells should remain in the sampling program. Sincerely, Alexander ZhitomirskyEngineering Geologist 2NYSDEC Region 2Division of Environmental Remediation" AZ4-15-2013 Reviewed LiRo report dated August 20-2012. LiRo will repair GWET system, perform a step drawn down test in extraction wells. The results will determine system design modifications. Some extraction wells could be overdrilled. 3 extraction wells will be overdrilled prior to performing the drawn down test. One additional vacuum monitoring point within ROI of SVE-02 will be installed. Wells MW-11 and MW-15 will be removed from the sampling program. AZ5-7-2013 Reviewed LiRo report dated November 12-2012. The step-test and constant rate pump test indicates the aquifer has adequate transmissivity. However, the recovery wells are not screened properly within the aquifer. LiRo will overdrill recovery well RW-03. A piezometer will be advanced 8' east of RW-03. Also, one additional vacuum monitoring point will be installed the ROI of well SVE-02 (approved by DEC in March 2012). AZLiRo will repair GWET system, perform a step drawn down test in extraction wells. The results will determine system design modifications. Some extraction wells could be overdrilled. 3 extraction wells will be overdrilled prior to performing the drawn down test. One additional vacuum monitoring point within ROI of SVE-02 will be installed. Wells MW-11 and MW-15 will be removed from the sampling program. AZ8-14-2013 S. Sangesland received a letter from a private citizen stating that there is gas tank at the property and complaining of gasoline fumes. No phone number was included in the letter. I contacted LiRo and asked to check for presence of gasoline fumes at the site. S. Frank will get back to me, AZ11-7-2013 Reviewed a quarterly monitoring report for August 2012--January 2013 dated March 28, 2013. LiRo recommends overdrilling of recovery well RW-01, this recommendation will be included in the upcoming DAR. According to the report, one additional vacuum monitoring point will be installed within ROI of well SVE-02 (approved March 2012). Installation of the vacuum point will be completed once modifications are finalized for the system. Well MW-02, which typically reports VOCs above AWQSGVs, was inaccessible in January 2013. VOC concentrations in MW-02 in October 2012 was 10,820 ppb. A Step Draw-Down Pump test was performed on RW-03R in December 2012. The test determined that based on the new recovery well configuration, a 72-hour Constant Rate Pump Test could be performed at 27 gpm. A 72-hour Constant Rate Pump test was completed on well RW-03R in January 2013. The pumping rate of 25 gpm was sustained and resulted in a drawdown of 1.303 feet. The estimated capture zone radius with a pumping rate of 25 gpm was conservatively estimated at 50 feet. AZ

Remarks: CALLER FOUND CONTAMINATED SOIL WHEN REMOVING TANKS. Also see spill #s 9710091, 9710102, 9830012.

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

Material:

| | |
|---|---|
| Site ID: | 99977 |
| Operable Unit ID: | 1033055 |
| Operable Unit: | 01 |
| Material ID: | 351283 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 9830012 |
| Facility Type: | ER |
| DER Facility ID: | 128289 |
| Site ID: | 150950 |
| DEC Region: | 2 |
| Spill Date: | 10/15/1998 |
| Spill Number/Closed Date: | 9830012 / 10/31/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 10/14/1998 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/15/1998 |
| Spill Record Last Update: | 12/22/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | NYC |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD" |
| Remarks: | THE PERSON CALLED IN AND SAID THAT HE SAW THE TRUCK CAUSED OIL OVERFILL AND SPREAD OVER THE GROUND IN THE PCT BEFORE, BUT HE STILL CAN SMELL THE ODOR NOW. HE SAID THE THE OLD UST AT SITE WAS CLOSED |

**76 PRECINCT NYPD -DDC (Continued)** **S102239868**

AND A NEW AST WAS PUT ON TO REPLACE THE OLD FUEL TANK. HE SAID PROBABLY BECAUSE THE ABOVEGROUND TANK IS HIGHER THAN THE TRUCK AND CAUSES THE SPILLS. Also see spill # 9601482

Material:

| | |
|---|---|
| Site ID: | 150950 |
| Operable Unit ID: | 1073914 |
| Operable Unit: | 01 |
| Material ID: | 309040 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AU406** **76 PCT** **NY UST** **U000408650**
**SSE** **191 UNION STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.191 mi.**
**1006 ft.** **Site 3 of 3 in cluster AU**

**Relative:**
**Higher**

**Actual:**
**35 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-343242 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2017/12/14 |
| UTM X: | 584519.48823999998 |
| UTM Y: | 4504093.4272400001 |
| Site Type: | Municipality (Incl. Waste Water Treatment Plants, |

Affiliation Records:

| | |
|---|---|
| Site Id: | 16669 |
| Affiliation Type: | Emergency Contact |
| Company Name: | ADMINISTRATIVE SERVICE DIVISION |
| Contact Type: | Not reported |
| Contact Name: | FUEL CONTROL UNIT |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 476-7524 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | BKFALVEY |
| Date Last Modified: | 2/4/2010 |

| | |
|---|---|
| Site Id: | 16669 |
| Affiliation Type: | Mail Contact |

**76 PCT (Continued)** **U000408650**

| | |
|---|---|
| Company Name: | NYC POLICE DEPARTMENT |
| Contact Type: | Not reported |
| Contact Name: | COMMANDING OFFICER |
| Address1: | BUILDING MAINTENANCE SECTION |
| Address2: | 59-06 BROOKLYN-QUEENS EXPRESSWAY |
| City: | WOODSIDE |
| State: | NY |
| Zip Code: | 11377 |
| Country Code: | 001 |
| Phone: | (718) 476-7576 |
| EMail: | NICHOLAS.GISONDA@NYPD.ORG |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 12/24/2013 |

| | |
|---|---|
| Site Id: | 16669 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 76 PCT |
| Contact Type: | Not reported |
| Contact Name: | NYC P.D. |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NY |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 834-3211 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | BKFALVEY |
| Date Last Modified: | 12/30/2009 |

| | |
|---|---|
| Site Id: | 16669 |
| Affiliation Type: | Facility Owner |
| Company Name: | ADMINISTRATIVE SERVICE DIVISION NYCPD/ASD |
| Contact Type: | SERGEANT |
| Contact Name: | BRENDAN MORAN |
| Address1: | 1 POLICE PLAZA, ROOM 800 |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10007 |
| Country Code: | 001 |
| Phone: | (646) 610-7650 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 3/6/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 32310 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 6000 |
| Install Date: | 02/01/1961 |

**76 PCT (Continued)** **U000408650**

| | |
|---|---|
| Date Tank Closed: | 02/15/1995 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 00 |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | dxliving |
| Last Modified: | 10/09/2009 |

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
G03 - Tank Secondary Containment - Vault (w/o access)

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 50806 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 03/01/1996 |
| Date Tank Closed: | 03/01/1996 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None

**76 PCT (Continued)** **U000408650**

| | |
|---|---|
| Tank Number: | 003 |
| Tank ID: | 50807 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 03/01/1996 |
| Date Tank Closed: | 03/01/1996 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None

| | |
|---|---|
| Tank Number: | 004 |
| Tank ID: | 50808 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 03/01/1996 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 11/12/2010 |

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass

**76 PCT (Continued)** **U000408650**

H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I03 - Overfill - Automatic Shut-Off
E04 - Piping Secondary Containment - Double-Walled (Underground)

| | |
|---|---|
| Tank Number: | 005 |
| Tank ID: | 231072 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 5000 |
| Install Date: | 03/01/1996 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 21 |
| Date Test: | 06/30/2009 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 11/12/2010 |

Equipment Records:

F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
G04 - Tank Secondary Containment - Double-Walled (Underground)

---

**BE407** **PLASTIFORM PACKAGING INCORPORATED** **ICIS 1011602405**
**SSW** **42 DELEVAN ST BROOKLYN NY 11231** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.191 mi.**
**1007 ft.** **Site 1 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

ICIS:

| | |
|---|---|
| Enforcement Action ID: | 02-1988-0135 |
| FRS ID: | 110001573690 |
| Program ID: | AIRS/AFS 3604700813 |

**PLASTIFORM PACKAGING INCORPORATED (Continued)** **1011602405**

| | |
|---|---|
| Action Name: | PLASTIFORM PACKAGING INC |
| Facility Name: | 42 DELEVAN ST BUILDING |
| Facility Address: | 42 DELEVAN ST BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | CAA 113 Notice Of Violation |
| Facility County: | Kings |
| EPA Region #: | 2 |
| Enforcement Action ID: | 02-1988-0135 |
| FRS ID: | 110001573690 |
| Program ID: | FRS 110001573690 |
| Action Name: | PLASTIFORM PACKAGING INC |
| Facility Name: | PLASTIFORM PACKAGING INCORPORATED |
| Facility Address: | 42 DELEVAN ST BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | CAA 113 Notice Of Violation |
| Facility County: | Kings |
| EPA Region #: | 2 |
| Program ID: | AIRS/AFS 3604700813 |
| Facility Name: | PLASTIFORM PACKAGING INCORPORATED |
| Address: | 42 DELEVAN ST |
| Tribal Indicator: | N |
| Fed Facility: | Not reported |
| NAIC Code: | Not reported |
| SIC Code: | 3089 |
| Latitude: | 40.67949 |
| Longitude: | -74.00768 |
| Program ID: | FRS 110001573690 |
| Facility Name: | PLASTIFORM PACKAGING INCORPORATED |
| Address: | 42 DELEVAN ST |
| Tribal Indicator: | N |
| Fed Facility: | Not reported |
| NAIC Code: | Not reported |
| SIC Code: | 3089 |
| Latitude: | 40.67949 |
| Longitude: | -74.00768 |

---

**BE408** **PLASTIFORM PACKAGING INC** **NY MANIFEST** **1009231736**
**SSW** **42 DELEVAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.191 mi.**
**1007 ft.** **Site 2 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000784645 |
| Country: | USA |
| Mailing Name: | PLASTIFORM PACKAGING INC |
| Mailing Contact: | GEORGE F SMITZ |
| Mailing Address: | 42 DELEVAN STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |

**PLASTIFORM PACKAGING INC (Continued)** **1009231736**

Mailing Phone: 212-875-6750

Document ID: NYO3179088
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 840809
Trans1 Recv Date: 840809
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840809
Part A Recv Date: 840820
Part B Recv Date: 840813
Generator EPA ID: NYP000784645
Trans1 EPA ID: NYD980592471
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00550
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 84

Document ID: NYO3072483
Manifest Status: Completed copy
Trans1 State ID: NY 2A-0
Trans2 State ID: Not reported
Generator Ship Date: 840411
Trans1 Recv Date: 840411
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840411
Part A Recv Date: 840418
Part B Recv Date: 840423
Generator EPA ID: NYP000784645
Trans1 EPA ID: NYD980592471
Trans2 EPA ID: Not reported
TSDF ID: NYD000824334
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02235
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 022
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 84

**BE409** **PLASTIFORM PACKAGING INCORPORATED** **FINDS** **1006533754**
**SSW** **42 DELEVAN ST** **US AIRS** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.191 mi.**
**1007 ft.** **Site 3 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

FINDS:

Registry ID: 110001573690

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110001573690 |
| Plant name: | 42 DELEVAN ST BUILDING |
| Plant address: | 42 DELEVAN ST<br>BROOKLYN, NY 11231 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | 001862200 |
| Air quality cntrl region: | 043 |
| Sic code: | 9999 |
| Sic code desc: | NONCLASSIFIABLE ESTABLISHMENTS |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |

**PLASTIFORM PACKAGING INCORPORATED (Continued)** **1006533754**

Current HPV: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:

Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR

**PLASTIFORM PACKAGING INCORPORATED (Continued)** **1006533754**

Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**BC410** **SHELL GAS** **NY LTANKS** **S103484030**
**ENE** **112 ATLANTIC AVE** **NY Spills** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.193 mi.**
**1021 ft.** **Site 3 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 183764 |
| Spill Number/Closed Date: | 0400263 / 3/10/2005 |
| Spill Date: | 4/8/2004 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Gasoline Station |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | KMFOLEY |
| Referred To: | Not reported |
| Reported to Dept: | 4/8/2004 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/8/2004 |
| Spill Record Last Update: | 3/10/2005 |
| Spiller Name: | MARY MCCONTEE |
| Spiller Company: | TEXACO STATION#138600 |
| Spiller Address: | 112 ATLANTIC AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 001 |
| Spiller Contact: | MARY MCCONTEE |
| Spiller Phone: | (631) 462-2226 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 153810 |
| DEC Memo: | 4/16/04 Rob Rule, Shell, is responsible for 112 Atlantic Ave. TTF letter mailed to R. Rule.(KMF)9/10/04 Received UST closure report for the removal of (1) 550gal heating oil UST completed 4/27-4/28/04. Pitting was observed on the bottom of the UST. Endpoint sampling results for the samples exceeded the recommended soil cleanup objectives for 5 SVOCs. In response to the documented residual hydrocarbons, a subsurface investigation was conducted. MW-5 was installed and soil samples collected at 5ft intervals from 5 to 48'bgs. Soil samples were screened in the field visually and with a PID. PID readings were 0 to 220ppmv(30-32'bgs) One composite sample was collected for lab analysis at 30-47'bgs and exceeded standards for xylenes.Groundwater samples were collected from all wells on 6/2-6/3/04. The sample collected from MW-5 exhibited concentrations of benzene, xylenes and MTBE above GWQS. Samples from MW1-4 did not |

**SHELL GAS (Continued)** **S103484030**

exhibit detectable concentrations of BTEX/MTBE.NES recommends two additional groundwater samples be collected from Sept and Dec 2004. MW1 thru MW4 will not be sampled. If data is consistent, site closure will be requested.11/12/04 Received update report (NES, 11/9/04). Additional GW sampling will be performed in 12/04. In 9/04, a GW sample was collected from MW-5 and all wells were guaged. BTEX was not detected above MDL and MTBE detected at 3.6ppb. DTW approx 33'bgs. Flow toward the north at 0.015ft/ft.11/23/04 Meeting held with M. Schneck, NES and R. Rule, Shell. Will resample in 12/04 and possibly propose closure if trends warrant it.2/14/05 Received update report with sampling results for MW-5 conducted in 12/04. Review of Sept and Dec 2004 lab analytical data indicates GW beneath the former heating oil UST meets GW standards. 3/10/05 NFA issued.

Remarks: Not reported

Material:

| | |
|---|---|
| Site ID: | 183764 |
| Operable Unit ID: | 884640 |
| Operable Unit: | 01 |
| Material ID: | 495049 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Site ID: | 183764 |
| Spill Tank Test: | 1529138 |
| Tank Number: | Not reported |
| Tank Size: | 1000 |
| Test Method: | 03 |
| Leak Rate: | 0 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified: | 10/1/2004 |
| Test Method: | Horner EZ Check I or II |

SPILLS:

| | |
|---|---|
| Facility ID: | 9806463 |
| Facility Type: | ER |
| DER Facility ID: | 153810 |
| Site ID: | 201675 |
| DEC Region: | 2 |
| Spill Date: | 8/25/1998 |
| Spill Number/Closed Date: | 9806463 / 7/11/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | MMMULQUE |

**SHELL GAS (Continued)** **S103484030**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 8/25/1998 |
| CID: | 211 |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/25/1998 |
| Spill Record Last Update: | 7/11/2002 |
| Spiller Name: | ROB RULE |
| Spiller Company: | SHELL GAS |
| Spiller Address: | 112 ATLANTIC AV |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | CARYN SILVERSTEIN |
| Contact Phone: | (516) 586-1800 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN"7/11/2002 - Closure report submitted to DEC and approved.Documents in DEC office - Shell Oil Archive Files |
| Remarks: | CALLER DOING TANK REMOVAL AND ENCOUNTERED SOIL CONTAMINATION - DIRT WILL BE STOCKPILED |

Material:

| | |
|---|---|
| Site ID: | 201675 |
| Operable Unit ID: | 1067646 |
| Operable Unit: | 01 |
| Material ID: | 317621 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0809729 |
| Facility Type: | ER |
| DER Facility ID: | 153810 |
| Site ID: | 407220 |
| DEC Region: | 2 |
| Spill Date: | 12/1/2008 |
| Spill Number/Closed Date: | 0809729 / 8/3/2010 |
| Spill Cause: | Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RVKETANI |

**SHELL GAS (Continued)** **S103484030**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 12/1/2008 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 12/1/2008 |
| Spill Record Last Update: | 8/3/2010 |
| Spiller Name: | ROB RULE |
| Spiller Company: | SHELL STATION # 138600 |
| Spiller Address: | 112 ATLANTIC AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | KRISTEN DISCENZA |
| Contact Phone: | (631) 753-8380 |
| DEC Memo: | 8/5/09- Complete file review by Intern EM Ibeh under supervision of DEC Vought. The file being reviewed is SP# 08-09729 on 112 Atlantic Ave., Brooklyn, a former Shell Service Station site. A spill number was assigned to the site in 2008 because during UST removals, PID readings were elevated throughout tank field excavation. Closed SP##0400263- Spill date-4/04, at 112 Atlantic Ave., Brooklyn, the site of a Texaco Station #138600. #2 fuel oil spilled after a TTF and "Shell was responsible for 112 Atlantic Ave.". Spill was closed on 3/05. PBS# 2-191051 was found for the above site and the owner/operator is listed as:Theodoros Zorbas112 Atlantic Ave., BrooklynNY 11201(713.277.8000)Tank Excavation Assessment Report and Closure Request (Sovereign Consulting -Kristen DiScenza Ph: 631-753-8380 fax: 631-753-8385) -2/3/09. Letter from Sovereign Consulting, Inc to DEC Vought stating that enclosed was a copy of the TEA report for 112 Atlantic Ave., documenting findings of UST removal activities, soil data, conclusions and recommendations and as a result, spill closure is recommended.Report SummarySovereign Consulting, Inc was retained by Motiva Enterprises, LLC to document UST removal activities at the former Shell Service Station #138600, located at the intersection of Henry St. and Atlantic Ave. from Nov 18, 08-Dec 15, 08. The site dispensed gasoline from 2 product dispensers located along the northern property boundary and the site contained a one story building with 3 service bays. The UST tank field was located along the southwest property boundary and contained (3) 4000-gallon single wall steel fiberglass lined gasoline USTs encased in concrete. General topography of the area sloped to the southwest and 5 monitoring wells (MW1- MW5) were located throughout the site. Flow/gradient was said to be northeasterly with a body of wetlands associated with the East River located ~1690ft west of the site. Upon completion of UST removals, (2) 12000gallon double wall fiberglass USTs were installed in the same area as the 3 4000-gallon tanks.Groundwater and Environmental Services (GES) performed a Phase II Environmental Assessment at this facility in March 2008 where groundwater was obtained from previously existing monitoring wells-MW-1, MW-2 & MW-5. MW-3 & MW-4 were found to be abandoned. No VOCs were detected above NYSDEC groundwater quality standards in any |

**SHELL GAS (Continued)** **S103484030**

of the groundwater samples. Field activities at the site included removal of USTs, associated piping and fueling equipment, removal of hydraulic lifts and Oil Water Separator and removal of 550gallon abandoned Underground Waste Oil Tank. The gasoline tanks had already been emptied and cleaned prior to the removal activities. The excavated and surrounding subsurface soils were screened with a PID to determine VOC presence and post-excavation endpoint samples were collected, placed into lab supply containers and delivered to Xenco Lab, TX for analysis. Sampling methodology was performed by the DEC Petroleum-Contaminated Soil Guidance Policy, (STARS) Memo #1. The (3) 4000gallon USTs were removed and noted to be in good condition with no visible holes and the soil surrounding the USTs was comprised of dark-colored medium to coarse grained silty sand and gravel. PID readings ranged from non-detect to 500ppm throughout tank field excavation. Former abandoned MW-3 was destroyed during UST excavation.Prior to installation of new USTs, 11 post-excavation endpoint soil samples were collected from the bottom and sidewalls of the former tank field and submitted to Xenco for analysis of STARS VOCs, including MTBE, by EPA Method 8260B and STARS SVOCs, by Method 8270C. (7) sidewall samples (T1 through T4, T7, T10, T11) were collected from depths of 12-14ft below grade. T1, T2 & T3 resulted in non-detect concentrations of BTEX, MTBE and all SVOCs; T4 had ND concentrations of BTEX and MTBE, 19800ppb Benzo(a)anthracene, 19900ppb Benzo(b)fluoroanthene, 55100ppb fluoroanthene and 49700ppb Phenanthrene.4 bottom samples (T5, T6, T8 & T9) collected from depths 14-15 ftbg resulted in non- detect concentrations of BTEX, MTBE and all SVOCs.2 product dispensers were removed from the northern portion of the property and 2 soil samples, D1 and D2, were taken beneath the dispensers along with 11 post-excavation soil samples (D3-D13) and were submitted to be analyzed for STARS VOCs, including MTBE, by EPA Method 8260B and STARS SVOCs, by Method 8270C. PID reading ranged from non-detect to 1048ppm throughout the excavation and soil with elevated PID levels was disposed of offsite. 2 VOCs, Xylenes and 1, 2, 4-Trimethylbenzene, were detected above RSCO in D7 (11,210ppb and 14,400ppb) respectively. Maximum SVOC concentrations were in D5 (4730ppb Benzo (a) anthracene) and D12 (2750ppb Benzo (a) pyrene). Product piping delivery lines from USTs to dispensers were also removed and delivery lines were excavated within both the UST and dispenser island excavations, and as such no samples were obtained from these locations. 2 hydraulic lifts and an oil water separator (OWS) were removed from the service bays. 2 soil samples each were collected from each lift location and the OWS excavation site and analyzed for STARS VOCs, including MTBE, by EPA Method 8260 and STARS SVOCs, by Method 8270. Results showed that no VOCs or SVOCs were detected above RSCO in either sample. A 550gallon abandoned Underground Waste Oil Tank was found on the western portion of the property. 5 soil samples were collected from the bottom and sidewalls (AWO-1-AWO-5) and submitted for analysis of STARS VOCs, including MTBE, by EPA Method 8260B and STARS SVOCs, by Method 8270C. AWO-1 & AWO-2 resulted in non-detect concentrations of BTEX, MTBE and all SVOCs; AWO-3 had non-detect concentrations of BTEX and MTBE, 3780ppb Benzo(a)anthracene, 10200ppb fluoroanthene and 6930ppb Phenanthrene. AWO-4 resulted in non-detect concentrations of BTEX, MTBE and all SVOCs and AWO-5 had non-detect concentrations of BTEX and MTBE, 2680ppb anthracene, 5710ppb Benzo(a)anthracene, 13600ppb fluoroanthene and 12500ppb phenanthrene.Groundwater VOC Monitoring Concentration-3/14/08MW-1 Benzene ND, Ethylbenzene ND, MTBE ND,

**SHELL GAS (Continued)** **S103484030**

Toluene ND and Xylene ND.MW-2 Benzene ND, MTBE ND, Toluene ND and Xylene ND.MW-5- Tetrachloroethane 3.3ppb, MTBE ND, Toluene ND and Xylene ND.Report concluded that since groundwater data from existing monitoring wells resulted in no VOCs or SVOCs detected, soils had been removed from site and structural integrity maintained, spill number should be closed. 8/6/09- DEC Vought spoke to Ms DiScenza and: Informed her that the DEC requires determination of groundwater flow direction through collection of downgradient groundwater samples due to TAGM exceedence in D7 and high phenanthrene levels in T4, seeing as no endpoint samples were collected from the product piping lines to confirm presence/absence of VOCs and SVOCs.As per Ms DiScenza, the property will remain a gas station.Shell Oil is the RP and their contact information is Rob Rule, 3139 Village Drive, Waynesboro, Virginia 22980 (P-540.943.8468, Fax: 540.943.7661).PBS registration contains erroneous information and needs to be updated: -TEA reports removal of a 550gallon abandoned Waste Oil tank but PBS shows a 1000gallon Waste Oil tank with no active fuel oil tank.
08/06/09-Letter was sent out to Rob Rule, copying DiScenza, requiring Shell Oil to perform groundwater flow determination and update PBS registration. Current PBS registration was also attached.08/26/09-Vought-Received email from Kristen DiScenza that "as per the August 6, 2009 DEC correspondence, groundwater sampling and monitoring well surveying will be conducted at the above mentioned site on Thursday September 3, 2009. Groundwater samples will be obtained from existing groundwater monitoring wells MW-1, MW-2 and MW-5. All samples will be analyzed forEPA Method 8260/8270. These monitoring wells will also be surveyed to determine groundwater flow direction." 3/29/10-Vought:Current file review by Vought:Letter from Sovereign to DEC Vought-10/12/09. Groundwater samples and survey data were collected in September 2009. Depth to water is 47-49'bg and flowing to the northeast. "...it was determined that the above mentioned 550-gallon waste oil UST was miss-reported and was found to be a 1,000-gallon waste oil UST." Vought checked PBS registration and registration was ammended to show closure of 1000-gallon waste oil UST.Spill Closure Follow Up (Sovereign-Kristen DeScenza-631-753-8380 Fax:631-753-8385)-2/8/10. Second closure request with data from above letter dated 10/12/09. Vought noted that with groundwater flow to the northwest that no groundwater sample had been collected downgradient of endpoint sample exceedence at sample D-7/D-8. Vought noted requirement of downgradient water sample collection and sent letter to Rob Rule with cc to DeScenza.DEC requires:1)Collection of groundwater sample downgradient from contaminated endpoint sample location D-7/D-8.6/11/10-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin and Vought transfer to Section A.8/3/10 - Raphael Ketani. I received the Sovereign Consulting, Inc. July 27, 2010 Spill Assessment Report and Closure Request. I reviewed the report. Boring B-1 was performed downgradient to D-7/D-8. The soil analyticals were completely non-detect and the groundwater analyticals were completely non-detect, except for two low level phthalate hits.There was no mention of removing the contaminated soil from the location of D7. I contacted Kristen DiScenza (631) 753-8380 regarding how much soil was removed and where the soil was removed. She told me that the contaminated soil that exceeded the RSCOs was removed from the area of the three 4,000 gal. USTs. She added that as part of the upgrade of the station, the 550 gal. waste oil UST was removed, along with the contaminated soil at AWO-3 and AWO-5. I asked her about the area of D-7. She said that the dispenser island was

**SHELL GAS (Continued)** **S103484030**

upgraded and the soil in the area of D-7 was removed.As the soil contamination has been removed, and as all of the parts of the fuel management system which had leaked gas have been removed, and as all of the tanks have been removed, and based upon the data in the reports submitted by Sovereign Consulting, I have determined that there is no threat to the public or the environment. Therefore, I am closing the spill case effective today.

Remarks: CALLER STATES THAT THEY ARE REMOVING 4000 GALLON UST AND NOTICED SOIL CONTAMINATION. CLEAN UP IS PENDING.

Material:

| | |
|---|---|
| Site ID: | 407220 |
| Operable Unit ID: | 1163773 |
| Operable Unit: | 01 |
| Material ID: | 2155115 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BC411** **SHELL OIL-S&D SERV STA INC** **RCRA NonGen / NLR** **1000140676**
**ENE** **112 ATLANTIC AVENUE** **FINDS** **NYD981483969**
**1/8-1/4** **BROOKLYN, NY 11201** **US AIRS**
**0.193 mi.**
**1021 ft.** **Site 4 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | S S PREMISES CO SHELL OIL CO |
| Facility address: | 112 ATLANTIC AVE<br>BROOKLYN, NY 11201 |
| EPA ID: | NYD981483969 |
| Mailing address: | JERICHO PLZ<br>JERICHO, NY 11753 |
| Contact: | JOHN SPINELLE |
| Contact address: | JERICHO PLZ<br>JERICHO, NY 11753 |
| Contact country: | US |
| Contact telephone: | (800) 431-5566 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | SHELL OIL CO |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |

**SHELL OIL-S&D SERV STA INC (Continued)** **1000140676**

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SHELL OIL CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: S S PREMISES CO SHELL OIL CO
Classification: Not a generator, verified

Date form received by agency: 04/28/1986
Facility name: S S PREMISES CO SHELL OIL CO
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110004404671

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the

**SHELL OIL-S&D SERV STA INC (Continued)** **1000140676**

estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110004404671 |
| Plant name: | SHELL OIL-S&D SERV STA INC |
| Plant address: | 112 ATLANTIC AVENUE<br>BROOKLYN, NY 11201 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 5541 |
| Sic code desc: | GASOLINE SERVICE STATIONS |
| North Am. industrial classf: | Not reported |
| NAIC code description: | Not reported |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1103 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1202 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1204 |
| Air prog code hist file: | SIP SOURCE |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |

**SHELL OIL-S&D SERV STA INC (Continued)** **1000140676**

Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

**BC412** **112 ATLANTIC AVENUE LLC** **NY AST** **A100300660**
**ENE** **112 ATLANTIC AVENUE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.193 mi.**
**1021 ft.** **Site 5 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-191051 |
| Program Type: | PBS |
| UTM X: | 585094.68565999996 |
| UTM Y: | 4505615.2396799996 |
| Expiration Date: | 2018/11/25 |
| Site Type: | Retail Gasoline Sales |

Affiliation Records:

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Facility Owner |
| Company Name: | THEODOROS ZORBAS |
| Contact Type: | PRESIDENT |
| Contact Name: | THEODOROS ZORBAS |
| Address1: | 199-07 32ND AVENUE |
| Address2: | Not reported |
| City: | FLUSHING |
| State: | NY |
| Zip Code: | 11358 |
| Country Code: | 001 |
| Phone: | (718) 762-3822 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 11/1/2013 |

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Mail Contact |
| Company Name: | SUPREME AUTO GROUP |
| Contact Type: | Not reported |
| Contact Name: | JOAN SAMAROO |
| Address1: | 199-07 32ND AVENUE |
| Address2: | Not reported |
| City: | FLUSHING |
| State: | NY |
| Zip Code: | 11358 |
| Country Code: | 001 |
| Phone: | (718) 762-4632 |
| EMail: | CANREALTY02@YAHOO.COM |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 11/1/2013 |

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THEODOROS ZORBAS |
| Contact Type: | Not reported |
| Contact Name: | SPIRO TRIANTAFILIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |

**112 ATLANTIC AVENUE LLC (Continued)** **A100300660**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 250-6235
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/24/2012

Site Id: 5934
Affiliation Type: On-Site Operator
Company Name: 112 ATLANTIC AVENUE LLC
Contact Type: Not reported
Contact Name: TONY PLATHWIAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 858-9517
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/24/2012

Tank Info:

Tank Number: 101
Tank Id: 215572
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/2003
Capacity Gallons: 240
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

**112 ATLANTIC AVENUE LLC (Continued)** **A100300660**

| | |
|---|---|
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | DMMOLOUG |
| Last Modified: | 11/01/2013 |
| Material Name: | Waste Oil/Used Oil |

---

**BC413** **EDR US Hist Auto Stat** **1015159937**
**ENE** **112 ATLANTIC AVE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.193 mi.**
**1021 ft.** **Site 6 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | COBBLEHILL SUPER SVC INC |
| Year: | 2010 |
| Address: | 112 ATLANTIC AVE |

---

**BC414** **ERNS** **2008891372**
**ENE** **112 ATLANTIC AVE.** **N/A**
**1/8-1/4** **BROOKLYN, NY 11210**
**0.193 mi.**
**1021 ft.** **Site 7 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

**BC415** **112 ATLANTIC AVENUE LLC** **NY UST** **U004076823**
**ENE** **112 ATLANTIC AVENUE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.193 mi.**
**1021 ft.** **Site 8 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-191051 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2018/11/25 |
| UTM X: | 585094.68565999996 |
| UTM Y: | 4505615.2396799996 |
| Site Type: | Retail Gasoline Sales |

Affiliation Records:

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Facility Owner |
| Company Name: | THEODOROS ZORBAS |
| Contact Type: | PRESIDENT |
| Contact Name: | THEODOROS ZORBAS |
| Address1: | 199-07 32ND AVENUE |
| Address2: | Not reported |
| City: | FLUSHING |
| State: | NY |
| Zip Code: | 11358 |
| Country Code: | 001 |
| Phone: | (718) 762-3822 |
| EMail: | Not reported |

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

| | |
|---|---|
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 11/1/2013 |

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Mail Contact |
| Company Name: | SUPREME AUTO GROUP |
| Contact Type: | Not reported |
| Contact Name: | JOAN SAMAROO |
| Address1: | 199-07 32ND AVENUE |
| Address2: | Not reported |
| City: | FLUSHING |
| State: | NY |
| Zip Code: | 11358 |
| Country Code: | 001 |
| Phone: | (718) 762-4632 |
| EMail: | CANREALTY02@YAHOO.COM |
| Fax Number: | Not reported |
| Modified By: | DMMOLOUG |
| Date Last Modified: | 11/1/2013 |

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | Emergency Contact |
| Company Name: | THEODOROS ZORBAS |
| Contact Type: | Not reported |
| Contact Name: | SPIRO TRIANTAFILIS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (516) 250-6235 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 8/24/2012 |

| | |
|---|---|
| Site Id: | 5934 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 112 ATLANTIC AVENUE LLC |
| Contact Type: | Not reported |
| Contact Name: | TONY PLATHWIAS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 858-9517 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 8/24/2012 |

Tank Info:

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 7380 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1970 |
| Date Tank Closed: | 12/03/2008 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 2712 |
| Common Name of Substance: | Gasoline/Ethanol |
| Tightness Test Method: | 21 |
| Date Test: | 08/19/2003 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 01/09/2009 |

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 7381 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 4000 |
| Install Date: | 12/01/1975 |
| Date Tank Closed: | 12/03/2008 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 2712 |
| Common Name of Substance: | Gasoline/Ethanol |
| Tightness Test Method: | 21 |
| Date Test: | 08/19/2003 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 01/09/2009 |

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off

Tank Number: 003
Tank ID: 7382
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1975
Date Tank Closed: 12/03/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 08/19/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/09/2009

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B07 - Tank External Protection - Retrofitted Sacrificial Anode
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 004
Tank ID: 7383
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1963
Date Tank Closed: 04/01/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: kxtang
Last Modified: 05/06/2004

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Tank Number: 005
Tank ID: 7384
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1963
Date Tank Closed: 04/22/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: cgfreedm
Last Modified: 05/11/2004

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 006
Tank ID: 226843
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 12/16/2008
Registered: True

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

| | |
|---|---|
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 01/06/2009 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Number: | 201 |
| Tank ID: | 227722 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 12000 |
| Install Date: | 04/20/2009 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 2712 |
| Common Name of Substance: | Gasoline/Ethanol |
| Tightness Test Method: | 00 |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | D |
| Modified By: | DMMOLOUG |
| Last Modified: | 11/01/2013 |

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser

| | |
|---|---|
| Tank Number: | 202A |
| Tank ID: | 227723 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 8000 |
| Install Date: | 04/20/2009 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 2712 |
| Common Name of Substance: | Gasoline/Ethanol |
| Tightness Test Method: | 00 |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | D |
| Modified By: | DMMOLOUG |
| Last Modified: | 11/01/2013 |

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass

| | |
|---|---|
| Tank Number: | 202B |
| Tank ID: | 227724 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 4000 |
| Install Date: | 04/20/2009 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Equivalent technology |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 00 |
| Date Test: | Not reported |

**112 ATLANTIC AVENUE LLC (Continued)** **U004076823**

Next Test Date: Not reported
Pipe Model: D
Modified By: DMMOLOUG
Last Modified: 11/01/2013

Equipment Records:

I03 - Overfill - Automatic Shut-Off
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

---

**AY416** **43 GARDEN PL** **NY LTANKS** **S102671766**
**NE** **43 GARDEN PL** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.194 mi.**
**1024 ft.** **Site 4 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 268474 |
| Spill Number/Closed Date: | 9108876 / 11/18/1994 |
| Spill Date: | 11/19/1991 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | 11/18/1994 |
| Cleanup Meets Standard: | True |
| SWIS: | 2401 |
| Investigator: | SIGONA |
| Referred To: | Not reported |
| Reported to Dept: | 11/19/1991 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/25/1991 |
| Spill Record Last Update: | 11/18/1994 |
| Spiller Name: | Not reported |
| Spiller Company: | PETRO HEAT & POWER |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |

**43 GARDEN PL (Continued)** **S102671766**

DEC Region: 2
DER Facility ID: 218705
DEC Memo: Not reported
Remarks: SPEEDY DRY APPLIED

Material:
Site ID: 268474
Operable Unit ID: 959065
Operable Unit: 01
Material ID: 417543
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AS417** **ROCKAWAY BEACH** **NY Spills** **S104193496**
**ENE** **116TH ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.195 mi.**
**1029 ft.** **Site 3 of 4 in cluster AS**

**Relative:**
**Higher**

**Actual:**
**53 ft.**

SPILLS:
Facility ID: 9905248
Facility Type: ER
DER Facility ID: 91644
Site ID: 103647
DEC Region: 2
Spill Date: 8/1/1999
Spill Number/Closed Date: 9905248 / 8/27/1999
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: SACCACIO
Referred To: Not reported
Reported to Dept: 8/1/1999
CID: 390
Water Affected: ATLANTIC OCEAN
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/1/1999
Spill Record Last Update: 8/27/1999
Spiller Name: UNKNOWN

**ROCKAWAY BEACH (Continued)** **S104193496**

| | |
|---|---|
| Spiller Company: | UNKNOWN |
| Spiller Address: | UNKNOWN |
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | OFFICER RODRIGUEZ |
| Contact Phone: | (718) 318-4200 |
| DEC Memo: | Not reported |
| Remarks: | SHEEN NOTICED IN THE WATER - UNK CLEAN UP |

Material:

| | |
|---|---|
| Site ID: | 103647 |
| Operable Unit ID: | 1079681 |
| Operable Unit: | 01 |
| Material ID: | 301552 |
| Material Code: | 0009 |
| Material Name: | Gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

| | |
|---|---|
| Facility ID: | 0107483 |
| Facility Type: | ER |
| DER Facility ID: | 231536 |
| Site ID: | 285540 |
| DEC Region: | 2 |
| Spill Date: | 1/20/2001 |
| Spill Number/Closed Date: | 0107483 / 2/13/2003 |
| Spill Cause: | Housekeeping |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 4101 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 10/22/2001 |
| CID: | 270 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/22/2001 |
| Spill Record Last Update: | 2/13/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | ROCKAWAY BEACH DINER |
| Spiller Address: | 116TH ST |
| Spiller City,St,Zip: | ROCKAWAY BEACH, NY |

**ROCKAWAY BEACH (Continued)** **S104193496**

Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"ADMINISTRATIVE CLOSURE - AUSTIN
Remarks: caller states that material is coming from trash compactor

Material:
Site ID: 285540
Operable Unit ID: 844569
Operable Unit: 01
Material ID: 532300
Material Code: 0046A
Material Name: COOKING GREASE
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**AZ418** **LI'S DRY CLEANER** **FINDS** **1007086427**
**SSE** **500 HENRY ST** **US AIRS** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.195 mi.**
**1030 ft.** **Site 2 of 5 in cluster AZ**

**Relative: Higher**

**Actual: 36 ft.**

FINDS:

Registry ID: 110015655254

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIRS (AFS):

Airs Minor Details:
EPA plant ID: 110015655254
Plant name: LI'S DRY CLEANER
Plant address: 500 HENRY ST
BROOKLYN, NY 11231
County: KINGS

**LI'S DRY CLEANER (Continued)** **1007086427**

| | |
|---|---|
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 7212 |
| Sic code desc: | Not reported |
| North Am. industrial classf: | 812320 |
| NAIC code description: | Drycleaning and Laundry Services (except Coin-Operated) |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

| | |
|---|---|
| Air program: | Not reported |
| National action type: | Not reported |
| Date achieved: | Not reported |
| Penalty amount: | Not reported |

Historical Compliance Minor Sources:

| | |
|---|---|
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1101 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1104 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1202 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1301 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1303 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1004 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1102 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1103 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |
| State compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Hist compliance date: | 1201 |
| Air prog code hist file: | MACT (SECTION 63 NESHAPS) |

**LI'S DRY CLEANER (Continued)** **1007086427**

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

Compliance & Violation Data by Minor Sources:
Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**AZ419** **VAULT #3598** **NY Spills** **S104880758**
**SSE** **SACKETT ST & HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.197 mi.**
**1038 ft.** **Site 3 of 5 in cluster AZ**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

SPILLS:
Facility ID: 0009860
Facility Type: ER
DER Facility ID: 130742
Site ID: 154157
DEC Region: 2
Spill Date: 11/30/2000
Spill Number/Closed Date: 0009860 / 1/18/2001
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 11/30/2000
CID: 390
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/30/2000
Spill Record Last Update: 4/11/2001
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN
Spiller Address: UNKNOWN

**VAULT #3598 (Continued)** **S104880758**

| | |
|---|---|
| Spiller City,St,Zip: | UNKNOWN, NY |
| Spiller Company: | 999 |
| Contact Name: | ANTHONY NATALE |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY"e2mis Notes:Approx 1 pint of unknown oil on 400gal water found in VS3598. Unit was pressure tested and held OK. Records show 1ppm PCB. Sample taken and returned <1ppm. Flush reports cleanup completed by double washing with slix. Liquids removed by tanker and solids by vactor. No leaking equipment was found. Sump was cemented 12/1/00.KMF 4/11/01 |
| Remarks: | 1 pt unk oil spilled on 400 gals of water - sample taken clean up pending lab resultscon ed #134557 |

Material:

| | |
|---|---|
| Site ID: | 154157 |
| Operable Unit ID: | 832035 |
| Operable Unit: | 01 |
| Material ID: | 555730 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AZ420** **CORNER OF** **NY Spills** **S109826643**
**SSE** **SACKETT ST AND HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.197 mi.**
**1038 ft.** **Site 4 of 5 in cluster AZ**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0903068 |
| Facility Type: | ER |
| DER Facility ID: | 364272 |
| Site ID: | 415147 |
| DEC Region: | 2 |
| Spill Date: | 6/15/2009 |
| Spill Number/Closed Date: | 0903068 / 8/5/2009 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | Con Ed Unassigned |
| Referred To: | Not reported |
| Reported to Dept: | 6/15/2009 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |

**CORNER OF (Continued)** **S109826643**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/15/2009 |
| Spill Record Last Update: | 8/5/2009 |
| Spiller Name: | ERT |
| Spiller Company: | UNKNOWN |
| Spiller Address: | SACKETT ST AND HENRY ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 08/05/09 - See eDocs for Con Ed report detailing cleanup and closure. |
| Remarks: | Clean up is pending at this time. Structure #63160. Report if release to soil. |

Material:

| | |
|---|---|
| Site ID: | 415147 |
| Operable Unit ID: | 1171506 |
| Operable Unit: | 01 |
| Material ID: | 2163315 |
| Material Code: | 0064A |
| Material Name: | UNKNOWN MATERIAL |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0.25 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AY421** **36 GARDEN PLACE** **NY LTANKS** **S102672967**
**NE** **36 GARDEN PLACE** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.198 mi.**
**1047 ft.** **Site 5 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 118736 |
| Spill Number/Closed Date: | 9504733 / 7/19/1995 |
| Spill Date: | 7/19/1995 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | 7/19/1995 |
| Cleanup Meets Standard: | True |
| SWIS: | 2401 |
| Investigator: | JMKRIMGO |
| Referred To: | Not reported |
| Reported to Dept: | 7/19/1995 |
| CID: | Not reported |
| Water Affected: | Not reported |

**36 GARDEN PLACE (Continued)** **S102672967**

| | |
|---|---|
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 8/2/1995 |
| Spill Record Last Update: | 9/30/2004 |
| Spiller Name: | Not reported |
| Spiller Company: | BAERENKLAU OIL |
| Spiller Address: | 740 JAMAICA AVENUE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 103177 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD" |
| Remarks: | ACCIDENTAL OVERFILL - CONCRETE BASEMENT FLOOR - CLEANED UP |

Material:

| | |
|---|---|
| Site ID: | 118736 |
| Operable Unit ID: | 1015656 |
| Operable Unit: | 01 |
| Material ID: | 561376 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AS422** **EDR US Hist Cleaners** **1015038370**
**ENE** **303 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.199 mi.**
**1053 ft.** **Site 4 of 4 in cluster AS**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | HEIGHTS CLEANERS |
| Year: | 2002 |
| Address: | 303 HENRY ST |
| Name: | HEIGHTS CLEANERS |
| Year: | 2010 |
| Address: | 303 HENRY ST |

**AY423** **APARTMENT BLDG** **NY LTANKS** **S102662883**
**NE** **262 HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.200 mi.**
**1055 ft.** **Site 6 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 186206 |
| Spill Number/Closed Date: | 9614314 / 12/31/1997 |
| Spill Date: | 3/10/1997 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | MMMULQUE |
| Referred To: | Not reported |
| Reported to Dept: | 3/10/1997 |
| CID: | 297 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/10/1997 |
| Spill Record Last Update: | 1/6/1998 |
| Spiller Name: | MR BERRY |
| Spiller Company: | ADVANCED MANAGEMENT SERV |
| Spiller Address: | 157 RAMANSEN AV |
| Spiller City,St,Zip: | BROOKLYN, NY 11201- |
| Spiller County: | 001 |
| Spiller Contact: | ADVANCED MANAGEMENT SERV |
| Spiller Phone: | (718) 243-1257 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 155681 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN" |
| Remarks: | CALLERS DRIVER STATES HE DID NOT OVERFILL TANK BUT THERE WAS 4-5 GALLONS IN THE BASEMENT AFTER THAY FILLED THE TANK |

Material:

| | |
|---|---|
| Site ID: | 186206 |
| Operable Unit ID: | 1041781 |
| Operable Unit: | 01 |
| Material ID: | 339418 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

**APARTMENT BLDG (Continued)** **S102662883**

Tank Test:

---

**BD424** **SPILL NUMBER 0303652** **NY Spills** **S106015836**
**SW** **IMLAY ST & VERONA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.200 mi.**
**1056 ft.** **Site 2 of 3 in cluster BD**

**Relative:**
**Lower**

**Actual:**
**3 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0303652 |
| Facility Type: | ER |
| DER Facility ID: | 152408 |
| Site ID: | 181760 |
| DEC Region: | 2 |
| Spill Date: | 7/7/2003 |
| Spill Number/Closed Date: | 0303652 / 8/19/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SKARAKHA |
| Referred To: | Not reported |
| Reported to Dept: | 7/8/2003 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 7/8/2003 |
| Spill Record Last Update: | 8/19/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY 10003 |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Con Ed e2mis #149116:7/7/03 - 0815C. MCCONNELL - 29670 - #9, WHILE RESPONDING TO A SMOKING SB, FOUND APPROX 2 QTS OF AN UNKNOWN OIL ON TOP OF APPROX 10 GALSOF WATER IN SB58038. SPILL IS CONTAINED. NO FIRE, SOME SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO SEWER CONNECTIONS. NO SUMPS. NO LARGE CRACKS IN THE STRUCTURE. MR. MCCONNELL DOES NOT HAVE A SPILL KIT OR CHAIN OF CUSTODY. AN ENV OPS CREW WAS SENT TO DELIVER THEM TO HIM. SAMPLE WILL BE TAKEN AND FORM WILL BE FILLED OUT UPON ARRIVAL.UPDATE: 7/7/03 - 0935N. MCCONNELL REPORTS PCB SAMPLE TAKEN AND CHAIN OF CUSTODY FORM # DD00441 FILLED OUT AND MARKED 'E' (WITHIN 8 HRS) PRIORITY. CLEANUP PENDING LAB RESULT.UPDATE - 07-JUL-2003 20:39 HRS.. LSN# 03-05609, MATRIX: OIL, GRAB. TOTAL PCB: <1.0 PPM.UPDATE: 7/8/03 - 1120E. TRINIDAD - ENV. OPS., REPORTS MEET WITH #9, # 9 CORRECTED CONDITION. THE STRUCTURE WAS DOUBLE WASHED WITH SLIX. |

**SPILL NUMBER 0303652 (Continued)** **S106015836**

Remarks: SERVICE BOX 58038. 2 QUARTS UNKNOWN OIL ON 10 GALLONS OF WATER. CONTAINED WITHIN SERVICE BOX. SAMPLES WERE TAKEN. TEST RESULTS INDICATE LESS THAN 1 PPM OF PCB'S. CLEAN UP WAS STARTED, BUT COULDB'T BE FINISHED BECAUSE OF MANHOLE FIRE AT THE SAME LOCATION. CON EDISON REFERENCE NUMBER 149116.

Material:

| | |
|---|---|
| Site ID: | 181760 |
| Operable Unit ID: | 870758 |
| Operable Unit: | 01 |
| Material ID: | 504518 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BF425** **NYNEX** **NY MANIFEST** **1009234524**
**South** **COLUMBIA ST & COLES ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.202 mi.**
**1064 ft.** **Site 1 of 7 in cluster BF**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000932103 |
| Country: | USA |
| Mailing Name: | NYNEX |
| Mailing Contact: | V ORCHIER |
| Mailing Address: | 2221 EAST 37TH STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10016 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-338-7126 |

| | |
|---|---|
| Document ID: | MIA4512990 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | Not reported |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 961120 |
| Trans1 Recv Date: | 961120 |
| Trans2 Recv Date: | 961122 |
| TSD Site Recv Date: | 961204 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 961231 |
| Generator EPA ID: | NYP000932103 |
| Trans1 EPA ID: | NYD010951986 |
| Trans2 EPA ID: | NYD046765574 |

**NYNEX (Continued)** **1009234524**

| | |
|---|---|
| TSDF ID: | MID096963194 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 00800 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 96 |

---

**BC426** **LONG ISLAND COLLEGE HOSPITAL** **NY MANIFEST** **1009232455**
**ENE** **112 PACIFIC ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.203 mi.**
**1070 ft.** **Site 9 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**44 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP000872374 |
| Country: | USA |
| Mailing Name: | LONG ISLAND COLLEGE HOSPITAL |
| Mailing Contact: | LONG ISLAND COLLEGE HOSPITAL |
| Mailing Address: | 112 PACIFIC STREET |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-780-1762 |

| | |
|---|---|
| Document ID: | NYA6254163 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 871028 |
| Trans1 Recv Date: | 871028 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 871028 |
| Part A Recv Date: | 871030 |
| Part B Recv Date: | 871104 |
| Generator EPA ID: | NYP000872374 |
| Trans1 EPA ID: | NYD049178296 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049178296 |
| Waste Code: | D009 - MERCURY 0.2 MG/L TCLP |
| Quantity: | 00400 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 87 |

| | |
|---|---|
| Document ID: | NYA6254046 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NY73819-G |

**LONG ISLAND COLLEGE HOSPITAL (Continued)** **1009232455**

| | |
|---|---|
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 871019 |
| Trans1 Recv Date: | 871019 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 871019 |
| Part A Recv Date: | 871027 |
| Part B Recv Date: | 871030 |
| Generator EPA ID: | NYP000872374 |
| Trans1 EPA ID: | NYD049178296 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049178296 |
| Waste Code: | D009 - MERCURY 0.2 MG/L TCLP |
| Quantity: | 00900 |
| Units: | P - Pounds |
| Number of Containers: | 009 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 100 |
| Year: | 87 |

---

**AY427** **TM 170** **NY Spills** **S106383759**
**NE** **JORALEMON ST E/0 HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.203 mi.**
**1072 ft.** **Site 7 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0313672 |
| Facility Type: | ER |
| DER Facility ID: | 255580 |
| Site ID: | 317046 |
| DEC Region: | 2 |
| Spill Date: | 3/13/2004 |
| Spill Number/Closed Date: | 0313672 / 6/9/2004 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 3/13/2004 |
| CID: | 74 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/13/2004 |
| Spill Record Last Update: | 6/9/2004 |
| Spiller Name: | ERT DESK |
| Spiller Company: | CON EDISON |
| Spiller Address: | 4 IRVING PLACE |
| Spiller City,St,Zip: | NEW YORK, NY |
| Spiller Company: | 001 |

**TM 170 (Continued)** **S106383759**

Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Chris Sawyer responded on off-hour shift. (JHO)~~~~~~~~~~~~~~~~~~~~~e2mis no. 152485:#9 reports while responding to emergency call from Fire Dept found TM170 cracked open on top of unit in structure. Upon his arrival the fire dept was not on location nor was there any signs of smoke or fire involved. Cannot determine how much oil spilled if any into the structure due to the amount of suds/foam sprayed by Fire Dept into Structure. Will get a closer estimate/look when fdr 1B66 is deenergized. Historical records indicate pcb to be 0 ppm dated 10/3/2000. Checked mh records which indicates structure is sewered dated 1929.0730 hrs Estimating there is 300 gallons of oil in unit. Estimating there is 75 gallons to 100 gallons in structure. Cannot access structure until fdr is deenergized and made safe to confirm mfr tag. Volumes will be finalized when access to structure.Lab Sequence Number: 04-01948-001Aroclor 120 < 1.0 ppmENV. OPE., REPORTS OIL & FOAM REMOVED FROM STRUCTURE BY CLEAN HARBORS. FOAM ON STREET CLEANED BY ENV OPS USING BIOGEN 760 (WE WERE TOLD BY FIRE DEPT THAT IT WAS CHICKEN BASED AND , THERFORE, NON-HAZARDOUS. VEHICLES WERE CLEANED BY ENV OPS USING A CAR WASH LIQUID. STRUCTURE DOUBLE W0. NO SUMPS OR DRAINS IN STRUCTURE. TRANSFORMER IS PRESENTLY BEING DRAINED BY B.Q.E. CREW AND ASTORIA TANKER. TAG RENAINS PENDING REMOVAL OF TRANSFORMER.The transformer was manufactured by GE. As per the incident report and field observation the manufacture?s plate on the transformer was illegible in order to read the total oil capacity of the transformer. The transformers oil was drained and 300 gallons of oil was removed. As per the Equipment Group?s records, the transformer should have an oil capacity of 290 gallons. There is a good possibility that the transformer was over filled or the spill amount was less.ENVIR OPPS REPORTS CLEANUP COMPLETED. DOULBED WASHED STRUCTURE USING BIO-GEN 760. REMOVED ALL LIQUID AND DEBRIS. FOUND NO SUMP. PER FDR REP T. REUTH THE TRANSFORMER WAS REMOVED.
Remarks: TM 170 (transformer) caught on fire. fire department sprayed foam on it to extinguish fire. Spill contained within the transformer vault. Historical records for the PCB count is 0. 730 hours called with update 100 gallons of transformer oil .elliot**No sewer connection from vault to sewer, per Ron Elliot, updated**

Material:
Site ID: 317046
Operable Unit ID: 878807
Operable Unit: 01
Material ID: 495269
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**AY428**
**NE**
**1/8-1/4**
**0.203 mi.**
**1073 ft.**

**CON EDISON**
**HICKS ST & JORALEMAN ST**
**BROOKLYN, NY 11201**

**Site 8 of 14 in cluster AY**

**NY MANIFEST** **S113495020**
**N/A**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004287165 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05-Feb-2013 00:00:00 |
| Trans1 Recv Date: | 05-Feb-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004287165 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002015985GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**CON EDISON (Continued)** **S113495020**

| | |
|---|---|
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05-Feb-2013 00:00:00 |
| Trans1 Recv Date: | 05-Feb-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004287165 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002015985GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-02-05 |
| Trans1 Recv Date: | 2013-02-05 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-02-07 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004287165 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002015985GBF |

**CON EDISON (Continued)** **S113495020**

| | |
|---|---|
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**BF429** **EDR US Hist Auto Stat** **1015448014**
**South** **360 COLUMBIA ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.204 mi.**
**1076 ft.** **Site 2 of 7 in cluster BF**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | NAYAGUEZ CAR SERVICE LLC |
| Year: | 2005 |
| Address: | 360 COLUMBIA ST |

---

**AY430** **CON EDISON MANHOLE: 1718** **RCRA-CESQG** **1016150045**
**NE** **HICKS ST & JORALEMON ST COR OF** **NYP004287165**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.204 mi.**
**1076 ft.** **Site 9 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 02/05/2013 |
| Facility name: | CON EDISON MANHOLE: 1718 |
| Facility address: | HICKS ST & JORALEMON ST COR OF<br>BROOKLYN, NY 11201 |
| EPA ID: | NYP004287165 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | KHARY BERRY |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 666-4574 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of |

**CON EDISON MANHOLE: 1718 (Continued)** **1016150045**

any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

---

**BG431** **OPPOSITE 253 VAN BRUNT ST** **NY Spills** **S102239987**
**SSW** **OPPOSITE 253 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.205 mi.**
**1085 ft.** **Site 1 of 5 in cluster BG**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9602193 |
| Facility Type: | ER |
| DER Facility ID: | 158062 |
| Site ID: | 189331 |
| DEC Region: | 2 |
| Spill Date: | 5/15/1996 |
| Spill Number/Closed Date: | 9602193 / 5/16/1996 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | O'DOWD |
| Referred To: | Not reported |
| Reported to Dept: | 5/15/1996 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 5/15/1996 |
| Spill Record Last Update: | 12/31/2002 |
| Spiller Name: | Not reported |

**OPPOSITE 253 VAN BRUNT ST (Continued)** **S102239987**

Spiller Company: MENTIC BUS COMPANY
Spiller Address: UNKNOWN
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: JULIE BOBB
Contact Phone: (718) 595-6777
DEC Memo: Not reported
Remarks: 15 ABANDONED DRUMS ON THE SIDEWALK

Material:
Site ID: 189331
Operable Unit ID: 1029689
Operable Unit: 01
Material ID: 351995
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**BC432** **HENRY GREEN CLEANERS** **FINDS** **1015760638**
**ENE** **113 PACIFIC STREET** **US AIRS** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.206 mi.**
**1090 ft.** **Site 10 of 13 in cluster BC**

**Relative: Higher**

**Actual: 44 ft.**

FINDS:

Registry ID: 110012710762

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIRS (AFS):

Airs Minor Details:
EPA plant ID: 110012710762
Plant name: HENRY GREEN CLEANERS
Plant address: 113 PACIFIC STREET

**HENRY GREEN CLEANERS (Continued)** **1015760638**

BROOKLYN, NY 11231
County: KINGS
Region code: 02
Dunn & Bradst #: Not reported
Air quality cntrl region: 043
Sic code: 7212
Sic code desc: Not reported
North Am. industrial classf: 812320
NAIC code description: Drycleaning and Laundry Services (except Coin-Operated)
Default compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV: Not reported

Compliance and Enforcement Major Issues:
Air program: Not reported
National action type: Not reported
Date achieved: Not reported
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

**HENRY GREEN CLEANERS (Continued)** **1015760638**

Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

Compliance & Violation Data by Minor Sources:
Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**BC433** **EDR US Hist Cleaners** **1014977098**
**ENE** **113 PACIFIC ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.206 mi.**
**1090 ft.** **Site 11 of 13 in cluster BC**

**Relative: Higher**
**Actual: 44 ft.**

EDR Historical Cleaners:
Name: HENLY GREEN CLEANERS
Year: 2005
Address: 113 PACIFIC ST

Name: HENLY GREEN CLEANERS
Year: 2007
Address: 113 PACIFIC ST

Name: HENLY GREEN CLEANERS
Year: 2008
Address: 113 PACIFIC ST

---

**BF434** **EDR US Hist Auto Stat** **1015218451**
**South** **14 COLES ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.207 mi.**
**1095 ft.** **Site 3 of 7 in cluster BF**

**Relative: Higher**
**Actual: 14 ft.**

EDR Historical Auto Stations:
Name: COLLISIONVILLE INC
Year: 2003
Address: 14 COLES ST

Name: COLLISIONVILLE INC
Year: 2004

**(Continued)** **1015218451**

Address: 14 COLES ST

Name: COLLISIONVILLE INC
Year: 2006
Address: 14 COLES ST

Name: COLLISIONVILLE INC
Year: 2007
Address: 14 COLES ST

Name: COLLISIONVILLE INC
Year: 2011
Address: 14 COLES ST

Name: COLLISIONVILLE INC
Year: 2012
Address: 14 COLES ST

---

**BD435** **EDR US Hist Auto Stat** **1015384402**
**SSW** **278 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.208 mi.**
**1096 ft.** **Site 3 of 3 in cluster BD**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

EDR Historical Auto Stations:
Name: 1811 AUTO REPAIR
Year: 2010
Address: 278 VAN BRUNT ST

Name: 1811 AUTO REPAIR
Year: 2011
Address: 278 VAN BRUNT ST

Name: 1811 AUTO REPAIR
Year: 2012
Address: 278 VAN BRUNT ST

---

**BH436** **DRUM RUN** **NY Spills** **S107408978**
**South** **61 RAPELYE ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.210 mi.**
**1110 ft.** **Site 1 of 2 in cluster BH**

**Relative:**
**Higher**

**Actual:**
**21 ft.**

SPILLS:
Facility ID: 0507279
Facility Type: ER
DER Facility ID: 299958
Site ID: 352660
DEC Region: 2
Spill Date: 9/16/2005
Spill Number/Closed Date: 0507279 / 9/29/2005
Spill Cause: Abandoned Drums
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS: 2401
Investigator: SFRAHMAN

**DRUM RUN (Continued)** **S107408978**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 9/16/2005 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 9/16/2005 |
| Spill Record Last Update: | 9/29/2005 |
| Spiller Name: | MAHENDAR RAMNARINE |
| Spiller Company: | HAMILTON AVE/HICKS AVE ON |
| Spiller Address: | RAFFELLE AVE |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | MAHENDAR RAMNARINE |
| Contact Phone: | (718) 595-4784 |
| DEC Memo: | 9/16/05 - Austin - Rec'd phone call from Brooklyn Comm. Bd. #6 (Leroy Branch, 718-643-3027, ext 204), indicating that two drums are in an abandoned white van, along with construction debris. Requested drum removal, so that NYCDOS can tow van away. Unable to contact Mr. Branch directly. - end09.29.05 SR// No drums found. |
| Remarks: | THESE TWO DRUMS ARE IN A BOX TRUCK AND THEY WILL PUT DEC # ON THE TRUCK(WHITE FORD TRUCK): CAN YOU CALL WHEN THEY ARE PICKED UP: |

Material:

| | |
|---|---|
| Site ID: | 352660 |
| Operable Unit ID: | 1110150 |
| Operable Unit: | 01 |
| Material ID: | 2100166 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BI437** **NICOBROS INC DBA J&E SERVICE** **NY UST U000405663**
**South** **640 HICKS STREET** **NY Spills N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.211 mi.**
**1115 ft.** **Site 1 of 4 in cluster BI**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-407097 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Expiration Date: | 2017/10/15 |
| UTM X: | 584245.66136000003 |
| UTM Y: | 4503765.2735400004 |
| Site Type: | Retail Gasoline Sales |

Affiliation Records:

| | |
|---|---|
| Site Id: | 19692 |
| Affiliation Type: | Mail Contact |
| Company Name: | NICOBROS DBA J&E SERVICE STA. |
| Contact Type: | Not reported |
| Contact Name: | EDDY NICOLI |
| Address1: | 640 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 625-3848 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 19692 |
| Affiliation Type: | Emergency Contact |
| Company Name: | JIMMY & EDDY NICOLI |
| Contact Type: | Not reported |
| Contact Name: | NAT NICOLI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 748-3978 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 9/4/2007 |

| | |
|---|---|
| Site Id: | 19692 |
| Affiliation Type: | On-Site Operator |
| Company Name: | NICOBROS INC DBA J&E SERVICE |
| Contact Type: | Not reported |
| Contact Name: | EDDY NICOLI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 625-3848 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 11/19/2008 |

| | |
|---|---|
| Site Id: | 19692 |

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Affiliation Type: | Facility Owner |
| Company Name: | EDDY NICOLI |
| Contact Type: | PRES |
| Contact Name: | EDDY NICOLI |
| Address1: | 640 HICKS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 625-3848 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 11/15/2012 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 23225 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 002 |
| Tank ID: | 23226 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Number: 003
Tank ID: 23227
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
B00 - Tank External Protection - None

Tank Number: 004

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Tank ID: | 23228 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

B00 - Tank External Protection - None
H99 - Tank Leak Detection - Other
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None

| | |
|---|---|
| Tank Number: | 005 |
| Tank ID: | 23229 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 006 |
| Tank ID: | 23230 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 007 |
| Tank ID: | 23231 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

B00 - Tank External Protection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 008
Tank ID: 23232
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Number: 009
Tank ID: 23233
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Number: 010
Tank ID: 23234
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Number: 011
Tank ID: 23235
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: dxliving
Last Modified: 10/29/2007

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 23236
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1970
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

Tank Number: 013
Tank ID: 23237
Tank Status: Closed - Removed

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Material Name: | Closed - Removed |
| Capacity Gallons: | 4000 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 01/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | 03 |
| Date Test: | 11/01/1997 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 014 |
| Tank ID: | 23238 |
| Tank Status: | Administratively Closed |
| Material Name: | Administratively Closed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0022 |
| Common Name of Substance: | Waste Oil/Used Oil |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | dxliving |
| Last Modified: | 10/29/2007 |

Equipment Records:

I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 015 |
| Tank ID: | 23239 |
| Tank Status: | Closed - Removed |
| Material Name: | Closed - Removed |
| Capacity Gallons: | 550 |
| Install Date: | 05/01/1970 |
| Date Tank Closed: | 02/01/1999 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | dxliving |
| Last Modified: | 10/29/2007 |

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H99 - Tank Leak Detection - Other
I00 - Overfill - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Number: | 101 |
| Tank ID: | 56543 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 8000 |
| Install Date: | 02/01/1999 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Fiberglass coated steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/15/2012 |

Equipment Records:

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

| | |
|---|---|
| Tank Number: | 102 |
| Tank ID: | 56544 |
| Tank Status: | In Service |
| Material Name: | In Service |
| Capacity Gallons: | 8000 |
| Install Date: | 02/01/1999 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Fiberglass coated steel |
| Material Code: | 0009 |
| Common Name of Substance: | Gasoline |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/15/2012 |

Equipment Records:

C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser

| | |
|---|---|
| Tank Number: | 103 |
| Tank ID: | 56545 |
| Tank Status: | In Service |

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Material Name: | In Service |
| Capacity Gallons: | 8000 |
| Install Date: | 02/01/1999 |
| Date Tank Closed: | Not reported |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Fiberglass coated steel |
| Material Code: | 0008 |
| Common Name of Substance: | Diesel |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | MSBAPTIS |
| Last Modified: | 11/15/2012 |

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser

SPILLS:

| | |
|---|---|
| Facility ID: | 0808610 |
| Facility Type: | ER |
| DER Facility ID: | 19662 |
| Site ID: | 406009 |
| DEC Region: | 2 |
| Spill Date: | 10/30/2008 |
| Spill Number/Closed Date: | 0808610 / 6/15/2012 |
| Spill Cause: | Other |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | HRPATEL |
| Referred To: | Not reported |
| Reported to Dept: | 10/30/2008 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Gasoline Station |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |

**NICOBROS INC DBA J&E SERVICE (Continued)** **U000405663**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/30/2008 |
| Spill Record Last Update: | 6/15/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | EQUIPMENT |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | EDDY |
| Contact Phone: | Not reported |
| DEC Memo: | 10/31/2008-HRAHMED-OFF HOURS RESPONDER-Called Eddy Nicoli (718 625 3848) of Nico Brothers. This site is a Gulf Gas Station. As per him 1 gallon of diesel spilled in the sump due to overfill. They hired Americal Resources to cleanup the sump. Ahmed talked to DEC Moses, as per Moses he inspected the site on 10/30/08 and noticed unreported 1 gallon of diesel spilled in the sump. He instructed Eddy to report that spill to DEC Hotline. As per Moses the spill happened due to pipe leak or failure. Ahmed would inform Moses after they cleanup the spill.10/31/11-Hiralkumar Patel. case transferred from DEC Hasan to DEC Patel.06/13/12-Hiralkumar Patel.alternate address: 69-81 Rapelye Street, 48 Woodhull Streetno other spills found.PBS #: 2-407097. as per PBS record, site has/had following tanks:- two 8,000 gal gasoline USTs, in-serive- one 8,000 gal diesel UST, in-service- twelve 550 gal gasoline USTs removed in Jan. 1999- one 4,000 gal diesel UST removed in Jan. 1999- one 550 gal #2 oil UST removed in Feb. 1999- one 550 gal waste oil tank adminstratively closedEddy Nicoli **property owner**640 Hicks StreetBrooklyn, NY 11231Ph. (718) 625-3848 (718) 748-397806/15/12-Hiralkumar Patel. spoke with DEC Moses. he mentioned that little oil was found in fill box and was cleaned up. based on observations during inspection, he suggested to close the case.case closed. |
| Remarks: | Eddy reported thet he thinks that the diesal may have got in to the sump during a fill up 10-27-08. He doesn't see any leaks. They have also put in call to American Resourses to clean up the diesal out of sump. They are coming sometime tomorrow. |

Material:

| | |
|---|---|
| Site ID: | 406009 |
| Operable Unit ID: | 1162621 |
| Operable Unit: | 01 |
| Material ID: | 2153901 |
| Material Code: | 0008 |
| Material Name: | Diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**BI438**
**South**
**1/8-1/4**
**0.211 mi.**
**1115 ft.**

**640 HICKS ST**
**BROOKLYN, NY 11231**

**Site 2 of 4 in cluster BI**

**EDR US Hist Auto Stat** **1015587180**
**N/A**

**Relative:**
**Higher**

**Actual:**
**26 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | J & E SVCE STATION |
| Year: | 1999 |
| Address: | 640 HICKS ST |
| Name: | J & E SVCE STATION |
| Year: | 2000 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2001 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2002 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2003 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2004 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2007 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2008 |
| Address: | 640 HICKS ST |
| Name: | J & E SERVICE STATION |
| Year: | 2009 |
| Address: | 640 HICKS ST |
| Name: | J & E SVC STATION |
| Year: | 2010 |
| Address: | 640 HICKS ST |

---

**AX439**
**SSW**
**1/8-1/4**
**0.211 mi.**
**1116 ft.**

**74 VERONA ST**
**BROOKLYN, NY 11231**

**Site 2 of 2 in cluster AX**

**EDR US Hist Auto Stat** **1015621750**
**N/A**

**Relative:**
**Higher**

**Actual:**
**7 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | BROOKLYN MOTOR WORKS |
| Year: | 2012 |
| Address: | 74 VERONA ST |

**BJ440** **2 GRACE OWNERS INC.** **NY AST** **U003387604**
**NNE** **2 GRACE COURT** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.212 mi.**
**1120 ft.** **Site 1 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-092185 |
| Program Type: | PBS |
| UTM X: | 584636.52477999998 |
| UTM Y: | 4505298.5994199999 |
| Expiration Date: | 2017/07/10 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 2359 |
| Affiliation Type: | Facility Owner |
| Company Name: | 2 GRACE OWNERS INC. |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 2 GRACE COURT |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (212) 557-3600 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 4/18/2013 |

| | |
|---|---|
| Site Id: | 2359 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 2 GRACE OWNERS INC. |
| Contact Type: | Not reported |
| Contact Name: | ADRIAN MORINA |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (917) 373-9920 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 4/18/2013 |

| | |
|---|---|
| Site Id: | 2359 |
| Affiliation Type: | Emergency Contact |
| Company Name: | 2 GRACE OWNERS INC. |
| Contact Type: | Not reported |
| Contact Name: | JANICE KELLER-MCDOWALL |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |

**2 GRACE OWNERS INC. (Continued)** **U003387604**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 557-3600
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/18/2013

Site Id: 2359
Affiliation Type: Mail Contact
Company Name: TUDOR REALTY SERVICES CORP.
Contact Type: Not reported
Contact Name: ANTHONY COLELLA
Address1: 250 PARK AVENUE SOUTH
Address2: 4TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 557-3600
EMail: JULIEC@TUDORREALTY.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 9/25/2013

Tank Info:

Tank Number: 001
Tank Id: 12276
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

I00 - Overfill - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B05 - Tank External Protection - Jacketed
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1924
Capacity Gallons: 6600
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

**2 GRACE OWNERS INC. (Continued)** **U003387604**

Register: True
Modified By: NRLOMBAR
Last Modified: 04/18/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

---

**BK441** **EDR US Hist Auto Stat** **1015383465**
**ENE** **276 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.213 mi.**
**1122 ft.** **Site 1 of 3 in cluster BK**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

EDR Historical Auto Stations:
Name: CITY GAS
Year: 2003
Address: 276 HENRY ST

---

**BG442** **RESIDENCE** **NY Spills** **S110306246**
**SSW** **280 VAN BRUNT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.213 mi.**
**1123 ft.** **Site 2 of 5 in cluster BG**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:
Facility ID: 0513119
Facility Type: ER
DER Facility ID: 309628
Site ID: 359542
DEC Region: 2
Spill Date: 2/14/2006
Spill Number/Closed Date: 0513119 / 12/5/2008
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 2/14/2006
CID: 408
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/14/2006
Spill Record Last Update: 5/12/2010
Spiller Name: Not reported
Spiller Company: MADISON OIL HEATING OIL P
Spiller Address: 2125 MILL AVE
Spiller City,St,Zip: BROOKLYN, NY 11234
Spiller Company: 001
Contact Name: DECLAN WALSH
Contact Phone: (718) 522-2447

**RESIDENCE (Continued)** **S110306246**

DEC Memo: Sangesland spoke to both the Oil Company and the building rep.Building is in the process of being purchased by Mr. DeClan Walshcell # 646-284-0416. Actual building owner is elderly and not involved.Maikin Walsh (wife) signed a service contract with Madison Oil in January. Madison inspected the site, came up with $600 worth of repairs that were needed to fix the boiler and filled the oil tank on Jan 10th.Oil deliveries were made:Jan 10 - 249 gallonsJan 24 - 248 gallonsFeb 3 - 233 gallonsFeb 10 - 267 gallonsMr. Walsh says the building is vacant and there is no water service to the building. He says when Madison came on January 10th, they took part of the boiler apart to determine what repairs were necessary to make it work. The boiler was never reassembled and the work has not yet been made. Mr. Walsh does not understand why all of the other deliveries were made.On Feb 11th (Saturday) Mr. Walsh called Madison to come to the site again because of the smell of oil. That was the first time Mr. Walsh heard that there have been several oil deliveries to the building. The Madison repairman saw the tank had a minor drip and there was a "minor" leak at the fill pipe. The Madison rep said the spill was very minor and that's why they did not call in the spill event. Madison told Mr. Walsh that his tank would need to be replaced and that Madison would NOT vac out the tank. Now there is a disagreement over who is at fault. Mr. Walsh, because the tank is leaking, or Madison because they kept delivering oil to a building they knew had no water service or a working boiler. A site visit will be set up with Mr. Walsh and Madison Oil.2/24/06-Vought-Site visit by Vought and meeting with property purchasers (Declan Walsh), Harbor Environmental Mike Alletto(516-609-9800x11)(hired by property purchaser), Madison Oil Co. (Richard Turchiano 718-444-3400). Spill out of vent pipe of 275-gallon #2 fuel oil AST and also to basement consisting of concrete in very poor condition. Vapors in above residence but no one is currently living at site. Site owners are elderly couple and are selling property. Vent pipe heavily rusted and showed no signs of spill out of vent pipe (pipe may not be connected). AS PER MEETING: 1/6-owner called Madison Oil Co. (former owners oil co) to perform diagnostic on boiler. Madison reqiured oil delivery contract in order for diagonistic to be performed. Property purchasers (Ms. Decklan Walsh) signed contract requesting automatic delivery. Madison requested that current tank be cleaned out and Walsh hired ABC to pump out tank. Current owners not aware of current oil deliveries. At time of deliveries, Madison oil co was also performing burner repair as burner was not working. Four deliveries occurred (1/10-249 gallons, 1/14-248 gallons, 2/3-233 gallons, 2/10-67 gallons) for a total of 797 gallons. 2/10-repair was being performed, oil was delivered and driver left note on residence door to call oil company. Walsh discovered oil and bought pump and removed oil from tank and placed into garbage drums. Delivery company was Fleet Oil Co. Due to partial responsibility of property owners (vent in poor condition, signed for automatic delivery) and partial responsiblity of oil company (as per 6NYCRRPart613.3 "if the operator is not on the premises or not in control of a petroleum transfer, the carrier will be responsible for the transfer activities".) a letter will be sent to the current property owners, Madison Oil Co. and Fleet Oil Co. DEC Patel to send letter to current property owner, Madison Oil with cc to Madison Oil Co's insurance(AIG Lockton Companies 444 West 47th Street. Suite 900, Kansas City, Mo. 64112 816-960-9000 Insured is Heating Oil Partners LP, DBA Madison Oil Co., Crawford and Company 800-241-2541, 973-439-6700 Ref#300204171 is

**RESIDENCE (Continued)** **S110306246**

contact for Madison) and Harbor Environmental requiring: 1)collection of endpoint samples.Richard TurchianoMadison Oil Company2125 Mill Ave, Brooklyn, NY 11234Fax: (718) 531-5525Vought called Walsh for property owners info and left message to return call to Patel with owners info. Vought called Harbor for contact info and he will fax information. No insurance on building.CSL sent out to Angelo Christiano, Declan Walsh and Richard Turchiano. Faxed to Declan (Ph.: 718-522-2447, 646-284-0416, FAX: 212-237-8691)Madison oil Company (718) 531-5525Ira Levine (Attorney of current owner) (PH.: 718-855-2110, FAX: 718-596-6137)Kenneth (Attorney of purchaser) (PH.: 516-496-9044, FAX: 516-496-9047)Crawford (Insurance company of oil company) (973) 227-5746Mike Alletto, Harbor (Environmental Consultant) (516) 609-980203/02/06-Hiralkumar Patel. Recived message from Kenneth. Spoke with Kenneth and he asked me for number for Crawford.Also spoke with Bill at Madison, who handles environmental problems at Madison. He was not aware of boiler repair by Madison at site.03/06/06-Hiralkumar Patel. Received letter from Kenneth Robinson.03/07/06-Hiralkumar Patel. Received message from Bill from Madison oil. Spoke with Bill at Madison and as per him they never disconnected boiler and burner was working and owner was using that burner all the time. i asked him to send me copies of work order for work they did on boiler as well as oil deliveries. owner called madison oil complaining no heat or hot water in building.Spoke with Walsh and he told me that burner was never connected back once madison took part apart for diagnosis.called Bill at Madison and asked him to find with owner.03/17/06-Hiralkumar Patel. Received message from Mr. Joe (856-354-8074), who is attorney representing Madison OIl Company. Left message for Joe. spoke with Joe. as per Joe, he called representative from ABC tank's insurance company that is Zurich INsurance and Ms. Kanan Sheth from Zurich is not cooperating Mr. Joe. Joe asked me to send letter to ABC Tank also as he thinks that something happened during emptying out tank and he wants ABC tank also in picture. i told him that i will call him back once i speak with ABC Tank and its insurance company.Spoke with Robert (718-272-2800) at ABC Tank and he told me that they just pumped out tank and cleaned it. during cleaning the tank, he has noticed that tank was rusted.03/20/06-Hiralkumar Patel. Spoke with Isaac at PTC asking general procedure of 275 gal AST cleanup. he told me that they generally take out plugs from top of tank and insert 1" hose to suck out oil/water from tank. they don't touch any piping to/from tank. they only disconnect pipes if pipe itself has any problem.Left message for Rober at ABC Tank. Spoke with Ms. Donna. they used vacuum truck and suck out oil from top of tank. they haven't touched bottom part or pipings of tank. they haven't noticed any kind of leakage from any pipings. they were instructed not to put clean good oil into tank once cleaning done. so they left tank empty after cleaning. and all the plugs they took out were placed back in proper way. Asked Donna to send me this procedure in writing.03/21/06-Hiralkumar Patel. REceived fax from Joe Ricchezza's office.Joe RicchezzaSalmon Ricchezza Singer & Turchi LLP110 East 59th Street29th FloorNew York, NY 10022Ph. (856) 354-8074 (212) 530-4471FAX (212) 530-447203/24/06-Hiralkumar Patel. Spoke with Mr. Robert at ABC Tank and he told me that Ms. Donna will be in at around 10:00 O'clock. Robert told me that they have received some documents from Madison oil yesterday.03/28/06-Hiralkumar Patel. REceived fax from Madison oil's lawyer.04/03/06-Hiralkumar Patel. i haven't received written procedure from ABC Tank yet.Received call from Kevin

**RESIDENCE (Continued)** **S110306246**

from Castleton. Madison OIl has hired Castleton for cleanup at site. Kevin visited site and he found some garbage cans with oil. also found oil in catch basin. he will go there tomorrow or day after and will remove that oil from site. as site had oil spill for long time, Kevin is planning to delineate site as well as surrounding areas. i have asked him to send me copy of work plan that he will submit to Madison oil.KevinCastletonPh. (201) 727-9001FAX (201) 727-910804/07/06-Hiralkumar Patel. Received fax from Madison oil's lawyer. letter states that Mr. Frank J. Maitland of Queens will conduct an inspection of the subject premises; this inspection will include, but will not be limited to, an inspection of the oil tank, and the fill and vent lines.04/18/06-Hiralkumar Patel. REceived fax from Madison oil's lawyer. abstract of letter:- Frank J. Maitland of Quense did inspection of site.- Frank J. Maitland will do further investigation including following: * move the oil tank to inspect for holes. this will require disonnecting the fill and vent lines. * if holes are not obvious in the oil tank, air pressure testing of the tank will be done to test for holes. * inspect the fuel line from the tank to burner/boiler * disable the fill line, by filling the street opening wiht concrete.05/08/06-Hiralkumar Patel. Received fax from Madison oil's lawyer.05/10/06-Hiralkumar Patel. Received fax from Madison oil's lawyer.05/15/06-Hiralkumar Patel. Received fax from Madison oil's lawyer stating that Frank Maitland will conduct an inspection of the site on Wed. June 7, 2006.05/25/06-Hiralkumar Patel. Received fax from Madison oil's lawyer stating that they will do final inspection of oil tank on June 7, 2006.06/30/06-Hiralkumar Patel. REceived message from Bob Zos (718-423-9848) from insurance company of this building.07/03/06-Hiralkumar Patel. left message for Mr. Zos.07/06/06-Hiralkumar Patel. spoke to Richard at Madison oil. Rich spoke to his lawyer and as per him, current owner and purchaser are willing to do cleanup. Rich is not sure whats going on currently. he will check with his lawyer and will call back.07/31/06-Hiralkumar Patel. spoke with Mr. Walsh. as per him, oil company will do cleanup. asked Mr. Walsh to get latest information and call back.08/03/06-Hiralkumar Patel. received message from Christopher (Cell: 973-332-8962) from Castleton Environmental Contractors. he has been hired by Heating Oil partners. left message for Christopher.08/04/06-Hiralkumar Patel. received call from Chris Miceli (FAX: 732-525-0311) from Castleton. he will be going onsite on Tuesday August 8,2006. he will send work plan on Monday August 7, 2006.08/07/06-Hiralkumar Patel. received work plan through fax from Mr. Miceli. they proposed to removed any free product from tank, sump pit and other locations in basement to prevent further movement of oil. also proposed for soil and groundwater investigation. Mr. Miceli will meet related parties tomorrow.08/17/06-Hiralkumar Patel. received message from Mr. Miceli. spoke with Mr. Miceli. they have removed impacted debris and absorbed free product from sump pit as well as from floor. this site is close to river and as water level goes up, groundwater comes into basement through cracks in floor. he took 9 soil samples about 4 ft bg and installed 9 temporary recovery wells at these boring location and vacuum these every other day. he observed heavy sheen on groundwater. he will submit soil analyticals with site plan.09/25/06-Hiralkumar Patel. left message for Mr. Miceli at Castleton.09/26/06-Hiralkumar Patel. received call from Chris Miceli from Castleton. he got lab analyticals for soil and groundwater samples. he has installed temporary recovery wells and recovered mostly free porduct and sheen. he will send me letter

**RESIDENCE (Continued)** **S110306246**

report for work done till now.09/27/06-Hiralkumar Patel. received fax from Chris contains lab analyticals for soil samples. - performed remedial activities in the form of free product collection, the removal and proper disposal of any and all impacted material and general site cleanup- due to poor condition of the existing floor in the form of numerous cracks, holes and breachees, CEC could not perform stringent cleaning via hot, high pressure washing.- installed nine borings throughout the basement- impacted soils were detected in all borings from the ground surface to approx. three ft below grade- groundwater was noted within all boring at approx. six inches below grade soil.- free product was noted within the sump pit, SB-1, SB-2, SB-3 and SB-7. oil sheen was noted within the remaining borings- temporary well points were installed into each boring and the surface interface around the well points was resealed with concrete to prevent surface infiltration.- groundwater was removed from all nine monitoring points via vacuum trucknone of the soil sample shows any contamination. this letter doesn't have consistent data as they found contaminated soil upto 3 ft and also found groundwater at 6 inch below grade.spoke with Chris. he will meet at site tomorrow at 12 PM.09/28/06-Vought-Received call from DEC Patel that he will be taking sick day and to call Chris and rescedule meeting set for today at 12pm. Vought called Chris and meeting rescheduled for 9/29 at 12pm.09/29/06-Hiralkumar Patel. visited site. Met Chris. as walking down a street, smelled oil at least 15 ft away from subject site as basement door was open. found cracks throughout basement floor. Chris was proposing excavating contaminated soil leaving atleast 8 inch area along foundation wall and pillers. they are planning to finish excavation in three phase. in each phase they will remove part of contamianted area and then backfill that spot with clean soil after endpoint samples taken. as per Chris, during initial cleanup, they opened two windows in basement and let all contaminated vapor go out in air through back of property. he hasn't got any complaints about oil vapor from neighbours. asked Chris not to do any more work without getting approval from the Department. asked Chris to submit work plan. as per Chris, there is dry cleaner facility on south side of property and former auto repair shop on north side of property.spoke with Chris about groundwater depth. as per Chris, they found groundwater right below basement floor at about 6 inch. he drilled through this to 3 ft and took soil samples. soil samples were wet.10/02/06-Hiralkumar Patel. spoke with Chris and asked to submit data regarding amount of oil/water removed from these wells with amount of oil/free product recovered in total volume on each site visit.10/04/06-Hiralkumar Patel. received fax from Chris with water/oil removal details from each well points. from nine well points, found free product in wells SB-2, SB-3 and SB-7. no product ever observed in remaining well points and also in sump pit. as of last EFR (enhanced fluid recovery) run on 09/14/06 no product observed on any well point, no sheen on well points SB-4, 5, 6 & 9 and slight sheen and odor on remaining points. removed an estimated 20-30 gal of product from well points during the course of nine EFR events.left message for Chris to submit Remedial Action summary report from which he faxed groundwater data.10/06/06-Hiralkumar Patel. left message for Chris. received call from Chris. he hasn't made any report yet. he was sending only those information that were required by the Department. asked Chris to include all his work detail till date in final report.sent out letter to Angelo Christino, Declan Walsh and Richard Turchiano requiring endpoint samples (soil &

**RESIDENCE (Continued)** **S110306246**

groundwater as groundwater is only 6 inch below the basement floor), vapor barrier installation and sub-slab depressurization system installation. letter faxed to Declan (212) 237-8691Madison oil Company (718) 531-5525Ira Levine (Attorney of current owner) (718) 596-6137Kenneth (Attorney of purchaser) (516) 496-9047Crawford (Insurance company of oil company) (973) 227-5746Mike Alletto, Harbor (Environmental Consultant) (516) 609-9802Chris Miceli, Castlton (732) 525-031110/18/06-Hiralkumar Patel. received message from Chris. they are ready to start work. spoke with Chris and asked him to send updates on regular basis.11/08/06-Hiralkumar Patel. received call from Chris. they have dug out half basement floor in back of basement and waiting for lab analyticals for endpoint samples. once he gets this results, he will backfill this excavated area after vapor barrier installation. then they will start working in front part of basement. Chris is leaving Castleton and somebody else will handle this project.11/17/06-Hiralkumar Patel. received call from Jake from Castleton. he found water right below basement concrete floor. they have removed some soil. they pumped out about 3000 gal water from excavation and found very little sheen on it. Jake was proposing inverted slotted pipe instead of vapor barrier as water level is right below floor concrete. asked Jake to take water sample and wait till receive endpoint sample analyticals.12/20/06-Hiralkumar Patel. left message for Jake (Cell: 973-332-4972) at Castleton. received call from Jake from Castleton. they have finished excavation. area has been backfilled. during first set of sampling, found contaminated soil in corner of property and contamianted groundwater. after that results, Castleton excavated that remaining spot to remove any contamination and cleaned out sump where they took groundwater believing that this sump cause contamination in water sample. they have taken another set of soil and groundwater sample yesterday and will send final report once they get lab data back. asked Jake to send lab analyticals for first set of samples. Jake will fax those lab data.01/02/07-Hiralkumar Patel. spoke with Jake. asked him to fax lab analyticals for first set of sampling. he is waiting for lab analytical for water sample that taken lateron. 01/03/07-Hiralkumar Patel. received call from Woody Maloney from Castlton. he will email lab data for first set of samples.received sample analyticals from Mr. Maloney (wmaloney@castlton.com). Castlton took nine post excavation samples. no contamination found in samples. no data for groundwater sample. will send final report once they get data for second set of samples.01/08/07-Hiralkumar Patel. received call from Mr. Maloney. they got groundwater analyticals for second set of sampling. he will email these data.02/13/07-Hiralkumar Patel. received water analyticals from Castlton. no contamination found in sample. spoke with Jake at Castlton. as per him, entire site is clean now. he was proposing drainage system installed under concrete and connect that to sump in corner. asked him to install such system with moisture barrier and also epoxy paint on floor to prevent any vapors coming into building. he will monitor water that comes into sump for next two months. water from sump will be discharged on street unless any oil/sheen observed on water. based on water analytical, approved his request to reconcrete building basement. Jake will submit report on work done till date after such work and will submit closure report after two months if no oil/sheen finds in water.02/22/07-Hiralkumar Patel. received fax from Castleton. abstract:- all contaminated soil removed from site- ~ 18 inch of gravel has been laid to an elevation of 2 inches beneath the original height of the removed floor wall and

**RESIDENCE (Continued)** **S110306246**

4 inches below where the new floor epoxy surface will be.- footing drains discharge system of 3 inch PVC with holes on the bottom 180 degree of the piping will be laid within surface culverts of the gravel layer.- footing drains discharge system will be 12 inches from the perimeter basement walls- sump pump will be installed- floor epoxy seal on the basement floor and sump pump will confine groundwater both underneath the basement floor wall and outwards, to the street drainage outside the residence- groundwater samples will be taken weekly for the next two months03/22/07-Hiralkumar Patel. received message from Ira Levine (718-855-2110), current owner's attorney. left message for Mr. Levine.06/19/07-Hiralkumar Patel. left message for Jake at Castleton.06/20/07-Hiralkumar Patel. received message from Susan Rose (845-624-1312) from castleton. spoke with Ms. Rose. they took groundwater samples at two times and found nothing in it. she is preparing report and will send soon.07/25/07-Hiralkumar Patel. spoke with Ms. Rose. she is still working on report and will send by Aug. 3rd, 2007.10/11/07-Hiralkumar Patel. left message for Ms. Rose about quaterly/closure report.10/31/07-Hiralkumar Patel. left message for Ms. Rose about quaterly/closure report.11/21/07-Hiralkumar Patel. received message from Ms. Rose. she asked to call Perry (?). left message for Perry.11/26/07-Hiralkuamr Patel. left message for Perry.11/28/07-Hiralkumar Patel. received call from Perry. he mentioned that Ms. Rose is on vacation (till 12/18) and will send report once comes back. asked Perry to submit groundwater sample data and other monitoring details for review.12/03/07-Hiralkumar Patel. received fax from Castleton but it contains old data.01/14/08-Hiralkumar Patel. left message for Ms. Rose.spoke with Mr. Walsh. asked to submit report. sent email to Mr. Walsh (dwalsh@jjay.cuny.edu) requiring report submission.01/15/08-Hiralkumar Patel. spoke with Bill at Castleton. he will send report.01/16/08-Hiralkumar Patel. received fax from Bill from Castleton. received few pages only. received call from Bill. asked him to re-submit data alongwith site map. also asked to take one more groundwater sample.left message for Mr. Walsh. asked him for another groundwater sample.received message from Mr. Walsh. as oil company hired Castleton, Mr. Walsh asked to contact oil company.received email from Ken Robinson, Mr. Walsh's attorney. he asked to contact Shari Bernstein, oil company's attorney regarding reports.sent email to Mr. Robinson (envlaw516@aol.com), Mr. Bernstein (sbernstein@srstlaw.com) and Mr. Walsh requiring another round of groundwater sampling. asked to submit work schedule by Jan. 25, 2008.02/29/08-Hiralkumar Patel. received fax from Ms. Rose from Castlton. they took groundwater sample. no contamination found in groundwater sample.03/20/08-Hiralkumar Patel. left message for Ms. Rose about drain system installation (as proposed in earlier report) and location of recent groundwater sample (from sump??)04/23/08-Hiralkumar Patel. received call from Ms. Rose. asked her about recent groundwater sampling location and status about previously proposed drain system. Ms. Rose mentioned that groundwater sample was collected from sump and drain system has been installed.11/26/08-Hiralkumar Patel. received call from Castleton asking status of spill case.spoke with Maria Walsh (917-741-5991) to schedule a site visit. she mentioned that they haven't purchased property yet because of open spill case. Ms. Walsh asked to contact current owner's attorney.left message for Ira Levine.12/01/08-Hiralkumar Patel. spoke with receptionist at Ira's office. she mentioned that they had contacted current owner and

**RESIDENCE (Continued)** **S110306246**

current owner will call to schedule site visit (to confirm cleanup).12/02/08-Hiralkumar Patel. received call from Angelo Christiano, current property owner. she will meet at site at 11 AM on 12/05/08.Angelo ChristianoMaureen ChristianoPh. (718) 207-7080 (C) (718) 207-7078 (C)12/05/08-Hiralkumar Patel. visited site. met Ms. Christiano. inspected basement. new concrete floor in middle portion of basement. no excavation was happened along foundation wall, so same old concrete floor exist. no sign of any oil seepage through floor. no oil found in sump. no odors in basement.based on all available documents and observation during last site visit, case closed.NFA sent to Ms. Christiano, Mr. Walsh and Rich (at Madison oil). letter faxed to Ira (owner's attorney) and Kenneth (buyer's attorney).

Remarks: THE OIL COMPANY DELIVERED 3 OR 4 OIL DELIVERYS OF 200 GALLONS EACH. SUCKED OIL OUT OF THE SUMP PUMP, IS IN GARBAGE CANS IN THE BASEMENT. WOULD LIKE A CALL BACK

Material:

| | |
|---|---|
| Site ID: | 359542 |
| Operable Unit ID: | 1116749 |
| Operable Unit: | 01 |
| Material ID: | 2107197 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 600 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BL443** **PIER 11 OIL STAIN & FIRE** **NY Spills** **S102144003**
**SSW** **PIER 11,COMMERCE ST.** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.213 mi.**
**1126 ft.** **Site 1 of 2 in cluster BL**

**Relative:**
**Higher**

**Actual:**
**12 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8601969 |
| Facility Type: | ER |
| DER Facility ID: | 153049 |
| Site ID: | 182661 |
| DEC Region: | 2 |
| Spill Date: | 6/23/1986 |
| Spill Number/Closed Date: | 8601969 / 6/23/1986 |
| Spill Cause: | Housekeeping |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | RWAUSTIN |
| Referred To: | Not reported |
| Reported to Dept: | 6/23/1986 |
| CID: | Not reported |

**PIER 11 OIL STAIN & FIRE (Continued)** **S102144003**

| | |
|---|---|
| Water Affected: | NONE |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Federal Government |
| Cleanup Ceased: | 6/23/1986 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/23/1986 |
| Spill Record Last Update: | 1/31/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNK |
| Spiller Address: | UNK |
| Spiller City,St,Zip: | UNK'UNK, ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN" |
| Remarks: | SPILL DISCOVERED ON PIER DURING PIERSHED FIRE; DISCOVERED BY USCG CUTTER DURING ROUTINE PATROL; SAWDUST PUT DOWN TO SORB OIL |

Material:

| | |
|---|---|
| Site ID: | 182661 |
| Operable Unit ID: | 899415 |
| Operable Unit: | 01 |
| Material ID: | 478430 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BE444** **IDEA NUIVA** **NY AST** **U004079692**
**SSW** **80 RICHARDS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.215 mi.**
**1137 ft.** **Site 4 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-608357 |
| Program Type: | PBS |
| UTM X: | 583819.45203000004 |
| UTM Y: | 4503618.9120500004 |
| Expiration Date: | 2013/12/30 |
| Site Type: | Manufacturing (Other than Chemical)/Processing |

**IDEA NUIVA (Continued)** **U004079692**

Affiliation Records:

| | |
|---|---|
| Site Id: | 30209 |
| Affiliation Type: | Mail Contact |
| Company Name: | 80 RICHARDS STREET LLC |
| Contact Type: | Not reported |
| Contact Name: | ISACC ADES |
| Address1: | 80 RICHARDS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 855-0617 |
| EMail: | ISAAC@IDEANUOVA.COM |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 8/1/2012 |

| | |
|---|---|
| Site Id: | 30209 |
| Affiliation Type: | On-Site Operator |
| Company Name: | IDEA NUIVA |
| Contact Type: | Not reported |
| Contact Name: | ISAAC ADES |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 855-0617 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 8/1/2012 |

| | |
|---|---|
| Site Id: | 30209 |
| Affiliation Type: | Emergency Contact |
| Company Name: | 80 RICHARDS STREET LLC |
| Contact Type: | Not reported |
| Contact Name: | ISAAC ADES |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 855-0617 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 8/1/2012 |

| | |
|---|---|
| Site Id: | 30209 |
| Affiliation Type: | Facility Owner |
| Company Name: | 80 RICHARDS STREET LLC |
| Contact Type: | COSMOS ENVIRONMENTAL SVS. INC |
| Contact Name: | ALEXANDER I. AVTACEN |

**IDEA NUIVA (Continued)** **U004079692**

| | |
|---|---|
| Address1: | 80 RICHARDS STREET |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11231 |
| Country Code: | 001 |
| Phone: | (718) 855-0617 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 8/1/2012 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 65073 |
| Material Code: | 0003 |
| Common Name of Substance: | #6 Fuel Oil (On-Site Consumption) |

Equipment Records:

D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
A01 - Tank Internal Protection - Epoxy Liner
H05 - Tank Leak Detection - In-Tank System (ATG)
E02 - Piping Secondary Containment - Vault (with Access)
G03 - Tank Secondary Containment - Vault (w/o access)
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 6 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/01/1950 |
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |
| Last Modified: | 08/01/2012 |
| Material Name: | #6 Fuel Oil (On-Site Consumption) |

**BM445** **MH #43281** **NY Spills** **S103827594**
**SSE** **HENRY ST & UNION ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.216 mi.**
**1138 ft.** **Site 1 of 5 in cluster BM**

**Relative:**
**Higher**

**Actual:**
**38 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9813126 |
| Facility Type: | ER |
| DER Facility ID: | 126342 |
| Site ID: | 148447 |
| DEC Region: | 2 |
| Spill Date: | 1/26/1999 |
| Spill Number/Closed Date: | 9813126 / 10/18/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 1/26/1999 |
| CID: | 366 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/26/1999 |
| Spill Record Last Update: | 10/18/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"e2mis no. 122-668:1/26/99 12:35 hrsRich Bocignone #07942, Splicer with Underground, reports at 12:15 hrs found an undiaperable sheen of unknown oil on approx. 250 gal. water in MH-43281, n/w/c Henry St. & Union St. Spill is contained. No sewers or waterways affected. Env. stop tag #21437 installed. One liquid sample oil & water taken on 4-6 hour priority turnaround. Cleanup pending test results from Chem Lab.UPDATE 1-27-99 ---- LAB RESULTS RECEIVED LAB SEQ#99-00793 PCB=1PPM.J.LIPORI OF ENVIRONMENTAL OPERATIONS REPORTS C/U COMPLETED WITH SLIX AT 1900HRS.2/5/99 - E.S.TAG#21437 REMOVED. |
| Remarks: | CALLER REPORTING FINDING UNKNOWN PETROLEUM IN MH. SAMPLE TAKEN, CLEAN UP PENDING RESULTS. |

Material:

| | |
|---|---|
| Site ID: | 148447 |
| Operable Unit ID: | 1070486 |
| Operable Unit: | 01 |
| Material ID: | 313400 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |

**MH #43281 (Continued)** **S103827594**

Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**BJ446** **42 GRACE COURT** **NY Spills** **S104495389**
**NE** **42 GRACE COURT** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.216 mi.**
**1139 ft.** **Site 2 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

SPILLS:
Facility ID: 9208894
Facility Type: ER
DER Facility ID: 252253
Site ID: 312863
DEC Region: 2
Spill Date: 11/2/1992
Spill Number/Closed Date: 9208894 / 11/2/1992
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 11/2/1992
CID: Not reported
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Other
Cleanup Ceased: 11/2/1992
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/4/1992
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"
Remarks: OIL LEAKED AFTER DISCONNECT CONTAINED AT FILL BOX-SPILLER DID CLEANUP

Material:
Site ID: 312863
Operable Unit ID: 972435

**42 GRACE COURT (Continued)** **S104495389**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 405968 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BJ447** **LADYZINSKI JOHN** **RCRA NonGen / NLR** **1001119430**
**NE** **44 GRACE CT** **FINDS** **NYR000027177**
**1/8-1/4** **BROOKLYN, NY** **NY MANIFEST**
**0.216 mi.**
**1141 ft.** **Site 3 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | LADYZINSKI JOHN |
| Facility address: | 44 GRACE CT<br>BROOKLYN, NY 112014182 |
| EPA ID: | NYR000027177 |
| Mailing address: | WILLOW ST<br>BROOKLYN, NY 11201 |
| Contact: | Not reported |
| Contact address: | WILLOW ST<br>BROOKLYN, NY 11201 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | JOHN LADYZINSKI |
| Owner/operator address: | 44 GRACE CT<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 852-9050 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | JOHN LADYZINSKI |
| Owner/operator address: | 44 GRACE CT<br>BROOKLYN, NY 11201 |
| Owner/operator country: | US |
| Owner/operator telephone: | (718) 852-9050 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |

**LADYZINSKI JOHN (Continued)** **1001119430**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: LADYZINSKI JOHN
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: LADYZINSKI JOHN
Classification: Not a generator, verified

Date form received by agency: 07/25/1996
Facility name: LADYZINSKI JOHN
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004526914

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000027177
Country: USA
Mailing Name: JOHN LADYZINSKI
Mailing Contact: MELINDA MAGNETT
Mailing Address: 44 GRACE COURT
Mailing Address 2: Not reported
Mailing City: BROOKLYN

**LADYZINSKI JOHN (Continued)** **1001119430**

| | |
|---|---|
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 999-999-9999 |

| | |
|---|---|
| Document ID: | NYB7763814 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | T3K760NJ |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 960910 |
| Trans1 Recv Date: | 960910 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 960911 |
| Part A Recv Date: | 960920 |
| Part B Recv Date: | 960930 |
| Generator EPA ID: | NYR000027177 |
| Trans1 EPA ID: | NJD054126164 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD049836679 |
| Waste Code: | D008 - LEAD 5.0 MG/L TCLP |
| Quantity: | 01600 |
| Units: | P - Pounds |
| Number of Containers: | 004 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 96 |

---

**BE448** **IDEA NUOVA GLOBAL** **NY Spills** **S112230977**
**SSW** **80 RICHARDS ST** **N/A**
**1/8-1/4** **RED HOOK, NY**
**0.216 mi.**
**1142 ft.** **Site 5 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1211033 |
| Facility Type: | ER |
| DER Facility ID: | 429432 |
| Site ID: | 474165 |
| DEC Region: | 2 |
| Spill Date: | 10/29/2012 |
| Spill Number/Closed Date: | 1211033 / 11/13/2012 |
| Spill Cause: | Storm |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | TJDEMEO |
| Referred To: | Not reported |
| Reported to Dept: | 11/13/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | DEC |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**IDEA NUOVA GLOBAL (Continued)** **S112230977**

| | |
|---|---|
| UST Trust: | False |
| Remediation Phase: | 1 |
| Date Entered In Computer: | 11/15/2012 |
| Spill Record Last Update: | 11/15/2012 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | Not reported |
| Spiller Company: | Not reported |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.6 story very old warehouse in Red Hook. Workers were shoveling oil/water out of the basement. 20,000gal #2 oil tank spilled in basement. Owner didn't report.Owner pumped oil directly into the sewer. DEC Todd (Region3) Pumped out the storm sewer. Owner also had 2 large electric transformers with possible PCB in the basement. This is a potentially serious problem which needs followup.DEC Pumped out 100 Gallons on 11/13/2012 |
| Remarks: | Not reported |

Material:

| | |
|---|---|
| Site ID: | 474165 |
| Operable Unit ID: | 1224009 |
| Operable Unit: | 01 |
| Material ID: | 2222177 |
| Material Code: | 0020A |
| Material Name: | TRANSFORMER OIL |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 100 |
| Units: | Gallons |
| Recovered: | 100 |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BK449** **283 HENRY ST/BROOKLYN** **NY Spills** **S102145691**
**ENE** **283 HENRY STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.217 mi.**
**1146 ft.** **Site 2 of 3 in cluster BK**

**Relative:**
**Higher**

**Actual:**
**61 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 8911344 |
| Facility Type: | ER |
| DER Facility ID: | 183867 |
| Site ID: | 222374 |
| DEC Region: | 2 |
| Spill Date: | 3/1/1990 |
| Spill Number/Closed Date: | 8911344 / 3/1/1990 |
| Spill Cause: | Human Error |
| Spill Class: | Not reported |
| SWIS: | 2401 |
| Investigator: | WILSON |

**283 HENRY ST/BROOKLYN (Continued)** **S102145691**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 3/1/1990 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | 3/1/1990 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/6/1990 |
| Spill Record Last Update: | 5/19/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | BAERENKLAU |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Not reported |
| Remarks: | DRIVER FAILED TO FIT NOZZLE TO FUEL PIPE PROPERLY, SPILL ON CONCRETE, SPEEDY DRY APPLIED, SPILL TEAM TO PICK UP & DISPOSE. |

Material:

| | |
|---|---|
| Site ID: | 222374 |
| Operable Unit ID: | 938330 |
| Operable Unit: | 01 |
| Material ID: | 440868 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BN450** **GRACE CHURCH** **NY UST** **U000397366**
**NE** **50 GRACE COURT** **NY HIST UST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.217 mi.**
**1148 ft.** **Site 1 of 2 in cluster BN**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-271497 / Unregulated |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | N/A |
| UTM X: | 584779.96148000006 |
| UTM Y: | 4505256.6142199999 |
| Site Type: | Religious Building (Church, Synagogue, Mosque, Tem |

**GRACE CHURCH (Continued)** **U000397366**

Affiliation Records:

| | |
|---|---|
| Site Id: | 11458 |
| Affiliation Type: | Facility Owner |
| Company Name: | GRACE CHURCH |
| Contact Type: | Not reported |
| Contact Name: | Not reported |
| Address1: | 50 GRACE CT |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 624-1850 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | CGFREEDM |
| Date Last Modified: | 12/15/2004 |

| | |
|---|---|
| Site Id: | 11458 |
| Affiliation Type: | Mail Contact |
| Company Name: | GRACE CHURCH |
| Contact Type: | Not reported |
| Contact Name: | SUPER FACILITY MANAGER |
| Address1: | 50 GRACE CT |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11201 |
| Country Code: | 001 |
| Phone: | (718) 624-1850 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | CGFREEDM |
| Date Last Modified: | 12/15/2004 |

| | |
|---|---|
| Site Id: | 11458 |
| Affiliation Type: | Emergency Contact |
| Company Name: | GRACE CHURCH |
| Contact Type: | Not reported |
| Contact Name: | JOSE CARDONA |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 624-1850 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 6/23/2005 |

| | |
|---|---|
| Site Id: | 11458 |
| Affiliation Type: | On-Site Operator |
| Company Name: | GRACE CHURCH |
| Contact Type: | Not reported |
| Contact Name: | ED ROSS |

**GRACE CHURCH (Continued)** **U000397366**

| | |
|---|---|
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 624-1850 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | NRLOMBAR |
| Date Last Modified: | 6/23/2005 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 9115 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 3000 |
| Install Date: | Not reported |
| Date Tank Closed: | 04/26/2005 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |
| Tightness Test Method: | 18 |
| Date Test: | 02/12/2003 |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | NRLOMBAR |
| Last Modified: | 06/23/2005 |

Equipment Records:

G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)

HIST UST:

| | |
|---|---|
| PBS Number: | 2-271497 |
| SPDES Number: | Not reported |
| Emergency Contact: | CESAR NEYRA |
| Emergency Telephone: | (718) 624-1850 |
| Operator: | CESAR NEYRA |
| Operator Telephone: | (718) 624-1850 |
| Owner Name: | GRACE CHURCH |
| Owner Address: | 50 GRACE CT |
| Owner City,St,Zip: | BKLYN, NY 11201 |

**GRACE CHURCH (Continued)** **U000397366**

| | |
|---|---|
| Owner Telephone: | (718) 624-1850 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Name: | GRACE CHURCH |
| Mailing Address: | 50 GRACE CT |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | BKLYN, NY 11201 |
| Mailing Contact: | SUPER FACILITY MANAGER |
| Mailing Telephone: | (718) 624-1850 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | 50 GRACE CT |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | Not reported |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 04/21/1998 |
| Expiration Date: | 06/18/2002 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 3000 |
| FAMT: | True |
| Facility Screen: | Minor Data Missing |
| Owner Screen: | No Missing Data |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 001 |
| Tank Location: | UNDERGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (gals): | 3000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Underground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Product Level Gauge |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | 12/27/1987 |

**GRACE CHURCH (Continued)** **U000397366**

| | |
|---|---|
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

---

**BN451** **X** **NY LTANKS** **S105997910**
**NE** **50 GRACE COURT** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.217 mi.**
**1148 ft.** **Site 2 of 2 in cluster BN**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

LTANKS:

| | |
|---|---|
| Site ID: | 74188 |
| Spill Number/Closed Date: | 0210381 / 11/21/2005 |
| Spill Date: | 1/15/2003 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | rmpiper |
| Referred To: | Not reported |
| Reported to Dept: | 1/15/2003 |
| CID: | 199 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/15/2003 |
| Spill Record Last Update: | 11/21/2005 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | ED ROSS |
| Spiller Phone: | (732) 541-7999 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 69687 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SAWYER"ARAKHAN 1/15/03 TTF LETTER SENT.11/20/05- Based on caller remarks, repairs, and 2/12/03. DEC Piper close1/7/04-Vought-Spill transferred from Vought to Austin.01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. |
| Remarks: | APPEARS IT IS A VENT LINE LEAK - LINE WILL BE REPAIRED AND TANKRETESTED - NO CALL BACK NEEDED -- THERE IS NO PRODUCT IN THE TANK |

Material:

| | |
|---|---|
| Site ID: | 74188 |
| Operable Unit ID: | 861627 |

**X (Continued)** **S105997910**

Operable Unit: 01
Material ID: 513766
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 74188
Spill Tank Test: 1527942
Tank Number: 001
Tank Size: 5000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

---

**BE452** **WAREHOUSE** **NY LTANKS** **S106124575**
**SSW** **80 RICHARDS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.218 mi.**
**1151 ft.** **Site 6 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

LTANKS:
Site ID: 270335
Spill Number/Closed Date: 0310837 / 2/13/2004
Spill Date: 12/20/2003
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 12/20/2003
CID: 72
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/20/2003
Spill Record Last Update: 2/13/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported

**WAREHOUSE (Continued)** **S106124575**

| | |
|---|---|
| Spiller City,St,Zip: | ***Update***, ZZ |
| Spiller County: | 001 |
| Spiller Contact: | ANTHONY LARA |
| Spiller Phone: | (646) 772-7180 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 220138 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"DeMeo responded to the site. 5,000 gal tank failure.2/13/04 TJDTank failure. All product contained inside tank vault, with concrete floor in good condition. No sumps or drains impacted. PTC performed pump out and pressure wash of tank room. No further action required. Spill closed. |
| Remarks: | Tank rupture of 5,000 gallon tank. Petroleum tank cleaners on the way to investigate. |

Material:

| | |
|---|---|
| Site ID: | 270335 |
| Operable Unit ID: | 875925 |
| Operable Unit: | 01 |
| Material ID: | 499681 |
| Material Code: | 0003A |
| Material Name: | #6 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Pounds |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BE453** **JOHN TURANO & SONS** **FINDS** **1006324537**
**SSW** **80 RICHARDS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.218 mi.**
**1151 ft.** **Site 7 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

FINDS:

Registry ID: 110012643835

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BJ454** **GRACE COURT OWNERS CORP.** **NY UST** **U004046985**
**NE** **45 GRACE COURT** **NY AST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.218 mi.**
**1152 ft.** **Site 4 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

UST:

| | |
|---|---|
| Id/Status: | 2-609330 / Active |
| Program Type: | PBS |
| Region: | STATE |
| DEC Region: | 2 |
| Expiration Date: | 2018/10/30 |
| UTM X: | 584637.91011000006 |
| UTM Y: | 4505327.9162900001 |
| Site Type: | Private Residence |

Affiliation Records:

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Mail Contact |
| Company Name: | ADVANCED MANAGEMENT SERVICES |
| Contact Type: | Not reported |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | 26 COURT STREET |
| Address2: | SUITE 804 |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11242 |
| Country Code: | 001 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Emergency Contact |
| Company Name: | GRACE COURT OWNERS CORP. C/O AMS |
| Contact Type: | Not reported |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | On-Site Operator |
| Company Name: | GRACE COURT OWNERS CORP. |
| Contact Type: | Not reported |
| Contact Name: | EDDIE LEON |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |

**GRACE COURT OWNERS CORP. (Continued)** **U004046985**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (347) 683-5053 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Facility Owner |
| Company Name: | GRACE COURT OWNERS CORP. C/O AMS |
| Contact Type: | MGR |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | 26 COURT STREET , SUITE 804 |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11242 |
| Country Code: | 001 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank ID: | 67166 |
| Tank Status: | Closed - In Place |
| Material Name: | Closed - In Place |
| Capacity Gallons: | 4000 |
| Install Date: | Not reported |
| Date Tank Closed: | 01/14/2003 |
| Registered: | True |
| Tank Location: | Underground |
| Tank Type: | Steel/carbon steel |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

| | |
|---|---|
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Pipe Model: | Not reported |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
B00 - Tank External Protection - None

**GRACE COURT OWNERS CORP. (Continued)** **U004046985**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-609330 |
| Program Type: | PBS |
| UTM X: | 584637.91011000006 |
| UTM Y: | 4505327.9162900001 |
| Expiration Date: | 2018/10/30 |
| Site Type: | Private Residence |

Affiliation Records:

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Mail Contact |
| Company Name: | ADVANCED MANAGEMENT SERVICES |
| Contact Type: | Not reported |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | 26 COURT STREET |
| Address2: | SUITE 804 |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11242 |
| Country Code: | 001 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Emergency Contact |
| Company Name: | GRACE COURT OWNERS CORP. C/O AMS |
| Contact Type: | Not reported |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | On-Site Operator |
| Company Name: | GRACE COURT OWNERS CORP. |
| Contact Type: | Not reported |
| Contact Name: | EDDIE LEON |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |

**GRACE COURT OWNERS CORP. (Continued)** **U004046985**

| | |
|---|---|
| Phone: | (347) 683-5053 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

| | |
|---|---|
| Site Id: | 31174 |
| Affiliation Type: | Facility Owner |
| Company Name: | GRACE COURT OWNERS CORP. C/O AMS |
| Contact Type: | MGR |
| Contact Name: | SAMMERIS BURGOS |
| Address1: | 26 COURT STREET , SUITE 804 |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11242 |
| Country Code: | 001 |
| Phone: | (718) 852-5310 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/25/2013 |

Tank Info:

| | |
|---|---|
| Tank Number: | 002 |
| Tank Id: | 67345 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
K00 - Spill Prevention - None

| | |
|---|---|
| Tank Location: | 6 |
| Tank Type: | Steel Tank in Concrete |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/01/1987 |
| Capacity Gallons: | 1500 |
| Tightness Test Method: | 00 |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |
| Last Modified: | 10/25/2013 |

**GRACE COURT OWNERS CORP. (Continued)** **U004046985**

Material Name: #2 Fuel Oil (On-Site Consumption)

---

**BM455** **MAZZOLA BAKERY** **NY Spills** **S104510650**
**SSE** **192 UNION ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.219 mi.**
**1155 ft.** **Site 2 of 5 in cluster BM**

**Relative:**
**Higher**

**Actual:**
**38 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9913889 |
| Facility Type: | ER |
| DER Facility ID: | 101492 |
| Site ID: | 116657 |
| DEC Region: | 2 |
| Spill Date: | 3/9/2000 |
| Spill Number/Closed Date: | 9913889 / 11/16/2005 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | kamalone |
| Referred To: | Not reported |
| Reported to Dept: | 3/9/2000 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/9/2000 |
| Spill Record Last Update: | 11/16/2005 |
| Spiller Name: | Not reported |
| Spiller Company: | MAZZOLA BAKERY |
| Spiller Address: | 192 UNION ST |
| Spiller City,St,Zip: | BROOKLYN, NY 11590- |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Contact Phone: | (718) 643-1719 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"3/9/00Spoke to Rose at Petro.She sent a service man over to the bakery,she will call DEC when she knows what is leaking.She said the oil is leaking into the basement.01/26/04Reassigned from Rommel to Austin02/17/04: Reassigned from AUSTIN to KRIMGOLD.Assigned to Maloney as part of the Spill InitiativeJuly 13, 2005 - Called bakery and left message for owner to call back ~MaloneyJuly 28, 2005 - Called bakery and left message for owner to call back ~MaloneyAugust 3, 2005 - Called bakery and left message for owner to call back ~MaloneyOctober 2005 - Building is now a Chinese Restaurant. No other information available. Site administratively closed. |
| Remarks: | oil coming out of the wall appears that there is a cracked pipe in wall service man on the way |

Material:

| | |
|---|---|
| Site ID: | 116657 |

**MAZZOLA BAKERY (Continued)** **S104510650**

| | |
|---|---|
| Operable Unit ID: | 1088425 |
| Operable Unit: | 01 |
| Material ID: | 292175 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 3 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AY456** **GRACE CHURCH** **FINDS** **1005622097**
**NE** **254 HICKS STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.220 mi.**
**1161 ft.** **Site 10 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

FINDS:

Registry ID: 110011497656

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

---

**AY457** **GRACE CHURCH** **FTTS** **1007279702**
**NE** **254 HICKS ST** **HIST FTTS** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.220 mi.**
**1161 ft.** **Site 11 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

FTTS INSP:

| | |
|---|---|
| Inspection Number: | 19980511N2005 1 |
| Region: | 02 |
| Inspection Date: | 05/11/98 |
| Inspector: | L. STEBER |
| Violation occurred: | Yes |
| Investigation Type: | AHERA, Enforcement, SEE Conducted |
| Investigation Reason: | For Cause, Private Citizen/Press Complaint |
| Legislation Code: | TSCA |
| Facility Function: | User |

HIST FTTS INSP:

| | |
|---|---|
| Inspection Number: | 19980511N2005 1 |
| Region: | 02 |

**GRACE CHURCH (Continued)** **1007279702**

Inspection Date: Not reported
Inspector: L. STEBER
Violation occurred: Yes
Investigation Type: AHERA, Enforcement, SEE Conducted
Investigation Reason: For Cause, Private Citizen/Press Complaint
Legislation Code: TSCA
Facility Function: User

---

**AY458** **GRACE CHURCH** **RCRA-CESQG** **1016451759**
**NE** **254 HICKS ST** **NYR000203513**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.220 mi.**
**1161 ft.** **Site 12 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

RCRA-CESQG:
Date form received by agency: 10/23/2013
Facility name: GRACE CHURCH
Facility address: 254 HICKS ST
BROOKLYN, NY 11201
EPA ID: NYR000203513
Mailing address: HICKS ST
BROOKLYN, NY 11201
Contact: THOMAS H PACE JR
Contact address: HICKS ST
BROOKLYN, NY 11201
Contact country: US
Contact telephone: (917) 370-6683
Contact email: TPACE67@GMAIL.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: RECTOR WARDENS & VESTRY GRACE CHURCH
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/1847
Owner/Op end date: Not reported

**GRACE CHURCH (Continued)** **1016451759**

Owner/operator name: GRACE CHURCH BROOKLYN HEIGHTS
Owner/operator address: HICKS ST
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 624-1850
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/01/1847
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

---

**AY459** **GRACE EPISCOPAL CHURCH** **NY UST** **U003800439**
**NE** **254 HICKS STREET** **NY HIST UST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.220 mi.**
**1161 ft.** **Site 13 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

UST:
Id/Status: 2-606667 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 2006/08/14
UTM X: 584810.72227999999
UTM Y: 4505212.7062499998
Site Type: School

Affiliation Records:
Site Id: 28525
Affiliation Type: Facility Owner
Company Name: RECTOR, WARDENS & VESTRY
Contact Type: Not reported
Contact Name: Not reported
Address1: 254 HICKS STREET
Address2: Not reported
City: BROOKLYN

**GRACE EPISCOPAL CHURCH (Continued)** **U003800439**

State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 624-1850
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28525
Affiliation Type: Mail Contact
Company Name: GRACE CHURCH
Contact Type: Not reported
Contact Name: THE REV. NILS BLATZ
Address1: 254 HICKS STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 624-1851
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28525
Affiliation Type: On-Site Operator
Company Name: GRACE EPISCOPAL CHURCH
Contact Type: Not reported
Contact Name: JOSE CARDONA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 624-1850
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28525
Affiliation Type: Emergency Contact
Company Name: RECTOR, WARDENS & VESTRY
Contact Type: Not reported
Contact Name: THE REV. NILS BLATZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 624-1850
EMail: Not reported
Fax Number: Not reported

**GRACE EPISCOPAL CHURCH (Continued)** **U003800439**

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 1
Tank ID: 61738
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 18
Date Test: 02/13/2003
Next Test Date: 02/13/2008
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

HIST UST:

PBS Number: 2-606667
SPDES Number: Not reported
Emergency Contact: THE REV. NILS BLATZ
Emergency Telephone: (718) 624-1850
Operator: JOSE CARDONA
Operator Telephone: (718) 624-1850
Owner Name: RECTOR, WARDENS & VESTRY
Owner Address: 254 HICKS STREET
Owner City,St,Zip: BROOKLYN, NY 11201
Owner Telephone: (718) 624-1850
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: GRACE CHURCH
Mailing Address: 254 HICKS STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11201
Mailing Contact: THE REV. NILS BLATZ
Mailing Telephone: (718) 624-1851
Owner Mark: First Owner

**GRACE EPISCOPAL CHURCH (Continued)** **U003800439**

| | |
|---|---|
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Facility Addr2: | Not reported |
| SWIS ID: | 6101 |
| Old PBS Number: | Not reported |
| Facility Type: | SCHOOL |
| Facility Type: | OTHER |
| Inspected Date: | Not reported |
| Inspector: | Not reported |
| Inspection Result: | Not reported |
| Federal ID: | Not reported |
| Certification Flag: | False |
| Certification Date: | 08/17/2001 |
| Expiration Date: | 08/14/2006 |
| Renew Flag: | False |
| Renewal Date: | Not reported |
| Total Capacity: | 3000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | Minor Data Missing |
| Tank Screen: | No Missing Data |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City: | 01 |
| Region: | 2 |

| | |
|---|---|
| Tank Id: | 1 |
| Tank Location: | UNDERGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (gals): | 3000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | None |
| Tank External: | None |
| Pipe Location: | Underground |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | None |
| Pipe External: | None |
| Second Containment: | None |
| Leak Detection: | None |
| Overfill Prot: | Vent Whistle |
| Dispenser: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | 12/27/1987 |
| Missing Data for Tank: | No Missing Data |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | True |
| Lat/long: | Not reported |

**AY460** **GRACE CHURCH** **NY MANIFEST** **S116045912**
**NE** **254 HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.220 mi.**
**1161 ft.** **Site 14 of 14 in cluster AY**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYR000203513 |
| Country: | USA |
| Mailing Name: | GRACE CHURCH |
| Mailing Contact: | GRACE CHURCH |
| Mailing Address: | 254 HICKS ST |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11201 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-244-2800 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 28-Oct-2013 00:00:00 |
| Trans1 Recv Date: | 28-Oct-2013 00:00:00 |
| Trans2 Recv Date: | 01-Nov-2013 00:00:00 |
| TSD Site Recv Date: | 02-Nov-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 770 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 14 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000632561PSC |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**GRACE CHURCH (Continued)** **S116045912**

| | |
|---|---|
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 13-Dec-2013 00:00:00 |
| Trans1 Recv Date: | 13-Dec-2013 00:00:00 |
| Trans2 Recv Date: | 17-Dec-2013 00:00:00 |
| TSD Site Recv Date: | 18-Dec-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 715 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 13 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000657260PSC |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 11-Oct-2013 00:00:00 |
| Trans1 Recv Date: | 11-Oct-2013 00:00:00 |
| Trans2 Recv Date: | 14-Oct-2013 00:00:00 |
| TSD Site Recv Date: | 15-Oct-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 220 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 4 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 006691319FLE |

**GRACE CHURCH (Continued)** **S116045912**

| | |
|---|---|
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 2013-10-28 |
| Trans1 Recv Date: | 2013-10-28 |
| Trans2 Recv Date: | 2013-11-01 |
| TSD Site Recv Date: | 2013-11-02 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 770 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 14 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000632561PSC |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 2013-12-13 |
| Trans1 Recv Date: | 2013-12-13 |
| Trans2 Recv Date: | 2013-12-17 |
| TSD Site Recv Date: | 2013-12-18 |

**GRACE CHURCH (Continued)** **S116045912**

| | |
|---|---|
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 715 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 13 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 000657260PSC |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD082785429 |
| Trans2 State ID: | PAD982661381 |
| Generator Ship Date: | 2013-10-11 |
| Trans1 Recv Date: | 2013-10-11 |
| Trans2 Recv Date: | 2013-10-14 |
| TSD Site Recv Date: | 2013-10-15 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYR000203513 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | RID040098352 |
| Waste Code: | Not reported |
| Quantity: | 220 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 4 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 006691319FLE |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |

**GRACE CHURCH (Continued)** **S116045912**

| | |
|---|---|
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**BC461** **CON EDISON** **NY MANIFEST** **S113816707**
**ENE** **119 PACIFIC ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11215**
**0.220 mi.**
**1161 ft.** **Site 12 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**45 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004331922 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 19-Jul-2013 00:00:00 |
| Trans1 Recv Date: | 19-Jul-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 22-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331922 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084478GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |

**CON EDISON (Continued)** **S113816707**

| | |
|---|---|
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 19-Jul-2013 00:00:00 |
| Trans1 Recv Date: | 19-Jul-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 22-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331922 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084478GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-07-19 |
| Trans1 Recv Date: | 2013-07-19 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-07-22 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331922 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |

**CON EDISON (Continued)** **S113816707**

| | |
|---|---|
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084478GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

---

**BC462** **CON EDISON** **NY MANIFEST** **S113816709**
**ENE** **120 PACIFIC ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11215**
**0.221 mi.**
**1168 ft.** **Site 13 of 13 in cluster BC**

**Relative:**
**Higher**

**Actual:**
**45 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004331948 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 19-Jul-2013 00:00:00 |
| Trans1 Recv Date: | 19-Jul-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 22-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331948 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |

**CON EDISON (Continued)** **S113816709**

| | |
|---|---|
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084692GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 19-Jul-2013 00:00:00 |
| Trans1 Recv Date: | 19-Jul-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 22-Jul-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331948 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084692GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |

**CON EDISON (Continued)** **S113816709**

| | |
|---|---|
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-07-19 |
| Trans1 Recv Date: | 2013-07-19 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-07-22 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004331948 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002084692GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

---

**BE463** **CLOSED IN LOT** **NY Spills** **S108467193**
**SSW** **35 DELVAN STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.222 mi.**
**1171 ft.** **Site 8 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**9 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0614015 |
| Facility Type: | ER |
| DER Facility ID: | 328673 |
| Site ID: | 379182 |
| DEC Region: | 2 |
| Spill Date: | 3/30/2007 |
| Spill Number/Closed Date: | 0614015 / 4/5/2007 |
| Spill Cause: | Housekeeping |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | hrpatel |
| Referred To: | Not reported |
| Reported to Dept: | 3/30/2007 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |

**CLOSED IN LOT (Continued)** **S108467193**

| | |
|---|---|
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/30/2007 |
| Spill Record Last Update: | 4/5/2007 |
| Spiller Name: | DENNIS HUACON |
| Spiller Company: | CLOSED IN LOT |
| Spiller Address: | 35 DELVAN STREET |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 001 |
| Contact Name: | DENNIS HUACON |
| Contact Phone: | (347) 865-1238 CELL |
| DEC Memo: | Patel will visit within the next few days04/05/07-Hiralkumar Patel. visited site yesterday. found no oil leak from any truck on site. no sheen observed on rainy water from parking lot. entire parking lot has concrete floor. based on site observations, case closed. |
| Remarks: | THERE ARE BOTTLE OF ANIFREEZE LAYING ON GROUND AND OIL DRIPPING FROM TRUCKS BEING PARKED THERE: DENNIS DID GO CHECK OUT AND THINKS DEC SHOULD CHECK IT OUT: ( HE WENT OVER THE WEEKEND) |

Material:

| | |
|---|---|
| Site ID: | 379182 |
| Operable Unit ID: | 1136672 |
| Operable Unit: | 01 |
| Material ID: | 2126619 |
| Material Code: | 0043A |
| Material Name: | ANTIFREEZE |
| Case No.: | Not reported |
| Material FA: | Other |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |
| Site ID: | 379182 |
| Operable Unit ID: | 1136672 |
| Operable Unit: | 01 |
| Material ID: | 2126618 |
| Material Code: | 0015 |
| Material Name: | Motor Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**464**
**South**
**1/8-1/4**
**0.223 mi.**
**1177 ft.**

**DRUM RUN**
**HICKS ST & SUMMIT ST**
**BROOKLYN, NY**

**NY Spills** **S110308155**
**N/A**

**Relative:**
**Higher**

**Actual:**
**30 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1000727 |
| Facility Type: | ER |
| DER Facility ID: | 388307 |
| Site ID: | 433405 |
| DEC Region: | 2 |
| Spill Date: | 4/19/2010 |
| Spill Number/Closed Date: | 1000727 / 5/5/2010 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | HRAHMED |
| Referred To: | Not reported |
| Reported to Dept: | 4/19/2010 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 4/19/2010 |
| Spill Record Last Update: | 5/5/2010 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | SHAWN PARKER |
| Contact Phone: | (718) 965-8269 |
| DEC Memo: | Sangesland tried calling FD HAZMAT at the number provided - got no answer.Since it's called in by the FD HAZMAT - assume it really is waste oil and is added to Drum Run list.05/05/10-HRAHMED-No drum was found during DRUM RUN on 4/23/10. DEP and Sanitation was notified.This case is closed. |
| Remarks: | Container is on sidewalk, waiting for pick up ref # 1850 18945 |

Material:

| | |
|---|---|
| Site ID: | 433405 |
| Operable Unit ID: | 1184294 |
| Operable Unit: | 01 |
| Material ID: | 2178535 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |

**DRUM RUN (Continued)** **S110308155**

Oxygenate: False

Tank Test:

---

**BE465** **CONSOLIDATED EDISON** **NY MANIFEST** **1009240620**
**SSW** **V2218 22 DELAVAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.223 mi.**
**1179 ft.** **Site 9 of 9 in cluster BE**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004082709 |
| Country: | USA |
| Mailing Name: | CONSOLIDATED EDISON |
| Mailing Contact: | FRANKLIN MURRAY |
| Mailing Address: | 4 IRVING PLACE RM 828 |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-2808 |

| | |
|---|---|
| Document ID: | NYE0710793 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/16/2001 |
| Trans1 Recv Date: | 05/16/2001 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/16/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004082709 |
| Trans1 EPA ID: | NYD980593636 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | GX3213 |
| Waste Code: | B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB |
| Quantity: | 01691 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 2001 |

**BJ466** **19 GRACE OWNERS CORP.** **NY AST** **A100291665**
**NNE** **19 GRACE COURT** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.224 mi.**
**1181 ft.** **Site 5 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**53 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-609432 |
| Program Type: | PBS |
| UTM X: | 584724.18417999998 |
| UTM Y: | 4505298.4807599997 |
| Expiration Date: | 2014/01/20 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 31276 |
| Affiliation Type: | Facility Owner |
| Company Name: | 19 GRACE OWNERS CORP. |
| Contact Type: | AGENT |
| Contact Name: | JACOB EISENSTEIN |
| Address1: | 1302 46TH ST., 3RD FL. |
| Address2: | Not reported |
| City: | BROOKLYN |
| State: | NY |
| Zip Code: | 11219 |
| Country Code: | 001 |
| Phone: | (718) 972-7879 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/29/2008 |

| | |
|---|---|
| Site Id: | 31276 |
| Affiliation Type: | Mail Contact |
| Company Name: | GRACE OWNERS CORP |
| Contact Type: | Not reported |
| Contact Name: | EK REALTY, LLC |
| Address1: | 939 8TH AVE |
| Address2: | SUITE 301 |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10019 |
| Country Code: | 001 |
| Phone: | (212) 957-1770 |
| EMail: | JACOB@EKREALTYLLC.COM |
| Fax Number: | Not reported |
| Modified By: | MSBAPTIS |
| Date Last Modified: | 10/29/2008 |

| | |
|---|---|
| Site Id: | 31276 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 19 GRACE OWNERS CORP. |
| Contact Type: | Not reported |
| Contact Name: | ZECK QOSAH |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |

**19 GRACE OWNERS CORP. (Continued)** **A100291665**

| | |
|---|---|
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 624-7769 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

| | |
|---|---|
| Site Id: | 31276 |
| Affiliation Type: | Emergency Contact |
| Company Name: | 19 GRACE OWNERS CORP. |
| Contact Type: | Not reported |
| Contact Name: | AVI COHEN |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 972-7879 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 67438 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 06/01/1975 |
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | MSBAPTIS |

**19 GRACE OWNERS CORP. (Continued)** **A100291665**

Last Modified: 10/29/2008
Material Name: #2 Fuel Oil (On-Site Consumption)

---

**BJ467** **APARTMENT BUILDING** **NY Spills** **S106736671**
**NNE** **19 GRACE COURT** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.224 mi.**
**1181 ft.** **Site 6 of 6 in cluster BJ**

**Relative:**
**Higher**

**Actual:**
**53 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0410977 |
| Facility Type: | ER |
| DER Facility ID: | 271413 |
| Site ID: | 336080 |
| DEC Region: | 2 |
| Spill Date: | 12/30/2004 |
| Spill Number/Closed Date: | 0410977 / 3/18/2005 |
| Spill Cause: | Unknown |
| Spill Class: | Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SMSANGES |
| Referred To: | Not reported |
| Reported to Dept: | 1/8/2005 |
| CID: | 38 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/10/2005 |
| Spill Record Last Update: | 3/18/2005 |
| Spiller Name: | TRUSZKOWSKI,BARBARA |
| Spiller Company: | APARTMENT BUILDING |
| Spiller Address: | 19 GRACE COURT |
| Spiller City,St,Zip: | BROOKLYN, NY 11201 |
| Spiller Company: | 001 |
| Contact Name: | TRUSZKOWSKI,BARBARA |
| Contact Phone: | (718) 852-3226 |
| DEC Memo: | Call to super says boiler repair work was done in basement. Work is complete |
| Remarks: | TENNANT IN APT BUILDING. REPORTS SOME TYPE OF FUEL OIL SPILL OCCURRED. ODOR STILL PRESENT NOT GOING AWAY. |

Material:

| | |
|---|---|
| Site ID: | 336080 |
| Operable Unit ID: | 1098128 |
| Operable Unit: | 01 |
| Material ID: | 578298 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |

**APARTMENT BUILDING (Continued)** **S106736671**

| | |
|---|---|
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BO468** **CON EDISON** **NY MANIFEST** **S116294029**
**SSE** **164 PRESIDENT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.224 mi.**
**1185 ft.** **Site 1 of 2 in cluster BO**

**Relative:**
**Higher**

**Actual:**
**37 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004452207 |
| Country: | USA |
| Mailing Name: | Not reported |
| Mailing Contact: | Not reported |
| Mailing Address: | Not reported |
| Mailing Address 2: | Not reported |
| Mailing City: | Not reported |
| Mailing State: | Not reported |
| Mailing Zip: | Not reported |
| Mailing Zip4: | Not reported |
| Mailing Country: | Not reported |
| Mailing Phone: | Not reported |

NY MANIFEST:

No Manifest Records Available

---

**BI469** **MANHOLE #57915** **NY Spills** **S103827223**
**South** **WOODHULL ST E OF HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.226 mi.**
**1194 ft.** **Site 3 of 4 in cluster BI**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9812670 |
| Facility Type: | ER |
| DER Facility ID: | 82612 |
| Site ID: | 91978 |
| DEC Region: | 2 |
| Spill Date: | 1/13/1999 |
| Spill Number/Closed Date: | 9812670 / 10/17/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 1/13/1999 |
| CID: | 384 |
| Water Affected: | Not reported |

**MANHOLE #57915 (Continued)** **S103827223**

| | |
|---|---|
| Spill Source: | Unknown |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/13/1999 |
| Spill Record Last Update: | 10/17/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"e2mis no. 122-421:17:36 1/13/98 A.MARCHIONE #14459 CABLE BR. REPORTED FINDING 1 QT.UNKNOWN OIL ON TOP OF 50 GAL. WATER IN MH57915 S/S WOODHULLST. 26'E/O HICKS ST. NO SEWERS OR WATERWAYS AFFECTED. SPILL WAS DISCOVERED WHILE GOING TO PULL PRI. CABLE. JOINT REGULATOR IN HOLE LOOKS O.K. SUMP IN HOLE CAN NOT TELL IF IT IS HOOKED UP TO SEWER. A SAMPLE WAS TAKEN PUT IN FOR 4-6 HRS. PRIORITY. BULLITT TO PICK UP SAMPLE. INSTALLED E.S.TAG #14384.LAB RESULT RECEIVED 1/14/99 - 0845. 6 PPM.UPDATE: 1/14/99 - 1215 J. RUSSO - 58886 - ENV. OPS., REPORTS 6 PPM CLEANUP COMPLETE WITH SLIX AND TAG #14384 REMOVED. SUMP WAS FOUND CLOGGED AND WAS CLEANED. INCIDENT IS CLOSED. |
| Remarks: | CON EDISON #122421 SAMPLES TAKEN AND CLEAN UP PENDING RESULTS. NO SEWERS OR WATERWAYS. |

Material:

| | |
|---|---|
| Site ID: | 91978 |
| Operable Unit ID: | 1069919 |
| Operable Unit: | 01 |
| Material ID: | 312950 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**BP470**
**SSW**
**1/8-1/4**
**0.229 mi.**
**1207 ft.**

**CON EDISON MANHOLE: 43937**
**VERONA & RICHARDS ST**
**BROOKLYN, NY**

**Site 1 of 4 in cluster BP**

**Relative: Higher**

**Actual: 8 ft.**

**FINDS** **1016407204**
**N/A**

FINDS:

Registry ID: 110055436880

Environmental Interest/Information System

---

**BP471**
**SSW**
**1/8-1/4**
**0.229 mi.**
**1207 ft.**

**CON EDISON MANHOLE: 43937**
**VERONA & RICHARDS ST**
**BROOKLYN, NY 11231**

**Site 2 of 4 in cluster BP**

**Relative: Higher**

**Actual: 8 ft.**

**RCRA-CESQG** **1016149834**
**NYP004285003**

RCRA-CESQG:

| | |
|---|---|
| Date form received by agency: | 01/23/2013 |
| Facility name: | CON EDISON MANHOLE: 43937 |
| Facility address: | VERONA & RICHARDS ST<br>BROOKLYN, NY 11231 |
| EPA ID: | NYP004285003 |
| Mailing address: | IRVING PL, RM 828<br>NEW YORK, NY 10003 |
| Contact: | ANTHONY SIGNORE |
| Contact address: | Not reported<br>Not reported |
| Contact country: | Not reported |
| Contact telephone: | (718) 802-3008 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Conditionally Exempt Small Quantity Generator |
| Description: | Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |
| Used oil fuel burner: | No |

**CON EDISON MANHOLE: 43937 (Continued)** **1016149834**

| | |
|---|---|
| Used oil processor: | No |
| User oil refiner: | No |
| Used oil fuel marketer to burner: | No |
| Used oil Specification marketer: | No |
| Used oil transfer facility: | No |
| Used oil transporter: | No |

Violation Status: No violations found

---

**BP472** **CON EDISON** **NY MANIFEST** **S113494810**
**SSW** **VERONA ST & RICHARDS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11234**
**0.229 mi.**
**1207 ft.** **Site 3 of 4 in cluster BP**

**Relative:**
**Higher**

**Actual:**
**8 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004285003 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 23-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 23-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285003 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001676234GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | Y |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |

**CON EDISON (Continued)** **S113494810**

| | |
|---|---|
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 23-Jan-2013 00:00:00 |
| Trans1 Recv Date: | 23-Jan-2013 00:00:00 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07-Feb-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285003 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001676234GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | Y |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 2013-01-23 |
| Trans1 Recv Date: | 2013-01-23 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 2013-02-07 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004285003 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |

**CON EDISON (Continued)** **S113494810**

| | |
|---|---|
| Waste Code: | Not reported |
| Quantity: | 400 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 001676234GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | Y |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H141 |

---

**BF473** **NYSDOT CONTRACT D252284** **RCRA NonGen / NLR** **1000554736**
**South** **373 COLUMBIA ST** **FINDS** **NYD986972115**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.229 mi.**
**1209 ft.** **Site 4 of 7 in cluster BF**

**Relative:**
**Higher**

**Actual:**
**14 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | NYSDOT CONTRACT D252284 |
| Facility address: | 373 COLUMBIA ST<br>BROOKLYN, NY 11231 |
| EPA ID: | NYD986972115 |
| Mailing address: | HUNTERS POINT PLZ<br>LONG ISLAND CITY, NY 11101 |
| Contact: | PHILIP SALERNO |
| Contact address: | HUNTERS POINT PLZ<br>LONG ISLAND CITY, NY 11101 |
| Contact country: | US |
| Contact telephone: | (718) 802-0180 |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | NYSDOT |
| Owner/operator address: | 51 CHAMBERS ST<br>NEW YORK, NY 10017 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 566-6620 |
| Legal status: | Municipal |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | NYSDOT |

**NYSDOT CONTRACT D252284 (Continued)** **1000554736**

Owner/operator address: 51 CHAMBERS ST
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: (212) 566-6620
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYSDOT CONTRACT D252284
Classification: Not a generator, verified

Date form received by agency: 10/03/1991
Facility name: NYSDOT CONTRACT D252284
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110004476807

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**474**
**SE**
**1/8-1/4**
**0.230 mi.**
**1213 ft.**

**CON EDISON**
**228 SACKETT ST**
**BROOKLYN, NY 11201**

**NY MANIFEST** **S113918803**
**N/A**

**Relative:**
**Higher**

**Actual:**
**38 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004348462 |
| Country: | USA |
| Mailing Name: | CON EDISON |
| Mailing Contact: | CON EDISON |
| Mailing Address: | 4 IRVING PL 15TH FL |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 212-460-3770 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 20-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 20-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 21-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 21-Aug-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004348462 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002086605GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**CON EDISON (Continued)** **S113918803**

| | |
|---|---|
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 20-Aug-2013 00:00:00 |
| Trans1 Recv Date: | 20-Aug-2013 00:00:00 |
| Trans2 Recv Date: | 21-Aug-2013 00:00:00 |
| TSD Site Recv Date: | 21-Aug-2013 00:00:00 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004348462 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002086605GBF |
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 2013-08-20 |
| Trans1 Recv Date: | 2013-08-20 |
| Trans2 Recv Date: | 2013-08-21 |
| TSD Site Recv Date: | 2013-08-21 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004348462 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD991291105 |
| Waste Code: | Not reported |
| Quantity: | 100 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Year: | 2013 |
| Manifest Tracking Num: | 002086605GBF |

**CON EDISON (Continued)** **S113918803**

| | |
|---|---|
| Import Ind: | N |
| Export Ind: | N |
| Discr Quantity Ind: | N |
| Discr Type Ind: | N |
| Discr Residue Ind: | N |
| Discr Partial Reject Ind: | N |
| Discr Full Reject Ind: | N |
| Manifest Ref Num: | Not reported |
| Alt Fac RCRA Id: | Not reported |
| Alt Fac Sign Date: | Not reported |
| Mgmt Method Type Code: | H110 |

---

**BG475** **AERIAL XFMR ON POLE #67195 HAS LEAK.** **NY Spills** **S108956438**
**SSW** **IN FRONT OF 284 VAN BRUNT STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.230 mi.**
**1217 ft.** **Site 3 of 5 in cluster BG**

**Relative:**
**Lower**

**Actual:**
**4 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0708562 |
| Facility Type: | ER |
| DER Facility ID: | 339060 |
| Site ID: | 389480 |
| DEC Region: | 2 |
| Spill Date: | 11/6/2007 |
| Spill Number/Closed Date: | 0708562 / 11/27/2007 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | gdbreen |
| Referred To: | Not reported |
| Reported to Dept: | 11/6/2007 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 11/6/2007 |
| Spill Record Last Update: | 11/27/2007 |
| Spiller Name: | ERTSDESK |
| Spiller Company: | CON EDISON |
| Spiller Address: | 284 VAN BRUNT ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | ERTSDESK |
| Contact Phone: | (212) 580-8383 |
| DEC Memo: | 11/27/07 - See eDocs for Con Ed report detailing cleanup and closure.208802. see eDocs |
| Remarks: | NON PCB; 4 OUNCES RELEASED; DIAPERS IN PLACE; CREWS IN ROUTE TO PREFORM CLEAN UP; IT SPILLED ON TO STREET AND CARS; REF #208802 |

Material:

**AERIAL XFMR ON POLE #67195 HAS LEAK. (Continued)** **S108956438**

| | |
|---|---|
| Site ID: | 389480 |
| Operable Unit ID: | 1146621 |
| Operable Unit: | 01 |
| Material ID: | 2136993 |
| Material Code: | 2630 |
| Material Name: | Mineral Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**AZ476** **EDR US Hist Cleaners** **1015022118**
**SE** **226 DEGRAW ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.232 mi.**
**1225 ft.** **Site 5 of 5 in cluster AZ**

**Relative:**
**Higher**

**Actual:**
**36 ft.**

EDR Historical Cleaners:

| | |
|---|---|
| Name: | LENNYS STEAM CARPET CLEANING |
| Year: | 2010 |
| Address: | 226 DEGRAW ST |

---

**BI477** **MANHOLE 57915** **NY Spills** **S106010773**
**South** **WOODHULL ST & HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.232 mi.**
**1225 ft.** **Site 4 of 4 in cluster BI**

**Relative:**
**Higher**

**Actual:**
**25 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 0210466 |
| Facility Type: | ER |
| DER Facility ID: | 138526 |
| Site ID: | 164278 |
| DEC Region: | 2 |
| Spill Date: | 1/17/2003 |
| Spill Number/Closed Date: | 0210466 / 2/26/2003 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KMFOLEY |
| Referred To: | Not reported |
| Reported to Dept: | 1/17/2003 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |

**MANHOLE 57915 (Continued)** **S106010773**

| | |
|---|---|
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/17/2003 |
| Spill Record Last Update: | 2/26/2003 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ - |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY"Con Ed e2mis #146781:1/17/03 - 0945J. LIPORI - ENV. OPS., REPORTS FINDING APPROX 2 QTS OF A THICK UNKNOWN OIL ON THE COMPACTED EARTHEN SUMP OF MH57915. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO PRIVATE PROPERTY AFFECTED. TAG # 36521 PLACED IN STRUCTURE. NO WATER. NO SEWER CONNECTIONS. NO SUBSTANTIAL CRACKS IN STRUCTURE. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # CC16325 FILLED OUT AND MARKED 'E' (WITHIN 8 HRS) PRIORITY. CLEANUP PENDING LAB RESULT.1/17/03=200hrs LAB RESULT RETURNED 6PPM LSN#004811/18/03=0400HRS K.HUFFORD ENVIR OPS REPORTS CLEANUP COMPLETED USING BIO-GEN 760 . DOUBLE WASHED STRUCTURE . CEMENTED SUMP.ENVIR TAG # 35521 REMOVED. |
| Remarks: | 2 QTS UNK OIL. CON ED #146781. ERTHIN SUMP IN MANHOLE. |

Material:

| | |
|---|---|
| Site ID: | 164278 |
| Operable Unit ID: | 863901 |
| Operable Unit: | 01 |
| Material ID: | 513848 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BF478** **EDR US Hist Auto Stat** **1015299151**
**South** **2 DWIGHT ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.232 mi.**
**1227 ft.** **Site 5 of 7 in cluster BF**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | A & B AUTO COLLISION |
| Year: | 1999 |
| Address: | 2 DWIGHT ST |
| Name: | A & B AUTO COLLISION |
| Year: | 2000 |

**(Continued)** **1015299151**

Address: 2 DWIGHT ST

Name: A & B AUTO COLLISION
Year: 2001
Address: 2 DWIGHT ST

Name: A & B AUTO COLLISION
Year: 2002
Address: 2 DWIGHT ST

Name: A & B AUTO COLLISION
Year: 2003
Address: 2 DWIGHT ST

---

**BK479** **269 HENRY STREET** **NY AST** **A100291973**
**ENE** **269 HENRY STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.233 mi.**
**1232 ft.** **Site 3 of 3 in cluster BK**

**Relative:**
**Higher**

**Actual:**
**62 ft.**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608828
Program Type: PBS
UTM X: 584823.66429999995
UTM Y: 4504926.8094899999
Expiration Date: 2015/05/31
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 30677
Affiliation Type: On-Site Operator
Company Name: 269 HENRY STREET
Contact Type: Not reported
Contact Name: LUIS MONTEMUIRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 783-6804
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 6/27/2007

Site Id: 30677
Affiliation Type: Emergency Contact
Company Name: NEERA RAJ
Contact Type: Not reported
Contact Name: LUIS MONTEMUIRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

**269 HENRY STREET (Continued)** **A100291973**

| | |
|---|---|
| Zip Code: | Not reported |
| Country Code: | 999 |
| Phone: | (917) 783-3804 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DXLIVING |
| Date Last Modified: | 6/27/2007 |

| | |
|---|---|
| Site Id: | 30677 |
| Affiliation Type: | Mail Contact |
| Company Name: | 269 HENRY ST. ASSOCIATES, LLC |
| Contact Type: | Not reported |
| Contact Name: | MANAGEMENT |
| Address1: | PO BOX 1454 |
| Address2: | Not reported |
| City: | PRINCETON |
| State: | NJ |
| Zip Code: | 08542 |
| Country Code: | 001 |
| Phone: | (609) 497-9051 |
| EMail: | PLAYKAN@AOL.COM |
| Fax Number: | Not reported |
| Modified By: | DXLIVING |
| Date Last Modified: | 6/27/2007 |

| | |
|---|---|
| Site Id: | 30677 |
| Affiliation Type: | Facility Owner |
| Company Name: | NEERA RAJ |
| Contact Type: | OWNER |
| Contact Name: | NEERA RAJ |
| Address1: | 190 BROOKS BEND |
| Address2: | Not reported |
| City: | PRINCETON |
| State: | NJ |
| Zip Code: | 08542 |
| Country Code: | 001 |
| Phone: | (609) 497-9051 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | DXLIVING |
| Date Last Modified: | 6/27/2007 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 65824 |
| Material Code: | ZZZZ |
| Common Name of Substance: | Invalid Material - Please Fix |

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

**269 HENRY STREET (Continued)** **A100291973**

I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | ZZ |
| Tank Status: | Closed - Removed |
| Pipe Model: | Not reported |
| Install Date: | Not reported |
| Capacity Gallons: | 550 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | TRANSLAT |
| Last Modified: | 03/04/2004 |
| Material Name: | Invalid Material - Please Fix |

| | |
|---|---|
| Tank Number: | 002 |
| Tank Id: | 65823 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 01/01/2005 |
| Capacity Gallons: | 3000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | DXLIVING |
| Last Modified: | 06/27/2007 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

**BH480** **HAMILTON AVE & HICKS ST** **NY Spills** **S102146569**
**South** **HAMILTON AVE & HICKS ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.236 mi.**
**1248 ft.** **Site 2 of 2 in cluster BH**

**Relative:**
**Higher**

**Actual:**
**19 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9302895 |
| Facility Type: | ER |
| DER Facility ID: | 227800 |
| Site ID: | 280554 |
| DEC Region: | 2 |
| Spill Date: | 6/3/1993 |
| Spill Number/Closed Date: | 9302895 / 6/3/1993 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | KSTANG |
| Referred To: | Not reported |
| Reported to Dept: | 6/3/1993 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | 6/3/1993 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 6/7/1993 |
| Spill Record Last Update: | 7/19/1993 |
| Spiller Name: | Not reported |
| Spiller Company: | UNK |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ***UPDATE***, ZZ |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"10/10/95: This is additional information about material spilled from the translation of the old spill file: 40' 3'. |
| Remarks: | OIL DISCOV ON ST - NYCDEP ENROUTE - CONCERNED ABOUT OIL RUNNING INTO BATTERY TUNNEL - CALL DEP ASK IF NEED ASSISTANCE BUT DEP DID NOT CALL BACK, COSMO WAS IN SCENE ASSUMED JOB HANDLED BY DEP. |

Material:

| | |
|---|---|
| Site ID: | 280554 |
| Operable Unit ID: | 981207 |
| Operable Unit: | 01 |
| Material ID: | 400006 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 0 |
| Units: | Not reported |
| Recovered: | No |
| Resource Affected: | Not reported |

**HAMILTON AVE & HICKS ST (Continued)** **S102146569**

Oxygenate: False

Tank Test:

---

**481**
**NE**
**1/8-1/4**
**0.237 mi.**
**1253 ft.**

**BEGAY REALTY CO** **NY AST** **U003384218**
**99 JORALEMON ST** **NY HIST AST** **N/A**
**BROOKLYN, NY 11201**

**Relative:**
**Higher**

**Actual:**
**63 ft.**

AST:

| | |
|---|---|
| Region: | STATE |
| DEC Region: | 2 |
| Site Status: | Active |
| Facility Id: | 2-085529 |
| Program Type: | PBS |
| UTM X: | 584876.34562000004 |
| UTM Y: | 4505166.5701400004 |
| Expiration Date: | 2013/08/07 |
| Site Type: | Apartment Building/Office Building |

Affiliation Records:

| | |
|---|---|
| Site Id: | 2057 |
| Affiliation Type: | On-Site Operator |
| Company Name: | 99 JORALEMON ST |
| Contact Type: | Not reported |
| Contact Name: | MONDI GJONI |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (718) 908-8664 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 6/12/2008 |

| | |
|---|---|
| Site Id: | 2057 |
| Affiliation Type: | Emergency Contact |
| Company Name: | JORALEMON HEIGHTS ASSOCS LLC % R A COHEN & ASSOCS |
| Contact Type: | Not reported |
| Contact Name: | DOLORES KARADZAS |
| Address1: | Not reported |
| Address2: | Not reported |
| City: | Not reported |
| State: | NN |
| Zip Code: | Not reported |
| Country Code: | 001 |
| Phone: | (646) 345-7421 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | TRANSLAT |
| Date Last Modified: | 3/4/2004 |

Site Id: 2057

**BEGAY REALTY CO (Continued)** **U003384218**

| | |
|---|---|
| Affiliation Type: | Facility Owner |
| Company Name: | JORALEMON HEIGHTS ASSOCS LLC % R A COHEN & ASSOCS |
| Contact Type: | AGENT |
| Contact Name: | FRED FRAGANO |
| Address1: | 60 E. 42ND ST., #850 |
| Address2: | Not reported |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10165 |
| Country Code: | 001 |
| Phone: | (212) 972-5900 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 6/12/2008 |

| | |
|---|---|
| Site Id: | 2057 |
| Affiliation Type: | Mail Contact |
| Company Name: | % R A COHEN & ASSOCS |
| Contact Type: | Not reported |
| Contact Name: | FRED FRAGANO |
| Address1: | 60 E. 42ND ST., #850 |
| Address2: | SUITE 850 |
| City: | NEW YORK |
| State: | NY |
| Zip Code: | 10165 |
| Country Code: | 001 |
| Phone: | (212) 835-9526 |
| EMail: | Not reported |
| Fax Number: | Not reported |
| Modified By: | msbaptis |
| Date Last Modified: | 6/12/2008 |

Tank Info:

| | |
|---|---|
| Tank Number: | 001 |
| Tank Id: | 3321 |
| Material Code: | 0001 |
| Common Name of Substance: | #2 Fuel Oil (On-Site Consumption) |

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

| | |
|---|---|
| Tank Location: | 1 |
| Tank Type: | Steel/Carbon Steel/Iron |
| Tank Status: | In Service |
| Pipe Model: | Not reported |
| Install Date: | 12/22/1922 |

**BEGAY REALTY CO (Continued)** **U003384218**

| | |
|---|---|
| Capacity Gallons: | 5000 |
| Tightness Test Method: | NN |
| Date Test: | Not reported |
| Next Test Date: | Not reported |
| Date Tank Closed: | Not reported |
| Register: | True |
| Modified By: | msbaptis |
| Last Modified: | 06/12/2008 |
| Material Name: | #2 Fuel Oil (On-Site Consumption) |

HIST AST:

| | |
|---|---|
| PBS Number: | 2-085529 |
| SWIS Code: | 6101 |
| Operator: | LUIS PINEDA |
| Facility Phone: | (718) 643-9014 |
| Facility Addr2: | 99 JORALEMON ST |
| Facility Type: | APARTMENT BUILDING |
| Emergency: | ARNOLD WEINSTEIN |
| Emergency Tel: | (914) 725-4199 |
| Old PBSNO: | Not reported |
| Date Inspected: | Not reported |
| Inspector: | Not reported |
| Result of Inspection: | Not reported |
| Owner Name: | BEGAY REALTY CO |
| Owner Address: | 200 NORTH CENTRAL AVE |
| Owner City,St,Zip: | HARTSDALE, NY 10530 |
| Federal ID: | Not reported |
| Owner Tel: | (914) 328-0420 |
| Owner Type: | Corporate/Commercial |
| Owner Subtype: | Not reported |
| Mailing Contact: | ARNOLD A. WEINSREIN |
| Mailing Name: | BEGAY REALTY CO |
| Mailing Address: | 200 NORTH CENTRAL AVE |
| Mailing Address 2: | Not reported |
| Mailing City,St,Zip: | HARTSDALE, NY 10530 |
| Mailing Telephone: | (914) 328-0420 |
| Owner Mark: | First Owner |
| Facility Status: | 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility. |
| Certification Flag: | False |
| Certification Date: | 02/06/1997 |
| Expiration: | 03/24/2002 |
| Renew Flag: | False |
| Renew Date: | 11/13/2001 |
| Total Capacity: | 5000 |
| FAMT: | True |
| Facility Screen: | No Missing Data |
| Owner Screen: | No Missing Data |
| Tank Screen: | Minor Data Missing |
| Dead Letter: | False |
| CBS Number: | Not reported |
| Town or City: | NEW YORK CITY |
| County Code: | 61 |
| Town or City Code: | 01 |
| Region: | 2 |

**BEGAY REALTY CO (Continued)** **U003384218**

| | |
|---|---|
| Tank ID: | 001 |
| Tank Location: | ABOVEGROUND |
| Tank Status: | In Service |
| Install Date: | Not reported |
| Capacity (Gal): | 5000 |
| Product Stored: | NOS 1,2, OR 4 FUEL OIL |
| Tank Type: | Steel/carbon steel |
| Tank Internal: | Not reported |
| Tank External: | Not reported |
| Pipe Location: | Not reported |
| Pipe Type: | STEEL/IRON |
| Pipe Internal: | Not reported |
| Pipe External: | Not reported |
| Tank Containment: | None |
| Leak Detection: | 0 |
| Overfill Protection: | 4 |
| Dispenser Method: | Suction |
| Date Tested: | Not reported |
| Next Test Date: | Not reported |
| Missing Data for Tank: | Minor Data Missing |
| Date Closed: | Not reported |
| Test Method: | Not reported |
| Deleted: | False |
| Updated: | False |
| SPDES Number: | Not reported |
| Lat/Long: | Not reported |

---

**BQ482** **SPILL NUMBER 9900296** **NY Spills** **S104648819**
**ENE** **136-138 ATLANTIC AVE** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.237 mi.**
**1254 ft.** **Site 1 of 2 in cluster BQ**

**Relative:**
**Higher**

**Actual:**
**55 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9900296 |
| Facility Type: | ER |
| DER Facility ID: | 75647 |
| Site ID: | 81916 |
| DEC Region: | 2 |
| Spill Date: | 4/8/1999 |
| Spill Number/Closed Date: | 9900296 / 4/8/1999 |
| Spill Cause: | Deliberate |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | JXZHAO |
| Referred To: | Not reported |
| Reported to Dept: | 4/8/1999 |
| CID: | 384 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |

**SPILL NUMBER 9900296 (Continued)** **S104648819**

| | |
|---|---|
| Date Entered In Computer: | 4/8/1999 |
| Spill Record Last Update: | 4/8/1999 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Contact Phone: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHAO"REFERRED TO DEP, ECS & INDUSTRIAL WASTE SECTION.REFERRED TO ECO. Not reported |
| Remarks: | an anonymous caller stated that an unknown company was cleaning the outside of building with some type of chemical and it was draining onto the ground and sewers. caller is concerned. |

Material:

| | |
|---|---|
| Site ID: | 81916 |
| Operable Unit ID: | 1079064 |
| Operable Unit: | 01 |
| Material ID: | 307436 |
| Material Code: | 0063A |
| Material Name: | UNKNOWN HAZARDOUS MATERIAL |
| Case No.: | Not reported |
| Material FA: | Hazardous Material |
| Quantity: | 0 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BO483** **MANHOLE 20859** **NY Spills** **S103827403**
**SSE** **HENRY STREET AT PRESIDENT** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.238 mi.**
**1255 ft.** **Site 2 of 2 in cluster BO**

**Relative:**
**Higher**

**Actual:**
**38 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 9812900 |
| Facility Type: | ER |
| DER Facility ID: | 114262 |
| Site ID: | 132749 |
| DEC Region: | 2 |
| Spill Date: | 1/20/1999 |
| Spill Number/Closed Date: | 9812900 / 10/18/2002 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | CAENGELH |
| Referred To: | Not reported |
| Reported to Dept: | 1/20/1999 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |

**MANHOLE 20859 (Continued)** **S103827403**

| | |
|---|---|
| Spill Notifier: | Local Agency |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1/20/1999 |
| Spill Record Last Update: | 10/18/2002 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | NY |
| Spiller Company: | 999 |
| Contact Name: | LISA PRIMEGGIA |
| Contact Phone: | (212) 580-6763 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"e2mis no. 122-559:1/20/99 1040HRS--PANPALEO U/G REPORTS FOUND APPROX.1/2 QUART OF UNKNOWN OIL ON 40' GALLONS OF WATER IN M-20859,CONTAINED NOSEWERS OR WATER WAYS EFFECTED,SAMPLE TAKEN TAG#02688 PLACED.UPDATE: 1/20/99 19:25HRS-LAB SEQ#99-00589-RESULTS <1.00PPM.UPDATE***** 1-21-99 01:15HRS S. DANTONE REPORTS, CLEANUP COMPLETED WITH SLIX & ENV. STOP TAG # 02688 REMOVED. INCIDENT IS CLOSED. |
| Remarks: | 1/2 QUART IN MANHOLE REFERENCE #122579 SAMPLE TAKEN CLEANUP PENDINGLAB RESULTS |

Material:

| | |
|---|---|
| Site ID: | 132749 |
| Operable Unit ID: | 1070146 |
| Operable Unit: | 01 |
| Material ID: | 313173 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | No |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**484**
**SE**
**1/8-1/4**
**0.238 mi.**
**1258 ft.**

**Relative:**
**Higher**

**Actual:**
**33 ft.**

**SACRED HEARTS** **NY LTANKS** **S102673263**
**56 STRONG PLACE** **N/A**
**BROOKLYN, NY**

LTANKS:

| | |
|---|---|
| Site ID: | 253704 |
| Spill Number/Closed Date: | 9514544 / 3/25/1996 |
| Spill Date: | 2/13/1996 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. |

**SACRED HEARTS (Continued)** **S102673263**

| | |
|---|---|
| | Willing Responsible Party. Corrective action taken. |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Standard: | False |
| SWIS: | 2401 |
| Investigator: | MMMULQUE |
| Referred To: | Not reported |
| Reported to Dept: | 2/13/1996 |
| CID: | 282 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2/13/1996 |
| Spill Record Last Update: | 3/26/1996 |
| Spiller Name: | PETER LEPORE |
| Spiller Company: | WALCO FUEL OIL |
| Spiller Address: | 1 COFFEY STREET |
| Spiller City,St,Zip: | BROOKLYN, NY 11231- |
| Spiller County: | 001 |
| Spiller Contact: | N/A |
| Spiller Phone: | (718) 596-7750 |
| Spiller Extention: | Not reported |
| DEC Region: | 2 |
| DER Facility ID: | 207817 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN" |
| Remarks: | TANK WAS OVERFILLED BY THE DRIVER.SPILL WAS CLEANED UP |

Material:

| | |
|---|---|
| Site ID: | 253704 |
| Operable Unit ID: | 1025643 |
| Operable Unit: | 01 |
| Material ID: | 354672 |
| Material Code: | 0001A |
| Material Name: | #2 Fuel Oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1 |
| Units: | Gallons |
| Recovered: | Yes |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

**BM485** **RANDEX CLEANERS** **RCRA-SQG** **1000188681**
**SSE** **534 HENRY ST** **NY MANIFEST** **NYD986886687**
**1/8-1/4** **BROOKLYN, NY 11231** **NY DRYCLEANERS**
**0.241 mi.** **US AIRS**
**1274 ft.** **Site 3 of 5 in cluster BM**

**Relative:**
**Higher**

**Actual:**
**40 ft.**

RCRA-SQG:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | RANDEX CLEANERS |
| Facility address: | 534 HENRY ST<br>BROOKLYN, NY 11231 |
| EPA ID: | NYD986886687 |
| Mailing address: | HENRY ST<br>BROOKLYN, NY 11231 |
| Contact: | Not reported |
| Contact address: | HENRY ST<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Small Small Quantity Generator |
| Description: | Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | UCHUL KARL |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Operator |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

| | |
|---|---|
| Owner/operator name: | UCHUL KARL |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |

Handler Activities Summary:

| | |
|---|---|
| U.S. importer of hazardous waste: | No |
| Mixed waste (haz. and radioactive): | No |
| Recycler of hazardous waste: | No |
| Transporter of hazardous waste: | No |
| Treater, storer or disposer of HW: | No |
| Underground injection activity: | No |
| On-site burner exemption: | No |
| Furnace exemption: | No |

**RANDEX CLEANERS (Continued)** **1000188681**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: RANDEX CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/14/1999
Facility name: RANDEX CLEANERS
Classification: Small Quantity Generator

Date form received by agency: 12/18/1989
Facility name: RANDEX CLEANERS
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD986886687
Country: USA
Mailing Name: RANDEX CLNRS
Mailing Contact: MOON RHEE
Mailing Address: 534 HENRY STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11231
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 716-624-6724

Document ID: NYG5363955
Manifest Status: Not reported
Trans1 State ID: NJD000564906
Trans2 State ID: Not reported
Generator Ship Date: 11/17/2005
Trans1 Recv Date: 11/17/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/18/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986886687
Trans1 EPA ID: NJ420
Trans2 EPA ID: Not reported
TSDF ID: NJD000564906
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00160 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | Not reported |
| Specific Gravity: | 01.00 |
| Waste Code: | Not reported |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYC0333077 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900619 |
| Trans1 Recv Date: | 900619 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900619 |
| Part A Recv Date: | 900801 |
| Part B Recv Date: | 900627 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0295683 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900601 |
| Trans1 Recv Date: | 900601 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900601 |
| Part A Recv Date: | 900726 |
| Part B Recv Date: | 900613 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00120 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYA9593379 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | EU1732NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 900403 |
| Trans1 Recv Date: | 900403 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900403 |
| Part A Recv Date: | 900425 |
| Part B Recv Date: | 900503 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0147936 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900503 |
| Trans1 Recv Date: | 900503 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900503 |
| Part A Recv Date: | 900613 |
| Part B Recv Date: | 900515 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Document ID: | NYC0381666 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900717 |
| Trans1 Recv Date: | 900717 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900717 |
| Part A Recv Date: | 900815 |
| Part B Recv Date: | 900802 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00120 |
| Units: | P - Pounds |
| Number of Containers: | 002 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0439637 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900814 |
| Trans1 Recv Date: | 900814 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900814 |
| Part A Recv Date: | 900830 |
| Part B Recv Date: | 900905 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0641327 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AM6252NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910423 |
| Trans1 Recv Date: | 910423 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910423 |
| Part A Recv Date: | 910503 |

**RANDEX CLEANERS (Continued)** **1000188681**

Part B Recv Date: 910502
Generator EPA ID: NYD986886687
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NYC1030241
Manifest Status: Completed copy
Trans1 State ID: LP3931NY
Trans2 State ID: Not reported
Generator Ship Date: 910620
Trans1 Recv Date: 910620
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910620
Part A Recv Date: 910703
Part B Recv Date: 910629
Generator EPA ID: NYD986886687
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NYC0858925
Manifest Status: Completed copy
Trans1 State ID: AM6252NY
Trans2 State ID: Not reported
Generator Ship Date: 910328
Trans1 Recv Date: 910328
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910328
Part A Recv Date: 910405
Part B Recv Date: 910408
Generator EPA ID: NYD986886687
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYC0707501 |
| Manifest Status: | Completed after the designated time period for a TSDF to get a copy to the DEC |
| Trans1 State ID: | NM8150NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910208 |
| Trans1 Recv Date: | 910208 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910208 |
| Part A Recv Date: | 910228 |
| Part B Recv Date: | 910312 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYC0574571 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | EU1732NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 901106 |
| Trans1 Recv Date: | 901106 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 901106 |
| Part A Recv Date: | 901116 |
| Part B Recv Date: | 901129 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC0484738 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 000000000 |

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Trans2 State ID: | 000000000 |
| Generator Ship Date: | 900913 |
| Trans1 Recv Date: | 900913 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 900913 |
| Part A Recv Date: | 901003 |
| Part B Recv Date: | 900919 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 90 |

| | |
|---|---|
| Document ID: | NYC1179685 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | LP3931NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910607 |
| Trans1 Recv Date: | 910607 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910607 |
| Part A Recv Date: | 910614 |
| Part B Recv Date: | 910617 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYC1251134 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AM6252NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 911011 |
| Trans1 Recv Date: | 911011 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 911011 |
| Part A Recv Date: | 911028 |
| Part B Recv Date: | 911031 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYC0783303 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NYAT8756 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910305 |
| Trans1 Recv Date: | 910305 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910305 |
| Part A Recv Date: | 910315 |
| Part B Recv Date: | 910311 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NYC1131827 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | LP3931NY |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910813 |
| Trans1 Recv Date: | 910813 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910813 |
| Part A Recv Date: | 910823 |
| Part B Recv Date: | 910821 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00060 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |

**RANDEX CLEANERS (Continued)** **1000188681**

Year: 91

Document ID: NYC1317071
Manifest Status: Completed copy
Trans1 State ID: LP3931NY
Trans2 State ID: Not reported
Generator Ship Date: 911106
Trans1 Recv Date: 911106
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911106
Part A Recv Date: Not reported
Part B Recv Date: 911114
Generator EPA ID: NYD986886687
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NYC1085321
Manifest Status: Completed copy
Trans1 State ID: LP3931NY
Trans2 State ID: Not reported
Generator Ship Date: 910717
Trans1 Recv Date: 910717
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910717
Part A Recv Date: 910725
Part B Recv Date: 910726
Generator EPA ID: NYD986886687
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NYC1205728
Manifest Status: Completed copy
Trans1 State ID: LP3931NY
Trans2 State ID: Not reported
Generator Ship Date: 910919
Trans1 Recv Date: 910919

**RANDEX CLEANERS (Continued)** **1000188681**

| | |
|---|---|
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910919 |
| Part A Recv Date: | 911003 |
| Part B Recv Date: | 910926 |
| Generator EPA ID: | NYD986886687 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NYD980785760 |
| Waste Code: | F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV |
| Quantity: | 00195 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 100 |
| Year: | 91 |

Click this hyperlink while viewing on your computer to access
174 additional NY_MANIFEST: record(s) in the EDR Site Report.

DRYCLEANERS:

| | |
|---|---|
| Facility ID: | 2-6102-00190 |
| Phone Number: | 718-624-6724 |
| Region: | Not reported |
| Registration Effective Date: | 1/15/2003 10:39:06:986 |
| Inspection Date: | 07APR27 |
| Install Date: | 00 |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | Not reported |
| Current Business: | Not reported |

AIRS (AFS):

Airs Minor Details:

| | |
|---|---|
| EPA plant ID: | 110002366804 |
| Plant name: | RANDEX CLEANERS |
| Plant address: | 534 HENRY ST<br>BROOKLYN, NY 112312803 |
| County: | KINGS |
| Region code: | 02 |
| Dunn & Bradst #: | Not reported |
| Air quality cntrl region: | 043 |
| Sic code: | 7216 |
| Sic code desc: | DRYCLEANING PLANTS, EXCEPT RUG |
| North Am. industrial classf: | 812320 |
| NAIC code description: | Drycleaning and Laundry Services (except Coin-Operated) |
| Default compliance status: | IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS |
| Default classification: | POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR |
| Govt facility: | ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT |
| Current HPV: | Not reported |

Compliance and Enforcement Major Issues:

**RANDEX CLEANERS (Continued)** **1000188681**

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Historical Compliance Minor Sources:
State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

**RANDEX CLEANERS (Continued)** **1000188681**

Hist compliance date: 1004
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1101
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:
Air program code: MACT (SECTION 63 NESHAPS)

**RANDEX CLEANERS (Continued)** **1000188681**

Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: UNCLASSIFIED
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

---

**BM486** **EDR US Hist Cleaners** **1015073010**
**SSE** **534 HENRY ST** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.241 mi.**
**1274 ft.** **Site 4 of 5 in cluster BM**

**Relative:**
**Higher**

**Actual:**
**40 ft.**

EDR Historical Cleaners:

Name: RANDEX CLEANERS
Year: 2001
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2005
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2006
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2007
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2008
Address: 534 HENRY ST

**(Continued)** **1015073010**

Name: RANDEX CLEANERS
Year: 2009
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2010
Address: 534 HENRY ST

Name: RANDEX CLEANERS
Year: 2011
Address: 534 HENRY ST

Name: RANDEX DRY CLEANING
Year: 2012
Address: 534 HENRY ST

---

**BM487** **RANDEX CLEANERS** **FINDS** **1016064321**
**SSE** **534 HENRY STREET** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.241 mi.**
**1274 ft.** **Site 5 of 5 in cluster BM**

**Relative:**
**Higher**

**Actual:**
**40 ft.**

FINDS:

Registry ID: 110002361738

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BP488** **COURTYARD OF APT COMPLEX** **NY Spills** **S112227320**
**SSW** **5 DELEVAN ST** **N/A**
**1/8-1/4** **BROOKLYN, NY**
**0.242 mi.**
**1278 ft.** **Site 4 of 4 in cluster BP**

**Relative:**
**Higher**

**Actual:**
**10 ft.**

SPILLS:

| | |
|---|---|
| Facility ID: | 1206890 |
| Facility Type: | ER |
| DER Facility ID: | 424220 |
| Site ID: | 469915 |
| DEC Region: | 2 |
| Spill Date: | 10/12/2012 |
| Spill Number/Closed Date: | 1206890 / 10/31/2013 |
| Spill Cause: | Unknown |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | vszhune |
| Referred To: | Not reported |
| Reported to Dept: | 10/12/2012 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 10/12/2012 |
| Spill Record Last Update: | 11/5/2013 |
| Spiller Name: | EDWARD |
| Spiller Company: | PROPERTY OWNER |
| Spiller Address: | 5 DELEVAN ST |
| Spiller City,St,Zip: | BROOKLYN, NY |
| Spiller Company: | 999 |
| Contact Name: | EDWARD |
| Contact Phone: | (917)6279366 |
| DEC Memo: | Cell # for Alan Schenk: 518-328-1762soil sampling and gw sampling - some exceedances foundProperty is being refinanced and bank wanted sampling done.03/20/13- Zhune visited the site met Manny Nazario from LCS 646-425-4854. Manny said they found free product in monitoring well MW-2 less the one quart of gallon. They pumped out the oil. Monitoring well MW-2 was installed in the area were they suspected the 10000 gallons AST was loocated. The buildings are heated via gas natural.04/24/13-Zhune received and reviewed the Phase I prepared by EBI Consulting dated 9/24/12. As per the report the site was used for industrial purposes from at 1904 to 2002. It was occupied by various industrial/manufacturing operations from 1904 that included Chesebrough manufacturing Co.(Vaseline), (1904); American Stopper Co.,(19150, American can Co.,(1938 to 1950) and a luggage company (1918 to 2002). In addition, the site appear to have contained to large aboveground bulk oil storage tanks in the late 1800s, a large aboveground oil recovering tank and a varnish and oil storage building.12/6/12- Zhune received and reviewed the Limited and Focused subsurface Soil and Groundwater Investigation Report sent by LCS inc. dated October 26, 2012.Nine soil borings (BH1 through BH9) were |

**COURTYARD OF APT COMPLEX (Continued)** **S112227320**

installed. Groundwater was encountered within borings BH1 through BH6 and BH8 at depths between 9.5 and 15.3 ft. bgs. Two temporary groundwater monitoring wells (TPMW-1- TPMW-2)were installed with boreholes BH4 and BH1 respectively.The soil analytical results detected two VOCs (Benzene 140 ug/kg and Total Xylenes 650 ug/kg) in sample BH4 exceeding the CP-51 soil cleanup levels and SVOCs (Benzo(a)anthracene 5000 ug/kg, Chrysene 4700 ug/kg, Benzo(b) fluoranthene 6,000 ug/kg, Benzo (K) fluoranthene 2,200 ug/kg, Benzo (a)pyrene 2300 ug/kg )in sample BH5 and (Benzo (a) anthracene 1,800 ug/kg, Chrysene 1700 ug/kg, Benzo(b) fluoranthene 2,800 ug/kg, Benzo (a) pyrene in sample BH7 exceeding the CP-51 soil cleanup levels.The graundawater analytical result detected the following SVOC analytes: Benzo(a)anthracene 2.2 ug/l and Chrysene 2.7 ug /lt at concentrations above the NYSDEC class GA groundwater criteria. No VOCs were dectected at concentration above the regulatory criteria. Spill Closed.

Remarks: just monitoring - no cleanup noted

Material:

| | |
|---|---|
| Site ID: | 469915 |
| Operable Unit ID: | 1219794 |
| Operable Unit: | 01 |
| Material ID: | 2218337 |
| Material Code: | 0066A |
| Material Name: | UNKNOWN PETROLEUM |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Resource Affected: | Not reported |
| Oxygenate: | False |

Tank Test:

---

**BQ489** **EDR US Hist Auto Stat** **1015210537**
**ENE** **134 ATLANTIC AVE** **N/A**
**1/8-1/4** **BROOKLYN, NY 11201**
**0.242 mi.**
**1280 ft.** **Site 2 of 2 in cluster BQ**

**Relative:**
**Higher**

**Actual:**
**55 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | AMOCO |
| Year: | 2005 |
| Address: | 134 ATLANTIC AVE |

**BF490**
**South**
**1/8-1/4**
**0.244 mi.**
**1288 ft.**

**204 HAMILTON AVE**
**BROOKLYN, NY 11231**

**Site 6 of 7 in cluster BF**

**EDR US Hist Auto Stat** **1015310846**
**N/A**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

EDR Historical Auto Stations:

| | |
|---|---|
| Name: | COLLISIONVILLE INCORPORATED BODY SHOP |
| Year: | 1999 |
| Address: | 204 HAMILTON AVE |
| Name: | COLLISIONVILLE INC |
| Year: | 2001 |
| Address: | 204 HAMILTON AVE |
| Name: | VERRAZANO AUTO COLLISION |
| Year: | 2003 |
| Address: | 204 HAMILTON AVE |
| Name: | CERTIFIED AUTO COLLISION |
| Year: | 2004 |
| Address: | 204 HAMILTON AVE |

---

**BF491**
**South**
**1/8-1/4**
**0.244 mi.**
**1288 ft.**

**TOM RUSSO'S SHOP COLLISIONVILLE**
**204 HAMILTON AVE**
**BROOKLYN, NY**

**Site 7 of 7 in cluster BF**

**RCRA NonGen / NLR** **1000286576**
**FINDS** **NYD066073420**
**NY MANIFEST**
**NY Spills**

**Relative:**
**Higher**

**Actual:**
**16 ft.**

RCRA NonGen / NLR:

| | |
|---|---|
| Date form received by agency: | 01/01/2007 |
| Facility name: | COLLISIONVILLE INC |
| Facility address: | 204 HAMILTON AVE<br>BROOKLYN, NY 112311848 |
| EPA ID: | NYD066073420 |
| Mailing address: | HAMILTON AVE<br>BROOKLYN, NY 11231 |
| Contact: | Not reported |
| Contact address: | HAMILTON AVE<br>BROOKLYN, NY 11231 |
| Contact country: | US |
| Contact telephone: | Not reported |
| Contact email: | Not reported |
| EPA Region: | 02 |
| Classification: | Non-Generator |
| Description: | Handler: Non-Generators do not presently generate hazardous waste |

Owner/Operator Summary:

| | |
|---|---|
| Owner/operator name: | TOM RUSSO |
| Owner/operator address: | NOT REQUIRED<br>NOT REQUIRED, WY 99999 |
| Owner/operator country: | US |
| Owner/operator telephone: | (212) 555-1212 |
| Legal status: | Private |
| Owner/Operator Type: | Owner |
| Owner/Op start date: | Not reported |
| Owner/Op end date: | Not reported |
| Owner/operator name: | TOM RUSSO |

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: COLLISIONVILLE INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: COLLISIONVILLE INC
Classification: Not a generator, verified

Date form received by agency: 06/30/1987
Facility name: COLLISIONVILLE INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004364820

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD066073420 |
| Country: | USA |
| Mailing Name: | COLLISIONVILLE INC |
| Mailing Contact: | TOM RUSSO |
| Mailing Address: | 204 HAMILTON AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City: | BROOKLYN |
| Mailing State: | NY |
| Mailing Zip: | 11231 |
| Mailing Zip4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 718-643-1200 |

| | |
|---|---|
| Document ID: | NJA0965567 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NJDEPS103 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 910221 |
| Trans1 Recv Date: | 910221 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 910222 |
| Part A Recv Date: | 910313 |
| Part B Recv Date: | 910318 |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | NJD980787147 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002454544 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 91 |

| | |
|---|---|
| Document ID: | NJA1393678 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NJDEPS103 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 920224 |
| Trans1 Recv Date: | 920224 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 920225 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 920306 |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | NJD986608941 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002454544 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00045 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

| | |
|---|---|
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 92 |

| | |
|---|---|
| Document ID: | NJA1702598 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | NJDEPS103 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 930601 |
| Trans1 Recv Date: | 930601 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 930602 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 930614 |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | NJD986608941 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002454544 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00020 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 93 |

| | |
|---|---|
| Document ID: | NJA1894195 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 10339 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 940518 |
| Trans1 Recv Date: | 940518 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 940518 |
| Part A Recv Date: | 940601 |
| Part B Recv Date: | 940602 |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | NJD986608941 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002454544 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00055 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 94 |

| | |
|---|---|
| Document ID: | NJA2103634 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | 10339 |

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

| | |
|---|---|
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 950418 |
| Trans1 Recv Date: | 950418 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 950420 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | 950501 |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | NJD986608941 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | NJD002454544 |
| Waste Code: | F003 - UNKNOWN |
| Quantity: | 00165 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 001 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | R Material recovery of more than 75 percent of the total material. |
| Specific Gravity: | 100 |
| Year: | 95 |

| | |
|---|---|
| Document ID: | ILA8991682 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD071629976 |
| Trans2 State ID: | NJD071629976 |
| Generator Ship Date: | 05/23/2000 |
| Trans1 Recv Date: | 05/23/2000 |
| Trans2 Recv Date: | 05/26/2000 |
| TSD Site Recv Date: | 06/03/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | ILD980613913 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | UPW151288 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00112 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2000 |

| | |
|---|---|
| Document ID: | ILA9837666 |
| Manifest Status: | Not reported |
| Trans1 State ID: | SCR000075150 |
| Trans2 State ID: | NJD071629976 |
| Generator Ship Date: | 09/18/2001 |
| Trans1 Recv Date: | 09/18/2001 |
| Trans2 Recv Date: | 09/21/2001 |
| TSD Site Recv Date: | 09/25/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD066073420 |
| Trans1 EPA ID: | ILD980613913 |

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

| | |
|---|---|
| Trans2 EPA ID: | Not reported |
| TSDF ID: | UPW151288 |
| Waste Code: | F005 - UNKNOWN |
| Quantity: | 00112 |
| Units: | P - Pounds |
| Number of Containers: | 001 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 01.00 |
| Year: | 2001 |

SPILLS:

| | |
|---|---|
| Facility ID: | 0713807 |
| Facility Type: | ER |
| DER Facility ID: | 345146 |
| Site ID: | 395625 |
| DEC Region: | 2 |
| Spill Date: | 3/30/2008 |
| Spill Number/Closed Date: | 0713807 / 4/7/2008 |
| Spill Cause: | Abandoned Drums |
| Spill Class: | Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. |
| SWIS: | 2401 |
| Investigator: | SFRAHMAN |
| Referred To: | Not reported |
| Reported to Dept: | 3/30/2008 |
| CID: | 41 |
| Water Affected: | Not reported |
| Spill Source: | Unknown |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 3/30/2008 |
| Spill Record Last Update: | 4/7/2008 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller City,St,Zip: | ZZ - |
| Spiller Company: | 001 |
| Contact Name: | ABOVE |
| Contact Phone: | Not reported |
| DEC Memo: | add to next drum run04/07/08 Drum found on 04/04/08,was pumped out and NYC sanitation was notified to pick up the empty drum.(sr) |
| Remarks: | ABANDONED DRUM ON STREET |

Material:

| | |
|---|---|
| Site ID: | 395625 |
| Operable Unit ID: | 1152567 |
| Operable Unit: | 01 |
| Material ID: | 2143346 |
| Material Code: | 0022 |
| Material Name: | Waste Oil/Used Oil |
| Case No.: | Not reported |

**TOM RUSSO'S SHOP COLLISIONVILLE (Continued)** **1000286576**

Material FA: Petroleum
Quantity: 40
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

---

**BL492** **TODD SHIPYARDS CORP** **RCRA-SQG** **1000183989**
**SSW** **FOOT OF DWIGHT ST** **NY MANIFEST** **NYD001288760**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.246 mi.**
**1297 ft.** **Site 2 of 2 in cluster BL**

**Relative:**
**Higher**

**Actual:**
**13 ft.**

RCRA-SQG:
Date form received by agency: 01/01/2007
Facility name: TODD SHIPYARDS CORP
Facility address: FOOT OF DWIGHT ST
BROOKLYN, NY 11231
EPA ID: NYD001288760
Contact: P OKEEFE
Contact address: FOOT OF DWIGHT ST
BROOKLYN, NY 11231
Contact country: US
Contact telephone: (718) 625-6820
Contact email: Not reported
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: TODD SHIPYARDS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TODD SHIPYARDS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

**TODD SHIPYARDS CORP (Continued)** **1000183989**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: TODD SHIPYARDS CORP
Classification: Not a generator, verified

Date form received by agency: 11/14/1980
Facility name: TODD SHIPYARDS CORP
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD001288760
Country: USA
Mailing Name: TODD SHIPYARDS CORPORATION
Mailing Contact: CLIFFORD E JONES
Mailing Address: ONE STATE STREET PLAZA
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-625-6820

Document ID: NYO3028833
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NYJA044
Trans2 State ID: Not reported
Generator Ship Date: 840323
Trans1 Recv Date: 840323
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840324
Part A Recv Date: 840510
Part B Recv Date: 840514
Generator EPA ID: NYD001288760
Trans1 EPA ID: NJD071629976
Trans2 EPA ID: Not reported
TSDF ID: PAD043583848

**TODD SHIPYARDS CORP (Continued)** **1000183989**

| | |
|---|---|
| Waste Code: | B011 - PCB CONTAMINATED TRANS CONT >500 PPM |
| Quantity: | 00220 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 004 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | Not reported |
| Specific Gravity: | 100 |
| Year: | 84 |

| | |
|---|---|
| Document ID: | PAO6359430 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AH0037 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 840814 |
| Trans1 Recv Date: | 840814 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 840814 |
| Part A Recv Date: | 840828 |
| Part B Recv Date: | 840831 |
| Generator EPA ID: | NYD001288760 |
| Trans1 EPA ID: | PAD064375470 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD064375470 |
| Waste Code: | D000 - NON-LISTED TOXIC WASTES |
| Quantity: | 02210 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 026 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 84 |

| | |
|---|---|
| Document ID: | PAO3844234 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AH0032 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 840815 |
| Trans1 Recv Date: | 840815 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 840815 |
| Part A Recv Date: | 840828 |
| Part B Recv Date: | 840904 |
| Generator EPA ID: | NYD001288760 |
| Trans1 EPA ID: | PAD064375470 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD064375470 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00045 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 003 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 84 |

**TODD SHIPYARDS CORP (Continued)** **1000183989**

| | |
|---|---|
| Document ID: | PAO3844223 |
| Manifest Status: | Completed copy |
| Trans1 State ID: | AH0032 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 840815 |
| Trans1 Recv Date: | 840815 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 840815 |
| Part A Recv Date: | 840827 |
| Part B Recv Date: | 840904 |
| Generator EPA ID: | NYD001288760 |
| Trans1 EPA ID: | PAD064375470 |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | PAD064375470 |
| Waste Code: | D002 - NON-LISTED CORROSIVE WASTES |
| Quantity: | 00275 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 005 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 100 |
| Year: | 84 |

| | |
|---|---|
| Document ID: | 06 |
| Manifest Status: | NYG0592677 |
| Trans1 State ID: | NYD001288760 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | OHR000034025 |
| Trans1 Recv Date: | Not reported |
| Trans2 Recv Date: | OHR000034025 |
| TSD Site Recv Date: | Not reported |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | N |
| Trans1 EPA ID: | N |
| Trans2 EPA ID: | N |
| TSDF ID: | N |
| Waste Code: | N |
| Quantity: | Not reported |
| Units: | 9 |
| Number of Containers: | DM |
| Container Type: | 450 |
| Handling Method: | G |
| Specific Gravity: | 1 |
| Waste Code: | T |
| Quantity: | Not reported |
| Units: | Not reported |
| Number of Containers: | Not reported |
| Container Type: | Not reported |
| Handling Method: | Not reported |
| Specific Gravity: | Not reported |
| Year: | Not reported |

| | |
|---|---|
| Document ID: | NYG0592677 |
| Manifest Status: | Not reported |

**TODD SHIPYARDS CORP (Continued)** **1000183989**

| | |
|---|---|
| Trans1 State ID: | OHR000034025 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 08/02/2006 |
| Trans1 Recv Date: | 08/02/2006 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 08/08/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD001288760 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID: | OHR000034025 |
| Waste Code: | B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC |
| Quantity: | 00450 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 009 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 01.00 |
| Year: | 2006 |

---

**BG493** **WYCKOFF MEDICAL CENTER OFFICE** **ICIS 1011519120**
**SSW** **267 VAN BRUNT STREET BROOKLYN NY 11231** **N/A**
**1/8-1/4** **BROOKLYN, NY 11231**
**0.248 mi.**
**1310 ft.** **Site 4 of 5 in cluster BG**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

ICIS:

| | |
|---|---|
| Enforcement Action ID: | 02-2004-0808 |
| FRS ID: | 110018934144 |
| Program ID: | FRS 110018934144 |
| Action Name: | WYCKOFF HEIGHTS MEDICAL CENTER |
| Facility Name: | WYCKOFF MEDICAL CENTER OFFICE |
| Facility Address: | 267 VAN BRUNT STREET BROOKLYN NY 11231<br>BROOKLYN, New York 11231 |
| Enforcement Action Type: | RCRA 3008A AO For Comp And/Or Penalty |
| Facility County: | Kings |
| EPA Region #: | 2 |

| | |
|---|---|
| Program ID: | FRS 110018934144 |
| Facility Name: | WYCKOFF MEDICAL CENTER OFFICE |
| Address: | 267 VAN BRUNT STREET |
| Tribal Indicator: | N |
| Fed Facility: | Not reported |
| NAIC Code: | Not reported |
| SIC Code: | 8049 |
| Latitude: | 40.67945 |
| Longitude: | -74.01041 |

**BG494**
**SSW**
**1/8-1/4**
**0.248 mi.**
**1310 ft.**

**WYCKOFF MEDICAL CENTER OFFICE**
**267 VAN BRUNT STREET**
**BROOKLYN, NY**

**Site 5 of 5 in cluster BG**

**FINDS** **1007735892**
**N/A**

**Relative:**
**Lower**

**Actual:**
**5 ft.**

FINDS:

Registry ID: 110018934144

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Count: 20 records. ORPHAN SUMMARY

| City | EDR ID | Site Name | Site Address | Zip | Database(s) |
|---|---|---|---|---|---|
| BROOKLYN | S110049531 | NYS DOT BIN 106539A | ROUTE 27 E TILLARY ST RAMP | 11201 | PA MANIFEST |
| BROOKLYN | S107787353 | EXIT 34 | ROUTE 278 SOUTHBOUND | | NY Spills |
| BROOKLYN | S109064521 | BELL ATLANTIC-NY | E 94 ST/BET CLARKSON AVE KINGS | | NY MANIFEST |
| BROOKLYN | S116293578 | CON EDISON | CONEY ISLAND & KINGS HWY | 11201 | NY MANIFEST |
| BROOKLYN | 1007796591 | RED HOOK MARINE TERMINAL-PIER 11 | FOOT OF HAMILTON AVENUE - PIER | | FINDS |
| BROOKLYN | S116293566 | CON EDISON | KINGS HWY CONEY ISLAND | 11201 | NY MANIFEST |
| BROOKLYN | S107407580 | KINGS HIGHWAY MOBIL | KINGS HIGHWAY | | NY Spills |
| BROOKLYN | S106737045 | BETW/AVE X & | KINGS HIGHWAY AVE U | | NY Spills |
| BROOKLYN | 1009235114 | BP PRODUCTS OF NORTH AMERICA INC | 5001 KINGS HIGHWAY SS671 | 11201 | NY MANIFEST |
| BROOKLYN | 1004569085 | NYCDEP RED HOOK WATER POLLUTION CO | MARSHALL STREET AND LITTLE STR | | FINDS |
| BROOKLYN | 1009238175 | CONSOLIDATED EDISON | MH38445-E 25TH ST & KINGS HWY | 11201 | NY MANIFEST |
| BROOKLYN | S113816641 | CON EDISON | NWC KINGS HWY & E 35 ST | 11201 | NY MANIFEST |
| BROOKLYN | 1007208397 | CON EDISION - MH38210 | S/INT KINGS HWY & W 7 ST. S/IN | 10003 | RCRA NonGen / NLR, NY MANIFEST |
| BROOKLYN | 1007760874 | US ARMY CORP-RED HOOK FLATS | UPPER BAY | | FINDS |
| BROOKLYN | 1007760866 | US ARMY CORP-RED HOOK CH | UPPER BAY | | FINDS |
| BROOKLYN | 1007208504 | CON EDISION - MH 2863 | W/INT 3RD AVE & STATE ST W/INT | 10003 | RCRA NonGen / NLR, NY MANIFEST |
| KINGS COUNTY | S109207895 | 205842; KINGS HWY | KINGS HWY | | NY Spills |
| NEW YORK | 1007208105 | CON EDISION - V4512 | STATE ST & SMITH ST STATE ST & | 10003 | RCRA NonGen / NLR, NY MANIFEST |
| NEW YORK | 1007207884 | CON EDISION - V04461 | STATE ST AND SMITH ST STATE ST | 10003 | RCRA NonGen / NLR, NY MANIFEST |
| NEW YORK CITY | 1007207251 | TR854 | ORANGE STREET AND COLUMBIA HEI | 11217 | RCRA NonGen / NLR, NY MANIFEST |

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

**STANDARD ENVIRONMENTAL RECORDS**

***Federal NPL site list***

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 01/28/2014
Number of Days to Update: 78

Source: EPA
Telephone: N/A
Last EDR Contact: 04/08/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 01/28/2014
Number of Days to Update: 78

Source: EPA
Telephone: N/A
Last EDR Contact: 04/08/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

***Federal Delisted NPL site list***

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 01/28/2014
Number of Days to Update: 78

Source: EPA
Telephone: N/A
Last EDR Contact: 04/08/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

***Federal CERCLIS list***

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 02/28/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/31/2013
Date Data Arrived at EDR: 07/08/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 151

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/11/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Varies

***Federal CERCLIS NFRAP site List***

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 02/28/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Quarterly

***Federal RCRA CORRACTS facilities list***

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

***Federal RCRA non-CORRACTS TSD facilities list***

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

***Federal RCRA generators list***

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Varies

***Federal institutional controls / engineering controls registries***

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 12/17/2013
Date Data Arrived at EDR: 01/14/2014
Date Made Active in Reports: 01/28/2014
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 12/17/2013
Date Data Arrived at EDR: 01/14/2014
Date Made Active in Reports: 01/28/2014
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/26/2014
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 55

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/14/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Varies

***Federal ERNS list***

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/30/2013
Date Data Arrived at EDR: 10/01/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 66

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 04/04/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Annually

***State- and tribal - equivalent CERCLIS***

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 02/17/2014
Date Data Arrived at EDR: 02/19/2014
Date Made Active in Reports: 03/31/2014
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/19/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Varies

***State and tribal landfill and/or solid waste disposal site lists***

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/12/2013
Date Data Arrived at EDR: 01/07/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Semi-Annually

***State and tribal leaking storage tank lists***

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/17/2014
Date Data Arrived at EDR: 02/19/2014
Date Made Active in Reports: 04/02/2014
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012
Date Data Arrived at EDR: 08/28/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 49

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 02/13/2014
Date Data Arrived at EDR: 02/14/2014
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 10
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/06/2013
Date Data Arrived at EDR: 11/07/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 29
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 42
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 184
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/30/2014
Next Scheduled EDR Contact: 05/12/2014
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/21/2013
Date Data Arrived at EDR: 11/26/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 90
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/22/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Semi-Annually

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 59
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 02/21/2014
Next Scheduled EDR Contact: 05/12/2014
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 02/20/2014
Date Data Arrived at EDR: 02/21/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 62
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

***State and tribal registered storage tank lists***

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/30/2013
Date Data Arrived at EDR: 01/02/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 04/02/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/30/2013
Date Data Arrived at EDR: 01/02/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/02/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/30/2013
Date Data Arrived at EDR: 01/02/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/02/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/31/2014
Date Data Arrived at EDR: 04/02/2014
Date Made Active in Reports: 04/29/2014
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/02/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/31/2014
Date Data Arrived at EDR: 04/02/2014
Date Made Active in Reports: 04/29/2014
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/02/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 02/06/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 65

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 07/30/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 129

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 08/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 92

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 02/20/2014
Date Data Arrived at EDR: 02/21/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 62

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 01/27/2014
Number of Days to Update: 271

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/30/2014
Next Scheduled EDR Contact: 05/12/2014
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 02/13/2014
Date Data Arrived at EDR: 02/14/2014
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 10

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/21/2013
Date Data Arrived at EDR: 11/26/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/22/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 01/29/2014
Date Data Arrived at EDR: 01/29/2014
Date Made Active in Reports: 03/12/2014
Number of Days to Update: 42

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/27/2014
Next Scheduled EDR Contact: 05/12/2014
Data Release Frequency: Semi-Annually

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/15/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Varies

***State and tribal institutional control / engineering control registries***

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 03/13/2014
Date Data Arrived at EDR: 04/01/2014
Date Made Active in Reports: 04/29/2014
Number of Days to Update: 28

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/24/2014
Next Scheduled EDR Contact: 07/07/2014
Data Release Frequency: No Update Planned

***State and tribal voluntary cleanup sites***

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/17/2013
Date Data Arrived at EDR: 10/01/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 04/01/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

***State and tribal Brownfields sites***

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Semi-Annually

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/20/2014
Date Data Arrived at EDR: 03/20/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/20/2014
Next Scheduled EDR Contact: 07/07/2014
Data Release Frequency: Semi-Annually

***Local Lists of Landfill / Solid Waste Disposal Sites***

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: No Update Planned

SWTIRE: Registered Waste Tire Storage & Facility List
A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 04/22/2014
Next Scheduled EDR Contact: 08/04/2014
Data Release Frequency: Annually

SWRCY: Registered Recycling Facility List
A listing of recycling facilities.

Date of Government Version: 12/12/2013
Date Data Arrived at EDR: 01/07/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

***Local Lists of Hazardous waste / Contaminated Sites***

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 12/04/2013
Date Data Arrived at EDR: 12/10/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 65

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/04/2014
Next Scheduled EDR Contact: 06/16/2014
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites
A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 03/27/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/04/2014
Next Scheduled EDR Contact: 06/16/2014
Data Release Frequency: No Update Planned

***Local Lists of Registered Storage Tanks***

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

***Local Land Records***

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 02/11/2014
Date Data Arrived at EDR: 02/13/2014
Date Made Active in Reports: 03/31/2014
Number of Days to Update: 46

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 02/10/2014
Next Scheduled EDR Contact: 05/26/2014
Data Release Frequency: Varies

***Records of Emergency Release Reports***

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 01/03/2014
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 52

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 04/01/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/17/2014
Date Data Arrived at EDR: 02/19/2014
Date Made Active in Reports: 04/02/2014
Number of Days to Update: 42
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40
Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63
Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27
Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/13/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 02/06/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 55

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 01/24/2014
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 31

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/27/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/11/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/25/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 28

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 03/05/2014
Next Scheduled EDR Contact: 06/16/2014
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/31/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 44

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/26/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/28/2014
Next Scheduled EDR Contact: 07/07/2014
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 02/24/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 02/24/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/29/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011
Date Data Arrived at EDR: 11/10/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 10/09/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2013
Date Data Arrived at EDR: 07/17/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 107

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/09/2014
Date Data Arrived at EDR: 01/10/2014
Date Made Active in Reports: 03/12/2014
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/09/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/18/2013
Date Data Arrived at EDR: 02/27/2014
Date Made Active in Reports: 03/12/2014
Number of Days to Update: 13

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 03/14/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 11/01/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/28/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 03/07/2014
Date Data Arrived at EDR: 03/12/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/12/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 02/28/2014
Date Data Arrived at EDR: 03/12/2014
Date Made Active in Reports: 04/29/2014
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 03/12/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 01/21/2014
Date Data Arrived at EDR: 01/22/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/17/2014
Next Scheduled EDR Contact: 06/30/2014
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 02/25/2014
Date Data Arrived at EDR: 02/27/2014
Date Made Active in Reports: 04/04/2014
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: No Update Planned

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 11/01/2013
Date Made Active in Reports: 01/09/2014
Number of Days to Update: 69
Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 03/12/2014
Date Data Arrived at EDR: 03/28/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 28
Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/24/2014
Next Scheduled EDR Contact: 07/07/2014
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34
Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing
The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54
Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 04/21/2014
Next Scheduled EDR Contact: 08/04/2014
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 01/07/2014
Date Data Arrived at EDR: 01/07/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 35
Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List
The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011
Date Data Arrived at EDR: 05/18/2012
Date Made Active in Reports: 05/25/2012
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/14/2014
Next Scheduled EDR Contact: 05/26/2014
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013
Date Data Arrived at EDR: 02/14/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/04/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 07/03/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 72

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 04/04/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Quarterly

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: N/A

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/23/2013
Date Data Arrived at EDR: 11/06/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 30

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 03/31/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/23/2013
Date Data Arrived at EDR: 11/06/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 30
Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 03/31/2014
Next Scheduled EDR Contact: 07/14/2014
Data Release Frequency: Annually

COAL ASH DOE: Sleam-Electric Plan Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information
All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 02/25/2014
Date Data Arrived at EDR: 02/27/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 41
Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 02/14/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/01/2013
Date Data Arrived at EDR: 12/05/2013
Date Made Active in Reports: 02/17/2014
Number of Days to Update: 74
Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/30/2014
Next Scheduled EDR Contact: 05/12/2014
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/11/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 01/07/2014
Date Data Arrived at EDR: 01/09/2014
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: Varies

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 02/10/2014
Next Scheduled EDR Contact: 05/26/2014
Data Release Frequency: Quarterly

**EDR HIGH RISK HISTORICAL RECORDS**

***EDR Exclusive Records***

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

**EDR RECOVERED GOVERNMENT ARCHIVES**

***Exclusive Recovered Govt. Archives***

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

**COUNTY RECORDS**

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2014
Date Data Arrived at EDR: 02/25/2014
Date Made Active in Reports: 04/01/2014
Number of Days to Update: 35

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 02/05/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 02/24/2014
Date Data Arrived at EDR: 02/25/2014
Date Made Active in Reports: 04/01/2014
Number of Days to Update: 35
Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 02/05/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/07/2014
Next Scheduled EDR Contact: 07/21/2014
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 12/17/2013
Date Data Arrived at EDR: 12/18/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 55
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 12/17/2013
Date Data Arrived at EDR: 12/18/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 55
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/10/2014
Next Scheduled EDR Contact: 06/23/2014
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 01/30/2014
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/03/2014
Number of Days to Update: 34
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/18/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 01/30/2014
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/03/2014
Number of Days to Update: 34
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/18/2014
Next Scheduled EDR Contact: 05/19/2014
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 03/18/2014
Date Data Arrived at EDR: 03/20/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 36
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 03/18/2014
Date Data Arrived at EDR: 03/20/2014
Date Made Active in Reports: 04/25/2014
Number of Days to Update: 36
Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

**OTHER DATABASE(S)**

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/21/2014
Next Scheduled EDR Contact: 06/02/2014
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 04/18/2014
Next Scheduled EDR Contact: 07/28/2014
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 07/24/2013
Date Made Active in Reports: 08/19/2013
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/21/2014
Next Scheduled EDR Contact: 08/04/2014
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 08/05/2013
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/24/2014
Next Scheduled EDR Contact: 06/09/2014
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 12/30/2013
Date Data Arrived at EDR: 02/11/2014
Date Made Active in Reports: 03/11/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/21/2014
Next Scheduled EDR Contact: 08/04/2014
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 08/09/2013
Date Made Active in Reports: 09/27/2013
Number of Days to Update: 49

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/17/2014
Next Scheduled EDR Contact: 06/30/2014
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

**STREET AND ADDRESS INFORMATION**

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

# GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

**TARGET PROPERTY ADDRESS**

RED HOOK
RED HOOK
BROOKLYN, NY 11231

**TARGET PROPERTY COORDINATES**

| | |
|---|---|
| Latitude (North): | 40.6886619345085 - 40° 41' 19.18'' |
| Longitude (West): | 74.00313173607 - 74° 0' 11.27'' |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 584234.3 |
| UTM Y (Meters): | 4504463.0 |
| Elevation: | 6 ft. above sea level |

**USGS TOPOGRAPHIC MAP**

| | |
|---|---|
| Target Property Map: | 40074-F1 JERSEY CITY, NJ NY |
| Most Recent Revision: | 1981 |
| East Map: | 40073-F8 BROOKLYN, NY |
| Most Recent Revision: | 1995 |

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**GROUNDWATER FLOW DIRECTION INFORMATION**

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


**TOPOGRAPHIC INFORMATION**

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

**TARGET PROPERTY TOPOGRAPHY**

General Topographic Gradient: General WNW

**SURROUNDING TOPOGRAPHY: ELEVATION PROFILES**




**Target Property Elevation: 6 ft.**

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

## HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

### FEMA FLOOD ZONE

| Target Property County | FEMA Flood Electronic Data |
|---|---|
| KINGS, NY | YES - refer to the Overview Map and Detail Map |

Flood Plain Panel at Target Property: 360497 - FEMA DFIRM Flood data

Additional Panels in search area:
3604970054B - FEMA Q3 Flood data
3604970055B - FEMA Q3 Flood data
3604970062B - FEMA Q3 Flood data
3604970063B - FEMA Q3 Flood data

### NATIONAL WETLAND INVENTORY

| NWI Quad at Target Property | NWI Electronic Data Coverage |
|---|---|
| JERSEY CITY | YES - refer to the Overview Map and Detail Map |

## HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

***Site-Specific Hydrogeological Data*:***

| | |
|---|---|
| Search Radius: | 1.25 miles |
| Location Relative to TP: | 1/2 - 1 Mile WNW |
| Site Name: | SUPPORT CENTER - GOVERNOR'S ISLAND |
| Site EPA ID Number: | NY5690319889 |
| Groundwater Flow Direction: | GENERALLY SSW. |
| Measured Depth to Water: | not available. |
| Hydraulic Connection: | Detailed hydraulic connection information is not available. |
| Sole Source Aquifer: | No information about a sole source aquifer is available |
| Data Quality: | Information is inferred in the CERCLIS investigation report(s) |

## AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

| MAP ID | LOCATION FROM TP | GENERAL DIRECTION GROUNDWATER FLOW |
|---|---|---|
| Not Reported | | |

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

## GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

## GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

**ROCK STRATIGRAPHIC UNIT**

| | |
|---|---|
| Era: | Paleozoic |
| System: | Ordovician |
| Series: | Ordovician |
| Code: | Oe *(decoded above as Era, System & Series)* |

**GEOLOGIC AGE IDENTIFICATION**

Category: Eugeosynclinal Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

**DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY**

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | | |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | Permeability Rate (in/hr) | Soil Reaction (pH) |
| 1 | 0 inches | 6 inches | variable | Not reported | Not reported | Max: 0.00<br>Min: 0.00 | Max: 0.00<br>Min: 0.00 |

**OTHER SOIL TYPES IN AREA**

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

**LOCAL / REGIONAL WATER AGENCY RECORDS**

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

**WELL SEARCH DISTANCE INFORMATION**

| DATABASE | SEARCH DISTANCE (miles) |
|---|---|
| Federal USGS | 0.250 |
| Federal FRDS PWS | Nearest PWS within 0.250 miles |
| State Database | 0.250 |

**FEDERAL USGS WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**FEDERAL USGS WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| 1 | USGS40000828628 | 0 - 1/8 Mile ENE |
| 2 | USGS40000828559 | 1/8 - 1/4 Mile SW |

**FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|

No PWS System Found


Note: PWS System location is not always the same as well location.

**STATE DATABASE WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|

No Wells Found

# PHYSICAL SETTING SOURCE MAP - 3929425.11s




- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

| | | | |
|---|---|---|---|
| SITE NAME: | Red Hook | CLIENT: | STV Inc. |
| ADDRESS: | Red Hook<br>Brooklyn NY 11231 | CONTACT: | Doug Glorie |
| LAT/LONG: | 40.6886619345085 / 74.003131736071 | INQUIRY #: | 3929425.11s |
| | | DATE: | May 01, 2014 2:20 pm |

Copyright © 2014 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

**1**
**ENE** **FED USGS** **USGS40000828628**
**0 - 1/8 Mile**
**Higher**

| | | | |
|---|---|---|---|
| Org. Identifier: | USGS-NY | | |
| Formal name: | USGS New York Water Science Center | | |
| Monloc Identifier: | USGS-404120074000601 | | |
| Monloc name: | K 2056. 1 | | |
| Monloc type: | Well | | |
| Monloc desc: | 0601 | | |
| Huc code: | 02030201 | Drainagearea value: | Not Reported |
| Drainagearea Units: | Not Reported | Contrib drainagearea: | Not Reported |
| Contrib drainagearea units: | Not Reported | Latitude: | 40.6889918 |
| Longitude: | -74.0012505 | Sourcemap scale: | 24000 |
| Horiz Acc measure: | 1 | Horiz Acc measure units: | seconds |
| Horiz Collection method: | Interpolated from map | | |
| Horiz coord refsys: | NAD83 | Vert measure val: | 10.0 |
| Vert measure units: | feet | Vertacc measure val: | 0.1 |
| Vert accmeasure units: | feet | | |
| Vertcollection method: | Level or other surveying method | | |
| Vert coord refsys: | NGVD29 | Countrycode: | US |
| Aquifername: | Not Reported | | |
| Formation type: | Not Reported | | |
| Aquifer type: | Not Reported | | |
| Construction date: | Not Reported | Welldepth: | Not Reported |
| Welldepth units: | Not Reported | Wellholedepth: | 85 |
| Wellholedepth units: | ft | | |

Ground-water levels, Number of Measurements: 0

---

**2**
**SW** **FED USGS** **USGS40000828559**
**1/8 - 1/4 Mile**
**Higher**

| | | | |
|---|---|---|---|
| Org. Identifier: | USGS-NY | | |
| Formal name: | USGS New York Water Science Center | | |
| Monloc Identifier: | USGS-404111074002001 | | |
| Monloc name: | K 1561. 1 | | |
| Monloc type: | Well | | |
| Monloc desc: | Not Reported | | |
| Huc code: | 02030201 | Drainagearea value: | Not Reported |
| Drainagearea Units: | Not Reported | Contrib drainagearea: | Not Reported |
| Contrib drainagearea units: | Not Reported | Latitude: | 40.6864919 |
| Longitude: | -74.0051395 | Sourcemap scale: | 24000 |
| Horiz Acc measure: | 1 | Horiz Acc measure units: | seconds |
| Horiz Collection method: | Interpolated from map | | |
| Horiz coord refsys: | NAD83 | Vert measure val: | 5.0 |
| Vert measure units: | feet | Vertacc measure val: | 0.1 |
| Vert accmeasure units: | feet | | |
| Vertcollection method: | Level or other surveying method | | |
| Vert coord refsys: | NGVD29 | Countrycode: | US |
| Aquifername: | Not Reported | | |
| Formation type: | Not Reported | | |

## GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

| | | | |
|---|---|---|---|
| Aquifer type: | Not Reported | | |
| Construction date: | Not Reported | Welldepth: | Not Reported |
| Welldepth units: | Not Reported | Wellholedepth: | 60 |
| Wellholedepth units: | ft | | |

Ground-water levels, Number of Measurements: 0

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
# RADON

**AREA RADON INFORMATION**

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

---

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

| Area | Average Activity | % <4 pCi/L | % 4-20 pCi/L | % >20 pCi/L |
|---|---|---|---|---|
| Living Area | 0.750 pCi/L | 100% | 0% | 0% |
| Basement | 1.370 pCi/L | 88% | 10% | 2% |

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

## HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

## HYDROGEOLOGIC INFORMATION

AQUIFLOW$^{R}$ Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

## GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

## OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

**STREET AND ADDRESS INFORMATION**

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

**Red Hook**
Red Hook
Brooklyn, NY 11231

Inquiry Number: 3929425.14
May 02, 2014

# The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

# TABLE OF CONTENTS

## SECTION

**Executive Summary**

**Findings**

**City Directory Images**

***Thank you for your business.***
Please contact EDR at 1-800-352-0050
with any questions or comments.

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

## DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2013. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 100 feet of the target property.

A summary of the information obtained is provided in the text of this report.

## RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

| Year | Source | TP | Adjoining | Text Abstract | Source Image |
|---|---|---|---|---|---|
| 2013 | Cole Information Services | - | - | - | - |
| 2008 | Cole Information Services | - | - | - | - |
| 2005 | Hill-Donnelly Corporation | - | - | - | - |
| 2000 | Cole Information Services | - | - | - | - |
| 1997 | NYNEX | - | - | - | - |
| 1992 | NYNEX Informantion Resource Co. | - | - | - | - |
| 1985 | NYNEX Information Resources Company | - | - | - | - |
| 1980 | New York Telephone | - | - | - | - |
| 1976 | New York Telephone | - | - | - | - |
| 1973 | New York Telephone | - | - | - | - |
| 1970 | New York Telephone | - | - | - | - |
| 1965 | New York Telephone | - | - | - | - |
| 1960 | New York Telephone | - | - | - | - |
| 1949 | New York Telephone | - | - | - | - |
| 1945 | New York Telephone | - | - | - | - |
| 1940 | New York Telephone | - | - | - | - |
| 1934 | R. L. Polk & Co. | - | - | - | - |
| 1928 | New York Telephone | - | - | - | - |

# FINDINGS

## TARGET PROPERTY INFORMATION

### ADDRESS

Red Hook
Brooklyn, NY 11231

### FINDINGS DETAIL

Target Property research detail.

# FINDINGS

## ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Addresses Found

# FINDINGS

## TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

| Address Researched | Address Not Identified in Research Source |
|---|---|
| Red Hook | 2013, 2008, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928 |

**Hunts Point**
Hunts Point
Bronx, NY 10474

Inquiry Number: 3929425.6
May 01, 2014

# The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

# TABLE OF CONTENTS

## SECTION

**Executive Summary**

**Findings**

**City Directory Images**

***Thank you for your business.***
Please contact EDR at 1-800-352-0050
with any questions or comments.

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

## DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1927 through 2013. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 100 feet of the target property.

A summary of the information obtained is provided in the text of this report.

## RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

| Year | Source | TP | Adjoining | Text Abstract | Source Image |
|---|---|---|---|---|---|
| 2013 | Cole Information Services | - | - | - | - |
| 2008 | Cole Information Services | - | - | - | - |
| 2005 | Hill-Donnelly Information Services | - | - | - | - |
| 2000 | Cole Information Services | - | - | - | - |
| 1993 | New York Telephone | - | - | - | - |
| 1983 | New York Telephone | - | - | - | - |
| 1976 | New York Telephone Company | - | - | - | - |
| 1971 | New York Telephone | - | - | - | - |
| 1965 | New York Telephone Company | - | - | - | - |
| 1961 | New York Telephone | - | - | - | - |
| 1956 | New York Telephone | - | - | - | - |
| 1949 | New York Telephone | - | - | - | - |
| 1940 | New York Telephone | - | - | - | - |
| 1931 | Manhattan and Bronx Directory Publishing Company Residential Directory | - | - | - | - |
| 1927 | New York Telephone | - | - | - | - |

# FINDINGS

## TARGET PROPERTY INFORMATION

### ADDRESS

Hunts Point
Bronx, NY 10474

### FINDINGS DETAIL

Target Property research detail.

# FINDINGS

## ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Addresses Found

# FINDINGS

## TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

| Address Researched | Address Not Identified in Research Source |
|---|---|
| Hunts Point | 2013, 2008, 2005, 2000, 1993, 1983, 1976, 1971, 1965, 1961, 1956, 1949, 1940, 1931, 1927 |

**SBMT**
646 Second Avenue
Brooklyn, NY 11232

Inquiry Number: 3929425.21
May 05, 2014

# Certified Sanborn® Map Report

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

# Certified Sanborn® Map Report

5/05/14

**Site Name:**
SBMT
646 Second Avenue
Brooklyn, NY 11232

**Client Name:**
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3929425.21

Contact: Doug Glorie

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by STV Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

## *Certified Sanborn Results:*

**Site Name:** SBMT
**Address:** 646 Second Avenue
**City, State, Zip:** Brooklyn, NY 11232
**Cross Street:**
**P.O. #** 4014403
**Project:** Cross Harbor
**Certification #** B7CC-4A0D-8FDE

**Maps Provided:**

| | | | | |
|---|---|---|---|---|
| 2007 | 2001 | 1988 | 1978 | 1921 |
| 2006 | 1995 | 1987 | 1965 | 1906 |
| 2005 | 1994 | 1985 | 1951 | 1888 |
| 2004 | 1993 | 1982 | 1928 | |
| 2003 | 1992 | 1980 | 1926 | |
| 2002 | 1991 | 1979 | 1922 | |

Sanborn® Library search results
Certification # B7CC-4A0D-8FDE

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

*The Sanborn Library LLC Since 1866™*

### Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


**Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


## *Sanborn Sheet Thumbnails*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


### 2007 Source Sheets




Volume 6, Sheet 5



Volume 6, Sheet 7



Volume 6, Sheet 8




Volume 6, Sheet 9


### 2006 Source Sheets




Volume 6, Sheet 5



Volume 6, Sheet 7



Volume 6, Sheet 8




Volume 6, Sheet 9


### 2005 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


### 2004 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 2003 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet r




Volume 6, Sheet 9


## 2002 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 2001 Source Sheets




Volume 6, Sheet 5



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1995 Source Sheets



Volume 6, Sheet 5



Volume 6, Sheet 7




Volume 6, Sheet 9


## 1994 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1993 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1992 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1991 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


**1988 Source Sheets**



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 8


**1987 Source Sheets**



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 8


**1985 Source Sheets**




Volume 6, Sheet 5



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


**1982 Source Sheets**



Volume 6, Sheet 9




Volume 6, Sheet 5




Volume 6, Sheet 7


## 1980 Source Sheets




Volume 6, Sheet 5




Volume 6, Sheet 7



Volume 6, Sheet 9



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1979 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1978 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1965 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7




Volume 6, Sheet 9


## 1951 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 9




Volume 6, Sheet 7

## 1928 Source Sheets




Volume Pier Maps, Sheet 51


## 1926 Source Sheets



Volume 6, Sheet 5




Volume 6, Sheet 7



Volume 6, Sheet 8

## 1922 Source Sheets




Volume Pier Maps, Sheet 43

## 1921 Source Sheets




Volume Atlas Maps, Sheet b-10

## 1906 Source Sheets




Volume 6, Sheet 10




Volume 6, Sheet 17

## 1888 Source Sheets



Volume 6, Sheet 163

# 2007 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2007 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2006 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2006 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2005 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2005 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 2004 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2004 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 2003 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2003 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet r
Volume 6, Sheet 9

N

# 2002 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2002 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 2001 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2001 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1995 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1995 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1994 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1994 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1993 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1993 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1992 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1992 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1991 Certified Sanborn Map






The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1991 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1988 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8

N

# 1987 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1987 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8

N

# 1985 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1985

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1982 Certified Sanborn Map






The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1982 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 9
Volume 6, Sheet 5
Volume 6, Sheet 7

N

# 1980 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1980 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9
Volume 6, Sheet 5
Volume 6, Sheet 7

Volume 6, Sheet 9

N

# 1979 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1979 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1978 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.

EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE

Copyright: 1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1965 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1965 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 9

N

# 1951 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1951 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 9
Volume 6, Sheet 7

N

# 1928 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1928 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 51

N

# 1926 Certified Sanborn Map






The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification #: B7CC-4A0D-8FDE
Copyright: 1926

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 5
Volume 6, Sheet 7
Volume 6, Sheet 8

N

# 1922 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1922

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



43

Volume Pier Maps, Sheet 43

N

# 1921 Certified Sanborn Map


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE




Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1921

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume Atlas Maps, Sheet b-10

0 Feet 165 330 660

N

# 1906 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1906

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 10
Volume 6, Sheet 17

N

# 1888 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660




Volume 6, Sheet 163

N

**SBMT**
646 Second Avenue
Brooklyn, NY 11232

Inquiry Number: 3929425.21
May 05, 2014

# Certified Sanborn® Map Report

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

# Certified Sanborn® Map Report

5/05/14

**Site Name:**
SBMT
646 Second Avenue
Brooklyn, NY 11232

**Client Name:**
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3929425.21

Contact: Doug Glorie

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by STV Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

## *Certified Sanborn Results:*

**Site Name:** SBMT
**Address:** 646 Second Avenue
**City, State, Zip:** Brooklyn, NY 11232
**Cross Street:**
**P.O. #** 4014403
**Project:** Cross Harbor
**Certification #** B7CC-4A0D-8FDE

**Maps Provided:**

| | | | | |
|---|---|---|---|---|
| 2007 | 2001 | 1988 | 1978 | 1906 |
| 2006 | 1995 | 1987 | 1965 | 1888 |
| 2005 | 1994 | 1985 | 1951 | |
| 2004 | 1993 | 1982 | 1928 | |
| 2003 | 1992 | 1980 | 1926 | |
| 2002 | 1991 | 1979 | 1922 | |

Sanborn® Library search results
Certification # B7CC-4A0D-8FDE

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

*The Sanborn Library LLC Since 1866™*

### Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


**Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


## *Sanborn Sheet Thumbnails*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


### 2007 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


### 2006 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


### 2005 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


### 2004 Source Sheets




Volume 6, Sheet 7



Volume 6, Sheet 8




Volume 6, Sheet 9




Volume 6, Sheet 11


## 2003 Source Sheets




Volume 6, Sheet r



Volume 6, Sheet 8




Volume 6, Sheet 9




Volume 6, Sheet 11


## 2002 Source Sheets




Volume 6, Sheet 7



Volume 6, Sheet 8




Volume 6, Sheet 9




Volume 6, Sheet 11


## 2001 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1995 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1994 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1993 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1992 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1991 Source Sheets




Volume 6, Sheet 7



Volume 6, Sheet 8




Volume 6, Sheet 9




Volume 6, Sheet 11


## 1988 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 8


## 1987 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 8


## 1985 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 9




Volume 6, Sheet 8


## 1982 Source Sheets



Volume 6, Sheet 9




Volume 6, Sheet 7




Volume 6, Sheet 8


## 1980 Source Sheets




Volume 6, Sheet 7




Volume 6, Sheet 8



Volume 6, Sheet 9



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1979 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1978 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1965 Source Sheets



Volume 6, Sheet 7




Volume 6, Sheet 8




Volume 6, Sheet 9


## 1951 Source Sheets



Volume 6, Sheet 8




Volume 6, Sheet 9




Volume 6, Sheet 7

## 1928 Source Sheets




Volume Pier Maps, Sheet 50




Volume Pier Maps, Sheet 51

## 1926 Source Sheets




Volume 6, Sheet 7




Volume 6, Sheet 8

## 1922 Source Sheets





Volume Pier Maps, Sheet 42





Volume Pier Maps, Sheet 43

## 1906 Source Sheets





Volume 6, Sheet 16





Volume 6, Sheet 17

## 1888 Source Sheets





Volume 6, Sheet 161




Volume 6, Sheet 161

# 2007 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2007 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2006 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2006 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2005 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2005 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2004 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2004 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 11

0 Feet 165 330 660

N

# 2003 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2003 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet r
Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 11

0 Feet 165 330 660

N

# 2002 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2002 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 11

N

# 2001 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2001 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1995 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1994 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1994 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1993 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1993 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1992 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1992 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1991 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1991 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 11

N

# 1988 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1988 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 8

0 Feet 165 330 660

N

# 1987 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 8

0 Feet 165 330 660

N

# 1985 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1985 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 9
Volume 6, Sheet 8

N

# 1982 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1982 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 9
Volume 6, Sheet 7
Volume 6, Sheet 8

0 Feet 165 330 660

N

# 1980 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1980 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 7
Volume 6, Sheet 8

Volume 6, Sheet 9

N

# 1979 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1979 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1978 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

0 Feet 165 330 660

N

# 1965 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1965 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 7
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1951 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1951 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 8
Volume 6, Sheet 9
Volume 6, Sheet 7

N

# 1928 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume Pier Maps, Sheet 50
Volume Pier Maps, Sheet 51

0 Feet 165 330 660

N

# 1926 Certified Sanborn Map






The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1926

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 7
Volume 6, Sheet 8

0 Feet 165 330 660

N

# 1922 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1922

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 42
Volume Pier Maps, Sheet 43

N

# 1906 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1906 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 16
Volume 6, Sheet 17

N

# 1888 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 165 330 660






Volume 6, Sheet 161
Volume 6, Sheet 161

# 1951 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1951 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12

0 Feet 165 330 660

N

# 1928 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1928

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 50
Volume Pier Maps, Sheet 51

N

# 1926 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1926 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12

N

# 1922 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1922

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 42
Volume Pier Maps, Sheet 43

N

# 1906 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1906 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6, Sheet 17
Volume 6, Sheet 18
Volume 6, Sheet 19
Volume 6, Sheet 20

0 Feet 165 330 660

N

# 1888 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 160
Volume 6, Sheet 161
Volume 6, Sheet 161

N

# 1980 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1980 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12
Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12
Volume 6, Sheet 12

N

# 1979 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1979 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12

N

# 1978 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12

0 Feet 165 330 660

N

# 1965 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1965 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.






Volume 6, Sheet 9
Volume 6, Sheet 10
Volume 6, Sheet 11
Volume 6, Sheet 12

N

**SBMT**
646 Second Avenue
Brooklyn, NY 11232

Inquiry Number: 3929425.21
May 05, 2014

# Certified Sanborn® Map Report

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

# Certified Sanborn® Map Report

5/05/14

**Site Name:**
SBMT
646 Second Avenue
Brooklyn, NY 11232

**Client Name:**
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3929425.21

Contact: Doug Glorie

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by STV Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

## *Certified Sanborn Results:*

**Site Name:** SBMT
**Address:** 646 Second Avenue
**City, State, Zip:** Brooklyn, NY 11232
**Cross Street:**
**P.O. #** 4014403
**Project:** Cross Harbor
**Certification #** B7CC-4A0D-8FDE

**Maps Provided:**

| | | | | |
|---|---|---|---|---|
| 2007 | 2001 | 1988 | 1978 | 1906 |
| 2006 | 1995 | 1987 | 1965 | 1888 |
| 2005 | 1994 | 1985 | 1951 | |
| 2004 | 1993 | 1982 | 1928 | |
| 2003 | 1992 | 1980 | 1926 | |
| 2002 | 1991 | 1979 | 1922 | |

Sanborn® Library search results
Certification # B7CC-4A0D-8FDE

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

*The Sanborn Library LLC Since 1866™*

### Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


**Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


## *Sanborn Sheet Thumbnails*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


### 2007 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 9

### 2006 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8

### 2005 Source Sheets




Volume 6, Sheet 6




Volume 6, Sheet 8

### 2004 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8


## 2003 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 9


## 2002 Source Sheets



Volume 6, Sheet 6



Volume 6, Sheet 8




Volume 6, Sheet 9


## 2001 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 9

## 1995 Source Sheets




Volume 6, Sheet 6




Volume 6, Sheet 8

## 1994 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8


## 1993 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 9

## 1992 Source Sheets




Volume 6, Sheet 6




Volume 6, Sheet 8


## 1991 Source Sheets



Volume 6, Sheet 6



Volume 6, Sheet 8




Volume 6, Sheet 9


**1988 Source Sheets**



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 8

**1987 Source Sheets**




Volume 6, Sheet 6




Volume 6, Sheet 8


**1985 Source Sheets**



Volume 6, Sheet 6



Volume 6, Sheet 8




Volume 6, Sheet 9

**1982 Source Sheets**




Volume 6, Sheet 6




Volume 6, Sheet 8

## 1980 Source Sheets




Volume 6, Sheet 6



Volume 6, Sheet 8



Volume 6, Sheet 6




Volume 6, Sheet 8




Volume 6, Sheet 9

## 1979 Source Sheets




Volume 6, Sheet 6



Volume 6, Sheet 8

## 1978 Source Sheets




Volume 6, Sheet 8




Volume 6, Sheet 6

## 1965 Source Sheets



Volume 6, Sheet 6




Volume 6, Sheet 8

## 1951 Source Sheets




Volume 6, Sheet 6



Volume 6, Sheet 8

## 1928 Source Sheets




Volume Pier Maps, Sheet 51

## 1926 Source Sheets




Volume 6, Sheet 6




Volume 6, Sheet 8

## 1922 Source Sheets




Volume Pier Maps, Sheet 43

## 1906 Source Sheets




Volume 6, Sheet 15



Volume 6, Sheet 16

## 1888 Source Sheets




Volume 6, Sheet 161



Volume 6, Sheet 162

# 2007 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2007 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2006 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification #: B7CC-4A0D-8FDE
Copyright: 2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 2005 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2005 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 2004 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2004 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 2003 Certified Sanborn Map


37TH ST
2ND AV.
USED CAR SALES
OFFICE
OFFICE
ELECTRICAL STA.
COSTCO
I-C.
NC-1986
C.B.-75'
IR. & STUCCO 22¢
PRIVATE
37TH ST
39TH ST
699
(703)
707
PARK'G.
LOFTS
LOFT CO-OPERATIVES
BUILDING
BUILDING
BUILDING

# 1926 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1926 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 1922 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1922

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume Pier Maps, Sheet 43

N

# 1906 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1906 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 15
Volume 6, Sheet 16

N

# 1888 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1888 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 161
Volume 6, Sheet 162

N

# 2002 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2002 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 2001 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 2001 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1995 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1995 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 1994 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1994 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 1993 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1992 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1992 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8

N

# 1991 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

| | |
|---|---|
| Site Name: | SBMT |
| Address: | 646 Second Avenue |
| City, ST, ZIP: | Brooklyn NY 11232 |
| Client: | STV Inc. |
| EDR Inquiry: | 3929425.21 |
| Order Date: | 5/5/2014 1:19:00 PM |
| Certification # | B7CC-4A0D-8FDE |
| Copyright: | 1991 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660







Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 9

N

# 1988 Certified Sanborn Map





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6, Sheet 6
Volume 6, Sheet 8
Volume 6, Sheet 8

0 Feet 165 330 660

N

# 1987 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # B7CC-4A0D-8FDE

Site Name: SBMT
Address: 646 Second Avenue
City, ST, ZIP: Brooklyn NY 11232
Client: STV Inc.
EDR Inquiry: 3929425.21
Order Date: 5/5/2014 1:19:00 PM
Certification # B7CC-4A0D-8FDE
Copyright: 1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6, Sheet 6
Volume 6, Sheet 8

N