Appendix E: Hazardous Materials

65th Street Expansion - Cross Harbor
2nd Avenue / 65th Street
Brooklyn, NY 11220

Inquiry Number: 3164235.4
September 12, 2011

The EDR-City Directory Abstract

Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2009 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2005. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 100 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2005	Hill-Donnelly Corporation	-	-	-	-
2000	Cole Information Services	-	-	-	-
1997	NYNEX	-	-	-	-
1992	NYNEX Informantion Resource Co.	-	-	-	-
1985	NYNEX Information Resources Company	-	-	-	-
1980	New York Telephone	-	-	-	-
1976	New York Telephone	-	-	-	-
1973	New York Telephone	-	-	-	-
1970	New York Telephone	-	-	-	-
1965	New York Telephone	-	-	-	-
1960	New York Telephone	-	-	-	-
1949	New York Telephone Company	-	-	-	-
1945	New York Telephone	-	-	-	-
1940	New York Telephone	-	-	-	-
1934	R. L. Polk & Co.	-	-	-	-
1928	New York Telephone	-	-	-	-

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

2nd Avenue / 65th Street
Brooklyn, NY 11220

FINDINGS DETAIL

Target Property research detail.

No Addresses Found

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Addresses Found

65th Street Expansion - Cross Harbor
2nd Avenue / 65th Street
Brooklyn, NY 11220

Inquiry Number: 3164235.2s
September 15, 2011

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	7
Orphan Summary	423
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	A-9

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2ND AVENUE / 65TH STREET
BROOKLYN, NY 11220

COORDINATES

Latitude (North):	40.642600 - 40° 38' 33.4''
Longitude (West):	74.027900 - 74° 1' 40.4''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	582197.9
UTM Y (Meters):	4499326.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	40074-F1 JERSEY CITY, NJ
Most Recent Revision:	1981

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	2006, 2008
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 7 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
NYC EDC 65TH ST RAIL YARD & FLOAT 65TH ST & 2ND AVE BROOKLYN, NY 11220	FINDS	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List

EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

State- and tribal - equivalent CERCLIS

SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State
VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

CBS UST ---------- Chemical Bulk Storage Database
MOSF UST ---------- Major Oil Storage Facilities Database
CBS AST ---------- Chemical Bulk Storage Database
MOSF AST ---------- Major Oil Storage Facilities Database
MOSF ---------- Major Oil Storage Facility Site Listing
CBS ---------- Chemical Bulk Storage Site Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

ENG CONTROLS ---------- Registry of Engineering Controls

INST CONTROL ..... Registry of Institutional Controls
RES DECL ..... Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ..... Voluntary Cleanup Priority Listing
VCP ..... Voluntary Cleanup Agreements

State and tribal Brownfields sites

ERP ..... Environmental Restoration Program Listing
BROWNFIELDS ..... Brownfields Site List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
SWTIRE ..... Registered Waste Tire Storage & Facility List
SWRCY ..... Registered Recycling Facility List
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL ..... Clandestine Drug Labs
DEL SHWS ..... Delisted Registry Sites
US HIST CDL ..... National Clandestine Laboratory Register

Local Land Records

LIENS 2 ..... CERCLA Lien Information
LUCIS ..... Land Use Control Information System

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System

Other Ascertainable Records

DOT OPS ..... Incident and Accident Data
DOD ..... Department of Defense Sites
CONSENT ..... Superfund (CERCLA) Consent Decrees
ROD ..... Records Of Decision
UMTRA ..... Uranium Mill Tailings Sites
MINES ..... Mines Master Index File
TSCA ..... Toxic Substances Control Act
FTTS ..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS ..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS Section 7 Tracking Systems
ICIS Integrated Compliance Information System
PADS PCB Activity Database System
MLTS Material Licensing Tracking System
RADINFO Radiation Information Database
RAATS RCRA Administrative Action Tracking System
HSWDS Hazardous Substance Waste Disposal Site Inventory
UIC Underground Injection Control Wells
DRYCLEANERS Registered Drycleaners
NPDES State Pollutant Discharge Elimination System
AIRS Air Emissions Data
E DESIGNATION E DESIGNATION SITE LISTING
INDIAN RESERV Indian Reservations
SCRD DRYCLEANERS State Coalition for Remediation of Drycleaners Listing
PCB TRANSFORMER PCB Transformer Registration Database
COAL ASH EPA Coal Combustion Residues Surface Impoundments List
COAL ASH Coal Ash Disposal Site Listing
FINANCIAL ASSURANCE Financial Assurance Information Listing
COAL ASH DOE Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/15/2011 has revealed that there are 2

RCRA-LQG sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYCEDC - BROOKLYN ARMY TERMINA	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E33	87
CON EDISON - MANHOLE 52535	71 STREET & RIDGE BLVD	SSW 1/8 - 1/4 (0.169 mi.)	V138	392

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/15/2011 has revealed that there is 1 RCRA-SQG site within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
I E H CORP	***140 58TH ST - 8TH FLOOR***	***NNE 0 - 1/8 (0.050 mi.)***	***E35***	***89***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 06/15/2011 has revealed that there are 2 RCRA-CESQG sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VANGUARD DIRECT	***140 58TH ST SUITE 1A BL***	***NNE 0 - 1/8 (0.050 mi.)***	***E46***	***132***
MORGAN STANLEY & CO INC	140 58TH ST STE G	NNE 0 - 1/8 (0.050 mi.)	E48	151

Federal ERNS list

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 04/05/2011 has revealed that there are 5 ERNS sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
140 58TH ST	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E30	86
140 58TH ST	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E32	87
140 58TH ST	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E34	89
140 58TH ST	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E45	131
INFRONT OF 260 65TH ST	INFRONT OF 260 65TH ST	SE 0 - 1/8 (0.086 mi.)	H61	170

EXECUTIVE SUMMARY

State and tribal leaking storage tank lists

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 07/05/2011 has revealed that there are 8 LTANKS sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J.C. DUGGAN INC. Date Closed: 12/12/1996	***111 58TH ST***	***NE 0 - 1/8 (0.050 mi.)***	***D23***	***64***
6665 COLONIAL ROAD Date Closed: 11/16/2006	6665 COLONIAL ROAD	SW 0 - 1/8 (0.101 mi.)	F79	243
Not reported Date Closed: 7/18/2002	57TH ST/FIRST AVE	NE 0 - 1/8 (0.102 mi.)	K90	266
BQE @ 56TH ST EXIT Date Closed: 6/7/1995	***BQE @ 56TH ST EXIT***	***ENE 0 - 1/8 (0.107 mi.)***	***K94***	***271***
NYFD CO 241 Date Closed: 1/6/1998	***6630 3RD AVE***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U131***	***371***
GRUBER RESIDENCE Date Closed: 3/13/2006	139 SENATOR ST	SW 1/8 - 1/4 (0.179 mi.)	V140	397
CLOSED-LACKOF RECENT INFO Date Closed: 3/6/2003	***VOLCKENING INC,6702 3 A***	***SSE 1/8 - 1/4 (0.181 mi.)***	***U146***	***414***

Lower Elevation	Address	Direction / Distance	Map ID	Page
OWLS HEAD WPC/BKLYN Date Closed: 1/21/1991	***OWLS HEAD WPC***	***SW 0 - 1/8 (0.108 mi.)***	***95***	***273***

HIST LTANKS: A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database.

A review of the HIST LTANKS list, as provided by EDR, and dated 01/01/2002 has revealed that there are 5 HIST LTANKS sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J.C. DUGGAN INC. Date Closed: 12/12/96	***111 58TH ST***	***NE 0 - 1/8 (0.050 mi.)***	***D23***	***64***
BQE @ 56TH ST EXIT Date Closed: 06/07/95	***BQE @ 56TH ST EXIT***	***ENE 0 - 1/8 (0.107 mi.)***	***K94***	***271***
NYFD CO 241 Date Closed: 01/06/98	***6630 3RD AVE***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U131***	***371***
CLOSED-LACKOF RECENT INFO Date Closed: / /	***VOLCKENING INC,6702 3 A***	***SSE 1/8 - 1/4 (0.181 mi.)***	***U146***	***414***

Lower Elevation	Address	Direction / Distance	Map ID	Page
OWLS HEAD WPC/BKLYN Date Closed: 01/21/91	***OWLS HEAD WPC***	***SW 0 - 1/8 (0.108 mi.)***	***95***	***273***

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the TANKS list, as provided by EDR, and dated 07/05/2011 has revealed that there is 1 TANKS site within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LIFE QUALITY MOTOR GROUP	201 64TH STREET	SE 0 - 1/8 (0.087 mi.)	I67	187

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 07/05/2011 has revealed that there are 19 UST sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KEEP DRIVING CO. INC.	5901 2ND AVENUE	ESE 0 - 1/8 (0.007 mi.)	A4	14
VAHL, INC.	***6401 SECOND AVENUE***	***SE 0 - 1/8 (0.009 mi.)***	***B11***	***30***
211 SERVICE LTD. LIAB. CO.	***211 63RD STREET***	***SE 0 - 1/8 (0.023 mi.)***	***14***	***44***
HARBOR CHARLIE	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E26	70
6647 BERGEN REALTY LLC	6647 BERGEN PLACE	SW 0 - 1/8 (0.077 mi.)	57	165
BAYRIDGE AIR RIGHTS	***260 65TH STREET***	***SE 0 - 1/8 (0.086 mi.)***	***H62***	***171***
5705 FIRST AVENUE OWNER REALTY	***5705 FIRST AVENUE***	***NE 0 - 1/8 (0.098 mi.)***	***K70***	***190***
ILANA ENTERPRISES ICN	***5702 SECOND AVE***	***NE 0 - 1/8 (0.099 mi.)***	***J72***	***197***
57 PHAT 2ND SERVICE STATION, I	***5701 SECOND AVENUE***	***NE 0 - 1/8 (0.100 mi.)***	***J75***	***211***
LIVERPOOL INDUSTRIES INC	***162 57TH ST***	***NE 0 - 1/8 (0.101 mi.)***	***J76***	***218***
COLONIAL PARK COOPERATIVE CORP	***6665 COLONIAL ROAD***	***SW 0 - 1/8 (0.101 mi.)***	***F80***	***244***
SIEGBERT KOHLMAN ENTERPRISES,	***200 60TH STREET***	***SE 0 - 1/8 (0.101 mi.)***	***N82***	***248***
MARINO POLISHING & PLATING	***244 59TH ST***	***SE 0 - 1/8 (0.121 mi.)***	***O100***	***284***
BLUE DIAMOND FUEL OIL CORP	***243 57TH ST***	***ENE 0 - 1/8 (0.123 mi.)***	***G102***	***291***
6002-6014 & 6016-6024 3RD AVE.	***6002-6014 & 6016-6024 3***	***SE 1/8 - 1/4 (0.135 mi.)***	***106***	***299***
7-ELEVEN #32884	301 65TH STREET	SE 1/8 - 1/4 (0.157 mi.)	R123	337
L & S SERVICE CENTER INC	***301 65TH STREET***	***SE 1/8 - 1/4 (0.157 mi.)***	***R125***	***343***
ENGINE 241 / LADDER 109	***6630 3RD AVENUE***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U132***	***374***
VOLKENING INC.	***6702 3RD AVENUE***	***SSE 1/8 - 1/4 (0.181 mi.)***	***U145***	***411***

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the AST list, as provided by EDR, and dated 07/05/2011 has revealed that there are 10 AST sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KEEP DRIVING CO. INC.	5901 2ND AVENUE	ESE 0 - 1/8 (0.007 mi.)	A3	11
CENTRAL DEPOT/FLEET SERVICES	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E40	120
6623 REALTY ASSOC	***6623 RIDGE BLVD***	***SSW 0 - 1/8 (0.099 mi.)***	***L71***	***194***
MUNOZ AUTO REPAIR INC.	5702 2ND AVENUE	NE 0 - 1/8 (0.099 mi.)	J73	208
DRIVING MORE AUTO REPAIR INC	***203 60TH ST***	***SE 0 - 1/8 (0.102 mi.)***	***N91***	***268***
BIRNRIDGE HOUSE INC	6702 RIDGE BLVD	SW 1/8 - 1/4 (0.126 mi.)	L103	296
CHARLES T. AUTO REPAIR, INC.	212 56TH STREET	NE 1/8 - 1/4 (0.152 mi.)	P117	326

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SEI CO REALTY ASSOC LLC	***5800 3 AVE***	***ESE 1/8 - 1/4 (0.158 mi.)***	***S126***	***359***
6701 COLONIAL APTS., LLC	6701 COLONIAL ROAD	SW 1/8 - 1/4 (0.161 mi.)	T127	362
6735 RIDGE BLVD	***6735 RIDGE BLVD***	***SSW 1/8 - 1/4 (0.170 mi.)***	***V139***	***393***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Registered Storage Tanks

HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 18 HIST UST sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RICHARD RIBELLINO & ALVA PARTN	5901 2ND AVENUE	E 0 - 1/8 (0.007 mi.)	A2	7
VAHL, INC.	***6401 SECOND AVENUE***	***SE 0 - 1/8 (0.009 mi.)***	***B11***	***30***
211 SERVICE LTD. LIAB. CO.	***211 63RD STREET***	***SE 0 - 1/8 (0.023 mi.)***	***14***	***44***
BAYRIDGE AIR RIGHTS	***260 65TH STREET***	***SE 0 - 1/8 (0.086 mi.)***	***H62***	***171***
201 64TH STREET CO.	201 64TH STREET	SE 0 - 1/8 (0.087 mi.)	I63	174
5705 FIRST AVENUE OWNER REALTY	***5705 FIRST AVENUE***	***NE 0 - 1/8 (0.098 mi.)***	***K70***	***190***
ILANA ENTERPRISES ICN	***5702 SECOND AVE***	***NE 0 - 1/8 (0.099 mi.)***	***J72***	***197***
57 PHAT 2ND SERVICE STATION, I	***5701 SECOND AVENUE***	***NE 0 - 1/8 (0.100 mi.)***	***J75***	***211***
LIVERPOOL INDUSTRIES INC	***162 57TH ST***	***NE 0 - 1/8 (0.101 mi.)***	***J76***	***218***
COLONIAL PARK COOPERATIVE CORP	***6665 COLONIAL ROAD***	***SW 0 - 1/8 (0.101 mi.)***	***F80***	***244***
SIEGBERT KOHLMAN ENTERPRISES,	***200 60TH STREET***	***SE 0 - 1/8 (0.101 mi.)***	***N82***	***248***
MARINO POLISHING & PLATING	***244 59TH ST***	***SE 0 - 1/8 (0.121 mi.)***	***O100***	***284***
BLUE DIAMOND FUEL OIL CORP	***243 57TH ST***	***ENE 0 - 1/8 (0.123 mi.)***	***G102***	***291***
6002-6014 & 6016-6024 3RD AVE.	***6002-6014 & 6016-6024 3***	***SE 1/8 - 1/4 (0.135 mi.)***	***106***	***299***
L & S SERVICE CENTER INC	***301 65TH STREET***	***SE 1/8 - 1/4 (0.157 mi.)***	***R125***	***343***
6701 COLONIAL APTS., LLC	6701 COLONIAL ROAD	SW 1/8 - 1/4 (0.161 mi.)	T128	364
ENGINE 241 / LADDER 109	***6630 3RD AVENUE***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U132***	***374***
VOLKENING INC.	***6702 3RD AVENUE***	***SSE 1/8 - 1/4 (0.181 mi.)***	***U145***	***411***

HIST AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the HIST AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 5 HIST AST sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
6623 REALTY ASSOC	***6623 RIDGE BLVD***	***SSW 0 - 1/8 (0.099 mi.)***	***L71***	***194***
BIRNRIDGE HOUSE INC	6702 RIDGE BLVD	SW 1/8 - 1/4 (0.126 mi.)	L104	298
CHARLES T. AUTO REPAIR, INC.	212 56TH ST.	NE 1/8 - 1/4 (0.152 mi.)	P116	325
SEI CO REALTY ASSOC LLC	***5800 3 AVE***	***ESE 1/8 - 1/4 (0.158 mi.)***	***S126***	***359***
6735 RIDGE BLVD	***6735 RIDGE BLVD***	***SSW 1/8 - 1/4 (0.170 mi.)***	***V139***	***393***

EXECUTIVE SUMMARY

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 07/05/2011 has revealed that there are 43 NY Spills sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
245 GALLONS FROM TM 2341 Date Closed: 12/21/2006	2 AVENUE & 64 STREET	SE 0 - 1/8 (0.007 mi.)	B5	19
PM 2341 Date Closed: 10/25/2002	***2ND ST AND 64TH ST***	***SE 0 - 1/8 (0.007 mi.)***	***B7***	***22***
6423 SECOND AVE Date Closed: 12/6/1995	***6423 SECOND AVE***	***SE 0 - 1/8 (0.008 mi.)***	***B9***	***25***
VAHL INC. Date Closed: 6/27/2007	6401 SECOND AVENUE	SE 0 - 1/8 (0.009 mi.)	B10	28
PERGAMENT STORES Date Closed: 2/11/2003	***57 65TH AVE***	***SE 0 - 1/8 (0.025 mi.)***	***C15***	***47***
SERVICE BOX #49934 Date Closed: 5/18/2000	***45-61ST STREET***	***SE 0 - 1/8 (0.031 mi.)***	***16***	***50***
DRUM RUN Date Closed: 12/1/2006	63RD - 64TH STREET	SE 0 - 1/8 (0.033 mi.)	B17	52
58 & 1H2 AVE Date Closed: 8/21/1987	***58 & 1H2 AVE***	***NE 0 - 1/8 (0.043 mi.)***	***D18***	***54***
ROADWAY Date Closed: 3/8/2010	58TH STREET AND 1ST AVE	NE 0 - 1/8 (0.049 mi.)	D22	63
NYC DEPT OF TRANSPORTATION Date Closed: 7/30/2009	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E36	115
NYC DEPT OF TRANSPORTATION Date Closed: 8/20/2009	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E39	119
NYC ECOMONIC DEVELOPMENT Date Closed: 2/28/2003	***140 58TH STREET***	***NNE 0 - 1/8 (0.050 mi.)***	***E42***	***128***
MANHOLE 51791 Date Closed: 12/1/2005	129 58 STREET - ON SIDE	N 0 - 1/8 (0.058 mi.)	D55	161
86-19 SHORE ROAD Date Closed: 11/5/1992	***86-19 SHORE ROAD***	***SW 0 - 1/8 (0.063 mi.)***	***F56***	***162***
VAULT 5078 Date Closed: 5/17/2001	***260 65TH ST***	***SE 0 - 1/8 (0.086 mi.)***	***H60***	***168***
A1 1ST CLASS MOVING & Date Closed: 1/12/2006	***201 64TH STREET***	***SE 0 - 1/8 (0.087 mi.)***	***I64***	***179***
BROOKLYN ARSENAL Date Closed: 8/28/2001	***201 64TH STREET***	***SE 0 - 1/8 (0.087 mi.)***	***I66***	***184***
249 58TH STREET Date Closed: 2/11/2003	***249 58TH STREET***	***E 0 - 1/8 (0.093 mi.)***	***G69***	***187***
57TH ST. & 2ND AVENUE Date Closed: 1/13/1995	***57TH ST/2ND AVE***	***NE 0 - 1/8 (0.101 mi.)***	***J83***	***251***
ONE PINT OIL IN MANHOLE # 5171 Date Closed: 4/24/2007	57 STREET & 1 AVENUE	NE 0 - 1/8 (0.102 mi.)	K87	260

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
57TH STREET & 1ST AVE. Date Closed: 12/19/1991	***57TH ST. & 1ST AVE.***	***NE 0 - 1/8 (0.102 mi.)***	***K88***	***262***
NEW YORK HARBOR UPPER BAY Date Closed: 7/19/2002	FIRST AVE /57TH ST	NE 0 - 1/8 (0.102 mi.)	K89	265
MANHOLE #6028 Date Closed: 6/13/2002	***67TH & RIDGE BLVD***	***SW 0 - 1/8 (0.121 mi.)***	***L97***	***276***
MH 6028 Date Closed: 5/5/1999	***67ST/RIDGE BLVD***	***SW 0 - 1/8 (0.121 mi.)***	***L98***	***279***
TM 1074 Date Closed: 3/19/2002	***67TH ST & RIDGE BLVD***	***SW 0 - 1/8 (0.121 mi.)***	***L99***	***281***
VS 5173 Date Closed: 9/23/2004	5620 FIRST AVE	NE 1/8 - 1/4 (0.140 mi.)	K107	309
MH 2210 Date Closed: 6/19/2001	***5620 1ST AVE***	***NE 1/8 - 1/4 (0.140 mi.)***	***K108***	***311***
LUTHERAN MEDICAL CENTER Date Closed: 7/20/2009	***5610 2ND AVENUE***	***NE 1/8 - 1/4 (0.144 mi.)***	***P109***	***314***
ONE PINT OIL IN XFMR VAULT 581 Date Closed: 12/21/2006	1 AVENUE & 56 STREET	NE 1/8 - 1/4 (0.151 mi.)	Q112	319
VAULT #5674 Date Closed: 5/3/2007	1 AVENUE & 56 STREET	NE 1/8 - 1/4 (0.151 mi.)	Q113	321
TWO GALLONS OIL IN VAULT # 571 Date Closed: 3/16/2007	56 STREET & 1 AVENUE	NE 1/8 - 1/4 (0.151 mi.)	Q115	323
Not reported Date Closed: 4/13/2004	65TH ST & 3RD AVE	SE 1/8 - 1/4 (0.154 mi.)	R118	328
MANHOLE 6077 Date Closed: 3/4/2002	***65TH ST & 3RD AVE***	***SE 1/8 - 1/4 (0.154 mi.)***	***R119***	***329***
MANHOLE 6022 Date Closed: 3/4/2002	***65TH ST & 3RD AV***	***SE 1/8 - 1/4 (0.154 mi.)***	***R120***	***332***
CLOSED GAS STATION Date Closed: 5/8/2000	***301 65TH ST***	***SE 1/8 - 1/4 (0.157 mi.)***	***R124***	***340***
SERVICE BOX - #SB51643 Date Closed: 11/5/1999	***IFO 245 56TH ST***	***ENE 1/8 - 1/4 (0.168 mi.)***	***129***	***366***
ENGINE CO. 241/LADD. CO. 109 F Date Closed: 2/17/2005	***6630 THIRD AVENUE***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U130***	***369***
CON EDISON Date Closed: 5/12/2008	***W49TH ST - SPRINBROOK S***	***SSE 1/8 - 1/4 (0.168 mi.)***	***U133***	***382***
Not reported Date Closed: 4/17/2003	3RD AVE & WAKEMAN PL	SSE 1/8 - 1/4 (0.168 mi.)	U136	388
GOWANUS EXP WB Date Closed: 2/3/1998	***AT 57TH ST***	***E 1/8 - 1/4 (0.180 mi.)***	***S143***	***403***
MANHOLE 6068 Date Closed: 12/17/2001 Date Closed: 8/23/2001	***3RD AVE/67TH ST***	***SSE 1/8 - 1/4 (0.181 mi.)***	***U144***	***405***
5604 3RD AVENUE Date Closed: 5/27/1994	***5604 3RD AVENUE***	***E 1/8 - 1/4 (0.184 mi.)***	***147***	***417***
Not reported Date Closed: 2/6/2001	***6735 RIDGE BLVD APT 2S***	***SSW 1/8 - 1/4 (0.184 mi.)***	***V148***	***419***

EXECUTIVE SUMMARY

NY Hist Spills: This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database.

A review of the NY Hist Spills list, as provided by EDR, and dated 01/01/2002 has revealed that there are 28 NY Hist Spills sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PM 2341	*2ND ST AND 64TH ST*	*SE 0 - 1/8 (0.007 mi.)*	*B7*	*22*
6423 SECOND AVE	*6423 SECOND AVE*	*SE 0 - 1/8 (0.008 mi.)*	*B9*	*25*
PERGAMENT STORES	*57 65TH AVE*	*SE 0 - 1/8 (0.025 mi.)*	*C15*	*47*
SERVICE BOX #49934	*45-61ST STREET*	*SE 0 - 1/8 (0.031 mi.)*	*16*	*50*
58 & 1H2 AVE	*58 & 1H2 AVE*	*NE 0 - 1/8 (0.043 mi.)*	*D18*	*54*
NYC ECOMONIC DEVELOPMENT	*140 58TH STREET*	*NNE 0 - 1/8 (0.050 mi.)*	*E42*	*128*
86-19 SHORE ROAD	*86-19 SHORE ROAD*	*SW 0 - 1/8 (0.063 mi.)*	*F56*	*162*
VAULT 5078	*260 65TH ST*	*SE 0 - 1/8 (0.086 mi.)*	*H60*	*168*
A1 1ST CLASS MOVING &	*201 64TH STREET*	*SE 0 - 1/8 (0.087 mi.)*	*I64*	*179*
BROOKLYN ARSENAL	*201 64TH STREET*	*SE 0 - 1/8 (0.087 mi.)*	*I66*	*184*
249 58TH STREET	*249 58TH STREET*	*E 0 - 1/8 (0.093 mi.)*	*G69*	*187*
57TH ST. & 2ND AVENUE	*57TH ST/2ND AVE*	*NE 0 - 1/8 (0.101 mi.)*	*J83*	*251*
57TH STREET & 1ST AVE.	*57TH ST. & 1ST AVE.*	*NE 0 - 1/8 (0.102 mi.)*	*K88*	*262*
MANHOLE #6028	*67TH & RIDGE BLVD*	*SW 0 - 1/8 (0.121 mi.)*	*L97*	*276*
MH 6028	*67ST/RIDGE BLVD*	*SW 0 - 1/8 (0.121 mi.)*	*L98*	*279*
TM 1074	*67TH ST & RIDGE BLVD*	*SW 0 - 1/8 (0.121 mi.)*	*L99*	*281*
MH 2210	*5620 1ST AVE*	*NE 1/8 - 1/4 (0.140 mi.)*	*K108*	*311*
LUTHERAN MEDICAL CENTER	*5610 2ND AVENUE*	*NE 1/8 - 1/4 (0.144 mi.)*	*P109*	*314*
MANHOLE 6077	*65TH ST & 3RD AVE*	*SE 1/8 - 1/4 (0.154 mi.)*	*R119*	*329*
MANHOLE 6022	*65TH ST & 3RD AV*	*SE 1/8 - 1/4 (0.154 mi.)*	*R120*	*332*
CLOSED GAS STATION	*301 65TH ST*	*SE 1/8 - 1/4 (0.157 mi.)*	*R124*	*340*
SERVICE BOX - #SB51643	*IFO 245 56TH ST*	*ENE 1/8 - 1/4 (0.168 mi.)*	*129*	*366*
ENGINE CO. 241/LADD. CO. 109 F	*6630 THIRD AVENUE*	*SSE 1/8 - 1/4 (0.168 mi.)*	*U130*	*369*
CON EDISON	*W49TH ST - SPRINBROOK S*	*SSE 1/8 - 1/4 (0.168 mi.)*	*U133*	*382*
GOWANUS EXP WB	*AT 57TH ST*	*E 1/8 - 1/4 (0.180 mi.)*	*S143*	*403*
MANHOLE 6068	*3RD AVE/67TH ST*	*SSE 1/8 - 1/4 (0.181 mi.)*	*U144*	*405*
5604 3RD AVENUE	*5604 3RD AVENUE*	*E 1/8 - 1/4 (0.184 mi.)*	*147*	*417*
Not reported	*6735 RIDGE BLVD APT 2S*	*SSW 1/8 - 1/4 (0.184 mi.)*	*V148*	*419*

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 06/15/2011 has revealed that there are 18 RCRA-NonGen sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 56095	*2 AVE & 64 ST*	*SE 0 - 1/8 (0.007 mi.)*	*B6*	*21*
YONG C KIM DRY CLEANERS	*22-27 65TH ST*	*SE 0 - 1/8 (0.013 mi.)*	*C12*	*33*
NEW YORK RAIL CAR CORP	*4 58 ST*	*NE 0 - 1/8 (0.049 mi.)*	*D19*	*56*

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HARBORSIDE INDUSTRIAL CENTER	***58TH ST & 1ST AVE***	***NE 0 - 1/8 (0.049 mi.)***	***D21***	***61***
W Z F INCORPORATED	***140 58TH STREET***	***NNE 0 - 1/8 (0.050 mi.)***	***E25***	***67***
OFFICE FURNITURE SERVICES	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E27***	***73***
NYC ECONOMIC DEVELOPMENT CORP	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E38***	***116***
COMPLETE MAILING SERVICES	***140 58TH ST SUITE 6D***	***NNE 0 - 1/8 (0.050 mi.)***	***E41***	***122***
AMERICAN IDENT PRODS INC	***145 58TH ST***	***NNE 0 - 1/8 (0.051 mi.)***	***E52***	***154***
NAB CONSTRUCTION RAILROAD	***58TH ST & 2ND AVE***	***NE 0 - 1/8 (0.052 mi.)***	***A54***	***159***
201 64TH STREET CO	***201 64TH ST***	***SE 0 - 1/8 (0.087 mi.)***	***I65***	***182***
LIVERPOOL INDUSTRIES INC	***162 57TH ST***	***NE 0 - 1/8 (0.101 mi.)***	***J76***	***218***
VERRAZANO AUTO COLLISION INC	***201 62ND STREET***	***SE 0 - 1/8 (0.101 mi.)***	***M78***	***232***
CUSTOM CRUISIN COLLISION INC	***201 60TH ST***	***SE 0 - 1/8 (0.102 mi.)***	***N85***	***254***
MARINO POLISHING & PLATING INC	***244-254 59TH ST***	***SE 0 - 1/8 (0.121 mi.)***	***O101***	***289***
BAY RIDGE MOTORS	***6002-6020 3RD AVE***	***SE 1/8 - 1/4 (0.149 mi.)***	***N111***	***317***
7-ELEVEN #32884	***6499 3RD AVE***	***SE 1/8 - 1/4 (0.156 mi.)***	***R121***	***335***
VOLCKENING	***6700 THIRD AVENUE***	***SSE 1/8 - 1/4 (0.180 mi.)***	***U142***	***400***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 12/31/2009 has revealed that there is 1 FUDS site within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MILITARY OCEAN TER		NW 0 - 1/8 (0.023 mi.)	13	43

TRIS: The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/2009 has revealed that there is 1 TRIS site within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
IEH CORP	140 58TH ST 8E	NNE 0 - 1/8 (0.050 mi.)	E43	131

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 04/14/2010 has revealed that there are 43 FINDS sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	2 AVE & 64 ST	SE 0 - 1/8 (0.007 mi.)	B8	25
NEW YORK RAIL CAR CORP	***4 58 ST***	***NE 0 - 1/8 (0.049 mi.)***	***D19***	***56***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARINE OCEAN TERMINAL	58TH & 1ST AVE	NE 0 - 1/8 (0.049 mi.)	D20	61
HARBORSIDE INDUSTRIAL CENTER	***58TH ST & 1ST AVE***	***NE 0 - 1/8 (0.049 mi.)***	***D21***	***61***
140 58TH ST BUILDING	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E24	67
W Z F INCORPORATED	***140 58TH STREET***	***NNE 0 - 1/8 (0.050 mi.)***	***E25***	***67***
OFFICE FURNITURE SERVICES	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E27***	***73***
DEFIANCE PRINTING-140 58TH ST	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E28	85
SMITH & WATSON	140 58TH ST	NNE 0 - 1/8 (0.050 mi.)	E29	86
IEH CORP	140 58TH ST 8E	NNE 0 - 1/8 (0.050 mi.)	E31	86
MEAD & JOSIPOVICH-140 58TH ST	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E37	116
NYC ECONOMIC DEVELOPMENT CORP	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E38***	***116***
COMPLETE MAILING SERVICES	***140 58TH ST SUITE 6D***	***NNE 0 - 1/8 (0.050 mi.)***	***E41***	***122***
CITIGROUP GLOBAL MARKETS INC	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E44	131
VANGUARD DIRECT	***140 58TH ST SUITE 1A BL***	***NNE 0 - 1/8 (0.050 mi.)***	***E46***	***132***
SB GRAPHICS CORP-140 58TH ST	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E49	153
EB DESIGNS	140 58TH STREET	NNE 0 - 1/8 (0.050 mi.)	E50	154
B NO 57 CORP - 57TH ST PIER	5802 FIRST AVE	NE 0 - 1/8 (0.050 mi.)	D51	154
AMERICAN IDENT PRODS INC	***145 58TH ST***	***NNE 0 - 1/8 (0.051 mi.)***	***E52***	***154***
MARINE OCEAN TERMINAL	58TH ST & 2ND AVE	NE 0 - 1/8 (0.052 mi.)	A53	159
NAB CONSTRUCTION RAILROAD	***58TH ST & 2ND AVE***	***NE 0 - 1/8 (0.052 mi.)***	***A54***	***159***
C M AUTOBODY SHOP	239 58TH STREET	E 0 - 1/8 (0.082 mi.)	G58	167
BAYRIDGE AIR RIGHTS 260	260 65TH ST	SE 0 - 1/8 (0.086 mi.)	H59	167
201 64TH STREET CO	***201 64TH ST***	***SE 0 - 1/8 (0.087 mi.)***	***I65***	***182***
GALLAGHER SWITCH BOARD CORP	5718 SECOND AVE	NE 0 - 1/8 (0.091 mi.)	J68	187
ILANA ENTERPRISES LTD	5701 2ND AVENUE	NE 0 - 1/8 (0.100 mi.)	J74	210
LIVERPOOL INDUSTRIES INC	***162 57TH ST***	***NE 0 - 1/8 (0.101 mi.)***	***J76***	***218***
PLATINUM TOWING INC	201-211 62ND ST	SE 0 - 1/8 (0.101 mi.)	M77	232
VERRAZANO AUTO COLLISION INC	***201 62ND STREET***	***SE 0 - 1/8 (0.101 mi.)***	***M78***	***232***
W & E BAUM BRONZE TABLET	200 60TH STREET	SE 0 - 1/8 (0.101 mi.)	N81	247
BAY RIDGE MAZDA-201 60TH ST	201 60TH STREET	SE 0 - 1/8 (0.102 mi.)	N84	254
CUSTOM CRUISIN COLLISION INC	***201 60TH ST***	***SE 0 - 1/8 (0.102 mi.)***	***N85***	***254***
DRIVING MORE AUTO REPAIR INC	***203 60TH ST***	***SE 0 - 1/8 (0.102 mi.)***	***N91***	***268***
DRIVING MORE AUTO	203 60 ST.	SE 0 - 1/8 (0.102 mi.)	N92	270
57TH STREET AUTOBODY INC	113 57TH ST	NE 0 - 1/8 (0.103 mi.)	93	270
CEPEDA S AUTO BODY	265 58TH STREET	E 0 - 1/8 (0.112 mi.)	G96	276
MARINO POLISHING & PLATING INC	***244-254 59TH ST***	***SE 0 - 1/8 (0.121 mi.)***	***O101***	***289***
EXOTIC AUTO BODY REPAIRS INC	272 59TH ST	SE 1/8 - 1/4 (0.134 mi.)	O105	299
COMPLETE AUTO REPAIR CORP	6202 3RD AVE	SE 1/8 - 1/4 (0.149 mi.)	M110	317
BAY RIDGE MOTORS	***6002-6020 3RD AVE***	***SE 1/8 - 1/4 (0.149 mi.)***	***N111***	***317***
7-ELEVEN #32884	***6499 3RD AVE***	***SE 1/8 - 1/4 (0.156 mi.)***	***R121***	***335***
7-ELEVEN INC, STORE # 32884	301 65TH STREET	SE 1/8 - 1/4 (0.157 mi.)	R122	336
VOLCKENING	***6700 THIRD AVENUE***	***SSE 1/8 - 1/4 (0.180 mi.)***	***U142***	***400***

MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the MANIFEST list, as provided by EDR, and dated 12/31/2010 has revealed that there are 24 MANIFEST sites within approximately 0.189 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE 56095	***2 AVE & 64 ST***	***SE 0 - 1/8 (0.007 mi.)***	***B6***	***21***
YONG C KIM DRY CLEANERS	***22-27 65TH ST***	***SE 0 - 1/8 (0.013 mi.)***	***C12***	***33***
NEW YORK RAIL CAR CORP	***4 58 ST***	***NE 0 - 1/8 (0.049 mi.)***	***D19***	***56***
W Z F INCORPORATED	***140 58TH STREET***	***NNE 0 - 1/8 (0.050 mi.)***	***E25***	***67***
OFFICE FURNITURE SERVICES	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E27***	***73***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
I E H CORP	***140 58TH ST - 8TH FLOOR***	***NNE 0 - 1/8 (0.050 mi.)***	***E35***	***89***
NYC ECONOMIC DEVELOPMENT CORP	***140 58TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***E38***	***116***
COMPLETE MAILING SERVICES	***140 58TH ST SUITE 6D***	***NNE 0 - 1/8 (0.050 mi.)***	***E41***	***122***
NYC ECOMONIC DEVELOPMENT	***140 58TH STREET***	***NNE 0 - 1/8 (0.050 mi.)***	***E42***	***128***
VANGUARD DIRECT	***140 58TH ST SUITE 1A BL***	***NNE 0 - 1/8 (0.050 mi.)***	***E46***	***132***
MORGAN STANLEY & CO INC.	140 58TH ST 8 G	NNE 0 - 1/8 (0.050 mi.)	E47	138
AMERICAN IDENT PRODS INC	***145 58TH ST***	***NNE 0 - 1/8 (0.051 mi.)***	***E52***	***154***
201 64TH STREET CO	***201 64TH ST***	***SE 0 - 1/8 (0.087 mi.)***	***I65***	***182***
LIVERPOOL INDUSTRIES INC	***162 57TH ST***	***NE 0 - 1/8 (0.101 mi.)***	***J76***	***218***
VERRAZANO AUTO COLLISION INC	***201 62ND STREET***	***SE 0 - 1/8 (0.101 mi.)***	***M78***	***232***
CUSTOM CRUISIN COLLISION INC	***201 60TH ST***	***SE 0 - 1/8 (0.102 mi.)***	***N85***	***254***
CONSOLIDATED EDISON	EAST 57TH STREET AND 1S	NE 0 - 1/8 (0.102 mi.)	K86	259
BAY RIDGE MOTORS	***6002-6020 3RD AVE***	***SE 1/8 - 1/4 (0.149 mi.)***	***N111***	***317***
CONSOLIDATED EDISON	1 AVE & 56 ST V5674	NE 1/8 - 1/4 (0.151 mi.)	Q114	322
CONSOLIDATED EDISON	WAKEMAN PL & 3 AVE	SSE 1/8 - 1/4 (0.168 mi.)	U134	385
CONSOLIDATED EDISON	3 AVE & WAKEMAN PL	SSE 1/8 - 1/4 (0.168 mi.)	U135	387
CONSOLIDATED EDISON	71 STREET & RIDGE BLVD	SSW 1/8 - 1/4 (0.169 mi.)	V137	390
CONSOLIDATED EDISON	317 65TH STREET - MH 60	SE 1/8 - 1/4 (0.179 mi.)	R141	398
VOLCKENING	***6700 THIRD AVENUE***	***SSE 1/8 - 1/4 (0.180 mi.)***	***U142***	***400***

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 360 records.

Site Name	Database(s)
CONSOLIDATED EDISON MH59268	MANIFEST
CONSOLIDATED EDISON MH55673	MANIFEST
MTA NYCT - 45TH ST STA N&R LINE	RCRA-CESQG, FINDS, MANIFEST
CON ED - MH 5789	RCRA-NonGen, MANIFEST
CONSOLIDATED EDISON	MANIFEST
CONSOLIDATED EDISON	MANIFEST
BELL ATLANTIC-NY	MANIFEST
CONSOLIDATED EDISON	MANIFEST
NYCDEP	MANIFEST
CONSOLIDATED EDISON	MANIFEST
CONSOLIDATED EDISON - MH 2901	MANIFEST
CONSOLIDATED EDISON	RCRA-NonGen, MANIFEST
NYNEX	MANIFEST
BELL ATLANTIC-NY	MANIFEST
CONSOLIDATED EDISON	MANIFEST
CONSOLIDATED EDISON	MANIFEST
CONSOLIDATED EDISON	MANIFEST
NYSDOT	RCRA-NonGen, FINDS, MANIFEST
CONSOLIDATED EDISON MH6322	MANIFEST
CONSOLIDATED EDISON	MANIFEST
K - SCHOLES ST. STATION	SHWS
CITYWIDE CESSPOOL COMPANY	SWF/LF, NY Spills, NY Hist Spills
SMITH STREET	SWF/LF, NY Spills, NY Hist Spills
GREEN HILL	LTANKS
GAS MAIN IN STREET	LTANKS
COMMERCIAL SITE - TTF	LTANKS
2110 BOLTON STREET	LTANKS, HIST LTANKS
2006 A FULTON STREET	LTANKS
OWL'S HEAD WPCP	UST
PUBLIC SCHOOL 314 - BROOKLYN	AST, HIST AST
CON EDISON - MANHOLE 5786	RCRA-LQG
CON EDISON - MANHOLE 5778	RCRA-LQG
CON EDISON - MANHOLE 5780	RCRA-LQG
CON EDISON - MANHOLE 5887	RCRA-LQG
CON EDISON - MANHOLE 58551	RCRA-LQG
CON EDISON - MANHOLE 52161	RCRA-LQG
CON EDISON - MANHOLE 52007	RCRA-LQG
CON EDISON - MANHOLE 57634	RCRA-LQG
NYSDOT BIN 223123A	RCRA-LQG
NYSDOT BIN 2231239	RCRA-LQG
NYSDOT BIN 106531B	RCRA-LQG
NYSDOT BIN 106531E	RCRA-LQG
NYSDOT BIN 106531M	RCRA-LQG
NYSDOT BIN 106531L	RCRA-LQG
CON EDISON - CUSTOMER MANHOLE 6468	RCRA-NonGen
CON EDISON - VAULT 5674	RCRA-NonGen
CON EDISON	RCRA-CESQG
NYCP&R - SPRING CREEK PARK	RCRA-CESQG
GRAND STREET	HMIRS
GRAND STREET	HMIRS
GRAND STREET	HMIRS
100TH STREET PLAYGROUND 100TH AND	ERNS
111TH STREET	ERNS
147TH STREET BEACH	ERNS
17TH AVE AND 59TH STREET	ERNS
22ND STREET & 3RD AVE	ERNS
EAST 22ND STREET AND CLINTON ROAD.	ERNS

EXECUTIVE SUMMARY

2ND AVENUE AND 6TH STREET	ERNS
2ND AVENUE AND 29TH STREET	ERNS
4TH AVENUE AND 1ST STREET	ERNS
#4 53 STREET	ERNS
53RD STREET	ERNS
0010 57TH ST - STILLWELL AVE	ERNS
58TH STREET AND AVE U	ERNS
5TH AVE AND 6TH STREET	ERNS
64TH STREET AND 3RD AVE	ERNS
EAST 66TH STREET AND	ERNS
EAST 68TH STREET	ERNS
EAST 68TH STREET AND AVE U	ERNS
6TH STREET AND 2ND AVE	ERNS
6TH STREET ADN 2ND AVE	ERNS
86TH STREET ON R LINE	ERNS
9TH STREET AND	ERNS
ABANDON VESSEL 21ST STREET	ERNS
ASH STREET AND MANHATTAN AVENUE	ERNS
1485 BEACON STREET	ERNS
BEHIND WHITMAN DRIVE / NEAR OHIO W	ERNS
BELT PARKWAY NY HARBOR	ERNS
BERGAN BEACH YACHT CLUB EAST 66TH	ERNS
3161 BRIGHTON 6 STREET	ERNS
BROOKLYN ARMY TERMINAL 65TH ST AT	ERNS
BUTTERVILLE CHANNEL - BUOY #1	ERNS
CAROL AND NEVINS STREET	ERNS
CAROL AND NEVINS STREET	ERNS
408 CARROL STREET	ERNS
COLUMBIA STREET	ERNS
COWANUS CANAL 29TH STREET AND 2ND	ERNS
CROPSEY AVE. CORNER OF BAY 54TH ST	ERNS
CROPSEY AVE. CORNER OF BAY 54TH ST	ERNS
NORTH FIRST STREET OIL FARM 214 KE	ERNS
55 GOLD STREET/ JOHN STREET	ERNS
GRAND STREET BRIDGE	ERNS
GREEN STREET AN MCGUINESS BLVD.	ERNS
NY HARBOR	ERNS
HAVA DAIRY BOND STREET	ERNS
HOLSEY STREET STATION	ERNS
HOPKINS AVENUE AND FULTON STREET I	ERNS
INTERSECTION OF HICKS AND KANE STR	ERNS
INTERSECTION OF BROADWAY AND FULTO	ERNS
KNAPP STREET	ERNS
MENAHAN STREET	ERNS
NEW YORK HARBOR & COASTAL NY WATER	ERNS
SOUTH OF THE STATION AT HALSEY STR	ERNS
OLD FULTON STREET	ERNS
RIVER STREET AND GRAND ST 94TH POL	ERNS
EAST RIVER BETWEEN N13 TO N16 STRE	ERNS
SHEEN SIZE: 1/2 PINT OF UNKNOWN OI	ERNS
SHEEPSHEAD BAY CROSS STREET OF EMM	ERNS
SHORE PARKWAY BETWEEN BAY 14TH STR	ERNS
SMITH STREET AND 9TH STREET	ERNS
STREET	ERNS
52 STREET AND 1ST AVENUE	ERNS
H STREET	ERNS
THE NEW YORK HARBOR	ERNS
UNKNOWN SHEEN ON THE STREET	ERNS
UNKNOWN SHEEN INCIDENT - SHEEPSHEA	ERNS
IN FRONT OF THIS ADDRESS 231 VARIC	ERNS
CON ED-11TH STREET CONDUIT	FINDS
NYC EDC - 23RD ST PIER	FINDS

NYC EDC - BROOKLYN WHOLESALE MEAT	FINDS
NYC DDC - 64TH ST	FINDS
PORT AUTHORITY OF NY/NJ - PIER 1	FINDS
NYC PARKS - PLUMB BEACH	FINDS
CON EDISON - CUSTOMER MANHOLE 6468	FINDS
NYCP&R - SPRING CREEK PARK	FINDS
NYC DPR - FOUR SPARROWS MARSH	FINDS
NYC EDC - PIER 12	FINDS
CON EDISON - VAULT 5674	FINDS
BAY RIDGE SUBARU - 530-63 STREET	FINDS
KINGS HARBOR VIEW-VAN BRUNT TO PIE	FINDS
NYS OPRHP - EMPIRE FULTON FERRY ST	FINDS
NEW YORK (C) - OWLS HEAD WPCP	FINDS
MANHOLE 4801 - STERLING	NY Spills, NY Hist Spills
N3 AND N4TH STREET	NY Spills, NY Hist Spills
DRUM RUN	NY Spills
VACANT LOT - X OF 2ND	NY Spills
MANHOLE #55328	NY Spills
PRIVATE RESIDENCE	NY Spills
531 144TH STREET	NY Spills, NY Hist Spills
14 AVE. & 15TH STREET	NY Spills, NY Hist Spills
ON STREET	NY Spills
101 EAST 179TH STREET	NY Spills, NY Hist Spills
17TH AVE & BELT PKWY	NY Spills
EAST 18TH STREET	NY Spills
18TH AV BET 65TH & 70TH S	NY Spills, NY Hist Spills
GOWANUS GAS TURBINE STA	NY Spills, NY Hist Spills
KAY ROCK SCREEN PRINTING	NY Spills
EAST 26TH STREET	NY Spills, NY Hist Spills
HENDRIX STREET / 26TH WAR	NY Spills, NY Hist Spills
CON EDISON	NY Spills, NY Hist Spills
27TH ST & 2ND AVENUE	NY Spills, NY Hist Spills
GOWANUS TURBINE SITE	NY Spills, NY Hist Spills
E 29TH ST & KINGS HWY	NY Spills, NY Hist Spills
SOUTH 2ND STREET	NY Spills, NY Hist Spills
2NS AVE & E. 154TH ST	NY Spills, NY Hist Spills
BS 3147 HAMILTON AND	NY Spills, NY Hist Spills
MANHOLE 63639	NY Spills, NY Hist Spills
SB 38848	NY Spills, NY Hist Spills
43RD ST BETWEEN	NY Spills, NY Hist Spills
BETWEEN 9TH / 10 TH STREE	NY Spills
29TH ST	NY Spills
SOUTH 2ND ST.	NY Spills, NY Hist Spills
CASTLE HARBOR REST.	NY Spills
36TH STREET	NY Spills, NY Hist Spills
STREET SPILL	NY Spills
IN THE STREET	NY Spills
23RD STREET AND	NY Spills, NY Hist Spills
PRESIDENT STREET &	NY Spills, NY Hist Spills
MH 55485	NY Spills, NY Hist Spills
FEEDER 25	NY Spills
MAN HOLE 5354	NY Spills
MANHOLE 57618	NY Spills, NY Hist Spills
54 STREET/VERNON BLVD	NY Spills, NY Hist Spills
BAY RIDGE CANAL - 57TH ST	NY Spills, NY Hist Spills
EAST 5TH ST/ CROSS ST GRRENWOOD AV	NY Spills
9TH STREET AT	NY Spills, NY Hist Spills
62ND STREET 3RD AVE.	NY Spills, NY Hist Spills
MANHOLE 15470	NY Spills, NY Hist Spills
GOWANIS HWY BY 65TH ST	NY Spills, NY Hist Spills
STREET	NY Spills
69TH ST - AVE.W	NY Spills, NY Hist Spills

38TH STREET YARD	NY Spills
38TH STREET YARD	NY Spills, NY Hist Spills
EAST 83RD STREET SUB STATION	NY Spills
86TH STREET - BELL PARKWA	NY Spills, NY Hist Spills
92ND ST - I278	NY Spills, NY Hist Spills
EAST 92ND STREET	NY Spills, NY Hist Spills
ENTRANCE TO 38TH STREET Y	NY Spills
BETWEEN 37TH STREET AND	NY Spills, NY Hist Spills
38TH STREET AT CORNER OF	NY Spills
ON STREET	NY Spills
IN THE AREA OF NY HARBOR	NY Spills, NY Hist Spills
EAST 89TH STREET	NY Spills, NY Hist Spills
MANHOLE # 71883	NY Spills
MANHOLE 2529	NY Spills
BETW/AVE X &	NY Spills
EAST 83RD STREET AT	NY Spills
AVE Z AND KNAPP STREET	NY Spills, NY Hist Spills
MANHOLE 6266	NY Spills, NY Hist Spills
NEW YORK HARBOR	NY Spills
LOWER BAY	NY Spills, NY Hist Spills
PARK CONSTRUCTION	NY Spills
RAMP D/ BELT PKWAY CONSTRUCTION SI	NY Spills
HYDRAULIC OIL LINE LEAK	NY Spills
BELT PKWY E B AT OCEAN AV	NY Spills, NY Hist Spills
BELT PARKWAY @ FLATBUSH A	NY Spills, NY Hist Spills
BELT PKWY-EXIT 2-5	NY Spills, NY Hist Spills
BELT PKWY OIL PUDDLE	NY Spills, NY Hist Spills
BELT PRKWY & KNAPPS AVE	NY Spills, NY Hist Spills
VAULT 2028	NY Spills, NY Hist Spills
SHEEPSHEAD BAY	NY Spills, NY Hist Spills
BELT PKWY & BEDFORD AVE	NY Spills, NY Hist Spills
CONSTRUCTION SITE	NY Spills
ROADWAY	NY Spills
CONSTRUCTION SITE BELT PARKWAY/PAE	NY Spills
CONSTRUCTION PROJECT AT FRESH CREE	NY Spills
SOIL	NY Spills
MILL BASIN BRIDGE	NY Spills
MILL BASIN BRIDGE	NY Spills
BELT PARKWAY	NY Spills
NOLL STREET	NY Spills, NY Hist Spills
PRESIDENT STREET	NY Spills, NY Hist Spills
14 MAJETA STREET	NY Spills, NY Hist Spills
BLDG 128 - NAVY YRD.	NY Spills, NY Hist Spills
BQE - SOUTH LIE BRIDGE	NY Spills, NY Hist Spills
BQE - ATLANTIC AVE	NY Spills, NY Hist Spills
STREET AND SEWER	NY Spills, NY Hist Spills
MANHOLE TM606	NY Spills, NY Hist Spills
FLUSHING & CLASSON AVES.	NY Spills, NY Hist Spills
2653 EAST 26TH STREET	NY Spills, NY Hist Spills
STREET BETW PILLING ST/CH	NY Spills
FOOT OF ADAM STREET	NY Spills, NY Hist Spills
BETWEEN CLAY/BOX STREET	NY Spills
89 JOHN STREET	NY Spills, NY Hist Spills
KNAPP STREET / CONEY ISLA	NY Spills, NY Hist Spills
IN THE STREET	NY Spills
STREET	NY Spills
MANHOLE #- 19415	NY Spills
EAST 98TH STREET AT	NY Spills
DOMINO SUGAR/S 2ND ST	NY Spills, NY Hist Spills
DRY DOCK #4 - NAVY SHIPYR	NY Spills, NY Hist Spills
CONOVER STREET BETWEEN	NY Spills
AVENUE L EAST43RD STREET	NY Spills, NY Hist Spills


EXECUTIVE SUMMARY

ON STREET	NY Spills
CHIEFS HEAD BAY	NY Spills, NY Hist Spills
EMMONS AVE & SHORE RD	NY Spills, NY Hist Spills
STREET	NY Spills
BQE @ ATLANTIC AVE.	NY Spills, NY Hist Spills
VERRAZANO BRIDGE	NY Spills
V2070F	NY Spills, NY Hist Spills
FEEDER ACCIDENT - MH 61598	NY Spills
FT HAMILITON - BLDG 106	NY Spills, NY Hist Spills
STREET	NY Spills
STREET INTERSECTION	NY Spills
GRAND STREET BRIDGE	NY Spills, NY Hist Spills
GRATTAN STREET	NY Spills, NY Hist Spills
NY HARBOR/BKLYN FLATS	NY Spills, NY Hist Spills
HILLARY STREET	NY Spills, NY Hist Spills
CON EDISON MANHOLE 62624	NY Spills
4TH STREET	NY Spills, NY Hist Spills
FRANKLIN STREET	NY Spills, NY Hist Spills
STREET	NY Spills
MANHATTAN BEACH	NY Spills
FARRAGUT S/S. CP 45 - ONE PINT	NY Spills
FARRAGUT SUBSTATION - XFMR # 3	NY Spills
KENT & N. 12TH STREET	NY Spills, NY Hist Spills
EXCAVATION - PIPELINE 7	NY Spills
IN THE STREET	NY Spills
BOX 38486	NY Spills, NY Hist Spills
TO ROADWAY	NY Spills
ROADWAY	NY Spills
KINGS HIGHWAY MOBIL	NY Spills
NYS DOT - BQE	NY Spills, NY Hist Spills
KNAPP STREET, CONEY ISLAN	NY Spills, NY Hist Spills
KNAPP STREET	NY Spills
STREET INTERSECTION	NY Spills
MANHOLE AT BOX STREET AND	NY Spills, NY Hist Spills
ON THE STREET 580 -574 MAPLE AVE	NY Spills
STREET	NY Spills
STREET SIDE	NY Spills
NEW YORK HARBOR	NY Spills, NY Hist Spills
291-A MONROE STREET	NY Spills, NY Hist Spills
MONTAGUE STREET	NY Spills, NY Hist Spills
IN THE STREET	NY Spills
175 FALMOUTH STREET / BRO	NY Spills, NY Hist Spills
NAVY YARD - DECK #4	NY Spills, NY Hist Spills
STREET BY NYNEX GARAGE	NY Spills, NY Hist Spills
MAN HOLE #1501	NY Spills, NY Hist Spills
DOUGLASS STREET AND	NY Spills
VAULT # V4438 - CON ED	NY Spills
STREET	NY Spills
EAST 94TH STREET AND	NY Spills
STREET	NY Spills
MANHOLE 60040	NY Spills, NY Hist Spills
TM# 2464	NY Spills, NY Hist Spills
STREET SPILL	NY Spills
MANHOLE 62992	NY Spills, NY Hist Spills
FLATBUSH AVENUE 300 FEET	NY Spills
OFF BELT PKWAY	NY Spills, NY Hist Spills
OFF SHORE-AMBROSE LIGHT	NY Spills, NY Hist Spills
OFF BELT PARKWAY AT KNAPP	NY Spills, NY Hist Spills
OFF SHORE PKWY & BAY 38TH	NY Spills, NY Hist Spills
OFF SHORE RD U/ VERRA BR	NY Spills, NY Hist Spills
BEHIND WHITMAN DR	NY Spills, NY Hist Spills
80TH STREET BRIDGE	NY Spills, NY Hist Spills

EXECUTIVE SUMMARY

69TH STREET & NARROWS / B	NY Spills, NY Hist Spills
STREET SPILL	NY Spills
PIER 2 -	NY Spills, NY Hist Spills
PLUM BEACH - BELT PKWY	NY Spills, NY Hist Spills
JAY STREET	NY Spills, NY Hist Spills
BUILDING 4 - VANYHS	NY Spills
TILLARY STREET AND	NY Spills, NY Hist Spills
SHORE PRKWY - 17TH AVE	NY Spills, NY Hist Spills
MARCEL - 5 AUTO SHOP	NY Spills, NY Hist Spills
RAMP TO I278	NY Spills, NY Hist Spills
SB PROSPECT EXPRESSWAY	NY Spills
1565 62 STREET	NY Spills, NY Hist Spills
E. RIVER - RED HOOK PIER	NY Spills, NY Hist Spills
NORTH 1ST STREET AND	NY Spills, NY Hist Spills
RUSSEL STREET	NY Spills, NY Hist Spills
APARTMENT - MISC	NY Spills
CANARSIE BEACH PARK	NY Spills, NY Hist Spills
UNDER BELT PARKWAY	NY Spills, NY Hist Spills
MANHOLE # 44766	NY Spills, NY Hist Spills
OWL'S HEAD WPCP DEP -DDC	NY Spills, NY Hist Spills
OWL'S HEAD WPCP DEP -DDC	NY Spills, NY Hist Spills
SHORE PKY/GERRITSEN INLET	NY Spills, NY Hist Spills
SHORE PKWY/BAYRIDGE BAY	NY Spills, NY Hist Spills
SHORE PKWY	NY Spills, NY Hist Spills
SHORE RD & 73RD ST	NY Spills, NY Hist Spills
VS 6130	NY Spills, NY Hist Spills
4322 WEST SHORE AVE	NY Spills, NY Hist Spills
SHORE PKWY & BAY 16 ST	NY Spills, NY Hist Spills
BAYSIDE FUEL TERMINAL	NY Spills, NY Hist Spills
NORTH OF ROCK AWAY PARKWAY INTERSE	NY Spills
MANHOLE #11191	NY Spills
STREET SPILL	NY Spills
PRESIDENT STREET AND	NY Spills, NY Hist Spills
NEW YORK HARBOR	NY Spills, NY Hist Spills
205	NY Spills
KENT AND KEEP STREET	NY Spills, NY Hist Spills
RODNEY STREET	NY Spills, NY Hist Spills
TM983 - LEXINGTON AV &	NY Spills, NY Hist Spills
XFMR EXPLOSION AND FIRE - TM #192	NY Spills
UNION STREET BRIDGE	NY Spills
20TH STREET	NY Spills, NY Hist Spills
NY HARBOR	NY Spills, NY Hist Spills
VERRAZANO - N BROOKLYN	NY Spills, NY Hist Spills
VAULT - #4359	NY Spills, NY Hist Spills
WOLCOH ST - AT END OFF	NY Spills, NY Hist Spills
218248; YORK STREET AND GREEN LANE	NY Spills
TM 2470	NY Spills, NY Hist Spills
206936; BAY PKWY; M67498 - 7B51	NY Spills
207656; EMPIRE BLVD; M3813 - F/O 3	NY Spills
206224; FRANKLIN AVE; SB26112 - F/	NY Spills
205842; KINGS HWY	NY Spills
206211; MONROE ST; SB30561 - OPP 1	NY Spills
205081; NEPTUNE AVE VS4897 - S/S N	NY Spills
208013; UNION ST; SB43384 - F/O 10	NY Spills
FOUNTAIN AVENUE LANDFILL	ODI

OVERVIEW MAP - 3164235.2s



0 1/4 1/2 1 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	65th Street Expansion - Cross Harbor	CLIENT:	STV Inc.
ADDRESS:	2nd Avenue / 65th Street Brooklyn NY 11220	CONTACT:	Doane E. Cafferty
LAT/LONG:	40.6426 / 74.0279	INQUIRY #:	3164235.2s
		DATE:	September 15, 2011 11:40 am

Copyright © 2011 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 3164235.2s



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	65th Street Expansion - Cross Harbor	CLIENT:	STV Inc.
ADDRESS:	2nd Avenue / 65th Street Brooklyn NY 11220	CONTACT:	Doane E. Cafferty
LAT/LONG:	40.6426 / 74.0279	INQUIRY #:	3164235.2s
		DATE:	September 15, 2011 11:41 am

Copyright © 2011 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL		0.189	0	0	NR	NR	NR	0
Proposed NPL		0.189	0	0	NR	NR	NR	0
NPL LIENS		0.189	0	0	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL		0.189	0	0	NR	NR	NR	0
Federal CERCLIS list								
CERCLIS		0.189	0	0	NR	NR	NR	0
FEDERAL FACILITY		0.189	0	0	NR	NR	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP		0.189	0	0	NR	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS		0.189	0	0	NR	NR	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF		0.189	0	0	NR	NR	NR	0
Federal RCRA generators list								
RCRA-LQG		0.189	1	1	NR	NR	NR	2
RCRA-SQG		0.189	1	0	NR	NR	NR	1
RCRA-CESQG		0.189	2	0	NR	NR	NR	2
Federal institutional controls / engineering controls registries								
US ENG CONTROLS		0.189	0	0	NR	NR	NR	0
US INST CONTROL		0.189	0	0	NR	NR	NR	0
Federal ERNS list								
ERNS		0.189	5	0	NR	NR	NR	5
State- and tribal - equivalent CERCLIS								
SHWS		0.189	0	0	NR	NR	NR	0
VAPOR REOPENED		0.189	0	0	NR	NR	NR	0
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF		0.189	0	0	NR	NR	NR	0
State and tribal leaking storage tank lists								
LTANKS		0.189	5	3	NR	NR	NR	8
HIST LTANKS		0.189	3	2	NR	NR	NR	5
INDIAN LUST		0.189	0	0	NR	NR	NR	0
State and tribal registered storage tank lists								
TANKS		0.189	1	0	NR	NR	NR	1

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UST		0.189	14	5	NR	NR	NR	19
CBS UST		0.189	0	0	NR	NR	NR	0
MOSF UST		0.189	0	0	NR	NR	NR	0
AST		0.189	5	5	NR	NR	NR	10
CBS AST		0.189	0	0	NR	NR	NR	0
MOSF AST		0.189	0	0	NR	NR	NR	0
MOSF		0.189	0	0	NR	NR	NR	0
CBS		0.189	0	0	NR	NR	NR	0
INDIAN UST		0.189	0	0	NR	NR	NR	0
FEMA UST		0.189	0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
ENG CONTROLS		0.189	0	0	NR	NR	NR	0
INST CONTROL		0.189	0	0	NR	NR	NR	0
RES DECL		0.189	0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
INDIAN VCP		0.189	0	0	NR	NR	NR	0
VCP		0.189	0	0	NR	NR	NR	0
State and tribal Brownfields sites								
ERP		0.189	0	0	NR	NR	NR	0
BROWNFIELDS		0.189	0	0	NR	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS		0.189	0	0	NR	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
ODI		0.189	0	0	NR	NR	NR	0
DEBRIS REGION 9		0.189	0	0	NR	NR	NR	0
SWTIRE		0.189	0	0	NR	NR	NR	0
SWRCY		0.189	0	0	NR	NR	NR	0
INDIAN ODI		0.189	0	0	NR	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL		0.189	0	0	NR	NR	NR	0
DEL SHWS		0.189	0	0	NR	NR	NR	0
US HIST CDL		0.189	0	0	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
HIST UST		0.189	13	5	NR	NR	NR	18
HIST AST		0.189	1	4	NR	NR	NR	5
Local Land Records								
LIENS 2		0.189	0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LUCIS		0.189	0	0	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS		0.189	0	0	NR	NR	NR	0
NY Spills		0.189	25	18	NR	NR	NR	43
NY Hist Spills		0.189	16	12	NR	NR	NR	28
Other Ascertainable Records								
RCRA-NonGen		0.189	15	3	NR	NR	NR	18
DOT OPS		0.189	0	0	NR	NR	NR	0
DOD		0.189	0	0	NR	NR	NR	0
FUDS		0.189	1	0	NR	NR	NR	1
CONSENT		0.189	0	0	NR	NR	NR	0
ROD		0.189	0	0	NR	NR	NR	0
UMTRA		0.189	0	0	NR	NR	NR	0
MINES		0.189	0	0	NR	NR	NR	0
TRIS		0.189	1	0	NR	NR	NR	1
TSCA		0.189	0	0	NR	NR	NR	0
FTTS		0.189	0	0	NR	NR	NR	0
HIST FTTS		0.189	0	0	NR	NR	NR	0
SSTS		0.189	0	0	NR	NR	NR	0
ICIS		0.189	0	0	NR	NR	NR	0
PADS		0.189	0	0	NR	NR	NR	0
MLTS		0.189	0	0	NR	NR	NR	0
RADINFO		0.189	0	0	NR	NR	NR	0
FINDS	X	0.189	37	6	NR	NR	NR	43
RAATS		0.189	0	0	NR	NR	NR	0
HSWDS		0.189	0	0	NR	NR	NR	0
UIC		0.189	0	0	NR	NR	NR	0
MANIFEST		0.189	17	7	NR	NR	NR	24
DRYCLEANERS		0.189	0	0	NR	NR	NR	0
NPDES		0.189	0	0	NR	NR	NR	0
AIRS		0.189	0	0	NR	NR	NR	0
E DESIGNATION		0.189	0	0	NR	NR	NR	0
INDIAN RESERV		0.189	0	0	NR	NR	NR	0
SCRD DRYCLEANERS		0.189	0	0	NR	NR	NR	0
PCB TRANSFORMER		0.189	0	0	NR	NR	NR	0
COAL ASH EPA		0.189	0	0	NR	NR	NR	0
COAL ASH		0.189	0	0	NR	NR	NR	0
FINANCIAL ASSURANCE		0.189	0	0	NR	NR	NR	0
COAL ASH DOE		0.189	0	0	NR	NR	NR	0
EDR PROPRIETARY RECORDS								
EDR Proprietary Records								
Manufactured Gas Plants		0.189	0	0	NR	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
Target Property
Actual: 14 ft.

NYC EDC 65TH ST RAIL YARD & FLOAT BRIDGE
65TH ST & 2ND AVE
BROOKLYN, NY 11220

FINDS **1007821062**
N/A

FINDS:

Registry ID: 110019836221

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

A2
East
< 1/8
0.007 mi.
37 ft.
Site 1 of 5 in cluster A

Relative: Higher

Actual: 29 ft.

RICHARD RIBELLINO & ALVA PARTNERS
5901 2ND AVENUE
BROOKLYN, NY 11209

HIST UST **U003740218**
N/A

HIST UST:

PBS Number:	2-604583
SPDES Number:	Not reported
Emergency Contact:	RICHARD RIBELLINO
Emergency Telephone:	(917) 335-7838
Operator:	RICHARD RIBELLINO & ALVA PARTS
Operator Telephone:	(718) 858-5555
Owner Name:	RICHARD BIBELLINO & ALVA PARTNERS
Owner Address:	386 3RD AVE.
Owner City,St,Zip:	BROOKLYN, NY 11215
Owner Telephone:	(718) 858-5555
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	ALVA PARTNERS
Mailing Address:	386 3RD AVE.
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11215
Mailing Contact:	RICHARD RIBELLINO &
Mailing Telephone:	(718) 858-5555
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	06/15/2005
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0

RICHARD RIBELLINO & ALVA PARTNERS (Continued) **U003740218**

Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False

RICHARD RIBELLINO & ALVA PARTNERS (Continued) **U003740218**

Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

RICHARD RIBELLINO & ALVA PARTNERS (Continued) **U003740218**

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed

RICHARD RIBELLINO & ALVA PARTNERS (Continued) **U003740218**

Install Date:	20000401
Capacity (gals):	550
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/2000
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

A3 **KEEP DRIVING CO. INC.** **AST** **A100294663**
ESE **5901 2ND AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.007 mi.
38 ft. **Site 2 of 5 in cluster A**

Relative:
Higher

Actual:
29 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604583
Program Type:	PBS
UTM X:	582678.41417999996
UTM Y:	4499685.1900599999
Expiration Date:	2010/05/09

Affiliation Records:

Site Id:	26454
Affiliation Type:	Emergency Contact
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

KEEP DRIVING CO. INC. (Continued) **A100294663**

Site Id:	26454
Affiliation Type:	Owner
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	PRES, SEC TREAS
Contact Name:	ZI KAI WANG
Address1:	5901 2ND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Site Id:	26454
Affiliation Type:	On-Site Operator
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Site Id:	26454
Affiliation Type:	Mail Contact
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	5901 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None

KEEP DRIVING CO. INC. (Continued) **A100294663**

I00 - Overfill - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
J00 - Dispenser - None
J00 - Dispenser - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J00 - Dispenser - None
B01 - Tank External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G05 - Tank Secondary Containment - Synthetic Liner
I00 - Overfill - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
I00 - Overfill - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground

KEEP DRIVING CO. INC. (Continued) **A100294663**

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Info:

Tank Number:	01
Tank Id:	206291
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	5/9/2005

A4 **KEEP DRIVING CO. INC.** **UST** **U004078383**
ESE **5901 2ND AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.007 mi.
38 ft. **Site 3 of 5 in cluster A**

Relative:
Higher

Actual:
29 ft.

UST:

Facility Id:	2-604583
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2010/05/09
UTM X:	582678.41417999996
UTM Y:	4499685.1900599999

Affiliation Records:

Site Id:	26454
Affiliation Type:	Emergency Contact
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

KEEP DRIVING CO. INC. (Continued) **U004078383**

Site Id:	26454
Affiliation Type:	Owner
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	PRES, SEC TREAS
Contact Name:	ZI KAI WANG
Address1:	5901 2ND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Site Id:	26454
Affiliation Type:	On-Site Operator
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Site Id:	26454
Affiliation Type:	Mail Contact
Company Name:	KEEP DRIVING CO. INC.
Contact Type:	Not reported
Contact Name:	ZI KAI WANG
Address1:	5901 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 765-0556
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/9/2005

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None

KEEP DRIVING CO. INC. (Continued) **U004078383**

I00 - Overfill - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
J00 - Dispenser - None
J00 - Dispenser - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J00 - Dispenser - None
B01 - Tank External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G05 - Tank Secondary Containment - Synthetic Liner
I00 - Overfill - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
I00 - Overfill - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground

KEEP DRIVING CO. INC. (Continued) **U004078383**

G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Info:

Site ID:	26454
Tank Number:	001
Tank ID:	58243
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	5/9/2005
Site ID:	26454
Tank Number:	002
Tank ID:	58244
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26454
Tank Number:	003
Tank ID:	58245
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5

KEEP DRIVING CO. INC. (Continued) **U004078383**

Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26454
Tank Number:	004
Tank ID:	58246
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26454
Tank Number:	005
Tank ID:	58247
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26454
Tank Number:	006
Tank ID:	58248
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5

KEEP DRIVING CO. INC. (Continued) **U004078383**

Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26454
Tank Number:	007
Tank ID:	58249
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	4/1/2000
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/2000
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

B5 **245 GALLONS FROM TM 2341** **NY Spills** **S108130008**
SE **2 AVENUE & 64 STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.007 mi.
39 ft. **Site 1 of 8 in cluster B**

Relative:
Higher

Actual:
33 ft.

NY Spills:

Site ID:	368821
Facility Addr2:	Not reported
Facility ID:	0605621
Spill Number:	0605621
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	8/14/2006
Reported to Dept:	8/14/2006
CID:	409
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/21/2006
Remediation Phase:	0
Date Entered In Computer:	8/14/2006
Spill Record Last Update:	12/21/2006

245 GALLONS FROM TM 2341 (Continued) **S108130008**

Spiller Name:	ERT DESK MIKE DAUGHTERY
Spiller Company:	CON EDISON TM 2341
Spiller Address:	2ND AVE/64TH ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT DESK MIKE DAUGHTERY
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	318717
DEC Memo:	12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. 201915. see eDocs DEC: Below please find the eMIS report for the incident referenced in the subject line of this email. This is an update to an incident that was initially reported as a 5 gallon spill on 8/14/06. Today, (8/16/06), at 18:30 a 245 gallon discrepancy between the unit and its label was discovered. Because of the discrepancy and the fact that there was an earthen sump in the structure, (it had been cemented over after the structure was cleaned but before the discrepancy was discovered), this update is being issued. <<report.sp0605621.2006-08-15.emis_201915.pdf>> Michael D'Agostino, Environmental Response Team, Con Edison
Remarks:	PENDING DEENERGIZATION OF THE FEEDER. ALSO ONE PINT ON SIDEWALK. ONTOP OF 200 GAL OF WATER. CON ED# 201915

Material:

Site ID:	368821
Operable Unit ID:	1126679
Operable Unit:	01
Material ID:	2116231
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

B6 **CON EDISON MANHOLE 56095** **RCRA-NonGen** **1010327066**
SE **2 AVE & 64 ST** **MANIFEST** **NYP004144457**
< 1/8 **BROOKLYN, NY 11201**
0.007 mi.
39 ft. **Site 2 of 8 in cluster B**

Relative:
Higher

Actual:
33 ft.

RCRA-NonGen:

Date form received by agency:	01/11/2007
Facility name:	CON EDISON MANHOLE 56095
Facility address:	2 AVE & 64 ST BROOKLYN, NY 11201
EPA ID:	NYP004144457
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	STEVEN MARTIS
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2007
Facility name:	CON EDISON MANHOLE 56095
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	01/09/2007
Facility name:	CON EDISON MANHOLE 56095
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004144457
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY

CON EDISON MANHOLE 56095 (Continued) **1010327066**

Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYE1587798
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2006
Trans1 Recv Date:	08/15/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/16/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004144457
Trans1 EPA ID:	18887JU
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00450
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2006

B7 **PM 2341** **NY Spills S103485175**
SE **2ND ST AND 64TH ST** **NY Hist Spills N/A**
< 1/8 **BROOKLYN, NY**
0.007 mi.
39 ft. **Site 3 of 8 in cluster B**

Relative:
Higher

Actual:
33 ft.

NY Spills:

Site ID:	232169
Facility Addr2:	Not reported
Facility ID:	9808531
Spill Number:	9808531
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	10/9/1998
Reported to Dept:	10/9/1998
CID:	270
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

PM 2341 (Continued) **S103485175**

Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/25/2002
Remediation Phase:	0
Date Entered In Computer:	10/9/1998
Spill Record Last Update:	10/25/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MR PHORTIN
Contact Phone:	(718) 246-6610
DEC Region:	2
DER Facility ID:	191334
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Con Ed e2mis #120422: 10.42 10/9/98 J.CAMPANILI #51238 O.S. NETWORKS REPORTED FINDING 1/2 GAL.UNKNOWN OIL ON TOP OF 100 GAL.WATER. IN TM2341 E/S 2 AVE. & 64 ST. TM WAS PRESSURED TESTED FOUND OK. NOT LEAKING. NO RECORDS SHOWING IF CONNECTED TO SEWER.NO SEWERS OR WATERWAYS AFFECTED. E.S.TAG INSTALLED #08579. RECORDS SHOW OIL IN TM. TO BE 27 PPM PCB A SAMPLE WAS TAKEN 4-6 HRS PRIORITY. DISCOVERED WHILE DOING ROUTINE INSP. NO PARKING 12-3 AM MON. & THUR. TO BE TREATED AS 50-499. Update 10/10/98 OIL SAMPLE LAB. SEQ. 98-10866 REPORTS OIL LESS THEN 1 PPM Update 10-13-98 g.kern of flush dept. reports cleanup complete with slix 1745hrs. 10/13/98. e.s.tag#08579 removed.
Remarks:	TRANSFORMER TESTED OK 120422

Material:

Site ID:	232169
Operable Unit ID:	1065938
Operable Unit:	01
Material ID:	316032
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

PM 2341 (Continued) **S103485175**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9808531
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/09/1998 10:42
Reported to Dept Date/Time:	10/09/98 11:36
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Contact:	MR PHORTIN
Spiller Phone:	(718) 246-6610
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	10/09/98
Date Spill Entered In Computer Data File:	Not reported
Update Date:	03/28/00
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	2
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0

PM 2341 (Continued) **S103485175**

Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: TRANSFORMER TESTED OK 120422

B8 **CON EDISON** **FINDS** **1010443270**
SE **2 AVE & 64 ST** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.007 mi.
39 ft. **Site 4 of 8 in cluster B**

Relative:
Higher

FINDS:

Registry ID: 110031405290

Actual:
33 ft.

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

B9 **6423 SECOND AVE** **NY Spills** **S102238382**
SE **6423 SECOND AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.008 mi.
44 ft. **Site 5 of 8 in cluster B**

Relative:
Higher

NY Spills:
Site ID: 320343
Facility Addr2: Not reported

Actual:
35 ft.

Facility ID: 9511200
Spill Number: 9511200
Facility Type: ER
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Spill Date: 12/6/1995
Reported to Dept: 12/6/1995
CID: 211
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

6423 SECOND AVE (Continued) **S102238382**

Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/6/1995
Remediation Phase: 0
Date Entered In Computer: 12/6/1995
Spill Record Last Update: 1/3/1996
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 258096
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG" CALLED DEP - ASKED TO CALL BACK IF NEED HELP - NO DEC ACTION NEEDED @2:30pm.
Remarks: 6 TO 8 ABANDONED DRUMS ON SIDE WALK WHICH CONTAIN SOME TYPE OF OIL PRODUCT AND OTHER CHEMICALS

Material:
Site ID: 320343
Operable Unit ID: 1021747
Operable Unit: 01
Material ID: 358550
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 320343
Operable Unit ID: 1021747
Operable Unit: 01
Material ID: 358551
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported

6423 SECOND AVE (Continued) **S102238382**

Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9511200
Investigator: TANG
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 12/06/1995 10:40
Reported to Dept Date/Time: 12/06/95 10:52
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Abandoned Drums
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Local Agency
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/06/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/06/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/03/96
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True

6423 SECOND AVE (Continued) **S102238382**

Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	True
Material:	UNKNOWN MATERIAL
Class Type:	UNKNOWN MATERIAL
Times Material Entry In File:	9140
CAS Number:	Not reported
Last Date:	19941109
Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	True
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	True
Material:	UNKNOWN PETROLEUM
Class Type:	UNKNOWN PETROLEUM
Times Material Entry In File:	16414
CAS Number:	Not reported
Last Date:	19940929
DEC Remarks:	CALLED DEP - ASKED TO CALL BACK IF NEED HELP - NO DEC ACTION NEEDED @2:30pm.
Remark:	6 TO 8 ABANDONED DRUMS ON SIDE WALK WHICH CONTAIN SOME TYPE OF OIL PRODUCT AND OTHER CHEMICALS

B10 **VAHL INC.** **NY Spills** **S108466352**
SE **6401 SECOND AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.009 mi.
45 ft. **Site 6 of 8 in cluster B**

Relative:
Higher

Actual:
34 ft.

NY Spills:

Site ID:	377869
Facility Addr2:	6401 2ND AVE
Facility ID:	0612916
Spill Number:	0612916
Facility Type:	ER
SWIS:	2401
Investigator:	sfrahman
Referred To:	Not reported
Spill Date:	1/22/2007
Reported to Dept:	3/1/2007
CID:	406
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/27/2007
Remediation Phase:	0
Date Entered In Computer:	3/1/2007
Spill Record Last Update:	6/27/2007
Spiller Name:	JACQUES GARNIER
Spiller Company:	VAHL INC.

VAHL INC. (Continued) **S108466352**

Spiller Address:	250 64TH ST.
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	JACQUES GARNIER
Contact Phone:	(718) 492-6655
DEC Region:	2
DER Facility ID:	12077
DEC Memo:	Sharif spoke with Jacques Garnier, a site assesment report will be sent to DEC.Letter was sent to VAHL Inc. 6401 2nd Avenue Brooklyn, NY 11220 Attn: Henry Dieken 06/27/07 Closure report prepared by DELTA.A 4,000 gallon steel gasoline UST was removed with good condition.No visible holes on the tank.No MTBE in end point samples.VOC/SVOCs are within TAGM limit.Two additional soil borings at depth of 20' and 40' respectively were installed at the former UST area.No GW was encountered.No exceedances of VOC/SVOCs.Report in edocs.Spill closed.(SR)
Remarks:	Lab results showed elevated levels of xylene which were found in soil samples. A 1000 gal tank containing gasoline had been removed from the site and the caller believes the contamination is from that tank. Unknown if groundwater was affected. Soil will be resampled to check if groundwater was affected.

Material:

Site ID:	377869
Operable Unit ID:	1135386
Operable Unit:	01
Material ID:	2125291
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	377869
Operable Unit ID:	1135386
Operable Unit:	01
Material ID:	2125728
Material Code:	0042A
Material Name:	XYLENE (MIXED)
Case No.:	01330207
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported

VAHL INC. (Continued) **S108466352**

Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

B11 **VAHL, INC.** **UST** **U000400869**
SE **6401 SECOND AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.009 mi.
45 ft. **Site 7 of 8 in cluster B**

Relative:
Higher

Actual:
34 ft.

UST:
Facility Id: 2-278653
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 582428.79345999996
UTM Y: 4499365.4940900002

Affiliation Records:
Site Id: 12093
Affiliation Type: Owner
Company Name: VAHL, INC.
Contact Type: OWNER
Contact Name: HENRY DIEKEN
Address1: 6401 SECOND AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11220
Country Code: 001
Phone: (718) 492-6655
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/29/2007

Site Id: 12093
Affiliation Type: On-Site Operator
Company Name: VAHL, INC.
Contact Type: Not reported
Contact Name: HENRY G DIEKEN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 492-6655
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

VAHL, INC. (Continued) **U000400869**

Site Id:	12093
Affiliation Type:	Mail Contact
Company Name:	VAHL, INC.
Contact Type:	Not reported
Contact Name:	HENRY G. DIEKEN
Address1:	6401 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(917) 873-5100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/29/2007

Site Id:	12093
Affiliation Type:	Emergency Contact
Company Name:	VAHL, INC.
Contact Type:	Not reported
Contact Name:	HENRY G DIEKEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-6655
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H99 - Tank Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
K01 - Spill Prevention - Catch Basin

Tank Info:

Site ID:	12093

Tank Number:	001
Tank ID:	14425
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	6/1/1980
Capacity Gallons:	4000

VAHL, INC. (Continued) **U000400869**

Tightness Test Method:	14
Next Test Date:	Not reported
Date Tank Closed:	1/23/2007
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	8/13/2004
Register:	True
Modified By:	NRLOMBAR
Last Modified:	1/29/2007

HIST UST:

PBS Number:	2-278653
SPDES Number:	Not reported
Emergency Contact:	HENRY G DIEKEN
Emergency Telephone:	(718) 492-6655
Operator:	HENRY G DIEKEN
Operator Telephone:	(718) 492-6655
Owner Name:	VAHL INC
Owner Address:	6401 2ND AVE
Owner City,St,Zip:	BKLYN, NY 11220
Owner Telephone:	(718) 492-6655
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	VAHL INC
Mailing Address:	6401 2ND AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BKLYN, NY 11220
Mailing Contact:	HENRY G. DIEKEN
Mailing Telephone:	(718) 492-6655
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	6401 2ND AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/12/2000
Expiration Date:	09/19/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	4000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

VAHL, INC. (Continued) **U000400869**

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19800601
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Sacrificial Anode
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Sacrificial Anode
Second Containment:	None
Leak Detection:	In-tank System
Overfill Prot:	Catch Basin
Dispenser:	Suction
Date Tested:	10/01/1999
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	USTest 2000
Deleted:	False
Updated:	True
Lat/long:	Not reported

C12 **YONG C KIM DRY CLEANERS** **RCRA-NonGen** **1000231677**
SE **22-27 65TH ST** **MANIFEST** **NYD982278558**
< 1/8 **BROOKLYN, NY 11204**
0.013 mi.
71 ft. **Site 1 of 2 in cluster C**

Relative:
Higher

Actual:
40 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	YONG C KIM DRY CLEANERS
Facility address:	22-27 65TH ST BROOKLYN, NY 112044001
EPA ID:	NYD982278558
Mailing address:	65TH ST BROOKLYN, NY 11204
Contact:	Not reported
Contact address:	65TH ST BROOKLYN, NY 11204
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	YONG C KIM
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: YONG C KIM
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: YONG C KIM DRY CLEANERS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: YONG C KIM DRY CLEANERS
Classification: Not a generator, verified

Date form received by agency: 11/10/1987
Facility name: YONG C KIM DRY CLEANERS
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD982278558
Country: USA
Mailing Name: YONG C KIM DRY CLNRS
Mailing Contact: YONG C KIM DRY CLNRS
Mailing Address: 22 27 65TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11204
Mailing Zip4: Not reported

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Mailing Country: USA
Mailing Phone: 718-259-9400

Document ID: NYA9728482
Manifest Status: Completed copy
Trans1 State ID: AM6252NY
Trans2 State ID: Not reported
Generator Ship Date: 891031
Trans1 Recv Date: 891031
Trans2 Recv Date: Not reported
TSD Site Recv Date: 891031
Part A Recv Date: 891103
Part B Recv Date: 891117
Generator EPA ID: NYD982278558
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00070
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYA9607329
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890731
Trans1 Recv Date: 890731
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890731
Part A Recv Date: 890808
Part B Recv Date: 890808
Generator EPA ID: NYD982278558
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00070
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYA9806602
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 891130

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Trans1 Recv Date:	891130
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891130
Part A Recv Date:	891205
Part B Recv Date:	891206
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	89

Document ID:	NYA9717805
Manifest Status:	Completed copy
Trans1 State ID:	AM6252NY
Trans2 State ID:	Not reported
Generator Ship Date:	891031
Trans1 Recv Date:	891031
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891031
Part A Recv Date:	891103
Part B Recv Date:	891117
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NYC0172078
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900315
Trans1 Recv Date:	900315
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900315
Part A Recv Date:	900410
Part B Recv Date:	900328
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYC0056654
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900119
Trans1 Recv Date:	900119
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900119
Part A Recv Date:	900129
Part B Recv Date:	900125
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0103691
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900215
Trans1 Recv Date:	900215
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900215
Part A Recv Date:	900308
Part B Recv Date:	900223
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Document ID:	NYC0209283
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900410
Trans1 Recv Date:	900410
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900410
Part A Recv Date:	900508
Part B Recv Date:	900418
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0313053
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900606
Trans1 Recv Date:	900606
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900606
Part A Recv Date:	900724
Part B Recv Date:	900618
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0396977
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900727
Trans1 Recv Date:	900727
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900727
Part A Recv Date:	900823

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Part B Recv Date: 900815
Generator EPA ID: NYD982278558
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00070
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90

Document ID: NYC0259266
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900509
Trans1 Recv Date: 900509
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900509
Part A Recv Date: 900627
Part B Recv Date: 900518
Generator EPA ID: NYD982278558
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00070
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90

Document ID: NYC0351009
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900703
Trans1 Recv Date: 900703
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900703
Part A Recv Date: 900807
Part B Recv Date: 900717
Generator EPA ID: NYD982278558
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00070
Units: P - Pounds
Number of Containers: 001

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0441674
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900831
Trans1 Recv Date:	900831
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900831
Part A Recv Date:	900906
Part B Recv Date:	900907
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0506935
Manifest Status:	Completed copy
Trans1 State ID:	AM6252NY
Trans2 State ID:	Not reported
Generator Ship Date:	901023
Trans1 Recv Date:	901023
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901023
Part A Recv Date:	901105
Part B Recv Date:	901105
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0653174
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	LP3931NY

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Trans2 State ID:	Not reported
Generator Ship Date:	901217
Trans1 Recv Date:	901217
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901217
Part A Recv Date:	910103
Part B Recv Date:	910116
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

Document ID:	NYC0840115
Manifest Status:	Completed copy
Trans1 State ID:	AP4503NY
Trans2 State ID:	Not reported
Generator Ship Date:	910315
Trans1 Recv Date:	910315
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910315
Part A Recv Date:	910327
Part B Recv Date:	910326
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NYC0892394
Manifest Status:	Completed copy
Trans1 State ID:	AP4503NY
Trans2 State ID:	Not reported
Generator Ship Date:	910405
Trans1 Recv Date:	910405
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910405
Part A Recv Date:	910418
Part B Recv Date:	910416
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NYC0950139
Manifest Status:	Completed copy
Trans1 State ID:	AM6252NY
Trans2 State ID:	Not reported
Generator Ship Date:	910507
Trans1 Recv Date:	910507
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910507
Part A Recv Date:	910520
Part B Recv Date:	910515
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Document ID:	NYC1005996
Manifest Status:	Completed copy
Trans1 State ID:	AP4503NY
Trans2 State ID:	Not reported
Generator Ship Date:	910605
Trans1 Recv Date:	910605
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910605
Part A Recv Date:	910614
Part B Recv Date:	910614
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

YONG C KIM DRY CLEANERS (Continued) **1000231677**

Year:	91
Document ID:	NYC1286278
Manifest Status:	Completed copy
Trans1 State ID:	AM6252NY
Trans2 State ID:	Not reported
Generator Ship Date:	911024
Trans1 Recv Date:	911024
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	911024
Part A Recv Date:	Not reported
Part B Recv Date:	911105
Generator EPA ID:	NYD982278558
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91

Click this hyperlink while viewing on your computer to access
25 additional NY_MANIFEST: record(s) in the EDR Site Report.

---

13 **MILITARY OCEAN TER** **FUDS** **1007211620**
NW **N/A**
< 1/8 **BROOKLYN, NY**
0.023 mi.
121 ft.

Relative:
Higher

Actual:
23 ft.

FUDS:

Federal Facility ID:	NY9799F1176
FUDS #:	C02NY0642
INST ID:	56645
Facility Name:	MILITARY OCEAN TER
City:	BROOKLYN
State:	NY
EPA Region:	2
County:	KINGS
Congressional District:	08
US Army District:	New England District (NAE)
Fiscal Year:	2009
Telephone:	978-318-8238
NPL Status:	Not Listed
RAB:	Not reported
CTC:	2104.92357649117
Current Owner:	CITY; PRIVATE

FUDS Description Details:

The Brooklyn Military Ocean Terminal occupied about 100 acres in Brooklyn, New York. It was used by the Army as a shipping terminal. Abandoned tanks and hazardous buildings are present. Most of the site is in beneficial use as office space or for oth

MILITARY OCEAN TER (Continued) **1007211620**

her commercial and industrial purposes.

FUDS History Details:

The DoD acquired the site through purchases and condemnation proceedings between April 1918 and May 1926. An additional 0.10 acre was obtained from Long Island Rail Road in January 1943. On 26 April 1968, the Bay Ridge Air Rights Corporation acquired d 2.95 acres by quitclaim deed. The City of New York acquired 96.73 acres of the site by quitclaim deed dated July 1981. Projects recommended on this site included: the removal of seven underground storage tanks (USTs), 100 drums (mostly of 55-gallon n capacity), and one transformer (CON/HTRW); demolition of severely weathered buildings that have become structurally unsound, causing potential falling, tripping, and similar hazards (BD/DR); further investigative activity to establish more precisel ly the extent of soil contamination from crushed drums, and potential remedial steps necessary (HTW).

FUDS Current Program Details:

FUDS Future Program Details:

14
SE
< 1/8
0.023 mi.
124 ft.

Relative:
Higher

Actual:
39 ft.

211 SERVICE LTD. LIAB. CO. **UST** **U003200572**
211 63RD STREET **HIST UST** **N/A**
BROOKLYN, NY 11220

UST:

Facility Id:	2-603115
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582505.45493000001
UTM Y:	4499424.9833800001

Affiliation Records:

Site Id:	25067
Affiliation Type:	On-Site Operator
Company Name:	211 SERVICE LTD. LIAB. CO.
Contact Type:	Not reported
Contact Name:	PETER LAMBARDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 921-6868
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

211 SERVICE LTD. LIAB. CO. (Continued) **U003200572**

Site Id:	25067
Affiliation Type:	Mail Contact
Company Name:	211 SERVICE LTD. LIAB. CO.
Contact Type:	Not reported
Contact Name:	HEINZ POPP
Address1:	855 65TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 921-9100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25067
Affiliation Type:	Emergency Contact
Company Name:	211 SERVICE LTD. LIAB. CO.
Contact Type:	Not reported
Contact Name:	HEINZ POPP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 921-9100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25067
Affiliation Type:	Owner
Company Name:	211 SERVICE LTD. LIAB. CO.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	211 63RD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 921-9100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction

211 SERVICE LTD. LIAB. CO. (Continued) **U003200572**

B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None

Tank Info:

Site ID:	25067
Tank Number:	001
Tank ID:	53099
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	10000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-603115
SPDES Number:	Not reported
Emergency Contact:	HEINZ POPP
Emergency Telephone:	(718) 921-9100
Operator:	PETER LAMBARDO
Operator Telephone:	(718) 921-6868
Owner Name:	211 SERVICE LTD. LIAB. CO.
Owner Address:	211 63RD STREET
Owner City,St,Zip:	BROOKLYN, NY 11220
Owner Telephone:	(718) 921-9100
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	211 SERVICE LTD. LIAB. CO.
Mailing Address:	855 65TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	HEINZ POPP
Mailing Telephone:	(718) 921-9100
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported

211 SERVICE LTD. LIAB. CO. (Continued) **U003200572**

Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	08/29/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	10000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	08/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

C15 **PERGAMENT STORES** **NY Spills** **S102180125**
SE **57 65TH AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.025 mi.
130 ft. **Site 2 of 2 in cluster C**

Relative:
Higher

Actual:
40 ft.

NY Spills:

Site ID:	326448
Facility Addr2:	Not reported
Facility ID:	9508762
Spill Number:	9508762
Facility Type:	ER
SWIS:	2401
Investigator:	TOMASELLO

PERGAMENT STORES (Continued) **S102180125**

Referred To:	Not reported
Spill Date:	10/17/1995
Reported to Dept:	10/17/1995
CID:	275
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/11/2003
Remediation Phase:	0
Date Entered In Computer:	10/17/1995
Spill Record Last Update:	2/11/2003
Spiller Name:	Not reported
Spiller Company:	RYDER DEDICATED LOGISTICS
Spiller Address:	PO BOX 610
Spiller City,St,Zip:	MARIAN, VI 24354-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	262985
DEC Memo:	Not reported
Remarks:	LEAK IN FUEL LINE - FD ON SCENE DOING CONTAINEMNT AND CLEAN-UP

Material:

Site ID:	326448
Operable Unit ID:	1023130
Operable Unit:	01
Material ID:	359722
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

PERGAMENT STORES (Continued) **S102180125**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9508762
Investigator:	TOMASELLO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/17/1995 13:15
Reported to Dept Date/Time:	10/17/95 16:06
SWIS:	61
Spiller Name:	RYDER DEDICATED LOGISTICS
Spiller Contact:	Not reported
Spiller Phone:	(540) 783-3219
Spiller Address:	PO BOX 610
Spiller City,St,Zip:	MARIAN, VI 24354-
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	07
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	10/17/95
Date Spill Entered In Computer Data File:	Not reported
Update Date:	11/08/95
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	15
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	True
Material:	DIESEL

PERGAMENT STORES (Continued) **S102180125**

Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: LEAK IN FUEL LINE - FD ON SCENE DOING CONTAINEMNT AND CLEAN-UP

16
SE
< 1/8
0.031 mi.
163 ft.

SERVICE BOX #49934
45-61ST STREET
BROOKLYN, NY

NY Spills **S103938519**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
38 ft.

NY Spills:
Site ID: 205872
Facility Addr2: Not reported
Facility ID: 9903107
Spill Number: 9903107
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 6/17/1999
Reported to Dept: 6/17/1999
CID: 252
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/18/2000
Remediation Phase: 0
Date Entered In Computer: 6/17/1999
Spill Record Last Update: 6/7/2000
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN
Spiller Address: UNKNOWN
Spiller City,St,Zip: UNKNOWN, NY
Spiller Company: 999
Contact Name: RICHARD ROACHE
Contact Phone: (212) 580-6764
DEC Region: 2
DER Facility ID: 170949
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Con ed e2mis notes: Approx 1 quart of unknown oil on 75 gallons of water, <1.00 ppm, cleanup complete and tag removed. Incident is closed.
Remarks: SPILL IS IN SERVICE BOX ON 10 GALLONS OF WATER-SAMPLE TAKEN-CLEANUP PENDING RESULTS-HAS NOT AFFECTED ANY SEWERS OR WATERWAYS. CON ED #125611

Material:

SERVICE BOX #49934 (Continued) **S103938519**

Site ID:	205872
Operable Unit ID:	1077702
Operable Unit:	01
Material ID:	303032
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9903107
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	06/17/1999 13:00
Reported to Dept Date/Time:	06/17/99 13:25
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Contact:	RICHARD ROACHE
Spiller Phone:	(212) 580-6764
Spiller Address:	UNK
Spiller City,St,Zip:	UNK
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /

SERVICE BOX #49934 (Continued) **S103938519**

Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/18/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/17/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/07/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con ed e2mis notes: Approx 1 quart of unknown oil on 75 gallons of water, <1.00 ppm, cleanup complete and tag removed. Incident is closed.
Remark: SPILL IS IN SERVICE BOX ON 10 GALLONS OF WATER-SAMPLE TAKEN-CLEANUP PENDING RESULTS-HAS NOT AFFECTED ANY SEWERS OR WATERWAYS. CON ED 125611

B17 **DRUM RUN** **NY Spills** **S108295373**
SE **63RD - 64TH STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.033 mi.
173 ft. **Site 8 of 8 in cluster B**

Relative:
Higher

Actual:
38 ft.

NY Spills:
Site ID: 372478
Facility Addr2: ON OVERPASS ON 7TH AVE
Facility ID: 0608496
Spill Number: 0608496
Facility Type: ER
SWIS: 2401
Investigator: SFRAHMAN
Referred To: Not reported
Spill Date: 10/24/2006
Reported to Dept: 10/24/2006
CID: 408
Spill Cause: Abandoned Drums

DRUM RUN (Continued) **S108295373**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/1/2006
Remediation Phase:	0
Date Entered In Computer:	10/24/2006
Spill Record Last Update:	12/1/2006
Spiller Name:	Not reported
Spiller Company:	DEC MARKED AND DATED
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	NYF DEPATMENT
Contact Phone:	(718) 965-8340
DEC Region:	2
DER Facility ID:	322209
DEC Memo:	12/01/06 Rahman- One drum and a 5 gallon container were found, were pumped out and NYC sanitation was notified to pick up the empty drums. Not reported
Remarks:	DATED MARKED 9/9/06 MARKED AS WASTE PETROLEUM;

Material:

Site ID:	372478
Operable Unit ID:	1130216
Operable Unit:	01
Material ID:	2119887
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

D18 **58 & 1H2 AVE** **NY Spills** **S102144082**
NE **58 & 1H2 AVE** **NY Hist Spills** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.043 mi.
229 ft. **Site 1 of 8 in cluster D**

Relative:
Higher

Actual:
22 ft.

NY Spills:

Site ID:	207880
Facility Addr2:	Not reported
Facility ID:	8603398
Spill Number:	8603398
Facility Type:	ER
SWIS:	3101
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	8/21/1986
Reported to Dept:	8/21/1986
CID:	Not reported
Spill Cause:	Deliberate
Water Affected:	NONE
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	8/21/1987
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	8/21/1987
Remediation Phase:	0
Date Entered In Computer:	9/10/1986
Spill Record Last Update:	8/31/1987
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, ZZ
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	172504
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " 10/10/95: This is additional information about material spilled from the translation of the old spill file: ORANGE LUBE OIL.
Remarks:	Not reported

Material:

Site ID:	207880
Operable Unit ID:	900295
Operable Unit:	01
Material ID:	476228
Material Code:	0016A
Material Name:	NON PCB OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

58 & 1H2 AVE (Continued) **S102144082**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	8603398
Investigator:	Not reported
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	08/21/1986
Reported to Dept Date/Time:	08/21/86 18:14
SWIS:	62
Spiller Name:	UNK
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Deliberate
Reported to Dept:	On Land
Water Affected:	NONE
Spill Source:	12
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	08/21/87
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	08/21/87
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	09/10/86
Date Spill Entered In Computer Data File:	Not reported
Update Date:	08/31/87
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported

58 & 1H2 AVE (Continued) **S102144082**

Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: NON PCB OIL
Class Type: NON PCB OIL
Times Material Entry In File: 2798
CAS Number: Not reported
Last Date: 19940928
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: ORANGE LUBE OIL.
Remark: Not reported

D19 **NEW YORK RAIL CAR CORP** **RCRA-NonGen** **1000457501**
NE **4 58 ST** **FINDS** **NYD986927549**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.049 mi.
258 ft. **Site 2 of 8 in cluster D**

Relative:
Higher

Actual:
22 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NEW YORK RAIL CAR CORP
Facility address: 58TH ST FIRST AVE
BROOKLYN, NY 11220
EPA ID: NYD986927549
Mailing address: PO BOX 336
BROOKLYN, NY 11220
Contact: Not reported
Contact address: PO BOX 336
BROOKLYN, NY 11220
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LAWRENCE LEVY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LAWRENCE LEVY

NEW YORK RAIL CAR CORP (Continued) **1000457501**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NEW YORK RAIL CAR CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NEW YORK RAIL CAR CORP
Classification: Not a generator, verified

Date form received by agency: 05/06/1992
Facility name: NEW YORK RAIL CAR CORP
Site name: NEW YORK RAILCAR CO.
Classification: Large Quantity Generator

Date form received by agency: 10/15/1990
Facility name: NEW YORK RAIL CAR CORP
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/16/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110012590133

NEW YORK RAIL CAR CORP (Continued) **1000457501**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD986927549
Country:	USA
Mailing Name:	NEW YORK RAIL CAR CORPORATION
Mailing Contact:	MIKE CASTIGLIONE
Mailing Address:	112-20 FOURTEETH AVENUE
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11356
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-762-0001

Document ID:	NJA0939000
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S8158
Trans2 State ID:	Not reported
Generator Ship Date:	901025
Trans1 Recv Date:	901025
Trans2 Recv Date:	901025
TSD Site Recv Date:	901025
Part A Recv Date:	910211
Part B Recv Date:	901108
Generator EPA ID:	NYD986927549
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002385730
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	05300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	90

Document ID:	NJA1117905
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS815
Trans2 State ID:	Not reported
Generator Ship Date:	910507
Trans1 Recv Date:	910507
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910507
Part A Recv Date:	910712

NEW YORK RAIL CAR CORP (Continued) **1000457501**

Part B Recv Date: 910522
Generator EPA ID: NYD986927549
Trans1 EPA ID: NJD156163438
Trans2 EPA ID: Not reported
TSDF ID: NJD002385730
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 05350
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 91

Document ID: NJA1179403
Manifest Status: Completed copy
Trans1 State ID: NJDEPS815
Trans2 State ID: Not reported
Generator Ship Date: 910927
Trans1 Recv Date: 910927
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910927
Part A Recv Date: Not reported
Part B Recv Date: 911009
Generator EPA ID: NYD986927549
Trans1 EPA ID: NJD156163438
Trans2 EPA ID: Not reported
TSDF ID: NJD002385730
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 05300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1504578
Manifest Status: Completed copy
Trans1 State ID: NJDEPS815
Trans2 State ID: Not reported
Generator Ship Date: 920724
Trans1 Recv Date: 920724
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920724
Part A Recv Date: Not reported
Part B Recv Date: 920805
Generator EPA ID: NYD986927549
Trans1 EPA ID: NJD156163438
Trans2 EPA ID: Not reported
TSDF ID: NJD002385730
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 45840
Units: P - Pounds
Number of Containers: 001

NEW YORK RAIL CAR CORP (Continued) **1000457501**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	92

Document ID:	NJA1504582
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS815
Trans2 State ID:	Not reported
Generator Ship Date:	920727
Trans1 Recv Date:	920727
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920727
Part A Recv Date:	Not reported
Part B Recv Date:	920812
Generator EPA ID:	NYD986927549
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002385730
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	42400
Units:	P - Pounds
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	92

Document ID:	PAC7888565
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0042
Trans2 State ID:	Not reported
Generator Ship Date:	930423
Trans1 Recv Date:	930423
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	930427
Part A Recv Date:	930505
Part B Recv Date:	930510
Generator EPA ID:	NYD986927549
Trans1 EPA ID:	PAD008781072
Trans2 EPA ID:	Not reported
TSDF ID:	PAD067098822
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	93

D20
NE
< 1/8
0.049 mi.
258 ft.

MARINE OCEAN TERMINAL
58TH & 1ST AVE
BROOKLYN, NY 11222

Site 3 of 8 in cluster D

Relative: Higher

Actual: 22 ft.

FINDS **1004572287**
N/A

FINDS:

Registry ID: 110010610302

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

D21
NE
< 1/8
0.049 mi.
258 ft.

HARBORSIDE INDUSTRIAL CENTER
58TH ST & 1ST AVE
BROOKLYN, NY 11222

Site 4 of 8 in cluster D

Relative: Higher

Actual: 22 ft.

RCRA-NonGen **1000164398**
FINDS **NYD980781520**

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	HARBORSIDE INDUSTRIAL CENTER
Facility address:	58TH ST & 1ST AVE BROOKLYN, NY 11222
EPA ID:	NYD980781520
Contact:	TED NABAVI
Contact address:	58TH ST & 1ST AVE BROOKLYN, NY 11222
Contact country:	US
Contact telephone:	(718) 669-8178
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

HARBORSIDE INDUSTRIAL CENTER (Continued) **1000164398**

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: HARBORSIDE INDUSTRIAL CENTER
Classification: Not a generator, verified

Date form received by agency: 07/06/1985
Facility name: HARBORSIDE INDUSTRIAL CENTER
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110008014594

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

D22
NE
< 1/8
0.049 mi.
258 ft.

ROADWAY
58TH STREET AND 1ST AVE
BROOKLYN, NY

Site 5 of 8 in cluster D

NY Spills **S110242876**
N/A

Relative:
Higher

Actual:
22 ft.

NY Spills:

Site ID:	425618
Facility Addr2:	Not reported
Facility ID:	0912713
Spill Number:	0912713
Facility Type:	ER
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Spill Date:	3/7/2010
Reported to Dept:	3/7/2010
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt:	3/8/2010
Remediation Phase:	0
Date Entered In Computer:	3/7/2010
Spill Record Last Update:	3/8/2010
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	WILFREDO RIVERA
Contact Phone:	(917) 559-7340
DEC Region:	2
DER Facility ID:	374510
DEC Memo:	DEC Piper spoke with caller and insturcted him to call FDNY Hospital or Police. Closed.
Remarks:	0420 THE CALLER ADVISED DISPATCH A SECURITY GUARD WAS FOUND DEAD AND DOT DOES NOT KNOW HOW TO CONDUCT CLEAN UP. THE CALLER IS REQUESTING DEC. THE SUBSTANCE IS CONTAINED. THE CALLER WAS NOT ABLE TO PROVIDE ANY FURTHER INFORMATION.

Material:

Site ID:	425618
Operable Unit ID:	1181334
Operable Unit:	01
Material ID:	2175409
Material Code:	0467A
Material Name:	BLOOD
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

ROADWAY (Continued) **S110242876**

Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

D23 **J.C. DUGGAN INC.** **LTANKS** **S100145729**
NE **111 58TH ST** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 6 of 8 in cluster D**

Relative:
Higher

Actual:
23 ft.

LTANKS:
Site ID: 203075
Spill No: 8908502
Spill Date: 11/28/1989
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/12/1996
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SULLIVAN
Referred To: Not reported
Reported to Dept: 11/28/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/29/1989
Spill Record Last Update: 5/15/1997
Spiller Name: Not reported
Spiller Company: J.C. DUGGAN INC.
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 168905

J.C. DUGGAN INC. (Continued) **S100145729**

Remarks: 550 GAL SYSTEMS TEST HORNER VISUAL GROSS LEAK AT FILL BOX AND STICK LINE NYC FIRE MARSHALL PRESENT.E I & R

Material:
Site ID: 203075
Operable Unit ID: 933559
Operable Unit: 01
Material ID: 445241
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 203075
Spill Tank Test: 1536475
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 8908502
Spill Date: 11/28/1989
Spill Time: 10:45
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/12/96
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SULLIVAN
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 11/28/89
Reported to Department Time: 14:03

J.C. DUGGAN INC. (Continued) **S100145729**

SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	J.C. DUGGAN INC.
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(718) 439-5353
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	11/29/89
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	05/15/97
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	-1
Unkonwn Quantity Spilled:	False
Units:	Pounds
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	DIESEL
Class Type:	DIESEL
Times Material Entry In File:	10625
CAS Number:	Not reported
Last Date:	19940728
DEC Remarks:	SEE QUEENS VILLAGE FIELD OFFICE FILE
Spill Cause:	550 GAL SYSTEMS TEST HORNER VISUAL GROSS LEAK AT FILL BOX AND STICK LINE NYC FIRE MARSHALL PRESENT.E I R

E24
NNE
< 1/8
0.050 mi.
264 ft.

140 58TH ST BUILDING
140 58TH ST
BROOKLYN, NY 11220

Site 1 of 28 in cluster E

Relative: Higher

Actual: 26 ft.

FINDS **1012120213**
N/A

FINDS:

Registry ID: 110038999466

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

E25
NNE
< 1/8
0.050 mi.
264 ft.

W Z F INCORPORATED
140 58TH STREET
BROOKLYN, NY 11220

Site 2 of 28 in cluster E

Relative: Higher

Actual: 26 ft.

RCRA-NonGen **1000118691**
FINDS **NYD986870301**
MANIFEST

RCRA-NonGen:

Date form received by agency:	10/21/2010
Facility name:	LIQUID TECHNOLOGY WAREHOUSE
Facility address:	140 58TH ST SUITE 3M BROOKLYN, NY 11220
EPA ID:	NYD986870301
Mailing address:	58TH ST SUITE 3M BROOKLYN, NY 11220
Contact:	ROBERT L RUEHLE
Contact address:	58TH ST SUITE 3M BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(646) 230-8637
Contact email:	RUEHLE@LIQUIDTECHNOLOGY.NET
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY
Owner/operator address:	BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1981
Owner/Op end date:	Not reported

W Z F INCORPORATED (Continued) **1000118691**

Owner/operator name: LIQUID TECHNOLOGY
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/01/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Consumer Electronics
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: LIQUID TECHNOLOGY WAREHOUSE
Site name: W Z F INC
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Facility name: LIQUID TECHNOLOGY WAREHOUSE
Site name: W Z F INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: LIQUID TECHNOLOGY WAREHOUSE
Site name: W Z F INC
Classification: Not a generator, verified

Date form received by agency: 06/17/1988
Facility name: LIQUID TECHNOLOGY WAREHOUSE
Site name: W Z F INC
Classification: Large Quantity Generator

W Z F INCORPORATED (Continued) **1000118691**

Hazardous Waste Summary:
Waste code: D005
Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Violation Status: No violations found

FINDS:

Registry ID: 110009476986

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986870301
Country: USA
Mailing Name: WZF INC
Mailing Contact: WZF INC
Mailing Address: 140 58TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-439-3200

Document ID: PAB5701220
Manifest Status: Completed copy
Trans1 State ID: PA-AH0278
Trans2 State ID: Not reported
Generator Ship Date: 890613
Trans1 Recv Date: 890613
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890614
Part A Recv Date: 890616
Part B Recv Date: 890622
Generator EPA ID: NYD986870301
Trans1 EPA ID: NJD000813477
Trans2 EPA ID: Not reported
TSDF ID: PAD098732118

W Z F INCORPORATED (Continued) **1000118691**

Waste Code:	F003 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

E26 **HARBOR CHARLIE** **UST** **U004154642**
NNE **140 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 3 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

UST:

Facility Id:	2-611331
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2011/12/10
UTM X:	582610.16361000005
UTM Y:	4499843.5433700001

Affiliation Records:

Site Id:	434278
Affiliation Type:	Owner
Company Name:	NYPD
Contact Type:	SUPERVISOR
Contact Name:	NICHOLAS GISONDS
Address1:	1 POLICE PLAZA
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(718) 476-7575
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	5/20/2010

Site Id:	434278
Affiliation Type:	Mail Contact
Company Name:	BUILDING MAINTENANCE SECTION
Contact Type:	Not reported
Contact Name:	COMMANDING OFFICER
Address1:	56-06 BROOKLYN-QUEENS EXPRESSWAY
Address2:	Not reported
City:	QUEENS
State:	NY
Zip Code:	11377
Country Code:	001
Phone:	(718) 476-7575
Phone Ext:	Not reported
Email:	Not reported

HARBOR CHARLIE (Continued) **U004154642**

Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	5/20/2010

Site Id:	434278
Affiliation Type:	On-Site Operator
Company Name:	HARBOR CHARLIE
Contact Type:	Not reported
Contact Name:	NYPD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 879-2083
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/3/2010

Site Id:	434278
Affiliation Type:	Emergency Contact
Company Name:	NYPD
Contact Type:	Not reported
Contact Name:	NYPD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 879-2083
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/3/2010

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
I05 - Overfill - Vent Whistle
I05 - Overfill - Vent Whistle
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F04 - Pipe External Protection - Fiberglass

HARBOR CHARLIE (Continued) **U004154642**

G04 - Tank Secondary Containment - Double-Walled (Underground)
F04 - Pipe External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction
B04 - Tank External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction

Tank Info:

Site ID:	434278
Tank Number:	01
Tank ID:	234155
Tank Status:	Temporarily Out of Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/10/2001
Capacity Gallons:	5000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	5/20/2010

Site ID:	434278
Tank Number:	02
Tank ID:	234156
Tank Status:	Temporarily Out of Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/10/2001
Capacity Gallons:	5000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	5/20/2010

E27 **OFFICE FURNITURE SERVICES** **RCRA-NonGen** **1000140284**
NNE **140 58TH ST** **FINDS** **NYD982736506**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.050 mi.
264 ft. **Site 4 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	OFFICE FURNITURE SERVICES
Facility address:	140 58TH ST 3B BROOKLYN ARMY TERMINAL BROOKLYN, NY 11220
EPA ID:	NYD982736506
Mailing address:	PO BOX 11 BROOKLYN, NY 11220
Contact:	JAY JIBODH
Contact address:	PO BOX 11 BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(718) 567-7400
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BROOKLYN ARMY TERMINAL
Owner/operator address:	140 58TH ST BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BROOKLYN ARMY TERMINAL
Owner/operator address:	140 58TH ST BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

OFFICE FURNITURE SERVICES (Continued) **1000140284**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: OFFICE FURNITURE SERVICES
Classification: Not a generator, verified

Date form received by agency: 08/06/1997
Facility name: OFFICE FURNITURE SERVICES
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 06/19/2007
Date achieved compliance: 01/22/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/24/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 01/22/2008
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 06/19/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 01/22/2008
Evaluation lead agency: State

Evaluation date: 11/05/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110009476227

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

OFFICE FURNITURE SERVICES (Continued) **1000140284**

NY MANIFEST:

EPA ID:	NYD982736506
Country:	USA
Mailing Name:	E B DESIGNS LTD
Mailing Contact:	E B DESIGNS LTD
Mailing Address:	140 58TH STREET SUITE 3B
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-439-3434

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-07-17
Trans1 Recv Date:	2009-07-17
Trans2 Recv Date:	2009-07-24
TSD Site Recv Date:	2009-07-25
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002021190SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA2800702
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCD987574647
Generator Ship Date:	07/13/1999
Trans1 Recv Date:	07/13/1999

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans2 Recv Date:	07/21/1999
TSD Site Recv Date:	07/23/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	NJD002182897
Trans2 EPA ID:	Not reported
TSDF ID:	08690
Waste Code:	F003 - UNKNOWN
Quantity:	00408
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NJA9628359
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS869
Trans2 State ID:	NJDEPS869
Generator Ship Date:	900214
Trans1 Recv Date:	900214
Trans2 Recv Date:	900215
TSD Site Recv Date:	900215
Part A Recv Date:	900406
Part B Recv Date:	900313
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00605
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	90

Document ID:	NJA1949862
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	950111
Trans1 Recv Date:	950111
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950113
Part A Recv Date:	Not reported
Part B Recv Date:	950125
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F003 - UNKNOWN

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Quantity:	00412
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	9/4/2007
Trans1 Recv Date:	9/4/2007
Trans2 Recv Date:	9/10/2007
TSD Site Recv Date:	9/11/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	240
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000073981SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/28/2007
Trans1 Recv Date:	11/28/2007
Trans2 Recv Date:	12/10/2007
TSD Site Recv Date:	12/11/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	256
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000092799SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA2049027
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	08690
Generator Ship Date:	950224
Trans1 Recv Date:	950224
Trans2 Recv Date:	950227
TSD Site Recv Date:	950228
Part A Recv Date:	Not reported
Part B Recv Date:	950314
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ILD984908202
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00530
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00416
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NJA0922113
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900815
Trans1 Recv Date:	900815
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900816
Part A Recv Date:	900913
Part B Recv Date:	900907
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00605
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NJA2806642
Manifest Status:	Not reported
Trans1 State ID:	ILD984908202
Trans2 State ID:	SCR000074591
Generator Ship Date:	05/04/2000
Trans1 Recv Date:	05/04/2000
Trans2 Recv Date:	05/09/2000
TSD Site Recv Date:	05/15/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	NJD002182897
Trans2 EPA ID:	Not reported
TSDF ID:	08690
Waste Code:	F003 - UNKNOWN
Quantity:	00408
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-05-14
Trans1 Recv Date:	2008-05-14
Trans2 Recv Date:	2008-05-21
TSD Site Recv Date:	2008-05-23
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000141723SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA1218539
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	910516
Trans1 Recv Date:	910516
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910522
Part A Recv Date:	910528
Part B Recv Date:	910617
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00604
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-07-17
Trans1 Recv Date:	2009-07-17
Trans2 Recv Date:	2009-07-24
TSD Site Recv Date:	2009-07-25

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002021190SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA1410596
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	920520
Trans1 Recv Date:	920520
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920527
Part A Recv Date:	Not reported
Part B Recv Date:	920619
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00604
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92

Document ID:	NJA1355149
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	920319

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans1 Recv Date:	920319
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920325
Part A Recv Date:	920331
Part B Recv Date:	920410
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	01214
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-05-14
Trans1 Recv Date:	2008-05-14
Trans2 Recv Date:	2008-05-21
TSD Site Recv Date:	2008-05-23
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000141723SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-06-30
Trans1 Recv Date:	2008-06-30
Trans2 Recv Date:	2008-07-14
TSD Site Recv Date:	2008-07-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001307131SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA1214116
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	911211
Trans1 Recv Date:	911211
Trans2 Recv Date:	911220
TSD Site Recv Date:	911220
Part A Recv Date:	Not reported
Part B Recv Date:	920117
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	NJD000813477
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00604
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Document ID:	NJA1433329
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	921216
Trans1 Recv Date:	921216
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	921221
Part A Recv Date:	Not reported
Part B Recv Date:	930108
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F003 - UNKNOWN
Quantity:	00410
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00563
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	92

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	MOD095038998
Generator Ship Date:	2008-08-15
Trans1 Recv Date:	2008-08-15
Trans2 Recv Date:	2008-08-22
TSD Site Recv Date:	2008-08-24
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001306999SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

OFFICE FURNITURE SERVICES (Continued) **1000140284**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA1436480
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS869
Trans2 State ID:	Not reported
Generator Ship Date:	920625
Trans1 Recv Date:	920625
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920629
Part A Recv Date:	Not reported
Part B Recv Date:	920717
Generator EPA ID:	NYD982736506
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00605
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92

Click this hyperlink while viewing on your computer to access
27 additional NY_MANIFEST: record(s) in the EDR Site Report.

E28
NNE
< 1/8
0.050 mi.
264 ft.

DEFIANCE PRINTING-140 58TH ST **FINDS** **1007745782**
140 58TH STREET **N/A**
BROOKLYN, NY 11220

Site 5 of 28 in cluster E

Relative:
Higher

Actual:
26 ft.

FINDS:

Registry ID: 110019081633

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E29
NNE
< 1/8
0.050 mi.
264 ft.

SMITH & WATSON
140 58TH ST
BROOKLYN, NY 11220

Site 6 of 28 in cluster E

FINDS **1007761240**
N/A

Relative:
Higher

Actual:
26 ft.

FINDS:

Registry ID: 110019236593

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E30
NNE
< 1/8
0.050 mi.
264 ft.

140 58TH ST
140 58TH ST
BROOKLAND, NY 11220

Site 7 of 28 in cluster E

ERNS **2009913207**
N/A

Relative:
Higher

Actual:
26 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

E31
NNE
< 1/8
0.050 mi.
264 ft.

IEH CORP
140 58TH ST 8E
BROOKLYN, NY 11220

Site 8 of 28 in cluster E

FINDS **1008382854**
N/A

Relative:
Higher

Actual:
26 ft.

FINDS:

Registry ID: 110022447538

Environmental Interest/Information System
The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

E32 **140 58TH ST** **ERNS** **2008913207**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLAND, NY 11220**
0.050 mi.
264 ft. **Site 9 of 28 in cluster E**

Relative:
Higher

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
26 ft.

E33 **NYCEDC - BROOKLYN ARMY TERMINAL PIER 1** **RCRA-LQG** **1005417215**
NNE **140 58TH STREET** **NYR000103390**
< 1/8 **BROOKLYN, NY 11201**
0.050 mi.
264 ft. **Site 10 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

RCRA-LQG:

Date form received by agency:	02/16/2010
Facility name:	NYCEDC - BROOKLYN ARMY TERMINAL PIER 1
Facility address:	140 58TH STREET BROOKLYN, NY 11201
EPA ID:	NYR000103390
Mailing address:	WILLIAM STREET NEW YORK, NY 10038
Contact:	KAY ZIAS
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 312-3752
Contact email:	KZIAS@NYCEDC.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY ECONOMIC DEVELOPMENT CORPO
Owner/operator address:	WILLIAMS STREET NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/1981
Owner/Op end date:	Not reported
Owner/operator name:	NEW YORK CITY ECONOMIC DEVELOPMENT CORPO
Owner/operator address:	WILLIAMS STREET NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	Not reported

NYCEDC - BROOKLYN ARMY TERMINAL PIER 1 (Continued) **1005417215**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/1981
Owner/Op end date: Not reported

Owner/operator name: NYC ECONOMIC DEVELOPMENT CORP
Owner/operator address: 110 WILLIAMS ST
NEW YORK, NY 10038
Owner/operator country: Not reported
Owner/operator telephone: (212) 312-3623
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/10/2008
Facility name: NYCEDC - BROOKLYN ARMY TERMINAL PIER 1
Site name: NYCEDC - BROOKLYN ARMY TERMINAL
Classification: Large Quantity Generator

Date form received by agency: 01/01/2007
Facility name: NYCEDC - BROOKLYN ARMY TERMINAL PIER 1
Site name: BROOKLYN ARMY TERMINAL
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Facility name: NYCEDC - BROOKLYN ARMY TERMINAL PIER 1
Site name: BROOKLYN ARMY TERMINAL
Classification: Not a generator, verified

Date form received by agency: 01/17/2002
Facility name: NYCEDC - BROOKLYN ARMY TERMINAL PIER 1
Site name: BROOKLYN ARMY TERMINAL
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

NYCEDC - BROOKLYN ARMY TERMINAL PIER 1 (Continued) **1005417215**

Waste code: B007
Waste name: B007

Waste code: D008
Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2011

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 8046000

Violation Status: No violations found

E34 **140 58TH ST** **ERNS** **2009914491**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLAND, NY 11220**
0.050 mi.
264 ft. **Site 11 of 28 in cluster E**

Relative: Higher

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual: 26 ft.

E35 **I E H CORP** **RCRA-SQG** **1001215414**
NNE **140 58TH ST - 8TH FLOOR** **MANIFEST** **NYD987001864**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.050 mi.
264 ft. **Site 12 of 28 in cluster E**

Relative: Higher

Actual: 26 ft.

RCRA-SQG:
Date form received by agency: 01/01/2007
Facility name: I E H CORP
Facility address: 140 58TH ST - 8TH FLOOR
BROOKLYN, NY 11220
EPA ID: NYD987001864
Mailing address: 58TH ST - 8TH FLOOR
BROOKLYN, NY 11220
Contact: EMIL AMALOVETZ
Contact address: 58TH ST - 8TH FLOOR
BROOKLYN, NY 11220
Contact country: US
Contact telephone: (718) 492-4440
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: I E H CORP

I E H CORP (Continued) **1001215414**

Owner/operator address: 140 58TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 492-4440
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: I E H CORP
Owner/operator address: 140 58TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 492-4440
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: I E H CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/18/1992
Facility name: I E H CORP
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/05/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 10/20/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

I E H CORP (Continued) **1001215414**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
EPA ID: NYD987001864
Country: USA
Mailing Name: IEH
Mailing Contact: WALDEMAN
Mailing Address: SUITE 8E 140 58TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-492-4440

Document ID: PAG0424609
Manifest Status: Not reported
Trans1 State ID: PAR000501577
Trans2 State ID: Not reported
Generator Ship Date: 03/20/2003
Trans1 Recv Date: 03/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987001864
Trans1 EPA ID: PAD085690592
Trans2 EPA ID: Not reported
TSDF ID: PAAH0682
Waste Code: U159 - METHYL ETHYL KETONE(L,T)
Quantity: 00110
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00012
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001

I E H CORP (Continued) **1001215414**

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Document ID: PAG0424609
Manifest Status: Not reported
Trans1 State ID: PAR000501577
Trans2 State ID: Not reported
Generator Ship Date: 03/20/2003
Trans1 Recv Date: 03/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987001864
Trans1 EPA ID: PAD085690592
Trans2 EPA ID: Not reported
TSDF ID: PAAH0682
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: P098 - POTASSIUM CYANIDE
Quantity: 00030
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: U228 - TRICHLOROETHENE
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

Document ID: PAG0424609
Manifest Status: Not reported
Trans1 State ID: PAR000501577
Trans2 State ID: Not reported
Generator Ship Date: 03/20/2003
Trans1 Recv Date: 03/20/2003

I E H CORP (Continued) **1001215414**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	PAAH0682
Waste Code:	U226 - 1,1,1-TRICHLOROETHANE
Quantity:	00120
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00060
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00130
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	PAG0424609
Manifest Status:	Not reported
Trans1 State ID:	PAR000501577
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2003
Trans1 Recv Date:	03/20/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	PAAH0682
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001

I E H CORP (Continued) **1001215414**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	PAG0424609
Manifest Status:	Not reported
Trans1 State ID:	PAR000501577
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2003
Trans1 Recv Date:	03/20/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	PAAH0682
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2003

Document ID:	NJA5075036
Manifest Status:	Not reported
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2004
Trans1 Recv Date:	04/01/2004

I E H CORP (Continued) **1001215414**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

Document ID:	NJA5075156
Manifest Status:	Not reported
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2004
Trans1 Recv Date:	04/07/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/07/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2004

Document ID:	06
Manifest Status:	NJA5311504
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJ0000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N

I E H CORP (Continued) **1001215414**

Quantity:	Not reported
Units:	1
Number of Containers:	DM
Container Type:	55
Handling Method:	G
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	06
Manifest Status:	NJA5311504
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJ0000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DM
Container Type:	30
Handling Method:	G
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	06
Manifest Status:	NJA5311504
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJ0000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

I E H CORP (Continued) **1001215414**

Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	CF
Container Type:	300
Handling Method:	P
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	06
Manifest Status:	NJA5311505
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJD000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	10
Handling Method:	P
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	06
Manifest Status:	NJA5311505
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046

I E H CORP (Continued) **1001215414**

Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJD000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	5
Handling Method:	G
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	06
Manifest Status:	NJA5311506
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJD000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	5
Handling Method:	G
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

I E H CORP (Continued) **1001215414**

Document ID:	06
Manifest Status:	NJA5311506
Trans1 State ID:	NYD987001864
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJD000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	5
Handling Method:	G
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	NJA5311504
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2006
Trans1 Recv Date:	06/01/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/01/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels

I E H CORP (Continued) **1001215414**

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2006

Document ID: NJA5311505
Manifest Status: Not reported
Trans1 State ID: NJD000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/01/2006
Trans1 Recv Date: 06/01/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/01/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987001864
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: U228 - TRICHLOROETHENE
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D003 - NON-LISTED REACTIVE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2006

Document ID: NJA5311506
Manifest Status: Not reported
Trans1 State ID: NJD000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/01/2006
Trans1 Recv Date: 06/01/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/01/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987001864
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

I E H CORP (Continued) **1001215414**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2006

Document ID:	RIB0019716
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	RI535
Generator Ship Date:	920902
Trans1 Recv Date:	920903
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920904
Part A Recv Date:	Not reported
Part B Recv Date:	920924
Generator EPA ID:	NYD987001864
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID:	RID001200252
Waste Code:	F007 - PLATING BATH SOL FM ELECTROPLATING OPER
Quantity:	00086
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92

NJ MANIFEST:

Manifest Code:	NJA5311505
EPA ID:	NYD987001864
Date Shipped:	20060601
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060601
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060601
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	07200621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5311506
EPA ID:	NYD987001864
Date Shipped:	20060601
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060601
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060601
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	07200621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

I E H CORP (Continued) **1001215414**

Manifest Code:	004258034JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	65240
Unit:	P
Hand Code:	H111

Manifest Code:	004258031JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	62500
Unit:	P
Hand Code:	H111

Manifest Code:	004258024JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	59740
Unit:	P
Hand Code:	H111

I E H CORP (Continued) **1001215414**

Manifest Code:	004258027JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	59760
Unit:	P
Hand Code:	H111

Manifest Code:	004258030JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/27/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 59300
Unit: P
Hand Code: H111

Manifest Code: 004258032JJK
EPA ID: NYR000103390
Date Shipped: 01/27/09
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/27/09
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/27/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 59960
Unit: P
Hand Code: H111

I E H CORP (Continued) **1001215414**

Manifest Code:	004258026JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	57080
Unit:	P
Hand Code:	H111

Manifest Code:	004258025JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/27/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 54840
Unit: P
Hand Code: H111

Manifest Code: 004258056JJK
EPA ID: NYR000103390
Date Shipped: 01/29/09
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/09
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/29/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 57980
Unit: P
Hand Code: H111

I E H CORP (Continued) **1001215414**

Manifest Code:	004258061JJK
EPA ID:	NYR000103390
Date Shipped:	01/29/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	56240
Unit:	P
Hand Code:	H111

Manifest Code:	004258060JJK
EPA ID:	NYR000103390
Date Shipped:	01/29/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	59360
Unit:	P
Hand Code:	H111

Manifest Code:	004258017JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	52980
Unit:	P
Hand Code:	H111

I E H CORP (Continued) **1001215414**

Manifest Code:	004258029JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	56640
Unit:	P
Hand Code:	H111

Manifest Code:	004258028JJK
EPA ID:	NYR000103390
Date Shipped:	01/27/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/27/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	65040
Unit:	P
Hand Code:	H111

Manifest Code:	004258065JJK
EPA ID:	NYR000103390
Date Shipped:	01/29/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	62980
Unit:	P
Hand Code:	H111

I E H CORP (Continued) **1001215414**

Manifest Code:	004258066JJK
EPA ID:	NYR000103390
Date Shipped:	01/29/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	59140
Unit:	P
Hand Code:	H111

Manifest Code:	004258058JJK
EPA ID:	NYR000103390
Date Shipped:	01/29/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

I E H CORP (Continued) **1001215414**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	63000
Unit:	P
Hand Code:	H111

Manifest Code:	004258050JJK
EPA ID:	NYR000103390
Date Shipped:	01/30/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/30/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/30/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	59540
Unit:	P
Hand Code:	H111

E36 **NYC DEPT OF TRANSPORTATION** **NY Spills** **S109828165**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 13 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

NY Spills:

Site ID:	417227
Facility Addr2:	Not reported
Facility ID:	0904994
Spill Number:	0904994
Facility Type:	ER
SWIS:	2401
Investigator:	smsanges
Referred To:	Not reported
Spill Date:	7/30/2009
Reported to Dept:	7/30/2009
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/30/2009
Remediation Phase:	0
Date Entered In Computer:	7/30/2009
Spill Record Last Update:	7/30/2009
Spiller Name:	LOU DESIO
Spiller Company:	NYC DEPT OF TRANSPORTATION
Spiller Address:	140 58TH ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	LOU DESIO
Contact Phone:	(718) 439-3622
DEC Region:	2
DER Facility ID:	366323
DEC Memo:	Sangesland spoke to Lou Desio. He said the site is a NYC DOT parking lot for city dump trucks. One parked truck leaked diesel to the ground and formed a puddle on the cement parking lot. No soil or drains were impacted. Area was cleaned.
Remarks:	DUE TO A LEAKING FILTER ON A TRUCK ABOUT 15 GALLONS SPILLED TO PAVEMENT. CLEAN UP IS IN PROGRESS, SPILL IS CONTAINED.

Material:

Site ID:	417227
Operable Unit ID:	1173462
Operable Unit:	01
Material ID:	2165388
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons

NYC DEPT OF TRANSPORTATION (Continued) **S109828165**

Recovered: 15
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

E37 **MEAD & JOSIPOVICH-140 58TH ST** **FINDS** **1006303578**
NNE **140 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 14 of 28 in cluster E**

Relative: Higher

Actual: 26 ft.

FINDS:

Registry ID: 110012393908

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E38 **NYC ECONOMIC DEVELOPMENT CORP** **RCRA-NonGen** **1004755920**
NNE **140 58TH ST** **FINDS** **NY0000869578**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.050 mi.
264 ft. **Site 15 of 28 in cluster E**

Relative: Higher

Actual: 26 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Facility address: 140 58TH ST
BROOKLYN ARMY TERMINAL

NYC ECONOMIC DEVELOPMENT CORP (Continued) **1004755920**

BROOKLYN, NY 11220
EPA ID: NY0000869578
Mailing address: FORT TOTTEN BLDG 200 ROOM 271
FLUSHING, NY 113590001
Contact: DONALD BRAUN
Contact address: FORT TOTTEN BLDG 200 ROOM 271
FLUSHING, NY 113590001
Contact country: US
Contact telephone: (718) 352-1888
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC ECONOMIC DEVELOPMENT CORP
Owner/operator address: 110 WILLIAM ST
NEW YORK, NY 10038
Owner/operator country: US
Owner/operator telephone: (212) 619-5000
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC ECONOMIC DEVELOPMENT CORP
Owner/operator address: 110 WILLIAM ST
NEW YORK, NY 10038
Owner/operator country: US
Owner/operator telephone: (212) 619-5000
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Classification: Not a generator, verified

NYC ECONOMIC DEVELOPMENT CORP (Continued) **1004755920**

Date form received by agency: 03/26/1996
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Site name: BROOKLYN ARMY TERMINAL - BLDG A
Classification: Large Quantity Generator

Date form received by agency: 10/05/1994
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002337766

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID: NY0000869578
Country: USA
Mailing Name: UNITED STATES ARMY CORPS OF ENG
Mailing Contact: RICHARD MC INERNEY
Mailing Address: FORT TOTEM BLDG 200 RM 271
Mailing Address 2: Not reported
Mailing City: FLUSHING
Mailing State: NY
Mailing Zip: 11359
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-352-1883

Document ID: NJA1603222
Manifest Status: Completed copy
Trans1 State ID: S2265
Trans2 State ID: Not reported
Generator Ship Date: 950307
Trans1 Recv Date: 950307
Trans2 Recv Date: 950308
TSD Site Recv Date: 950308
Part A Recv Date: Not reported
Part B Recv Date: 950324
Generator EPA ID: NY0000869578
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

NYC ECONOMIC DEVELOPMENT CORP (Continued) **1004755920**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01859
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

E39 **NYC DEPT OF TRANSPORTATION** **NY Spills** **S109828543**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 16 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

NY Spills:

Site ID:	417732
Facility Addr2:	Not reported
Facility ID:	0905468
Spill Number:	0905468
Facility Type:	ER
SWIS:	2401
Investigator:	HRAHMED
Referred To:	Not reported
Spill Date:	8/11/2009
Reported to Dept:	8/11/2009
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	8/20/2009
Remediation Phase:	0
Date Entered In Computer:	8/11/2009
Spill Record Last Update:	8/20/2009
Spiller Name:	LOU DESSIO
Spiller Company:	NYC DEPT OF TRANSPORTATION
Spiller Address:	140 58TH ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	LOU DESSIO
Contact Phone:	(718) 439-3622
DEC Region:	2
DER Facility ID:	366323
DEC Memo:	08/20/09-HRAHMED-Spill was on the pavement. Cleanup was done by putting speedy dry. This case is closed.
Remarks:	DUE TO A LEAKING FUEL TRUCK #82C ABOUT 20 GALLONS SPILLED TO PAVEMENT. CLEAN UP WAS DONE

Material:

Site ID:	417732
Operable Unit ID:	1173946

NYC DEPT OF TRANSPORTATION (Continued) **S109828543**

Operable Unit:	01
Material ID:	2166138
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20
Units:	Gallons
Recovered:	20
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

E40 **CENTRAL DEPOT/FLEET SERVICES** **AST** **A100304634**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 17 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610557
Program Type:	PBS
UTM X:	582610.16361000005
UTM Y:	4499843.5433700001
Expiration Date:	2016/08/01

Affiliation Records:

Site Id:	381099
Affiliation Type:	Mail Contact
Company Name:	NYC DOT FACILITIES MANAGEMENT
Contact Type:	Not reported
Contact Name:	PETER SAMBALIS
Address1:	55 WATER STREET
Address2:	7TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10041
Country Code:	001
Phone:	(212) 839-8920
Phone Ext:	Not reported
Email:	PSAMBALIS@DOT.NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR

CENTRAL DEPOT/FLEET SERVICES (Continued) **A100304634**

Date Last Modified:	5/13/2011
Site Id:	381099
Affiliation Type:	On-Site Operator
Company Name:	CENTRAL DEPOT/FLEET SERVICES
Contact Type:	Not reported
Contact Name:	MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-3635
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	5/8/2007
Site Id:	381099
Affiliation Type:	Owner
Company Name:	NYC DOT
Contact Type:	DIRECTOR OF BULK STORAGE TANKS
Contact Name:	PET4R SAMBALIS
Address1:	55 WATER ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10041
Country Code:	001
Phone:	(212) 839-8920
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/13/2011
Site Id:	381099
Affiliation Type:	Emergency Contact
Company Name:	NYC DOT
Contact Type:	Not reported
Contact Name:	DOT CENTRAL ROOM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 433-3340
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/13/2011

CENTRAL DEPOT/FLEET SERVICES (Continued) **A100304634**

Equipment Records:

L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
D00 - Pipe Type - No Piping
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None

Tank Info:

Tank Number:	703
Tank Id:	217106
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/2006
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	5/13/2011

E41 **COMPLETE MAILING SERVICES** **RCRA-NonGen** **1004762925**
NNE **140 58TH ST SUITE 6D** **FINDS** **NYR000101857**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.050 mi.
264 ft. **Site 18 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	COMPLETE MAILING SERVICES
Facility address:	140 58TH ST SUITE 6D BROOKLYN, NY 11220
EPA ID:	NYR000101857
Mailing address:	58TH ST SUITE 6D BROOKLYN, NY 11220
Contact:	KEVIN PATTERSON
Contact address:	58TH ST SUITE 6D BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(212) 741-7641
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

COMPLETE MAILING SERVICES (Continued) **1004762925**

Owner/Operator Summary:
Owner/operator name: COMPLETE MAILING SERVICES
Owner/operator address: 140 58TH ST SUITE 6D
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 238-2919
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: COMPLETE MAILING SERVICES
Owner/operator address: 140 58TH ST SUITE 6D
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 238-2919
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: COMPLETE MAILING SERVICES
Classification: Not a generator, verified

Date form received by agency: 10/30/2001
Facility name: COMPLETE MAILING SERVICES
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012201134

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

COMPLETE MAILING SERVICES (Continued) **1004762925**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000101857
Country:	USA
Mailing Name:	COMPLETE MAILING SVCS
Mailing Contact:	AL BATISTA
Mailing Address:	140 58TH ST STE 6D
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-238-2919

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CT5000001495
Trans2 State ID:	Not reported
Generator Ship Date:	2009-04-16
Trans1 Recv Date:	2009-04-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-04-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000101857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CT5000001495
Waste Code:	Not reported
Quantity:	304.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	100016192CTN
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H010

COMPLETE MAILING SERVICES (Continued) **1004762925**

Document ID: NYG3193794
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 12/12/2001
Trans1 Recv Date: 12/12/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/14/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000101857
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG3192237
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2001
Trans1 Recv Date: 11/21/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/26/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000101857
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-16
Trans1 Recv Date: 2009-04-16
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-16
Part A Recv Date: Not reported

COMPLETE MAILING SERVICES (Continued) **1004762925**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000101857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CT5000001495
Waste Code:	Not reported
Quantity:	304.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	100016192CTN
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H010

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CT5000001495
Trans2 State ID:	Not reported
Generator Ship Date:	2009-04-16
Trans1 Recv Date:	2009-04-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-04-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000101857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CT5000001495
Waste Code:	Not reported
Quantity:	304.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	100016192CTN
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

COMPLETE MAILING SERVICES (Continued) **1004762925**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-16
Trans1 Recv Date: 2009-04-16
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-16
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000101857
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 304.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 100016192CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: NYG3565512
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 12/30/2002
Trans1 Recv Date: 12/30/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/31/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000101857
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 40580PANY
Waste Code: F003 - UNKNOWN

COMPLETE MAILING SERVICES (Continued) **1004762925**

Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

E42 **NYC ECOMONIC DEVELOPMENT** **MANIFEST** **S102149982**
NNE **140 58TH STREET** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11201** **NY Hist Spills**
0.050 mi.
264 ft. **Site 19 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

NY MANIFEST:

EPA ID:	NYR000103390
Country:	USA
Mailing Name:	NYC ECOMONIC DEVELOPMENT
Mailing Contact:	N/S
Mailing Address:	110 WILLIAM ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10038
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-312-3623

NY MANIFEST:

No Manifest Records Available

NY Spills:

Site ID:	283463
Facility Addr2:	Not reported
Facility ID:	9500832
Spill Number:	9500832
Facility Type:	ER
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Spill Date:	3/8/1995
Reported to Dept:	4/20/1995
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt:	2/28/2003
Remediation Phase:	0
Date Entered In Computer:	5/12/1995

NYC ECOMONIC DEVELOPMENT (Continued) **S102149982**

Spill Record Last Update:	4/9/2003
Spiller Name:	Not reported
Spiller Company:	MARINE CORP
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	229904
DEC Memo:	Not reported
Remarks:	2 TANKS 1-K EACH GASOLINE , N/S 15 CUB. Y OF CONTAMINATED SOIL, FOUND WHEN REMOVING TANKS 1 1/2 MONTHS AGO.

Material:

Site ID:	283463
Operable Unit ID:	1014957
Operable Unit:	01
Material ID:	369447
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9500832
Investigator:	TOMASELLO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/08/1995 12:00
Reported to Dept Date/Time:	04/20/95 01:35
SWIS:	61
Spiller Name:	MARINE CORP
Spiller Contact:	Not reported

NYC ECOMONIC DEVELOPMENT (Continued) **S102149982**

Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/12/95
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: 2 TANKS 1-K EACH GASOLINE , N/S 15 CUB. Y OF CONTAMINATED SOIL, FOUND WHEN REMOVING TANKS 1 1/2 MONTHS AGO.

E43 **IEH CORP** **TRIS** **1009396298**
NNE **140 58TH ST 8E** **11220HCRPX14**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 20 of 28 in cluster E**

Relative: Higher

Actual: 26 ft.

E44 **CITIGROUP GLOBAL MARKETS INC** **FINDS** **1007800137**
NNE **140 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 21 of 28 in cluster E**

Relative: Higher

FINDS:

Registry ID: 110019626555

Actual: 26 ft.

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E45 **140 58TH ST** **ERNS** **2008914491**
NNE **140 58TH ST** **N/A**
< 1/8 **BROOKLAND, NY 11220**
0.050 mi.
264 ft. **Site 22 of 28 in cluster E**

Relative: Higher

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual: 26 ft.

E46
NNE
< 1/8
0.050 mi.
264 ft.

VANGUARD DIRECT
140 58TH ST SUITE 1A BLDG B
BROOKLYN, NY 11220

Site 23 of 28 in cluster E

RCRA-CESQG 1004762679
FINDS NYR000099374
MANIFEST

Relative:
Higher

Actual:
26 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	VANGUARD DIRECT
Facility address:	140 58TH ST SUITE 1A BLDG B BROOKLYN, NY 11220
EPA ID:	NYR000099374
Mailing address:	58TH ST SUITE 1A BLDG B BROOKLYN, NY 11220
Contact:	ALFRED BIRKERT
Contact address:	58TH ST SUITE 1A BLDG B BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(718) 748-8900
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALFRED BIRKERT
Owner/operator address:	140 58TH ST SUITE 1A BLDG B BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(718) 748-8900
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	ALFRED BIRKERT
Owner/operator address:	140 58TH ST SUITE 1A BLDG B BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(718) 748-8900
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

VANGUARD DIRECT (Continued) **1004762679**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VANGUARD DIRECT
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/20/2001
Facility name: VANGUARD DIRECT
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012267607

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000099374
Country: USA
Mailing Name: VANGUARD DIRECT
Mailing Contact: N/S
Mailing Address: 140 58TH ST STE 1A BLDG B
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip4: 2521
Mailing Country: USA
Mailing Phone: 718-748-8900

VANGUARD DIRECT (Continued) **1004762679**

Document ID:	MAQ0717010
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2003
Trans1 Recv Date:	12/03/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	MAD982755639
Trans2 EPA ID:	Not reported
TSDF ID:	NYCAT8305
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00270
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2003

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	2/9/2007
Trans1 Recv Date:	2/9/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2/27/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MAD982755639
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000006261SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

VANGUARD DIRECT (Continued) **1004762679**

Mgmt Method Type Code: H010

Document ID: 06
Manifest Status: MAU0045618
Trans1 State ID: NYR000099374
Trans2 State ID: Not reported
Generator Ship Date: MAD982755639
Trans1 Recv Date: Not reported
Trans2 Recv Date: TXR000050930
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DF
Container Type: 200
Handling Method: P
Specific Gravity: 1
Waste Code: R
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: MAU0045618
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 03/21/2006
Trans1 Recv Date: 03/21/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/29/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000099374
Trans1 EPA ID: YC94889JF
Trans2 EPA ID: Not reported
TSDF ID: MAD982755639
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2006

VANGUARD DIRECT (Continued) **1004762679**

Document ID:	07
Manifest Status:	000006261SKS
Trans1 State ID:	NYR000099374
Trans2 State ID:	Not reported
Generator Ship Date:	MAD982755639
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	TXR000050930
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	100
Handling Method:	P
Specific Gravity:	1
Waste Code:	R
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	MAM9784270
Manifest Status:	Not reported
Trans1 State ID:	SCR000075150
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2001
Trans1 Recv Date:	08/17/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/27/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	NJD002182897
Trans2 EPA ID:	Not reported
TSDF ID:	NYGF2859
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00060
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2001

Document ID:	MAQ0052440
Manifest Status:	Not reported

VANGUARD DIRECT (Continued) **1004762679**

Trans1 State ID:	SCR000075150
Trans2 State ID:	NJD071629976
Generator Ship Date:	02/19/2002
Trans1 Recv Date:	02/19/2002
Trans2 Recv Date:	02/22/2002
TSD Site Recv Date:	02/28/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	MAD982755639
Trans2 EPA ID:	Not reported
TSDF ID:	NYXAB6384
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00016
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	2007-02-09
Trans1 Recv Date:	2007-02-09
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-27
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MAD982755639
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	2007
Manifest Tracking Num:	000006261SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H010

VANGUARD DIRECT (Continued) **1004762679**

Document ID:	MAU0045618
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	03/21/2006
Trans1 Recv Date:	03/21/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/29/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000099374
Trans1 EPA ID:	YC94889JF
Trans2 EPA ID:	Not reported
TSDF ID:	MAD982755639
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2006

E47 **MORGAN STANLEY & CO INC.** **MANIFEST** **1010184055**
NNE **140 58TH ST 8 G** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 24 of 28 in cluster E**

Relative:
Higher

Actual:
26 ft.

NY MANIFEST:

EPA ID:	NYD987029550
Country:	USA
Mailing Name:	MORGAN STANLEY & CO INC.
Mailing Contact:	BARRY ALESSI
Mailing Address:	140 58TH ST 8 G
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-754-5228

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-02-09
Trans1 Recv Date:	2009-02-09
Trans2 Recv Date:	2009-02-13
TSD Site Recv Date:	2009-02-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000117934SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-09-18
Trans1 Recv Date:	2009-09-18
Trans2 Recv Date:	2009-09-22
TSD Site Recv Date:	2009-09-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002036251SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-05-19
Trans1 Recv Date:	2009-05-19
Trans2 Recv Date:	2009-05-26
TSD Site Recv Date:	2009-05-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001805109SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2/9/2007
Trans1 Recv Date:	2/9/2007
Trans2 Recv Date:	2/21/2007
TSD Site Recv Date:	2/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	250
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Year:	2007
Manifest Tracking Num:	000006270SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	8/16/2007
Trans1 Recv Date:	8/16/2007
Trans2 Recv Date:	8/22/2007
TSD Site Recv Date:	8/23/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000049875SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NYD980769947
Generator Ship Date:	11/12/2007
Trans1 Recv Date:	11/12/2007

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Trans2 Recv Date:	11/19/2007
TSD Site Recv Date:	11/24/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	250
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000092729SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-02-13
Trans1 Recv Date:	2008-02-13
Trans2 Recv Date:	2008-02-19
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000117896SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-04-21
Trans1 Recv Date:	2008-04-21
Trans2 Recv Date:	2008-04-28
TSD Site Recv Date:	2008-04-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124992SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-02-13
Trans1 Recv Date:	2008-02-13
Trans2 Recv Date:	2008-02-19
TSD Site Recv Date:	2008-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000117896SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-07-29
Trans1 Recv Date:	2008-07-29
Trans2 Recv Date:	2008-08-12
TSD Site Recv Date:	2008-08-13
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001307231SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-04-21
Trans1 Recv Date: 2008-04-21
Trans2 Recv Date: 2008-04-28
TSD Site Recv Date: 2008-04-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987029550
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 000124992SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2009-09-18
Trans1 Recv Date: 2009-09-18
Trans2 Recv Date: 2009-09-22
TSD Site Recv Date: 2009-09-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987029550
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 200.0
Units: P - Pounds
Number of Containers: 1.0

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	002036251SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-02-09
Trans1 Recv Date:	2009-02-09
Trans2 Recv Date:	2009-02-13
TSD Site Recv Date:	2009-02-15
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000117934SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Trans2 State ID:	NJD071629976
Generator Ship Date:	2009-05-19
Trans1 Recv Date:	2009-05-19
Trans2 Recv Date:	2009-05-26
TSD Site Recv Date:	2009-05-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	001805109SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NYC7849991
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	08/17/2006
Trans1 Recv Date:	08/17/2006
Trans2 Recv Date:	08/25/2006
TSD Site Recv Date:	08/28/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	NYCAD6277
Trans2 EPA ID:	T2L231
TSDF ID:	KYD053348108
Waste Code:	F003 - UNKNOWN
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2006

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Document ID:	NYC7742272
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	01/27/2006
Trans1 Recv Date:	01/27/2006
Trans2 Recv Date:	02/03/2006
TSD Site Recv Date:	02/06/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	NYC58468J
Trans2 EPA ID:	T77180NJ
TSDF ID:	KYD053348108
Waste Code:	F003 - UNKNOWN
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2006

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-10-20
Trans1 Recv Date:	2008-10-20
Trans2 Recv Date:	2008-10-23
TSD Site Recv Date:	2008-10-24
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	220.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001317073SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-07-29
Trans1 Recv Date: 2008-07-29
Trans2 Recv Date: 2008-08-12
TSD Site Recv Date: 2008-08-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987029550
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 150.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001307231SKS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: NJD071629976
Generator Ship Date: 2008-02-13
Trans1 Recv Date: 2008-02-13
Trans2 Recv Date: 2008-02-19
TSD Site Recv Date: 2008-02-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987029550
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: KYD053348108
Waste Code: Not reported
Quantity: 200.0
Units: P - Pounds
Number of Containers: 1.0

MORGAN STANLEY & CO INC. (Continued) **1010184055**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000117896SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	2008-04-21
Trans1 Recv Date:	2008-04-21
Trans2 Recv Date:	2008-04-28
TSD Site Recv Date:	2008-04-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029550
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	KYD053348108
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	000124992SKS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Click this hyperlink while viewing on your computer to access
7 additional NY_MANIFEST: record(s) in the EDR Site Report.

E48
NNE
< 1/8
0.050 mi.
264 ft.

MORGAN STANLEY & CO INC
140 58TH ST STE G
BROOKLYN, NY 11220

Site 25 of 28 in cluster E

RCRA-CESQG **1000833530**
NYD987029550

Relative:
Higher

Actual:
26 ft.

RCRA-CESQG:

Date form received by agency:	10/04/2010
Facility name:	MORGAN STANLEY & CO INC
Facility address:	140 58TH ST BROOKLYN, NY 11220
EPA ID:	NYD987029550
Mailing address:	58TH ST BROOKLYN, NY 11220
Contact:	EDUARDO FIALLO
Contact address:	58TH ST BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(718) 754-5228
Contact email:	EDUARDO.FIALLO@MORGANSTANLEY.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY ECONOMIC DEV CORP
Owner/operator address:	110 WILLIAM ST NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	(212) 619-5000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MORGAN STANLEY & CO INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/01/2009
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY ECONOMIC DEV CORP

MORGAN STANLEY & CO INC (Continued) **1000833530**

Owner/operator address: 110 WILLIAM ST
NEW YORK, NY 10038
Owner/operator country: US
Owner/operator telephone: (212) 619-5000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MORGAN STANLEY & CO INC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/01/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: MORGAN STANLEY & CO INC
Site name: SMITH BARNEY HARRIS UPHAM INC
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Facility name: MORGAN STANLEY & CO INC
Site name: SMITH BARNEY HARRIS UPHAM INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/05/1996
Facility name: MORGAN STANLEY & CO INC
Site name: SMITH BARNEY
Classification: Large Quantity Generator

Date form received by agency: 03/08/1993
Facility name: MORGAN STANLEY & CO INC
Site name: SMITH BARNEY HARRIS UPHAM INC
Classification: Small Quantity Generator

MORGAN STANLEY & CO INC (Continued) **1000833530**

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

E49 **SB GRAPHICS CORP-140 58TH ST** **FINDS** **1006765673**
NNE **140 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.050 mi.
264 ft. **Site 26 of 28 in cluster E**

Relative: Higher

Actual: 26 ft.

FINDS:

Registry ID: 110013338637

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E50
NNE
< 1/8
0.050 mi.
264 ft.

EB DESIGNS
140 58TH STREET
BROOKLYN, NY 11220

Site 27 of 28 in cluster E

FINDS **1006765672**
N/A

Relative: Higher

Actual: 26 ft.

FINDS:

Registry ID: 110013338628

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

D51
NE
< 1/8
0.050 mi.
266 ft.

B NO 57 CORP - 57TH ST PIER
5802 FIRST AVE
BROOKLYN, NY 11220

Site 7 of 8 in cluster D

FINDS **1007808880**
N/A

Relative: Higher

Actual: 22 ft.

FINDS:

Registry ID: 110019714175

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

E52
NNE
< 1/8
0.051 mi.
269 ft.

AMERICAN IDENT PRODS INC
145 58TH ST
BROOKLYN, NY 11220

Site 28 of 28 in cluster E

RCRA-NonGen **1000358700**
FINDS **NYD059178079**
MANIFEST

Relative: Higher

Actual: 26 ft.

RCRA-NonGen:

Date form received by agency: 01/01/2007
Facility name: AMERICAN IDENT PRODS INC
Facility address: 145 58TH ST
BROOKLYN, NY 112202515
EPA ID: NYD059178079
Mailing address: 58TH ST
BROOKLYN, NY 11220

AMERICAN IDENT PRODS INC (Continued) **1000358700**

Contact: Not reported
Contact address: 58TH ST
BROOKLYN, NY 11220
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: *
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: *
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: AMERICAN IDENT PRODS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: AMERICAN IDENT PRODS INC

AMERICAN IDENT PRODS INC (Continued) **1000358700**

Classification: Not a generator, verified

Date form received by agency: 05/07/1992
Facility name: AMERICAN IDENT PRODS INC
Site name: AMERICAN IDENT PRODS
Classification: Large Quantity Generator

Date form received by agency: 08/31/1988
Facility name: AMERICAN IDENT PRODS INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 10/28/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004361707

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD059178079
Country: USA
Mailing Name: AMERICAN IDENTIFICATION PRODUCTS INC
Mailing Contact: N/S
Mailing Address: 145 58TH ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip4: 2515
Mailing Country: USA
Mailing Phone: 718-492-3400

Document ID: NJA1900904
Manifest Status: Completed copy
Trans1 State ID: 2809
Trans2 State ID: Not reported
Generator Ship Date: 950606
Trans1 Recv Date: 950606
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950606
Part A Recv Date: 950627

AMERICAN IDENT PRODS INC (Continued) **1000358700**

Part B Recv Date:	950616
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	NJD002454544
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	95

Document ID:	NYG1676196
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/1999
Trans1 Recv Date:	09/09/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/27/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	FLD980559728
Trans2 EPA ID:	Not reported
TSDF ID:	PC4340NY
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	09520
Units:	P - Pounds
Number of Containers:	028
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NJA1097510
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGX6293
Trans2 State ID:	NJDEPS103
Generator Ship Date:	901120
Trans1 Recv Date:	901120
Trans2 Recv Date:	901121
TSD Site Recv Date:	901121
Part A Recv Date:	910411
Part B Recv Date:	910109
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	NYD000691949
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005

AMERICAN IDENT PRODS INC (Continued) **1000358700**

Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYG1445022
Manifest Status:	Not reported
Trans1 State ID:	FLD980559728
Trans2 State ID:	NYD049178296
Generator Ship Date:	09/20/1999
Trans1 Recv Date:	09/20/1999
Trans2 Recv Date:	09/20/1999
TSD Site Recv Date:	09/24/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	GAD093380814
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	F005 - UNKNOWN
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYG1445697
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	FLD980551728
Generator Ship Date:	07/07/1999
Trans1 Recv Date:	07/08/1999
Trans2 Recv Date:	07/13/1999
TSD Site Recv Date:	07/19/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	FLD980559728
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

AMERICAN IDENT PRODS INC (Continued) **1000358700**

Specific Gravity:	01.00
Year:	99
Document ID:	NYB1582362
Manifest Status:	Completed copy
Trans1 State ID:	NJXK18WY
Trans2 State ID:	NYGX6293
Generator Ship Date:	910705
Trans1 Recv Date:	910705
Trans2 Recv Date:	910705
TSD Site Recv Date:	910708
Part A Recv Date:	910718
Part B Recv Date:	910717
Generator EPA ID:	NYD059178079
Trans1 EPA ID:	NYD000691949
Trans2 EPA ID:	NYD000691949
TSDF ID:	NYD000691949
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00715
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	013
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	91

A53 **MARINE OCEAN TERMINAL** **FINDS** **1007123443**
NE **58TH ST & 2ND AVE** **N/A**
< 1/8 **BROOKLYN, NY 11222**
0.052 mi.
274 ft. **Site 4 of 5 in cluster A**

Relative:
Higher

Actual:
34 ft.

FINDS:

Registry ID: 110015740313

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

A54 **NAB CONSTRUCTION RAILROAD** **RCRA-NonGen** **1000108432**
NE **58TH ST & 2ND AVE** **FINDS** **NYD981872450**
< 1/8 **BROOKLYN, NY 11220**
0.052 mi.
274 ft. **Site 5 of 5 in cluster A**

Relative:
Higher

Actual:
34 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NAB CONSTRUCTION RAILROAD
Facility address:	58TH ST & 2ND AVE BROOKLYN, NY 11220

NAB CONSTRUCTION RAILROAD (Continued) **1000108432**

EPA ID: NYD981872450
Contact: Not reported
Contact address: 58TH ST & 2ND AVE
BROOKLYN, NY 11220
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LARRY LEVAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LARRY LEVAN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NAB CONSTRUCTION RAILROAD
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NAB CONSTRUCTION RAILROAD

NAB CONSTRUCTION RAILROAD (Continued) **1000108432**

Classification: Not a generator, verified

Date form received by agency: 01/06/1987
Facility name: NAB CONSTRUCTION RAILROAD
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008023478

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

D55 **MANHOLE 51791** **NY Spills** **S107409379**
North **129 58 STREET - ON SIDEWALK** **N/A**
< 1/8 **BROOKLYN, NY**
0.058 mi.
308 ft. **Site 8 of 8 in cluster D**

Relative:
Higher

Actual:
25 ft.

NY Spills:

Site ID:	353474
Facility Addr2:	Not reported
Facility ID:	0507968
Spill Number:	0507968
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	10/3/2005
Reported to Dept:	10/4/2005
CID:	41
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/1/2005
Remediation Phase:	0
Date Entered In Computer:	10/4/2005
Spill Record Last Update:	12/1/2005
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10001

MANHOLE 51791 (Continued) **S107409379**

Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	300811
DEC Memo:	161344. 10/3/05 - 1354hrs - Charles Lugo # 03594 Mech A Env. Ops reports while on routine flush using acct # 44562 found 1 pt unknown oil on 200 gallons water in MH51791. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample taken marked E priority - chain of custody # DD19535 - 72 hr program. Env. stop tag # 49474 placed. Clean up pending test results. cn#19661 Lab Sequence Number: 05-10348-001 Date < 1.0 ppm UPDATE 10/4/05 01:00 HRS ENV OPS HUFFORD REPORTS FINDING AN EARTHEN SUMP, THE CLEAN UP IS IN PROGRESS, AND THE SUMP WILL BE SEALED. J ANDERSON UPDATE 1/4/05 01:02 HRS CIG C. HAYNES NOTIFIED OF REMOVAL FROM 72 HOUR PROGRAM. Closed. 12-1-05. see eDocs. GB
Remarks:	1 pint on 200 gals water - ref #161344

Material:

Site ID:	353474
Operable Unit ID:	1110933
Operable Unit:	01
Material ID:	2100974
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

F56 **86-19 SHORE ROAD** **NY Spills** **S104495391**
SW **86-19 SHORE ROAD** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.063 mi.
331 ft. **Site 1 of 3 in cluster F**

Relative:
Higher

Actual:
30 ft.

NY Spills:

Site ID:	221339
Facility Addr2:	Not reported
Facility ID:	9209069
Spill Number:	9209069
Facility Type:	ER

86-19 SHORE ROAD (Continued) **S104495391**

SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Spill Date:	11/5/1992
Reported to Dept:	11/5/1992
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	11/5/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/5/1992
Remediation Phase:	0
Date Entered In Computer:	11/10/1992
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	183058
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"
Remarks:	HOSO SPLIT-CONTAINED ON PAVEMENT-CREW IN SCENE FOR CLEANUP

Material:

Site ID:	221339
Operable Unit ID:	972721
Operable Unit:	01
Material ID:	406134
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported

86-19 SHORE ROAD (Continued) **S104495391**

Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9209069
Investigator: TANG
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/05/1992 11:50
Reported to Dept Date/Time: 11/05/92 13:01
SWIS: 61
Spiller Name: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 08
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: 11/05/92
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/05/92
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/10/92
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 4

86-19 SHORE ROAD (Continued) **S104495391**

Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Remark: HOSO SPLIT-CONTAINED ON PAVEMENT-CREW IN SCENE FOR CLEANUP

57
SW
< 1/8
0.077 mi.
408 ft.

Relative:
Higher

Actual:
54 ft.

6647 BERGEN REALTY LLC **UST** **U004046131**
6647 BERGEN PLACE **N/A**
BROOKLYN, NY 11220

UST:
Facility Id: 2-608251
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2013/02/12
UTM X: 582186.45481000002
UTM Y: 4499189.9924999997

Affiliation Records:
Site Id: 30103
Affiliation Type: On-Site Operator
Company Name: BERGEN REALTY
Contact Type: Not reported
Contact Name: EDUARDO AREVALO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 748-7538
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30103
Affiliation Type: Mail Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: GEORGE POULAKAKOS
Address1: 186 80TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001

6647 BERGEN REALTY LLC (Continued) **U004046131**

Phone:	(718) 680-0689
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2/4/2008

Site Id:	30103
Affiliation Type:	Owner
Company Name:	GEORGE POULAKAKOS
Contact Type:	PRESIDENT
Contact Name:	DESPINA POULAKAKOS
Address1:	186 80TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11209
Country Code:	001
Phone:	(718) 680-0689
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2/4/2008

Site Id:	30103
Affiliation Type:	Emergency Contact
Company Name:	GEORGE POULAKAKOS
Contact Type:	Not reported
Contact Name:	DESPINA POULAKAKOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 836-5000
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None

Tank Info:

6647 BERGEN REALTY LLC (Continued) **U004046131**

Site ID: 30103

Tank Number: 001
Tank ID: 64954
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 4/1/1970
Capacity Gallons: 1500
Tightness Test Method: 21
Next Test Date: 12/13/2012
Date Tank Closed: Not reported
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 12/13/2007
Register: True
Modified By: dxliving
Last Modified: 2/4/2008

G58 **C M AUTOBODY SHOP** **FINDS** **1007784566**
East **239 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.082 mi.
435 ft. **Site 1 of 4 in cluster G**

Relative:
Higher

FINDS:

Registry ID: 110019470384

Actual:
44 ft.

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

H59 **BAYRIDGE AIR RIGHTS 260** **FINDS** **1007820089**
SE **260 65TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.086 mi.
452 ft. **Site 1 of 4 in cluster H**

Relative:
Higher

FINDS:

Registry ID: 110019826483

Actual:
41 ft.

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V

BAYRIDGE AIR RIGHTS 260 (Continued) **1007820089**

of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

H60 **VAULT 5078** **NY Spills** **S104953706**
SE **260 65TH ST** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.086 mi.
452 ft. **Site 2 of 4 in cluster H**

Relative:
Higher

Actual:
41 ft.

NY Spills:

Site ID:	150764
Facility Addr2:	Not reported
Facility ID:	0013587
Spill Number:	0013587
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	3/28/2001
Reported to Dept:	3/28/2001
CID:	382
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/17/2001
Remediation Phase:	0
Date Entered In Computer:	3/28/2001
Spill Record Last Update:	11/25/2002
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Company:	001
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	128164
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" 3/28/01 Met with Ron Cosentino (B/Q EH&S). 300gal transformer oil spilled in vault 5078. Sump pump found not connected. Opened drain and found oil. 245gal estimated as released to sewer. Transformer found to be leaking from bottom. WIll be replaced tomorrow. Partial cleanup will be completed today. Estimated 90gal in transformer, sump and dirt.(KMF)
Remarks:	CAUSED BY TRANSFORMER LEAK THAT HAS 335 GAL CAPACITY - EST 300 GALS MISSING FROM TRANSFORMER - ONLY 20 GALS IN VAULT. SUMP PUMP

VAULT 5078 (Continued) **S104953706**

DISCONNECTED AND FOUND TRACES OF OIL. PCB HX 16 PPM. SAMPLE TAKEN. CLEAN UP CREWS ENROUTE TO LOCATION. DISCOVERY OF SEWER ENTRY @1209 HRS.

Material:

Site ID:	150764
Operable Unit ID:	835066
Operable Unit:	01
Material ID:	540296
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0013587
Investigator:	FOLEY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/28/2001 11:15
Reported to Dept Date/Time:	03/28/01 12:29
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	CALLER
Spiller Phone:	(212) 580-6763
Spiller Contact:	BILL MURPHY
Spiller Phone:	(212) 580-6763
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spill Cause:	Equipment Failure
Reported to Dept:	In Sewer
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party

VAULT 5078 (Continued) **S104953706**

PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/17/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/28/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/17/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 300
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: CAUSED BY TRANSFORMER LEAK THAT HAS 335 GAL CAPACITY - EST 300 GALS MISSING FROM TRANSFORMER - ONLY 20 GALS IN VAULT. SUMP PUMP DISCONNECTED AND FOUND TRACES OF OIL. PCB HX 16 PPM. SAMPLE TAKEN. CLEAN UP CREWS ENROUTE TO LOCATION. DISCOVERY OF SEWERENTRY @1209 HRS.

H61 **INFRONT OF 260 65TH ST** **ERNS 2001560975**
SE **INFRONT OF 260 65TH ST** **N/A**
< 1/8 **BROOKLYN, NY 0**
0.086 mi.
452 ft. **Site 3 of 4 in cluster H**

Relative:
Higher

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
41 ft.

H62 **BAYRIDGE AIR RIGHTS** **UST** **U001836350**
SE **260 65TH STREET** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.086 mi.
452 ft. **Site 4 of 4 in cluster H**

Relative:
Higher

Actual:
41 ft.

UST:

Facility Id:	2-266795
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2012/08/17
UTM X:	582484.24341999996
UTM Y:	4499237.5242299996

Affiliation Records:

Site Id:	11043
Affiliation Type:	Owner
Company Name:	BAY RIDGE AIR RIGHTS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	260/350 65TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 492-5300
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/26/2009

Site Id:	11043
Affiliation Type:	Mail Contact
Company Name:	BAY RIDGE AIR RIGHTS
Contact Type:	Not reported
Contact Name:	BENJAMIN HAWKINS
Address1:	% COOPER SQUARE REALTY
Address2:	6 EAST 43RD ST., 14TH FL
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 634-8988
Phone Ext:	Not reported
Email:	BEN.HAWKINS@COOPERSQUARE.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/26/2009

Site Id:	11043
Affiliation Type:	Emergency Contact
Company Name:	BAY RIDGE AIR RIGHTS
Contact Type:	Not reported
Contact Name:	ANGEL VALLE/SUPERINTENDENT
Address1:	Not reported
Address2:	Not reported

BAYRIDGE AIR RIGHTS (Continued) **U001836350**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 533-9091
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	8/9/2007

Site Id:	11043
Affiliation Type:	On-Site Operator
Company Name:	BAYRIDGE AIR RIGHTS
Contact Type:	Not reported
Contact Name:	ANGEL VALLE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-5300
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	8/9/2007

Equipment Records:

H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Info:

Site ID:	11043

Tank Number:	001
Tank ID:	18210
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1970
Capacity Gallons:	9000
Tightness Test Method:	NN
Next Test Date:	12/27/1987
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported

BAYRIDGE AIR RIGHTS (Continued) **U001836350**

Register:	True
Modified By:	NRLOMBAR
Last Modified:	5/26/2009

HIST UST:

PBS Number:	2-266795
SPDES Number:	Not reported
Emergency Contact:	STEVE OKROS
Emergency Telephone:	(718) 764-9345
Operator:	STEVE OKROS
Operator Telephone:	(212) 492-5300
Owner Name:	BAYRIDGE AIR RIGHTS
Owner Address:	260 65TH ST
Owner City,St,Zip:	BKLYN, NY 11220
Owner Telephone:	(212) 492-5300
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	BAYRIDGE AIR RIGHTS
Mailing Address:	260 65TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BKLYN, NY 11220
Mailing Contact:	PETER PANTELIDIS
Mailing Telephone:	(212) 492-5300
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	260 65TH ST
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	08/15/1997
Expiration Date:	08/17/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	9000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19701201
Capacity (gals):	9000

BAYRIDGE AIR RIGHTS (Continued) **U001836350**

Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Diking
Leak Detection:	Other
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

I63 **201 64TH STREET CO.** **HIST UST** **U002034288**
SE **201 64TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.087 mi.
459 ft. **Site 1 of 5 in cluster I**

Relative:
Higher

Actual:
47 ft.

HIST UST:

PBS Number:	2-601946
SPDES Number:	Not reported
Emergency Contact:	BOB POSSES
Emergency Telephone:	(718) 748-0068
Operator:	ANDREW HOCHMAN
Operator Telephone:	(718) 748-0068
Owner Name:	201 64TH STREET CO.
Owner Address:	201 64TH STREET
Owner City,St,Zip:	BROOKLYN, NY 11220
Owner Telephone:	(718) 748-0068
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	201 64TH STREET CO.
Mailing Address:	201 64TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	ANDREW HOCHMAN
Mailing Telephone:	(718) 748-0068
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	UTILITY
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False

201 64TH STREET CO. (Continued) **U002034288**

Certification Date:	Not reported
Expiration Date:	08/23/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None

201 64TH STREET CO. (Continued) **U002034288**

Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction

201 64TH STREET CO. (Continued) **U002034288**

Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data

201 64TH STREET CO. (Continued) **U002034288**

Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	008
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False

201 64TH STREET CO. (Continued) **U002034288**

Updated:	True
Lat/long:	Not reported

Tank Id:	009
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

I64 **A1 1ST CLASS MOVING &** **NY Spills** **S102560171**
SE **201 64TH STREET** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.087 mi.
459 ft. **Site 2 of 5 in cluster I**

Relative:
Higher

Actual:
47 ft.

NY Spills:

Site ID:	312560
Facility Addr2:	Not reported
Facility ID:	9612531
Spill Number:	9612531
Facility Type:	ER
SWIS:	2401
Investigator:	JLDYBER
Referred To:	Not reported
Spill Date:	1/13/1997
Reported to Dept:	1/21/1997
CID:	297
Spill Cause:	Housekeeping
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response.

A1 1ST CLASS MOVING & (Continued) **S102560171**

	Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/12/2006
Remediation Phase:	0
Date Entered In Computer:	1/21/1997
Spill Record Last Update:	1/12/2006
Spiller Name:	MIKE LABY
Spiller Company:	A1 FIRST CLASS MOVING &
Spiller Address:	STORAGE-201 64TH ST
Spiller City,St,Zip:	BROOKLYN, NY 11220-
Spiller Company:	001
Contact Name:	MIKE LABY
Contact Phone:	(718) 748-0050
DEC Region:	2
DER Facility ID:	65421
DEC Memo:	1/12/05, Dyber: Reviewed report from F&N. No further action needed. 11/8-11/9/05, Dyber: Oversaw removal of 3 USTs at site. 8/31/05, Dyber: David Oloke committed to begin field work by October 3. He will notify me of field work by September 26. 8/12/05, Dyber: Received Subsurface Investigation Report from F&N and reviewed. 8/11/05, Dyber: Spoke with David Oloke. He said he sent the Phase 2 and will send the Phase 1. 8/3/05, Dyber: Mike Laby called. He said that he sold the property in January 2005 and has no records of cleanup past April 18, 1997. 7/28/05, Dyber: David Oloke from Fenley & Nicol called, representing a prospective buyer. His firm may clean up spill. I faxed him the two most recent letters. He will get back to me and send me a copy of the current Phase 1 ESA when it is finalized. 7/26/05, Dyber: Matt Boeckel indicated that his company will not be working on this spill. I left a message for Mike Laby at the spill site (718) 748-0050. 7/22/05, Dyber: Spoke with Matt Boeckel, who said he could not find file on the spill. I faxed him the last two letters in file. He will read them, contact his client, and get back to me. 7/13/05: Spoke with Matt Boeckel. He has not contacted his client and will check to see if he has file. 6/30/05: Matt Boeckel will talk with his client to determine if he will do the work in our 4/97 letter. Call him on 7/13/05 at 800-842-5073.
Remarks:	CALLER RECIEVED RESULTS FROM A PHASE 1 ENVIROMENTAL SITE ASSESSMENT - SPILL WILL BE REMEDIATED TOMMORROW USING A VAC TRUCK - CONTAMINATION FOUND IN A DRY WELL

Material:

Site ID:	312560
Operable Unit ID:	1040363
Operable Unit:	01
Material ID:	341174
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported

A1 1ST CLASS MOVING & (Continued) **S102560171**

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9612531
Investigator: O'DOWD
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/13/1997 12:00
Reported to Dept Date/Time: 01/21/97 14:21
SWIS: 61
Spiller Name: A1 FIRST CLASS MOVING &
Spiller Contact: MIKE LABY
Spiller Phone: (718) 748-0050
Spiller Contact: MIKE LABY
Spiller Phone: (718) 748-0050
Spiller Address: STORAGE-201 64TH ST
Spiller City,St,Zip: BROOKLYN, NY 11220-
Spill Cause: Housekeeping
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/21/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/22/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported

A1 1ST CLASS MOVING & (Continued) **S102560171**

Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: CALLER RECIEVED RESULTS FROM A PHASE 1 ENVIROMENTAL SITE ASSESSMENT - SPILL WILL BE REMEDIATED TOMMORROW USING A VAC TRUCK - CONTAMINATION FOUND IN A DRY WELL

I65 **201 64TH STREET CO** **RCRA-NonGen** **1004755863**
SE **201 64TH ST** **FINDS** **NY0000588400**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.087 mi.
459 ft. **Site 3 of 5 in cluster I**

Relative:
Higher

Actual:
47 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: 201 64TH STREET CO
Facility address: 201 64TH ST
BROOKLYN, NY 11220
EPA ID: NY0000588400
Mailing address: 64TH ST
BROOKLYN, NY 11220
Contact: ROBERT POSSES
Contact address: 64TH ST
BROOKLYN, NY 11220
Contact country: US
Contact telephone: (718) 748-5506
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: 201 64TH STREET CO
Owner/operator address: 201 64TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 748-5506
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: 201 64TH STREET CO

201 64TH STREET CO (Continued) **1004755863**

Owner/operator address: 201 64TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 748-5506
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: 201 64TH STREET CO
Classification: Not a generator, verified

Date form received by agency: 08/12/1994
Facility name: 201 64TH STREET CO
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110029208391

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NY0000588400
Country: USA
Mailing Name: 201 64 ST CO
Mailing Contact: JULIE FIGUEROA
Mailing Address: 201 64 ST

201 64TH STREET CO (Continued) **1004755863**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-748-5506

Document ID:	NJA1895628
Manifest Status:	Completed copy
Trans1 State ID:	S50078
Trans2 State ID:	Not reported
Generator Ship Date:	940909
Trans1 Recv Date:	940912
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940912
Part A Recv Date:	Not reported
Part B Recv Date:	940922
Generator EPA ID:	NY0000588400
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

I66 **BROOKLYN ARSENAL** **NY Spills** **S105141877**
SE **201 64TH STREET** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.087 mi.
459 ft. **Site 4 of 5 in cluster I**

Relative:
Higher

Actual:
47 ft.

NY Spills:

Site ID:	68725
Facility Addr2:	Not reported
Facility ID:	0130024
Spill Number:	0130024
Facility Type:	ER
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Spill Date:	8/28/2001
Reported to Dept:	8/28/2001
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended

BROOKLYN ARSENAL (Continued) **S105141877**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/28/2001
Remediation Phase:	0
Date Entered In Computer:	8/28/2001
Spill Record Last Update:	3/11/2003
Spiller Name:	JULIE FIGUEROA
Spiller Company:	BROOKLYN ARSENAL
Spiller Address:	201 64TH STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	JULIE FIGUEROA
Contact Phone:	(718) 748-5506
DEC Region:	2
DER Facility ID:	65421
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"
Remarks:	SOIL CONTAMINATION ENCOUNTERED DURING TANK REMOVAL. SOIL REMOVED. POST EX SAMPLES SHOW MINOR CONTAMINATION.

Material:

Site ID:	68725
Operable Unit ID:	849567
Operable Unit:	01
Material ID:	526713
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0130024
Investigator:	TIBBE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported

BROOKLYN ARSENAL (Continued) **S105141877**

Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	08/28/2001 12:42
Reported to Dept Date/Time:	08/28/01 12:42
SWIS:	61
Spiller Name:	BROOLYN ARSENAL
Spiller Contact:	JULIE FIGUEROA
Spiller Phone:	(718) 748-5506
Spiller Contact:	JULIE FIGUEROA
Spiller Phone:	(718) 748-5506
Spiller Address:	201 64TH STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	DEC
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	08/28/01
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	08/28/01
Date Spill Entered In Computer Data File:	12:49
Update Date:	08/28/01
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	True
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	True
Material:	#2 FUEL OIL
Class Type:	#2 FUEL OIL
Times Material Entry In File:	24464
CAS Number:	Not reported
Last Date:	19941207
DEC Remarks:	Not reported
Remark:	SOIL CONTAMINATION ENCOUNTERED DURING TANK REMOVAL. SOIL REMOVED. POST EX SAMPLES SHOW MINOR CONTAMINATION.

I67 **LIFE QUALITY MOTOR GROUP** **TANKS** **S110771979**
SE **201 64TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.087 mi.
459 ft. **Site 5 of 5 in cluster I**

Relative:
Higher

Actual:
47 ft.

TANKS:

Facility Id:	2-601946
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582434.01344999997
UTM Y:	4499364.1642500004

J68 **GALLAGHER SWITCH BOARD CORP** **FINDS** **1007758214**
NE **5718 SECOND AVE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.091 mi.
482 ft. **Site 1 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110019206269

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

G69 **249 58TH STREET** **NY Spills** **S102147581**
East **249 58TH STREET** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.093 mi.
493 ft. **Site 2 of 4 in cluster G**

Relative:
Higher

Actual:
47 ft.

NY Spills:

Site ID:	306351
Facility Addr2:	Not reported
Facility ID:	9312247
Spill Number:	9312247
Facility Type:	ER
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Spill Date:	1/18/1994
Reported to Dept:	1/18/1994
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended

249 58TH STREET (Continued) **S102147581**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/11/2003
Remediation Phase:	0
Date Entered In Computer:	1/19/1994
Spill Record Last Update:	2/11/2003
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, ZZ
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	247430
DEC Memo:	Not reported
Remarks:	FD IS THERE - HAZMAT IS RESPONDING.

Material:

Site ID:	306351
Operable Unit ID:	990870
Operable Unit:	01
Material ID:	556915
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9312247
Investigator:	SULLIVAN
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported

249 58TH STREET (Continued) **S102147581**

Spill Date/Time: 01/18/1994 12:30
Reported to Dept Date/Time: 01/18/94 12:39
SWIS: 61
Spiller Name: UNK
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Federal Government
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/19/94
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: FD IS THERE - HAZMAT IS RESPONDING.

K70 **5705 FIRST AVENUE OWNER REALTY** **UST** **U002034272**
NE **5705 FIRST AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.098 mi.
519 ft. **Site 1 of 9 in cluster K**

Relative:
Higher

Actual:
23 ft.

UST:

Facility Id:	2-601930
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582588.16000999999
UTM Y:	4499952.5029699998

Affiliation Records:

Site Id:	23892
Affiliation Type:	Emergency Contact
Company Name:	CHRIS FOUNTOUKIS
Contact Type:	Not reported
Contact Name:	CHRIS FOUNTOUKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 745-2923
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23892
Affiliation Type:	Mail Contact
Company Name:	CHRIS FOUNTOUKIS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	146 MAJOR AVENUE
Address2:	Not reported
City:	STATEN ISLAND
State:	NY
Zip Code:	10305
Country Code:	001
Phone:	(718) 816-3047
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23892
Affiliation Type:	Owner
Company Name:	CHRIS FOUNTOUKIS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	146 MAJOR AVENUE
Address2:	Not reported

5705 FIRST AVENUE OWNER REALTY (Continued) **U002034272**

City:	STATEN ISLAND
State:	NY
Zip Code:	10305
Country Code:	001
Phone:	(718) 816-3047
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23892
Affiliation Type:	On-Site Operator
Company Name:	5705 FIRST AVENUE OWNER REALTY
Contact Type:	Not reported
Contact Name:	BAY WELDING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 745-2923
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Info:

Site ID:	23892

Tank Number:	001
Tank ID:	48356
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1000

5705 FIRST AVENUE OWNER REALTY (Continued) **U002034272**

Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	23892
Tank Number:	002
Tank ID:	48357
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-601930
SPDES Number:	Not reported
Emergency Contact:	CHRIS FOUNTOUKIS
Emergency Telephone:	(718) 745-2923
Operator:	BAY WELDING
Operator Telephone:	(718) 745-2923
Owner Name:	CHRIS FOUNTOUKIS
Owner Address:	146 MAJOR AVENUE
Owner City,St,Zip:	STATEN ISLAND, NY 10305
Owner Telephone:	(718) 816-3047
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	CHRIS FOUNTOUKIS
Mailing Address:	146 MAJOR AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STATEN ISLAND, NY 10305
Mailing Contact:	Not reported
Mailing Telephone:	(718) 816-3047
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	TRUCKING/TRANSPORTATION
Inspected Date:	Not reported
Inspector:	Not reported

5705 FIRST AVENUE OWNER REALTY (Continued) **U002034272**

Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	08/03/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	04/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON

5705 FIRST AVENUE OWNER REALTY (Continued) **U002034272**

Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	04/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

L71 **6623 REALTY ASSOC** **AST** **U003392029**
SSW **6623 RIDGE BLVD** **HIST AST** **N/A**
< 1/8 **BKLYN, NY 11220**
0.099 mi.
522 ft. **Site 1 of 6 in cluster L**

Relative:
Higher

Actual:
61 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-405795
Program Type:	PBS
UTM X:	582277.66319999995
UTM Y:	4499156.8678299999
Expiration Date:	2012/10/15

Affiliation Records:

Site Id:	19577
Affiliation Type:	On-Site Operator
Company Name:	6623 REALTY ASSOC
Contact Type:	Not reported
Contact Name:	DIEGO BETANCOURT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-9384
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	8/17/2007

Site Id:	19577
Affiliation Type:	Emergency Contact
Company Name:	6623 REALTY ASSOC
Contact Type:	Not reported
Contact Name:	BETTY HOCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported

6623 REALTY ASSOC (Continued) **U003392029**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 851-9384
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19577
Affiliation Type: Owner
Company Name: 6623 REALTY ASSOC
Contact Type: AGENT
Contact Name: DAVID HOCH
Address1: POB 190-525
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11219-0011
Country Code: 001
Phone: (718) 851-9384
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 8/17/2007

Site Id: 19577
Affiliation Type: Mail Contact
Company Name: 6623 REALTY ASSOC
Contact Type: Not reported
Contact Name: Not reported
Address1: POB 190-525
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11219-0011
Country Code: 001
Phone: (718) 851-9384
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 12/16/2004

Equipment Records:

J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

6623 REALTY ASSOC (Continued) **U003392029**

Tank Info:

Tank Number:	001
Tank Id:	23130
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	10/15/1983
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KAKYER
Last Modified:	8/17/2007

HIST AST:

PBS Number:	2-405795
SWIS Code:	6101
Operator:	CHARLES GARWUILD
Facility Phone:	(718) 851-9384
Facility Addr2:	6623 RIDGE BLVD
Facility Type:	APARTMENT BUILDING
Emergency:	BETTY HOCH
Emergency Tel:	(718) 851-9384
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	6623 REALTY ASSOC
Owner Address:	POB 190-525
Owner City,St,Zip:	BKLYN, NY 11219-0011
Federal ID:	Not reported
Owner Tel:	(718) 851-9384
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	6623 REALTY ASSOC
Mailing Address:	POB 190-525
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BKLYN, NY 11219-0011
Mailing Telephone:	(718) 851-9384
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	10/07/1997
Expiration:	10/15/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	4000
FAMT:	True

6623 REALTY ASSOC (Continued) **U003392029**

Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	4000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

J72 **ILANA ENTERPRISES ICN** **UST** **U001837856**
NE **5702 SECOND AVE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.099 mi.
523 ft. **Site 2 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

UST:

Facility Id:	2-405876
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582783.82261999999
UTM Y:	4499810.8067300003

Affiliation Records:

Site Id:	19583
Affiliation Type:	Owner
Company Name:	ASTI HOLDING CORP
Contact Type:	Not reported

ILANA ENTERPRISES ICN (Continued) **U001837856**

Contact Name:	Not reported
Address1:	251 LOMBARDY ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 387-7700
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/16/2004

Site Id:	19583
Affiliation Type:	Mail Contact
Company Name:	MESSINA MGMT CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	251 LOMBARDY ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 387-7700
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	19583
Affiliation Type:	Emergency Contact
Company Name:	ASTI HOLDING CORP
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA JR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-7900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	19583
Affiliation Type:	On-Site Operator
Company Name:	ILANA ENTERPRISES ICN
Contact Type:	Not reported
Contact Name:	ILANA ENTERPRISES INC
Address1:	Not reported
Address2:	Not reported

ILANA ENTERPRISES ICN (Continued) **U001837856**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-9714
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
I00 - Overfill - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

ILANA ENTERPRISES ICN (Continued) **U001837856**

F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
C00 - Pipe Location - No Piping
I00 - Overfill - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction

Tank Info:

Site ID:	19583
Tank Number:	001
Tank ID:	23136
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1948
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583

ILANA ENTERPRISES ICN (Continued) **U001837856**

Tank Number:	002
Tank ID:	23137
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1948
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583
Tank Number:	003
Tank ID:	23138
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1948
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583
Tank Number:	004
Tank ID:	23139
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583

ILANA ENTERPRISES ICN (Continued) **U001837856**

Tank Number:	005
Tank ID:	23140
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583
Tank Number:	006
Tank ID:	23141
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583
Tank Number:	007
Tank ID:	23142
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583

ILANA ENTERPRISES ICN (Continued) **U001837856**

Tank Number:	008
Tank ID:	23143
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	3/1/1990
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19583
Tank Number:	009
Tank ID:	23144
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/1956
Capacity Gallons:	275
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-405876
SPDES Number:	Not reported
Emergency Contact:	JOSEPH MACCHIA JR
Emergency Telephone:	(516) 565-9003
Operator:	ILANA ENTERPRISES INC
Operator Telephone:	(718) 439-9714
Owner Name:	ASTI HOLDING CORP
Owner Address:	251 LOMBARDY ST
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Telephone:	(718) 387-7700
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	MESSINA MGMT CORP
Mailing Address:	251 LOMBARDY ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11222
Mailing Contact:	Not reported
Mailing Telephone:	(718) 387-7700
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)

ILANA ENTERPRISES ICN (Continued) **U001837856**

	and Subpart 360-14.
Facility Addr2:	5702 2ND AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/08/1993
Expiration Date:	10/15/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	275
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19480801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19480801

ILANA ENTERPRISES ICN (Continued) **U001837856**

Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19480801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19560801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel

ILANA ENTERPRISES ICN (Continued) **U001837856**

Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19560801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19560801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported

ILANA ENTERPRISES ICN (Continued) **U001837856**

Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19560801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	008
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19560801
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported

ILANA ENTERPRISES ICN (Continued) **U001837856**

Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	009
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19560801
Capacity (gals):	275
Product Stored:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

J73 **MUNOZ AUTO REPAIR INC.** **AST** **A100295184**
NE **5702 2ND AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.099 mi.
523 ft. **Site 3 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609213
Program Type:	PBS
UTM X:	582766.19240000006
UTM Y:	4499827.6738799997
Expiration Date:	2008/08/26

Affiliation Records:

Site Id:	31058

MUNOZ AUTO REPAIR INC. (Continued) **A100295184**

Affiliation Type:	Emergency Contact
Company Name:	WASHINGTON MUNOZ
Contact Type:	Not reported
Contact Name:	FABIAN MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 567-8057
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	5/13/2004

Site Id:	31058
Affiliation Type:	Mail Contact
Company Name:	MUNOZ AUTO REPAIR
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5702 2ND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 507-8297
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	31058
Affiliation Type:	On-Site Operator
Company Name:	MUNOZ AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	WASHINGTON MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 567-8297
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	31058
Affiliation Type:	Owner
Company Name:	WASHINGTON MUNOZ
Contact Type:	Not reported

MUNOZ AUTO REPAIR INC. (Continued) **A100295184**

Contact Name:	Not reported
Address1:	444 53RD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 567-8297
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
J01 - Dispenser - Submersible
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Info:

Tank Number:	1
Tank Id:	66799
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

J74 **ILANA ENTERPRISES LTD** **FINDS** **1004567228**
NE **5701 2ND AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.100 mi.
528 ft. **Site 4 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110001573137

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of

ILANA ENTERPRISES LTD (Continued) **1004567228**

Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

J75 **57 PHAT 2ND SERVICE STATION, INC.** **UST** **U003312816**
NE **5701 SECOND AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.100 mi.
528 ft. **Site 5 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

UST:

Facility Id:	2-402826
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2008/12/03
UTM X:	582785.05353999999
UTM Y:	4499812.1635299996

Affiliation Records:

Site Id:	19310
Affiliation Type:	On-Site Operator
Company Name:	57 PHAT 2ND SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	CHARGANJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 439-6069
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/25/2007

Site Id:	19310
Affiliation Type:	Emergency Contact
Company Name:	57 PHAT 2ND SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	CHARGANJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Zip Code:	Not reported
Country Code:	999
Phone:	(718) 439-6069
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/25/2007

Site Id:	19310
Affiliation Type:	Mail Contact
Company Name:	57 PHAT 2ND SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	MR. CHARGANJIT SINGH
Address1:	5701 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 760-5036
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	19310
Affiliation Type:	Owner
Company Name:	57 PHAT 2ND SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2947 JEROME AVENUE
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	11030
Country Code:	001
Phone:	(718) 760-5036
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	10/25/2007

Equipment Records:

L00 - Piping Leak Detection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
D10 - Pipe Type - Copper
J01 - Dispenser - Submersible
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B02 - Tank External Protection - Original Sacrificial Anode
B04 - Tank External Protection - Fiberglass

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Submersible
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
B07 - Tank External Protection - Retrofitted Sacrificial Anode
D10 - Pipe Type - Copper
G00 - Tank Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
J01 - Dispenser - Submersible
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F00 - Pipe External Protection - None
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
B02 - Tank External Protection - Original Sacrificial Anode
B04 - Tank External Protection - Fiberglass
A01 - Tank Internal Protection - Epoxy Liner
K01 - Spill Prevention - Catch Basin
K01 - Spill Prevention - Catch Basin
B01 - Tank External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Submersible
F07 - Pipe External Protection - Retrofitted Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
J01 - Dispenser - Submersible

Tank Info:

Site ID:	19310
Tank Number:	001
Tank ID:	22882
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1970
Capacity Gallons:	4000

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Tightness Test Method:	21
Next Test Date:	4/28/2009
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	4/28/2004
Register:	True
Modified By:	bkfalvey
Last Modified:	12/12/2007
Site ID:	19310
Tank Number:	002
Tank ID:	22883
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1970
Capacity Gallons:	4000
Tightness Test Method:	21
Next Test Date:	4/28/2009
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	4/28/2004
Register:	True
Modified By:	bkfalvey
Last Modified:	12/12/2007
Site ID:	19310
Tank Number:	003
Tank ID:	22884
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	7/1/1975
Capacity Gallons:	4000
Tightness Test Method:	21
Next Test Date:	4/28/2009
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	4/28/2004
Register:	True
Modified By:	bkfalvey
Last Modified:	12/12/2007
Site ID:	19310
Tank Number:	004
Tank ID:	55570
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1998
Capacity Gallons:	4000

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Tightness Test Method:	00
Next Test Date:	12/1/2008
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Fiberglass coated steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	19310
Tank Number:	005
Tank ID:	55571
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1998
Capacity Gallons:	4000
Tightness Test Method:	00
Next Test Date:	12/1/2008
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Fiberglass coated steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-402826
SPDES Number:	Not reported
Emergency Contact:	CHARGANJIT SINGH
Emergency Telephone:	(718) 760-5036
Operator:	CHARGANJIT SINGH
Operator Telephone:	(718) 439-6069
Owner Name:	57 PAHT 2ND SERVICE STATION, INC.
Owner Address:	2947 JEROME AVENUE
Owner City,St,Zip:	BRONX, NY 00000-0000
Owner Telephone:	(718) 760-5036
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	57 PHAT 2ND SERVICE STATION, INC.
Mailing Address:	5701 SECOND AVENUE
Mailing Address 2:	5701 SECOND AVENUE
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	MR. CHARGANJIT SINGH
Mailing Telephone:	(718) 760-5036
Owner Mark:	Third Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	5701 2ND AVENUE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	Not reported

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/21/1998
Expiration Date:	12/03/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	20000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19701201
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	12
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Sacrificial Anode
Second Containment:	None
Leak Detection:	In-tank System
Overfill Prot:	High Level Alarm, Catch Basin
Dispenser:	Submersible
Date Tested:	06/01/1997
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19701201
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	12
Pipe Location:	Underground

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Sacrificial Anode
Second Containment:	None
Leak Detection:	In-tank System
Overfill Prot:	High Level Alarm, Catch Basin
Dispenser:	Submersible
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19750701
Capacity (gals):	4000
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	12
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Sacrificial Anode
Second Containment:	None
Leak Detection:	In-tank System
Overfill Prot:	High Level Alarm, Catch Basin
Dispenser:	Submersible
Date Tested:	06/01/1997
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19981201
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	24
Pipe Location:	Underground
Pipe Type:	FIBERGLASS COATED STEEL
Pipe Internal:	None
Pipe External:	None

57 PHAT 2ND SERVICE STATION, INC. (Continued) **U003312816**

Second Containment:	Vault (w/access)
Leak Detection:	41
Overfill Prot:	High Level Alarm, Catch Basin
Dispenser:	Submersible
Date Tested:	Not reported
Next Test Date:	12/01/2013
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19981201
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	24
Pipe Location:	Underground
Pipe Type:	FIBERGLASS COATED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	Vault (w/access)
Leak Detection:	41
Overfill Prot:	High Level Alarm, Catch Basin
Dispenser:	Submersible
Date Tested:	Not reported
Next Test Date:	12/01/2013
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

J76 **LIVERPOOL INDUSTRIES INC** **RCRA-NonGen** **1000217350**
NE **162 57TH ST** **FINDS** **NYD001263748**
< 1/8 **BROOKLYN, NY 11220** **UST**
0.101 mi. **HIST UST**
531 ft. **Site 6 of 7 in cluster J** **MANIFEST**

Relative:
Higher

Actual:
32 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	LIVERPOOL INDUSTRIES INC
Facility address:	162 57TH ST BROOKLYN, NY 11220
EPA ID:	NYD001263748
Mailing address:	58TH ST BROOKLYN, NY 11220
Contact:	Not reported
Contact address:	58TH ST BROOKLYN, NY 11220
Contact country:	US

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LIVERPOOL INDUSTRIES INC
Owner/operator address: 162 57TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 492-0770
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LIVERPOOL INDUSTRIES INC
Owner/operator address: 162 57TH ST
BROOKLYN, NY 11220
Owner/operator country: US
Owner/operator telephone: (718) 492-0770
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: LIVERPOOL INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 03/24/1995
Facility name: LIVERPOOL INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 08/04/1980
Facility name: LIVERPOOL INDUSTRIES INC
Classification: Conditionally Exempt Small Quantity Generator

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Violation Status: No violations found

FINDS:

Registry ID: 110004333034

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

UST:

Facility Id:	2-602320
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582747.76032
UTM Y:	4499842.4270500001

Affiliation Records:

Site Id:	24277
Affiliation Type:	Emergency Contact
Company Name:	CHENS MANAGEMENT COMPANY
Contact Type:	Not reported
Contact Name:	GLENN TANZMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-0770
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24277
Affiliation Type:	Owner
Company Name:	CHENS MANAGEMENT COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	162 57TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 439-8969
Phone Ext:	Not reported
Email:	Not reported

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24277
Affiliation Type:	On-Site Operator
Company Name:	CHENS MANAGEMENT COMPANY
Contact Type:	Not reported
Contact Name:	GLENN TANZMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-0770
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	24277
Affiliation Type:	Mail Contact
Company Name:	CHENS MANAGEMENT COMPANY
Contact Type:	Not reported
Contact Name:	BRENDA LEE
Address1:	162 57TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 439-8969
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None

Tank Info:

Site ID:	24277

Tank Number:	001
Tank ID:	49795
Tank Status:	Closed - In Place

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	21
Next Test Date:	Not reported
Date Tank Closed:	6/4/2002
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	3/27/2000
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-602320
SPDES Number:	Not reported
Emergency Contact:	GLENN TANZMAN
Emergency Telephone:	(516) 486-3776
Operator:	GLENN TANZMAN
Operator Telephone:	(718) 492-0770
Owner Name:	REALTY
Owner Address:	60 SHELLBOURNE
Owner City,St,Zip:	MANHASSET HILLS, NY 11030
Owner Telephone:	(516) 437-9435
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	LIVERPOOL INDUSTRIES
Mailing Address:	162 57TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	GLENN TANZMAN
Mailing Telephone:	(718) 492-0770
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	3X1PQ
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/28/2000
Expiration Date:	07/03/2000
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Town or City: NEW YORK CITY
County Code: 61
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Vent Whistle
Dispenser: Suction
Date Tested: 03/27/2000
Next Test Date: 03/27/2005
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: 21
Deleted: False
Updated: True
Lat/long: Not reported

NY MANIFEST:
EPA ID: NYD001263748
Country: USA
Mailing Name: LIVERPOOL INDUSTRIES INC
Mailing Contact: LIVERPOOL INDUSTRIES INC
Mailing Address: 162 57TH STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11220
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-492-0770

Document ID: NJA2800550
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 04/27/1999
Trans1 Recv Date: 04/27/1999
Trans2 Recv Date: 04/29/1999
TSD Site Recv Date: 05/04/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001263748

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Trans1 EPA ID: NJD002182897
Trans2 EPA ID: Not reported
TSDF ID: 08690
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NJA2800593
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 05/25/1999
Trans1 Recv Date: 05/25/1999
Trans2 Recv Date: 05/26/1999
TSD Site Recv Date: 06/02/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001263748
Trans1 EPA ID: NJD002182897
Trans2 EPA ID: Not reported
TSDF ID: 08690
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 99

Document ID: NJA2800734
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: SCD987574647
Generator Ship Date: 08/10/1999
Trans1 Recv Date: 08/10/1999
Trans2 Recv Date: 08/11/1999
TSD Site Recv Date: 08/12/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001263748
Trans1 EPA ID: NJD002182897
Trans2 EPA ID: Not reported
TSDF ID: 08690
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00916
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Specific Gravity: 01.00
Year: 99

Document ID: NJA1838263
Manifest Status: Completed copy
Trans1 State ID: NJDEP0869
Trans2 State ID: 628506292
Generator Ship Date: 950302
Trans1 Recv Date: 950302
Trans2 Recv Date: 950306
TSD Site Recv Date: 950307
Part A Recv Date: 950309
Part B Recv Date: 950320
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ILD984908202
TSDF ID: NJD002182897
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 01374
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYB7969266
Manifest Status: Completed copy
Trans1 State ID: 1374EE
Trans2 State ID: Not reported
Generator Ship Date: 950524
Trans1 Recv Date: 950524
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950524
Part A Recv Date: 950605
Part B Recv Date: 950609
Generator EPA ID: NYD001263748
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00098
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 149
Year: 95

Document ID: NYB6651603
Manifest Status: Completed copy
Trans1 State ID: 1374EE
Trans2 State ID: Not reported
Generator Ship Date: 950302

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Trans1 Recv Date:	950302
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950302
Part A Recv Date:	Not reported
Part B Recv Date:	950321
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	149
Year:	95

Document ID:	NYB7969554
Manifest Status:	Completed copy
Trans1 State ID:	1374EE
Trans2 State ID:	Not reported
Generator Ship Date:	950913
Trans1 Recv Date:	950913
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950913
Part A Recv Date:	950928
Part B Recv Date:	951003
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00019
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	139
Year:	95

Document ID:	NJA2247740
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	951122
Trans1 Recv Date:	951122
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	951129
Part A Recv Date:	951211
Part B Recv Date:	951215
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NYB7969788
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	1374EE
Trans2 State ID:	Not reported
Generator Ship Date:	951108
Trans1 Recv Date:	951108
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	951108
Part A Recv Date:	951117
Part B Recv Date:	960206
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00038
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	95

Document ID:	NJA2085423
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	950907
Trans1 Recv Date:	950907
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950914
Part A Recv Date:	950915
Part B Recv Date:	950929
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	01832
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Document ID:	NYB2093724
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	IA7667
Trans2 State ID:	Not reported
Generator Ship Date:	910515
Trans1 Recv Date:	910515
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910516
Part A Recv Date:	910626
Part B Recv Date:	910530
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	129
Year:	91

Document ID:	NJA2221593
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	0602
Generator Ship Date:	960222
Trans1 Recv Date:	960222
Trans2 Recv Date:	960227
TSD Site Recv Date:	960227
Part A Recv Date:	960229
Part B Recv Date:	960313
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	NYD980769947
TSDF ID:	NJD002182897
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	00916
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	96

Document ID:	SCA1211910
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	911211
Trans1 Recv Date:	911211
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	911219
Part A Recv Date:	920211

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Part B Recv Date: 920309
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: SCD077995488
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00916
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA2221697
Manifest Status: Completed copy
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 960501
Trans1 Recv Date: 960501
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960501
Part A Recv Date: 960509
Part B Recv Date: 960521
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NJA1321308
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920319
Trans1 Recv Date: 920319
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920325
Part A Recv Date: 920327
Part B Recv Date: 920410
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00050
Units: P - Pounds
Number of Containers: 001

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: TXA5678800
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 11581P
Trans2 State ID: Not reported
Generator Ship Date: 921002
Trans1 Recv Date: 921002
Trans2 Recv Date: 921008
TSD Site Recv Date: 921009
Part A Recv Date: Not reported
Part B Recv Date: 921230
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: NYD980769947
TSDF ID: TXD077603371
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92

Document ID: NJA2640850
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 08690
Trans2 State ID: Not reported
Generator Ship Date: 961010
Trans1 Recv Date: 961010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961016
Part A Recv Date: 961023
Part B Recv Date: 961106
Generator EPA ID: NYD001263748
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00458
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NYB5006088
Manifest Status: Completed copy
Trans1 State ID: ET4521

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Trans2 State ID:	Not reported
Generator Ship Date:	920610
Trans1 Recv Date:	920610
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920612
Part A Recv Date:	Not reported
Part B Recv Date:	920624
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00052
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	131
Year:	92

Document ID:	TXA0557880
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	11581P
Trans2 State ID:	Not reported
Generator Ship Date:	921002
Trans1 Recv Date:	921002
Trans2 Recv Date:	921008
TSD Site Recv Date:	921009
Part A Recv Date:	Not reported
Part B Recv Date:	930223
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	NYD980769947
TSDF ID:	TXD077603371
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	92

Document ID:	NJA2662918
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	970630
Trans1 Recv Date:	970630
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970710
Part A Recv Date:	970710
Part B Recv Date:	970804
Generator EPA ID:	NYD001263748
Trans1 EPA ID:	ILD984908202

LIVERPOOL INDUSTRIES INC (Continued) **1000217350**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D005 - BARIUM 100.0 MG/L TCLP
Quantity:	00458
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	97

Click this hyperlink while viewing on your computer to access
14 additional NY_MANIFEST: record(s) in the EDR Site Report.

M77 **PLATINUM TOWING INC** **FINDS** **1007805192**
SE **201-211 62ND ST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.101 mi.
531 ft. **Site 1 of 3 in cluster M**

Relative:
Higher

Actual:
52 ft.

FINDS:

Registry ID: 110019677241

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

M78 **VERRAZANO AUTO COLLISION INC** **RCRA-NonGen** **1000354148**
SE **201 62ND STREET** **FINDS** **NYD095761565**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.101 mi.
531 ft. **Site 2 of 3 in cluster M**

Relative:
Higher

Actual:
52 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	VERRAZANO AUTO COLLISION INC
Facility address:	201 62ND ST BROOKLYN, NY 11220
EPA ID:	NYD095761565
Mailing address:	62ND ST BROOKLYN, NY 11220
Contact:	FRANK FRASCA
Contact address:	62ND ST BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	(718) 492-5100
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	FRANK FRASCA

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FRANK FRASCA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VERRAZANO AUTO COLLISION INC
Classification: Not a generator, verified

Date form received by agency: 03/01/1990
Facility name: VERRAZANO AUTO COLLISION INC
Site name: VERRAZANO AUTO COLLISION INCORPORATED
Classification: Large Quantity Generator

Date form received by agency: 06/20/1988
Facility name: VERRAZANO AUTO COLLISION INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004375836

Environmental Interest/Information System

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD095761565
Country:	USA
Mailing Name:	VERRAZANO AUTO COLLISION INC
Mailing Contact:	VERRAZANO AUTO COLLISION INC
Mailing Address:	201 62ND STREET-ATTN: FRASCA
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-492-5100

Document ID:	NJA0628914
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	890926
Trans1 Recv Date:	890926
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890926
Part A Recv Date:	890929
Part B Recv Date:	891003
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00140
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NYC3162352
Manifest Status:	Completed copy
Trans1 State ID:	DF2839NY
Trans2 State ID:	Not reported
Generator Ship Date:	940726
Trans1 Recv Date:	940726

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940726
Part A Recv Date:	940804
Part B Recv Date:	940803
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NYC3212256
Manifest Status:	Completed copy
Trans1 State ID:	GF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	940823
Trans1 Recv Date:	940823
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940823
Part A Recv Date:	940901
Part B Recv Date:	940901
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NYC3130997
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	940920
Trans1 Recv Date:	940920
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940920
Part A Recv Date:	Not reported
Part B Recv Date:	940929
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Quantity:	00030
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NYC3386283
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	941213
Trans1 Recv Date:	941213
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	941213
Part A Recv Date:	941227
Part B Recv Date:	941221
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

Document ID:	NYC3325950
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	941114
Trans1 Recv Date:	941114
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	941114
Part A Recv Date:	941128
Part B Recv Date:	941123
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Document ID:	NYC3501415
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	950309
Trans1 Recv Date:	950309
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950309
Part A Recv Date:	950322
Part B Recv Date:	950316
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NYC3903131
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	950531
Trans1 Recv Date:	950531
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950531
Part A Recv Date:	950607
Part B Recv Date:	950608
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NYC3450126
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	950207
Trans1 Recv Date:	950207
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950207
Part A Recv Date:	Not reported

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Part B Recv Date:	950215
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	MAK0490320
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/1999
Trans1 Recv Date:	03/19/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	MAD053452637
Trans2 EPA ID:	Not reported
TSDF ID:	P298709IL
Waste Code:	F003 - UNKNOWN
Quantity:	00080
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NJA0840926
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	900103
Trans1 Recv Date:	900103
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900103
Part A Recv Date:	900111
Part B Recv Date:	900112
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NJA1009578
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 900529
Trans1 Recv Date: 900529
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900530
Part A Recv Date: 900726
Part B Recv Date: 900808
Generator EPA ID: NYD095761565
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00240
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NYC3308387
Manifest Status: Completed copy
Trans1 State ID: DF2859NY
Trans2 State ID: Not reported
Generator Ship Date: 941021
Trans1 Recv Date: 941021
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941021
Part A Recv Date: 941104
Part B Recv Date: 941101
Generator EPA ID: NYD095761565
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NYC3413158
Manifest Status: Completed copy
Trans1 State ID: DF2859NY

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Trans2 State ID:	Not reported
Generator Ship Date:	950110
Trans1 Recv Date:	950110
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950110
Part A Recv Date:	950120
Part B Recv Date:	950120
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NYC3578016
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	950626
Trans1 Recv Date:	950626
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950626
Part A Recv Date:	950714
Part B Recv Date:	950705
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980785760
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	NYC3550140
Manifest Status:	Completed copy
Trans1 State ID:	DF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	950405
Trans1 Recv Date:	950405
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950405
Part A Recv Date:	950414
Part B Recv Date:	950414
Generator EPA ID:	NYD095761565
Trans1 EPA ID:	ILD984908202

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYC3865285
Manifest Status: Completed copy
Trans1 State ID: DF2859NY
Trans2 State ID: Not reported
Generator Ship Date: 950504
Trans1 Recv Date: 950504
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950504
Part A Recv Date: 950523
Part B Recv Date: 950511
Generator EPA ID: NYD095761565
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA0950536
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900924
Trans1 Recv Date: 900924
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900925
Part A Recv Date: 901026
Part B Recv Date: 901005
Generator EPA ID: NYD095761565
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100

VERRAZANO AUTO COLLISION INC (Continued) **1000354148**

Year: 90

Document ID: NYC3794995
Manifest Status: Completed copy
Trans1 State ID: JE4550NY
Trans2 State ID: Not reported
Generator Ship Date: 951212
Trans1 Recv Date: 951212
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951212
Part A Recv Date: 960105
Part B Recv Date: 951221
Generator EPA ID: NYD095761565
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYC3720712
Manifest Status: Completed copy
Trans1 State ID: AM6252NY
Trans2 State ID: Not reported
Generator Ship Date: 951020
Trans1 Recv Date: 951020
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951020
Part A Recv Date: 951107
Part B Recv Date: 951031
Generator EPA ID: NYD095761565
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NYD980785760
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Click this hyperlink while viewing on your computer to access
78 additional NY_MANIFEST: record(s) in the EDR Site Report.

F79 **6665 COLONIAL ROAD** **LTANKS** **S108131203**
SW **6665 COLONIAL ROAD** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.101 mi.
532 ft. **Site 2 of 3 in cluster F**

Relative:
Higher

Actual:
35 ft.

LTANKS:

Site ID:	368456
Spill No:	0605319
Spill Date:	8/7/2006
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/16/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	8/7/2006
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/7/2006
Spill Record Last Update:	11/16/2006
Spiller Name:	MARLIN JOSEPH
Spiller Company:	Not reported
Spiller Address:	6665 COLONAL ROAD
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	109
DEC Region:	2
DER Facility ID:	896
Remarks:	ABOVE LIQUID LEAK

Material:

Site ID:	368456
Operable Unit ID:	1126332
Operable Unit:	01
Material ID:	2115864
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

6665 COLONIAL ROAD (Continued) **S108131203**

Tank Test:

Site ID:	368456
Spill Tank Test:	1550185
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	8/7/2006
Test Method:	Horner EZ Check I or II

F80 **COLONIAL PARK COOPERATIVE CORP** **UST** **U003153128**
SW **6665 COLONIAL ROAD** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.101 mi.
532 ft. **Site 3 of 3 in cluster F**

Relative:
Higher

Actual:
35 ft.

UST:

Facility Id:	2-056111
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2011/12/02
UTM X:	582035.56738000002
UTM Y:	4499246.3142900001

Affiliation Records:

Site Id:	896
Affiliation Type:	Owner
Company Name:	COLONIAL PARK COOPERATIVE CORP
Contact Type:	MGR AGENT
Contact Name:	GERALD LEMMERMAN
Address1:	6665 COLONIAL ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 266-1110
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	11/10/2006

Site Id:	896
Affiliation Type:	Mail Contact
Company Name:	% COLONIAL PARK COOPERATIVE CORP
Contact Type:	Not reported
Contact Name:	JAL/DIVERSIFIED MGMT.
Address1:	9437 SHORE ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11209

COLONIAL PARK COOPERATIVE CORP (Continued) **U003153128**

Country Code:	001
Phone:	(718) 745-3500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	896
Affiliation Type:	On-Site Operator
Company Name:	COLONIAL PARK COOPERATIVE CORP
Contact Type:	Not reported
Contact Name:	STEVE LOPEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 238-0329
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	896
Affiliation Type:	Emergency Contact
Company Name:	COLONIAL PARK COOPERATIVE CORP
Contact Type:	Not reported
Contact Name:	JAL MGMT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 745-3500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None

Tank Info:

COLONIAL PARK COOPERATIVE CORP (Continued) **U003153128**

Site ID: 896

Tank Number: 001
Tank ID: 1861
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 5/1/1955
Capacity Gallons: 5000
Tightness Test Method: 21
Next Test Date: 9/1/2011
Date Tank Closed: Not reported
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 9/1/2006
Register: True
Modified By: CGFREEDM
Last Modified: 11/9/2006

HIST UST:
PBS Number: 2-056111
SPDES Number: Not reported
Emergency Contact: JAL MGMT.
Emergency Telephone: (718) 745-3500
Operator: STEVE LOPEZ
Operator Telephone: (718) 238-0329
Owner Name: COLONIAL PARK COOPERATIVE CORP
Owner Address: 6665 COLONIAL ROAD
Owner City,St,Zip: BROOKLYN, NY 11220
Owner Telephone: (718) 266-1110
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: % COLONIAL PARK COOPERATIVE CORP
Mailing Address: 9437 SHORE ROAD
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11209
Mailing Contact: JAL/DIVERSIFIED MGMT.
Mailing Telephone: (718) 745-3500
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 6665 COLONIAL ROAD
SWIS ID: 6101
Old PBS Number: Not reported
Facility Type: APARTMENT BUILDING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 10/26/2001
Expiration Date: 12/02/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 5000
FAMT: True

COLONIAL PARK COOPERATIVE CORP (Continued) **U003153128**

Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19550501
Capacity (gals):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	11/01/1995
Next Test Date:	11/01/2000
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

N81 **W & E BAUM BRONZE TABLET** **FINDS** **1007773207**
SE **200 60TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.101 mi.
535 ft. **Site 1 of 7 in cluster N**

Relative:
Higher

Actual:
56 ft.

FINDS:

Registry ID: 110019356542

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

N82 **SIEGBERT KOHLMAN ENTERPRISES, LTD.** **UST** **U003764770**
SE **200 60TH STREET** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.101 mi.
535 ft. **Site 2 of 7 in cluster N**

Relative:
Higher

Actual:
56 ft.

UST:

Facility Id:	2-604964
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2006/01/08
UTM X:	582631.59426000004
UTM Y:	4499613.8952599997

Affiliation Records:

Site Id:	26833
Affiliation Type:	On-Site Operator
Company Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Contact Type:	Not reported
Contact Name:	BERT KOHLMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7035
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26833
Affiliation Type:	Mail Contact
Company Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Contact Type:	Not reported
Contact Name:	BERT KOHLMAN
Address1:	50 EAST 79TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 734-6247
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26833
Affiliation Type:	Owner
Company Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	200 60TH STREET
Address2:	Not reported

SIEGBERT KOHLMAN ENTERPRISES, LTD. (Continued) **U003764770**

City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(212) 734-6247
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26833
Affiliation Type:	Emergency Contact
Company Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Contact Type:	Not reported
Contact Name:	BERT KOHLMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7035
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
I05 - Overfill - Vent Whistle

Tank Info:

Site ID:	26833

Tank Number:	001
Tank ID:	59260
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	21
Next Test Date:	12/19/2005
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel

SIEGBERT KOHLMAN ENTERPRISES, LTD. (Continued) **U003764770**

Date Test:	12/19/2000
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-604964
SPDES Number:	Not reported
Emergency Contact:	BERT KOHLMAN
Emergency Telephone:	(212) 734-6247
Operator:	BERT KOHLMAN
Operator Telephone:	(718) 492-7035
Owner Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Owner Address:	200 60TH STREET
Owner City,St,Zip:	BROOKLYN, NY 11220
Owner Telephone:	(212) 734-6247
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	SIEGBERT KOHLMAN ENTERPRISES, LTD.
Mailing Address:	50 EAST 79TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10021
Mailing Contact:	BERT KOHLMAN
Mailing Telephone:	(212) 734-6247
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/12/2001
Expiration Date:	01/08/2006
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service

SIEGBERT KOHLMAN ENTERPRISES, LTD. (Continued) **U003764770**

Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge, Vent Whistle
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	12/27/1987
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

J83 **57TH ST. & 2ND AVENUE** **NY Spills** **S102148151**
NE **57TH ST/2ND AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.101 mi.
535 ft. **Site 7 of 7 in cluster J**

Relative:
Higher

Actual:
36 ft.

NY Spills:

Site ID:	268327
Facility Addr2:	Not reported
Facility ID:	9401068
Spill Number:	9401068
Facility Type:	ER
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Spill Date:	4/21/1994
Reported to Dept:	4/21/1994
CID:	Not reported
Spill Cause:	Vandalism
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Local Agency
Cleanup Ceased:	4/25/1994
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt:	1/13/1995
Remediation Phase:	0
Date Entered In Computer:	4/27/1994
Spill Record Last Update:	8/4/1998
Spiller Name:	Not reported
Spiller Company:	UNKOWN

57TH ST. & 2ND AVENUE (Continued) **S102148151**

Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 218577
DEC Memo: Not reported
Remarks: ABANDONED 3,000 GALLON TANKER LEFT ON THE STREET 1 BLOCK FROM WATERWAY AFRAID OF RELEASE. DEC (SIGONA) HIRED MILRO CONTRACTORS TO PUMP OUT THE TANK TRUCK. CONTENTS FOUND TO BE HAZ WASTE.

Material:
Site ID: 268327
Operable Unit ID: 998410
Operable Unit: 01
Material ID: 384840
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 150
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 268327
Operable Unit ID: 998410
Operable Unit: 01
Material ID: 384841
Material Code: 0063A
Material Name: UNKNOWN HAZARDOUS MATERIAL
Case No.: Not reported
Material FA: Hazardous Material
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9401068
Investigator: SIGONA

57TH ST. & 2ND AVENUE (Continued) **S102148151**

Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/21/1994 17:45
Reported to Dept Date/Time: 04/21/94 17:57
SWIS: 61
Spiller Name: UNKOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Vandalism
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 08
Spill Notifier: Local Agency
PBS Number: Not reported
Cleanup Ceased: 04/25/94
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt: 01/13/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/27/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/04/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 150
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728

57TH ST. & 2ND AVENUE (Continued) **S102148151**

Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN HAZARDOUS MATERIAL
Class Type: UNKNOWN HAZARDOUS MATERIAL
Times Material Entry In File: 2093
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: ABANDONED 3,000 GALLON TANKER LEFT ON THE STREET 1 BLOCK FROM WATERWAY AFRAID OF RELEASE. DEC SIGONA) HIRED MILRO CONTRACTORS TO PUMP OUT THE TANK TRUCK. CONTENTS FOUND TO BE HAZ WASTE.

N84 **BAY RIDGE MAZDA-201 60TH ST** **FINDS** **1007786878**
SE **201 60TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.102 mi.
536 ft. **Site 3 of 7 in cluster N**

Relative: Higher

Actual: 56 ft.

FINDS:

Registry ID: 110019493617

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

N85 **CUSTOM CRUISIN COLLISION INC** **RCRA-NonGen** **1000129941**
SE **201 60TH ST** **FINDS** **NYD982726895**
< 1/8 **BROOKLYN, NY 11220** **MANIFEST**
0.102 mi.
536 ft. **Site 4 of 7 in cluster N**

Relative: Higher

Actual: 56 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: CUSTOM CRUISIN COLLISION INC
Facility address: 201 60TH ST
BROOKLYN, NY 112203711
EPA ID: NYD982726895
Mailing address: 60TH ST
BROOKLYN, NY 11220
Contact: Not reported
Contact address: 60TH ST
BROOKLYN, NY 11220
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CUSTOM CRUISIN COLLISION INC (Continued) **1000129941**

Owner/Operator Summary:
Owner/operator name: WILLIAM FALLETTA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: WILLIAM FALLETTA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: CUSTOM CRUISIN COLLISION INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: CUSTOM CRUISIN COLLISION INC
Classification: Not a generator, verified

Date form received by agency: 11/12/1991
Facility name: CUSTOM CRUISIN COLLISION INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004428263

CUSTOM CRUISIN COLLISION INC (Continued) **1000129941**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD982726895
Country:	USA
Mailing Name:	CUSTOM CRUISIN COLLISION INC
Mailing Contact:	AMIL MAHSUROCLU
Mailing Address:	201 60TH STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-238-6850

Document ID:	NJA0628766
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	890906
Trans1 Recv Date:	890906
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890906
Part A Recv Date:	891023
Part B Recv Date:	890914
Generator EPA ID:	NYD982726895
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00095
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NJA1317375
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	920128
Trans1 Recv Date:	920128
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920129
Part A Recv Date:	920211

CUSTOM CRUISIN COLLISION INC (Continued) **1000129941**

Part B Recv Date: 920210
Generator EPA ID: NYD982726895
Trans1 EPA ID: NJD986608941
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 00095
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

Document ID: NJA1490975
Manifest Status: Completed copy
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 920720
Trans1 Recv Date: 920720
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920721
Part A Recv Date: Not reported
Part B Recv Date: 920730
Generator EPA ID: NYD982726895
Trans1 EPA ID: NJD986608941
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

Document ID: NJA1529910
Manifest Status: Completed copy
Trans1 State ID: NJDEPS103
Trans2 State ID: Not reported
Generator Ship Date: 930111
Trans1 Recv Date: 930111
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930112
Part A Recv Date: Not reported
Part B Recv Date: 930126
Generator EPA ID: NYD982726895
Trans1 EPA ID: NJD986608941
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001

CUSTOM CRUISIN COLLISION INC (Continued) **1000129941**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	93

Document ID:	NJA0627753
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	890411
Trans1 Recv Date:	890411
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890411
Part A Recv Date:	890601
Part B Recv Date:	890418
Generator EPA ID:	NYD982726895
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F005 - UNKNOWN
Quantity:	00260
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89

Document ID:	NJA1886106
Manifest Status:	Completed copy
Trans1 State ID:	10339
Trans2 State ID:	Not reported
Generator Ship Date:	940321
Trans1 Recv Date:	940321
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940324
Part A Recv Date:	Not reported
Part B Recv Date:	940406
Generator EPA ID:	NYD982726895
Trans1 EPA ID:	NJD986608941
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F003 - UNKNOWN
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	94

K86
NE
< 1/8
0.102 mi.
538 ft.

CONSOLIDATED EDISON
EAST 57TH STREET AND 1ST AVENU
BROOKLYN, NY 11201

Site 2 of 9 in cluster K

MANIFEST **1009234281**
N/A

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

EPA ID:	NYP000927798
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYB7236144
Manifest Status:	Completed copy
Trans1 State ID:	SM1708
Trans2 State ID:	Not reported
Generator Ship Date:	960830
Trans1 Recv Date:	960830
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960830
Part A Recv Date:	960912
Part B Recv Date:	960918
Generator EPA ID:	NYP000927798
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	02264
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	96

Document ID:	NYB7310673
Manifest Status:	Completed copy
Trans1 State ID:	SM1563
Trans2 State ID:	Not reported
Generator Ship Date:	960823
Trans1 Recv Date:	960823
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960826
Part A Recv Date:	960906
Part B Recv Date:	960913
Generator EPA ID:	NYP000927798
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636

CONSOLIDATED EDISON (Continued) **1009234281**

Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	03127
Units:	P - Pounds
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	96

Document ID:	NYB7236054
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	80336AB
Trans2 State ID:	Not reported
Generator Ship Date:	960830
Trans1 Recv Date:	960830
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960903
Part A Recv Date:	960916
Part B Recv Date:	961022
Generator EPA ID:	NYP000927798
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00001
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	96

K87 **ONE PINT OIL IN MANHOLE # 51713** **NY Spills** **S108466923**
NE **57 STREET & 1 AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
538 ft. **Site 3 of 9 in cluster K**

Relative:
Higher

Actual:
23 ft.

NY Spills:

Site ID:	378748
Facility Addr2:	Not reported
Facility ID:	0613669
Spill Number:	0613669
Facility Type:	ER
SWIS:	2401
Investigator:	gdbreen
Referred To:	Not reported
Spill Date:	3/19/2007
Reported to Dept:	3/21/2007
CID:	76
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

ONE PINT OIL IN MANHOLE # 51713 (Continued) **S108466923**

Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/24/2007
Remediation Phase:	0
Date Entered In Computer:	3/22/2007
Spill Record Last Update:	4/24/2007
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	328276
DEC Memo:	04/24/07 - See e-docs for Con Ed report detailing cleanup and closure. 204981. see eDocs
Remarks:	CALLER REPORTS 1 PINT ON 300 GALLONS OF WATER. EARTHEN SUMP DISCOVERED ON 3/20/07 @ 18:49. MANHOLE ENCLOSED IN CONCRETE. NO THO THE 5 QUESTIONS. REF# 204981.

Material:

Site ID:	378748
Operable Unit ID:	1136243
Operable Unit:	01
Material ID:	2126174
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

K88 **57TH STREET & 1ST AVE.** **NY Spills** **S102142439**
NE **57TH ST. & 1ST AVE.** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
538 ft. **Site 4 of 9 in cluster K**

Relative:
Higher

Actual:
23 ft.

NY Spills:

Site ID:	84338
Facility Addr2:	Not reported
Facility ID:	9109843
Spill Number:	9109843
Facility Type:	ER
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Spill Date:	12/15/1991
Reported to Dept:	12/15/1991
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	NY HARBOR
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Federal Government
Cleanup Ceased:	12/19/1991
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	12/19/1991
Remediation Phase:	0
Date Entered In Computer:	2/12/1992
Spill Record Last Update:	2/12/1992
Spiller Name:	Not reported
Spiller Company:	UNK.
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	77574
DEC Memo:	Not reported
Remarks:	LAST NIGHT A DEVICK CRAIN TIPPED OVER, CG TEAM SENT TO INVESTIGATE.

Material:

Site ID:	84338
Operable Unit ID:	959870
Operable Unit:	01
Material ID:	418422
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	84338
Operable Unit ID:	959870

57TH STREET & 1ST AVE. (Continued) **S102142439**

Operable Unit:	01
Material ID:	418424
Material Code:	0013
Material Name:	Lube Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9109843
Investigator:	TOMASELLO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	12/15/1991 10:00
Reported to Dept Date/Time:	12/15/91 10:57
SWIS:	61
Spiller Name:	UNK.
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Equipment Failure
Reported to Dept:	Surface Water
Water Affected:	NY HARBOR
Spill Source:	02
Spill Notifier:	Federal Government
PBS Number:	Not reported
Cleanup Ceased:	12/19/91
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /

57TH STREET & 1ST AVE. (Continued) **S102142439**

UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 12/19/91
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/12/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/12/92
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: LUBRICATING OIL
Class Type: LUBRICATING OIL
Times Material Entry In File: 292
CAS Number: Not reported
Last Date: Not reported
Material: LUBE OIL
Class Type: LUBE OIL
Times Material Entry In File: 295
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: LAST NIGHT A DEVICK CRAIN TIPPED OVER, CG TEAM SENT TO INVESTIGATE.

K89 **NEW YORK HARBOR UPPER BAY** **NY Spills** **S106005589**
NE **FIRST AVE /57TH ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
538 ft. **Site 5 of 9 in cluster K**

Relative:
Higher

Actual:
23 ft.

NY Spills:

Site ID:	293822
Facility Addr2:	Not reported
Facility ID:	0203914
Spill Number:	0203914
Facility Type:	ER
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Spill Date:	7/15/2002
Reported to Dept:	7/15/2002
CID:	246
Spill Cause:	Unknown
Water Affected:	NEW YORK HARBOR
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/19/2002
Remediation Phase:	0
Date Entered In Computer:	7/15/2002
Spill Record Last Update:	11/24/2003
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	237784
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO" 7/15/2002 - 6:10am: Initial information call made to notifier Allen and US Coast Guard, Eric Brown. Allen confirmed petroleum odor detected is from water in this area since wind blowed to shoreline direction. It smelled in the blowed winds. Mr Brown stated that US Coast Guard was on scene and found sheen with a size of 50'by 100'. Investegation continues. 7/15/2002 - Bouchard reported spill at 8:23am Spill No. 0203916. US Coast Guard received information and found evidence around the Bouchard barge before noon. Ken's Marine and Miller Environmental contractors have been hired by RP. 7/16/2002 - Information provided by contractor was Bouchard personnel were transfering diesel fuel from vessel internal storage tank to a 6,000 gallon day tank on vessel deck. The day tank was overfilled causing release of estimated 500 gallons into New York Harbour. - Information from personnel on site was that during transfer operations the barge crew ordered pizza and took a break to eat the pizza and forgot about the transfer operation which led to spill. - The volume of spill was

NEW YORK HARBOR UPPER BAY (Continued) **S106005589**

probably much higher than 500 gallons but rest of diesel was on deck and did not make it into water. The diesel which did not make its way into water was drained back into a vessel holding tank. - At the time of spills first involvement Tuesday 7/16 @1pm the clean up was well underway and all material was contained inside booms. - Combined personnel on site for contractors was approximately 50 men using absorbents ands a vaccuum truck to remeadiate petroluem impacts. -schedualed activities for the remainder of yesterday and today were to continue to recover pooled product and remove most of the booms placing just one boom across the affected pier openings and leaving it in place for a minimum of two tidal cycles. -Digital photographs on a disk are provided to DEL desk.

Remarks: caller reports oil sheen on water of upper bay. dimensions of sheen 100x50 ft. Investigation underway.

Material:

Site ID:	293822
Operable Unit ID:	855202
Operable Unit:	01
Material ID:	521718
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

K90 **LTANKS** **S105996268**
NE **57TH ST/FIRST AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
538 ft. **Site 6 of 9 in cluster K**

Relative:
Higher

Actual:
23 ft.

LTANKS:

Site ID:	331028
Spill No:	0203916
Spill Date:	7/15/2002
Spill Cause:	Tank Overfill
Spill Source:	Vessel
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/18/2002

(Continued) **S105996268**

Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	7/15/2002
CID:	396
Water Affected:	NEW YORK HARBOR
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/15/2002
Spill Record Last Update:	7/18/2002
Spiller Name:	KEVIN NUGENT
Spiller Company:	BOUCHARD TRANSPORTATION
Spiller Address:	77 NEWBRIDGE ROAD
Spiller City,St,Zip:	HICKSVILLE, NY 11801-
Spiller County:	001
Spiller Contact:	KEVIN NUGENT
Spiller Phone:	(516) 681-4900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266232
Remarks:	day tank on barge was overfilled...materail in under the dock booms have been put out.

Material:

Site ID:	331028
Operable Unit ID:	856701
Operable Unit:	01
Material ID:	521720
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

N91
SE
< 1/8
0.102 mi.
541 ft.

DRIVING MORE AUTO REPAIR INC
203 60TH ST
BROOKLYN, NY 11220

Site 5 of 7 in cluster N

FINDS **1009446627**
AST **N/A**

Relative:
Higher

Actual:
56 ft.

FINDS:

Registry ID: 110024769008

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610698
Program Type:	PBS
UTM X:	582754.16958999995
UTM Y:	4499548.9752700003
Expiration Date:	2012/11/08

Affiliation Records:

Site Id:	389604
Affiliation Type:	On-Site Operator
Company Name:	DRIVING MORE AUTO REPAIR INC
Contact Type:	Not reported
Contact Name:	ZHAO X WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7301
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/8/2007

Site Id:	389604
Affiliation Type:	Emergency Contact
Company Name:	DRIVING MORE AUTO REPAIR INC
Contact Type:	Not reported
Contact Name:	ZHAO X WANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7301
Phone Ext:	Not reported
Email:	Not reported

DRIVING MORE AUTO REPAIR INC (Continued) **1009446627**

Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/8/2007

Site Id: 389604
Affiliation Type: Owner
Company Name: DRIVING MORE AUTO REPAIR INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 203 60TH ST.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11220
Country Code: 001
Phone: (718) 492-7301
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/8/2007

Site Id: 389604
Affiliation Type: Mail Contact
Company Name: DRIVING MORE AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: ZHAO X WANG
Address1: 203 60TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11220
Country Code: 001
Phone: (718) 492-7301
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/8/2007

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
I00 - Overfill - None
G10 - Tank Secondary Containment - Impervious Underlayment
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None

Tank Info:

Tank Number: 001

DRIVING MORE AUTO REPAIR INC (Continued) **1009446627**

Tank Id:	220308
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	11/8/2007

N92 **DRIVING MORE AUTO** **FINDS** **1012218119**
SE **203 60 ST.** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.102 mi.
541 ft. **Site 6 of 7 in cluster N**

Relative:
Higher

Actual:
56 ft.

FINDS:

Registry ID: 110040503041

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

---

93 **57TH STREET AUTOBODY INC** **FINDS** **1012221655**
NE **113 57TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.103 mi.
543 ft.

Relative:
Higher

Actual:
29 ft.

FINDS:

Registry ID: 110040597379

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

K94 **BQE @ 56TH ST EXIT** **LTANKS** **S100153391**
ENE **BQE @ 56TH ST EXIT** **HIST LTANKS** **N/A**
< 1/8 **BKLYN, NY**
0.107 mi.
567 ft. **Site 7 of 9 in cluster K**

Relative:
Higher

Actual:
20 ft.

LTANKS:

Site ID:	95895
Spill No:	9107100
Spill Date:	10/2/1991
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/7/1995
Facility Addr2:	BQE @ 56TH ST EXIT
Cleanup Ceased:	6/7/1995
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	10/2/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/7/1991
Spill Record Last Update:	6/7/1995
Spiller Name:	Not reported
Spiller Company:	YELLOW FREIGHT
Spiller Address:	10990 ROE AVE
Spiller City,St,Zip:	OVERLAND PARK, KS 662
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	85753
Remarks:	RUPTURED FUEL TANK. FD & PD ON SCENE. USCG WILL NOTIFY DEP

Material:

Site ID:	95895
Operable Unit ID:	957432
Operable Unit:	01
Material ID:	419330
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

BQE @ 56TH ST EXIT (Continued) **S100153391**

Tank Test:

Site ID:	95895
Spill Tank Test:	1539125
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	2
Spill Number:	9107100
Spill Date:	10/02/1991
Spill Time:	14:30
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	06/07/95
Cleanup Ceased:	06/07/95
Cleanup Meets Standard:	True
Investigator:	FINGER
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	10/02/91
Reported to Department Time:	15:06
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	YELLOW FREIGHT
Spiller Address:	10990 ROE AVE
Spiller City,St,Zip:	OVERLAND PARK, KANSAS 662
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(913) 344-3000
Facility Extention:	Not reported
Spill Notifier:	Other
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True

BQE @ 56TH ST EXIT (Continued) **S100153391**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/07/91
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 06/07/95
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 50
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Spill Cause: RUPTURED FUEL TANK. FD PD ON SCENE. USCG WILL NOTIFY DEP

---

95 **OWLS HEAD WPC/BKLYN** **LTANKS S100146741**
SW **OWLS HEAD WPC** **HIST LTANKS N/A**
< 1/8 **NEW YORK CITY, NY**
0.108 mi.
570 ft.

Relative:
Lower

Actual:
5 ft.

LTANKS:
Site ID: 271641
Spill No: 9011157
Spill Date: 1/21/1991
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Spill Closed Dt: 1/21/1991
Facility Addr2: Not reported
Cleanup Ceased: 1/21/1991
Cleanup Meets Standard: True
SWIS: 2401
Investigator: MANDALA
Referred To: Not reported
Reported to Dept: 1/21/1991
CID: Not reported
Water Affected: LOWER NEW YORK BAY
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0

OWLS HEAD WPC/BKLYN (Continued) **S100146741**

Date Entered In Computer: 3/15/1991
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: NYCDEP
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 221072
Remarks: (2) PRELIMINARY STP TANKS OUT OF SERVICE, TRYING TO FIX THEM,REFERRED TO SPDES.

Material:
Site ID: 271641
Operable Unit ID: 948164
Operable Unit: 01
Material ID: 427715
Material Code: 0062A
Material Name: RAW SEWAGE
Case No.: Not reported
Material FA: Other
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 2
Spill Number: 9011157
Spill Date: 01/21/1991
Spill Time: 16:03
Spill Cause: Tank Failure
Resource Affectd: Surface Water
Water Affected: LOWER NEW YORK BAY
Spill Source: Other Non Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 01/21/91
Cleanup Ceased: 01/21/91
Cleanup Meets Standard: True

OWLS HEAD WPC/BKLYN (Continued) **S100146741**

Investigator:	MANDALA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	01/21/91
Reported to Department Time:	17:12
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYCDEP
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Local Agency
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	03/15/91
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	/ /
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Hazardous Material
Quantity Spilled:	-1
Unkonwn Quantity Spilled:	False
Units:	Not reported
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	RAW SEWAGE
Class Type:	RAW SEWAGE
Times Material Entry In File:	1993
CAS Number:	Not reported
Last Date:	19940728

DEC Remarks: Not reported

OWLS HEAD WPC/BKLYN (Continued) **S100146741**

Spill Cause: 2) PRELIMINARY STP TANKS OUT OF SERVICE, TRYING TO FIX THEM,REFERRED TO SPDES.

G96 **CEPEDA S AUTO BODY** **FINDS** **1007798534**
East **265 58TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.112 mi.
589 ft. **Site 3 of 4 in cluster G**

Relative:
Higher

FINDS:

Registry ID: 110019610465

Actual:
51 ft.

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

L97 **MANHOLE #6028** **NY Spills** **S103936700**
SW **67TH & RIDGE BLVD** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.121 mi.
638 ft. **Site 2 of 6 in cluster L**

Relative:
Higher

NY Spills:

Actual:
64 ft.

Site ID:	132656
Facility Addr2:	Not reported
Facility ID:	9901061
Spill Number:	9901061
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	4/28/1999
Reported to Dept:	4/28/1999
CID:	257
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/13/2002
Remediation Phase:	0
Date Entered In Computer:	4/28/1999
Spill Record Last Update:	6/13/2002
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001

MANHOLE #6028 (Continued) **S103936700**

Contact Name:	FRANK MASSERIA
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	122959
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" CON ED E2MIS NOTES 5-10-99 Leaking tube from joint regulator found in MH 6028. Approx. 1 qt. of dielectric fluid leaked onto floor of MH. NO sewers or waterways affected, liquid sample taken with a 4-6 hr. turnaround. Tag # 16035 placed. Repairs wer made to tubing on joint regulator,side silicone taped tubing by joint side. Permanent rpairs pending safe access. 1725 hrs. Lab Seq# 99-04357 <1ppm Update 5-18-99 Cleanup delayed due to D Faulted Feeder in the same structure. Repairs will be scheduled when system conditions allow feeder to be taken out of service. UPDATE - AS PER EMAIL FROM R. DONOVAN AND J. STOLFI'S EMAIL DATED 5/20/99 5/18/99 1410HR J. STOLFI REPORTS MANHOLE MADE SAFE BY REMOVING SILICONE TAPE OFF TUBING AND INSTALLED A TUBING INSULATOR. HOLE IS SAFE FOR ENTRY. WILL REMOVE TANK AND DRAIN AND FILL JOINT ON FEEDER 8B81 ON C-FAULT. 6-22-99 WALKER (FLUSH) REPORTS, CLEANUP COMPLETED AND TAG # 16035 REMOVED.
Remarks:	clean up pending test results and after manhole made safe ref #124503

Material:

Site ID:	132656
Operable Unit ID:	1075850
Operable Unit:	01
Material ID:	563510
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9901061
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported

MANHOLE #6028 (Continued) **S103936700**

Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/28/1999 09:45
Reported to Dept Date/Time: 04/28/99 10:41
SWIS: 61
Spiller Name: CON ED
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Contact: FRANK MASSERIA
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/28/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 07/17/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: CON ED E2MIS NOTES 5-10-99 Leaking tube from joint regulator found in MH

MANHOLE #6028 (Continued) **S103936700**

6028. Approx. 1 qt. of dielectric fluid leaked onto floor of MH. NO sewers or waterways affected, liquid sample taken with a 4-6 hr. turnaround. Tag 16035 placed. Repairs wer made to tubing on joint regulator,side silicone taped tubing by joint side. Permanent rpairs pending safe access. 1725 hrs. Lab Seq 99-04357 <1ppm Update 5-18-99 Cleanup delayed due to D Faulted Feeder in the same structure. Repairs will be scheduled when system conditions allow feeder to be taken out of service.

Remark: clean up pending test results and after manhole made safe ref 124503

L98 **MH 6028** **NY Spills** **S103936501**
SW **67ST/RIDGE BLVD** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.121 mi.
638 ft. **Site 3 of 6 in cluster L**

Relative:
Higher

Actual:
64 ft.

NY Spills:

Site ID:	85725
Facility Addr2:	Not reported
Facility ID:	9900829
Spill Number:	9900829
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	4/22/1999
Reported to Dept:	4/22/1999
CID:	270
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/5/1999
Remediation Phase:	0
Date Entered In Computer:	4/22/1999
Spill Record Last Update:	6/14/2000
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	78719
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Con ed e2mis notes: Approx 1 gallon of an unknown oil on mud. Joint regulator in mh. <1ppm, env. ops. reports <1ppm cleanup complete and tag removed.
Remarks:	1 gal material on mud con ed 124381 samples taken clean up pending

Material:

MH 6028 (Continued) **S103936501**

Site ID:	85725
Operable Unit ID:	1079586
Operable Unit:	01
Material ID:	307946
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9900829
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	04/22/1999 09:45
Reported to Dept Date/Time:	04/22/99 10:32
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /

MH 6028 (Continued) **S103936501**

Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/05/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/22/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/14/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con ed e2mis notes: Approx 1 gallon of an unknown oil on mud. Joint regulator in mh. <1ppm, env. ops. reports <1ppm cleanup complete and tag removed.
Remark: 1 gal material on mud con ed 124381 samples taken clean up pending

---

L99 **TM 1074** **NY Spills** **S104509424**
SW **67TH ST & RIDGE BLVD** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.121 mi.
638 ft. **Site 4 of 6 in cluster L**

Relative:
Higher

Actual:
64 ft.

NY Spills:
Site ID: 144243
Facility Addr2: Not reported
Facility ID: 9912331
Spill Number: 9912331
Facility Type: ER
SWIS: 2401
Investigator: COMENALE
Referred To: Not reported
Spill Date: 1/27/2000
Reported to Dept: 1/27/2000
CID: 322
Spill Cause: Equipment Failure

TM 1074 (Continued) **S104509424**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/19/2002
Remediation Phase:	0
Date Entered In Computer:	1/27/2000
Spill Record Last Update:	3/19/2002
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	122959
DEC Memo:	Not reported
Remarks:	CON ED #129760 - HOLE IN TRANSFORMER CAUSED SPILL - 1 FT OF PACKED DIRT ON FLOOR WITH A SEWER CONNECTION - NONE ENTERED SEWER PCB SAMPE TAKEN - CLEAN UP WILL BE DONE 50/499- HISTORY INDICATED 15 PPM PCB'S

Material:

Site ID:	144243
Operable Unit ID:	1091032
Operable Unit:	01
Material ID:	294217
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

TM 1074 (Continued) **S104509424**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9912331
Investigator:	COMENALE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	01/27/2000 14:10
Reported to Dept Date/Time:	01/27/00 15:06
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	CALLER
Spiller Phone:	(212) 580-6763
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	NEW YORK, NY -
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	01/27/00
Date Spill Entered In Computer Data File:	Not reported
Update Date:	03/23/00
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	10
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	TRANSFORMER OIL

TM 1074 (Continued) **S104509424**

Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Not reported
Remark: CON ED 129760 - HOLE IN TRANSFORMER CAUSED SPILL - 1 FT OF PACKED DIRT ON FLOOR WITH A SEWER CONNECTION - NONE ENTERED SEWER PCB SAMPE TAKEN - CLEAN UP WILL BE DONE 50/499- HISTORY INDICATED 15 PPM PCB S

O100 **MARINO POLISHING & PLATING** **UST** **1000555719**
SE **244 59TH ST** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.121 mi.
638 ft. **Site 1 of 3 in cluster O**

Relative:
Higher

Actual:
57 ft.

UST:
Facility Id: 2-064351
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 582761.07328000001
UTM Y: 4499627.2895400003

Affiliation Records:
Site Id: 1339
Affiliation Type: Owner
Company Name: MARINO POLISHING & PLATING
Contact Type: Not reported
Contact Name: Not reported
Address1: 244 59TH ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11220
Country Code: 001
Phone: (718) 492-9822
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1339
Affiliation Type: Mail Contact
Company Name: MARINO POLISHING & PLATING
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 244 59TH ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11220
Country Code: 001
Phone: (718) 492-9822
Phone Ext: Not reported
Email: Not reported

MARINO POLISHING & PLATING (Continued) **1000555719**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	1339
Affiliation Type:	On-Site Operator
Company Name:	MARINO POLISHING & PLATING
Contact Type:	Not reported
Contact Name:	GERALD MARINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-9822
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	1339
Affiliation Type:	Emergency Contact
Company Name:	MARINO POLISHING & PLATING
Contact Type:	Not reported
Contact Name:	GERALD MARINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-9822
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None

MARINO POLISHING & PLATING (Continued) **1000555719**

J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Info:

Site ID:	1339
Tank Number:	001
Tank ID:	2379
Tank Status:	Tank Converted to Non-Regulated Use
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	1339
Tank Number:	002
Tank ID:	2380
Tank Status:	Tank Converted to Non-Regulated Use
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	1339
Tank Number:	003
Tank ID:	2381
Tank Status:	Tank Converted to Non-Regulated Use
Tank Model:	Not reported
Pipe Model:	Not reported

MARINO POLISHING & PLATING (Continued) **1000555719**

Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-064351
SPDES Number:	Not reported
Emergency Contact:	GERALD MARINO
Emergency Telephone:	(718) 492-9822
Operator:	GERALD MARINO
Operator Telephone:	(718) 492-9822
Owner Name:	MARINO POLISHING & PLATING
Owner Address:	244 59TH ST
Owner City,St,Zip:	BROOKLYN, NY 11220
Owner Telephone:	(718) 492-9822
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	MARINO POLISHING & PLATING
Mailing Address:	244 59TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	SUPER FACILITY MANAGER
Mailing Telephone:	(718) 492-9822
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	244 59TH ST
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	02/19/1992
Expiration Date:	03/10/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01

MARINO POLISHING & PLATING (Continued) **1000555719**

Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Tank Converted To Non-Regulated Use
Install Date: Not reported
Capacity (gals): 550
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Tank Converted To Non-Regulated Use
Install Date: Not reported
Capacity (gals): 550
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 003

MARINO POLISHING & PLATING (Continued) **1000555719**

Tank Location:	UNDERGROUND
Tank Status:	Tank Converted To Non-Regulated Use
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	08/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

O101 **MARINO POLISHING & PLATING INC** **RCRA-NonGen** **1001968774**
SE **244-254 59TH ST** **FINDS** **NYN008008005**
< 1/8 **BROOKLYN, NY 11220**
0.121 mi.
638 ft. **Site 2 of 3 in cluster O**

Relative:
Higher

Actual:
57 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	MARINO POLISHING & PLATING INC
Facility address:	244-254 59TH ST BROOKLYN, NY 11220
EPA ID:	NYN008008005
Mailing address:	59TH ST BROOKLYN, NY 11220
Contact:	Not reported
Contact address:	59TH ST BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NON REGULATED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(718) 555-1212
Legal status:	Private

MARINO POLISHING & PLATING INC (Continued) **1001968774**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (718) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MARINO POLISHING & PLATING INC
Classification: Not a generator, verified

Date form received by agency: 03/29/2000
Facility name: MARINO POLISHING & PLATING INC
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/11/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/24/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

MARINO POLISHING & PLATING INC (Continued) **1001968774**

Registry ID: 110009483790

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

G102 **BLUE DIAMOND FUEL OIL CORP** **UST** **U001838839**
ENE **243 57TH ST** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11220**
0.123 mi.
649 ft. **Site 4 of 4 in cluster G**

Relative:
Higher

Actual:
46 ft.

UST:

Facility Id:	2-004448
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582864.51179000002
UTM Y:	4499755.2426399998

Affiliation Records:

Site Id:	40
Affiliation Type:	Owner
Company Name:	BLUE DIAMOND FUEL OIL CORP
Contact Type:	Not reported
Contact Name:	Not reported

BLUE DIAMOND FUEL OIL CORP (Continued) **U001838839**

Address1:	194 34TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 439-5518
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	40
Affiliation Type:	Mail Contact
Company Name:	BLUE DIAMOND FUEL OIL CORP
Contact Type:	Not reported
Contact Name:	MICHAEL PROSCIA
Address1:	149 34TH STREET
Address2:	P.O. BOX 320157
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 965-0900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	40
Affiliation Type:	On-Site Operator
Company Name:	BLUE DIAMOND FUEL OIL CORP
Contact Type:	Not reported
Contact Name:	FRANCIS S PROSCIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-0900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	40
Affiliation Type:	Emergency Contact
Company Name:	BLUE DIAMOND FUEL OIL CORP
Contact Type:	Not reported
Contact Name:	MICHAEL PROSCIA OR RICHARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported

BLUE DIAMOND FUEL OIL CORP (Continued) **U001838839**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-0900
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
D02 - Pipe Type - Galvanized Steel
I04 - Overfill - Product Level Gauge (A/G)
I04 - Overfill - Product Level Gauge (A/G)
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction

Tank Info:

Site ID: 40

Tank Number: 001
Tank ID: 26769
Tank Status: Closed - In Place
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 8/1/1979
Capacity Gallons: 4000
Tightness Test Method: 03
Next Test Date: Not reported
Date Tank Closed: 9/1/1998
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 5/1/1997
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

Site ID: 40

Tank Number: 002
Tank ID: 26770
Tank Status: Closed - In Place
Tank Model: Not reported
Pipe Model: Not reported

BLUE DIAMOND FUEL OIL CORP (Continued) **U001838839**

Install Date:	8/1/1996
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-004448
SPDES Number:	Not reported
Emergency Contact:	MICHAEL PROSCIA OR RICHARD
Emergency Telephone:	(718) 965-0900
Operator:	FRANCIS S PROSCIA
Operator Telephone:	(718) 965-0900
Owner Name:	BLUE DIAMOND FUEL OIL CORP
Owner Address:	194 34TH STREET
Owner City,St,Zip:	BROOKLYN, NY 11232
Owner Telephone:	(718) 439-5518
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	BLUE DIAMOND FUEL OIL CORP
Mailing Address:	149 34TH STREET
Mailing Address 2:	P.O. BOX 320157
Mailing City,St,Zip:	BROOKLYN, NY 11232
Mailing Contact:	MICHAEL PROSCIA
Mailing Telephone:	(718) 965-0900
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	243 57TH ST
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	TRUCKING/TRANSPORTATION
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	09/17/1997
Expiration Date:	10/23/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01

BLUE DIAMOND FUEL OIL CORP (Continued) **U001838839**

Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: 19790801
Capacity (gals): 4000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Diking
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: 05/01/1997
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 09/01/1998
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: 19960801
Capacity (gals): 550
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Other
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 08/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

L103 **BIRNRIDGE HOUSE INC** **AST** **A100177851**
SW **6702 RIDGE BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.126 mi.
664 ft. **Site 5 of 6 in cluster L**

Relative:
Higher

Actual:
65 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602631
Program Type:	PBS
UTM X:	582227.78988000005
UTM Y:	4499089.3739900002
Expiration Date:	2016/03/01

Affiliation Records:

Site Id:	24588
Affiliation Type:	On-Site Operator
Company Name:	BIRNRIDGE HOUSE INC
Contact Type:	Not reported
Contact Name:	VICTOR PELOQUIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 228-2071
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	12/27/2007

Site Id:	24588
Affiliation Type:	Emergency Contact
Company Name:	BIRNRIDGE HOUSE INC
Contact Type:	Not reported
Contact Name:	ROBERT MOZILO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 584-4276
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	12/27/2007

Site Id:	24588
Affiliation Type:	Mail Contact
Company Name:	LIVE RIGHT MANAGEMENT
Contact Type:	Not reported
Contact Name:	RANDY STAR SULZER
Address1:	313 97TH STREET
Address2:	Not reported

BIRNRIDGE HOUSE INC (Continued) **A100177851**

City:	BROOKLYN
State:	NY
Zip Code:	11209
Country Code:	001
Phone:	(718) 630-5551
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/25/2011

Site Id:	24588
Affiliation Type:	Owner
Company Name:	BIRNRIDGE HOUSE INC
Contact Type:	MANAGING AGENT
Contact Name:	ROBERT MOZILO
Address1:	6702 RIDGE BLVD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(917) 584-4276
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	12/27/2007

Equipment Records:

K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

Tank Info:

Tank Number:	001
Tank Id:	50886
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1936
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

BIRNRIDGE HOUSE INC (Continued) **A100177851**

Modified By: BVCAMPBE
Last Modified: 3/21/2011

L104 **BIRNRIDGE HOUSE INC** **HIST AST** **S107782973**
SW **6702 RIDGE BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.126 mi.
664 ft. **Site 6 of 6 in cluster L**

Relative:
Higher

Actual:
65 ft.

HIST AST:

PBS Number:	2-602631
SWIS Code:	6101
Operator:	VICTOR PELOQUIN
Facility Phone:	(718) 745-1074
Facility Addr2:	Not reported
Facility Type:	APARTMENT BUILDING
Emergency:	MARY JO KELLY
Emergency Tel:	(718) 332-0777
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	BIRNRIDGE HOUSE INC
Owner Address:	6702 RIDGE BLVD
Owner City,St,Zip:	BROOKLYN, NY 11220
Federal ID:	Not reported
Owner Tel:	(718) 332-0777
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	MARY JO KELLY
Mailing Name:	ARCO
Mailing Address:	2940 AVENUE X
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11235
Mailing Telephone:	(718) 332-0777
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	04/10/2001
Expiration:	03/01/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND

BIRNRIDGE HOUSE INC (Continued) **S107782973**

Tank Status:	In Service
Install Date:	19361201
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	00
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	00
Overfill Protection:	00
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

O105 **EXOTIC AUTO BODY REPAIRS INC** **FINDS** **1007751942**
SE **272 59TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.134 mi.
706 ft. **Site 3 of 3 in cluster O**

Relative:
Higher

Actual:
63 ft.

FINDS:

Registry ID: 110019143390

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

---

106 **6002-6014 & 6016-6024 3RD AVE.** **UST** **U003749703**
SE **6002-6014 & 6016-6024 3RD AVE** **HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.135 mi.
714 ft.

Relative:
Higher

Actual:
59 ft.

UST:

Facility Id:	2-604625
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582834.63543000002
UTM Y:	4499467.5987099996

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Affiliation Records:

Site Id:	26496
Affiliation Type:	On-Site Operator
Company Name:	6002-6014 & 6016-6024 3RD AVE.
Contact Type:	Not reported
Contact Name:	LENA LOMELI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(845) 496-9249
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26496
Affiliation Type:	Mail Contact
Company Name:	LENA LO MELI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 CARLISLE WAY
Address2:	Not reported
City:	WASHINGTONVILLE
State:	NY
Zip Code:	10950
Country Code:	001
Phone:	(845) 781-5888
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26496
Affiliation Type:	Emergency Contact
Company Name:	LENA LOMELI
Contact Type:	Not reported
Contact Name:	LENA LOMELI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(845) 496-9249
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26496
Affiliation Type:	Owner

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Company Name:	LENA LOMELI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 CARLISLE WAY
Address2:	Not reported
City:	WASHINGTONVILLE
State:	NY
Zip Code:	10992
Country Code:	001
Phone:	(845) 496-9249
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C00 - Pipe Location - No Piping
C00 - Pipe Location - No Piping
I00 - Overfill - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
I00 - Overfill - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
I00 - Overfill - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Info:

Site ID:	26496
Tank Number:	001
Tank ID:	58374
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	002
Tank ID:	58375
Tank Status:	Closed - Removed

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	003
Tank ID:	58376
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	004
Tank ID:	58377
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	005
Tank ID:	58378
Tank Status:	Closed - Removed

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	006
Tank ID:	58379
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	007
Tank ID:	58993
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	26496
Tank Number:	008
Tank ID:	58994
Tank Status:	Closed - Removed

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-604625
SPDES Number:	Not reported
Emergency Contact:	LENA LOMELI
Emergency Telephone:	(845) 496-9249
Operator:	LENA LOMELI
Operator Telephone:	(845) 496-9249
Owner Name:	LENA LOMELI
Owner Address:	4 CARLISLE WAY
Owner City,St,Zip:	WASHINGTONVILLE, NY 10992
Owner Telephone:	(845) 496-9249
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Name:	LENA LO MELI
Mailing Address:	4 CARLISLE WAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WASHINGTONVILLE, NY 10950
Mailing Contact:	Not reported
Mailing Telephone:	(845) 781-5888
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	6002 & 6020 3RD AVE.
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/21/2000
Expiration Date:	07/14/2005
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE

6002-6014 & 6016-6024 3RD AVE. (Continued) **U003749703**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	008
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

K107 **VS 5173** **NY Spills** **S106470274**
NE **5620 FIRST AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.140 mi.
740 ft. **Site 8 of 9 in cluster K**

Relative:
Higher

Actual:
24 ft.

NY Spills:

Site ID:	61086
Facility Addr2:	Not reported
Facility ID:	0403101
Spill Number:	0403101

VS 5173 (Continued) **S106470274**

Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	6/21/2004
Reported to Dept:	6/21/2004
CID:	408
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/23/2004
Remediation Phase:	0
Date Entered In Computer:	6/21/2004
Spill Record Last Update:	9/23/2004
Spiller Name:	ERT DESK
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	59547
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" e2mis no. 153963: APPROX 1 PT OF AN UNKNOWN OIL ON APPROX 60 GALS OF WATER IN THE STRUCTURE. SPILL IS CONTAINED. HISTORICAL PCB COUNT OF THE TRANSFORMER IS 11 PPM DTD 5/4/95. CLEANUP PENDING LAB RESULT. DIPPED THE TRANSFORMER AND FOUND THE OIL LEVEL TO BE AT MAX. THE UNIT, HOWEVER, DID NOT HOLD PRESSURE. HE BELIEVES THERE IS A HOLE SOMEWHERE ON THE TOP OF THE UNIT. THIS UNIT WAS ALREADY CONDEMENED FOR INTERNAL FAILURE. MR. THORNGREN WILL TAKE A SAMPLE FROM THE TRANSFORMER. Lab Sequence No: 04-04839-001: PCBs < 1 ppm (STRUCTURE: VAULT) Lab Sequence No: 04-04839-002: TOTAL PCB 11 ppm 7-2-04 04:00HRS A. ADLER (NET) REPORTS, UNIT WAS REMOVED FROM STRUCTURE AND CLEANUP BEGAN. 7-2-04 05:00HRS A. GLODOWSKI REPORTS, DOUBLE WASHED STRUCTRE USING BULL DOG. SUMP WAS FOUND SEALED.
Remarks:	THINK THAT THE TRANSFORMER FAILED THE PRESSURE TEST: UNSURE IF THE OIL SPILLED IS TRANSFORMER OIL: TESTS ARE BEING TAKEN: HAS NOT BEEN CLEANED UP:

Material:

Site ID:	61086
Operable Unit ID:	886599
Operable Unit:	01
Material ID:	490704
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	1

VS 5173 (Continued) **S106470274**

Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

K108 **MH 2210** **NY Spills** **S105057557**
NE **5620 1ST AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.140 mi.
740 ft. **Site 9 of 9 in cluster K**

Relative:
Higher

Actual:
24 ft.

NY Spills:

Site ID:	111113
Facility Addr2:	Not reported
Facility ID:	0102019
Spill Number:	0102019
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	5/21/2001
Reported to Dept:	5/22/2001
CID:	270
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/19/2001
Remediation Phase:	0
Date Entered In Computer:	5/22/2001
Spill Record Last Update:	8/30/2001
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	CALLER

MH 2210 (Continued) **S105057557**

Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	97201
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" CON ED E2MIS REPORT 5-21-01 Approx. 1/2 pt. of unknown oil on 200gals. of water in TM-2210. Appears to be contained. Unit was pressure tested and held. No sump in structure, 1 sample taken. LSN 01-05872-01 <1ppm PCB 5-22-01 1030hrs. Flush Dept. requested we take this off 24hr. deminimus, because of reoccurance o fa sheen and due to the feeder work in the structure. 6-06-01 17:15hrs. Doublewashed structure with slix. Tanker removed all liquids, solids by vactor. Sealed sump and removed tag. Cleanup complete.
Remarks:	ON 200 GALS WATER. NO SEWER OR WATER TRANSFORMER PASSED PRESSURE TEST 137218

Material:

Site ID:	111113
Operable Unit ID:	840833
Operable Unit:	01
Material ID:	537710
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0102019
Investigator:	FOLEY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	05/21/2001 14:25
Reported to Dept Date/Time:	05/22/01 10:34
SWIS:	61
Spiller Name:	UNKNOWN

MH 2210 (Continued) **S105057557**

Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Address: Not reported
Spiller City,St,Zip: -
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 06/19/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/22/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/30/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: CON ED E2MIS REPORT 5-21-01 Approx. 1/2 pt. of unknown oil on 200gals. of water in TM-2210. Appears to be contained. Unit was pressure tested and held. No sump in structure, 1 sample taken. LSN 01-05872-01 <1ppm PCB 5-22-01 1030hrs.Flush Dept. requested we take this off 24hr. deminimus, because of reoccurance o fa sheen and due to the feeder work in the structure. 6-06-01 17:15hrs. Doublewashed structure with slix. Tanker removed all liquids, solids by vactor. Sealed sumpand removed tag. Cleanup complete.
Remark: ON 200 GALS WATER. NO SEWER OR WATER TRANSFORMER PASSED PRESSURE TEST 137218

P109 **LUTHERAN MEDICAL CENTER** **NY Spills** **S105058028**
NE **5610 2ND AVENUE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.144 mi.
762 ft. **Site 1 of 3 in cluster P**

Relative:
Higher

Actual:
36 ft.

NY Spills:

Site ID:	149367
Facility Addr2:	Not reported
Facility ID:	0102671
Spill Number:	0102671
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	6/11/2001
Reported to Dept:	6/11/2001
CID:	323
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/20/2009
Remediation Phase:	0
Date Entered In Computer:	6/11/2001
Spill Record Last Update:	7/20/2009
Spiller Name:	ROBERT WALSH - DIRECTOR
Spiller Company:	HISTORIC SPILL
Spiller Address:	LUTHERAN MED CENTER
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	NICK RECCHIA
Contact Phone:	(516) 746-4400
DEC Region:	2
DER Facility ID:	127064
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO" 9/30/05-Vought-Spoke with Robert Frey (consultant for owner 973-398-8183x252 (Lutheran Medical Center). 8/10/05 Received a Corrective Action Plan submitted by Robert Fry of Enviro-Sciences, Inc. The submittal cites that the plan presents the scope of work necessary to comply with NYSDEC's letter dated June 20, 2001 and the NYCDEP's letters dated November 4, 2002 and December 2, 2003 regarding remediation of the property. Work has started under the Corrective Action Plan. Bishop 5/29/07 - Raphael Ketani. Nick Canonico of NOVA Consulting (718) 343-4440 called regarding the site. He said that the site is on Second Avenue and is a parking lot for the Lutheran Medical Center. He said that LMC wants to develop the site and building a multistory parking garage. He said they will remove soil down to 25 feet, thereby capturing the contaminated soil. Groundwater is at 35 feet and is contaminated. DEP gave a restrictive declaration for the site. 6/7/07 - Austin - Received letter from Nick Canonico of Nova Consulting (dated 5/31/07) requesting project

LUTHERAN MEDICAL CENTER (Continued) **S105058028**

reassignment. Project reassigned to Sharif Rahman for further review. - end 09/19/07 Rec'd GW Investigation Addendum Report prepared by Nova Consulting.Ground water samples were collected from the eight GW monitoring wells(MW-1,MW-2,MW-3,MW-4,TW-1,TW-2,TW-3 and TW-4) at LMC.TW-3 indicate that seventeen(17)VOCs were detected at concentration between 2 and 290 ppb.Sample from TW-4 shows fifteen(15) VOCs were detected at concentration between 5 and 660 ppb. Sample from MW-2 shows presence of one VOC(Tetrachloroethene,PCE) was detected at concentration of 24 ppb.Sample from MW-3 indicates two VOCs, PCE and Acetone at concentration of 2 & 21 ppb, are present in ground water.Nova recommends that no further soil or ground water delineation at the site is warranted and will prepare a Remedial Work Plan to satisfy the requirements of NYS DEC and NYC DEP. A limited subsurface investigation was done by Enviro Services Inc and discovered soil and ground water contamination in 2005. Spoke with RSE regarding the clean up of this site.The VOCs detected in groundwater sample are not representative of historic site operations and are not related to heating oil compounds typically found in former heating oil tanks located down gradient. There is a gas station upgradient at 57-01 2nd Avenue,PBS:2-402826.(SR) 03/20/08 Rec'd RAP, Health & Safety Plan prepared by NOVA Consulting. RAP consists of end point smapling plan, installation of SSDS.Closure report will be submitted to DEC.(sr) 07/20/09 Rec'd closure report from NOVA.NOVA identified the presence of fuel soaked soils in the former tank area which was mixed with materials consisting of wood,concrete,brick, and solid waste.During excavation a 55 gallon drum was discovered with liquid in it and was removed. Another 150 gallon UST was discovered on Jan 6,2009 and was removed. Waste characterization sample was taken.Results indicated that the drum contents were hydraulic oil.End point samples were taken..VOcs were not detected above their TAGM#4046 values.Only five SVOCs were detected slightly above their respective TAGM RSCOs.GW end point samples were not collected by NOVA as it was not encountered during the excavation.Pictures of the excavation in the report.Waste disposal manifest attached. Case closed.(sr)

Remarks: test results show contaminated soil from historic spill. found concentration above stars and tagm guidelines.

Material:

Site ID:	149367
Operable Unit ID:	839339
Operable Unit:	01
Material ID:	534785
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported

LUTHERAN MEDICAL CENTER (Continued) **S105058028**

Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0102671
Investigator: DEMEO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 06/11/2001 09:00
Reported to Dept Date/Time: 06/11/01 09:41
SWIS: 61
Spiller Name: HISTORIC SPILL
Spiller Contact: ROBERT WALSH - DIRECTOR
Spiller Phone: (718) 630-7155
Spiller Contact: NICK RECCHIA
Spiller Phone: (516) 746-4400
Spiller Address: LUTHERAN MED CENTER
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/11/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/13/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported

LUTHERAN MEDICAL CENTER (Continued) **S105058028**

Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Remark: test results show contaminated soil from historic spill. found concentration above stars and tagm guidelines.

M110 **COMPLETE AUTO REPAIR CORP** **FINDS** **1008980479**
SE **6202 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.149 mi.
786 ft. **Site 3 of 3 in cluster M**

Relative: Higher

Actual: 60 ft.

FINDS:

Registry ID: 110024242871

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

N111 **BAY RIDGE MOTORS** **RCRA-NonGen** **1004761859**
SE **6002-6020 3RD AVE** **FINDS** **NYR000091124**
1/8-1/4 **BROOKLYN, NY 11220** **MANIFEST**
0.149 mi.
787 ft. **Site 7 of 7 in cluster N**

Relative: Higher

Actual: 70 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: BAY RIDGE MOTORS
Facility address: 6002-6020 3RD AVE
BROOKLYN, NY 11220
EPA ID: NYR000091124
Mailing address: 3RD AVE
BROOKLYN, NY 11220
Contact: RICHARD IZZO
Contact address: 3RD AVE
BROOKLYN, NY 11220
Contact country: US
Contact telephone: (516) 576-8844
Contact email: Not reported
EPA Region: 02

BAY RIDGE MOTORS (Continued) **1004761859**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LENA LEE LOMELI
Owner/operator address: 4 CARLISLE WAY
WASHINGTONVILLE, NY 10992
Owner/operator country: US
Owner/operator telephone: (914) 496-9249
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: LENA LEE LOMELI
Owner/operator address: 4 CARLISLE WAY
WASHINGTONVILLE, NY 10992
Owner/operator country: US
Owner/operator telephone: (914) 496-9249
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: BAY RIDGE MOTORS
Classification: Not a generator, verified

Date form received by agency: 11/13/2000
Facility name: BAY RIDGE MOTORS
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004565499

BAY RIDGE MOTORS (Continued) **1004761859**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000091124
Country:	USA
Mailing Name:	LOMELLI AUTO REPAIR
Mailing Contact:	GEORGE SOTO
Mailing Address:	60TH ST & 3RD
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-439-6877

Document ID:	NYG1814769
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	11/17/2000
Trans1 Recv Date:	11/17/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000091124
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1011
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01100
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Q112 **ONE PINT OIL IN XFMR VAULT 5811** **NY Spills** **S108294292**
NE **1 AVENUE & 56 STREET** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.151 mi.
798 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
24 ft.

NY Spills:

Site ID:	370548
Facility Addr2:	Not reported
Facility ID:	0607090

ONE PINT OIL IN XFMR VAULT 5811 (Continued) **S108294292**

Spill Number:	0607090
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	9/18/2006
Reported to Dept:	9/20/2006
CID:	410
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/21/2006
Remediation Phase:	0
Date Entered In Computer:	9/20/2006
Spill Record Last Update:	12/21/2006
Spiller Name:	ERTS
Spiller Company:	CON EDISON V- 5811
Spiller Address:	WEST SIDE OF 1ST AVE NORT
Spiller City,St,Zip:	BROOKLYN, NY 11220
Spiller Company:	001
Contact Name:	ERTS
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	320364
DEC Memo:	12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. 202512. see eDocs
Remarks:	1 PINT OF UNKNOWN OIL ON TOP OF 300 GALLONS OF WATER: CONTAINED: COMING OFF 72 HOUR CLOCK: CLEANUP PENDING ACCESS: CONED # 202512

Material:

Site ID:	370548
Operable Unit ID:	1128352
Operable Unit:	01
Material ID:	2117966
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported

ONE PINT OIL IN XFMR VAULT 5811 (Continued) **S108294292**

Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Q113 **VAULT #5674** **NY Spills** **S107416124**
NE **1 AVENUE & 56 STREET** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.151 mi.
798 ft. **Site 2 of 4 in cluster Q**

Relative:
Higher

Actual:
24 ft.

NY Spills:

Site ID:	354086
Facility Addr2:	Not reported
Facility ID:	0508532
Spill Number:	0508532
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	10/17/2005
Reported to Dept:	10/17/2005
CID:	444
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/3/2007
Remediation Phase:	0
Date Entered In Computer:	10/17/2005
Spill Record Last Update:	5/3/2007
Spiller Name:	ERT DESK’
Spiller Company:	VAULT#5674
Spiller Address:	1ST AVE & 56 TH STREET
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	ERT DESK’
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	320364
DEC Memo:	05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. 161523. D. REYES - 18610 - BQE MECH, WHILE DOING 460 ROUTINES (ACCT: C3257), REPORTS FINDING APPROX 10 GALS OF DIEL FLUID FROM THE UNIT IN V5674 ON APPROX 15 GALS OF WATER. SPILL IS CONTAINED IN STRUCTURE. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES. NO PRIVATE PROPERTY AFFECTED. NO MOVEMENT IN THE WATER. THERE IS A SEWER CONNECTION IN THE STRUCTURE VIA A SUMP PUMP (IN A CEMENT SUMP) & PIPING. THE PUMP WAS NOT RUNNING. OIL LEVEL

VAULT #5674 (Continued) **S107416124**

IS MIN. TEMP IS 40. NO PARKING 2400 - 0300 MON & THURS. HISTORICAL PCB COUNT OF UNIT IS 19 PPM DTD 1/21/02. ENV TAG # 36667 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # DD22000 FILLED OUT AND MARKED 'E' PRORITY. CLEANUP TO BEGIN AS 50 - 499. TJ - 50495

Remarks: ON 15 GALLONS OF WATER: NO TO 5 QUESTIONS; CONED # 161523

Material:

Site ID:	354086
Operable Unit ID:	1111525
Operable Unit:	01
Material ID:	2101566
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Q114 **CONSOLIDATED EDISON** **MANIFEST** **1009244036**
NE **1 AVE & 56 ST V5674** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.151 mi.
798 ft. **Site 3 of 4 in cluster Q**

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:

EPA ID:	NYP004136766
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYE0637947
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359

CONSOLIDATED EDISON (Continued) **1009244036**

Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2005
Trans1 Recv Date:	10/17/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/18/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004136766
Trans1 EPA ID:	46107JM
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity:	02548
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	Not reported

Document ID:	NYE0637947
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2005
Trans1 Recv Date:	10/17/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/18/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004136766
Trans1 EPA ID:	46107JM
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity:	02548
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2005

Q115 **TWO GALLONS OIL IN VAULT # 5716** **NY Spills** **S108297200**
NE **56 STREET & 1 AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.151 mi.
798 ft. **Site 4 of 4 in cluster Q**

Relative:
Higher

Actual:
24 ft.

NY Spills:

Site ID:	375573
Facility Addr2:	Not reported
Facility ID:	0611012
Spill Number:	0611012
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN

TWO GALLONS OIL IN VAULT # 5716 (Continued) **S108297200**

Referred To:	Not reported
Spill Date:	1/2/2007
Reported to Dept:	1/2/2007
CID:	408
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/16/2007
Remediation Phase:	0
Date Entered In Computer:	1/2/2007
Spill Record Last Update:	3/15/2007
Spiller Name:	ERTS
Spiller Company:	CON EDISON V # 5716
Spiller Address:	WEST 1ST AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERTS
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	325194
DEC Memo:	03/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 203907. see eDocs
Remarks:	2 GALLONS OF OIL, 50 GALLONS WATER; CLEAN UP PENDING TEST RESULTS; SPILL UIS CONTAINED; 203907

Material:

Site ID:	375573
Operable Unit ID:	1133196
Operable Unit:	01
Material ID:	2123000
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported

TWO GALLONS OIL IN VAULT # 5716 (Continued) **S108297200**

Last Modified: Not reported
Test Method: Not reported

P116 **CHARLES T. AUTO REPAIR, INC.** **HIST AST** **S107784677**
NE **212 56TH ST.** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.152 mi.
803 ft. **Site 2 of 3 in cluster P**

Relative:
Higher

Actual:
38 ft.

HIST AST:

PBS Number:	2-605965
SWIS Code:	6101
Operator:	CHARLES J. TORIBIO
Facility Phone:	(718) 439-8643
Facility Addr2:	Not reported
Facility Type:	OTHER
Emergency:	CHARLES J. TORBIO
Emergency Tel:	(718) 439-8643
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CHARLES T. AUTO REPAIR, INC.
Owner Address:	212 56TH ST.
Owner City,St,Zip:	BROOKLYN, NY 11220
Federal ID:	Not reported
Owner Tel:	(718) 439-8643
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	CHARLES J. TORBIO
Mailing Name:	CHARLES T. AUTO REPAIR, INC.
Mailing Address:	212 56TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Telephone:	(718) 439-8643
Owner Mark:	First Owner
Facility Status:	4 - Subpart 360-14 only (active)
Certification Flag:	False
Certification Date:	06/08/2001
Expiration:	06/07/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	275
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	275
Tank Location:	ABOVEGROUND
Tank Status:	In Service

CHARLES T. AUTO REPAIR, INC. (Continued) **S107784677**

Install Date:	Not reported
Capacity (Gal):	275
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Synthetic Liner
Leak Detection:	Not reported
Overfill Protection:	Not reported
Dispenser Method:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

P117 **CHARLES T. AUTO REPAIR, INC.** **AST** **A100178200**
NE **212 56TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.152 mi.
803 ft. **Site 3 of 3 in cluster P**

Relative:
Higher

Actual:
38 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605965
Program Type:	PBS
UTM X:	582860.49823999999
UTM Y:	4499853.0318799997
Expiration Date:	2011/06/07

Affiliation Records:

Site Id:	27830
Affiliation Type:	Emergency Contact
Company Name:	CHARLES T. AUTO REPAIR, INC.
Contact Type:	Not reported
Contact Name:	CHARLES J. TORIBIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 439-8643
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/12/2006

CHARLES T. AUTO REPAIR, INC. (Continued) **A100178200**

Site Id:	27830
Affiliation Type:	On-Site Operator
Company Name:	CHARLES T. AUTO REPAIR, INC.
Contact Type:	Not reported
Contact Name:	CHARLES J. TORIBIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 439-8643
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/12/2006

Site Id:	27830
Affiliation Type:	Owner
Company Name:	CHARLES T. AUTO REPAIR, INC.
Contact Type:	PRESIDENT
Contact Name:	CHARLES J. TORIBIO
Address1:	212 56TH ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 439-8643
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/12/2006

Site Id:	27830
Affiliation Type:	Mail Contact
Company Name:	CHARLES T. AUTO REPAIR, INC.
Contact Type:	Not reported
Contact Name:	CHARLES J. TORIBIO
Address1:	212 56TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 439-8643
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/12/2006

Equipment Records:

D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None

CHARLES T. AUTO REPAIR, INC. (Continued) **A100178200**

C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
I00 - Overfill - None
J00 - Dispenser - None

Tank Info:

Tank Number:	275
Tank Id:	60767
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

R118 **NY Spills** **S106018162**
SE **65TH ST & 3RD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.154 mi.
815 ft. **Site 1 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

NY Spills:

Site ID:	85445
Facility Addr2:	Not reported
Facility ID:	0306385
Spill Number:	0306385
Facility Type:	ER
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Spill Date:	9/16/2003
Reported to Dept:	9/16/2003
CID:	418
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/13/2004
Remediation Phase:	0

(Continued) **S106018162**

Date Entered In Computer: 9/16/2003
Spill Record Last Update: 4/13/2004
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: SEAN DONOHUE
Contact Phone: (212) 689-1520
DEC Region: 2
DER Facility ID: 132735
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"
Remarks: comp called stated that a 1000ft oil slick in the street at the address provided. Some oil has made it to the sewer unknown of the amount

Material:
Site ID: 85445
Operable Unit ID: 875106
Operable Unit: 01
Material ID: 503609
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

R119 **MANHOLE 6077** **NY Spills** **S104508941**
SE **65TH ST & 3RD AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.154 mi.
815 ft. **Site 2 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

NY Spills:
Site ID: 156888
Facility Addr2: Not reported
Facility ID: 9911734
Spill Number: 9911734
Facility Type: ER
SWIS: 2401

MANHOLE 6077 (Continued) **S104508941**

Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	1/8/2000
Reported to Dept:	1/8/2000
CID:	205
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/4/2002
Remediation Phase:	0
Date Entered In Computer:	1/8/2000
Spill Record Last Update:	11/17/2004
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	132735
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" e2mis no. 129533: 1/08/2000 13:30 hrs S. Fuller #37342, Splicer with Underground, reports at 13:25 hrs found approx. 3 oz. oil leaked from shrink-covered straight joint on secondary paper-insulated lead cable (PILC) and ran back toward duct and down wall of MH-6077 -- N/E/C 65 St. & 3 Ave. No sewers or waterways affected. Env. stop tag #08333 placed. Fuller reports not enough oil on walls to take a sample. I contacted ERT M. Kessler regarding need for a sample -- he agrees that as per the "Revision 3 Interim Procedure dated 10/14/99...", section 2.1, secondary PILC cable is considered to be <50 ppm. Therefore no oil sample needed and cleanup to be done as <50 ppm. update 1-20-00 1930 hrs k.quest flush dept reports in mh6077 < 50 ppm cleanup completed and e.s.tag # 08333 was removed. NOTE: Joint was found repaired. No sump or drain in structure. Structure cleaned by double washing with slix. Liquid waste removed by tanker. Solid waste removed by vactor. Incident is closed.
Remarks:	caller reported 3oz with no water affected. con ed #129533. leak from secondary paper insulated lead cable. secondary pilc cable less than 50 ppm pcb's.cleanup to be completed.

Material:

Site ID:	156888
Operable Unit ID:	1090422
Operable Unit:	01
Material ID:	297181
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported

MANHOLE 6077 (Continued) **S104508941**

Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9911734
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	01/08/2000 13:25
Reported to Dept Date/Time:	01/08/00 15:07
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	CALLER
Spiller Phone:	(212) 580-6763
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	NEW YORK, NY -
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

MANHOLE 6077 (Continued) **S104508941**

Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/08/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/18/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: caller reported 3o with no water affected. con ed 129533. leak from secondary paper insulated lead cable. secondary pilc cable less than 50 ppm pcb s.cleanup to be completed.

R120 **MANHOLE 6022** **NY Spills** **S104508935**
SE **65TH ST & 3RD AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.154 mi.
815 ft. **Site 3 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

NY Spills:
Site ID: 66490
Facility Addr2: Not reported
Facility ID: 9911728
Spill Number: 9911728
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 1/8/2000
Reported to Dept: 1/8/2000
CID: 312
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended

MANHOLE 6022 (Continued) **S104508935**

UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/4/2002
Remediation Phase:	0
Date Entered In Computer:	1/8/2000
Spill Record Last Update:	11/17/2004
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	132735
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" e2mis no. 129531: S.Fuller #37342 mech a doing preinspection in mh 6022 found an undiaperable sheen of unknown oil on 5 gallons of water. contained to structure no sewers or waterways appear affected. sump not visiable due to dirt. there is a tank in structure, liquid sample taken with a emergency turnaround & stop tag #08332 placed. cleanup pending results. Update - Chem lab results recd 1/8/00 2205hrs - lsn# 00-00252 325ppm 1/8/00 - EPA # ISSUED. NYP004048369 update 1-9-2000 2010 hrs a. howell os flush reports in mh6022 (325 ppm) hole was double wash and cleanup was completed and e.s.tag 08332 was removed. found a 3" drain in hole. drain was inactive , found no oil in drain pipe. double wash pipe and cemented drain. found no earthen sump in hole. cleanup was completed at 2000 hrs. NOTE: THERE WAS NO LEAKING EQUIPMENT IN STRUCTURE.
Remarks:	UNDIAPERABLE SHEEN OF UNK OIL - CASE #129531 - SAMPLE TAKEN - MARK TIBBE CONTACTED. pcb is 325 ppm.

Material:

Site ID:	66490
Operable Unit ID:	1086335
Operable Unit:	01
Material ID:	297175
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported

MANHOLE 6022 (Continued) **S104508935**

Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9911728
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/08/2000 12:00
Reported to Dept Date/Time: 01/08/00 13:01
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/08/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/18/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False

MANHOLE 6022 (Continued) **S104508935**

Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: UNDIAPERABLE SHEEN OF UNK OIL - CASE 129531 - SAMPLE TAKEN - MARK TIBBE CONTACTED. pcb is 325 ppm.

R121 **7-ELEVEN #32884** **RCRA-NonGen** **1006810284**
SE **6499 3RD AVE** **FINDS** **NYR000109587**
1/8-1/4 **BROOKLYN, NY 11220**
0.156 mi.
824 ft. **Site 4 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: 7-ELEVEN #32884
Facility address: 6499 3RD AVE
BROOKLYN, NY 112204875
EPA ID: NYR000109587
Mailing address: BAKER RD
VIRGINIA BEACH, NY 23462
Contact: GARRY BLAIR
Contact address: BAKER RD
VIRGINIA BEACH, NY 23462
Contact country: US
Contact telephone: (757) 490-1711
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: 7-ELEVEN INC
Owner/operator address: PO BOX 711
DALLAS, TX 75221
Owner/operator country: US
Owner/operator telephone: (214) 828-0711
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: 7-ELEVEN INC
Owner/operator address: PO BOX 711
DALLAS, TX 75221
Owner/operator country: US
Owner/operator telephone: (214) 828-0711
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

7-ELEVEN #32884 (Continued) **1006810284**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: 7-ELEVEN #32884
Classification: Not a generator, verified

Date form received by agency: 10/02/2002
Facility name: 7-ELEVEN #32884
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110013291758

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

R122 **7-ELEVEN INC, STORE # 32884** **FINDS** **1011934813**
SE **301 65TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.157 mi.
827 ft. **Site 5 of 9 in cluster R**

Relative: Higher

Actual: 50 ft.

FINDS:

Registry ID: 110037583521

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is

7-ELEVEN INC, STORE # 32884 (Continued) **1011934813**

used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

R123 **7-ELEVEN #32884** **UST** **U004045728**
SE **301 65TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.157 mi.
827 ft. **Site 6 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

UST:

Facility Id:	2-607870
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2012/06/24
UTM X:	582578.42960000003
UTM Y:	4499175.5717799999

Affiliation Records:

Site Id:	29722
Affiliation Type:	Emergency Contact
Company Name:	7-ELEVEN, INC.
Contact Type:	Not reported
Contact Name:	JULIE SPENCER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(978) 589-3000
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	12/11/2007

Site Id:	29722
Affiliation Type:	Mail Contact
Company Name:	7-ELEVEN, INC.
Contact Type:	Not reported
Contact Name:	SUZANNE PARKER SCHWEIKART
Address1:	Not reported
Address2:	814 BAKER ROAD
City:	VIRGINIA BEACH
State:	VA
Zip Code:	23462
Country Code:	001
Phone:	(757) 490-6339
Phone Ext:	Not reported
Email:	BJOHNS03@7-11.COM
Fax Number:	Not reported

7-ELEVEN #32884 (Continued) **U004045728**

Modified By:	KXTANG
Date Last Modified:	11/20/2007
Site Id:	29722
Affiliation Type:	On-Site Operator
Company Name:	7-ELEVEN #32884
Contact Type:	Not reported
Contact Name:	7-ELEVEN, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-9280
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/1/2007
Site Id:	29722
Affiliation Type:	Owner
Company Name:	7-ELEVEN, INC.
Contact Type:	ENV COMPLIANCE SPECIALIST
Contact Name:	SUZANNE PARKER SCHWEIKART
Address1:	P.O.BOX 711
Address2:	Not reported
City:	DALLAS
State:	TX
Zip Code:	75221-0711
Country Code:	001
Phone:	(972) 828-0711
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	12/11/2007

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D11 - Pipe Type - Flexible Piping
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
F00 - Pipe External Protection - None
J01 - Dispenser - Submersible
J01 - Dispenser - Submersible
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin

7-ELEVEN #32884 (Continued) **U004045728**

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None

Tank Info:

Site ID:	29722
Tank Number:	001
Tank ID:	63675
Tank Status:	In Service
Tank Model:	104
Pipe Model:	Not reported
Install Date:	6/1/2003
Capacity Gallons:	12000
Tightness Test Method:	14
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	10/22/2003
Register:	True
Modified By:	dxliving
Last Modified:	12/11/2007

Site ID:	29722
Tank Number:	002
Tank ID:	63678
Tank Status:	In Service
Tank Model:	104
Pipe Model:	Not reported
Install Date:	6/1/2003
Capacity Gallons:	10000
Tightness Test Method:	14
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	10/22/2003
Register:	True
Modified By:	dxliving
Last Modified:	12/11/2007

R124 **CLOSED GAS STATION** **NY Spills** **S103574622**
SE **301 65TH ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.157 mi.
827 ft. **Site 7 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

NY Spills:

Site ID:	307847
Facility Addr2:	Not reported
Facility ID:	9810617
Spill Number:	9810617
Facility Type:	ER
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Spill Date:	11/21/1998
Reported to Dept:	11/21/1998
CID:	211
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	True
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/8/2000
Remediation Phase:	0
Date Entered In Computer:	11/21/1998
Spill Record Last Update:	4/1/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	MR MURALI
Contact Phone:	(718) 331-5003
DEC Region:	2
DER Facility ID:	248623
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND" 11/2/99 Sangesland spoke with Steven Hightower (attorney for property owner) Mr. Hightower received a letter from CPT telling him to put in 3 wells on site. He felt this was excessive. CPT was asked and CPT said Mr. Hightower could do a single well in the center of the tank area down to groundwater. If the well is clean, CPT would "Probably" close the site out. If the well has any problems, CPT would need to decide what to do next. 2/14/2000 Stephen Hightower (212-962-4888) submitted a set of documents requesting a closeout letter on the site. A well was installed in Dec '99 per our discussion. On 1/3/2000 a water sample was taken and tested. Unfortunately in CPT's letter to Mr. Hightower on 10/20/99 CPT requested water testing to 8021/8270 and MTBE. Instead of this, Mr. Hightower ran a test on BTEX and MTBE. 3/6/2000 Mr. Hightower called looking for a close out letter. Sangesland informed Mr. Hightower that another water test would be required and 8021/8270 would need to be run. A close out letter will be issued if these tests come back

CLOSED GAS STATION (Continued) **S103574622**

clean. 4/3/2000 Mr. Hightower called to follow up on a letter he submitted dated 3/29/2000. This letter shows that a new water sample was taken from the site on 3/8/2000 and submitted to Accutest. (Depth to water is 75 feet) Testing for 8270 shows all Non Detect..... 8021 shows 95% Non Detect and a couple of very minor hits. 8021 hits are: Chloroform 3.5 ug/l Methylene Chloride 2.6 ug/l Methyl Tert Butyl Ether 9.6 ug/l Bromodichforomethane 0.66 ug/l Everything else is Non Detect 5/8/2000 SANGESLAND SPOKE WITH JOE O'CONNELL CONCERNING LEVELS LISTED ABOVE. MR. O'CONNEL SAID ALL OF THESE ITEMS WERE BELOW CLASS GA WATER STANDARDS. OK TO CLOSE OUT. SPILL CLOSED 5/8/2000 - CLOSE OUT LETTER SENT TO: Kenneth Lee Raich Esq. Ref: Estate of James Mannix 1 Edgewater Plaza - Suite 306 Staten Island, NY 10305 fax copy to Stephen Hightower 212-406-3340

Remarks: CALLER REMOVING TANK AND FOUND SOIL CONTAMINATION UNDER ISLAND - POSSIBLE CAUSE LEAK FROM PUMP - PBS # FOR TANK 2-600368

Material:

Site ID:	307847
Operable Unit ID:	1071650
Operable Unit:	01
Material ID:	566459
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9810617
Investigator:	SANGESLAND
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/21/1998 13:00
Reported to Dept Date/Time:	11/21/98 13:42
SWIS:	61

CLOSED GAS STATION (Continued) **S103574622**

Spiller Name: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Contact: MR MURALI
Spiller Phone: (718) 331-5003
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 05
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: True
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/08/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/21/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/08/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 11/2/99 Sangesland spoke with Steven Hightower attorney for property owner) Mr. Hightower received a letter from CPT telling him to put in 3 wells on site. He felt this was excessive. CPT was asked and CPT said Mr. Hightower could do a single well in the center of the tank area down to groundwater. If the well is clean, CPT would Probably close the site out. If the well has any problems, CPT would need to decide what to do next. 2/14/2000 Stephen Hightower 212-962-4888) submitteda set of documents requesting a closeout

CLOSED GAS STATION (Continued) **S103574622**

letter on the site. A well was installed in Dec 99 per our discussion. On 1/3/2000 a water sample was taken and tested. Unfortunately in CPT s letter to Mr. Hightower on 10/20/99 CPT requested water testing to 8021/8270 and MTBE. Instead of this, Mr. Hightower ran a test on BTEX and MTBE. 3/6/2000 Mr. Hightower called looking for a close out letter. Sangesland informed Mr. Hightower that another water test would be required and 8021/8270 wouldneed to be run. A close out letter will be issued if these tests come back clean. 4/3/2000 Mr. Hightower called to follow up on a letter he submitted dated 3/29/2000. This letter shows that a new water sample was taken from the site on 3/8/2000 and submitted to Accutest. Depth to water is 75 feet) Testing for 8270 shows all Non Detect..... 8021 shows 95 Non Detect and a couple of very minor hits. 8021 hits are: Chloroform 3.5 ug/l Methylene Chloride 2.6 ug/l Methyl Tert Butyl Ether 9.6 ug/l Bromodichforomethane 0.66 ug/l Everything else is Non Detect 5/8/2000 SANGESLAND SPOKE WITH JOE O CONNELL CONCERNING LEVELS LISTED ABOVE. MR. O CONNEL SAID ALL OF THESE ITEMS WERE BELOW CLASS GA WATER STANDARDS. OK TO CLOSE OUT. SPILL CLOSED 5/8/2000 - CLOSE OUT LETTER SENT TO: Kenneth Lee Raich Esq. Ref: Estate of James Mannix 1 Edgewater Pla a - Suite 306 Staten Island, NY 10305 fax copy to Stephen Hightower 212-406-3340

Remark: CALLER REMOVING TANK AND FOUND SOIL CONTAMINATION UNDER ISLAND - POSSIBLE CAUSE LEAK FROM PUMP - PBS FOR TANK 2-600368

R125 **L & S SERVICE CENTER INC** **UST U001841418**
SE **301 65TH STREET** **HIST UST N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.157 mi.
827 ft. **Site 8 of 9 in cluster R**

Relative:
Higher

Actual:
50 ft.

UST:

Facility Id:	2-600368
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582576.82820999995
UTM Y:	4499162.9006700004

Affiliation Records:

Site Id:	22351
Affiliation Type:	Mail Contact
Company Name:	L & S SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	NICHOLAS LADA
Address1:	301 65TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 439-4747
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id: 22351

L & S SERVICE CENTER INC (Continued) **U001841418**

Affiliation Type:	On-Site Operator
Company Name:	L & S SERVICE CENTER INC
Contact Type:	Not reported
Contact Name:	NICHOLAS LADAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-4747
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22351
Affiliation Type:	Emergency Contact
Company Name:	KENNETH LEE RAISCH
Contact Type:	Not reported
Contact Name:	NICHOLAS LADAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-4858
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	22351
Affiliation Type:	Owner
Company Name:	KENNETH LEE RAISCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	ONE EDGEWATER PLAZA
Address2:	Not reported
City:	STATEN ISLAND
State:	NY
Zip Code:	10305
Country Code:	001
Phone:	(718) 816-1131
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None

L & S SERVICE CENTER INC (Continued) **U001841418**

A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
I00 - Overfill - None
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J00 - Dispenser - None
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
H00 - Tank Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G01 - Tank Secondary Containment - Diking (Aboveground)
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
B00 - Tank External Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None

L & S SERVICE CENTER INC (Continued) **U001841418**

H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
B00 - Tank External Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
I00 - Overfill - None
G01 - Tank Secondary Containment - Diking (Aboveground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
I00 - Overfill - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J00 - Dispenser - None
A00 - Tank Internal Protection - None
I00 - Overfill - None

L & S SERVICE CENTER INC (Continued) **U001841418**

H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None

Tank Info:

Site ID:	22351
Tank Number:	001
Tank ID:	42371
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	002
Tank ID:	42372
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	003
Tank ID:	42373
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03

L & S SERVICE CENTER INC (Continued) **U001841418**

Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	004
Tank ID:	42374
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	005
Tank ID:	42375
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	006
Tank ID:	42376
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03

L & S SERVICE CENTER INC (Continued) **U001841418**

Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	007
Tank ID:	42377
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	008
Tank ID:	42378
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	009
Tank ID:	42379
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03

L & S SERVICE CENTER INC (Continued) **U001841418**

Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	010
Tank ID:	42380
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	011
Tank ID:	42381
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03
Next Test Date:	Not reported
Date Tank Closed:	11/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	7/1/1995
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	22351
Tank Number:	012
Tank ID:	42382
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	03

L & S SERVICE CENTER INC (Continued) **U001841418**

Next Test Date: Not reported
Date Tank Closed: 11/1/1998
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 7/1/1995
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

Site ID: 22351

Tank Number: 013
Tank ID: 42383
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4000
Tightness Test Method: 03
Next Test Date: Not reported
Date Tank Closed: 11/1/1998
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: 7/1/1995
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

Site ID: 22351

Tank Number: 014
Tank ID: 55700
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: 11/1/1998
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

HIST UST:
PBS Number: 2-600368
SPDES Number: Not reported
Emergency Contact: NICHOLAS LADAS
Emergency Telephone: (718) 439-4858
Operator: NICHOLAS LADAS
Operator Telephone: (718) 439-4747
Owner Name: KENNETH LEE RAISCH
Owner Address: ONE EDGEWATER PLAZA
Owner City,St,Zip: STATEN ISLAND, NY 10305

L & S SERVICE CENTER INC (Continued) **U001841418**

Owner Telephone:	(718) 816-1131
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	L & S SERVICE CENTER, INC.
Mailing Address:	301 65TH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	NICHOLAS LADA
Mailing Telephone:	(718) 439-4747
Owner Mark:	Second Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	301 65 STREET
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/21/1998
Expiration Date:	12/17/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing

L & S SERVICE CENTER INC (Continued) **U001841418**

Date Closed: 11/01/1998
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: 8
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: 07/01/1995
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1998
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 003
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: 8
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: 07/01/1995
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1998
Test Method: Horner EZ Check
Deleted: False

L & S SERVICE CENTER INC (Continued) **U001841418**

Updated: True
Lat/long: Not reported

Tank Id: 004
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: 8
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: 07/01/1995
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1998
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 005
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: 8
Leak Detection: None
Overfill Prot: None
Dispenser: Not reported
Date Tested: 07/01/1995
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1998
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

L & S SERVICE CENTER INC (Continued) **U001841418**

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	008
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed

L & S SERVICE CENTER INC (Continued) **U001841418**

Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	009
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	010
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE

L & S SERVICE CENTER INC (Continued) **U001841418**

Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	011
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	012
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None

L & S SERVICE CENTER INC (Continued) **U001841418**

Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	013
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	8
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Not reported
Date Tested:	07/01/1995
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1998
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	014
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	NONE
Pipe Internal:	None

L & S SERVICE CENTER INC (Continued) **U001841418**

Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1998
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

S126 **SEI CO REALTY ASSOC LLC** **AST** **U003396126**
ESE **5800 3 AVE** **HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.158 mi.
832 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
62 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-601316
Program Type:	PBS
UTM X:	582942.48300999997
UTM Y:	4499594.0142099997
Expiration Date:	N/A

Affiliation Records:

Site Id:	23283
Affiliation Type:	Mail Contact
Company Name:	SEI CO REALTY ASSOC LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5800 3 AVE
Address2:	5800 3 AVE
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 492-3800
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23283
Affiliation Type:	Owner
Company Name:	SEI CO REALTY ASSOC LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5800 3 AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY

SEI CO REALTY ASSOC LLC (Continued) **U003396126**

Zip Code:	11220
Country Code:	001
Phone:	(718) 492-3800
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23283
Affiliation Type:	On-Site Operator
Company Name:	SEI CO REALTY ASSOC LLC
Contact Type:	Not reported
Contact Name:	KEITH SIMONELLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7513
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23283
Affiliation Type:	Emergency Contact
Company Name:	SEI CO REALTY ASSOC LLC
Contact Type:	Not reported
Contact Name:	KEITH SIMONELLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-7513
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B05 - Tank External Protection - Jacketed
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction
G01 - Tank Secondary Containment - Diking (Aboveground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I01 - Overfill - Float Vent Valve
A01 - Tank Internal Protection - Epoxy Liner

Tank Info:

SEI CO REALTY ASSOC LLC (Continued) **U003396126**

Tank Number:	1
Tank Id:	45423
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1950
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	4/1/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-601316
SWIS Code:	6101
Operator:	KEITH SIMONELLI
Facility Phone:	(718) 492-7513
Facility Addr2:	5800 3 AVE
Facility Type:	MANUFACTURING
Emergency:	KEITH SIMONELLI
Emergency Tel:	(718) 492-7513
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	SEI CO REALTY ASSOC LLC
Owner Address:	5800 3 AVE
Owner City,St,Zip:	BROOKLYN, NY 11220
Federal ID:	Not reported
Owner Tel:	(718) 492-3800
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	SEI CO REALTY ASSOC LLC
Mailing Address:	5800 3 AVE
Mailing Address 2:	5800 3 AVE
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Telephone:	(718) 492-3800
Owner Mark:	Second Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Certification Flag:	False
Certification Date:	Not reported
Expiration:	06/11/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False

SEI CO REALTY ASSOC LLC (Continued) **U003396126**

CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	1
Tank Location:	ABOVEGROUND
Tank Status:	Closed-Removed
Install Date:	19501201
Capacity (Gal):	10000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	1
Tank External:	5
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	6
Tank Containment:	8
Leak Detection:	5
Overfill Protection:	1
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	04/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

T127 **6701 COLONIAL APTS., LLC** **AST** **A100300201**
SW **6701 COLONIAL ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.161 mi.
851 ft. **Site 1 of 2 in cluster T**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-046388
Program Type:	PBS
UTM X:	581998.80212999997
UTM Y:	4499202.4287299998
Expiration Date:	2011/12/02

Affiliation Records:

Site Id:	652
Affiliation Type:	Owner
Company Name:	6701 COLONIAL APTS., LLC
Contact Type:	MEMBER
Contact Name:	ZEV POLLAK
Address1:	1388 E 15 ST
Address2:	Not reported
City:	BROOKLYN

6701 COLONIAL APTS., LLC (Continued) **A100300201**

State: NY
Zip Code: 11230
Country Code: 001
Phone: (718) 339-0500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/2/2006

Site Id: 652
Affiliation Type: Mail Contact
Company Name: 6701 COLONIAL APTS., LLC
Contact Type: Not reported
Contact Name: ZEV POLLAK
Address1: 1388 E 15 ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11230
Country Code: 001
Phone: (718) 339-0500
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/2/2006

Site Id: 652
Affiliation Type: On-Site Operator
Company Name: 6701 COLONIAL APTS., LLC
Contact Type: Not reported
Contact Name: TAIP QOKU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 745-6071
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 652
Affiliation Type: Emergency Contact
Company Name: 6701 COLONIAL APTS., LLC
Contact Type: Not reported
Contact Name: ZEV POLLAK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999

6701 COLONIAL APTS., LLC (Continued) **A100300201**

Phone:	(718) 339-0500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	10/25/2006

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
G07 - Tank Secondary Containment - Excavation/Trench Liner System
H99 - Tank Leak Detection - Other
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:

Tank Number:	001
Tank Id:	1483
Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1928
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	11/2/2006

T128 **6701 COLONIAL APTS., LLC** **HIST UST** **U000393796**
SW **6701 COLONIAL ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.161 mi.
851 ft. **Site 2 of 2 in cluster T**

Relative:
Higher

Actual:
42 ft.

HIST UST:

PBS Number:	2-046388
SPDES Number:	Not reported
Emergency Contact:	ZEV POLLAK
Emergency Telephone:	(718) 851-4100
Operator:	TAIP QOKU
Operator Telephone:	(718) 745-6071
Owner Name:	6701 COLONIAL APTS., LLC
Owner Address:	4917 12TH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11219
Owner Telephone:	(718) 851-4100
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	6701 COLONIAL APTS., LLC

6701 COLONIAL APTS., LLC (Continued) **U000393796**

Mailing Address:	4917 12TH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11219
Mailing Contact:	ZEV POLLAK
Mailing Telephone:	(718) 851-4100
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	6701 COLONIAL RD
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	08/31/2001
Expiration Date:	12/02/2006
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19281201
Capacity (gals):	3000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Vault (w/o access)
Leak Detection:	Other
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False

6701 COLONIAL APTS., LLC (Continued) **U000393796**

Updated: False
Lat/long: Not reported

129
ENE
1/8-1/4
0.168 mi.
887 ft.

SERVICE BOX - #SB51643
IFO 245 56TH ST
BROOKLYN, NY

NY Spills **S104193683**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
45 ft.

NY Spills:

Site ID:	68653
Facility Addr2:	Not reported
Facility ID:	9905455
Spill Number:	9905455
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	8/5/1999
Reported to Dept:	8/5/1999
CID:	390
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/5/1999
Remediation Phase:	0
Date Entered In Computer:	8/5/1999
Spill Record Last Update:	5/25/2000
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	MIKE CESARE
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	65364
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" con ed e2mis notes: Found 1-1/2 pt of unknown oil on 20 gallons of water in S/B 51643. The water in S/B was turned into I&A services because of customers complaint of water leak into basement. 1 liquid sample was taken. Attempted to take 2 oil sample for i.d. only found car parked over mh no parking monday and thursday 9:30 am, Melvyn Baptiste, was asked to check on the customer's end line box to verify that it was dry. Confirmed this time 16:00 hrs, that it is. RECD chem lab results lab seq#99-08165<1ppm Inspecting pull boxes of 243 56th st and 245 56th st. both boxes were found to be free of any trace of oil and were also found cemented. Both customers were satisfied with findings. Clean up completed 8/7/99 1900hrs as per K.Quest and G.Kern, flush operators, env. ops. env. stop tag removed.

SERVICE BOX - #SB51643 (Continued) **S104193683**

Remarks: 1.5 PINTS OF UNK OIL IN THE SERVICE BOX - CLEAN UP PENDING LAB RESULTS CON ED #127063

Material:

Site ID:	68653
Operable Unit ID:	1079988
Operable Unit:	01
Material ID:	301748
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9905455
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	08/05/1999 11:30
Reported to Dept Date/Time:	08/05/99 12:34
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Contact:	MIKE CESARE
Spiller Phone:	(212) 580-6763
Spiller Address:	UNK
Spiller City,St,Zip:	UNK, NY
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Local Agency
PBS Number:	Not reported

SERVICE BOX - #SB51643 (Continued) **S104193683**

Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/05/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/05/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/25/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: con ed e2mis notes: Found 1-1/2 pt of unknown oil on 20 gallons of water in S/B 51643. The water in S/B was turned into I A services because of customers complaint of water leak into basement. 1 liquid sample was taken. Attempted to take 2 oil sample for i.d. only found car parked over mh no parking monday and thursday 9:30 am, Melvyn Baptiste, was asked to check on the customer s end line box to verify that it was dry. Confirmed this time 16:00 hrs, that it is. RECD chem lab results lab seq 99-08165<1ppm Inspecting pull boxes of 243 56th st and 245 56th st. both boxes were found to be free of any trace of oil and were also found cemented. Both customers were satisfied with findings. Clean up completed 8/7/99 1900hrs as per K.Quest and G.Kern, flush operators, env. ops. env. stop tag removed.
Remark: 1.5 PINTS OF UNK OIL IN THE SERVICE BOX - CLEAN UP PENDING LAB RESULTS CON ED 127063

U130 **ENGINE CO. 241/LADD. CO. 109 FDNY -DDC** **NY Spills** **S103036587**
SSE **6630 THIRD AVENUE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.168 mi.
887 ft. **Site 1 of 11 in cluster U**

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	162667
Facility Addr2:	Not reported
Facility ID:	9713690
Spill Number:	9713690
Facility Type:	ER
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Spill Date:	11/6/1997
Reported to Dept:	3/10/1998
CID:	282
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt:	2/17/2005
Remediation Phase:	0
Date Entered In Computer:	3/10/1998
Spill Record Last Update:	2/17/2005
Spiller Name:	N/A
Spiller Company:	NYC FIRE DEPT 241
Spiller Address:	6630 THIRD AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	N/A
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	137227
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY" The site was remediated under NYCDDC Consent Order. CM - LiRo Engineering. SVE system was installed. NFA letter was issued on Dec. 2003. Alex Zhitomirsky 2/17/2005
Remarks:	they got soil samples back and diesel was found in the sample.unknown how the diesel got into the soil.there was no discoloration no obm readings tnaks were structuraaly sound.tanks were in a vault.samples were taken from the end walls.

Material:

Site ID:	162667
Operable Unit ID:	1056550
Operable Unit:	01
Material ID:	324689
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum

ENGINE CO. 241/LADD. CO. 109 FDNY -DDC (Continued) **S103036587**

Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9713690
Investigator:	ZHITOMIRSKY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/06/1997 12:00
Reported to Dept Date/Time:	03/10/98 15:38
SWIS:	61
Spiller Name:	NYC FIRE DEPT 241
Spiller Contact:	N/A
Spiller Phone:	Not reported
Spiller Contact:	N/A
Spiller Address:	6630 THIRD AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /

ENGINE CO. 241/LADD. CO. 109 FDNY -DDC (Continued) **S103036587**

Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/10/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/11/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: they got soil samples back and diesel was found in the sample.unknown how the diesel got into the soil.there was no discoloration no obm readings tnaks were structuraaly sound.tanks were in a vault.samples were taken from the end walls.

U131 **NYFD CO 241** **LTANKS** **S102960506**
SSE **6630 3RD AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.168 mi.
887 ft. **Site 2 of 11 in cluster U**

Relative:
Higher

Actual:
56 ft.

LTANKS:
Site ID: 313652
Spill No: 9711208
Spill Date: 1/6/1998
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 1/6/1998
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 1/6/1998
CID: 233
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False

NYFD CO 241 (Continued) **S102960506**

Remediation Phase:	0
Date Entered In Computer:	1/6/1998
Spill Record Last Update:	7/7/2005
Spiller Name:	Not reported
Spiller Company:	NYFD CO 241
Spiller Address:	6630 3RD AVE
Spiller City,St,Zip:	BROOKLYN, NY 11220-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	137227
Remarks:	new install tank underground on filling product came out thru vent unk cause may be an overfill or some problem in tank

Material:

Site ID:	313652
Operable Unit ID:	1057710
Operable Unit:	01
Material ID:	325914
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8
Units:	Gallons
Recovered:	8
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	2
Spill Number:	9711208
Spill Date:	01/06/1998
Spill Time:	12:55
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	01/06/98

NYFD CO 241 (Continued) **S102960506**

Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: ZHITOMIRSKY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 01/06/98
Reported to Department Time: 14:48
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYFD CO 241
Spiller Address: 6630 3RD AVE
Spiller City,St,Zip: BROOKLYN, NY 11220-
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (718) 965-8241
Facility Extention: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/06/98
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 01/15/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 8
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 8
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported

NYFD CO 241 (Continued) **S102960506**

Last Date: 19940728
DEC Remarks: 1,00 GALS TANK. 700 GALS WERE PUT IN. IT S NOT AN OVERFILL. TANK WILL BE STICKED TOMORROW, CHECK GAGES.
Spill Cause: new install tank underground on filling product came out thru vent unk cause may be an overfill or some problem in tank

---

U132 **ENGINE 241 / LADDER 109** **UST** **U001840049**
SSE **6630 3RD AVENUE** **HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.168 mi.
887 ft. **Site 3 of 11 in cluster U**

Relative:
Higher

Actual:
56 ft.

UST:
Facility Id: 2-357480
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2014/07/21
UTM X: 582464.07490000001
UTM Y: 4499022.5109900003

Affiliation Records:
Site Id: 17898
Affiliation Type: On-Site Operator
Company Name: ENGINE 241 / LADDER 109
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-8241
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 17898
Affiliation Type: Mail Contact
Company Name: N Y F D-BUILDING MAINTENANCE
Contact Type: Not reported
Contact Name: ASST COMMR JOSEPH M. MASTROPIETRO
Address1: 48-34 35TH STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 784-6510
Phone Ext: Not reported
Email: MASTROY@FDNY.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 9/17/2009

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Site Id:	17898
Affiliation Type:	Emergency Contact
Company Name:	N Y F D
Contact Type:	Not reported
Contact Name:	F.D.N.Y.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-7900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/30/2009

Site Id:	17898
Affiliation Type:	Owner
Company Name:	N Y F D
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METRO TECH
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-7900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/30/2009

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
D02 - Pipe Type - Galvanized Steel
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F04 - Pipe External Protection - Fiberglass
B00 - Tank External Protection - None

ENGINE 241 / LADDER 109 (Continued) **U001840049**

H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
D02 - Pipe Type - Galvanized Steel
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
A99 - Tank Internal Protection - Other
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Info:

Site ID:	17898
Tank Number:	001
Tank ID:	35081
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Site ID:	17898
Tank Number:	002
Tank ID:	35082
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	17898
Tank Number:	003
Tank ID:	35083
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	17898
Tank Number:	004
Tank ID:	35084
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1972
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Site ID: 17898

Tank Number: 005
Tank ID: 35085
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 11/1/1972
Capacity Gallons: 2500
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank Location: 6
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

Site ID: 17898

Tank Number: 006
Tank ID: 55027
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 1/1/1998
Capacity Gallons: 1000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank Location: 5
Tank Type: Equivalent technology
Date Test: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 9/17/2009

HIST UST:
PBS Number: 2-357480
SPDES Number: Not reported
Emergency Contact: F.D.N.Y.
Emergency Telephone: (718) 403-1580
Operator: COMPANY OFFICER
Operator Telephone: (718) 965-8241
Owner Name: N Y F D
Owner Address: 9 METRO TECH
Owner City,St,Zip: BKLN, NY 11201-3857
Owner Telephone: (718) 999-2094
Owner Type: Local Government
Owner Subtype: The City of New York
Mailing Name: N Y F D-BUILDING MAINTENANCE
Mailing Address: 48-34 35TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: DIRECTOR
Mailing Telephone: (718) 784-6510

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	6630 3RD AVENUE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	09/04/1998
Expiration Date:	07/28/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	1000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19721101
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	12/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Tank Status:	Closed-Removed
Install Date:	19721101
Capacity (gals):	550
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	12/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19721101
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	12/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19721101
Capacity (gals):	550

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1997
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 005
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-Removed
Install Date: 19721101
Capacity (gals): 2500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Diking
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 006
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 19980101
Capacity (gals): 1000
Product Stored: DIESEL
Tank Type: Fiberglass reinforced plastic [FRP]
Tank Internal: Other

ENGINE 241 / LADDER 109 (Continued) **U001840049**

Tank External:	Fiberglass
Pipe Location:	Underground
Pipe Type:	STAINLESS STEEL ALLOY
Pipe Internal:	Other
Pipe External:	Fiberglass
Second Containment:	Vault (w/access)
Leak Detection:	14
Overfill Prot:	High Level Alarm
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

U133 **CON EDISON** **NY Spills** **S103038661**
SSE **W49TH ST - SPRINBROOK S/S** **NY Hist Spills** **N/A**
1/8-1/4 **MANHATTAN - BRONX, NY**
0.168 mi.
887 ft. **Site 4 of 11 in cluster U**

Relative:
Higher

Actual:
55 ft.

NY Spills:

Site ID:	142049
Facility Addr2:	Not reported
Facility ID:	9510768
Spill Number:	9510768
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	11/27/1995
Reported to Dept:	11/27/1995
CID:	282
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/12/2008
Remediation Phase:	0
Date Entered In Computer:	11/27/1995
Spill Record Last Update:	5/12/2008
Spiller Name:	ANDREW PETE
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	MR GRANDY
Contact Phone:	(212) 580-6662

CON EDISON (Continued) **S103038661**

DEC Region: 2
DER Facility ID: 121261
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Original spill rpeort was for Feeder M52 from W.49th St substation to Sprainbrook substation. (JHO) 11/27/95 - UPDATE FROM CON ED CIG CONSTANTINE - UNCONTAINED - THEY HAVE PEOPLE OUT CHECKING MANHOLES - 350 GALLONS IS DISCREPANCY IN METER READING - FEEDER SPILL UNDER WATER GOETHALS - GOWANUS UNCONFIRMED - MISSING 350 GALLONS. 5/12/08: Spill submitted for closure by Con Ed. Sent e-mail to Con Ed (Rich Lund) requesting clarification: "The referenced spill was submitted for closure with the March submittals. The spreadsheet states: 'On August 25, 2005, Transmission Operations inspected Manhole 61736, Feeder M52 and reports that no oil was found in this structure.' How and when was the spill located in that manhole? The report submitted for that spill (see attached) seems to reference a spill in manhole 66772 in Brooklyn, which is not along the run of feeder M52. Please have S&TO clarify the discrepancy and provide explanation as to why MH 61736 was checked." Spoke later with Richie Lund and Tom McCreight. It appears that CIG transposed the feeder number on the original spill report to read Feeder 52 instead of Feeder 25. Since the updated report states unequivically that the leak of 350 gallons was located in manhole 66772 on feeder 25 in Brooklyn, told R. Lund to have S&TO inspect that manhole and provide results for closure of this spill. Con Ed (R. Lund) sent e-mail: "The attached documentation (in PDF format) is 1) A Work Order Report for Feeder Inspection in Manhole 66772 and 2) A Field Visit Hours Report for Manhole 66772. On May 23, 2005, a feeder inspection was performed on Manhole 66772 and there was no oil found in the structure. This information is indicated in the Work Order Report next to Ops - 4, Description - OIL IN MANHOLE." Close. (JHO)
Remarks: FEEDER STATION M52 SUBSTATION WEST 49TH STREET TO SPRINBROOK SUBSTATION IS WHERE THE SPILL OCCURRED.SPILL STARTED OVER A 5 DAY PERIOD.THIS SPILL IS 360 GALLONS.

Material:
Site ID: 142049
Operable Unit ID: 1025207
Operable Unit: 01
Material ID: 358120
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 360
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported

CON EDISON (Continued) **S103038661**

Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9510768
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/27/1995 15:00
Reported to Dept Date/Time: 11/27/95 16:13
SWIS: 62
Spiller Name: CON EDISON
Spiller Contact: ANDREW PETE
Spiller Phone: (212) 460-3849
Spiller Contact: MR GRANDY
Spiller Phone: (212) 580-6662
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Other
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 02
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/27/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/02/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

CON EDISON (Continued) **S103038661**

Material:
- Material Class Type: Petroleum
- Quantity Spilled: 360
- Unkonwn Quantity Spilled: False
- Units: Gallons
- Quantity Recovered: 0
- Unkonwn Quantity Recovered: True
- Material: DIELECTRIC FLUID
- Class Type: DIELECTRIC FLUID
- Times Material Entry In File: 41
- CAS Number: Not reported
- Last Date: Not reported
- DEC Remarks: UNCONTAINED - THEY HAVE PEOPLE OUT CHECKING MANHOLES - 3350 GALLONS IS DISCREPANCY IN METER READING - 11/27/95 - SPOKE TO MR. CONSTANTINE, FEEDER SPILL UNDER WATER GOETHALS - GOWANUS UNCONFIRMED - MISSING 350 GALLONS - PEOPLE OUT CHECKING WALKING ROUTE TO CHECK.
- Remark: FEEDER STATION M52 SUBSTATION WEST 49TH STREET TO SPRINBROOK SUBSTATION IS WHERE THE SPILL OCCURRED.SPILL STARTED OVER A 5 DAY PERIOD.THIS SPILL IS 360 GALLONS.

U134 **CONSOLIDATED EDISON** **MANIFEST** **1009241829**
SSE **WAKEMAN PL & 3 AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.168 mi.
887 ft. **Site 5 of 11 in cluster U**

Relative:
Higher

Actual:
55 ft.

NY MANIFEST:
- EPA ID: NYP004103628
- Country: USA
- Mailing Name: CONSOLIDATED EDISON
- Mailing Contact: FRANKLIN MURRAY
- Mailing Address: 4 IRVING PLACE RM 828
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: 212-460-2808

- Document ID: NYE1311894
- Manifest Status: Not reported
- Trans1 State ID: NYD006982359
- Trans2 State ID: Not reported
- Generator Ship Date: 10/31/2002
- Trans1 Recv Date: 10/31/2002
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 10/31/2002
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004103628
- Trans1 EPA ID: NYD980593636
- Trans2 EPA ID: Not reported
- TSDF ID: 20856AD
- Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
- Quantity: 03336

CONSOLIDATED EDISON (Continued) **1009241829**

Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYE1273842
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/31/2002
Trans1 Recv Date: 10/31/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/04/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004103628
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 96590JE
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00188
Units: K - Kilograms (2.2 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2002

Document ID: NYE0679437
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/15/2002
Trans1 Recv Date: 10/15/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004103628
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: 20854AD
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 00300
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYE0629298

CONSOLIDATED EDISON (Continued) **1009241829**

Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	NYD006982359
Generator Ship Date:	10/15/2002
Trans1 Recv Date:	10/15/2002
Trans2 Recv Date:	10/16/2002
TSD Site Recv Date:	10/17/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004103628
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	28190AU
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00315
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2002

U135 **CONSOLIDATED EDISON** **MANIFEST** **1009243712**
SSE **3 AVE & WAKEMAN PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.168 mi.
887 ft. **Site 6 of 11 in cluster U**

Relative:
Higher

Actual:
55 ft.

NY MANIFEST:

EPA ID:	NYP004132460
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYE0777519
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/16/2005
Trans1 Recv Date:	06/16/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004132460
Trans1 EPA ID:	12446JT
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES

CONSOLIDATED EDISON (Continued) **1009243712**

Quantity:	00162
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	Not reported

Document ID:	NYE0777519
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/16/2005
Trans1 Recv Date:	06/16/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004132460
Trans1 EPA ID:	12446JT
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00162
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	2005

U136 **NY Spills** **S106001349**
SSE **3RD AVE & WAKEMAN PL** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.168 mi.
887 ft. **Site 7 of 11 in cluster U**

Relative:
Higher

Actual:
55 ft.

NY Spills:

Site ID:	63233
Facility Addr2:	Not reported
Facility ID:	0111172
Spill Number:	0111172
Facility Type:	ER
SWIS:	2401
Investigator:	AERODRIG
Referred To:	Not reported
Spill Date:	2/24/2002
Reported to Dept:	2/24/2002
CID:	266
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended

(Continued) **S106001349**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/17/2003
Remediation Phase:	0
Date Entered In Computer:	2/25/2002
Spill Record Last Update:	4/17/2003
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	61143
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ" e2mis notes: 2/ 24/ 02 20: 05 HRS. P. KELLY #16016, FIELD OPERATOR WITH F. O. D. ON LOCATION TO MARK PHASES ON FEEDER 8B82, REPORTS AT 19: 55 HRS. FOUND APPROX. 5 GAL. UNKNOWN OIL ON APPROX. 300 GAL. WATER IN MH- 75218. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE/ SMOKE INVOLVED. ENV. STOP TAG #08923 PLACED. LIQUID SAMPLE TAKEN ON "E" PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # AA- 27026. CLEANUP PENDING RESULTS FROM CHEM LAB. NO PARKING ANYTIME, EXCEPT AUTHORIZED VEHICLES (LOCATED NEAR FIREHOUSE). 2/ 24/ 02 20: 50 HRS. -- SAMPLE DELIVERED TO CHEM LAB AT THIS TIME. -- W. W. #17344 -- 2/ 24/ 02 21: 07 HRS. -- NOTIFIED A. NATALE OF CIG. -- W. W. #17344 -- UPDATE @ 0100HRS 2/ 25 TEST RESULTS RECEIVED SEQ # 02- 01570- 001 @ 2489 PPM. #12255 VDC. UPDATE EPA # NYP004096285 TANKER ORDERED FOR AM SHIFT. #12255 VDC. UPDATE: 2/ 25/ 02 - 0840 DUE TO HIGH LAB RESULT & HAVING TO TAKE WIPE SAMPLES, THE INCIDENT TYPE FOR THIS INCIDENT HAS BEEN CHANGED FROM SPILL - DEMINIMUS (24 HR UNDERGROUND) TO SPILL - OIL (UNKNOWN TYPE). TJ - 50495 UPDATE: 2/25/02 - 1000 E. WILLIAMS - O.S. - ENV. OPS., REPORTS FINDING AN EARTHEN SUMP IN STRUCTURE. SUMP WILL BE DUG DOWN APPROX 1 FT AND SAMPLES TAKEN. UPDATE 2-25-02 1120 HRS E. WILLIAMS OS FLUSH DEPT REPORTS THAT THIS IS A NEW MANHOLE WHICH IS NOT ON THE C&D PLATES. THERE IS A D-FAULT #344 IN STRUCTURE JOINTS UP THE DUCT AND A JOINT LAYING ON FLOOR BURIED IN CEMENT. SERV BUR OS K. NEWLAND PLACED D- FAULT TAG # 344. E. WILLIAMS ALSO REPORTS THEY REMOVED ALL LIQUIDS FROM THE TOP WITH AND OVER 50 PPM TANKER. THEY ALSO FOUND A EARTHEN IN STRUCTURE. COULD NOT CLEAN EARTHEN SUMP AT THIS TIME DUE TO D-FAULT IN STRUCTURE. LAZ # 04425 3-27-02 14:00hrs QUIJIJIE (ENV OPS) REPORTS, FOUND 100 GALLONS OF WATER IN STRUCTURE AND PPE. PPE WILL BE BARRELED AND TAKEN AWAY WHEN CLEANUP IS COMPLETED. S.PACE 49874. NEW EPA # ISSUED 10/14/02 - 1340. NYP 004 103 628. UPDATE: OCT-15-2002 1915HRS A WALKER ENVIROMENTAL O/S REPORTS. REMOVED 75 GALLONS LIQUID WITH CONED OVER 50 TANKER. 4 DRUMS OF SOILD DEBRIS. #9 ON LOCATION CLEARED D- FAULT. 2 SUMP SAMPLES TAKEN. AND CEMENTED SUMP. MEET UNDERGROUND TO RERACK SO WE CAN FINISH CLEANUP. UPDATE OCT-16-2002 1610HRS SUMP SAMPLES RECEIVED. LAB SEQ 02-09669-001 SUMP WALLS 5 PPM.... SEQ 02-09669-004 SUMP BOTTOM 7 PPM... 10/31/02=1125HRS O.S. SCARPINITO REPORTS U/G RERACKED CABLE AT 0300HRS . ENVIR OPS DOUBLE WASHED & SODA BLASTED STRUCTURE . 860 GALLONS OF LIQUIDS REMOVED WITH ASTORIA TANKER. 0830HRS CHEMIST ARRIVED AND TOOK 21 WIPE SAMPLES. 1030HRS 3-DRUMS PICKED UP . TAG REMAINS PENDING WIPE SAMPLES. UPDATE 01-NOV-2002 23:05 HRS 21 WIPE

(Continued) **S106001349**

Remarks: RESULTS RECEIVED. WIPE POINTS 1-21 CAME BACK AS <1.0 ug/100 cm^2 ALL WIPES PASSED. CLEANUP IS COMPLETE. TAG TO BE REMOVED. UPDATE 02-NOV-2002 13:30 HRS. ENVIR. OPER. OPER.SUPV. E.WILLIAMS EMP# 56346 REPORTS: ENVIR. TAG# 08923 REMOVED. CLEANUP COMPLETE 100%. MANHOLE 65218. FIVE GALLONS UNKNOWN OIL ON 300 GALLONS OF WATER. CONTAINED WITHIN MANHOLE. SAMPLES TAKEN. TEST RESULTS INDICATE 2489 PPM OF PCB'S. WAITING FOR TANKER FOR CLEAN UP. CON EDISON REFERENCE NUMBER 141492.

Material:
- Site ID: 63233
- Operable Unit ID: 848253
- Operable Unit: 01
- Material ID: 528766
- Material Code: 0066A
- Material Name: UNKNOWN PETROLEUM
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: 5
- Units: Gallons
- Recovered: No
- Resource Affected: Not reported
- Oxygenate: False

Tank Test:
- Site ID: Not reported
- Spill Tank Test: Not reported
- Tank Number: Not reported
- Tank Size: Not reported
- Test Method: Not reported
- Leak Rate: Not reported
- Gross Fail: Not reported
- Modified By: Not reported
- Last Modified: Not reported
- Test Method: Not reported

V137 **CONSOLIDATED EDISON** **MANIFEST** **S110045746**
SSW **71 STREET & RIDGE BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.169 mi.
892 ft. **Site 1 of 5 in cluster V**

Relative:
Higher

Actual:
70 ft.

NY MANIFEST:
- EPA ID: NYP004190575
- Country: USA
- Mailing Name: CONSOLIDATED EDISON
- Mailing Contact: FRANKLYN MURRAY
- Mailing Address: 4 IRVING PLACE RM 828
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: Not reported

CONSOLIDATED EDISON (Continued) **S110045746**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-08-25
Trans1 Recv Date:	2009-08-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-08-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004190575
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	400.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000894332GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-08-25
Trans1 Recv Date:	2009-08-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-08-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004190575
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	400.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0

CONSOLIDATED EDISON (Continued) **S110045746**

Year:	2009
Manifest Tracking Num:	000894332GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

V138 **CON EDISON - MANHOLE 52535** **RCRA-LQG** **1014396742**
SSW **71 STREET & RIDGE BLVD** **NYP004190575**
1/8-1/4 **BROOKLYN, NY 11220**
0.169 mi.
892 ft. **Site 2 of 5 in cluster V**

Relative:
Higher

Actual:
70 ft.

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - MANHOLE 52535
Facility address:	71 STREET & RIDGE BLVD BROOKLYN, NY 11220
EPA ID:	NYP004190575
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(212) 460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

CON EDISON - MANHOLE 52535 (Continued) **1014396742**

Owner/Op start date: 08/12/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/12/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/12/2009
Facility name: CON EDISON - MANHOLE 52535
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

V139 **6735 RIDGE BLVD** **AST** **U003393957**
SSW **6735 RIDGE BLVD** **HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.170 mi.
899 ft. **Site 3 of 5 in cluster V**

Relative:
Higher

Actual:
70 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-348163
Program Type: PBS
UTM X: 582199.50497999997
UTM Y: 4499021.5411799997
Expiration Date: 2013/04/19

6735 RIDGE BLVD (Continued) **U003393957**

Affiliation Records:

Site Id:	17090
Affiliation Type:	Owner
Company Name:	6735 RIDGE OWNERS CORP
Contact Type:	PRESIDENT
Contact Name:	CHAIM BABAD
Address1:	P.O. BOX 313 PARKVILLE STATION
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11204
Country Code:	001
Phone:	(718) 633-7586
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2/6/2008

Site Id:	17090
Affiliation Type:	Mail Contact
Company Name:	6735 RIDGE OWNERS CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	P.O. BOX 313
Address2:	PARKVILLE STATION
City:	BROOKLYN
State:	NY
Zip Code:	11204
Country Code:	001
Phone:	(718) 633-7586
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	17090
Affiliation Type:	On-Site Operator
Company Name:	6735 RIDGE BLVD
Contact Type:	Not reported
Contact Name:	RAFAEL ARIAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 921-4563
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	17090
Affiliation Type:	Emergency Contact

6735 RIDGE BLVD (Continued) **U003393957**

Company Name:	6735 RIDGE OWNERS CORP
Contact Type:	Not reported
Contact Name:	RAFAEL ARIAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 921-4563
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Info:

Tank Number:	001
Tank Id:	33261
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1927
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-348163
SWIS Code:	6101
Operator:	PRESIDENTIAL MGMT CORP
Facility Phone:	(718) 680-1443
Facility Addr2:	6735 RIDGE BLVD
Facility Type:	APARTMENT BUILDING
Emergency:	FRANCISCO GALARZA
Emergency Tel:	(718) 680-1443
Old PBSNO:	303739
Date Inspected:	Not reported
Inspector:	Not reported

6735 RIDGE BLVD (Continued) **U003393957**

Result of Inspection:	Not reported
Owner Name:	6735 RIDGE OWNERS CORP
Owner Address:	P.O. BOX 313 PARKVILLE STATION
Owner City,St,Zip:	BROOKLYN, NY 11204
Federal ID:	Not reported
Owner Tel:	(718) 633-7586
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	6735 RIDGE OWNERS CORP
Mailing Address:	P.O. BOX 313 PARKVILLE STATION
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11204
Mailing Telephone:	(718) 633-7586
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	03/11/1998
Expiration:	04/19/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	5000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	19271201
Capacity (Gal):	5000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported

6735 RIDGE BLVD (Continued) **U003393957**

Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

V140 **GRUBER RESIDENCE** **LTANKS** **S107523230**
SW **139 SENATOR ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.179 mi.
946 ft. **Site 4 of 5 in cluster V**

Relative:
Higher

Actual:
66 ft.

LTANKS:

Site ID:	357227
Spill No:	0511134
Spill Date:	12/22/2005
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/13/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	12/22/2005
CID:	409
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/22/2005
Spill Record Last Update:	3/13/2006
Spiller Name:	THOMAS BUTLER
Spiller Company:	CONSUMERS ENERGY GROUP
Spiller Address:	222 BARRICK AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	ANN GRUBER
Spiller Phone:	(718) 836-1157
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	307254
Remarks:	HAS BEEN CLEANED UP. LOCATED ON CEMENT.

Material:

Site ID:	357227
Operable Unit ID:	1114508
Operable Unit:	01
Material ID:	2104578
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum

GRUBER RESIDENCE (Continued) **S107523230**

Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

R141 **CONSOLIDATED EDISON** **MANIFEST** **S110045825**
SE **317 65TH STREET - MH 6021** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.179 mi.
947 ft. **Site 9 of 9 in cluster R**

Relative:
Higher

Actual:
52 ft.

NY MANIFEST:
EPA ID: NYP004190690
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 2009-08-21
Trans1 Recv Date: 2009-08-21
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-08-21
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004190690
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 200.0
Units: G - Gallons (liquids only)* (8.3 pounds)

CONSOLIDATED EDISON (Continued) **S110045825**

Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000894948GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-08-21
Trans1 Recv Date:	2009-08-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-08-21
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004190690
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	000894948GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

U142 **VOLCKENING** **RCRA-NonGen** **1000990682**
SSE **6700 THIRD AVENUE** **FINDS** **NY0001039783**
1/8-1/4 **BROOKLYN, NY 11220** **MANIFEST**
0.180 mi.
952 ft. **Site 8 of 11 in cluster U**

Relative:
Higher

Actual:
65 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	VOLCKENING
Facility address:	6700 3RD AVE BROOKLYN, NY 112205296
EPA ID:	NY0001039783
Mailing address:	3RD AVE BROOKLYN, NY 11220
Contact:	Not reported
Contact address:	3RD AVE BROOKLYN, NY 11220
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	VOLCKENING INC
Owner/operator address:	6700 3RD AVE BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(718) 836-4000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	VOLCKENING INC
Owner/operator address:	6700 3RD AVE BROOKLYN, NY 11220
Owner/operator country:	US
Owner/operator telephone:	(718) 836-4000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

VOLCKENING (Continued) **1000990682**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VOLCKENING
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: VOLCKENING
Classification: Not a generator, verified

Date form received by agency: 10/10/1996
Facility name: VOLCKENING
Site name: VOLCKENING INC
Classification: Large Quantity Generator

Date form received by agency: 02/17/1995
Facility name: VOLCKENING
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 10/07/1996
Date achieved compliance: 10/16/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/07/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 11/05/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/01/1996
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 10/16/1996
Evaluation lead agency: State

FINDS:

Registry ID: 110000877392

Environmental Interest/Information System

VOLCKENING (Continued) **1000990682**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NY0001039783
Country:	USA
Mailing Name:	VOLCKENING
Mailing Contact:	MAX LEFEBURE
Mailing Address:	6700 THIRD AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11220
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-836-4000

Document ID:	NJA1932426
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	950222
Trans1 Recv Date:	950222
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950224
Part A Recv Date:	950321
Part B Recv Date:	950314
Generator EPA ID:	NY0001039783
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	02233
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00422
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00050
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

VOLCKENING (Continued) **1000990682**

Specific Gravity: 100
Year: 95

S143 **GOWANUS EXP WB** **NY Spills** **S103571641**
East **AT 57TH ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.180 mi.
953 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
62 ft.

NY Spills:

Site ID:	201555
Facility Addr2:	Not reported
Facility ID:	9712267
Spill Number:	9712267
Facility Type:	ER
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Spill Date:	2/3/1998
Reported to Dept:	2/3/1998
CID:	369
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/3/1998
Remediation Phase:	0
Date Entered In Computer:	2/3/1998
Spill Record Last Update:	2/4/1998
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	FDNY
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	167698
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG" WB GOWANUS. FD PUT DOWN PADS WAITING FOR SANDER. NO ACCIDENT JUST TRACTOR TRAILER LOST FUEL. HANDLED BY NYC FIRE HAZMAT.
Remarks:	truck in road has leaked diesel in road-largfe quantity of materiel at site-pd and fd on scene. nfi

Material:

Site ID:	201555
Operable Unit ID:	1058639
Operable Unit:	01
Material ID:	326886
Material Code:	0008
Material Name:	Diesel

GOWANUS EXP WB (Continued) **S103571641**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9712267
Investigator:	TANG
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	02/03/1998 12:00
Reported to Dept Date/Time:	02/03/98 12:38
SWIS:	61
Spiller Name:	Not reported
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Contact:	FDNY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Other
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

GOWANUS EXP WB (Continued) **S103571641**

Spill Closed Dt: 02/03/98
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/03/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/04/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: WB GOWANUS. FD PUT DOWN PADS WAITING FOR SANDER. NO ACCIDENT JUST TRACTOR TRAILER LOST FUEL. HANDLED BY NYC FIRE HAZMAT.
Remark: truck in road has leaked diesel in road-largfe quantity of materiel at site-pd and fd on scene. nfi

---

U144 **MANHOLE 6068** **NY Spills** **S104790656**
SSE **3RD AVE/67TH ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.181 mi.
954 ft. **Site 9 of 11 in cluster U**

Relative:
Higher

Actual:
65 ft.

NY Spills:
Site ID: 78021
Facility Addr2: Not reported
Facility ID: 0102281
Spill Number: 0102281
Facility Type: ER
SWIS: 2401
Investigator: KMFOLEY
Referred To: Not reported
Spill Date: 5/30/2001
Reported to Dept: 5/31/2001
CID: 312
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended

MANHOLE 6068 (Continued) **S104790656**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/23/2001
Remediation Phase:	0
Date Entered In Computer:	5/31/2001
Spill Record Last Update:	8/30/2001
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	104928
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" CON ED E2MIS REPORT 5-30-01 Found 3gals.of unknown oil on 50gals. water in MH6068. Spill is contained to structure. Sample taken and marked "E" priority. Tag placed. LSN 01-06096-001 ; 1981ppm 5-31-01 0510hrs. Cleaned up debris on floor of structure and found no sump. There is a sewer connection that was previously sealed. 1240hrs. Structure double washed with slix adn Biogen 760. Tag left in place. Cleanup pending soda blasting,four barrels were removed by Astoria transportation. 6-04-01 2030hrs. Soda blasted & double washed with Bio gen 760. Liquid waste removed by tanker, solid waste placed in 2 barrels. No sump, no lekaing equipent. Tag remains pending wipe samples. 6-14-01 Soda blasted structure , cleanup incomplete will follow up. 6-15-01 Structure double washed and rinsed. Chemist took wipe samples from grind points - 1,5,6,9,10,11,12,14,15,16. 6-17-01 Wipe results received, grind points 1,5,6,9,10,11,16 passed. Points 14 &15 failed Structure will be recleaned tomorrow. 6-18-01 1225hrs. Structure double washed and rinsed 750 gals. liquid removed by tanker, 1 drum of zone material and PPE was generated. Chemist has taken additional two wipe samples from grind points 14 & 15. Tag remains in place. 6-19-01 0730hrs. Wipe results, grind points 14& 15 passed. 1020hrs. incident closed.
Remarks:	ON 50GAL OF WATER - 1918PPM OF PCB - CASE #137337

Material:

Site ID:	78021
Operable Unit ID:	841075
Operable Unit:	01
Material ID:	534394
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported

MANHOLE 6068 (Continued) **S104790656**

Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	120896
Facility Addr2:	Not reported
Facility ID:	0008307
Spill Number:	0008307
Facility Type:	ER
SWIS:	2401
Investigator:	OKWUOHA
Referred To:	Not reported
Spill Date:	10/16/2000
Reported to Dept:	10/16/2000
CID:	389
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/17/2001
Remediation Phase:	0
Date Entered In Computer:	10/16/2000
Spill Record Last Update:	12/17/2001
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	104928
DEC Memo:	Not reported
Remarks:	CALLER REPORTING A SPILL DUE TO EQUIP. FAILURE LEAKING INTO SEWER/DRAIN NO CLENA UP NO CALLBACK feeder electric feeder joint leaking into drain in manhole drain in manhole probably connected to storm sewer joint is connected to 5 gal joint regulator leak is active crews attempting to remotely block drain crews contacted to de-energerized and repair.

Material:

Site ID:	120896
Operable Unit ID:	830639
Operable Unit:	01
Material ID:	545818

MANHOLE 6068 (Continued) **S104790656**

Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	0008307
Investigator:	OKWUOHA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/16/2000 12:15
Reported to Dept Date/Time:	10/16/00 12:40
SWIS:	61
Spiller Name:	CON EDISON
Spiller Contact:	Not reported
Spiller Phone:	(212) 580-6763
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003-
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended

MANHOLE 6068 (Continued) **S104790656**

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/17/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/16/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/17/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Con Ed e2mis 133951 Notes: 10-16-00 1qt dielectric oil from leaking joint onto 2gal water in manhole 6068. Cleanup to be done as 50-499ppm. 10-17-00 Structure was double washed with slix. Liquids removed by tanker, 7 drums of solids removed and drummed. Floor drain filled with cement. 9 made repairs to leaking joint.
Remark: CALLER REPORTING A SPILL DUE TO EQUIP. FAILURE LEAKING INTO SEWER/DRAIN NO CLENA UP NO CALLBACK feeder electric feeder joint leaking into drain in manhole drain in manhole probably connected to storm sewer joint is connected to 5 gal joint regulator leak is active crews attempting to remotely block drain crews contacted to de-energeri ed and repair.

Region of Spill: 2
Spill Number: 0102281
Investigator: FOLEY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/30/2001 15:10
Reported to Dept Date/Time: 05/31/01 00:05
SWIS: 61
Spiller Name: Not reported

MANHOLE 6068 (Continued) **S104790656**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/23/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/31/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/30/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 3
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: CON ED E2MIS REPORT 5-30-01 Found 3gals.of unknown oil on 50gals. water in MH6068. Spill is contained to structure. Sample taken and marked E priority. Tag placed. LSN 01-06096-001 ; 1981ppm 5-31-01 0510hrs. Cleaned up debris on floor ofstructure and found no sump. There is a sewer connection that was previously sealed. 1240hrs. Structure double washed with slix adn Biogen 760. Tag left in place. Cleanup pending soda blasting,four barrels were removed by Astoria transportation. 6-04-01 2030hrs. Soda blasted double washed with Bio gen 760. Liquid waste removed by tanker, solid waste placed in 2 barrels. No sump, no lekaing equipent. Tag remains pending wipe samples. 6-14-01 Soda blasted structure , cleanup incomplete will follow up. 6-15-01

MANHOLE 6068 (Continued) **S104790656**

Structure double washed and rinsed. Chemist took wipe samples from grind points - 1,5,6,9,10,11,12,14,15,16. 6-17-01 Wipe results received, grind points 1,5,6,9,10,11,16 passed. Points 14 15 failed Structure will be recleaned tomorrow. 6-18-01 1225hrs. Structure double washed and rinsed 750 gals. liquid removed by tanker, 1 drum of one material and PPE was generated. Chemist has taken additional two wipe samples from grind points 14 15. Tag remainsin place. 6-19-01 0730hrs. Wipe results, grind points 14 15 passed. 1020hrs. incident closed.

Remark: ON 50GAL OF WATER - 1918PPM OF PCB - CASE 137337

U145 **VOLKENING INC.** **UST** **U001840987**
SSE **6702 3RD AVENUE** **HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.181 mi.
955 ft. **Site 10 of 11 in cluster U**

Relative:
Higher

Actual:
65 ft.

UST:

Facility Id:	2-480622
Region:	STATE
DEC Region:	2
Site Status:	Administratively Closed
Program Type:	PBS
Expiration Date:	N/A
UTM X:	582448.05547999998
UTM Y:	4498989.0241299998

Affiliation Records:

Site Id:	21454
Affiliation Type:	Owner
Company Name:	VOLKENING INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6702 3RD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 836-4000
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	21454
Affiliation Type:	Mail Contact
Company Name:	VOLKENING INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	6702 3RD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 836-4000
Phone Ext:	Not reported

VOLKENING INC. (Continued) **U001840987**

Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	21454
Affiliation Type:	Emergency Contact
Company Name:	VOLKENING INC.
Contact Type:	Not reported
Contact Name:	W.L. SHEWAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(201) 739-3532
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	21454
Affiliation Type:	On-Site Operator
Company Name:	VOLKENING INC.
Contact Type:	Not reported
Contact Name:	VOLKENING INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 836-4000
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None

Tank Info:

Site ID:	21454
Tank Number:	001
Tank ID:	39002

VOLKENING INC. (Continued) **U001840987**

Tank Status:	Administratively Closed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/1963
Capacity Gallons:	1500
Tightness Test Method:	01
Next Test Date:	Not reported
Date Tank Closed:	3/1/1996
Tank Location:	6
Tank Type:	Steel/carbon steel
Date Test:	3/1/1990
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-480622
SPDES Number:	Not reported
Emergency Contact:	W.L. SHEWAN
Emergency Telephone:	(201) 739-3532
Operator:	VOLKENING INC.
Operator Telephone:	(718) 836-4000
Owner Name:	VOLKENING INC.
Owner Address:	6702 3RD
Owner City,St,Zip:	BROOKLYN, NY 11220
Owner Telephone:	(718) 836-4000
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	VOLKENING INC.
Mailing Address:	6702 3RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11220
Mailing Contact:	Not reported
Mailing Telephone:	(718) 836-4000
Owner Mark:	First Owner
Facility Status:	3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).
Facility Addr2:	6702 3RD AVENUE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/24/1993
Expiration Date:	05/15/1995
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False

VOLKENING INC. (Continued) **U001840987**

CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Tank Status:	Undefined
Install Date:	19630101
Capacity (gals):	1500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	03/01/1990
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	03/01/1996
Test Method:	Petro-Tite
Deleted:	False
Updated:	True
Lat/long:	Not reported

U146 **CLOSED-LACKOF RECENT INFO** **LTANKS** **S100145907**
SSE **VOLCKENING INC,6702 3 AV** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.181 mi.
955 ft. **Site 11 of 11 in cluster U**

Relative:
Higher

Actual:
65 ft.

LTANKS:

Site ID:	200808
Spill No:	8912022
Spill Date:	3/19/1990
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/6/2003
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	3/19/1990
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S100145907**

Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/19/1990
Spill Record Last Update: 3/6/2003
Spiller Name: Not reported
Spiller Company: SAME/VOLCKENING INC
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167087
Remarks: 1.5K TANK FAILS PETRO - L R =-0.096 GPH TK ONLY. CLEAN & SLURRY TANK - WILL ABANDON & INSTALL 1080 AG TK.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS.

Material:
Site ID: 200808
Operable Unit ID: 938867
Operable Unit: 01
Material ID: 441504
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 200808
Spill Tank Test: 1536871
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 8912022
Spill Date: 03/19/1990
Spill Time: 15:00
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial

CLOSED-LACKOF RECENT INFO (Continued) **S100145907**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	BATTISTA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	03/19/90
Reported to Department Time:	16:18
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	SAME
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Other
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	03/19/90
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	11/27/92
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	-1
Unkonwn Quantity Spilled:	False
Units:	Not reported
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#2 FUEL OIL

CLOSED-LACKOF RECENT INFO (Continued) **S100145907**

Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: 1.5K TANK FAILS PETRO - L R =-0.096 GPH TK ONLY. CLEAN SLURRY TANK - WILL ABANDON INSTALL 1080 AG TK

147
East
1/8-1/4
0.184 mi.
970 ft.

Relative:
Higher

Actual:
59 ft.

5604 3RD AVENUE
5604 3RD AVENUE
BROOKLYN, NY

NY Spills **S104495702**
NY Hist Spills **N/A**

NY Spills:
Site ID: 162719
Facility Addr2: Not reported
Facility ID: 9402841
Spill Number: 9402841
Facility Type: ER
SWIS: 2401
Investigator: SMMARTIN
Referred To: Not reported
Spill Date: 5/27/1994
Reported to Dept: 5/27/1994
CID: Not reported
Spill Cause: Housekeeping
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: 5/27/1994
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Not reported
Spill Closed Dt: 5/27/1994
Remediation Phase: 0
Date Entered In Computer: 7/22/1994
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: R.J. ROMANO & CO
Spiller Address: Not reported
Spiller City,St,Zip: COLLEGE POINT, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 137276
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" 10/10/95: This is additional information about material spilled from the translation of the old spill file: LEAD PAINT & DUST. Not reported
Remarks: PAINTING GOWANUS HWY BRIDGE & LEAD DUST FALLING ON AREA -REFERRED TO DEC AIR RESOURCES IWCS

Material:
Site ID: 162719

5604 3RD AVENUE (Continued) **S104495702**

Operable Unit ID: 996635
Operable Unit: 01
Material ID: 383013
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9402841
Investigator: MARTINKAT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/27/1994 08:52
Reported to Dept Date/Time: 05/27/94 08:52
SWIS: 61
Spiller Name: R.J. ROMANO & CO
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: COLLEGE POINT, NY
Spill Cause: Housekeeping
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: 05/27/94
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /

5604 3RD AVENUE (Continued) **S104495702**

Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 05/27/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/22/94
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: LEAD PAINT DUST.
Remark: PAINTING GOWANUS HWY BRIDGE LEAD DUST FALLING ON AREA -REFERRED TO DEC AIR RESOURCES IWCS

V148
SSW
1/8-1/4
0.184 mi.
974 ft.

Relative:
Higher

Actual:
71 ft.

6735 RIDGE BLVD APT 2S
BROOKLYN, NY

Site 5 of 5 in cluster V

NY Spills **S104951325**
NY Hist Spills **N/A**

NY Spills:
Site ID: 331146
Facility Addr2: APT 2S
Facility ID: 0011899
Spill Number: 0011899
Facility Type: ER
SWIS: 2401
Investigator: JMKRIMGO
Referred To: Not reported
Spill Date: 1/1/2001
Reported to Dept: 2/3/2001
CID: 322
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported

(Continued) **S104951325**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/6/2001
Remediation Phase:	0
Date Entered In Computer:	2/3/2001
Spill Record Last Update:	2/6/2001
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	NATALIE GULIYEVA
Contact Phone:	(718) 921-9328
DEC Region:	2
DER Facility ID:	266321
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD" Y. KRIMGOLD CHEKED THE PPM IN THE APPARTMENT. NO READINGS. nOT A PETROL. ODOR IN THE APATRTMENT.
Remarks:	caller states she is getting unk type fumes (smell like exhaust) in her bedroom - the fumes make her cough and also give her a headache -

Material:

Site ID:	331146
Operable Unit ID:	833798
Operable Unit:	01
Material ID:	542189
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0011899
Investigator:	KRIMGOLD

(Continued) **S104951325**

Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/01/2001 12:00
Reported to Dept Date/Time: 02/03/01 22:05
SWIS: 61
Spiller Name: UNK
Spiller Contact: UNK
Spiller Phone: (000) 000-0000
Spiller Contact: NATALIE GULIYEVA
Spiller Phone: (718) 921-9328
Spiller Address: UNK
Spiller City,St,Zip: UNK, NY
Spill Cause: Unknown
Reported to Dept: Air
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 02/06/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/03/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/06/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Raw Sewage
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN MATERIAL
Class Type: UNKNOWN MATERIAL
Times Material Entry In File: 9140

(Continued) **S104951325**

CAS Number: Not reported
Last Date: 19941109
DEC Remarks: Y. KRIMGOLD CHEKED THE PPM IN THE APPARTMENT. NO READINGS. nOT A PETROL. ODOR IN THE APATRTMENT.
Remark: caller states she is getting unk type fumes smell like exhaust) in her bedroom - the fumes make her cough and also give her a headache -

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S103573758	MANHOLE 4801 - STERLING	ST & BEDFORD AVE		NY Spills, NY Hist Spills
BROOKLYN	S102143631	N3 AND N4TH STREET	N3 & N 4TH ST		NY Spills, NY Hist Spills
BROOKLYN	99618878	100TH STREET PLAYGROUND 100TH AND	100TH STREET PLAYGROUND 100TH		ERNS
BROOKLYN	2005613462	111TH STREET	111TH STREET		ERNS
BROOKLYN	1007767195	CON ED-11TH STREET CONDUIT	11TH ST BETWEEN 53RD AND ASH		FINDS
BROOKLYN	S110488176	DRUM RUN	123RD 47TH ST & 2ND AVE		NY Spills
BROOKLYN	S106002384	VACANT LOT - X OF 2ND	12TH ST		NY Spills
BROOKLYN	S106721354	MANHOLE #55328	E 13TH ST & SHORE PARK		NY Spills
BROOKLYN	S110242738	PRIVATE RESIDENCE	13TH & 2ND SAINT FELIX ST		NY Spills
BROOKLYN	S102148893	531 144TH STREET	531 144TH ST		NY Spills, NY Hist Spills
BROOKLYN	8871857	147TH STREET BEACH	147TH STREET BEACH		ERNS
BROOKLYN	S102148192	14 AVE. & 15TH STREET	14TH AVE & 15TH ST		NY Spills, NY Hist Spills
BROOKLYN	S106127284	ON STREET	W 16TH & HEARTPLACE		NY Spills
BROOKLYN	S102146991	101 EAST 179TH STREET	101 E 179TH ST		NY Spills, NY Hist Spills
BROOKLYN	99617157	17TH AVE AND 59TH STREET	17TH AVE AND 59TH STREET		ERNS
BROOKLYN	S106005258		17TH AVE & BELT PKWY		NY Spills
BROOKLYN	S109372164	EAST 18TH STREET	E 18TH ST		NY Spills
BROOKLYN	S102141184	18TH AV BET 65TH & 70TH S	18TH AVE BET 65TH & 70TH S		NY Spills, NY Hist Spills
BROOKLYN	S103829627	GOWANUS GAS TURBINE STA	20TH MAIN ST & 2ND AVE		NY Spills, NY Hist Spills
BROOKLYN	S110309026	KAY ROCK SCREEN PRINTING	210TH KENT AVE & 2ND FLOOR		NY Spills
BROOKLYN	974086311	22ND STREET & 3RD AVE	22ND ST & 3RD AVE		ERNS
BROOKLYN	96490556	EAST 22ND STREET AND CLINTON ROAD.	EAST 22ND STREET AND CLINTON R		ERNS
BROOKLYN	1007821043	NYC EDC - 23RD ST PIER	23RD ST		FINDS
BROOKLYN	S102143714	EAST 26TH STREET	E 26TH ST		NY Spills, NY Hist Spills
BROOKLYN	S102144285	HENDRIX STREET / 26TH WAR	26TH WARD PLANT		NY Spills, NY Hist Spills
BROOKLYN	S102148375	CON EDISON	27TH ST & 2ND AVE		NY Spills, NY Hist Spills
BROOKLYN	S106701768	27TH ST & 2ND AVENUE	27TH ST & 2ND AVE		NY Spills, NY Hist Spills
BROOKLYN	S104510174	GOWANUS TURBINE SITE	27TH ST & 2ND AVE		NY Spills, NY Hist Spills
BROOKLYN	S102142527	E 29TH ST & KINGS HWY	E 29TH ST & KINGS HWY		NY Spills, NY Hist Spills
BROOKLYN	S106701720	SOUTH 2ND STREET	S 2ND ST		NY Spills, NY Hist Spills
BROOKLYN	2003651611	2ND AVENUE AND 6TH STREET	2ND AVENUE AND 6TH STREET		ERNS
BROOKLYN	2010958811	2ND AVENUE AND 29TH STREET	2ND AVENUE AND 29TH ST		ERNS
BROOKLYN	S102149730	2NS AVE & E. 154TH ST	2ND AVE & E 145TH ST		NY Spills, NY Hist Spills
BROOKLYN	S104880657	BS 3147 HAMILTON AND	2ND AVE		NY Spills, NY Hist Spills
BROOKLYN	S104194816	MANHOLE 63639	E 2ND ST & KINGS H WAY		NY Spills, NY Hist Spills
BROOKLYN	S104789265	SB 38848	2ND ST & GOWANUS CANAL		NY Spills, NY Hist Spills
BROOKLYN	S105235469	43RD ST BETWEEN	2ND AVE & 1ST AVE		NY Spills, NY Hist Spills
BROOKLYN	S105999093	GREEN HILL	2ND REWE ST & 300 VANDERVOO		LTANKS
BROOKLYN	S106867580	BETWEEN 9TH / 10 TH STREE	2ND AVE		NY Spills
BROOKLYN	S106698120	29TH ST	2ND AVE		NY Spills
BROOKLYN	S110046940	CONSOLIDATED EDISON MH59268	59268 2ND AVENUE 13TH ST		MANIFEST
BROOKLYN	S110046926	CONSOLIDATED EDISON MH55673	MH55673 2ND AVE & 48TH ST		MANIFEST
BROOKLYN	S102147942	SOUTH 2ND ST.	S 2ND ST		NY Spills, NY Hist Spills

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S106011802	CASTLE HARBOR REST.	3149TH EMMONS AVE & 2841ST FR		NY Spills
BROOKLYN	S102143252	36TH STREET	36TH ST		NY Spills, NY Hist Spills
BROOKLYN	S109582860	STREET SPILL	3RD AVE & 53RD ST	11220	NY Spills
BROOKLYN	1014396738	CON EDISON - MANHOLE 5786	3RD AVENUE AND 49TH ST	11220	RCRA-LQG
BROOKLYN	1014396723	CON EDISON - MANHOLE 5778	3RD AVENUE AND 55TH ST	11220	RCRA-LQG
BROOKLYN	1014396722	CON EDISON - MANHOLE 5780	3RD AVENUE AND 54TH ST	11220	RCRA-LQG
BROOKLYN	S111064060	IN THE STREET	3RD AVE AND 60TH ST		NY Spills
BROOKLYN	S104194127	23RD STREET AND	3RD AVE		NY Spills, NY Hist Spills
BROOKLYN	S104787053	PRESIDENT STREET &	3RD AVE		NY Spills, NY Hist Spills
BROOKLYN	S103937488	MH 55485	3RD AVE & 63RD ST	11220	NY Spills, NY Hist Spills
BROOKLYN	S106006129	FEEDER 25	3RD AVE & 63RD ST	11220	NY Spills
BROOKLYN	S110540059	MAN HOLE 5354	3RD & AVE AND 2ND ST		NY Spills
BROOKLYN	1014396721	CON EDISON - MANHOLE 5887	684 44TH STREET AND 6TH	11220	RCRA-LQG
BROOKLYN	S104653655	MANHOLE 57618	44TH ST & 20TH FORT 2ND AVE E		NY Spills, NY Hist Spills
BROOKLYN	1005444350	MTA NYCT - 45TH ST STA N&R LINE	45TH ST & 4TH AVE	11220	RCRA-CESQG, FINDS, MANIFEST
BROOKLYN	1007206623	CON ED - MH 5789	46TH ST & 3RD AVE	11220	RCRA-NonGen, MANIFEST
BROOKLYN	2010935316	4TH AVENUE AND 1ST STREET	4TH AVENUE AND 1ST ST		ERNS
BROOKLYN	1014396720	CON EDISON - MANHOLE 58551	5623 4TH AVENUE AND 57TH	11220	RCRA-LQG
BROOKLYN	96517558	#4 53 STREET	#4 53 STREET		ERNS
BROOKLYN	2008883519	53RD STREET	53RD STREET		ERNS
BROOKLYN	S102146432	54 STREET/VERNON BLVD	54TH ST & VERNON BLVD		NY Spills, NY Hist Spills
BROOKLYN	2004738423	0010 57TH ST - STILLWELL AVE	0010 57TH ST - STILLWELL AVE		ERNS
BROOKLYN	1009449135	NYC EDC - BROOKLYN WHOLESALE MEAT	57TH ST	11220	FINDS
BROOKLYN	S102150275	BAY RIDGE CANAL - 57TH ST	57TH SAINT PIER & BAY RDG		NY Spills, NY Hist Spills
BROOKLYN	2000538334	58TH STREET AND AVE U	58TH STREET AND AVE U	0	ERNS
BROOKLYN	S110044197	EAST 5TH ST/ CROSS ST GRRENWOOD AV	E 5TH ST		NY Spills
BROOKLYN	2001561173	5TH AVE AND 6TH STREET	5TH AVE AND 6TH STREET	0	ERNS
BROOKLYN	S105058160	9TH STREET AT	5TH AVE		NY Spills, NY Hist Spills
BROOKLYN	U003394301	PUBLIC SCHOOL 314 - BROOKLYN	60TH ST & 3RD AVE	11220	AST, HIST AST
BROOKLYN	S102143299	62ND STREET 3RD AVE.	62ND STREET 3RD AVE		NY Spills, NY Hist Spills
BROOKLYN	S104952663	MANHOLE 15470	63RD AVE & AUSTIN AVE		NY Spills, NY Hist Spills
BROOKLYN	1014396719	CON EDISON	63RD ST & 4TH AVE	11220	RCRA-CESQG
BROOKLYN	2002618389	64TH STREET AND 3RD AVE	64TH STREET AND 3RD AVE	0	ERNS
BROOKLYN	1010017769	NYC DDC - 64TH ST	64TH ST AT HARBOR	11220	FINDS
BROOKLYN	1014396753	CON EDISON - MANHOLE 52161	65TH ST & RIDGE BLVD	11220	RCRA-LQG
BROOKLYN	S102663359	GOWANIS HWY BY 65TH ST	BY 65TH ST		NY Spills, NY Hist Spills
BROOKLYN	S110044420	STREET	E 66TH BETWEEN M & N		NY Spills
BROOKLYN	2008870622	EAST 66TH STREET AND	EAST 66TH STREET AND		ERNS
BROOKLYN	U004063965	OWL'S HEAD WPCP	6700TH SHORE RD & BELT PKWY	11220	UST
BROOKLYN	2000535604	EAST 68TH STREET	EAST 68TH STREET	0	ERNS
BROOKLYN	99649722	EAST 68TH STREET AND AVE U	EAST 68TH STREET AND AVE U		ERNS
BROOKLYN	S102240366	69TH ST - AVE.W	69TH SAINT AREA OF AVE W		NY Spills, NY Hist Spills
BROOKLYN	S108638485	38TH STREET YARD	6TH AVE & 38TH ST		NY Spills
BROOKLYN	94372754	6TH STREET AND 2ND AVE	6TH STREET AND 2ND AVE		ERNS
BROOKLYN	94390836	6TH STREET ADN 2ND AVE	6TH STREET ADN 2ND AVE		ERNS
BROOKLYN	S104880683	38TH STREET YARD	6TH AVE & 38TH ST		NY Spills, NY Hist Spills
BROOKLYN	1009241382	CONSOLIDATED EDISON	MH5494 7TH AVE & 2ND ST		MANIFEST

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S110044881	EAST 83RD STREET SUB STATION	E 83RD ST		NY Spills
BROOKLYN	1014396733	CON EDISON - MANHOLE 52007	847TH 63RD ST & 8TH AVE	11220	RCRA-LQG
BROOKLYN	S110046360	CONSOLIDATED EDISON	847TH 63RD ST & 8TH AVE	11220	MANIFEST
BROOKLYN	S102147933	86TH STREET - BELL PARKWA	86TH ST BELL PKY		NY Spills, NY Hist Spills
BROOKLYN	2010934192	86TH STREET ON R LINE	86TH ST		ERNS
BROOKLYN	S106972104	GAS MAIN IN STREET	86TH ST & BAY 24TH AVE		LTANKS
BROOKLYN	1014396801	CON EDISON - MANHOLE 57634	883RD 65TH ST & 8TH AVE	11220	RCRA-LQG
BROOKLYN	1010787646	NYSDOT BIN 223123A	RTE 907C AT 63RD ST	11220	RCRA-LQG
BROOKLYN	1010787647	NYSDOT BIN 2231239	RTE 907C OVER SHORE PKWY EB E	11220	RCRA-LQG
BROOKLYN	S102148271	92ND ST - I278	92ND ST		NY Spills, NY Hist Spills
BROOKLYN	S102147070	EAST 92ND STREET	E 92ND ST		NY Spills, NY Hist Spills
BROOKLYN	S109064521	BELL ATLANTIC-NY	E 94TH ST & BET CLARKSON AVEN		MANIFEST
BROOKLYN	2007330337	9TH STREET AND	9TH STREET AND		ERNS
BROOKLYN	S106736914	ENTRANCE TO 38TH STREET Y	9TH AVENUE 38TH ST		NY Spills
BROOKLYN	S104880596	BETWEEN 37TH STREET AND	9TH AVE		NY Spills, NY Hist Spills
BROOKLYN	94404412	ABANDON VESSEL 21ST STREET	ABANDON VESSEL 21ST STREET		ERNS
BROOKLYN	S106004783	38TH STREET AT CORNER OF	ANE M		NY Spills
BROOKLYN	S109206140	ON STREET	APPLOLO ST & MEEKER AVE		NY Spills
BROOKLYN	2010928836	ASH STREET AND MANHATTAN AVENUE	ASH STREET AND MANHATTAN AVE		ERNS
BROOKLYN	1010787606	NYSDOT BIN 106531B	I-278 AT 63RD ST OVER RELIEF	11220	RCRA-LQG
BROOKLYN	1010787608	NYSDOT BIN 106531E	I-278 AT 59TH ST OVER RTE 907C	11220	RCRA-LQG
BROOKLYN	S111012256	COMMERCIAL SITE - TTF	967 ATLANITC AVE		LTANKS
BROOKLYN	1007803392	PORT AUTHORITY OF NY/NJ - PIER 1	ATLANTIC WHARF, WESTERLY END O		FINDS
BROOKLYN	S104192617	IN THE AREA OF NY HARBOR	ATLANTIC AVE		NY Spills, NY Hist Spills
BROOKLYN	S102446624	EAST 89TH STREET	AVE D		NY Spills, NY Hist Spills
BROOKLYN	S106737213	MANHOLE # 71883	E AVE SIDE 2ND 50 98TH S		NY Spills
BROOKLYN	S106970079	MANHOLE 2529	AVE S & E 2ND ST		NY Spills
BROOKLYN	S106737045	BETW/AVE X &	AVE KINGS HWY		NY Spills
BROOKLYN	S106010679	EAST 83RD STREET AT	AVENUE SUB STA N		NY Spills
BROOKLYN	S102142994	AVE Z AND KNAPP STREET	AVENUE Z AND KNAPP ST		NY Spills, NY Hist Spills
BROOKLYN	S103939251	MANHOLE 6266	AVENUE C E 2ND ST		NY Spills, NY Hist Spills
BROOKLYN	S106003383	NEW YORK HARBOR	BAY ANCHORAGE		NY Spills
BROOKLYN	S104510756	LOWER BAY	BAY PKWY & SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	S110750922	PARK CONSTRUCTION	BAY 44TH ST AND SHORE PKWY		NY Spills
BROOKLYN	2006787742	1485 BEACON STREET	1485 BEACON STREET		ERNS
BROOKLYN	99618540	BEHIND WHITMAN DRIVE / NEAR OHIO W	BEHIND WHITMAN DRIVE / NEAR OH		ERNS
BROOKLYN	1012313471	NYC PARKS - PLUMB BEACH	BELT PKWY - S SIDE & E OF KNAP		FINDS
BROOKLYN	90172889	BELT PARKWAY NY HARBOR	BELT PARKWAY NY HARBOR		ERNS
BROOKLYN	S110540414	RAMP D/ BELT PKWAY CONSTRUCTION SI	BELT PKWAY AT ROCKAWAY PKWY		NY Spills
BROOKLYN	S110539931	HYDRAULIC OIL LINE LEAK	BELT PKWY		NY Spills
BROOKLYN	S102143074	BELT PKWY E B AT OCEAN AV	BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102144512	BELT PARKWAY @ FLATBUSH A	BELT PKWY & FLATBUSH AVE		NY Spills, NY Hist Spills
BROOKLYN	S102148598	BELT PKWY-EXIT 2-5	BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102144978	BELT PKWY OIL PUDDLE	BELT PKWY & FOUNTAIN AVE		NY Spills, NY Hist Spills
BROOKLYN	S102146913	BELT PRKWY & KNAPPS AVE	BELT PKWY & KNAPPS AVE		NY Spills, NY Hist Spills
BROOKLYN	S104789991	VAULT 2028	BELT PKWY & FLT BUSH		NY Spills, NY Hist Spills
BROOKLYN	S104789467	SHEEPSHEAD BAY	BELT PKWY		NY Spills, NY Hist Spills

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S104648797		BELT PKWY & BEDFORD AVE		NY Spills, NY Hist Spills
BROOKLYN	S111011773	CONSTRUCTION SITE	BELT PKWY W		NY Spills
BROOKLYN	S111010925	ROADWAY	BELT PKWY		NY Spills
BROOKLYN	S110769049	CONSTRUCTION SITE BELT PARKWAY/PAE	BELT PKWY		NY Spills
BROOKLYN	1009239804	CONSOLIDATED EDISON	BELT PKWY		MANIFEST
BROOKLYN	S110750294	CONSTRUCTION PROJECT AT FRESH CREE	BELT PKWY		NY Spills
BROOKLYN	S110750950	SOIL	BELT PKWY ON PAERDEGAT BRG		NY Spills
BROOKLYN	S106005177	MILL BASIN BRIDGE	BELT PKWY & MILL BASIN BR		NY Spills
BROOKLYN	S106005178	MILL BASIN BRIDGE	BELT PKWY & MILL BASIN BR		NY Spills
BROOKLYN	S110138671	BELT PARKWAY	BELT PARKWAY AT PAERDEGAT BRG		NY Spills
BROOKLYN	99650276	BERGAN BEACH YACHT CLUB EAST 66TH	BERGAN BEACH YACHT CLUB EAST 6		ERNS
BROOKLYN	1010325604	CON EDISON - CUSTOMER MANHOLE 6468	S/S BERGEN ST., 35‘ W/O FRANKL	11220	RCRA-NonGen
BROOKLYN	1010440435	CON EDISON - CUSTOMER MANHOLE 6468	S/S BERGEN ST., 35‘ W/O FRANKL	11220	FINDS
BROOKLYN	S104787652	NOLL STREET	BETW CENTRAL AVE+WILSON		NY Spills, NY Hist Spills
BROOKLYN	S104653744	PRESIDENT STREET	BETWEEN 3RD AVE & NEVINS		NY Spills, NY Hist Spills
BROOKLYN	S104790662	14 MAJETA STREET	BETWEEN LARMA & UNION		NY Spills, NY Hist Spills
BROOKLYN	S102147187	BLDG 128 - NAVY YRD.	BLDG NAVY YRD		NY Spills, NY Hist Spills
BROOKLYN	S102672033	2110 BOLTON STREET	2110 BOLTON ST		LTANKS, HIST LTANKS
BROOKLYN	S102150342	BQE - SOUTH LIE BRIDGE	BQE SOUTH LIE BRG		NY Spills, NY Hist Spills
BROOKLYN	S102149254	BQE - ATLANTIC AVE	BQE ATLANTIC AVENUE NR BRG		NY Spills, NY Hist Spills
BROOKLYN	S103572411	STREET AND SEWER	N BQU & TILLERY ST		NY Spills, NY Hist Spills
BROOKLYN	2001558948	3161 BRIGHTON 6 STREET	3161 BRIGHTON 6 STREET	0	ERNS
BROOKLYN	S104654292	MANHOLE TM606	BRIGHTON 2ND ST		NY Spills, NY Hist Spills
BROOKLYN	98459009	BROOKLYN ARMY TERMINAL 65TH ST AT	BROOKLYN ARMY TERMINAL 65TH ST		ERNS
BROOKLYN	S102149486	FLUSHING & CLASSON AVES.	BROOKLYN QUEENS EXPRESSWAY EAS		NY Spills, NY Hist Spills
BROOKLYN	1009235734	NYCDEP	BTW 2ND & 3RD AVE		MANIFEST
BROOKLYN	S103570592	2653 EAST 26TH STREET	BTWN AVE Z & VORHEES		NY Spills, NY Hist Spills
BROOKLYN	89133738	BUTTERVILLE CHANNEL - BUOY #1	BUTTERVILLE CHANNEL - BUOY #1		ERNS
BROOKLYN	2009906368	CAROL AND NEVINS STREET	CAROL AND NEVINS STREET		ERNS
BROOKLYN	2008906368	CAROL AND NEVINS STREET	CAROL AND NEVINS STREET		ERNS
BROOKLYN	89109502	408 CARROL STREET	408 CARROL STREET		ERNS
BROOKLYN	S108982105	STREET BETW PILLING ST/CH	CENTRALAVE		NY Spills
BROOKLYN	S102147069	FOOT OF ADAM STREET	COAST OF ADAM ST		NY Spills, NY Hist Spills
BROOKLYN	2006785094	COLUMBIA STREET	COLUMBIA STREET		ERNS
BROOKLYN	S108130261	BETWEEN CLAY/BOX STREET	COMMERCIAL ST		NY Spills
BROOKLYN	S102148430	89 JOHN STREET	CON ED FARRAGUT SUB STA		NY Spills, NY Hist Spills
BROOKLYN	S102671141	KNAPP STREET / CONEY ISLA	CONEY IS		NY Spills, NY Hist Spills
BROOKLYN	S110769103	IN THE STREET	CONEY ISLAND AVE AND CHURCH AV		NY Spills
BROOKLYN	S110752343	STREET	NW CORNER FOUNTAIN AVE		NY Spills
BROOKLYN	98463809	COWANUS CANAL 29TH STREET AND 2ND	COWANUS CANAL 29TH STREET AND		ERNS
BROOKLYN	974109761	CROPSEY AVE. CORNER OF BAY 54TH ST	CROPSEY AVE. CORNER OF BAY 54T		ERNS
BROOKLYN	974109760	CROPSEY AVE. CORNER OF BAY 54TH ST	CROPSEY AVE. CORNER OF BAY 54T		ERNS
BROOKLYN	S110046200	CONSOLIDATED EDISON	CYPRESS AVE & STATE ST		MANIFEST
BROOKLYN	S106126718	MANHOLE #- 19415	DEAN ST & GASTON BLVD		NY Spills
BROOKLYN	S106015392	EAST 98TH STREET AT	DITMAS AVE		NY Spills
BROOKLYN	S102142647	DOMINO SUGAR/S 2ND ST	DOMINO SUGAR & S 2ND ST		NY Spills, NY Hist Spills
BROOKLYN	S102147179	DRY DOCK #4 - NAVY SHIPYR	DRY DOCK NAVY SHIPYR		NY Spills, NY Hist Spills

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S106002787	CONOVER STREET BETWEEN	DYKEMAN & COFFEY		NY Spills
BROOKLYN	S102143209	AVENUE L EAST43RD STREET	L EAST 43RD ST		NY Spills, NY Hist Spills
BROOKLYN	S106127355	ON STREET	EASTSIDE 7TH & GARFIELD		NY Spills
BROOKLYN	1010787612	NYSDOT BIN 106531M	I-278 EB AT INTERS OF 2ND AVE	11220	RCRA-LQG
BROOKLYN	S104651684	CHIEFS HEAD BAY	EMMONDS AVE & SHORE AVE		NY Spills, NY Hist Spills
BROOKLYN	S102141417	EMMONS AVE & SHORE RD	EMMONS AVE & SHORE RD		NY Spills, NY Hist Spills
BROOKLYN	S109062621	STREET	EMPIRE BLVD & WASHINGTON A		NY Spills
BROOKLYN	S102662590	BQE @ ATLANTIC AVE.	ENTRANCE RAMP BQE & ATLAN		NY Spills, NY Hist Spills
BROOKLYN	S109062462	VERRAZANO BRIDGE	EXIT RAMP 92 ST & 231ST DAHLG		NY Spills
BROOKLYN	99607598	NORTH FIRST STREET OIL FARM 214 KE	NORTH FIRST STREET OIL FARM 21		ERNS
BROOKLYN	S104880729	V2070F	FLATBUSH AVE & BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S103573626	CITYWIDE CESSPOOL COMPANY	FLATLANDS AVE		SWF/LF, NY Spills, NY Hist Spills
BROOKLYN	S107416589	FEEDER ACCIDENT - MH 61598	FLUSHING AVENUE NEAR ADELPHI S		NY Spills
BROOKLYN	S102239375	FT HAMILITON - BLDG 106	FORT HAMILTON PKWY		NY Spills, NY Hist Spills
BROOKLYN	1012186239	NYCP&R - SPRING CREEK PARK	FOUNTAIN AVE BETW SEAVIEW AVE	11220	RCRA-CESQG
BROOKLYN	1012107873	NYCP&R - SPRING CREEK PARK	FOUNTAIN AVE BETW SEAVIEW AVE	11220	FINDS
BROOKLYN	S107789119	2006 A FULTON STREET	2006 A FULTON ST		LTANKS
BROOKLYN	S110491271	CONSOLIDATED EDISON - MH 2901	FULTON & CLASSON		MANIFEST
BROOKLYN	S106698082	STREET	GARRISON & SEBA AVE		NY Spills
BROOKLYN	2003633309	55 GOLD STREET/ JOHN STREET	55 GOLD STREET/ JOHN STREET		ERNS
BROOKLYN	S106383560	STREET INTERSECTION	GOWANUS EXPY & 92ND		NY Spills
BROOKLYN	S102961680	GRAND STREET BRIDGE	GRAND ST		NY Spills, NY Hist Spills
BROOKLYN	2007446504	GRAND STREET	GRAND STREET		HMIRS
BROOKLYN	2007446430	GRAND STREET	GRAND STREET		HMIRS
BROOKLYN	97408280	GRAND STREET BRIDGE	GRAND STREET BRIDGE		ERNS
BROOKLYN	2008447862	GRAND STREET	GRAND STREET		HMIRS
BROOKLYN	S102147117	GRATTAN STREET	GRATTAN ST		NY Spills, NY Hist Spills
BROOKLYN	2007318749	GREEN STREET AN MCGUINESS BLVD.	GREEN STREET AN MCGUINESS BLVD		ERNS
BROOKLYN	2009919509	NY HARBOR	NY HARBOR		ERNS
BROOKLYN	94370471	HAVA DAIRY BOND STREET	HAVA DAIRY BOND STREET		ERNS
BROOKLYN	S102141301	NY HARBOR/BKLYN FLATS	NY HBR & BKLYN FLTS		NY Spills, NY Hist Spills
BROOKLYN	S102146992	HILLARY STREET	HILLARY ST		NY Spills, NY Hist Spills
BROOKLYN	2011966057	HOLSEY STREET STATION	HOLSEY STREET STA		ERNS
BROOKLYN	S110539704	CON EDISON MANHOLE 62624	HOMECREST AVE & SHORE PKWY		NY Spills
BROOKLYN	8712898	HOPKINS AVENUE AND FULTON STREET I	HOPKINS AVENUE AND FULTON STRE		ERNS
BROOKLYN	S102146473	4TH STREET	HOYT & BOND ST		NY Spills, NY Hist Spills
BROOKLYN	S102560339	FRANKLIN STREET	HURON ST		NY Spills, NY Hist Spills
BROOKLYN	S109828747	STREET	INTERSECTION CENTRAL AVE & CH		NY Spills
BROOKLYN	2008878065	INTERSECTION OF HICKS AND KANE STR	INTERSECTION OF HICKS AND KANE		ERNS
BROOKLYN	98456693	INTERSECTION OF BROADWAY AND FULTO	INTERSECTION OF BROADWAY AND F		ERNS
BROOKLYN	S110044684	MANHATTAN BEACH	INTERSECTION OXFORD & SHORE B		NY Spills
BROOKLYN	S109063418	FARRAGUT S/S. CP 45 - ONE PINT	89 JOHNS ST		NY Spills
BROOKLYN	S108981865	FARRAGUT SUBSTATION - XFMR # 3	89 JOHNS STREET AT BRIDGE ST		NY Spills
BROOKLYN	S102149908	KENT & N. 12TH STREET	KENT N 12TH ST		NY Spills, NY Hist Spills
BROOKLYN	S106866696	EXCAVATION - PIPELINE 7	KENT AVE N & O NORTH 4TH ST		NY Spills
BROOKLYN	S108636535	IN THE STREET	KENTH AVE		NY Spills

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S103938400	BOX 38486	KINGS HWY & ROCKAWAY PARK		NY Spills, NY Hist Spills
BROOKLYN	S111011885	TO ROADWAY	KINGS HWY		NY Spills
BROOKLYN	S111011715	ROADWAY	KINGS HIGHWAY AND OCEAN PKWY		NY Spills
BROOKLYN	1007208397	CONSOLIDATED EDISON	MH38210 KINGS HWY & W 7TH ST		RCRA-NonGen, MANIFEST
BROOKLYN	1009234540	NYNEX	KINGS HWY & AVE H		MANIFEST
BROOKLYN	S107407580	KINGS HIGHWAY MOBIL	KINGS HWY		NY Spills
BROOKLYN	S103560694	NYS DOT - BQE	KINGSLAND & MEEKER AVES		NY Spills, NY Hist Spills
BROOKLYN	S103560204	KNAPP STREET, CONEY ISLAN	KNAPP ST		NY Spills, NY Hist Spills
BROOKLYN	92267208	KNAPP STREET	KNAPP STREET		ERNS
BROOKLYN	S106736211	KNAPP STREET	KNAPP ST		NY Spills
BROOKLYN	S106384772	STREET INTERSECTION	LIVINGSTON & SCHEMNERHORN		NY Spills
BROOKLYN	S104787727	MANHOLE AT BOX STREET AND	MANHATTAN AVE		NY Spills, NY Hist Spills
BROOKLYN	S110752200	ON THE STREET 580 -574 MAPLE AVE	MAPLE AVE		NY Spills
BROOKLYN	S106002644	STREET	MARCUS GDN & BROADWAY		NY Spills
BROOKLYN	S110540713	STREET SIDE	318 MCDOUGALL ST		NY Spills
BROOKLYN	2006800198	MENAHAN STREET	MENAHAN STREET		ERNS
BROOKLYN	S102560248	NEW YORK HARBOR	1 MILE WEST OF ROCKAWAY		NY Spills, NY Hist Spills
BROOKLYN	S102149972	291-A MONROE STREET	2910 MONROE ST		NY Spills, NY Hist Spills
BROOKLYN	S103271837	MONTAGUE STREET	MONTAGUE ST		NY Spills, NY Hist Spills
BROOKLYN	S111012147	IN THE STREET	MOTHER GASPON AND SUTTER AVE		NY Spills
BROOKLYN	S102144594	175 FALMOUTH STREET / BRO	MRS ISAACS PVT DWELL		NY Spills, NY Hist Spills
BROOKLYN	S102147197	NAVY YARD - DECK #4	NAVY YARD DECK		NY Spills, NY Hist Spills
BROOKLYN	S103274217	STREET BY NYNEX GARAGE	NEPTUNE AVENUE BY 12TH ST		NY Spills, NY Hist Spills
BROOKLYN	S103938724	MAN HOLE #1501	NEPTUNE AVE & W 2ND ST		NY Spills, NY Hist Spills
BROOKLYN	S106126094	DOUGLASS STREET AND	NEVIS ST & 3RD AVE		NY Spills
BROOKLYN	S109581770	VAULT # V4438 - CON ED	NEW YORK 181 FEET OF SNYDER AV		NY Spills
BROOKLYN	8716759	NEW YORK HARBOR & COASTAL NY WATER	NEW YORK HARBOR & COASTAL NY W		ERNS
BROOKLYN	S109205537	STREET	890 NEW LOTTS		NY Spills
BROOKLYN	S106013020	EAST 94TH STREET AND	E NEW YORK AVE		NY Spills
BROOKLYN	S106719254	STREET	NINTH SAINTBETWEEN 2ND & 3RD		NY Spills
BROOKLYN	S104651761	MANHOLE 60040	S NORTH SERVICE & SHORE PARK		NY Spills, NY Hist Spills
BROOKLYN	S104510391	TM# 2464	NORTHSIDE AVE Z & W 2ND		NY Spills, NY Hist Spills
BROOKLYN	S106968463	STREET SPILL	E NY AVE & E 95TH ST		NY Spills
BROOKLYN	S104880865	MANHOLE 62992	OCEAN PARKWAY AT SHORE PARK		NY Spills, NY Hist Spills
BROOKLYN	1007811921	NYC DPR - FOUR SPARROWS MARSH	EAST OF FLATBUSH AVE/EXIT 11N		FINDS
BROOKLYN	2011971335	SOUTH OF THE STATION AT HALSEY STR	S OF THE STATION AT HALSEY ST		ERNS
BROOKLYN	S106005467	FLATBUSH AVENUE 300 FEET	S OF BELT PKWY		NY Spills
BROOKLYN	S102146538	OFF BELT PKWAY	OFF BELT PKWAY		NY Spills, NY Hist Spills
BROOKLYN	S102148382	OFF SHORE-AMBROSE LIGHT	OFF SHORE AMBROSE LGT		NY Spills, NY Hist Spills
BROOKLYN	S102672436	OFF BELT PARKWAY AT KNAPP	OFF BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102146887	OFF SHORE PKWY & BAY 38TH	OFF SHORE PKWY & BAY 38TH		NY Spills, NY Hist Spills
BROOKLYN	S102143226	OFF SHORE RD U/ VERRA BR	OFF SHORE RD U & VERR BR		NY Spills, NY Hist Spills
BROOKLYN	1007444974	FOUNTAIN AVENUE LANDFILL	OFF SHORE PARKWAY		ODI
BROOKLYN	S103936168	BEHIND WHITMAN DR	OHIO STATE WALK & E 66TH ST		NY Spills, NY Hist Spills
BROOKLYN	2002593058	OLD FULTON STREET	OLD FULTON STREET	0	ERNS
BROOKLYN	S102240282	80TH STREET BRIDGE	OVER BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102144583	69TH STREET & NARROWS / B	OWLS HEAD STP		NY Spills, NY Hist Spills

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S106968985	STREET SPILL	PARKSIDE AVE & CONEY IS		NY Spills
BROOKLYN	S102147975	PIER 2 -	PIER 2		NY Spills, NY Hist Spills
BROOKLYN	1008170799	NYC EDC - PIER 12	PIONEER ST & FERRIS ST	11220	FINDS
BROOKLYN	S109064593	BELL ATLANTIC-NY	PKWY BELT SVC RD		MANIFEST
BROOKLYN	S102150164	PLUM BEACH - BELT PKWY	PLUM BEACH BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102240042	JAY STREET	PLYMOUTH ST		NY Spills, NY Hist Spills
BROOKLYN	S109415576	BUILDING 4 - VANYHS	800 POLY PL		NY Spills
BROOKLYN	S102560644	TILLARY STREET AND	PRINCE ST		NY Spills, NY Hist Spills
BROOKLYN	S102146856	SHORE PRKWY - 17TH AVE	PRKWY 17TH AVE		NY Spills, NY Hist Spills
BROOKLYN	S102150198	MARCEL - 5 AUTO SHOP	PROSPECT PARK SW		NY Spills, NY Hist Spills
BROOKLYN	S102141467	RAMP TO I278	RAMP 278		NY Spills, NY Hist Spills
BROOKLYN	S106015273	SB PROSPECT EXPRESSWAY	RAMP		NY Spills
BROOKLYN	S103570427	1565 62 STREET	RESIDENTS		NY Spills, NY Hist Spills
BROOKLYN	S102147103	E. RIVER - RED HOOK PIER	E RIV		NY Spills, NY Hist Spills
BROOKLYN	99618314	RIVER STREET AND GRAND ST 94TH POL	RIVER STREET AND GRAND ST 94TH		ERNS
BROOKLYN	93337470	EAST RIVER BETWEEN N13 TO N16 STRE	EAST RIVER BETWEEN N13 TO N16		ERNS
BROOKLYN	S105058167	NORTH 1ST STREET AND	RIVER		NY Spills, NY Hist Spills
BROOKLYN	S103938065	RUSSEL STREET	RUSSELL ST		NY Spills, NY Hist Spills
BROOKLYN	1009241860	CONSOLIDATED EDISON	V6281 S 2ND ST & KEAP		MANIFEST
BROOKLYN	S106867249	APARTMENT - MISC	850 SAINT MARKS PL		NY Spills
BROOKLYN	S110487592	K - SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS MESSER		SHWS
BROOKLYN	S102402063	CANARSIE BEACH PARK	SEAVIEW AVE & SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	98421291	SHEEN SIZE: 1/2 PINT OF UNKNOWN OI	SHEEN SIZE: 1/2 PINT OF UNKNOW		ERNS
BROOKLYN	99609665	SHEEPSHEAD BAY CROSS STREET OF EMM	SHEEPSHEAD BAY CROSS STREET OF		ERNS
BROOKLYN	S102240530	UNDER BELT PARKWAY	SHELL RD & BELT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S103936114	MANHOLE # 44766	SHELL ROAD 125FT S SHORE PARK		NY Spills, NY Hist Spills
BROOKLYN	89111234	SHORE PARKWAY BETWEEN BAY 14TH STR	SHORE PARKWAY BETWEEN BAY 14TH		ERNS
BROOKLYN	S102146089	OWL'S HEAD WPCP DEP -DDC	6700 SHORE RD	11220	NY Spills, NY Hist Spills
BROOKLYN	S102146090	OWL'S HEAD WPCP DEP -DDC	6700 SHORE RD	11220	NY Spills, NY Hist Spills
BROOKLYN	S102143112	SHORE PKY/GERRITSEN INLET	SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102143133	SHORE PKWY/BAYRIDGE BAY	SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102143304	SHORE PKWY	SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	S104787045		SHORE RD & 73RD ST		NY Spills, NY Hist Spills
BROOKLYN	S104880573	VS 6130	SHORE PKWY & N BAY 44 ST		NY Spills, NY Hist Spills
BROOKLYN	S104646725		4322 WEST SHORE AVE		NY Spills, NY Hist Spills
BROOKLYN	S104648896		SHORE PKWY & BAY 16 ST		NY Spills, NY Hist Spills
BROOKLYN	1009243861	CONSOLIDATED EDISON	MH66777 SHORE RD & 91ST ST		MANIFEST
BROOKLYN	1009243901	CONSOLIDATED EDISON	MH66778 SHORE RD & SHORE PKWY		MANIFEST
BROOKLYN	1000889940	NYSDOT	SHORE RD & 255 42ND ST	11220	RCRA-NonGen, FINDS, MANIFEST
BROOKLYN	S110046953	CONSOLIDATED EDISON MH6322	MH6322 SHORE RD & NARROWS AVE		MANIFEST
BROOKLYN	S102145550	BAYSIDE FUEL TERMINAL	SHORE PKWY		NY Spills, NY Hist Spills
BROOKLYN	S110540163	NORTH OF ROCK AWAY PARKWAY INTERSE	SHOULDER OF BELT PKWY		NY Spills
BROOKLYN	1010325997	CON EDISON - VAULT 5674	WEST SIDE OF 1ST AVE. 200 FEET	11220	RCRA-NonGen
BROOKLYN	1010460773	CON EDISON - VAULT 5674	WEST SIDE OF 1ST AVE. 200 FEET	11220	FINDS
BROOKLYN	S106697861	MANHOLE #11191	N SIDE OF HIGHLAND AVE & 63RD		NY Spills
BROOKLYN	2008861865	SMITH STREET AND 9TH STREET	SMITH STREET AND 9TH STREET		ERNS
BROOKLYN	S107488773	STREET SPILL	SMITH ST & STLANTIC AVE		NY Spills

Count: 360 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S105142575	PRESIDENT STREET AND	SMITH ST		NY Spills, NY Hist Spills
BROOKLYN	S102143752	SMITH STREET	SMITH ST		SWF/LF, NY Spills, NY Hist Spills
BROOKLYN	S103271779	NEW YORK HARBOR	STAPLETON ANCHORAGE		NY Spills, NY Hist Spills
BROOKLYN	S106699727	205	STATE ST		NY Spills
BROOKLYN	2000670704	STREET	STREET		ERNS
BROOKLYN	2008884371	52 STREET AND 1ST AVENUE	52 STREET AND 1ST AVENUE		ERNS
BROOKLYN	2000671706	H STREET	H STREET		ERNS
BROOKLYN	1007805032	BAY RIDGE SUBARU - 530-63 STREET	530-63 STREET	11220	FINDS
BROOKLYN	2005617602	THE NEW YORK HARBOR	THE NEW YORK HARBOR		ERNS
BROOKLYN	S105057947	KENT AND KEEP STREET	ON THE CORNER		NY Spills, NY Hist Spills
BROOKLYN	S104284247	RODNEY STREET	IN THE AREA OF 485		NY Spills, NY Hist Spills
BROOKLYN	S103937863	TM983 - LEXINGTON AV &	TOMPKINS AVE		NY Spills, NY Hist Spills
BROOKLYN	S108764386	XFMR EXPLOSION AND FIRE - TM #192	44 ST UNDER BQE		NY Spills
BROOKLYN	S108764295	UNION STREET BRIDGE	UNION BRG		NY Spills
BROOKLYN	S102148323	20TH STREET	UNK FAC ON 20TH AVE		NY Spills, NY Hist Spills
BROOKLYN	96482518	UNKNOWN SHEEN ON THE STREET	UNKNOWN SHEEN ON THE STREET		ERNS
BROOKLYN	2011965133	UNKNOWN SHEEN INCIDENT - SHEEPSHEA	UNKNOWN SHEEN INCIDENT SHEEPSH		ERNS
BROOKLYN	1007802512	KINGS HARBOR VIEW-VAN BRUNT TO PIE	VAN BRUNT ST TO PIER 41		FINDS
BROOKLYN	2010931882	IN FRONT OF THIS ADDRESS 231 VARIC	231 VARICK ST		ERNS
BROOKLYN	S103482634	NY HARBOR	VERRAZANO BRG		NY Spills, NY Hist Spills
BROOKLYN	S102146680	VERRAZANO - N BROOKLYN	VERRAZANO N BROOKLYN		NY Spills, NY Hist Spills
BROOKLYN	1007820204	NYS OPRHP - EMPIRE FULTON FERRY ST	WATER ST - BTWN NEW DOCK ST &		FINDS
BROOKLYN	1010787611	NYSDOT BIN 106531L	I-278 WB AT INTERS OF 2ND AVE	11220	RCRA-LQG
BROOKLYN	S104952854	VAULT - #4359	WINDSON PL & PROSPECT PKWY		NY Spills, NY Hist Spills
BROOKLYN	S102147492	WOLCOH ST - AT END OFF	WOLCOH ST		NY Spills, NY Hist Spills
BROOKLYN	S110307360	218248; YORK STREET AND GREEN LANE	YORK ST & GREEN LN		NY Spills
BROOKLYN	S104194939	TM 2470	YORK STATE & HUDSON AVE		NY Spills, NY Hist Spills
KINGS COUNTY	S109207966	206936; BAY PKWY; M67498 - 7B51	BAY PKWY; M67498 - 7B51		NY Spills
KINGS COUNTY	S109208026	207656; EMPIRE BLVD; M3813 - F/O 3	EMPIRE BLVD; M3813 - F/O 377 E		NY Spills
KINGS COUNTY	S109207916	206224; FRANKLIN AVE; SB26112 - F/	FRANKLIN AVE; SB26112 - F/O 10		NY Spills
KINGS COUNTY	S109207895	205842; KINGS HWY	KINGS HWY		NY Spills
KINGS COUNTY	S109207914	206211; MONROE ST; SB30561 - OPP 1	MONROE ST; SB30561 - OPP 177 M		NY Spills
KINGS COUNTY	S109207858	205081; NEPTUNE AVE VS4897 - S/S N	NEPTUNE AVE VS4897 - S/S NEPTU		NY Spills
KINGS COUNTY	S109208049	208013; UNION ST; SB43384 - F/O 10	UNION ST; SB43384 - F/O 1038 U		NY Spills
NEW YORK	1009239506	CONSOLIDATED EDISON	TM2046 2ND AVE & 60TH ST	11220	MANIFEST
NEW YORK	1012249043	NEW YORK (C) - OWLS HEAD WPCP	BAY RIDGE AVE & THE NARROWS	11220	FINDS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPAa??s Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/10/2010
Date Data Arrived at EDR: 01/11/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/09/2011
Date Data Arrived at EDR: 03/15/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 91

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/16/2011
Date Data Arrived at EDR: 03/25/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/16/2011
Date Data Arrived at EDR: 03/25/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 04/05/2011
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 70

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 11/24/2010
Date Made Active in Reports: 12/17/2010
Number of Days to Update: 23

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/26/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/01/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 08/11/2011
Date Data Arrived at EDR: 08/12/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 32

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/31/2011
Date Data Arrived at EDR: 02/01/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 48

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 08/04/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 39
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 05/05/2011
Date Data Arrived at EDR: 08/02/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 42
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 02/16/2011
Date Data Arrived at EDR: 06/02/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 103
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/18/2011
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 25
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 31
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS UST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage
Registered Aboveground Storage Tanks.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 31

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing
These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing
These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 07/01/2011
Date Data Arrived at EDR: 08/26/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 18

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 08/11/2011
Date Data Arrived at EDR: 08/12/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 32

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 08/04/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 39

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/18/2011
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 25

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/01/2011
Date Data Arrived at EDR: 06/01/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 13

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 08/04/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 39

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 05/05/2011
Date Data Arrived at EDR: 08/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 36

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 12/23/2010
Date Made Active in Reports: 02/11/2011
Number of Days to Update: 50

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/29/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 05/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 70

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 09/05/2011
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 06/27/2011
Date Data Arrived at EDR: 06/27/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 78

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 07/29/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/08/2011
Date Data Arrived at EDR: 06/16/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 89
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/07/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites
A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/24/2011
Date Data Arrived at EDR: 05/25/2011
Date Made Active in Reports: 07/05/2011
Number of Days to Update: 41
Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 05/05/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 125

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/12/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 09/05/2011
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 04/05/2011
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 161

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/01/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/12/2011
Date Data Arrived at EDR: 02/11/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 08/09/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 08/12/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 112

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 70

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 05/31/2011
Date Data Arrived at EDR: 06/15/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 90

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/14/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/21/2010
Date Made Active in Reports: 01/28/2011
Number of Days to Update: 99

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/06/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 09/08/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/17/2010
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 94

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/30/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 08/18/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/07/2011
Date Data Arrived at EDR: 01/21/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 59
Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2010
Date Data Arrived at EDR: 11/10/2010
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 98

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/21/2011
Date Data Arrived at EDR: 07/15/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 60

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/11/2011
Date Data Arrived at EDR: 01/13/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/14/2010
Date Data Arrived at EDR: 04/16/2010
Date Made Active in Reports: 05/27/2010
Number of Days to Update: 41

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 09/13/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/13/2011
Date Data Arrived at EDR: 06/15/2011
Date Made Active in Reports: 07/18/2011
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 09/14/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 05/12/2011
Date Made Active in Reports: 05/24/2011
Number of Days to Update: 12

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 08/09/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 06/28/2011
Date Data Arrived at EDR: 06/29/2011
Date Made Active in Reports: 07/05/2011
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/20/2011
Next Scheduled EDR Contact: 10/03/2011
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/19/2011
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 11/02/2010
Date Made Active in Reports: 12/17/2010
Number of Days to Update: 45

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 05/02/2011
Next Scheduled EDR Contact: 08/15/2011
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 06/14/2011
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 20

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/30/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Varies

FINANCIAL ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/31/2008
Date Data Arrived at EDR: 11/25/2008
Date Made Active in Reports: 12/11/2008
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/14/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 01/01/2008
Date Data Arrived at EDR: 02/18/2009
Date Made Active in Reports: 05/29/2009
Number of Days to Update: 100

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/05/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

FINANCIAL ASSURANCE 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/10/2011
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands
Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: N/A

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 36

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 36

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 06/17/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 19

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 06/17/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 19

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 05/25/2011
Date Data Arrived at EDR: 05/27/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 05/25/2011
Date Data Arrived at EDR: 05/27/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/11/2009
Number of Days to Update: 16

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/26/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/11/2011
Number of Days to Update: 22

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/20/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/24/2011
Date Made Active in Reports: 06/30/2011
Number of Days to Update: 6

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 08/11/2011
Date Data Arrived at EDR: 08/26/2011
Date Made Active in Reports: 09/14/2011
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/25/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/15/2011
Number of Days to Update: 27

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 10/03/2011
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

65TH STREET EXPANSION - CROSS HARBOR
2ND AVENUE / 65TH STREET
BROOKLYN, NY 11220

TARGET PROPERTY COORDINATES

Latitude (North):	40.64260 - 40° 38' 33.4''
Longitude (West):	74.0279 - 74° 1' 40.4''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	582197.9
UTM Y (Meters):	4499326.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40074-F1 JERSEY CITY, NJ
Most Recent Revision:	1981

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 14 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
KINGS, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 360497 - FEMA DFIRM Flood data

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
JERSEY CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	0.189
Federal FRDS PWS	Nearest PWS within 0.189 miles
State Database	0.189

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 3164235.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	65th Street Expansion - Cross Harbor	CLIENT:	STV Inc.
ADDRESS:	2nd Avenue / 65th Street Brooklyn NY 11220	CONTACT:	Doane E. Cafferty
LAT/LONG:	40.6426 / 74.0279	INQUIRY #:	3164235.2s
		DATE:	September 15, 2011 11:41 am

Copyright © 2011 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

65th Street Expansion - Cross Harbor
2nd Avenue / 65th Street
Brooklyn, NY 11220

Inquiry Number: 3164235.3
September 19, 2011

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

9/19/11

Site Name:
65th Street Expansion - Cross
2nd Avenue / 65th Street
Brooklyn, NY 11220

Client Name:
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3164235.3

Contact: Doane E. Cafferty

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by STV Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, State, Zip: Brooklyn, NY 11220
Cross Street:
P.O. # 4014403
Project: Cross Harbor - 65th Street Exp
Certification # A8C9-4044-9FE7

Maps Provided:

2007	2001	1990	1978	1926
2006	1995	1988	1976	1922
2005	1994	1987	1970	1905
2004	1993	1982	1951	
2003	1992	1980	1942	
2002	1991	1979	1928	

Sanborn® Library search results
Certification # A8C9-4044-9FE7

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2006 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2005 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2004 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2003 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2002 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2001 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1995 Source Sheets




Volume 6A, Sheet 5

1994 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1993 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1992 Source Sheets




Volume 6A, Sheet 5



Volume 6A, Sheet 8

1991 Source Sheets




Volume 6A, Sheet 5

1990 Source Sheets


1988 Source Sheets

1987 Source Sheets




Volume 6A, Sheet 5

1982 Source Sheets




Volume 6A, Sheet 5

1980 Source Sheets




Volume 6A, Sheet 5

1979 Source Sheets




Volume 6A, Sheet 5

1978 Source Sheets




Volume 6A, Sheet 5

1976 Source Sheets




Volume 6A, Sheet 5

1970 Source Sheets




Volume 6A, Sheet 5

1951 Source Sheets




Volume 6A, Sheet 5

1942 Source Sheets




Volume 6A, Sheet 5

1928 Source Sheets




Volume Pier Maps, Sheet 52

1926 Source Sheets




Volume 6A, Sheet 8




Volume 6A, Sheet 5

1922 Source Sheets



Volume Pier Maps, Sheet 44

1905 Source Sheets



Volume 11, Sheet 16

2007 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2007

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2006 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2006


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2005 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2005


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2004 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2004


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2003 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2003


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2002 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2002

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2001 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2001


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1995 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1995


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5

N

1994 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1994


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1993 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1993

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1992 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1992


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1991 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1991


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5

N

1990 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.


EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1990

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





0 Feet 165 330 660

N

1988 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1988


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





1987 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1987


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 5

1982 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1982


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6A, Sheet 5

0 Feet 165 330 660

N

1980 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1980

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6A, Sheet 5

0 Feet 165 330 660

N

1979 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1979

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5


N

1978 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1978


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6A, Sheet 5

0 Feet 165 330 660

N

1976 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1976

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5

N

1970 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1970

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 6A, Sheet 5

0 Feet 165 330 660

N

1951 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1951


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6A, Sheet 5



1942 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1942


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5


N

1928 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1928


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume Pier Maps, Sheet 52


N

1926 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1926


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 8
Volume 6A, Sheet 5


N

1922 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1922


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume Pier Maps, Sheet 44

N

1905 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1905

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 11, Sheet 16

N

65th Street Expansion - Cross Harbor
2nd Avenue / 65th Street
Brooklyn, NY 11220

Inquiry Number: 3164235.3
September 19, 2011

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

9/19/11

Site Name:
65th Street Expansion - Cross
2nd Avenue / 65th Street
Brooklyn, NY 11220

Client Name:
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3164235.3

Contact: Doane E. Cafferty

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by STV Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, State, Zip: Brooklyn, NY 11220
Cross Street:
P.O. # 4014403
Project: Cross Harbor - 65th Street Exp
Certification # A8C9-4044-9FE7

Maps Provided:

2007	2001	1990	1978	1926
2006	1995	1988	1976	1922
2005	1994	1987	1970	1905
2004	1993	1982	1951	1893
2003	1992	1980	1942	
2002	1991	1979	1928	

Sanborn® Library search results
Certification # A8C9-4044-9FE7

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

2006 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

2005 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 1

2004 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

2003 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

2002 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

2001 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1995 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1994 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1993 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1992 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1991 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1990 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1988 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1987 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1982 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1980 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1979 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1978 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1976 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1970 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 1

1951 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1942 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1928 Source Sheets




Volume Pier Maps, Sheet 52

1926 Source Sheets




Volume 6A, Sheet 1




Volume 6A, Sheet 5

1922 Source Sheets




Volume Pier Maps, Sheet 44

1905 Source Sheets



Volume 11, Sheet 16




Volume 11, Sheet 33

1893 Source Sheets

2007 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2007




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

2006 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2006



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

2005 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2005





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 5
Volume 6A, Sheet 1

N

2004 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2004


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

2003 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification #: A8C9-4044-9FE7
Copyright: 2003





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

2002 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2002





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

2001 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2001




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1995 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification #: A8C9-4044-9FE7
Copyright: 1995




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1994 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification #: A8C9-4044-9FE7
Copyright: 1994




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N


1993 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1993



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1992 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification #: A8C9-4044-9FE7
Copyright: 1992




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1991 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification #: A8C9-4044-9FE7
Copyright: 1991





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1990 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1990


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1988 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1988




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1987 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1987


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1982 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1982




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 1
Volume 6A, Sheet 5


N

1980 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1980


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1979 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1979




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1978 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1978





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1976 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1976



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N


1970 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1970



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 5
Volume 6A, Sheet 1

N

1951 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1951



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5

N

1942 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1942


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5


N

1928 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660




52

Volume Pier Maps, Sheet 52

N

1926 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1926




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 1
Volume 6A, Sheet 5


N


1922 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume Pier Maps, Sheet 44


N

1905 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1905

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 11, Sheet 16
Volume 11, Sheet 33

N

1893 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1893



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660

N

65th Street Expansion - Cross Harbor
2nd Avenue / 65th Street
Brooklyn, NY 11220

Inquiry Number: 3164235.3
September 19, 2011

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

9/19/11

Site Name:
65th Street Expansion - Cross
2nd Avenue / 65th Street
Brooklyn, NY 11220

Client Name:
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3164235.3

Contact: Doane E. Cafferty

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by STV Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, State, Zip: Brooklyn, NY 11220
Cross Street:
P.O. # 4014403
Project: Cross Harbor - 65th Street Exp
Certification # A8C9-4044-9FE7

Maps Provided:

2007	2001	1990	1978	1926
2006	1995	1988	1976	1922
2005	1994	1987	1970	1905
2004	1993	1982	1951	1893
2003	1992	1980	1942	
2002	1991	1979	1928	

Sanborn® Library search results
Certification # A8C9-4044-9FE7

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2007 Source Sheets



Volume 6A, Sheet 5




Volume 6A, Sheet 7




Volume 6A, Sheet 8

2006 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2005 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2004 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2003 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2002 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

2001 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1995 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1994 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1993 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1992 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1991 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8


1990 Source Sheets



Volume 6A, Sheet 5




Volume 6A, Sheet 7




Volume 6A, Sheet 8

1988 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1987 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1982 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1980 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1979 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1978 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1976 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1970 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1951 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1942 Source Sheets




Volume 6A, Sheet 5




Volume 6A, Sheet 8

1928 Source Sheets




Volume Pier Maps, Sheet 52

1926 Source Sheets




Volume 6A, Sheet 8




Volume 6A, Sheet 5

1922 Source Sheets




Volume Pier Maps, Sheet 44


1905 Source Sheets



Volume 11, Sheet 14




Volume 11, Sheet 15



Volume 11, Sheet 16

1893 Source Sheets



Volume A, Sheet 29

2007 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2007

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 7
Volume 6A, Sheet 8

N

2006 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2006


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6A, Sheet 5
Volume 6A, Sheet 8

0 Feet 165 330 660

N

2005 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2005

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660

Volume 6A, Sheet 5
Volume 6A, Sheet 8

2004 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2004


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2003 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 2003





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

2002 Certified Sanborn Map


Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 2002




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 6A, Sheet 5
Volume 6A, Sheet 8

0 Feet 165 330 660

N

2001 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 2001


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1995 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1995


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1994 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1994


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1993 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1993


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1992 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1992


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1991 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1991





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1990 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1990


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 7
Volume 6A, Sheet 8

N

1988 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1988


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1987 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1987


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1982 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1982


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1980 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1980


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1979 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220

Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7


Copyright: 1979


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A8C9-4044-9FE7

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1978 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1978

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1976 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1976


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1970 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1970

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8

N

1951 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street

City, ST, ZIP: Brooklyn NY 11220


Client: STV Inc.

EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7

Copyright: 1951


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1942 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1942

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 6A, Sheet 5
Volume 6A, Sheet 8


N

1928 Certified Sanborn Map

Site Name: 65th Street Expansion - Cross Harbor
Address: 2nd Avenue / 65th Street
City, ST, ZIP: Brooklyn NY 11220
Client: STV Inc.
EDR Inquiry: 3164235.3
Order Date: 9/19/2011 11:20:01 AM
Certification # A8C9-4044-9FE7
Copyright: 1928


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # A8C9-4044-9FE7



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume Pier Maps, Sheet 52

N