166 JUNIUS STREET (Continued) **U003383718**

Modified By: TRANSLAT
Last Modified: 3/4/2004

HIST AST:
PBS Number: 2-061107
SWIS Code: 6101
Operator: TITO QUNONES
Facility Phone: (718) 858-9875
Facility Addr2: 166 JUNIUS STREET
Facility Type: APARTMENT BUILDING
Emergency: TITO QUINONES/JUNI RALTY COR.
Emergency Tel: (718) 858-9873
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: JUNI REALTY CORPORATION
Owner Address: 32 COURT STREET, SUITE 1408
Owner City,St,Zip: BROOKLYN, NY 11201
Federal ID: Not reported
Owner Tel: (718) 858-8873
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: JUNI REALTY CORPORATION
Mailing Address: 32 COURT STREET
Mailing Address 2: SUITE 1408
Mailing City,St,Zip: BROOKLYN, NY 11201
Mailing Telephone: (718) 858-8873
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 09/15/1998
Expiration: 09/15/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 4750
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: 19620901
Capacity (Gal): 4750
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

166 JUNIUS STREET (Continued) **U003383718**

Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	9
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

F30 **SIMTEC AUTO REPAIR & DIAGNOSTIC CENTER** **AST** **A100300838**
WSW **248 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.003 mi.
14 ft. **Site 3 of 3 in cluster F**

Relative:
Higher

Actual:
39 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610454
Program Type:	PBS
UTM X:	592735.43695
UTM Y:	4502566.3028199999
Expiration Date:	2012/01/24

Affiliation Records:

Site Id:	376495
Affiliation Type:	On-Site Operator
Company Name:	SIMTEC AUTO REPAIR & DIAGNOSTIC CENTER
Contact Type:	Not reported
Contact Name:	SIMON BUSANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 312-1464
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/24/2007

Site Id:	376495
Affiliation Type:	Owner
Company Name:	SIMON BUSANO

SIMTEC AUTO REPAIR & DIAGNOSTIC CENTER (Continued) **A100300838**

Contact Type:	PROPRIETOR
Contact Name:	SIMON BUSANO
Address1:	248 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 312-1464
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/24/2007

Site Id:	376495
Affiliation Type:	Mail Contact
Company Name:	SIMTEC AUTO REPAIR & DIAGNOSTIC CENTER
Contact Type:	Not reported
Contact Name:	MR. SIMON BUSANO
Address1:	248 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 312-1464
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/24/2007

Site Id:	376495
Affiliation Type:	Emergency Contact
Company Name:	SIMON BUSANO
Contact Type:	Not reported
Contact Name:	SIMON BUSANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 927-9784
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/24/2007

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Tank Info:

SIMTEC AUTO REPAIR & DIAGNOSTIC CENTER (Continued) **A100300838**

Tank Number:	1
Tank Id:	215549
Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	1/24/2007

I31 **BROOKLYN CLASSICS** **FINDS** **1007788719**
WSW **84 JUNIUS ST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.003 mi.
14 ft. **Site 2 of 11 in cluster I**

Relative:
Higher

Actual:
51 ft.

FINDS:

Registry ID: 110019512062

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

G32 **CONSOLIDATED EDISON OF NY** **MANIFEST** **S107908902**
WSW **134 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.003 mi.
14 ft. **Site 4 of 5 in cluster G**

Relative:
Higher

Actual:
48 ft.

NJ MANIFEST:

Manifest Code:	NJA5067313
EPA ID:	NYD004132791
Date Shipped:	20050623
TSDF EPA ID:	NJD991291105

CONSOLIDATED EDISON OF NY (Continued) **S107908902**

Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050623
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050624
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08230522
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

G33 **IN FRONT OF** **NY Spills** **S106968976**
WSW **134 JUNIUS ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.003 mi.
14 ft. **Site 5 of 5 in cluster G**

Relative:
Higher

Actual:
48 ft.

NY Spills:

Site ID:	347974
Facility Addr2:	Not reported
Facility ID:	0503380
Spill Number:	0503380
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	6/20/2005
Reported to Dept:	6/20/2005
CID:	408
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

IN FRONT OF (Continued) **S106968976**

Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/29/2005
Remediation Phase:	0
Date Entered In Computer:	6/20/2005
Spill Record Last Update:	8/29/2005
Spiller Name:	Not reported
Spiller Company:	UNKNOWN, 3RD PARTY SPILL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	ERT DESK MIKE DAUGHTERY
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	294323
DEC Memo:	159319. 20-JUN-2005 1545 HRS SPINELLI # 86136 MAINT CONST REPORTS FOUND 8 GALLONS ANTIFREEZE ON 10 GALLONS WATER IN M-5160. FOUND WHILE DOING INSPECTION. NO FIRE OR SMOKE. NO PRIVATE PROPERTY. NO INJURIES. NO SEWERS OR WATERWAYS AFFECTED. IT APPEARS TO BE CONTAINED TO STRUCTURE. TOOK SAMPLE ON A 4 TO 6 HOUR PRIORITY E TURNAROUND. PLACED ENVIROMENTAL STOP TAG # 42774 . CLEANUP PENDING RESULTS. NO CRACKS IN THE STRUCTURE WALLS. NO VISUAL WATER MOVEMENT. WATER STANDING STILL. CHAIN OF CUSTODY # IS EE05074. NOTIFY CIG SHIKARIDES @1623 HRS. JR78448 UPDATE 6-20-05 20:00 HRS CHEM LAB CALLED, AND SAID NOT ENOUGH PRODUCT TO DO PCB SAMPLING. S. PACE 49874. UPDATE 6-20-05 23:30 HRS MIDNIGHT CREW WILL RE-SAMPLE FOR OIL ID & PCB. S. PACE 49874. June 21, 2005 1:18 PM. Lab Sequence Number: 05-05965-001 Aroclor 1260 < 1.0 ppm Oil Identification. No oil extracted to perform oil identification UPDATE 23-JUN-2005 02:40 HRS. ENVIR. OPER. O.S. E.WILLIAMS EMP# 56346 REPORTS: (VENDOR) ALL STATE POWER VAC. REMOVED 600 GALS OF LIQUID FROM STRUCTURE. CREW THEN DBL. WASHED STRUCTURE NO SUMP IN STRUCTURE. ENVIR.TAG# 42774 REMOVED. CLEANUP COMPLETE 100%. C.HOGAN 07511 Closed. 8-29-05. GB
Remarks:	NO TO 5 QUESTIONS. PENDING SAMPLE RESULTS ON ED #159319

Material:

Site ID:	347974
Operable Unit ID:	1105652
Operable Unit:	01
Material ID:	1521466
Material Code:	0043A
Material Name:	ANTIFREEZE
Case No.:	Not reported
Material FA:	Other
Quantity:	8
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported

IN FRONT OF (Continued) **S106968976**

Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

J34 **LEO INTERNATIONAL WAREHOUSE** **RCRA-NonGen** **1005417311**
East **471 SUTTER AVE** **FINDS** **NYR000104372**
< 1/8 **BROOKLYN, NY 11208**
0.003 mi.
14 ft. **Site 1 of 3 in cluster J**

Relative:
Higher

Actual:
39 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	LEO INTERNATIONAL WAREHOUSE
Facility address:	471 SUTTER AVE BROOKLYN, NY 11208
EPA ID:	NYR000104372
Mailing address:	COOPER AVE GLENDALE, NY 11385
Contact:	GARY STERN
Contact address:	COOPER AVE GLENDALE, NY 11385
Contact country:	US
Contact telephone:	(718) 418-2644
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	GARY P STERN
Owner/operator address:	80-00 COOPER AVE GLENDALE, NY 11385
Owner/operator country:	US
Owner/operator telephone:	(718) 418-2644
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	GARY P STERN
Owner/operator address:	80-00 COOPER AVE GLENDALE, NY 11385
Owner/operator country:	US
Owner/operator telephone:	(718) 418-2644
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

LEO INTERNATIONAL WAREHOUSE (Continued) **1005417311**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: LEO INTERNATIONAL WAREHOUSE
Classification: Not a generator, verified

Date form received by agency: 03/01/2002
Facility name: LEO INTERNATIONAL WAREHOUSE
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012262700

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

J35 **MTA NYCT - SUTTER AVE STATION L-LINE** **RCRA-LQG** **1005444348**
East **SUTTER & VAN SINDEREN AVE** **FINDS** **NYR000106690**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.003 mi. **MANIFEST**
17 ft. **Site 2 of 3 in cluster J**

Relative:
Higher

Actual:
39 ft.

RCRA-LQG:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - SUTTER AVE STATION L-LINE
Facility address:	SUTTER & VAN SINDEREN AVE BROOKLYN, NY 11207
EPA ID:	NYR000106690
Mailing address:	BROADWAY 2ND FLOOR NEW YORK, NY 10004
Contact:	THOMAS A ABDALLAH
Contact address:	BROADWAY 2ND FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3500
Contact email:	Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: MTA NYCT
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Owner/operator name: MTA NYCT
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 03/01/1968
Owner/Op end date: Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT - SUTTER AVE STATION L-LINE
Classification: Not a generator, verified

Date form received by agency: 12/22/2004
Facility name: MTA NYCT - SUTTER AVE STATION L-LINE
Classification: Small Quantity Generator

Date form received by agency: 06/04/2002
Facility name: MTA NYCT - SUTTER AVE STATION L-LINE
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110012553842

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:
Manifest Code: NJA5286944
EPA ID: NYR000106690
Date Shipped: 20060221
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060221
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060221
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04060625
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5319608
EPA ID:	NYR000106690
Date Shipped:	20060512
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060512
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060515
Tranporter 1 Decal:	Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Tranporter 2 Decal: Not reported
Data Entry Number: 06210621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5286897
EPA ID: NYR000106690
Date Shipped: 20060106
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060106
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060106
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 04030621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5319778
EPA ID: NYR000106690
Date Shipped: 20060714
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060714
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060715
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08100622
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5319566
EPA ID:	NYR000106690
Date Shipped:	20060425
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060425
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060425
Tranporter 1 Decal:	Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Tranporter 2 Decal: Not reported
Data Entry Number: 06200622
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5286973
EPA ID: NYR000106690
Date Shipped: 20060314
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060314
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060315
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 04110621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

NY MANIFEST:
EPA ID: NYR000106690
Country: USA
Mailing Name: NYCTA CPM ENVIRO ENG DIV
Mailing Contact: N/S
Mailing Address: 2 BROADWAY 2ND FL

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	646-252-3500

Document ID:	NJA5286973
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2006
Trans1 Recv Date:	03/14/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106690
Trans1 EPA ID:	S8424
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA5319608
Manifest Status:	Not reported
Trans1 State ID:	NYD046745574
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2006
Trans1 Recv Date:	05/12/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/15/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106690
Trans1 EPA ID:	087987
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Document ID:	NJA5286897
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/2006
Trans1 Recv Date:	01/06/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106690
Trans1 EPA ID:	S8424
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA5286944
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/2006
Trans1 Recv Date:	02/21/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106690
Trans1 EPA ID:	S8424
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA5319566
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	04/25/2006
Trans1 Recv Date:	04/25/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2006
Part A Recv Date:	Not reported

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Part B Recv Date: Not reported
Generator EPA ID: NYR000106690
Trans1 EPA ID: S8424
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 05000
Units: P - Pounds
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 06

Document ID: NJA5286897
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 01/06/2006
Trans1 Recv Date: 01/06/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/06/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000106690
Trans1 EPA ID: S8424
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 06

Document ID: NJA5286944
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 02/21/2006
Trans1 Recv Date: 02/21/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/21/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000106690
Trans1 EPA ID: S8424
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03000
Units: P - Pounds
Number of Containers: 006

MTA NYCT - SUTTER AVE STATION L-LINE (Continued) **1005444348**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA5286973
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2006
Trans1 Recv Date:	03/14/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/15/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106690
Trans1 EPA ID:	S8424
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

J36 **NYCDOT SUTTER AVE BRIDGE #2243890** **RCRA-CESQG** **1006817529**
East **SUTTER AVE BRG OVER LIRR** **MANIFEST** **NYR000116483**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.003 mi.
17 ft. **Site 3 of 3 in cluster J**

Relative:
Higher

Actual:
39 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	NYCDOT SUTTER AVE BRIDGE #2243890
Facility address:	SUTTER AVE BRG OVER LIRR BROOKLYN, NY 11207
EPA ID:	NYR000116483
Mailing address:	RECTOR ST - 5TH FLOOR NEW YORK, NY 10006
Contact:	ALEX BEZCHASTNOV
Contact address:	RECTOR ST - 5TH FLOOR NEW YORK, NY 10006
Contact country:	US
Contact telephone:	(212) 788-2091
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

NYCDOT SUTTER AVE BRIDGE #2243890 (Continued) **1006817529**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYCDOT
Owner/operator address:	RECTOR ST NEW YORK, NY 10006
Owner/operator country:	US
Owner/operator telephone:	(212) 788-2091
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	12/31/1979
Owner/Op end date:	Not reported

Owner/operator name:	NYCDOT
Owner/operator address:	SUTTER AVE BRG OVER LIRR BROOKLYN, NY 11207
Owner/operator country:	US
Owner/operator telephone:	(212) 788-2091
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	12/31/1979
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	NYCDOT SUTTER AVE BRIDGE #2243890
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	06/23/2003
Facility name:	NYCDOT SUTTER AVE BRIDGE #2243890
Classification:	Small Quantity Generator

Violation Status: No violations found

NYCDOT SUTTER AVE BRIDGE #2243890 (Continued) **1006817529**

NY MANIFEST:

EPA ID:	NYR000116483
Country:	USA
Mailing Name:	SUNRISE DECKING CORPORATION
Mailing Contact:	N/S
Mailing Address:	PO BOX 843
Mailing Address 2:	Not reported
Mailing City:	AMITYVILLE
Mailing State:	NY
Mailing Zip:	11701
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-672-8163

Document ID:	NJA5009784
Manifest Status:	Not reported
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2004
Trans1 Recv Date:	03/05/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/05/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000116483
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	04

NJ MANIFEST:

Manifest Code:	NJA5009784
EPA ID:	NYR000116483
Date Shipped:	20040305
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040305
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

NYCDOT SUTTER AVE BRIDGE #2243890 (Continued) **1006817529**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040305
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04300421
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

---

37 **LEGION LIGHTING CO** **RCRA-NonGen** **1000259298**
East **221 GLENMORE AVE.** **FINDS** **NYD001212406**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.003 mi.
18 ft.

Relative:
Higher

Actual:
47 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	LEGION LIGHTING CO INC
Facility address:	221 GLENMORE AVE BROOKLYN, NY 112073394
EPA ID:	NYD001212406
Mailing address:	GLENMORE AVE BROOKLYN, NY 11207
Contact:	Not reported
Contact address:	GLENMORE AVE BROOKLYN, NY 11207
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LEGION LIGHTING CO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

LEGION LIGHTING CO (Continued) **1000259298**

Owner/operator name: LEGION LIGHTING CO INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: LEGION LIGHTING CO INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: LEGION LIGHTING CO INC
Classification: Not a generator, verified

Date form received by agency: 04/23/1982
Facility name: LEGION LIGHTING CO INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/23/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110001602169

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the

LEGION LIGHTING CO (Continued) **1000259298**

National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYD001212406
Country:	USA
Mailing Name:	LEGION LIGHTING COMPANY
Mailing Contact:	CHARLES TZOUCALIS
Mailing Address:	221-3 GLENMORE AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-498-1770

Document ID:	NJA0841512
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS-81
Trans2 State ID:	Not reported
Generator Ship Date:	900206
Trans1 Recv Date:	900206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900206
Part A Recv Date:	900220
Part B Recv Date:	900222
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.

LEGION LIGHTING CO (Continued) **1000259298**

Specific Gravity: 100
Year: 90

Document ID: NYO1586385
Manifest Status: Completed copy
Trans1 State ID: H1A019
Trans2 State ID: Not reported
Generator Ship Date: 820810
Trans1 Recv Date: 820810
Trans2 Recv Date: Not reported
TSD Site Recv Date: 820810
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001212406
Trans1 EPA ID: NYD077515575
Trans2 EPA ID: Not reported
TSDF ID: NJD048810279
Waste Code: F001 - UNKNOWN
Quantity: 00090
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 82

Document ID: NJA1013486
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 900504
Trans1 Recv Date: 900504
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900504
Part A Recv Date: 900622
Part B Recv Date: 900626
Generator EPA ID: NYD001212406
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: F005 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 90

Document ID: NJA0938309
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS-81
Trans2 State ID: Not reported
Generator Ship Date: 900719

LEGION LIGHTING CO (Continued) **1000259298**

Trans1 Recv Date:	900719
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900720
Part A Recv Date:	900830
Part B Recv Date:	900824
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90

Document ID:	NYO1586322
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	830113
Trans1 Recv Date:	830113
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830113
Part A Recv Date:	030120
Part B Recv Date:	030120
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NYD077515575
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00095
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	83

Document ID:	NYO1726065
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	830603
Trans1 Recv Date:	830603
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	830603
Part A Recv Date:	030613
Part B Recv Date:	030613
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NYD077515575
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279

LEGION LIGHTING CO (Continued) **1000259298**

Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	83

Document ID:	NJA0970698
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS815
Trans2 State ID:	Not reported
Generator Ship Date:	910417
Trans1 Recv Date:	910417
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910417
Part A Recv Date:	910426
Part B Recv Date:	910429
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD156163438
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

Document ID:	NYO1726056
Manifest Status:	Completed copy
Trans1 State ID:	S6329AF
Trans2 State ID:	Not reported
Generator Ship Date:	840127
Trans1 Recv Date:	840127
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840127
Part A Recv Date:	840203
Part B Recv Date:	840207
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NYD077515575
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	84

LEGION LIGHTING CO (Continued) **1000259298**

Document ID:	NJA0003094
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS632
Trans2 State ID:	NA-NJ
Generator Ship Date:	841002
Trans1 Recv Date:	841002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	841002
Part A Recv Date:	841009
Part B Recv Date:	841011
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	84

Document ID:	NJA0009926
Manifest Status:	Completed copy
Trans1 State ID:	JA-195NJS
Trans2 State ID:	Not reported
Generator Ship Date:	850627
Trans1 Recv Date:	850627
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850627
Part A Recv Date:	850718
Part B Recv Date:	850702
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	85

Document ID:	NJA1168931
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS815
Trans2 State ID:	Not reported
Generator Ship Date:	910807
Trans1 Recv Date:	910807
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910807
Part A Recv Date:	910815

LEGION LIGHTING CO (Continued) **1000259298**

Part B Recv Date: 910819
Generator EPA ID: NYD001212406
Trans1 EPA ID: NJD156163438
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F001 - UNKNOWN
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA2020281
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 8809
Trans2 State ID: Not reported
Generator Ship Date: 951114
Trans1 Recv Date: 951114
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951114
Part A Recv Date: Not reported
Part B Recv Date: 951215
Generator EPA ID: NYD001212406
Trans1 EPA ID: NJD002454544
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F001 - UNKNOWN
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00050
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 95

Document ID: NJA0009773
Manifest Status: Completed copy
Trans1 State ID: NJSWAS632
Trans2 State ID: Not reported
Generator Ship Date: 850305
Trans1 Recv Date: 850305
Trans2 Recv Date: Not reported
TSD Site Recv Date: 850305
Part A Recv Date: 850312
Part B Recv Date: 850312
Generator EPA ID: NYD001212406

LEGION LIGHTING CO (Continued) **1000259298**

Trans1 EPA ID:	NJD048810279
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	85

Document ID:	NYO1586313
Manifest Status:	Completed copy
Trans1 State ID:	JA-195
Trans2 State ID:	Not reported
Generator Ship Date:	840410
Trans1 Recv Date:	840410
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840410
Part A Recv Date:	840417
Part B Recv Date:	840417
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NYD077515575
Trans2 EPA ID:	Not reported
TSDF ID:	NJD048810279
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	84

Document ID:	NJA0173399
Manifest Status:	Completed copy
Trans1 State ID:	NJDEP#S06
Trans2 State ID:	NJDEP#S06
Generator Ship Date:	860626
Trans1 Recv Date:	860626
Trans2 Recv Date:	860627
TSD Site Recv Date:	860627
Part A Recv Date:	860702
Part B Recv Date:	860701
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD981138324
Trans2 EPA ID:	NJD981138324
TSDF ID:	NJD002454544
Waste Code:	F001 - UNKNOWN
Quantity:	00136
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.

LEGION LIGHTING CO (Continued) **1000259298**

Specific Gravity: 100
Year: 86

Document ID: NJA1157514
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 910726
Trans1 Recv Date: 910726
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910726
Part A Recv Date: 910802
Part B Recv Date: 910812
Generator EPA ID: NYD001212406
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: F005 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1302866
Manifest Status: Completed copy
Trans1 State ID: NJDEPS815
Trans2 State ID: Not reported
Generator Ship Date: 920309
Trans1 Recv Date: 920309
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920309
Part A Recv Date: 920317
Part B Recv Date: 920319
Generator EPA ID: NYD001212406
Trans1 EPA ID: NJD156163438
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F001 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

Document ID: MAC0871460
Manifest Status: Completed copy
Trans1 State ID: NJDEP#S06
Trans2 State ID: NJDEP#S07
Generator Ship Date: 861009

LEGION LIGHTING CO (Continued) **1000259298**

Trans1 Recv Date:	861009
Trans2 Recv Date:	861010
TSD Site Recv Date:	861015
Part A Recv Date:	861015
Part B Recv Date:	861021
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD981138324
Trans2 EPA ID:	MAD019371079
TSDF ID:	MAD019371079
Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86

Document ID:	NYA3127724
Manifest Status:	Completed copy
Trans1 State ID:	PLATE#
Trans2 State ID:	Not reported
Generator Ship Date:	870326
Trans1 Recv Date:	870326
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870326
Part A Recv Date:	870331
Part B Recv Date:	870407
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F005 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	87

Document ID:	NJA0173208
Manifest Status:	Completed copy
Trans1 State ID:	JA-195NJD
Trans2 State ID:	NJDEP#S06
Generator Ship Date:	860306
Trans1 Recv Date:	860306
Trans2 Recv Date:	860307
TSD Site Recv Date:	860307
Part A Recv Date:	860311
Part B Recv Date:	860317
Generator EPA ID:	NYD001212406
Trans1 EPA ID:	NJD981138324
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544

LEGION LIGHTING CO (Continued) **1000259298**

Waste Code:	F001 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86

Click this hyperlink while viewing on your computer to access
19 additional NY_MANIFEST: record(s) in the EDR Site Report.

K38 **ATLANTIC COLLISION** **RCRA-SQG 1004762384**
East **482 BLAKE AVE** **FINDS NYR000096396**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.005 mi. **MANIFEST**
29 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	ATLANTIC COLLISION
Facility address:	482 BLAKE AVE BROOKLYN, NY 11207
EPA ID:	NYR000096396
Mailing address:	BLAKE AVE BROOKLYN, NY 11207
Contact:	ABE CYMBAL
Contact address:	BLAKE AVE BROOKLYN, NY 11207
Contact country:	US
Contact telephone:	(718) 498-6100
Contact email:	Not reported
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	850 ATLANTIC COLLISION INC
Owner/operator address:	41C W MERRICK RD VALLEY STREAM, NY 11580
Owner/operator country:	US
Owner/operator telephone:	(516) 678-6900
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	850 ATLANTIC COLLISION INC
Owner/operator address:	41C W MERRICK RD VALLEY STREAM, NY 11580
Owner/operator country:	US
Owner/operator telephone:	(516) 678-6900
Legal status:	Private

ATLANTIC COLLISION (Continued) **1004762384**

Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ATLANTIC COLLISION
Classification: Small Quantity Generator

Date form received by agency: 05/01/2001
Facility name: ATLANTIC COLLISION
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110009451636

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:
Manifest Code: NJA5034249
EPA ID: NYR000096396
Date Shipped: 20041116
TSDF EPA ID: NJD002454544
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD002454544
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	041116
Date Trans2 Transported Waste:	041119
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	041119
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	01120521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	004072147JJK
EPA ID:	NYR000096396
Date Shipped:	7/1/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	7/1/2008
Date Trans2 Transported Waste:	7/3/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	7/3/2008
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No

ATLANTIC COLLISION (Continued) **1004762384**

Reason Load Was Rejected: Not reported
Waste Code: F003
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 1350
Unit: P
Hand Code: H141

Manifest Code: 004718277JJK
EPA ID: NYR000096396
Date Shipped: 02/05/10
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 02/05/10
Date Trans2 Transported Waste: 2/8/10
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 02/12/10
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: F003
Manifest Year: 2010 New Jersey Manifest Data
Quantity: 1350
Unit: P
Hand Code: H141

Manifest Code: NJA5037335
EPA ID: NYR000096396
Date Shipped: 20040317
TSDF EPA ID: NJD002454544
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD002454544
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040317
Date Trans2 Transported Waste:	040323
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040323
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04290425
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5034250
EPA ID:	NYR000096396
Date Shipped:	20040701
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD002454544
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040701
Date Trans2 Transported Waste:	040709
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040709
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08040422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No

ATLANTIC COLLISION (Continued) **1004762384**

Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5034251
EPA ID: NYR000096396
Date Shipped: 20040512
TSDF EPA ID: NJD002454544
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD002454544
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040512
Date Trans2 Transported Waste: 040514
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040514
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 05270422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5279727
EPA ID: NYR000096396
Date Shipped: 20051024
TSDF EPA ID: NJD002454544
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD002454544
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	051024
Date Trans2 Transported Waste:	051028
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	051028
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	01090621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	004718801JJK
EPA ID:	NYR000096396
Date Shipped:	05/27/09
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/27/09
Date Trans2 Transported Waste:	5/27/09
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/29/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No

ATLANTIC COLLISION (Continued) **1004762384**

Reason Load Was Rejected: Not reported
Waste Code: F003
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 450
Unit: P
Hand Code: H141

NY MANIFEST:

EPA ID:	NYR000096396
Country:	USA
Mailing Name:	ATLANTIC AUTO BODY
Mailing Contact:	MARC CAPUS
Mailing Address:	482 BLAKE AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2009-05-27
Trans1 Recv Date:	2009-05-27
Trans2 Recv Date:	2009-05-27
TSD Site Recv Date:	2009-05-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	450.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	004718801JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Mgmt Method Type Code: H141

Document ID: NJA5279727
Manifest Status: Not reported
Trans1 State ID: NYD064748304
Trans2 State ID: NJD002454544
Generator Ship Date: 10/24/2005
Trans1 Recv Date: 10/24/2005
Trans2 Recv Date: 10/28/2005
TSD Site Recv Date: 10/28/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000096396
Trans1 EPA ID: NY1A378
Trans2 EPA ID: 2809
TSDF ID: NJD002454544
Waste Code: F003 - UNKNOWN
Quantity: 01800
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA5034249
Manifest Status: Not reported
Trans1 State ID: 1A378
Trans2 State ID: 2809
Generator Ship Date: 11/16/2004
Trans1 Recv Date: 11/16/2004
Trans2 Recv Date: 11/19/2004
TSD Site Recv Date: 11/19/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000096396
Trans1 EPA ID: NYD064748304
Trans2 EPA ID: Not reported
TSDF ID: NJD002454
Waste Code: F003 - UNKNOWN
Quantity: 01350
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 04

Document ID: NJA5034250
Manifest Status: Not reported
Trans1 State ID: 1A378
Trans2 State ID: 2809
Generator Ship Date: 07/01/2004
Trans1 Recv Date: 07/01/2004

ATLANTIC COLLISION (Continued) **1004762384**

Trans2 Recv Date:	07/09/2004
TSD Site Recv Date:	07/09/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	NYD064748304
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454
Waste Code:	F003 - UNKNOWN
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	04

Document ID:	NJA5037335
Manifest Status:	Not reported
Trans1 State ID:	NY1A378
Trans2 State ID:	2809
Generator Ship Date:	03/17/2004
Trans1 Recv Date:	03/17/2004
Trans2 Recv Date:	03/23/2004
TSD Site Recv Date:	03/23/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	NYD064748304
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454
Waste Code:	F003 - UNKNOWN
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	04

Document ID:	NJA5034251
Manifest Status:	Not reported
Trans1 State ID:	26676JENY
Trans2 State ID:	2809
Generator Ship Date:	05/12/2004
Trans1 Recv Date:	05/12/2004
Trans2 Recv Date:	05/14/2004
TSD Site Recv Date:	05/14/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	NYD064748304
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454
Waste Code:	F003 - UNKNOWN

ATLANTIC COLLISION (Continued) **1004762384**

Quantity:	01350
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	04

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2008-07-01
Trans1 Recv Date:	2008-07-01
Trans2 Recv Date:	2008-07-03
TSD Site Recv Date:	2008-07-03
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	004072147JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	NJA5279727
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD002454544
Generator Ship Date:	10/24/2005
Trans1 Recv Date:	10/24/2005
Trans2 Recv Date:	10/28/2005
TSD Site Recv Date:	10/28/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	NY1A378

ATLANTIC COLLISION (Continued) **1004762384**

Trans2 EPA ID:	2809
TSDF ID:	NJD002454544
Waste Code:	F003 - UNKNOWN
Quantity:	01800
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2005

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2009-05-27
Trans1 Recv Date:	2009-05-27
Trans2 Recv Date:	2009-05-27
TSD Site Recv Date:	2009-05-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	450.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	004718801JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2010-02-05
Trans1 Recv Date:	2010-02-05
Trans2 Recv Date:	2010-02-08
TSD Site Recv Date:	2010-02-12
Part A Recv Date:	Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	10
Manifest Tracking Num:	004718277JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2008-07-01
Trans1 Recv Date:	2008-07-01
Trans2 Recv Date:	2008-07-03
TSD Site Recv Date:	2008-07-03
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	004072147JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

ATLANTIC COLLISION (Continued) **1004762384**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2010-02-05
Trans1 Recv Date:	2010-02-05
Trans2 Recv Date:	2010-02-08
TSD Site Recv Date:	2010-02-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported
Quantity:	1350.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	004718277JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Trans2 State ID:	NJD080631369
Generator Ship Date:	2009-05-27
Trans1 Recv Date:	2009-05-27
Trans2 Recv Date:	2009-05-27
TSD Site Recv Date:	2009-05-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096396
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD980536593
Waste Code:	Not reported

ATLANTIC COLLISION (Continued) **1004762384**

Quantity:	450.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	004718801JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

L39 **MANHOLE 3940** **NY Spills** **S111065356**
ESE **LIVONIA AVE @ VAN SINDEREN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
49 ft. **Site 1 of 7 in cluster L**

Relative:
Lower

Actual:
36 ft.

NY Spills:

Site ID:	451090
Facility Addr2:	Not reported
Facility ID:	1103525
Spill Number:	1103525
Facility Type:	ER
SWIS:	2401
Investigator:	mxferoze
Referred To:	Not reported
Spill Date:	6/29/2011
Reported to Dept:	6/29/2011
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	6/29/2011
Spill Record Last Update:	6/29/2011
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	LIVONIA AVE @ VAN SINDEREN AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT

MANHOLE 3940 (Continued) **S111065356**

Contact Phone: (212) 580-8383
DEC Region: 2
DER Facility ID: 405631
DEC Memo: 6/29/11-HRAHMED-Case assinged to Feroze Mohammod for routine closure.
Remarks: Caller reporting 1 Quart of Dielectric oil in manhole. Clean up pending.

Material:
Site ID: 451090
Operable Unit ID: 1201291
Operable Unit: 01
Material ID: 2197808
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

L40 **MTA NYCT - LIVIONIA AVE STA L-LINE** **RCRA-LQG** **1005905719**
ESE **LIVONIA & VAN SINDEREN AVE** **FINDS** **NYR000108043**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.009 mi. **MANIFEST**
49 ft. **Site 2 of 7 in cluster L**

Relative:
Lower

Actual:
36 ft.

RCRA-LQG:
Date form received by agency: 01/01/2007
Facility name: MTA NYCT - LIVIONIA AVE STA L-LINE
Facility address: LIVONIA & VAN SINDEREN AVE
BROOKLYN, NY 11207
EPA ID: NYR000108043
Mailing address: BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Contact: WILLIAM JEHLE
Contact address: BROADWAY 2ND FLOOR
NEW YORK, NY 10004
Contact country: US
Contact telephone: (646) 252-3500
Contact email: Not reported
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any

MTA NYCT - LIVIONIA AVE STA L-LINE (Continued) **1005905719**

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 2ND FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3500
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 2ND FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3500
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	MTA NYCT - LIVIONIA AVE STA L-LINE
Classification:	Not a generator, verified

Date form received by agency:	07/22/2002

MTA NYCT - LIVIONIA AVE STA L-LINE (Continued) **1005905719**

Facility name: MTA NYCT - LIVIONIA AVE STA L-LINE
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012568122

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

Manifest Code:	NJA5319807
EPA ID:	NYR000108043
Date Shipped:	20060719
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060719
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060720
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	09190621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

MTA NYCT - LIVIONIA AVE STA L-LINE (Continued) **1005905719**

Manifest Code:	000067542WAS
EPA ID:	NYR000108043
Date Shipped:	3/2/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	3/2/20
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	3/2/20
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	300
Unit:	P
Hand Code:	H11

NY MANIFEST:

EPA ID:	NYR000108043
Country:	USA
Mailing Name:	NYCTA LIVONIA AVE STATION
Mailing Contact:	R TAYLOR
Mailing Address:	LIVONIA AVE & VA SINDEREN AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported

MTA NYCT - LIVIONIA AVE STA L-LINE (Continued) **1005905719**

Generator Ship Date:	3/2/2007
Trans1 Recv Date:	3/2/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	3/2/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000108043
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000067542WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	NJA5319807
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	07/19/2006
Trans1 Recv Date:	07/19/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/20/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000108043
Trans1 EPA ID:	S8424
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	03000
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	Not reported

MTA NYCT - LIVIONIA AVE STA L-LINE (Continued) **1005905719**

Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2007-03-02
Trans1 Recv Date:	2007-03-02
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000108043
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000067542WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	NYG3537018
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2002
Trans1 Recv Date:	08/15/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/23/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000108043
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID:	NYP04389
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	02

E41
East
< 1/8
0.010 mi.
53 ft.

ROYAL LACE CORP.
200 LIBERTY AVENUE
BROOKLYN, NY 11207

Site 2 of 5 in cluster E

Relative:
Higher

Actual:
60 ft.

UST **U001842052**
HIST UST **N/A**

UST:

Facility Id:	2-601711
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592733.48048999999
UTM Y:	4503027.7941699997

Affiliation Records:

Site Id:	23673
Affiliation Type:	Mail Contact
Company Name:	ROYAL LACE CORP.
Contact Type:	Not reported
Contact Name:	NATHAN GRAAN
Address1:	200 LIBERTY AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 495-9335
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23673
Affiliation Type:	Owner
Company Name:	AARON GUTTMAN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5323 13TH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 871-2235
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23673
Affiliation Type:	On-Site Operator
Company Name:	ROYAL LACE CORP.
Contact Type:	Not reported
Contact Name:	AARON GUTTMAN
Address1:	Not reported
Address2:	Not reported

ROYAL LACE CORP. (Continued) **U001842052**

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 495-9327
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23673
Affiliation Type: Emergency Contact
Company Name: AARON GUTTMAN
Contact Type: Not reported
Contact Name: MOSES GUTTMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 633-2411
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Equipment Records:

B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
J00 - Dispenser - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Info:
Site ID: 23673

Tank Number: 001
Tank ID: 47551
Tank Status: Closed - In Place
Tank Model: Not reported
Pipe Model: Not reported

ROYAL LACE CORP. (Continued) **U001842052**

Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	1/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	23673
Tank Number:	002
Tank ID:	47552
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	10000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	1/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-601711
SPDES Number:	Not reported
Emergency Contact:	MOSES GUTTMAN
Emergency Telephone:	(718) 633-2411
Operator:	AARON GUTTMAN
Operator Telephone:	(718) 495-9327
Owner Name:	AARON GUTTMAN
Owner Address:	5323 13TH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11219
Owner Telephone:	(718) 871-2235
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	ROYAL LACE CORP.
Mailing Address:	200 LIBERTY AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11207
Mailing Contact:	NATHAN GRAAN
Mailing Telephone:	(718) 495-9335
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	200 LIBERTY AVENUE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER

ROYAL LACE CORP. (Continued) **U001842052**

Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	01/27/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	01/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	10000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported

ROYAL LACE CORP. (Continued) **U001842052**

Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	01/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

M42 **LINEN & BATH CREATIONS, INC.** **UST** **U000405325**
East **491 DUMONT AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.021 mi.
111 ft. **Site 1 of 8 in cluster M**

Relative:
Lower

Actual:
38 ft.

UST:

Facility Id:	2-216658
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592921.70311999996
UTM Y:	4502129.0001699999

Affiliation Records:

Site Id:	8158
Affiliation Type:	Emergency Contact
Company Name:	DUMONT EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	MARK NUSSERI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 524-0804
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8158
Affiliation Type:	On-Site Operator
Company Name:	LINEN & BATH CREATIONS, INC.
Contact Type:	Not reported
Contact Name:	MARK NUSSERI
Address1:	Not reported

LINEN & BATH CREATIONS, INC. (Continued) **U000405325**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 524-0804
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8158
Affiliation Type:	Mail Contact
Company Name:	DUMONT EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	JOSEPH SARDAR
Address1:	350 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 599-4848
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8158
Affiliation Type:	Owner
Company Name:	DUMONT EQUITIES, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	350 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 599-4848
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction

LINEN & BATH CREATIONS, INC. (Continued) **U000405325**

I04 - Overfill - Product Level Gauge (A/G)

Tank Info:

Site ID:	8158
Tank Number:	001
Tank ID:	22401
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	21
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	8/28/1998
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-216658
SPDES Number:	Not reported
Emergency Contact:	THOMAS SAAD
Emergency Telephone:	(516) 561-0403
Operator:	THOMAS SAAD
Operator Telephone:	(718) 342-5800
Owner Name:	VAN SINDEREN REALTY C/O SAUL FRIEDMAN & COMPANY
Owner Address:	6201 15TH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11219
Owner Telephone:	(718) 232-1111
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	UGI, INC.
Mailing Address:	580 5TH AVENUE, ROOM 617
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10036
Mailing Contact:	DAVID WEISZ
Mailing Telephone:	(212) 251-6251
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	491 DUMONT AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	02/04/2000
Expiration Date:	10/15/2002
Renew Flag:	False

LINEN & BATH CREATIONS, INC. (Continued) **U000405325**

Renewal Date:	Not reported
Total Capacity:	5000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	08/28/1998
Next Test Date:	08/28/2003
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	21
Deleted:	False
Updated:	True
Lat/long:	Not reported

M43 **491 DUMONT AVE** **LTANKS** **S103238294**
East **491 DUMONT AVE** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.021 mi.
111 ft. **Site 2 of 8 in cluster M**

Relative:
Lower

Actual:
38 ft.

LTANKS:

Site ID:	311695
Spill No:	9800417
Spill Date:	4/9/1998
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/14/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401

491 DUMONT AVE (Continued) **S103238294**

Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	4/10/1998
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/10/1998
Spill Record Last Update:	8/14/2006
Spiller Name:	VAN SINTEREN REALTY
Spiller Company:	491 DUMONT AVE
Spiller Address:	491 DUMONT AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(516) 321-4670
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	8147
Remarks:	tank tested anf failed. .

Material:

Site ID:	311695
Operable Unit ID:	1060985
Operable Unit:	01
Material ID:	322389
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	311695
Spill Tank Test:	1545762
Tank Number:	1
Tank Size:	5000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

HIST LTANKS:

Region of Spill:	2
Spill Number:	9800417
Spill Date:	04/09/1998

491 DUMONT AVE (Continued) **S103238294**

Spill Time:	12:30
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	TOMASELLO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	04/10/98
Reported to Department Time:	10:19
SWIS:	61
Spiller Contact:	CALLER
Spiller Phone:	(516) 321-4670
Spiller Extention:	Not reported
Spiller Name:	491 DUMONT AVE
Spiller Address:	491 DUMONT AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Cleanup Date:	/ /
Facility Contact:	VAN SINTEREN REALTY
Facility Phone:	(718) 692-0290
Facility Extention:	Not reported
Spill Notifier:	Responsible Party
PBS Number:	2-216658
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	04/10/98
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	04/13/98
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	1
Tank Size:	5000
Test Method:	Horner EZ Check
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	0

491 DUMONT AVE (Continued) **S103238294**

Unkonwn Quantity Spilled:	True
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#2 FUEL OIL
Class Type:	#2 FUEL OIL
Times Material Entry In File:	24464
CAS Number:	Not reported
Last Date:	19941207
DEC Remarks:	Not reported
Spill Cause:	tank tested anf failed.

L44 **MANHOLE #711** **NY Spills** **S103573652**
SE **SNEDIKER & LAVONIA AVES** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
125 ft. **Site 3 of 7 in cluster L**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	302298
Facility Addr2:	Not reported
Facility ID:	9809561
Spill Number:	9809561
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	10/29/1998
Reported to Dept:	10/29/1998
CID:	384
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/31/2002
Remediation Phase:	0
Date Entered In Computer:	10/29/1998
Spill Record Last Update:	10/31/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	244239
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" 10/29/98 - DEC (Saccacio) 1/2 pint of oil unkown in 300 gallons of water. The manhole contained a new transformer and a sump pump that was inoperable. A sample was taken with a 4-6 hour

MANHOLE #711 (Continued) **S103573652**

turnaround. The cleanup was pending the sample results. If the results were not in before the 50 - 499 clean up team becomes available, then they will clean it up as such. Con Ed e2mis #120914: G. LEVERETT #17338 OS UG REPORTS IN TM711 (WORKING ON ISOL FDR. 3B90 NEW TRANSF IN HOLE COULD NOT PRESSURE TEST UNIT.DOSE NOT SEE IT LEAKING VISUALLY) W/S SNEDIKER AVE 65' S/O LIVONIA AVE HE FOUND 1/2 PINT OIL ON 300 GAL OF WATER FROM UNKNOWN SOURCE. HOLE IS CONTAINED (NO SUMP PUMP RUNNING) AND NO SEWERS OR WATERWAYS AFFECTED. LIQUID SAMPLE TAKEN (4-6 HRS PRIORITY) AND E.S.TAG #16177 WAS PLACED. CIG DEVOTI NOTIFIED 1815 HRS UPDATE 30-OCT-1998 01:05 CHEM LAB RESULTS RECEIVED SEQUENCE #98-11859 < 1 PPM 1931HRS 11/12/98 S.ROSENKING REPORTS CLEANUP COMPLETED WITH SLIX & STOP TAG #16177 REMOVED.

Remarks: CON EDISON #120914 CLEAN UP IS PENDING LAB RESULTS.

Material:

Site ID:	302298
Operable Unit ID:	1070642
Operable Unit:	01
Material ID:	313467
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9809561
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/29/1998 17:20
Reported to Dept Date/Time:	10/29/98 18:21
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported

MANHOLE #711 (Continued) **S103573652**

Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/29/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/02/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 10/29/98 - DEC Saccacio) 1/2 pint of oil unkown in 300 gallons of water. The manhole contained a new transformer and a sump pump that was inoperable. A sample was taken with a 4-6 hour turnaround. The cleanup was pending the sample results. Ifthe results were not in before the 50 - 499 clean up team becomes available, then they will clean it up as such.
Remark: CON EDISON 120914 CLEAN UP IS PENDING LAB RESULTS.

L45 **TM #711** **NY Spills** **S103574396**
SE **SNEVIKER AV & LAVONIA AV** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
125 ft. **Site 4 of 7 in cluster L**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	229122
Facility Addr2:	Not reported
Facility ID:	9810369
Spill Number:	9810369
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	11/17/1998
Reported to Dept:	11/17/1998
CID:	351
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/31/2002
Remediation Phase:	0
Date Entered In Computer:	11/17/1998
Spill Record Last Update:	10/31/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	STEVE ROMERO
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	188918
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"
Remarks:	4 OUNCES OF UNKNOWN OIL ON 50 GALLONS OF WATER - SPILL CLEAN UP PENDING TEST RESULTS - CON ED SPILL #121308

Material:

Site ID:	229122
Operable Unit ID:	1067643
Operable Unit:	01
Material ID:	314241
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

TM #711 (Continued) **S103574396**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9810369
Investigator: ENGELHARDT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/17/1998 09:45
Reported to Dept Date/Time: 11/17/98 10:52
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Contact: STEVE ROMERO
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/17/98
Date Spill Entered In Computer Data File: Not reported

TM #711 (Continued) **S103574396**

Update Date: 11/19/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: 4 OUNCES OF UNKNOWN OIL ON 50 GALLONS OF WATER - SPILL CLEAN UP PENDING TEST RESULTS - CON ED SPILL 121308

M46 **ADDICTION RESEARCH AND TREATMENT CORPORA** **AST** **U003396742**
East **494 DUMONT AVENUE** **HIST AST** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.024 mi.
125 ft. **Site 3 of 8 in cluster M**

Relative:
Lower

Actual:
38 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-602601
Program Type: PBS
UTM X: 592932.69325999997
UTM Y: 4502131.1064600004
Expiration Date: 2016/02/05

Affiliation Records:
Site Id: 24558
Affiliation Type: Owner
Company Name: ADDICTION RESEARCH AND TREATMENT CORPORATION
Contact Type: SR. VE. RESOURCES & CORPORATE ADMIN.
Contact Name: DEBORAH A. WRIGHT, M. ED
Address1: 22 CHAPEL STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 260-2933
Phone Ext: Not reported
Email: DWRIGHT@ARTCNY.ORG
Fax Number: Not reported

ADDICTION RESEARCH AND TREATMENT CORPORA (Continued) **U003396742**

Modified By:	NRLOMBAR
Date Last Modified:	5/3/2011
Site Id:	24558
Affiliation Type:	Emergency Contact
Company Name:	ADDICTION RESEARCH AND TREATMENT CORPORATION
Contact Type:	Not reported
Contact Name:	ARTC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 260-2900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/3/2011
Site Id:	24558
Affiliation Type:	Mail Contact
Company Name:	ADDICTION RESEARCH AND TREATMENT CORPORATION
Contact Type:	SR. VE. RESOURCES & CORPORATE ADMIN.
Contact Name:	DEBORAH A. WRIGHT, M. ED
Address1:	22 CHAPEL STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 260-2933
Phone Ext:	Not reported
Email:	DWRIGHT@ARTCNY.ORG
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/3/2011
Site Id:	24558
Affiliation Type:	On-Site Operator
Company Name:	ADDICTION RESEARCH AND TREATMENT CORPORATION
Contact Type:	Not reported
Contact Name:	LAUDRICK DALZELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 345-0808
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	12/20/2010

ADDICTION RESEARCH AND TREATMENT CORPORA (Continued) **U003396742**

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Info:

Tank Number:	001
Tank Id:	50688
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/1930
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BVCAMPBE
Last Modified:	12/20/2010

HIST AST:

PBS Number:	2-602601
SWIS Code:	6101
Operator:	STANLEY KENSMIL
Facility Phone:	(718) 345-0808
Facility Addr2:	Not reported
Facility Type:	OTHER
Emergency:	ARTC
Emergency Tel:	(718) 260-2900
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	ADDICTION RESEARCH AND TREATMENT CORPORATION
Owner Address:	22 CHAPEL STREET
Owner City,St,Zip:	BROOKLYN, NY 11201
Federal ID:	Not reported
Owner Tel:	(718) 260-2900
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	ALTON S. GIBSON, JR.
Mailing Name:	ADDICTION RESEARCH AND TREATMENT CORPORATION
Mailing Address:	22 CHAPEL STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11201
Mailing Telephone:	(718) 260-2900

ADDICTION RESEARCH AND TREATMENT CORPORA (Continued) **U003396742**

Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	06/01/2001
Expiration:	02/05/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	11
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	08
Leak Detection:	00
Overfill Protection:	44
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

N47 1 JUINUS ST **NY Spills S102446664**
WSW 1 JUINUS ST **NY Hist Spills N/A**
< 1/8 BROOKLYN, NY
0.025 mi.
133 ft. Site 1 of 7 in cluster N

Relative: Higher

Actual: 63 ft.

NY Spills:

Site ID:	159949
Facility Addr2:	Not reported
Facility ID:	9610713
Spill Number:	9610713
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	11/26/1996
Reported to Dept:	11/27/1996
CID:	351
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/19/1998
Remediation Phase:	0
Date Entered In Computer:	11/27/1996
Spill Record Last Update:	3/17/2003
Spiller Name:	PAT MCHUGH
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	PAT MCHUGH
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	135108
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"
Remarks:	a network protector set on fire possibly causing a release - samples are currently being taken

Material:

Site ID:	159949
Operable Unit ID:	1042096
Operable Unit:	01
Material ID:	342925
Material Code:	0026A
Material Name:	ASBESTOS
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

1 JUINUS ST (Continued) **S102446664**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9610713
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/26/1996 07:00
Reported to Dept Date/Time: 11/27/96 11:11
SWIS: 61
Spiller Name: CON ED
Spiller Contact: PAT MCHUGH
Spiller Phone: (212) 580-6764
Spiller Contact: PAT MCHUGH
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/19/98
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/27/96
Date Spill Entered In Computer Data File: Not reported

1 JUINUS ST (Continued) **S102446664**

Update Date: 10/19/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Nonpetroleum/Nonhazardous
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: ASBESTOS
Class Type: ASBESTOS
Times Material Entry In File: 0
CAS Number: 01332214
Last Date: Not reported
DEC Remarks: Not reported
Remark: a network protector set on fire possibly causing a release - samples are currently being taken

---

N48 **NABS, INC.** **HIST AST** **S107783827**
WSW **1 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.025 mi.
133 ft. **Site 2 of 7 in cluster N**

Relative:
Higher

Actual:
63 ft.

HIST AST:
PBS Number: 2-604881
SWIS Code: 6101
Operator: FRANK IANELLA
Facility Phone: (718) 498-1144
Facility Addr2: Not reported
Facility Type: Not reported
Emergency: FRANK IANELLA
Emergency Tel: (718) 832-2337
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: J&A REALTY CO.
Owner Address: 41 WORTH STREET
Owner City,St,Zip: NEW YORK, NY 10013
Federal ID: Not reported
Owner Tel: (212) 966-3310
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: FRANK IANELLA
Mailing Name: NABS, INC.
Mailing Address: 1 JUNIUS STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11212
Mailing Telephone: (718) 498-1144

NABS, INC. (Continued) **S107783827**

Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	12/15/2000
Expiration:	12/05/2005
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	5000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	5000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	0
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	0
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	46
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

N49 **JUNIUS DEVELOPMENT LLC** **AST** **A100301202**
WSW **1-25 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.025 mi.
133 ft. **Site 3 of 7 in cluster N**

Relative:
Higher

Actual:
63 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-604881
Program Type:	PBS
UTM X:	592605.65067
UTM Y:	4503200.1061000004
Expiration Date:	N/A

Affiliation Records:

Site Id:	26750
Affiliation Type:	Emergency Contact
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 335-9590
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26750
Affiliation Type:	Owner
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	325 E. 104TH ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10029
Country Code:	001
Phone:	(212) 996-6456
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26750
Affiliation Type:	Mail Contact
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	325 EAST 104TH STREET
Address2:	Not reported

JUNIUS DEVELOPMENT LLC (Continued) **A100301202**

City:	NEW YORK
State:	NY
Zip Code:	10029
Country Code:	001
Phone:	(212) 996-6456
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	26750
Affiliation Type:	On-Site Operator
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 335-9590
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

G99 - Tank Secondary Containment - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
B99 - Tank External Protection - Other
J01 - Dispenser - Submersible
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground

Tank Info:

Tank Number:	001
Tank Id:	59055
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	8/16/2002
Register:	True
Modified By:	TRANSLAT

JUNIUS DEVELOPMENT LLC (Continued) **A100301202**

Last Modified: 3/4/2004

N50 **FACTORY** **LTANKS** **S105054906**
WSW **1 JUNIUS ST** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.025 mi.
133 ft. **Site 4 of 7 in cluster N**

Relative:
Higher

Actual:
63 ft.

LTANKS:

Site ID:	159948
Spill No:	0101889
Spill Date:	5/17/2001
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/14/2003
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	5/18/2001
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/18/2001
Spill Record Last Update:	8/14/2003
Spiller Name:	SAME
Spiller Company:	FACTORY
Spiller Address:	1 JUNIUS ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	BILL SILVERI
Spiller Phone:	(212) 563-3933
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135108
Remarks:	obvious vent pipe leak, minimally.

Material:

Site ID:	159948
Operable Unit ID:	838763
Operable Unit:	01
Material ID:	537584
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No

FACTORY (Continued) **S105054906**

Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 159948
Spill Tank Test: 1526308
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

HIST LTANKS:
Region of Spill: 2
Spill Number: 0101889
Spill Date: 05/17/2001
Spill Time: 10:00
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SANGESLAND
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 05/18/01
Reported to Department Time: 13:44
SWIS: 61
Spiller Contact: BILL SILVERI
Spiller Phone: (212) 563-3933
Spiller Extention: Not reported
Spiller Name: FACTORY
Spiller Address: 1 JUNIUS ST
Spiller City,St,Zip: BROOKLYN, NY
Spiller Cleanup Date: / /
Facility Contact: SAME
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended

FACTORY (Continued) **S105054906**

Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 05/18/01
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 05/18/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 1
Tank Size: 5000
Test Method: Horner EZ Check
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Talk Test Failures only pass or fail

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: obvious vent pipe leak, minimally.

N51 **CON ED V 2312** **RCRA-NonGen** **1007206098**
West **1 JUNIS ST** **MANIFEST** **NYP004003547**
< 1/8 **BROOKLYN, NY 11201**
0.025 mi.
134 ft. **Site 5 of 7 in cluster N**

Relative:
Higher

Actual:
64 ft.

RCRA-NonGen:
Date form received by agency: 02/28/1998
Facility name: CON ED V 2312
Facility address: 1 JUNIS ST
BROOKLYN, NY 112010000
EPA ID: NYP004003547
Mailing address: CON EDISON INC
4 IRVING PL ROOM 300
NEW YORK, NY 100030000
Contact: ANTHONY DRUMMINGS
Contact address: CON EDISON INC
NEW YORK, NY 100030000
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CON ED V 2312 (Continued) **1007206098**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 02/27/1998
- Facility name: CON ED V 2312
- Classification: Not a generator, verified

- Date form received by agency: 02/26/1998
- Facility name: CON ED V 2312
- Classification: Large Quantity Generator

- Violation Status: No violations found

NY MANIFEST:
- EPA ID: NYP004003547
- Country: USA
- Mailing Name: CON ED V 2312
- Mailing Contact: Not reported
- Mailing Address: Not reported
- Mailing Address 2: Not reported
- Mailing City: Not reported
- Mailing State: Not reported
- Mailing Zip: Not reported
- Mailing Zip4: Not reported
- Mailing Country: Not reported
- Mailing Phone: Not reported

NY MANIFEST:
No Manifest Records Available

N52 **VAULT # 2483** **NY Spills** **S105236535**
West **JUNIUS ST/NEW YORK AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.025 mi.
134 ft. **Site 6 of 7 in cluster N**

Relative:
Higher

Actual:
64 ft.

NY Spills:
- Site ID: 165527
- Facility Addr2: Not reported
- Facility ID: 0109010
- Spill Number: 0109010
- Facility Type: ER

VAULT # 2483 (Continued) **S105236535**

SWIS:	2401
Investigator:	AERODRIG
Referred To:	Not reported
Spill Date:	12/10/2001
Reported to Dept:	12/10/2001
CID:	233
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/19/2002
Remediation Phase:	0
Date Entered In Computer:	12/10/2001
Spill Record Last Update:	2/19/2002
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	UNK
Spiller City,St,Zip:	UNK, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	139516
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ"
Remarks:	con ed # 140536 spil on 3 gallons of water confined in vault now sewers or waterways no smoke or fire transformer in vault but tested neg. for any problems tests on oil show 899 ppm pcb

Material:

Site ID:	165527
Operable Unit ID:	846401
Operable Unit:	01
Material ID:	530215
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported

VAULT # 2483 (Continued) **S105236535**

Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0109010
Investigator: RODRIGUEZ
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 12/10/2001 10:10
Reported to Dept Date/Time: 12/10/01 21:13
SWIS: 61
Spiller Name: UNK
Spiller Contact: Not reported
Spiller Phone: (000) 000-0000
Spiller Address: UNK
Spiller City,St,Zip: UNK
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/10/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/14/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

VAULT # 2483 (Continued) **S105236535**

Material:
- Material Class Type: Petroleum
- Quantity Spilled: 0
- Unkonwn Quantity Spilled: True
- Units: Gallons
- Quantity Recovered: 0
- Unkonwn Quantity Recovered: False
- Material: UNKNOWN PETROLEUM
- Class Type: UNKNOWN PETROLEUM
- Times Material Entry In File: 16414
- CAS Number: Not reported
- Last Date: 19940929
- DEC Remarks: Not reported
- Remark: con ed 140536 spil on 3 gallons of water confined in vault now sewers or waterways no smoke or fire transformer in vault but tested neg. for any problems tests on oil show 899 ppm pcb

---

C53 **444 BLAKE AVENUE** **AST** **A100183363**
WSW **444 BLAKE AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.029 mi.
154 ft. **Site 5 of 6 in cluster C**

Relative:
Lower

Actual:
38 ft.

AST:
- Region: STATE
- DEC Region: 2
- Site Status: Active
- Facility Id: 2-606784
- Program Type: PBS
- UTM X: 592756.17587000004
- UTM Y: 4502273.6720000003
- Expiration Date: 2006/08/22

Affiliation Records:
- Site Id: 28641
- Affiliation Type: On-Site Operator
- Company Name: 444 BLAKE AVENUE
- Contact Type: Not reported
- Contact Name: ASST. COMMISSIONER/DPM
- Address1: Not reported
- Address2: Not reported
- City: Not reported
- State: NN
- Zip Code: Not reported
- Country Code: 001
- Phone: (212) 863-7087
- Phone Ext: Not reported
- Email: Not reported
- Fax Number: Not reported
- Modified By: TRANSLAT
- Date Last Modified: 3/4/2004

- Site Id: 28641
- Affiliation Type: Emergency Contact
- Company Name: NYC/HPD/DPM
- Contact Type: Not reported
- Contact Name: ASST. COMMISSIONER/DPM
- Address1: Not reported

444 BLAKE AVENUE (Continued) **A100183363**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	8/19/2004

Site Id:	28641
Affiliation Type:	Mail Contact
Company Name:	NYC/HPD/DPM
Contact Type:	Not reported
Contact Name:	ASST. COMMISSIONER/DPM
Address1:	100 GOLD STREET
Address2:	#6Z1
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	7/11/2006

Site Id:	28641
Affiliation Type:	Owner
Company Name:	NYC/HPD/DPM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	100 GOLD ST., #6Z1
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	8/19/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

444 BLAKE AVENUE (Continued) **A100183363**

C03 - Pipe Location - Aboveground/Underground Combination

Tank Info:

Tank Number:	001
Tank Id:	61876
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

C54 **444 BLAKE AVENUE** **HIST AST** **S107785322**
WSW **444 BLAKE AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.029 mi.
154 ft. **Site 6 of 6 in cluster C**

Relative:
Lower

Actual:
38 ft.

HIST AST:

PBS Number:	2-606784
SWIS Code:	6101
Operator:	ASST. COMMISSIONER/DPM
Facility Phone:	(212) 863-7087
Facility Addr2:	Not reported
Facility Type:	APARTMENT BUILDING
Emergency:	ASST. COMMISSIONER/DPM
Emergency Tel:	(212) 863-7087
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	NYC/HPD/DPM
Owner Address:	100 GOLD ST., #6Z1
Owner City,St,Zip:	NEW YORK, NY 10038
Federal ID:	Not reported
Owner Tel:	(212) 863-7087
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	ASST. COMMISSIONER/DPM
Mailing Name:	NYC/HPD/DPM
Mailing Address:	100 GOLD STREET
Mailing Address 2:	#6Z1
Mailing City,St,Zip:	NEW YORK, NY 10038
Mailing Telephone:	(212) 863-7087
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False

444 BLAKE AVENUE (Continued) **S107785322**

Certification Date:	08/24/2001
Expiration:	08/22/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2100
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2100
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	1
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	0
Tank Containment:	Not reported
Leak Detection:	0
Overfill Protection:	6
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

O55 **2490 ATLANTIC AVENUE** **NY Spills** **S103575925**
NNW **2490 ATLANTIC AVENUE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.030 mi.
157 ft. **Site 1 of 7 in cluster O**

Relative:
Higher

Actual:
64 ft.

NY Spills:

Site ID:	263377
Facility Addr2:	Not reported
Facility ID:	9812107
Spill Number:	9812107
Facility Type:	ER
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported

2490 ATLANTIC AVENUE (Continued) **S103575925**

Spill Date:	12/29/1998
Reported to Dept:	12/29/1998
CID:	204
Spill Cause:	Housekeeping
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	5/17/1999
Remediation Phase:	0
Date Entered In Computer:	12/29/1998
Spill Record Last Update:	5/17/1999
Spiller Name:	JOE TARNOWSKI
Spiller Company:	PEREY MANUAFACTURING CO.
Spiller Address:	45 CHURCH STREET
Spiller City,St,Zip:	STAMFORD, CT
Spiller Company:	001
Contact Name:	ED HENDRICKSON
Contact Phone:	(203) 961-8444
DEC Region:	2
DER Facility ID:	214707
DEC Memo:	Not reported
Remarks:	CONTAMINATED SOIL - NO PRODUCT OR ODORS

Material:

Site ID:	263377
Operable Unit ID:	1069366
Operable Unit:	01
Material ID:	312390
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

2490 ATLANTIC AVENUE (Continued) **S103575925**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9812107
Investigator:	SIGONA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	12/29/1998 09:47
Reported to Dept Date/Time:	12/29/98 09:47
SWIS:	61
Spiller Name:	PEREY MANUAFACTURING CO.
Spiller Contact:	JOE TARNOWSKI
Spiller Phone:	(203) 961-8444
Spiller Contact:	ED HENDRICKSON
Spiller Phone:	(203) 961-8444
Spiller Address:	45 CHURCH STREET
Spiller City,St,Zip:	STAMFORD, CT
Spill Cause:	Housekeeping
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Local Agency
PBS Number:	2-603884
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	05/17/99
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	12/29/98
Date Spill Entered In Computer Data File:	Not reported
Update Date:	05/17/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	True
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	True

2490 ATLANTIC AVENUE (Continued) **S103575925**

Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: DEC Sigona) conducted site inspections, supervised investigation. The site had some restrictions which prohibited borings next to tank. Deeper boring on outside of the building did not reveal any sigificant petroleum contamination. Letter from DEC Sigona) to Perey Turnstiles dated May 17, 1999 closed the spill case.
Remark: CONTAMINATED SOIL - NO PRODUCT OR ODORS

P56 **NYCT - LIVONIA PLAYGROUND** **RCRA-CESQG** **1004762586**
WSW **LIVONIA AVE BETW JUNIUS ST** **FINDS** **NYR000098442**
< 1/8 **BROOKLYN, NY 11212** **MANIFEST**
0.031 mi. **MANIFEST**
164 ft. **Site 1 of 7 in cluster P**

Relative:
Lower

Actual:
35 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: NYCT - LIVONIA PLAYGROUND
Facility address: LIVONIA AVE BETW JUNIUS ST
& POWELL AVE
BROOKLYN, NY 11212
EPA ID: NYR000098442
Mailing address: JAY ST ROOM 819
BROOKLYN, NY 11201
Contact: JAMES CRANDALL
Contact address: JAY ST ROOM 819
BROOKLYN, NY 11201
Contact country: US
Contact telephone: (718) 243-4581
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK CITY TRANSIT
Owner/operator address: 370 JAY ST ROOM 819
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 243-4581
Legal status: Other

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY TRANSIT
Owner/operator address: 370 JAY ST ROOM 819
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 243-4581
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCT - LIVONIA PLAYGROUND
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/11/2001
Facility name: NYCT - LIVONIA PLAYGROUND
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110007905222

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Manifest Code:	NJA5077906
EPA ID:	NYR000098442
Date Shipped:	20040720
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040720
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040720
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08060425
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5077683
EPA ID:	NYR000098442
Date Shipped:	20040330
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040330
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040330
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04280421
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5077727
EPA ID:	NYR000098442
Date Shipped:	20040407
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040407
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040407
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	05100422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Manifest Code:	NJA5314300
EPA ID:	NYR000098442
Date Shipped:	20060419
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060419
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060419
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	05310621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5212754
EPA ID:	NYR000098442
Date Shipped:	20050420
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050420
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050420
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	06150521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5081932
EPA ID:	NYR000098442
Date Shipped:	20050902
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050902
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050902
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	10170521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

NY MANIFEST:

EPA ID:	NYR000098442
Country:	USA
Mailing Name:	NYCTA
Mailing Contact:	BERNARD JENS
Mailing Address:	370 JAY STREET RM 819
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	781-243-4227

Document ID:	NJA4110474
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/27/2003
Trans1 Recv Date:	10/27/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/27/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	S5811
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	03

Document ID:	NJA4118202
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/20/2003
Trans1 Recv Date:	05/20/2003
Trans2 Recv Date:	05/21/2003
TSD Site Recv Date:	05/22/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	H10376
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00080
Units:	P - Pounds
Number of Containers:	001

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 03

Document ID: NJA4071288
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/17/2003
Trans1 Recv Date: 11/17/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/17/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098442
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSDF ID: S5811
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 03

Document ID: NJA5081932
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/02/2005
Trans1 Recv Date: 09/02/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/02/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098442
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA5212754
Manifest Status: Not reported
Trans1 State ID: NJ0000027193

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Trans2 State ID:	Not reported
Generator Ship Date:	04/20/2005
Trans1 Recv Date:	04/20/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/20/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	Not reported

Document ID:	NJA5077683
Manifest Status:	Not reported
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2004
Trans1 Recv Date:	03/30/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	04

Document ID:	NJA5077906
Manifest Status:	Not reported
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2004
Trans1 Recv Date:	07/20/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/20/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	NJ0000027193

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Trans2 EPA ID: Not reported
TSDF ID: NJD002200
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00010
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 04

Document ID: NJA5077727
Manifest Status: Not reported
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 04/07/2004
Trans1 Recv Date: 04/07/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/07/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098442
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 04

Document ID: NJA5212754
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/20/2005
Trans1 Recv Date: 04/20/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/20/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098442
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Year:	2005
Document ID:	NJA5081932
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/2005
Trans1 Recv Date:	09/02/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/02/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2005

Document ID:	06
Manifest Status:	NJA5314300
Trans1 State ID:	NYR000098442
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJ0000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	5
Handling Method:	G
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

NYCT - LIVONIA PLAYGROUND (Continued) **1004762586**

Document ID:	NJA5314300
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2006
Trans1 Recv Date:	04/19/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA4106459
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2002
Trans1 Recv Date:	04/16/2002
Trans2 Recv Date:	04/22/2002
TSD Site Recv Date:	04/22/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098442
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	H10376
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	02

P57 **MTA NYCT - JUNIUS ST STATION - 3 LINE** **RCRA-SQG** **1012186250**
WSW **LIVONIA AVE & JUNIUS ST** **NYR000161117**
< 1/8 **BROOKLYN, NY 11212**
0.031 mi.
164 ft. **Site 2 of 7 in cluster P**

Relative:
Lower

Actual:
35 ft.

RCRA-SQG:

Date form received by agency:	10/30/2008
Facility name:	MTA NYCT - JUNIUS ST STATION - 3 LINE
Facility address:	LIVONIA AVE & JUNIUS ST BROOKLYN, NY 11212

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **1012186250**

EPA ID:	NYR000161117
Mailing address:	BROADWAY 5TH FLOOR NEW YORK, NY 10004
Contact:	LUMINITA MARINESCU
Contact address:	BROADWAY 5TH FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3506
Contact email:	LUMINITA.MARINESCU@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY 5TH FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	MTA NYCT
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **1012186250**

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

P58 **MTA NYCT - JUNIUS ST STATION - 3 LINE** **MANIFEST** **S110047114**
WSW **LIVONIA AVE & JUNIUS ST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.031 mi.
164 ft. **Site 3 of 7 in cluster P**

Relative:
Lower

Actual:
35 ft.

NY MANIFEST:
EPA ID: NYR000161117
Country: USA
Mailing Name: MTA NYCT - JUNIUS ST STATION - 3 LINE
Mailing Contact: NYCT-OSS (CPM) CONT# R-50545
Mailing Address: 2 BROADWAY ROOM 427.64
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 646-252-5777

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 2009-10-02
Trans1 Recv Date: 2009-10-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-10-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000161117
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: MID980991566
Waste Code: Not reported
Quantity: 300.0
Units: P - Pounds
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 000195138WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **S110047114**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000198411WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-07-28
Trans1 Recv Date:	2009-07-28
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-07-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	600.0

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **S110047114**

Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000198536WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-05-19
Trans1 Recv Date:	2009-05-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-05-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000201282WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **S110047114**

Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-05-19
Trans1 Recv Date:	2009-05-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-05-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000201282WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-07-28
Trans1 Recv Date:	2009-07-28
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-07-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09

MTA NYCT - JUNIUS ST STATION - 3 LINE (Continued) **S110047114**

Manifest Tracking Num:	000198536WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000161117
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	1200.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000198411WAS
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

P59
WSW
< 1/8
0.031 mi.
164 ft.

MTA NYCT - JUNIUS ST STATION - 3 LINE
LIVONIA AVE & JUNIUS ST
BROOKLYN, NY 11212

Site 4 of 7 in cluster P

FINDS **1012107920**
N/A

Relative:
Lower

Actual:
35 ft.

FINDS:

Registry ID: 110038899298

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

P60
WSW
< 1/8
0.035 mi.
185 ft.

SOLID BOX CORP.
454 LIVONIA AVE.
BROOKLYN, NY 11207

Site 5 of 7 in cluster P

UST **U004118737**
AST **N/A**

Relative:
Lower

Actual:
34 ft.

UST:

Facility Id:	2-610749
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2013/05/12
UTM X:	592948.72438999999
UTM Y:	4502011.9492899999

Affiliation Records:

Site Id:	392300
Affiliation Type:	Owner
Company Name:	JEFFREY SCHATZ
Contact Type:	OWNER
Contact Name:	JAY SOLOMON
Address1:	400 DAWSON LANE
Address2:	Not reported
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(347) 992-2517
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	On-Site Operator
Company Name:	SOLID BOX CORP.
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	Not reported

SOLID BOX CORP. (Continued) **U004118737**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-1500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	Emergency Contact
Company Name:	JEFFREY SCHATZ
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 992-2343
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	Mail Contact
Company Name:	SOLID BOX CORP.
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	454 LIVONIA AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 495-1500
Phone Ext:	Not reported
Email:	SOLIDBOX@RCN.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Equipment Records:

L00 - Piping Leak Detection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

SOLID BOX CORP. (Continued) **U004118737**

E00 - Piping Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

Tank Info:

Site ID:	392300
Tank Number:	001
Tank ID:	221151
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/1975
Capacity Gallons:	4000
Tightness Test Method:	21
Next Test Date:	1/21/2011
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	1/21/2006
Register:	True
Modified By:	dxliving
Last Modified:	9/12/2008

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610749
Program Type:	PBS
UTM X:	592948.72438999999
UTM Y:	4502011.9492899999
Expiration Date:	2013/05/12

Affiliation Records:

Site Id:	392300
Affiliation Type:	Owner
Company Name:	JEFFREY SCHATZ
Contact Type:	OWNER
Contact Name:	JAY SOLOMON
Address1:	400 DAWSON LANE
Address2:	Not reported
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(347) 992-2517

SOLID BOX CORP. (Continued) **U004118737**

Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	On-Site Operator
Company Name:	SOLID BOX CORP.
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-1500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	Emergency Contact
Company Name:	JEFFREY SCHATZ
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 992-2343
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	1/15/2008

Site Id:	392300
Affiliation Type:	Mail Contact
Company Name:	SOLID BOX CORP.
Contact Type:	Not reported
Contact Name:	JAY SOLOMON
Address1:	454 LIVONIA AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 495-1500
Phone Ext:	Not reported
Email:	SOLIDBOX@RCN.COM
Fax Number:	Not reported

SOLID BOX CORP. (Continued) **U004118737**

Modified By: dxliving
Date Last Modified: 1/15/2008

Equipment Records:

L00 - Piping Leak Detection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

Tank Info:

Tank Number:	002
Tank Id:	221152
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/1975
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	dxliving
Last Modified:	9/12/2008

Q61 **DRUM RUN** **NY Spills** **S109582420**
East **234 BELMONT AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.041 mi.
217 ft. **Site 1 of 3 in cluster Q**

Relative:
Lower

Actual:
38 ft.

NY Spills:

Site ID:	413207
Facility Addr2:	BETWEEN VANSINDREN AVE AND SNEDECKER AV
Facility ID:	0901237
Spill Number:	0901237
Facility Type:	ER

DRUM RUN (Continued) **S109582420**

SWIS:	2401
Investigator:	HRAHMED
Referred To:	Not reported
Spill Date:	4/30/2009
Reported to Dept:	4/30/2009
CID:	Not reported
Spill Cause:	Abandoned Drums
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/27/2009
Remediation Phase:	0
Date Entered In Computer:	4/30/2009
Spill Record Last Update:	5/27/2009
Spiller Name:	ANDREW KELLY
Spiller Company:	UNKNOWN
Spiller Address:	234 BELMONT AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ANDREW KELLY
Contact Phone:	(718) 595-4761
DEC Region:	2
DER Facility ID:	362357
DEC Memo:	add to next drum run 05/27/09-HRAHMED-Duplicate spill of spill#0901252. No drum found in this location during drum run on 05/07/09. This case is closed.
Remarks:	3 55 Gallon Drums discovered at the above location.

Material:

Site ID:	413207
Operable Unit ID:	1169654
Operable Unit:	01
Material ID:	2161315
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	170
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported

DRUM RUN (Continued) **S109582420**

Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported
Site ID:	413222
Facility Addr2:	Not reported
Facility ID:	0901252
Spill Number:	0901252
Facility Type:	ER
SWIS:	2401
Investigator:	HRAHMED
Referred To:	Not reported
Spill Date:	4/30/2009
Reported to Dept:	4/30/2009
CID:	Not reported
Spill Cause:	Abandoned Drums
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	5/15/2009
Remediation Phase:	0
Date Entered In Computer:	4/30/2009
Spill Record Last Update:	6/2/2009
Spiller Name:	CHRIS KENCROT
Spiller Company:	UNKNOWN
Spiller Address:	234 BELMONT AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	362371
DEC Memo:	05/15/09-No drum found during drum run on 05/07/09. See EMIS reports in EDocs file - closed - end This case is closed.
Remarks:	Some of the fluid from the drums has leaked into one of Con Ed's manholes. Clean up is pending until samples are obtained.

Material:

Site ID:	413222
Operable Unit ID:	1169670
Operable Unit:	01
Material ID:	2161331
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	165
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported

DRUM RUN (Continued) **S109582420**

Oxygenate:	False
Site ID:	413222
Operable Unit ID:	1169670
Operable Unit:	01
Material ID:	2161334
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

Q62 **234 BELMONT AVE** **ERNS** **2008904208**
East **234 BELMONT AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.041 mi.
217 ft. **Site 2 of 3 in cluster Q**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
38 ft.

Q63 **234 BELMONT AVE** **ERNS** **2009904208**
East **234 BELMONT AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.041 mi.
217 ft. **Site 3 of 3 in cluster Q**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
38 ft.

R64 **NYC-HA SETH LOW HOUSES** **RCRA-NonGen** **1000550124**
WSW **230 POWELL AVENUE** **FINDS** **NYD986870962**
< 1/8 **BROOKLYN, NY 11201**
0.042 mi.
224 ft. **Site 1 of 5 in cluster R**

Relative:
Higher

Actual:
41 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCHA - SETH LOW
Facility address:	230 POWELL ST BROOKLYN, NY 11212
EPA ID:	NYD986870962
Mailing address:	BROADWAY NEW YORK, NY 10007
Contact:	Not reported
Contact address:	BROADWAY NEW YORK, NY 10007
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYC HOUSING AUTHORITY
Owner/operator address:	250 BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	(212) 306-3229
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYC HOUSING AUTHORITY
Owner/operator address:	250 BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	(212) 306-3229
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

NYC-HA SETH LOW HOUSES (Continued) **1000550124**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - SETH LOW
Classification: Not a generator, verified

Date form received by agency: 04/03/1998
Facility name: NYCHA - SETH LOW
Classification: Not a generator, verified

Date form received by agency: 02/27/1998
Facility name: NYCHA - SETH LOW
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001570755

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

S65 **MANHOLE #5261** **NY Spills** **S103828843**
East **62 SNEDIKER AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.045 mi.
238 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
57 ft.

NY Spills:

Site ID:	80394
Facility Addr2:	Not reported
Facility ID:	9814644
Spill Number:	9814644
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	3/9/1999
Reported to Dept:	3/9/1999
CID:	312
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/5/2002
Remediation Phase:	0
Date Entered In Computer:	3/9/1999
Spill Record Last Update:	6/5/2002
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	74503
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" Con Ed e2mis #124519: 3/9/99-11:00HRS-K. MASON-49738-SPLICER I&A-IN FIELD DOING SERVICE CUT FOUND APPROX 2 QTS UNKNOWN OIL ON 200 GALLONS WATER IN MH 5261-F/O 62 SNEDIKER AVE.-CONTAINED-NO SEWERS OR WATERWAYS AFFECT-DID NOT SEE JOINT REGULATOR IN STRUCTURE-COULD NOT SEE IF THERE IS A SUMP-NO SEWER CONNECTIONS-MH IN STREET IN FRONT OF DRIVEWAY-TOOK A LIQUID SAMPLE WITH A 4-6 HOUR PRIORITY AND PLACED ENV TAG#22069. CLEANUP PENDING LAB RESULTS NOTIFIED CIG S. CRIBBIN @ 12:00HRS. 3/09/99 21:55 HRS -- LAB SEQ #99-02487, <1.0 PPM PCB LIPORI BKLYN FLUSH REPORTS CLEANUP COMPLETED WITH SLIX & STOP TAG #22069 REMOVED @ 0100 HRA 3/11/99.
Remarks:	2 QTS OF UNK OIL ON 200 GAL OF WATER - CONTAINED - CASE #123519 SAMPLE TAKEN - CLEAN UP IS PENDING

Material:

Site ID:	80394
Operable Unit ID:	1075677
Operable Unit:	01

MANHOLE #5261 (Continued) **S103828843**

Material ID:	311325
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9814644
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/09/1999 11:00
Reported to Dept Date/Time:	03/09/99 12:05
SWIS:	61
Spiller Name:	CON EDISON
Spiller Contact:	Not reported
Spiller Phone:	( ) -
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003-
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False

MANHOLE #5261 (Continued) **S103828843**

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/09/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/12/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: 2 QTS OF UNK OIL ON 200 GAL OF WATER - CONTAINED - CASE 123519 SAMPLE TAKEN - CLEAN UP IS PENDING

S66 **EAST NEW SERVICE CORPORATION** **UST U000417953**
East **36 SNEDIKER AVENUE** **HIST UST N/A**
< 1/8 **BROOKLYN, NY 11207**
0.045 mi.
238 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
60 ft.

UST:
Facility Id: 2-344346
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 592770.22242999997
UTM Y: 4503180.6616000002

Affiliation Records:
Site Id: 16748
Affiliation Type: Mail Contact
Company Name: EAST NEW YORK SERVICE CORPORATION
Contact Type: Not reported
Contact Name: Not reported
Address1: 5381 KINGS HIGHWAY
Address2: Not reported
City: BROOKLYN

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

State:	NY
Zip Code:	11203
Country Code:	001
Phone:	(718) 629-6900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	16748
Affiliation Type:	On-Site Operator
Company Name:	EAST NEW SERVICE CORPORATION
Contact Type:	Not reported
Contact Name:	ANTHONY CURCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 342-6510
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	16748
Affiliation Type:	Owner
Company Name:	CLARENDON HOLDING COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5381 KINGS HIGHWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11203
Country Code:	001
Phone:	(718) 629-6900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	16748
Affiliation Type:	Emergency Contact
Company Name:	CLARENDON HOLDING COMPANY
Contact Type:	Not reported
Contact Name:	ANTHONY CURCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Phone:	(718) 342-6510
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B00 - Tank External Protection - None
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I00 - Overfill - None
I00 - Overfill - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
B00 - Tank External Protection - None
I00 - Overfill - None
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Info:

Site ID:	16748
Tank Number:	001
Tank ID:	32551
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1994
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	7/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	002
Tank ID:	32552
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1994
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	7/1/1994
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	003
Tank ID:	48528

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	004
Tank ID:	48529
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	005
Tank ID:	48530
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	006
Tank ID:	48531

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1997
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	16748
Tank Number:	007
Tank ID:	48741
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-344346
SPDES Number:	Not reported
Emergency Contact:	ANTHONY CURCIO
Emergency Telephone:	(718) 342-6510
Operator:	ANTHONY CURCIO
Operator Telephone:	(718) 342-6510
Owner Name:	CLARENDON HOLDING COMPANY
Owner Address:	5381 KINGS HIGHWAY
Owner City,St,Zip:	BROOKLYN, NY 11203
Owner Telephone:	(718) 629-6900
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	EAST NEW YORK SERVICE CORPORATION
Mailing Address:	5381 KINGS HIGHWAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11203
Mailing Contact:	Not reported
Mailing Telephone:	(718) 629-6900
Owner Mark:	Second Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	36 SNEDIKER AVENUE

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	11/08/1994
Expiration Date:	09/13/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19941101
Capacity (gals):	550
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	07/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19941101
Capacity (gals):	550
Product Stored:	NOS 1,2, OR 4 FUEL OIL

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	07/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	05/01/1998
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

O67 **NYCTA-ATLANTIC AVENUE STATION (L LINE)** **RCRA-CESQG** **1001202984**
North **ATLANTIC & VAN SINDEREN AVE** **FINDS** **NYR000042838**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.045 mi. **MANIFEST**
240 ft. **Site 2 of 7 in cluster O**

Relative:
Higher

Actual:
67 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	NYCTA-ATLANTIC AVENUE STATION (L LINE)
Facility address:	ATLANTIC AVENUE AND VAN SINDEREN AVENUE BROOKLYN, NY 11201
EPA ID:	NYR000042838
Mailing address:	JAY STREET, ROOM 819 BROOKLYN, NY 11201
Contact:	JOSEPHINE F BROWN
Contact address:	JAY STREET, ROOM 819

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

BROOKLYN, NY 11201
Contact country: US
Contact telephone: (718) 243-4581
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: MTA NYCT
Owner/operator address: 10 COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 307-5589
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MTA NYCT
Owner/operator address: 10 COLUMBUS CIR 25TH FLOOR
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 307-5589
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/20/2002
Facility name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Classification: Large Quantity Generator

Date form received by agency: 07/08/1999
Facility name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Site name: MTA NYCT - ATLANTIC AVE STATION
Classification: Not a generator, verified

Date form received by agency: 07/24/1997
Facility name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Site name: MTA NYCT - ATLANTIC AVE STATION
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/20/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110008100072

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:
Manifest Code: NJA5025344
EPA ID: NYR000042838
Date Shipped: 20040823
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040823
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040823
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	09210421
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5006850
EPA ID:	NYR000042838
Date Shipped:	20040218
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040218
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040219
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	03180425
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5104708
EPA ID: NYR000042838
Date Shipped: 20040512
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040512
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040512
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 05270421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

NY MANIFEST:
EPA ID: NYR000042838
Country: USA
Mailing Name: NYCTA-OFFICE OF SYSTEM SAFETY
Mailing Contact: N/S
Mailing Address: 370 JAY ST-RM 819
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-243-4581

Document ID: NJA5045071
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 08/20/2003
Trans1 Recv Date: 08/20/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/20/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: S8424
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 03

Document ID: NJA4113113
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 02/06/2003
Trans1 Recv Date: 02/06/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: S8424
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 03

Document ID: NJA5006850
Manifest Status: Not reported
Trans1 State ID: 08424
Trans2 State ID: Not reported

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Generator Ship Date:	02/18/2004
Trans1 Recv Date:	02/18/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	04

Document ID:	NJA5025344
Manifest Status:	Not reported
Trans1 State ID:	08424
Trans2 State ID:	Not reported
Generator Ship Date:	08/23/2004
Trans1 Recv Date:	08/23/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/23/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00200
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	04

Document ID:	NJA5104708
Manifest Status:	Not reported
Trans1 State ID:	08424
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2004
Trans1 Recv Date:	05/12/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

TSDF ID: NJD991291
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00500
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 04

Document ID: MIA7096781
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 03/15/2001
Trans1 Recv Date: 03/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/20/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: MID980991566
Trans2 EPA ID: Not reported
TSDF ID: Not reported
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 01

Document ID: NYG3162717
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2001
Trans1 Recv Date: 10/22/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/23/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01800
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 01

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Document ID: NYG2934423
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 06/15/2001
Trans1 Recv Date: 06/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/18/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03500
Units: P - Pounds
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 01

Document ID: NYG2901933
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 04/25/2001
Trans1 Recv Date: 04/25/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/27/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03800
Units: P - Pounds
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 01

Document ID: NJA4151939
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 09/06/2002
Trans1 Recv Date: 09/06/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/06/2002
Part A Recv Date: Not reported

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: S8424
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02500
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 02

Document ID: NJA4049860
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2002
Trans1 Recv Date: 07/12/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/12/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: S8424
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03500
Units: P - Pounds
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 02

Document ID: NYG1056546
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 11/25/1998
Trans1 Recv Date: 11/25/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/30/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001

NYCTA-ATLANTIC AVENUE STATION (L LINE) (Continued) **1001202984**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	98

Document ID:	NYG3328263
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/2002
Trans1 Recv Date:	04/10/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/11/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	02

O68 **APEX AIRTRONICS INC** **RCRA-NonGen** **1000438728**
North **2465-69 ATLANTIC AVE** **FINDS** **NYD001284439**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.046 mi.
244 ft. **Site 3 of 7 in cluster O**

Relative:
Higher

Actual:
67 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	APEX AIRTRONICS INC
Facility address:	2465-69 ATLANTIC AVE BROOKLYN, NY 11207
EPA ID:	NYD001284439
Mailing address:	ATLANTIC AVE BROOKLYN, NY 11207
Contact:	Not reported
Contact address:	ATLANTIC AVE BROOKLYN, NY 11207
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	APEX AIRTRONICS INC
Owner/operator address:	NOT REQUIRED

APEX AIRTRONICS INC (Continued) **1000438728**

NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: APEX AIRTRONICS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: APEX AIRTRONICS INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Facility name: APEX AIRTRONICS INC
Classification: Small Quantity Generator

Date form received by agency: 08/18/1980
Facility name: APEX AIRTRONICS INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/23/1992
Date achieved compliance: 09/22/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/23/1993

APEX AIRTRONICS INC (Continued) **1000438728**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/23/1992
Date achieved compliance: 09/22/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/23/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/07/1991
Date achieved compliance: 09/22/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/23/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/07/1991
Date achieved compliance: 09/22/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/07/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/07/1991
Date achieved compliance: 09/22/1998
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/23/1993
Enf. disposition status: Not reported

APEX AIRTRONICS INC (Continued) **1000438728**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 09/16/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/22/1998
Evaluation lead agency: State

Evaluation date: 06/19/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/22/1998
Evaluation lead agency: State

Evaluation date: 01/17/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/22/1998
Evaluation lead agency: State

FINDS:

Registry ID: 110001596096

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:
EPA ID: NYD001284439
Country: USA

APEX AIRTRONICS INC (Continued) **1000438728**

Mailing Name:	APEX AIRTRONICS INC
Mailing Contact:	FRANK ROSENBLUM
Mailing Address:	2465-69 ATLANTIC AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-485-8560

Document ID:	PAE1197766
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PAAH0414
Trans2 State ID:	Not reported
Generator Ship Date:	950720
Trans1 Recv Date:	950720
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950814
Part A Recv Date:	Not reported
Part B Recv Date:	950901
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00400
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95

Document ID:	PAE9140655
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	01/04/2000
Trans1 Recv Date:	01/04/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	0440375ME

APEX AIRTRONICS INC (Continued) **1000438728**

Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	F003 - UNKNOWN
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	2008-09-25
Trans1 Recv Date:	2008-09-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD066060609
Waste Code:	Not reported
Quantity:	750.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	003110110JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	PAC5809882
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0067
Trans2 State ID:	PAAH0067

APEX AIRTRONICS INC (Continued) **1000438728**

Generator Ship Date:	930609
Trans1 Recv Date:	930609
Trans2 Recv Date:	930610
TSD Site Recv Date:	930610
Part A Recv Date:	930626
Part B Recv Date:	930622
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	NJD054126164
TSDF ID:	PAD085690592
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00090
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	93

Document ID:	PAE1197184
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	31124MA
Trans2 State ID:	Not reported
Generator Ship Date:	971105
Trans1 Recv Date:	971105
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	971119
Part A Recv Date:	Not reported
Part B Recv Date:	971204
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	97

APEX AIRTRONICS INC (Continued) **1000438728**

Document ID:	PAC8927273
Manifest Status:	Completed copy
Trans1 State ID:	PAAH0317
Trans2 State ID:	Not reported
Generator Ship Date:	940328
Trans1 Recv Date:	940328
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940331
Part A Recv Date:	940414
Part B Recv Date:	940419
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00600
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	94

Document ID:	PAG0368513
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2002
Trans1 Recv Date:	10/10/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	PAD085690592
Trans2 EPA ID:	Not reported
TSDF ID:	PAAH0067
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Quantity:	02000
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels

APEX AIRTRONICS INC (Continued) **1000438728**

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 02

O69 **APEX AIRTRONICS INC** **AST** **A100343927**
North **2465 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.046 mi.
244 ft. **Site 4 of 7 in cluster O**

Relative:
Higher

Actual:
67 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-611061
Program Type: PBS
UTM X: 592673.88118000003
UTM Y: 4503378.71655
Expiration Date: N/A

Affiliation Records:
Site Id: 413008
Affiliation Type: Owner
Company Name: APEX AIRTRONICS INC
Contact Type: MGR
Contact Name: HOWARD KARP
Address1: 2465 ATLANTIC AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11207
Country Code: 001
Phone: (718) 485-8560
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/27/2009

Site Id: 413008
Affiliation Type: On-Site Operator
Company Name: APEX AIRTRONICS INC
Contact Type: Not reported
Contact Name: APEX AIRTRONICS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 485-8560
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/27/2009

Site Id: 413008

APEX AIRTRONICS INC (Continued) **A100343927**

Affiliation Type:	Mail Contact
Company Name:	APEX AIRTRONICS INC
Contact Type:	MGR
Contact Name:	HOWARD KARP
Address1:	2465 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 485-8560
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	4/27/2009

Site Id:	413008
Affiliation Type:	Emergency Contact
Company Name:	APEX AIRTRONICS INC
Contact Type:	Not reported
Contact Name:	HOWARD KAPP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 295-1748
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	4/27/2009

Equipment Records:

L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction
E03 - Piping Secondary Containment - Vault (without Access)
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Info:

Tank Number:	01
Tank Id:	228149
Tank Location:	2
Tank Type:	Steel Tank in Concrete
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported

APEX AIRTRONICS INC (Continued) **A100343927**

Install Date:	1/1/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	4/27/2009

O70 **FACTORY** **NY Spills** **S108956688**
North **2465 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.046 mi.
244 ft. **Site 5 of 7 in cluster O**

Relative:
Higher

Actual:
67 ft.

NY Spills:

Site ID:	389803
Facility Addr2:	Not reported
Facility ID:	0708834
Spill Number:	0708834
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	11/13/2007
Reported to Dept:	11/13/2007
CID:	444
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/6/2009
Remediation Phase:	0
Date Entered In Computer:	11/13/2007
Spill Record Last Update:	4/6/2009
Spiller Name:	HOWARD KARP
Spiller Company:	FACTORY
Spiller Address:	2465 ATLANTIC AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	HOWARD KARP
Contact Phone:	(718) 485-8560
DEC Region:	2
DER Facility ID:	339389
DEC Memo:	contact at Petro is: Sangesland spoke to Mr. Karp. Yesterday during a fuel delivery they noticed oil coming through the wall around the fill line. Probably oil in the soil under the sidewalk cement along the remote fill pipe line. Mr. Karp said that Petro would be repairing the pipe, but Sangesland specifically wanted to know who would do the soil digout/remediation once the sidewalk was opened up

FACTORY (Continued) **S108956688**

and the fill line exposed. Mr. Karp said Petro would come back on Nov 20th to make the repairs. There is a chance that the sidewalk fill line is installed through a coal chute into the basement wall and NOT through soil. When Petro opens up the sidewalk on Nov 20th they will call the DEC to confirm that either No soil was impacted OR there was soil impact and they will hire a company to do the cleanup. 12/19/08 Spoke with Mr. Karp. Mr. Karp told me the spill in the basement was cleaned up with speedy dry.He has no idea about any soil contamination at the site. I told him to find out exactly where was the leak on fill line and if the leaky portion of the line runs underground through the soil.He said he would contact Petro oil to find out the information. Letter was sent to Apex Airtronics Inc 2465 Atlantic Avenue Brooklyn, NY 11207-2305 Attn: Howard Karp (sr) 03/31/09 Performed site visit today. Tank is totally vaulted,i.e can't be seen without taking the top cement off.No PBS registration found though the capacity is above 1,100 gallon. Tightness testing required.As per Mr. Karp, the spill was minor quantity from the fill line in the tank room.Spill was on the concrete floor that was cleaned up by Petro Oil.Fill line has been replaced.No evidence of spill exists in the tank room.I told Mr. Karp to register the tank and have the tightness testing done.(sr) ** Case closed as there is no evidence of oil spill present at the site**S.R.

Remarks: FILL PIPE IS LEAKING AND SEEPED THROUGH THE WALL; PETRO ON SCENE

Material:

Site ID:	389803
Operable Unit ID:	1146930
Operable Unit:	01
Material ID:	2137321
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

E71
East
< 1/8
0.047 mi.
246 ft.

CON EDISON
SNEDIKER AVE & LIBERTY AVE
BROOKLYN, NY 11207

Site 3 of 5 in cluster E

RCRA-CESQG | **1014397147** | **NYP004194650**

Relative:
Higher

Actual:
57 ft.

RCRA-CESQG:

Date form received by agency:	09/17/2009
Facility name:	CON EDISON
Facility address:	SNEDIKER AVE & LIBERTY AVE BROOKLYN, NY 11207
EPA ID:	NYP004194650
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CAROLINE ISKANDER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(718) 666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

E72
East
< 1/8
0.047 mi.
246 ft.

CON EDISON
SNEDIKER AVE & LIBERTY AVE
BROOKLYN, NY 11207

Site 4 of 5 in cluster E

RCRA-CESQG **1014397187**
NYP004195053

Relative:
Higher

Actual:
57 ft.

RCRA-CESQG:

Date form received by agency:	09/18/2009
Facility name:	CON EDISON
Facility address:	SNEDIKER AVE & LIBERTY AVE BROOKLYN, NY 11207
EPA ID:	NYP004195053
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CAROLINE ISKANDER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(718) 666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

E73
East
< 1/8
0.047 mi.
246 ft.

CONSOLIDATED EDISON
SNEDIKER AVE & LIBERTY AVE
BROOKLYN, NY 11207

Site 5 of 5 in cluster E

MANIFEST **S110046688**
N/A

Relative:
Higher

Actual:
57 ft.

NY MANIFEST:

EPA ID:	NYP004195053
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-05
Trans1 Recv Date:	2009-10-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004194650
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000893802GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

CONSOLIDATED EDISON (Continued) **S110046688**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-05
Trans1 Recv Date:	2009-10-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004195053
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000893800GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

EPA ID:	NYP004194650
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-05
Trans1 Recv Date:	2009-10-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S110046688**

Generator EPA ID:	NYP004194650
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000893802GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-05
Trans1 Recv Date:	2009-10-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004195053
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000893800GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

CONSOLIDATED EDISON (Continued) **S110046688**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

T74 **SCHOOL BUS DEPOT** **NY Spills** **S107409979**
East **148 SNEDIKER AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.047 mi.
247 ft. **Site 1 of 6 in cluster T**

Relative:
Higher

Actual:
48 ft.

NY Spills:

Site ID:	353440
Facility Addr2:	Not reported
Facility ID:	0507935
Spill Number:	0507935
Facility Type:	ER
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Spill Date:	10/3/2005
Reported to Dept:	10/3/2005
CID:	408
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/28/2005
Remediation Phase:	0
Date Entered In Computer:	10/3/2005
Spill Record Last Update:	4/13/2006
Spiller Name:	NICK RECHRA
Spiller Company:	SCHOOL BUS DEPOT
Spiller Address:	148 SNEDIKER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	NICK RECHRA
Contact Phone:	(516) 746-4400 12
DEC Region:	2
DER Facility ID:	300770
DEC Memo:	Property is used for storage/fueling of yellow school buses. Owner: Yellow Management Corp. 148 Snediker Ave Brooklyn, NY 11207 Attn: John Curcio Property is being refinanced and bank required Phase 1/2 on site. Problems found with surface contamination (diesel or #2 fuel ?) around bus fueling platform (broken gravel pad). 1 of 3 borings on the site showed a problem down to 7 ft depth. EEA proposes to do additional borings around the site. Based on this information, they will then propose the next step in remediation. Contaminated soil letter sent to owner - John Curcio 11/5/05. EEA submitted an SIR with a proposal to excavate contaminated soil. YK. 11/8/05 - EEA called and will excavate the shallow contamination and take end-point samples. Will send report to DEC when complete. - KST 12/28/05.

SCHOOL BUS DEPOT (Continued) **S107409979**

J.Krimgold reviewed the Remedial Corrective Action Report submitted by EEA Inc. According to the report contaminated soil was removed to thr depth of ten feet. Post-excavation samples show no elevated levels of pertol contaminants. NFA letter.

Remarks: pta readings at 700 at surface and than after 7 ft. it is clear or product, This is the result of a phase two result.

Material:
Site ID: 353440
Operable Unit ID: 1110899
Operable Unit: 01
Material ID: 2100940
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

T75 **EMPIRE STATE BUS CORP** **RCRA-NonGen** **1008892067**
East **148 SNEDIKER AVE** **NYN008015125**
< 1/8 **BROOKLYN, NY 11207**
0.047 mi.
247 ft. **Site 2 of 6 in cluster T**

Relative:
Higher

Actual:
48 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: EMPIRE STATE BUS CORP
Facility address: 148 SNEDIKER AVE
BROOKLYN, NY 11207
EPA ID: NYN008015125
Mailing address: SNEDIKER AVE
BROOKLYN, NY 11207
Contact: JOHN CURCIO
Contact address: SNEDIKER AVE
BROOKLYN, NY 11207
Contact country: US
Contact telephone: (718) 485-8002
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator

EMPIRE STATE BUS CORP (Continued) **1008892067**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: EMPIRE STATE BUS CORP
Classification: Not a generator, verified

Date form received by agency: 11/17/2005
Facility name: EMPIRE STATE BUS CORP
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/14/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

T76 **EMPIRE CHARTER SERVICE INC** **FINDS** **1008913791**
East **148 SNEDIKER AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.047 mi.
247 ft. **Site 3 of 6 in cluster T**

Relative:
Higher

Actual:
48 ft.

FINDS:

Registry ID: 110024257267

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when

EMPIRE CHARTER SERVICE INC (Continued) **1008913791**

complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

U77 **194 SNEDIKER AVE** **NY Spills** **S107658530**
East **194 SNEDIKER AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.047 mi.
250 ft. **Site 1 of 9 in cluster U**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	362102
Facility Addr2:	Not reported
Facility ID:	0600153
Spill Number:	0600153
Facility Type:	ER
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Spill Date:	4/5/2006
Reported to Dept:	4/5/2006
CID:	444
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/2/2006
Remediation Phase:	0
Date Entered In Computer:	4/5/2006
Spill Record Last Update:	8/2/2006
Spiller Name:	CHRIS HOSS
Spiller Company:	Not reported
Spiller Address:	194 SNEDIKER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	CHRIS HOSS
Contact Phone:	(917) 769-1263
DEC Region:	2
DER Facility ID:	312347
DEC Memo:	05/17/06-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin. 6/16/06 - Raphael Ketani. I tried calling Chris Hoss

194 SNEDIKER AVE (Continued) **S107658530**

of DEP (718) 595-4784 (cell (917) 769-1263) regarding the unsafe tank, but could only leave a message. 7/5/06 - Raphael Ketani. I tried to reach Mr. Hoss, but could only leave a message. 7/12/06 - Raphael Ketani. Mr. Hoss called me back. He said that he was told to go out to the site to inspect the conditions. When he got there, he found that it was a triangular plot of land that looked like someone may have taken out a tank. However, all that could be seen was a vacant leveled piece of land with no indication of any contamination. He said this is all the information he has, but he will try to contact the Fire Department to see if they have some more data about the site. 8/2/06 - Raphael Ketani. I tried calling the NYFD Hazmat office at (718) 476-6288, but the line was busy. I will try later. I made contact with Lt. Cassidy of NYFD Hazmat. He looked up the Fire Department responses on or about 4/5/06, the date the spill was called in, and found nothing. He said that meant there was no information. Given the lack of information about the spill and the observation that the site was a flat piece of land with nothing on it with no contamination evident, I am closing the spill case administratively.

Remarks: REPORTING UNSAFE STORAGE OF ABOVE OIL IN BACK OF LOCATION: NO OTHER INFO IS AVAILABLE:

Material:

Site ID:	362102
Operable Unit ID:	1120208
Operable Unit:	01
Material ID:	2109701
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

U78 **MANHOLE 739** **NY Spills** **S106012235**
East **SNEDIKER AV / PITKIN AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.048 mi.
251 ft. **Site 2 of 9 in cluster U**

Relative:
Higher

Actual:
43 ft.

NY Spills:

Site ID:	183761
Facility Addr2:	Not reported
Facility ID:	0212296
Spill Number:	0212296
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	3/13/2003
Reported to Dept:	3/14/2003
CID:	365
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/26/2003
Remediation Phase:	0
Date Entered In Computer:	3/14/2003
Spill Record Last Update:	9/29/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	153807
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" Con Ed e2mis #147506: 3-13-03 1135 HRS J. CUADRDO # 82019 MECH "A" FLUSH DEPT REPORTS WHILE GETTING READY TO FLUSH TM739 C/O SNEDIKER AVE 41' S/O PITKIN AVE HE FOUND APPROX 1 GALLON UNKNOWN OIL ON 40 GALLONS WATER. THE TRANSF IN THIS STRUCTURE WAS ON FDR.3B91 AND THIS FEEDER OFF THE SYSTEM AT THIS TIME. TRANSF IS DRAINED AND WAS REMOVED AT THIS TIME. TRANSF WAS PREVIOUSLY PRESSURE TESTED AND FAILED TESTING, THAT WHY IT WAS BEING REMOVED . HISTORICAL RECORD OF TRANSF IS 180 PPM LAST TESTED 10-16-98 LIB SEQ # 98-11446. HE DOES NOT KNOWN HOW MUCH OIL WAS DRAINED FRON TRANSF. TRANSF CREW LEFT LOCATION. WHEN CLEANUP IS COMPLETED A NEW TRANSF TO BE INSTALL HE TOOK A LIQUID SAMPLE AND REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULT. CLEANUP PENDING SAMPLE RESULTS. HE PLACED E.S.TAG # 34890. CHAIN OF CUSTODY # CC16309. Update - 3/13/03 - lab results received, sequence # 03-02088-001. PCB <1.0 PPM UPDATE 3-14-03 1040 HRS AS PER OS E. WILLIAMS FLUSH DEPT REPORTS DUE TO THE AMOUNT OF WORK LEFT IN STRUCTURE , THIS CLEANUP WILL NOT BE COMPLETED ON TIME FOR THE 24 HRS

MANHOLE 739 (Continued) **S106012235**

DEMINIMIS PROGRAM. CALL GIG L. COSTA AT 1042 HRS TO TAKE THIS OFF THE 24 HRS DEMINIMIS PROGRAM LAZ # 04425 UPDATE: 3/14/03 - 1330 E. WILLIAMS - O.S. - ENV. OPS., REPORTS STRUCTURE DOUBLE WASHED WITH BIO GEN 760. TAG # 34890 REMOVED. UPDATE 5/14/03 .... THE INITIAL REPORT STATES THE TRANSFORMER IS DRAINED AND WAS REMOVED AT THIS TIME....

Remarks: 1 GAL UNK OIL ON 40 GAL WATER IN A MANHOLE - UNABLE TO BE CLEANED UP UNDER THE 24 HR DIMINIMOUS PROGRAM - REF #147506

Material:

Site ID:	183761
Operable Unit ID:	865743
Operable Unit:	01
Material ID:	512033
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

U79 **NYNEX** **MANIFEST** **1009234055**
East **SNEDICKER AVE & PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.048 mi.
251 ft. **Site 3 of 9 in cluster U**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

EPA ID:	NYP000924928
Country:	USA
Mailing Name:	NYNEX
Mailing Contact:	SUSHMITA BISWAS
Mailing Address:	221 EAST 37TH STREET
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-338-7126

Document ID: MIA4134113

NYNEX (Continued) **1009234055**

Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	3167A1NY
Generator Ship Date:	960508
Trans1 Recv Date:	960508
Trans2 Recv Date:	960519
TSD Site Recv Date:	960521
Part A Recv Date:	Not reported
Part B Recv Date:	960611
Generator EPA ID:	NYP000924928
Trans1 EPA ID:	NYD010951986
Trans2 EPA ID:	NYD046765574
TSDF ID:	MID096963194
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02400
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	96

U80 **NYNEX SUB SURFACE** **MANIFEST** **1009233994**
East **PITKIN AVE & SNEDICKER A** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.048 mi.
251 ft. **Site 4 of 9 in cluster U**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

EPA ID:	NYP000923995
Country:	USA
Mailing Name:	NYNEX SUB SURFACE
Mailing Contact:	JOSE E RODRIGUEZ
Mailing Address:	101 WILLOUGHBY STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-389-4064

Document ID:	NJA2295865
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	50060
Trans2 State ID:	Not reported
Generator Ship Date:	960318
Trans1 Recv Date:	960318
Trans2 Recv Date:	960322
TSD Site Recv Date:	960322
Part A Recv Date:	960415
Part B Recv Date:	960412
Generator EPA ID:	NYP000923995
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP

NYNEX SUB SURFACE (Continued) **1009233994**

Quantity:	00825
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	015
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	96

U81 **MANHOLE 5196** **NY Spills** **S103938930**
East **SNEDIKER AVE & PITKIN AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.048 mi.
251 ft. **Site 5 of 9 in cluster U**

Relative:
Higher

Actual:
43 ft.

NY Spills:

Site ID:	211484
Facility Addr2:	Not reported
Facility ID:	9903581
Spill Number:	9903581
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	6/28/1999
Reported to Dept:	6/28/1999
CID:	389
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/7/2001
Remediation Phase:	0
Date Entered In Computer:	6/28/1999
Spill Record Last Update:	6/12/2001
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	175254
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 6-28-99 Found approx. 3 gallons of unknown oil in MH5196. No water in structure, dirt at bottom. No sewers or waterways seem affected at this time. Took liquid sample with 4-6hr turnaround. Lab Seq# 99-06724 64ppm 6-29-99 Possible abatement in structure. Chem Lab took sample of the arcproofing to test for abatement. 6-29-99 2100hrs. Double washed structure, sealed drain, no liquid found in drain, found oilsoaked

MANHOLE 5196 (Continued) **S103938930**

asbestos which needs to be removed(abatement) Lab Seq#99-06751 results indicate no trace of asbestos. 1-26-01 1100hrs. Arcproofing removed from structure. 1-28-01 15:40hrs. All debris removed from structure, structur double washed with Biogen 760, Env. Tag removed 1-29-01 0515hrs. Cleanup complete, incident closed.

Remarks: approx 3 gal of an unknown oil leaked into a manhole oil is contained to the manhole con ed# 125849 clean up pending lab results caller dosen't wish a callback from dec - UPDATE 5/29 @ 0236HRS: THE PCB COUNT WAS 64PPM

Material:

Site ID:	211484
Operable Unit ID:	1078170
Operable Unit:	01
Material ID:	566336
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9903581
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	06/28/1999 21:45
Reported to Dept Date/Time:	06/28/99 22:34
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Address:	UNK
Spiller City,St,Zip:	UNK, NY
Spill Cause:	Unknown

MANHOLE 5196 (Continued) **S103938930**

Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/07/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/28/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/12/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 3
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: DEC INSPECTOR S NOTES CON ED E2MIS REPORT 6-28-99 Found approx. 3 gallons of unknown oil in MH5196. No water in structure, dirt at bottom. No sewers or waterways seem affected at this time. Took liquid sample with 4-6hr turnaround. LabSeq 99-06724 64ppm 6-29-99 Possible abatement in structure. Chem Lab took sample of the arcproofing to test for abatement. 6-29-99 2100hrs. Double washed structure, sealed drain, no liquid found in drain, found oilsoaked asbestos which needs to be removed abatement) Lab Seq 99-06751 results indicate no trace of asbestos. 1-26-01 1100hrs. Arcproofing removed from structure. 1-28-01 15:40hrs. All debris removed from structure, structur double washed with Biogen 760, Env. Tag removed 1-29-01 0515hrs. Cleanup complete, incident closed.
Remark: approx 3 gal of an unknown oil leaked into a manhole oil is contained to the manhole con ed 125849 clean up pending lab results caller dosen t wish a callback from dec - UPDATE 5/29 @ 0236HRS: THE PCB COUNT WAS 64PPM

U82 **NYNEX MANHOLE** **MANIFEST** **S109064994**
East **PITKIN AVE & SNEDICKER AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.048 mi.
251 ft. **Site 6 of 9 in cluster U**

Relative:
Higher

Actual:
43 ft.

NY MANIFEST:

EPA ID:	NYP000923955
Country:	USA
Mailing Name:	NYNEX MANHOLE
Mailing Contact:	Not reported
Mailing Address:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

NY MANIFEST:

No Manifest Records Available

O83 **ARIES AUTOWORLD LTD** **SWF/LF** **S108145674**
NNE **2471 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.048 mi.
254 ft. **Site 6 of 7 in cluster O**

Relative:
Higher

Actual:
65 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling
Activity Number:	Not reported
Active:	No
East Coordinate:	592730
North Coordinate:	4503291
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	None
Authorization Date:	Not reported
Expiration Date:	Not reported

T84 **EMPIRE METAL SPINNING CORP** **RCRA-NonGen** **1000457630**
East **157-159 SNEDIKER AVE** **FINDS** **NYD986928919**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.049 mi.
257 ft. **Site 4 of 6 in cluster T**

Relative:
Higher

Actual:
46 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	EMPIRE METAL SPINNING CORP
Facility address:	157-159 SNEDIKER AVE BROOKLYN, NY 112073303
EPA ID:	NYD986928919
Mailing address:	SNEDIKER AVE BROOKLYN, NY 11207
Contact:	Not reported
Contact address:	SNEDIKER AVE BROOKLYN, NY 11207
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EMPIRE METAL SPINNING CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	EMPIRE METAL SPINNING CORP
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

EMPIRE METAL SPINNING CORP (Continued) **1000457630**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: EMPIRE METAL SPINNING CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: EMPIRE METAL SPINNING CORP
Classification: Not a generator, verified

Date form received by agency: 10/26/1990
Facility name: EMPIRE METAL SPINNING CORP
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004454938

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986928919
Country: USA
Mailing Name: EMPIRE METAL SPINNERS CORP
Mailing Contact: FRANK
Mailing Address: 157-159 SNEDITEN AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11207
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-498-1515

Document ID: NJA0802643
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: NJDEPS869
Generator Ship Date: 910214
Trans1 Recv Date: 910214
Trans2 Recv Date: 910220
TSD Site Recv Date: 910221
Part A Recv Date: 910228
Part B Recv Date: 910307

EMPIRE METAL SPINNING CORP (Continued) **1000457630**

Generator EPA ID:	NYD986928919
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00595
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91

T85 **RITE-WAY WOOD-CRAFTS CO INC** **FINDS** **1011459114**
East **145 SNEDIKER AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
258 ft. **Site 5 of 6 in cluster T**

Relative:
Higher

Actual:
48 ft.

FINDS:

Registry ID: 110035963213

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

U86 **BIG APPLE AUTO INC** **SWF/LF** **S108145711**
East **1934 PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
259 ft. **Site 7 of 9 in cluster U**

Relative:
Higher

Actual:
42 ft.

SWF/LF:

Flag:	ACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Michael Deluca
Contact Address:	1934 Pilkin Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn;, NY 11207
Contact Email:	Bigappleauto1@optimum.net
Contact Phone:	7184951781
Activity Desc:	Vehicle Dismantling
Activity Number:	Not reported
Active:	Yes
East Coordinate:	592856

BIG APPLE AUTO INC (Continued) **S108145711**

North Coordinate: 4502761
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: None
Authorization Date: Not reported
Expiration Date: Not reported

U87 **BIG APPLEAUTO INC.** **AST** **A100297761**
East **1934 PITKIN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
259 ft. **Site 8 of 9 in cluster U**

Relative:
Higher

Actual:
42 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610235
Program Type: PBS
UTM X: 592853.15133999998
UTM Y: 4502816.6629100004
Expiration Date: 2016/06/12

Affiliation Records:
Site Id: 365277
Affiliation Type: Owner
Company Name: BIG APPLE AUTO INC.
Contact Type: AUTHORIZED REPRESENTATIVE
Contact Name: MICHAEL DELUCA
Address1: 1934 PITKIN AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11207-3328
Country Code: 001
Phone: (718) 495-1781
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/29/2011

Site Id: 365277
Affiliation Type: Emergency Contact
Company Name: BIG APPLE AUTO INC.
Contact Type: Not reported
Contact Name: MIKE DELUCA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 662-3550
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported

BIG APPLEAUTO INC. (Continued) **A100297761**

Modified By:	NRLOMBAR
Date Last Modified:	6/12/2006
Site Id:	365277
Affiliation Type:	Mail Contact
Company Name:	BIG APPLE AUTO INC.
Contact Type:	Not reported
Contact Name:	MIKE DELUCA
Address1:	1934 PITKIN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207-3328
Country Code:	001
Phone:	(718) 495-1781
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/12/2006
Site Id:	365277
Affiliation Type:	On-Site Operator
Company Name:	BIG APPLEAUTO INC.
Contact Type:	Not reported
Contact Name:	MIKE DELUCA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-1781
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/12/2006

Equipment Records:

L02 - Piping Leak Detection - Interstitial - Manual Monitoring
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
A01 - Tank Internal Protection - Epoxy Liner
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping

Tank Info:

Tank Number:	001
Tank Id:	212205

BIG APPLEAUTO INC. (Continued) **A100297761**

Tank Location:	2
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/26/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	6/12/2006

U88 **BIG APPLE AUTO INC** **FINDS** **1010494487**
East **1934 PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
259 ft. **Site 9 of 9 in cluster U**

Relative:
Higher

Actual:
42 ft.

FINDS:

Registry ID: 110032604073

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

V89 **GENESIS NEIGHBORHOOD PLAZA II** **RCRA-LQG** **1014399567**
East **350 SNEDIKER AVE** **NYR000176560**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
261 ft. **Site 1 of 3 in cluster V**

Relative:
Lower

Actual:
36 ft.

RCRA-LQG:

Date form received by agency:	07/23/2010
Facility name:	GENESIS NEIGHBORHOOD PLAZA II
Facility address:	350 SNEDIKER AVE BROOKLYN, NY 11207
EPA ID:	NYR000176560
Mailing address:	HANOVER SQUARE 17TH FLOOR NEW YORK, NY 10004
Contact:	LARRY BELINSKY
Contact address:	HANOVER SQUARE 17TH FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	214007070
Telephone ext.:	2

GENESIS NEIGHBORHOOD PLAZA II (Continued) **1014399567**

Contact email: IBELINSKY@HELPUSA.ORG
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: GENESIS NEIGHBORHOOD PLAZA II LP
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/08/2010
Owner/Op end date: Not reported

Owner/operator name: PLAZA HOUSING DEV FUND CO
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/08/2010
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D008

GENESIS NEIGHBORHOOD PLAZA II (Continued) **1014399567**

Waste name: LEAD

Violation Status: No violations found

V90 **GENESIS NEIGHBORHOOD PLAZA II** **MANIFEST** **S110611253**
East **350 SNEDIKER AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.049 mi.
261 ft. **Site 2 of 3 in cluster V**

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:

EPA ID:	NYR000176560
Country:	USA
Mailing Name:	GENESIS NEIGHBORHOOD PLAZA II
Mailing Contact:	GENESIS NEIGHBORHOOD PLAZA II
Mailing Address:	5 HANOVER SQUARE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-377-6300
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-13
Trans1 Recv Date:	2010-08-13
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-13
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	59340.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461778JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-13
Trans1 Recv Date:	2010-08-13
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-13
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	59400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461779JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-16
Trans1 Recv Date:	2010-08-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	52580.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Year:	2010
Manifest Tracking Num:	007461780JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-16
Trans1 Recv Date:	2010-08-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	55800.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461806JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-16
Trans1 Recv Date:	2010-08-16

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	62460.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461808JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-16
Trans1 Recv Date:	2010-08-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	58940.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461809JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-17
Trans1 Recv Date:	2010-08-17
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	52660.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461810JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-17
Trans1 Recv Date:	2010-08-17
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	57840.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461811JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-17
Trans1 Recv Date:	2010-08-17
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	58060.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461812JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000363820
Trans2 State ID: Not reported
Generator Ship Date: 2010-08-17
Trans1 Recv Date: 2010-08-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-08-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176560
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 58180.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007461813JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000363820
Trans2 State ID: Not reported
Generator Ship Date: 2010-08-17
Trans1 Recv Date: 2010-08-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-08-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176560
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 20.0
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 1.0

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461814JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461815JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461816JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461817JJK
Import Ind:	N

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461818JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461819JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461820JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461821JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461822JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000363820
Trans2 State ID:	Not reported
Generator Ship Date:	2010-08-19
Trans1 Recv Date:	2010-08-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-08-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	20.0
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	007461823JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

GENESIS NEIGHBORHOOD PLAZA II (Continued) **S110611253**

Click this hyperlink while viewing on your computer to access
94 additional NY_MANIFEST: record(s) in the EDR Site Report.

K91 **H E L P HOUSES DEVELOPMENT CORP** **RCRA-NonGen** **1001818206**
East **SNEDIKER & BLAKE AVES SW COR** **FINDS** **NYR000077131**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.050 mi.
264 ft. **Site 2 of 2 in cluster K**

Relative:
Lower

Actual:
36 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	H E L P HOUSES DEVELOPMENT CORP
Facility address:	SNEDIKER & BLAKE AVES SW COR BROOKLYN, NY 11207
EPA ID:	NYR000077131
Mailing address:	E 33RD ST NEW YORK, NY 10016
Contact:	MARTIN DUNN
Contact address:	E 33RD ST NEW YORK, NY 10016
Contact country:	US
Contact telephone:	(718) 388-9407
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	H E L P HOUSES DEVELOPMENT CORP
Owner/operator address:	30 E 33RD ST NEW YORK, NY 10016
Owner/operator country:	US
Owner/operator telephone:	(212) 779-3350
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	H E L P HOUSES DEVELOPMENT CORP
Owner/operator address:	30 E 33RD ST NEW YORK, NY 10016
Owner/operator country:	US
Owner/operator telephone:	(212) 779-3350
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: H E L P HOUSES DEVELOPMENT CORP
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Facility name: H E L P HOUSES DEVELOPMENT CORP
Site name: H.E.L.P. HOUSES DEVELOPMENT CORP
Classification: Large Quantity Generator

Date form received by agency: 10/01/1999
Facility name: H E L P HOUSES DEVELOPMENT CORP
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 07/19/2000
Date achieved compliance: 10/16/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/19/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 03/01/2000
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 10/16/2000
Evaluation lead agency: State

FINDS:

Registry ID: 110008109796

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000077131
Country:	USA
Mailing Name:	HELP HOUSES DEVELOPMENT
Mailing Contact:	MELISSA A MCGOOGAN
Mailing Address:	SNEDIKER AVE & BLAKE AVE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-340-9790

Document ID:	NYB9265131
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	12/16/1999
Trans1 Recv Date:	12/16/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	XB47591PA
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	53420
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9266193
Manifest Status:	Not reported
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/1999
Trans1 Recv Date:	12/20/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	XE02935PA
Waste Code:	D008 - LEAD 5.0 MG/L TCLP

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Quantity:	48920
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9266229
Manifest Status:	Not reported
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/1999
Trans1 Recv Date:	12/20/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	955TMRNJ
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	50440
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9266238
Manifest Status:	Not reported
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1999
Trans1 Recv Date:	12/21/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	58945MNY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	46660
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Document ID:	NYB9266247
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1999
Trans1 Recv Date:	12/21/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	TZ47348PA
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	47400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9266256
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	12/21/1999
Trans1 Recv Date:	12/21/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	XA60931PA
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	41140
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9266265
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	12/22/1999
Trans1 Recv Date:	12/22/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/27/1999
Part A Recv Date:	Not reported

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XB47591PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 56760
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266292
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/22/1999
Trans1 Recv Date: 12/22/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/27/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XG70657PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 51840
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266301
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/22/1999
Trans1 Recv Date: 12/22/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/27/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XD93448PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 54640
Units: P - Pounds
Number of Containers: 001

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266319
Manifest Status: Not reported
Trans1 State ID: NYD986969947
Trans2 State ID: Not reported
Generator Ship Date: 12/21/1999
Trans1 Recv Date: 12/21/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 52866RNY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 69540
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266328
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/21/1999
Trans1 Recv Date: 12/21/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/22/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XD73450PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49100
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266337
Manifest Status: Not reported
Trans1 State ID: PAD146714878

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Trans2 State ID: Not reported
Generator Ship Date: 12/20/1999
Trans1 Recv Date: 12/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XA49178PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 48360
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266346
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/20/1999
Trans1 Recv Date: 12/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XD54330PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 53160
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266355
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/20/1999
Trans1 Recv Date: 12/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Trans2 EPA ID: Not reported
TSDF ID: XB47591PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49880
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266364
Manifest Status: Not reported
Trans1 State ID: NYD986969947
Trans2 State ID: Not reported
Generator Ship Date: 12/20/1999
Trans1 Recv Date: 12/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 186724ANY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50100
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9266373
Manifest Status: Not reported
Trans1 State ID: NYD986969947
Trans2 State ID: Not reported
Generator Ship Date: 12/20/1999
Trans1 Recv Date: 12/20/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 58944MNY
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 50540
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Year: 99

Document ID: NYB9265149
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/16/1999
Trans1 Recv Date: 12/16/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/17/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XF96227PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 49020
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9265158
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/16/1999
Trans1 Recv Date: 12/16/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/17/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000077131
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: PAXA07719
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 57780
Units: P - Pounds
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYB9265167
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 12/16/1999
Trans1 Recv Date: 12/16/1999

H E L P HOUSES DEVELOPMENT CORP (Continued) **1001818206**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	TY14548
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	48960
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYB9265176
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	12/16/1999
Trans1 Recv Date:	12/16/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000077131
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	Not reported
TSDF ID:	XG70656PA
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	49520
Units:	P - Pounds
Number of Containers:	001
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Click this hyperlink while viewing on your computer to access
86 additional NY_MANIFEST: record(s) in the EDR Site Report.

W92 **149 POWELL STREET** **UST** **U004045037**
WSW **149 POWELL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.050 mi.
266 ft. **Site 1 of 2 in cluster W**

Relative:
Higher

Actual:
47 ft.

UST:

Facility Id:	2-609768
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592612.69058000005

149 POWELL STREET (Continued) **U004045037**

UTM Y: 4502824.7234500004

Affiliation Records:

Site Id: 333564
Affiliation Type: Emergency Contact
Company Name: MODI REALTY INC.
Contact Type: Not reported
Contact Name: GITTU MODI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 776-6901
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/10/2004

Site Id: 333564
Affiliation Type: On-Site Operator
Company Name: 149 POWELL STREET
Contact Type: Not reported
Contact Name: GITTU MODI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 776-6901
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/10/2004

Site Id: 333564
Affiliation Type: Owner
Company Name: MODI REALTY INC.
Contact Type: PRESIDENT
Contact Name: GAURI MODI
Address1: 82-47, 210TH STREET
Address2: Not reported
City: MILLIS MILLS
State: NY
Zip Code: 11427
Country Code: 001
Phone: (718) 776-6901
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/10/2004

Site Id: 333564

149 POWELL STREET (Continued) **U004045037**

Affiliation Type:	Mail Contact
Company Name:	HYDRO TECH ENVIRONMENTAL, CORP.
Contact Type:	Not reported
Contact Name:	MARK ROBBINS
Address1:	2171 JERICHO TURNPIKE
Address2:	SUITE 240
City:	COMMACK
State:	NY
Zip Code:	11725
Country Code:	001
Phone:	(631) 462-5866
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	11/10/2004

Equipment Records:

L00 - Piping Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None

Tank Info:

Site ID:	333564
Tank Number:	001
Tank ID:	180784
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	00
Next Test Date:	Not reported
Date Tank Closed:	5/28/2004
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	11/10/2004

W93 **NYC ECONOMIC DEVELOPMENT CORP** **RCRA-NonGen** **1001493670**
WSW **171 POWELL ST** **FINDS** **NYR000075655**
< 1/8 **BROOKLYN, NY 11212** **MANIFEST**
0.051 mi.
267 ft. **Site 2 of 2 in cluster W**

Relative:
Higher

Actual:
45 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYC ECONOMIC DEVELOPMENT CORP
Facility address:	171 POWELL ST BROOKLYN, NY 11212
EPA ID:	NYR000075655
Mailing address:	WILLIAM ST NEW YORK, NY 10038
Contact:	KAY ZIAS
Contact address:	WILLIAM ST NEW YORK, NY 10038
Contact country:	US
Contact telephone:	(212) 312-3752
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYC ECONOMIC DEVELOPMENT CORP
Owner/operator address:	110 WILLIAM ST NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	(212) 312-3752
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYC ECONOMIC DEVELOPMENT CORP
Owner/operator address:	110 WILLIAM ST NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	(212) 312-3752
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

NYC ECONOMIC DEVELOPMENT CORP (Continued) **1001493670**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Classification: Not a generator, verified

Date form received by agency: 08/23/1999
Facility name: NYC ECONOMIC DEVELOPMENT CORP
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004555838

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000075655
Country: USA
Mailing Name: NYC ECONOMIC DEVELOPMENT CORP
Mailing Contact: JUAN SOTO
Mailing Address: 110 WILLIAM ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10038
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-312-3752

Document ID: MIA7332342
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 09/01/1999
Trans1 Recv Date: 09/01/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000075655
Trans1 EPA ID: MID060975844
Trans2 EPA ID: Not reported
TSDF ID: XD93505PA

NYC ECONOMIC DEVELOPMENT CORP (Continued) **1001493670**

Waste Code:	F005 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

X94 **NYCEDC - PROPERTY** **FINDS** **1007081643**
WSW **181 POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
268 ft. **Site 1 of 5 in cluster X**

Relative:
Higher

Actual:
44 ft.

FINDS:

Registry ID: 110015588265

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

X95 **NYCEDC - PROPERTY** **RCRA-CESQG** **1006931267**
WSW **181 POWELL ST** **MANIFEST** **NYR000117465**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
268 ft. **Site 2 of 5 in cluster X**

Relative:
Higher

Actual:
44 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	NYCEDC - PROPERTY
Facility address:	181 POWELL ST BROOKLYN, NY 112128104
EPA ID:	NYR000117465
Mailing address:	WILLIAMS ST NEW YORK, NY 10038
Contact:	KAY ZIAS
Contact address:	WILLIAMS ST NEW YORK, NY 10038
Contact country:	US
Contact telephone:	(212) 312-3752
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

NYCEDC - PROPERTY (Continued) **1006931267**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYCEDC
Owner/operator address:	UNKNOWN UNKNOWN, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	12/31/1979
Owner/Op end date:	Not reported

Owner/operator name:	UNKNOWN
Owner/operator address:	UNKNOWN UNKNOWN, NY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	12/31/1979
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	NYCEDC - PROPERTY
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	08/06/2003
Facility name:	NYCEDC - PROPERTY
Classification:	Large Quantity Generator

NYCEDC - PROPERTY (Continued) **1006931267**

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYR000117465
Country:	USA
Mailing Name:	NYC ECONOMIC DEVELOPMENT CORP
Mailing Contact:	N/S
Mailing Address:	110 WILLIAMS ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10038
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	631-586-2000

Document ID:	NYG3230019
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2003
Trans1 Recv Date:	08/28/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/08/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000117465
Trans1 EPA ID:	OHD066060609
Trans2 EPA ID:	Not reported
TSDF ID:	0440464ME
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.05
Year:	03

M96 **MASTERMADE FURNITURE CORP.** **HIST AST** **S107782951**
East **410 SNEDIKER AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.051 mi.
268 ft. **Site 4 of 8 in cluster M**

Relative:
Lower

Actual:
35 ft.

HIST AST:

PBS Number:	2-602407
SWIS Code:	6101
Operator:	MARTIN LEVINE
Facility Phone:	(718) 345-2100
Facility Addr2:	Not reported
Facility Type:	MANUFACTURING
Emergency:	MARTIN LEVINE
Emergency Tel:	(631) 491-1830
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported

MASTERMADE FURNITURE CORP. (Continued) **S107782951**

Result of Inspection:	Not reported
Owner Name:	HOPKINS TRADING CORP.
Owner Address:	410 SNEDIKER AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11207
Federal ID:	Not reported
Owner Tel:	(718) 345-2100
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	MARTIN LEVINE
Mailing Name:	MASTERMADE FURNITURE CORP.
Mailing Address:	410 SNEDIKER AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11207
Mailing Telephone:	(718) 345-2100
Owner Mark:	Second Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	10/18/2001
Expiration:	10/12/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3500
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	1
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	5
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	0
Tank Containment:	Diking
Leak Detection:	1
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported

MASTERMADE FURNITURE CORP. (Continued) **S107782951**

Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

M97 **MASTERMADE FURNITURE CORP.** **AST** **A100194072**
East **410 SNEDIKER AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.051 mi.
268 ft. **Site 5 of 8 in cluster M**

Relative:
Lower

Actual:
35 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated
Facility Id: 2-602407
Program Type: PBS
UTM X: 592999.72649000003
UTM Y: 4502086.4938399997
Expiration Date: N/A

Affiliation Records:
Site Id: 24364
Affiliation Type: Owner
Company Name: HOPKINS TRADING CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 410 SNEDIKER AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11207
Country Code: 001
Phone: (718) 345-2100
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/25/2009

Site Id: 24364
Affiliation Type: Emergency Contact
Company Name: HOPKINS TRADING CORP.
Contact Type: Not reported
Contact Name: MARTY LEVINE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 345-2100
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/25/2009

MASTERMADE FURNITURE CORP. (Continued) **A100194072**

Site Id:	24364
Affiliation Type:	On-Site Operator
Company Name:	MASTERMADE FURNITURE CORP.
Contact Type:	Not reported
Contact Name:	MARTY LEVINE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 345-2100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	3/25/2009

Site Id:	24364
Affiliation Type:	Mail Contact
Company Name:	MASTERMADE FURNITURE CORP.
Contact Type:	Not reported
Contact Name:	MARTIN LEVINE
Address1:	410 SNEDIKER AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 345-2100
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B05 - Tank External Protection - Jacketed
L00 - Piping Leak Detection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle

Tank Info:

Tank Number:	0001
Tank Id:	50000
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron

MASTERMADE FURNITURE CORP. (Continued) **A100194072**

Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	3/19/2009
Register:	True
Modified By:	NRLOMBAR
Last Modified:	3/25/2009

I98 **206663; POWELL ST & LIBERTY AVE** **NY Spills** **S109207947**
WSW **POWELL ST & LIBERTY AVE** **N/A**
< 1/8 **KINGS (County), NY**
0.051 mi.
268 ft. **Site 3 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	399201
Facility Addr2:	M-5142 S/INT POWELL ST & LIBERTY AVE
Facility ID:	0890113
Spill Number:	0890113
Facility Type:	ER
SWIS:	2401
Investigator:	Unassigned
Referred To:	Not reported
Spill Date:	6/26/2007
Reported to Dept:	8/2/2007
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/17/2007
Remediation Phase:	0
Date Entered In Computer:	6/12/2008
Spill Record Last Update:	6/12/2008
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller City,St,Zip:	New York, NY
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	348800
DEC Memo:	Not reported
Remarks:	M-5142 FOUND APPX 1 GALLON OF DIELECTRIC OIL ON 2 GALLONS OF WATER IN

206663; POWELL ST & LIBERTY AVE (Continued) **S109207947**

STRUCTURE Closed: Agency Approval Not Required

Material:

Site ID:	399201
Operable Unit ID:	1156067
Operable Unit:	01
Material ID:	2146946
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

I99 **CONSOLIDATED EDISON** **MANIFEST** **S108650765**
WSW **LIBERTY AVE & POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.051 mi.
269 ft. **Site 4 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

NY MANIFEST:

EPA ID:	NYP004150199
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	1/11/2007
Trans1 Recv Date:	1/11/2007
Trans2 Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S108650765**

TSD Site Recv Date:	1/12/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000331139FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	1/25/2007
Trans1 Recv Date:	1/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	1/29/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000331309FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N

CONSOLIDATED EDISON (Continued) **S108650765**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	4/27/2007
Trans1 Recv Date:	4/27/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	4/30/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001436047FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-04-27
Trans1 Recv Date:	2007-04-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-04-30
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CONSOLIDATED EDISON (Continued) **S108650765**

TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001436047FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-11
Trans1 Recv Date:	2007-01-11
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000331139FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

CONSOLIDATED EDISON (Continued) **S108650765**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-25
Trans1 Recv Date:	2007-01-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000331309FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

EPA ID:	NYP004147526
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	WOO DONG KIM
Mailing Address:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	1/11/2007
Trans1 Recv Date:	1/11/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	1/12/2007

CONSOLIDATED EDISON (Continued) **S108650765**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000331139FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	1/25/2007
Trans1 Recv Date:	1/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	1/29/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000331309FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

CONSOLIDATED EDISON (Continued) **S108650765**

Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	4/27/2007
Trans1 Recv Date:	4/27/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	4/30/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001436047FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-04-27
Trans1 Recv Date:	2007-04-27
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-04-30
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263

CONSOLIDATED EDISON (Continued) **S108650765**

Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001436047FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-11
Trans1 Recv Date:	2007-01-11
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000331139FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

CONSOLIDATED EDISON (Continued) **S108650765**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-25
Trans1 Recv Date:	2007-01-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-29
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000331309FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

I100 **CON ED - MH 5143** **RCRA-NonGen** **1007206488**
WSW **LIBERTY AVE & POWELL ST** **MANIFEST** **NYP004010690**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
269 ft. **Site 5 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

RCRA-NonGen:

Date form received by agency:	02/28/1998
Facility name:	CON ED - MH 5143
Facility address:	LIBERTY AVE & POWELL ST BROOKLYN, NY 112120000
EPA ID:	NYP004010690
Mailing address:	CONSOLIDATED EDISON INC 4 IRVING PL RM 300 NEW YORK, NY 100030000
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC NEW YORK, NY 100030000
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON ED - MH 5143 (Continued) **1007206488**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/27/1998
Facility name: CON ED - MH 5143
Classification: Not a generator, verified

Date form received by agency: 02/26/1998
Facility name: CON ED - MH 5143
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004010690
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: NYG0905247
Manifest Status: Completed copy
Trans1 State ID: 20854AD
Trans2 State ID: Not reported
Generator Ship Date: 970828
Trans1 Recv Date: 970828
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970828
Part A Recv Date: 970912
Part B Recv Date: 970917
Generator EPA ID: NYP004010690
Trans1 EPA ID: NYD006982359

CON ED - MH 5143 (Continued) **1007206488**

Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 00341
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0904959
Manifest Status: Completed copy
Trans1 State ID: 20856AD
Trans2 State ID: Not reported
Generator Ship Date: 970828
Trans1 Recv Date: 970828
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970829
Part A Recv Date: 970912
Part B Recv Date: 970916
Generator EPA ID: NYP004010690
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 00455
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0903582
Manifest Status: Completed copy
Trans1 State ID: 80336AB
Trans2 State ID: Not reported
Generator Ship Date: 970828
Trans1 Recv Date: 970828
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970829
Part A Recv Date: 970912
Part B Recv Date: 970918
Generator EPA ID: NYP004010690
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00001
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

CON ED - MH 5143 (Continued) **1007206488**

Year: 97

I101
WSW
< 1/8
0.051 mi.
269 ft.

CON EDISON MANHOLE 5142 **RCRA-NonGen** **1010787494**
POWELL ST & LIBERTY AVE **NYP004150199**
BROOKLYN, NY 11201

Site 6 of 11 in cluster I

Relative:
Higher

Actual:
56 ft.

RCRA-NonGen:

Date form received by agency:	03/15/2008
Facility name:	CON EDISON MANHOLE 5142
Facility address:	POWELL ST & LIBERTY AVE BROOKLYN, NY 11201
EPA ID:	NYP004150199
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL D'AGOSTINO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/14/2008
Facility name:	CON EDISON MANHOLE 5142
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

I102 **MH 5142** **NY Spills** **S106008193**
WSW **LIBERTY AV/POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
269 ft. **Site 7 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	148091
Facility Addr2:	Not reported
Facility ID:	0207073
Spill Number:	0207073
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	10/8/2002
Reported to Dept:	10/8/2002
CID:	270
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/23/2003
Remediation Phase:	0
Date Entered In Computer:	10/8/2002
Spill Record Last Update:	1/28/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	126063
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" Con Ed e2mis #145469: 08-OCT-2002 09:40 HRS. UNDER GROUND DEPT. SPLICER L. BILBO EMP# 38673 REPORTS: WHILE ON LOCATION FOR INSPECTION WORK FOUND: APPROX. 3 QT'S OF UNKNOWN OIL ON APPROX. 200 GAL'S OF WATER. RESERVOIR TANK IN STRUCTURE. CUT AND UNCAPPED PRIMARY CABLE ALSO VISIBLE IN STRUCTURE. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THERE IS NOT NOW NOR WAS THERE PRIOR FIRE INVOLVEMENT .THERE IS NOT NOW NOR WAS THERE PRIOR SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL . NO KNOWN SUMP OR PUMP. NO KNOWN SEWER CONNECTION PRESENT. NO PRIVATE PROPERTY AFFECTED . OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 37349 PLACED. 1 LIQ. SAMPLE TAKEN FROM SPILL & MARKED PRIORITY " E " 24 HR. DEMINIMIS PROGRAM. CHAIN OF CUSTODY# CC-08850. SAMPLE TO BE TAKEN TO ASTORIA CHEM. LAB. CLEANUP PENDING TEST RESULTS. UPDATE - 08-OCT-2002 10:24 HRS. CIG MR. K.MCARDLE NOTIFIED UPDATE @ 2128 HRS 10/8 LAB

MH 5142 (Continued) **S106008193**

RESULTS RECEIVED SEQ # 02-09449-001 @ 65 PPM PCB. UPDATE @ 2220 HRS 10/8 EPA #NYP004103420 ISSUED. UPDATE @ 2335 HRS 10/8 REMOVE INCIDENT FROM 24 HOUR PROGRAM DUE TO A LACK OF MAN POWER. CIG P.MCGUIRE NOTIFIED 2338HRS. UPDATE 10/9/02 13:05 HRS. -- J. DEKANCHUK, O.S. BROOKLYN ENV. OPS., REPORTS PARTIAL CLEANUP WAS DONE DUE TO CUT & UNCAPPED FEEDER CABLES IN HOLE. ENV. OPS. CREW DOUBLE WASHED STRUCTURE WITH BIOGEN 760. ZONE MATERIAL BROUGHT BACK TO 3RD AVE YARD UNDER ONE TRIP RULE. ENV. STOP TAG REMAINS IN PLACE. UPDATE #9 REPORTS H.UDIT BAGGED LEAKY CABLE JOINT & LEFT SAME IN HOLE.CLEANUP CREW TO REMOVE. 3C CABLE , THE LEAD WAS PULLED RIGHT OFF UP TO THE DUCT, PAPERS EXPOSED, NEED CABLE TO PULL CABLE OUT. UPDATE 10/10/02 11:00 HRS CABLE REMOVED CABLE TJ 50495 UPDATE**********
10-10-02 23:10HRS A. WALKER REPORTS, AT 23:00HRS ENV OPS CREW REMOVED 330 GALLONS OF LIQUID WITH TANKER. FOUR DRUMS OF LEAD SLUDGE SOLID WASTE AND ONE DRUM OF OIL SOAKED ASBESTOS ARCPROOF REMOVED. DRAIN FOUND SEALED, AND DOUBLE WASHED WITH BULL DOG AND 760. JOB IS 100% COMPLETED. S.PACE 49874.

Remarks: 3 qts on 200 gals water. 145469

Material:

Site ID:	148091
Operable Unit ID:	858806
Operable Unit:	01
Material ID:	517661
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

I103 **CON ED - MH 5143** **FINDS** **1005630189**
WSW **LIBERTY AVE & POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
269 ft. **Site 8 of 11 in cluster I**

Relative:
Higher

FINDS:

Registry ID: 110017253256

Actual:
56 ft.

Environmental Interest/Information System

CON ED - MH 5143 (Continued) **1005630189**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

I104 **CON EDISON** **FINDS** **1011405690**
WSW **POWELL ST & LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.051 mi.
269 ft. **Site 9 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

FINDS:

Registry ID: 110035431672

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

I105 **MANHOLE 5143** **NY Spills** **S107522308**
WSW **LIBERTY AVE & POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
269 ft. **Site 10 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	358482
Facility Addr2:	Not reported
Facility ID:	0512277
Spill Number:	0512277
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	1/23/2006
Reported to Dept:	1/23/2006
CID:	71
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

MANHOLE 5143 (Continued) **S107522308**

Spill Closed Dt:	6/14/2006
Remediation Phase:	0
Date Entered In Computer:	1/24/2006
Spill Record Last Update:	7/17/2006
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10020
Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	308491
DEC Memo:	06/14/06 - See e-docs for Con Ed report detailing cleanup and closure. 162676. 01/23/2006 10:12 HRS. P. SARDONE #75445, SPLICER WITH BROOKLYN UNDERGROUND, REPORTS ON LOCATION TO SERVICE JOINT REGULATORS (ACCT # C- 3255) AT 10:00 HRS. AND FOUND APPROX. 5 GAL. UNKNOWN OIL ON APPROX. 50 GAL. WATER IN MH-5143. NO LEAKING EQUIPMENT SEEN IN STRUCTURE. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR SMOKE INVOLVED. ENV. STOP TAG # 46529 PLACED. LIQUID SAMPLE TAKEN. "E" PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # EE-02529. SAMPLE WILL BE DELIVERED TO CHEM LAB BY COURIER. CLEANUP PENDING PCB RESULTS. PARKING RESTRICTIONS: N.P. 8AM - 6PM, MON - FRI. -- W. WAINWRIGHT #17344 -- 23-JAN-2006 2030HRS. Results of Analysis. TOTAL PCB 609 ppm THIS INCIDENT TO BE TAKEN OFF THE THE 72 HOUR CLOCK , WILL NOT MEET THE TIME CRITERIA. BORCHERDINGC
Remarks:	FLUID FOUND IN MANHOLE. CLEAN UP PENDING. CON ED REF 162676

Material:

Site ID:	358482
Operable Unit ID:	1115721
Operable Unit:	01
Material ID:	2105825
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

I106 **MANHOLE 5143** **NY Spills** **S108057664**
WSW **LIBERTY AVENUE & POWELL STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
269 ft. **Site 11 of 11 in cluster I**

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	365815
Facility Addr2:	Not reported
Facility ID:	0603155
Spill Number:	0603155
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	6/21/2006
Reported to Dept:	6/22/2006
CID:	77
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/16/2007
Remediation Phase:	0
Date Entered In Computer:	6/22/2006
Spill Record Last Update:	2/16/2007
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Company:	Not reported
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	315926
DEC Memo:	02/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 200737. see eDocs.
Remarks:	1/2 GAL OF UNKN OIL ON 50 GALS. LAB RESULT CAN BACK OVER 500 PPM, REPORTABLE SPILL. CON ED REF 200737. NO TO 5 QUESTIONS.

Material:

Site ID:	365815
Operable Unit ID:	1123789
Operable Unit:	01
Material ID:	2113266
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

MANHOLE 5143 (Continued) **S108057664**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Y107 **NYCHA - WOODSON** **RCRA-NonGen** **1001223892**
WSW **403 POWELL ST** **FINDS** **NYR000051086**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
271 ft. **Site 1 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - WOODSON
Facility address: 403 POWELL ST
BROOKLYN, NY 11212
EPA ID: NYR000051086
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: Not reported
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator

NYCHA - WOODSON (Continued) **1001223892**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - WOODSON
Classification: Not a generator, verified

Date form received by agency: 04/03/1998
Facility name: NYCHA - WOODSON
Classification: Not a generator, verified

Date form received by agency: 02/27/1998
Facility name: NYCHA - WOODSON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004540836

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Y108 **WOODSON HOUSES** **UST** **U000410747**
WSW **403 POWELL STREET** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.051 mi.
271 ft. **Site 2 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

UST:

Facility Id:	2-474290
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2014/03/28
UTM X:	592764.75416999997
UTM Y:	4502037.1171800001

Affiliation Records:

Site Id:	20898
Affiliation Type:	On-Site Operator
Company Name:	WOODSON HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	5/15/2008

Site Id:	20898
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPARTMENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey
Date Last Modified:	1/14/2009

Site Id:	20898
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR

WOODSON HOUSES (Continued) **U000410747**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/19/2010

Site Id:	20898
Affiliation Type:	Owner
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	FUEL OIL REMEDIATION COORDINATOR
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F05 - Pipe External Protection - Jacketed
L08 - Piping Leak Detection - Tank Top Sump
B09 - Tank External Protection - Urethane
I03 - Overfill - Automatic Shut-Off
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Info:

Site ID:	20898

WOODSON HOUSES (Continued) **U000410747**

Tank Number:	1
Tank ID:	58493
Tank Status:	In Service
Tank Model:	108
Pipe Model:	E
Install Date:	7/1/1999
Capacity Gallons:	12000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	0
Date Test:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008
Site ID:	20898
Tank Number:	OLD 1
Tank ID:	37641
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1949
Capacity Gallons:	25000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	6/1/1999
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	aaanasta
Last Modified:	4/28/2004

HIST UST:

PBS Number:	2-474290
SPDES Number:	Not reported
Emergency Contact:	EMERGENCY SERVICE DEPT.
Emergency Telephone:	(212) 289-3940
Operator:	MR. LUIS PONCE
Operator Telephone:	(718) 707-5725
Owner Name:	NEW YORK CITY HOUSING AUTHORITY
Owner Address:	23-02 49TH AVENUE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 707-5725
Owner Type:	Local Government
Owner Subtype:	51
Mailing Name:	NEW YORK CITY HOUSING AUTHORITY
Mailing Address:	23-02 49TH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	LUIS PONCE
Mailing Telephone:	(718) 707-5725
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is

WOODSON HOUSES (Continued) **U000410747**

	greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	403 POWELL STREET (MGMT. OFFICE)
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	06/28/2001
Expiration Date:	03/28/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	12000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19990701
Capacity (gals):	12000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Fiberglass coated steel
Tank Internal:	Not reported
Tank External:	Fiberglass
Pipe Location:	Underground
Pipe Type:	FIBERGLASS REINFORCED PLASTIC
Pipe Internal:	Other
Pipe External:	Other
Second Containment:	Vault (w/access)
Leak Detection:	14
Overfill Prot:	High Level Alarm
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	OLD 1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed

WOODSON HOUSES (Continued) **U000410747**

Install Date:	19491201
Capacity (gals):	25000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	06/01/1990
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Y109 **WOODSON HOUSING** **LTANKS** **S103238311**
WSW **403 POWELL ST** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
271 ft. **Site 3 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

LTANKS:

Site ID:	331459
Spill No:	9800758
Spill Date:	4/17/1998
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/23/1999
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	4/17/1998
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/17/1998
Spill Record Last Update:	3/23/1999
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-

WOODSON HOUSING (Continued) **S103238311**

Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266592
Remarks:	TANK WILL BE EMPTIED AND INVESTIGATED

Material:

Site ID:	331459
Operable Unit ID:	1061389
Operable Unit:	01
Material ID:	322706
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	331459
Spill Tank Test:	1545791
Tank Number:	1
Tank Size:	25000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

HIST LTANKS:

Region of Spill:	2
Spill Number:	9800758
Spill Date:	04/17/1998
Spill Time:	12:55
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gallons
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	03/23/99
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported

WOODSON HOUSING (Continued) **S103238311**

Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 04/17/98
Reported to Department Time: 13:17
SWIS: 61
Spiller Contact: FRANK OCELLO
Spiller Phone: (212) 306-3233
Spiller Extention: Not reported
Spiller Name: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: MANHATTEN, NY 10007-
Spiller Cleanup Date: / /
Facility Contact: FRANK OCELLO
Facility Phone: (212) 306-3233
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: -474290
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 04/17/98
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/23/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 1
Tank Size: 25000
Test Method: Horner EZ Check
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 3/23/99 -Saccacio- Subsequent tank test failure. Previous tank test failure 9009729)to remain open. Spill closed 3/23/99.
Spill Cause: TANK WILL BE EMPTIED AND INVESTIGATED

Y110 **WOODSON HOUSES -NYCHA** **NY Spills** **S103937873**
WSW **403 POWELL ST** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
271 ft. **Site 4 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	331460
Facility Addr2:	Not reported
Facility ID:	9902415
Spill Number:	9902415
Facility Type:	ER
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Spill Date:	6/2/1999
Reported to Dept:	6/2/1999
CID:	390
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/24/2005
Remediation Phase:	0
Date Entered In Computer:	6/2/1999
Spill Record Last Update:	10/27/2005
Spiller Name:	EDWARD MALONE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY
Spiller Company:	001
Contact Name:	FRANK OCELLO
Contact Phone:	(212) 306-3229
DEC Region:	2
DER Facility ID:	266592
DEC Memo:	10/24/05: Have reviewed ISRP dated June 2005 submitted by Gannett Fleming, in consultation with supervisor Jonathan Kolleeny. Based on soil boring and GW sample analysis summarized in the report it has been determined that this site poses no immediate threat to the surrounding area. No VOCs or PAHs were detected. Ok to close spill. S.Kraszewski
Remarks:	WHILE REMOVING THE TANK FROM THE GROUND CONTAMINATED SOIL WAS NOTICED UNDERNEATH STATE ENVIRONMENTAL IS IN THE PROCESS OF REMOVING THE SOIL FOR DISPOSAL

Material:

Site ID:	331460
Operable Unit ID:	1077182
Operable Unit:	01
Material ID:	305921
Material Code:	0003
Material Name:	#6 Fuel Oil
Case No.:	Not reported

WOODSON HOUSES -NYCHA (Continued) **S103937873**

Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	331460
Operable Unit ID:	1077182
Operable Unit:	01
Material ID:	305919
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	331460
Operable Unit ID:	1077182
Operable Unit:	01
Material ID:	305920
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9902415
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported

WOODSON HOUSES -NYCHA (Continued) **S103937873**

Spill Date/Time: 06/02/1999 08:00
Reported to Dept Date/Time: 06/02/99 15:07
SWIS: 61
Spiller Name: NYC HOUSING AUTHORITY
Spiller Contact: EDWARD MALONE
Spiller Phone: (212) 306-8480
Spiller Contact: FRANK OCELLO
Spiller Phone: (212) 306-3229
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: MANHATTAN, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: -474290
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/02/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/03/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons

WOODSON HOUSES -NYCHA (Continued) **S103937873**

Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #6 FUEL OIL
Class Type: #6 FUEL OIL
Times Material Entry In File: 2190
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: WHILE REMOVING THE TANK FROM THE GROUND CONTAMINATED SOIL WAS NOTICED UNDERNEATH STATE ENVIRONMENTAL IS IN THE PROCESS OF REMOVING THE SOIL FOR DISPOSAL

Y111 **WOODSON HOUSES** **LTANKS** **S100146596**
WSW **403 POWELL STREET** **HIST LTANKS** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.051 mi.
271 ft. **Site 5 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

LTANKS:
Site ID: 101484
Spill No: 9009729
Spill Date: 12/7/1990
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/24/2005
Facility Addr2: Not reported
Cleanup Ceased: 4/27/1995
Cleanup Meets Standard: True
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 12/7/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/12/1990
Spill Record Last Update: 10/24/2005
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY 10007-

WOODSON HOUSES (Continued) **S100146596**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266592
Remarks:	25K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK,TO PUMP TANK OUT & INVESTIGATE, TO REPAIR & RETEST. SEE SPILL # 9410324

Material:

Site ID:	101484
Operable Unit ID:	946759
Operable Unit:	01
Material ID:	429930
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	101484
Spill Tank Test:	1538004
Tank Number:	001
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	2
Spill Number:	9009729
Spill Date:	12/07/1990
Spill Time:	12:15
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	04/27/95
Cleanup Meets Standard:	True
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported

WOODSON HOUSES (Continued) **S100146596**

Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 12/07/90
Reported to Department Time: 12:30
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY 10007-
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (212) 306-3142
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: 2-474290
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 12/12/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/23/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 3/23/99 -Saccacio- Subsequent tank test failure s) 9713498 9410324) closed and refered to this spill. Spill reopened to reflect first TTF in database.
Spill Cause: 25K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK,TO PUMP TANK OUT INVESTIGATE, TO REPAIR RETEST. SEE SPILL 9410324

Y112 **WOODSON HOUSES** **LTANKS** **S101341135**
WSW **403 POWELL STREET** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
271 ft. **Site 6 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

LTANKS:

Site ID:	101485
Spill No:	9410324
Spill Date:	11/2/1994
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/23/1999
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	11/3/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/7/1994
Spill Record Last Update:	10/21/2005
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266592
Remarks:	WILL EMPTY/REPAIR/RETEST

Material:

Site ID:	101485
Operable Unit ID:	1008078
Operable Unit:	01
Material ID:	376201
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

WOODSON HOUSES (Continued) **S101341135**

Tank Test:

Site ID:	101485
Spill Tank Test:	1543309
Tank Number:	001
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	2
Spill Number:	9410324
Spill Date:	11/02/1994
Spill Time:	16:00
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	03/23/99
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	11/03/94
Reported to Department Time:	09:56
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(212) 306-3142
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	-474290
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False

WOODSON HOUSES (Continued) **S101341135**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 11/07/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/23/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: TTF. 3/23/99 -Saccacio- Subsequent tank test failure. Previous tank test failure 9009729)to remain open. Spill closed 3/23/99.
Spill Cause: WILL EMPTY/REPAIR/RETEST

M113 **CONSOLIDATED EDISON** **MANIFEST** **S108933360**
East **SNEDIKER AVE & DUMONT AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
272 ft. **Site 6 of 8 in cluster M**

Relative:
Lower

Actual:
36 ft.

NY MANIFEST:
EPA ID: NYP004153540
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CONSOLIDATED EDISON (Continued) **S108933360**

Generator Ship Date:	9/2/2007
Trans1 Recv Date:	9/2/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	9/4/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004153540
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	300
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001451484FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	9/2/2007
Trans1 Recv Date:	9/2/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	9/4/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004153540
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001451484FLE
Import Ind:	N
Export Ind:	N

CONSOLIDATED EDISON (Continued) **S108933360**

Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-09-02
Trans1 Recv Date:	2007-09-02
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-09-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004153540
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001451484FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-09-02
Trans1 Recv Date:	2007-09-02
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-09-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S108933360**

Generator EPA ID:	NYP004153540
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	300.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001451484FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Y114 **NYCHA - WOODSON HOUSES** **RCRA-NonGen** **1001493638**
WSW **393 POWELL ST** **FINDS** **NYR000075291**
< 1/8 **BROOKLYN, NY 11212**
0.052 mi.
273 ft. **Site 7 of 8 in cluster Y**

Relative:
Lower

Actual:
34 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCHA - WOODSON HOUSES
Facility address:	393 POWELL ST BROOKLYN, NY 112122516
EPA ID:	NYR000075291
Mailing address:	BROADWAY NEW YORK, NY 100072516
Contact:	FRANK OCELLO
Contact address:	BROADWAY NEW YORK, NY 100072516
Contact country:	US
Contact telephone:	(212) 306-3229
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYCHA
Owner/operator address:	250 BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	(212) 306-3229
Legal status:	Municipal
Owner/Operator Type:	Owner

NYCHA - WOODSON HOUSES (Continued) **1001493638**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - WOODSON HOUSES
Classification: Not a generator, verified

Date form received by agency: 08/12/1999
Facility name: NYCHA - WOODSON HOUSES
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004555589

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

L115 **MTA NYCT - JUNIUS ST SIGNAL TOWER** **RCRA-NonGen** **1005417346**
East **LIVONIA & SNEDIKER AVE** **FINDS** **NYR000104729**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.052 mi.
276 ft. **Site 5 of 7 in cluster L**

Relative:
Lower

Actual:
33 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - JUNIUS ST SIGNAL TOWER
Facility address:	LIVONIA & SNEDIKER AVE BROOKLYN, NY 11207
EPA ID:	NYR000104729
Mailing address:	BROADWAY 2ND FL NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 2ND FL NEW YORK, NY 10004
Contact country:	US
Contact telephone:	(646) 252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 2ND FL NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3500
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 2ND FL NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	(646) 252-3500
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

MTA NYCT - JUNIUS ST SIGNAL TOWER (Continued) **1005417346**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT - JUNIUS ST SIGNAL TOWER
Classification: Not a generator, verified

Date form received by agency: 03/21/2002
Facility name: MTA NYCT - JUNIUS ST SIGNAL TOWER
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012216495

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000104729
Country: USA
Mailing Name: NYC TRANSIT AUTHORITY ENVIRO ENGINEERING
Mailing Contact: NYC TRANSIT AUTHORITY ENVIRO ENGINEERING
Mailing Address: 2 BROAD 2ND FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 646-252-3500

Document ID: NYG3213117
Manifest Status: Not reported
Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 03/22/2002
Trans1 Recv Date: 03/22/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/28/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000104729
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: PC4339NY

MTA NYCT - JUNIUS ST SIGNAL TOWER (Continued) **1005417346**

Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00600
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	02

L116 **MANHOLE 3941** **NY Spills** **S109373683**
East **LAVONIA AVE & SNEDKIER AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
276 ft. **Site 6 of 7 in cluster L**

Relative:
Lower

Actual:
33 ft.

NY Spills:

Site ID:	406650
Facility Addr2:	Not reported
Facility ID:	0809205
Spill Number:	0809205
Facility Type:	ER
SWIS:	2401
Investigator:	asnagi
Referred To:	Not reported
Spill Date:	11/14/2008
Reported to Dept:	11/14/2008
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/22/2008
Remediation Phase:	0
Date Entered In Computer:	11/14/2008
Spill Record Last Update:	12/22/2008
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	LAVONIA AVE & SNEDKIER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	355914
DEC Memo:	12/22/08 - See eDocs for Con Ed report detailing cleanup and closure.
Remarks:	A pump failure caused oil to spill onto the floor of the manhole. Clean up is progress.

Material:

Site ID:	406650
Operable Unit ID:	1163228

MANHOLE 3941 (Continued) **S109373683**

Operable Unit: 01
Material ID: 2154539
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

L117 **SB 64021** **NY Spills** **S104881381**
East **LIVONIA AV/SNEDIKER AV** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
276 ft. **Site 7 of 7 in cluster L**

Relative:
Lower

Actual:
33 ft.

NY Spills:
Site ID: 218257
Facility Addr2: Not reported
Facility ID: 0010874
Spill Number: 0010874
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 1/3/2001
Reported to Dept: 1/3/2001
CID: 270
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 5/30/2001
Remediation Phase: 0
Date Entered In Computer: 1/3/2001

SB 64021 (Continued) **S104881381**

Spill Record Last Update:	8/14/2001
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	180581
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" CON ED E2MIS REPORT 1-03-01 4gals. of unknown oil and approx. 1 gal. water in SB 64021. Source is unknown, but appears to be vehicle transmission fluid. No sewers or waterways affected. Liquid sample taken on emergency priority. LSN 01-00038 Oil ID analysis indicates the sample similar to lubricating fluid. LSN 01-0037 PCB <1.0ppm 1-09-01 Cleanup completed, tag removed. Structure was double washed with slix. Liquids were removed using coagulent and diapers. No lekaing company equipment. Incident closed.
Remarks:	sample taken clean up pending

Material:

Site ID:	218257
Operable Unit ID:	832152
Operable Unit:	01
Material ID:	544756
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0010874
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported

SB 64021 (Continued) **S104881381**

Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/03/2001 09:15
Reported to Dept Date/Time: 01/03/01 10:37
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/30/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/03/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/14/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 4
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: CON ED E2MIS REPORT 1-03-01 4gals. of unknown oil and approx. 1 gal. water in SB 64021. Source is unknown, but appears to be vehicle transmission fluid. No

SB 64021 (Continued) **S104881381**

sewers or waterways affected. Liquid sample taken on emergency priority.
LSN 01-00038Oil ID analysis indicates the sample similar to lubricating fluid.
LSN 01-0037 PCB <1.0ppm 1-09-01 Cleanup completed, tag removed.
Structure was double washed with slix. Liquids were removed using coagulent and diapers. No lekaing company equipment. Incident closed.

Remark: sample taken clean up pending

X118 **SETH LOW HOUSES** **UST** **U004064341**
WSW **180 POWELL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.053 mi.
278 ft. **Site 3 of 5 in cluster X**

Relative:
Higher

Actual:
44 ft.

UST:

Facility Id:	2-474185
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2014/03/28
UTM X:	592663.49713999999
UTM Y:	4502520.2312200004

Affiliation Records:

Site Id:	20888
Affiliation Type:	On-Site Operator
Company Name:	SETH LOW HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008

Site Id:	20888
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	bkfalvey

SETH LOW HOUSES (Continued) **U004064341**

Date Last Modified: 6/1/2009

Site Id: 20888
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/19/2010

Site Id: 20888
Affiliation Type: Owner
Company Name: NEW YORK CITY HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/19/2011

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F06 - Pipe External Protection - Wrapped
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground

SETH LOW HOUSES (Continued) **U004064341**

C01 - Pipe Location - Aboveground
L08 - Piping Leak Detection - Tank Top Sump
F05 - Pipe External Protection - Jacketed
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction
E10 - Piping Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B09 - Tank External Protection - Urethane
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
D11 - Pipe Type - Flexible Piping
K00 - Spill Prevention - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Info:

Site ID:	20888
Tank Number:	1
Tank ID:	58781
Tank Status:	In Service
Tank Model:	108
Pipe Model:	E
Install Date:	11/1/1999
Capacity Gallons:	15000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	0
Date Test:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008
Site ID:	20888
Tank Number:	OLD 1
Tank ID:	37616
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1967
Capacity Gallons:	20000
Tightness Test Method:	NN

SETH LOW HOUSES (Continued) **U004064341**

Next Test Date:	Not reported
Date Tank Closed:	11/1/1999
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	20888
Tank Number:	OLD 2
Tank ID:	39937
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1967
Capacity Gallons:	20000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	11/1/1999
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

X119 **SETH LOW HOUSES -NYCHA** **LTANKS** **S101658382**
WSW **180 POWELL STREET** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY** **NY Spills**
0.053 mi. **NY Hist Spills**
278 ft. **Site 4 of 5 in cluster X**

Relative:
Higher

Actual:
44 ft.

LTANKS:

Site ID:	249122
Spill No:	9503722
Spill Date:	6/26/1995
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/7/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	6/26/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/28/1995

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Spill Record Last Update: 2/7/2006
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 204278
Remarks: TANK #1 COULDN'T HOLD VACUUM. TANK #2 - LEAK RATE OF 3.5

Material:
Site ID: 249122
Operable Unit ID: 1018188
Operable Unit: 01
Material ID: 365230
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 249122
Spill Tank Test: 1543949
Tank Number: 001
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown
Site ID: 249122
Spill Tank Test: 1543950
Tank Number: 002
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Site ID: 249121
Spill No: 9104796
Spill Date: 8/2/1991
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/28/1995
Facility Addr2:	Not reported
Cleanup Ceased:	6/28/1995
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	8/2/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/7/1991
Spill Record Last Update:	1/27/2003
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204278
Remarks:	20K TANK (#2) FAILED HORNER EZY CHECK,VISUAL GROSS LEAK,PLUMBING LEAK,SYSTEM TEST,WILL EXCAVATE,ISOLATE & RETEST. CLOSE OUT-SEE SPILL #9503722 (SUBSEQUENT TANK TEST FAILURE)

Material:

Site ID:	249121
Operable Unit ID:	958855
Operable Unit:	01
Material ID:	423855
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	249121
Spill Tank Test:	1538845
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown
Site ID:	249121
Spill Tank Test:	1538844
Tank Number:	001
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	2
Spill Number:	9503722
Spill Date:	06/26/1995
Spill Time:	11:00
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	06/26/95
Reported to Department Time:	14:25
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(212) 306-3142
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	2-474185
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 06/28/95
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/07/95
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
PBS Number: Not reported
Tank Number: 002
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: TANK 1 COULDN T HOLD VACUUM. TANK 2 - LEAK RATE OF 3.5

Region of Spill: 2
Spill Number: 9104796
Spill Date: 08/02/1991
Spill Time: 10:30
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 06/28/95
Cleanup Ceased: 06/28/95
Cleanup Meets Standard: True
Investigator: HEALY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 08/02/91
Reported to Department Time: 16:04
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYCHA
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, N.Y.
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (212) 306-3142
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: 2-474185
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 08/07/91
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 06/28/95
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported
PBS Number: Not reported
Tank Number: 002
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
DEC Remarks: Not reported
Spill Cause: 20K TANK 2) FAILED HORNER EZY CHECK,VISUAL GROSS LEAK,PLUMBING LEAK,SYSTEM

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

TEST,WILL EXCAVATE,ISOLATE RETEST. CLOSE OUT-SEE SPILL 9503722 SUBSEQUENT TANK TEST FAILURE)

NY Spills:

Site ID:	146499
Facility Addr2:	Not reported
Facility ID:	9407081
Spill Number:	9407081
Facility Type:	ER
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Spill Date:	8/25/1994
Reported to Dept:	8/25/1994
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/7/2006
Remediation Phase:	0
Date Entered In Computer:	8/25/1994
Spill Record Last Update:	2/7/2006
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	204278
DEC Memo:	11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/07/06: This spill closed to consolidate with open spill #9906013. - SK
Remarks:	FUEL LINE FAILURE - BLUE WATER ENVIRONMENTAL (TOM SPATAFORA 516-752-2145) AND NYCHA PERSONNEL DOING CLEANUP. APPROXIMATELY 30 TO 40 CUBIC YARDS OF CONTAMINATED SOIL.

Material:

Site ID:	146499
Operable Unit ID:	1004507
Operable Unit:	01
Material ID:	380100
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	146499
Spill Tank Test:	1543080
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	250473
Facility Addr2:	Not reported
Facility ID:	0209860
Spill Number:	0209860
Facility Type:	ER
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Spill Date:	12/28/2002
Reported to Dept:	12/28/2002
CID:	398
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	12/30/2002
Remediation Phase:	0
Date Entered In Computer:	12/28/2002
Spill Record Last Update:	12/30/2002
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTH
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	CHARLES MCINNIS
Contact Phone:	(718) 707-5725
DEC Region:	2
DER Facility ID:	204278
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE" 12/30/2002 TIPPLE--THE EXISTING REMEDIATION SYSTEM LOCATED IN BOILER ROOM HAD A HIGH FLOAT ALARM FAILURE CAUSING AN OIL WATER MIX TO SPILL ONTO THE FLOOR. CLEAN VENTURES WERE CALLED AND CLEANED THE SPILL FROM THE FLOOR, THE SYSTEM HAS BEEN TURNED OFF UNTIL REPAIRS CAN BE MADE AND THE RETENTION TANK EMPTIED. THIS WORK IS

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Remarks: SCHEDULED TO BE COMPLETED BY END OF BUSINESS DECEMBER 31. oil and water changer failed. clean up crew enroute. oil and water mixture may of been 30-40 gals.

Material:
Site ID: 250473
Operable Unit ID: 861096
Operable Unit: 01
Material ID: 513280
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:
Region of Spill: 2
Spill Number: 9407081
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 08/25/1994 09:45
Reported to Dept Date/Time: 08/25/94 09:50
SWIS: 61
Spiller Name: NYC HOUSING AUTHORITY
Spiller Contact: Not reported
Spiller Phone: (212) 306-3142
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 02

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Spill Notifier: Other
PBS Number: 2-474185
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/25/94
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: SOIL.
Remark: FUEL LINE FAILURE - BLUE WATER ENVIRONMENTAL TOM SPATAFORA 516-752-2145) AND NYCHA PERSONNEL DOING CLEANUP. APPROXIMATELY 30 TO 40 CUBIC YARDS OF CONTAMINATED SOIL.

X120 **SETH LOW HOUSES** **AST** **A100295998**
WSW **180 POWELL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.053 mi.
278 ft. **Site 5 of 5 in cluster X**

Relative:
Higher

Actual:
44 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-474185
Program Type: PBS
UTM X: 592663.49713999999

SETH LOW HOUSES (Continued) **A100295998**

UTM Y: 4502520.2312200004
Expiration Date: 2014/03/28

Affiliation Records:

Site Id: 20888
Affiliation Type: On-Site Operator
Company Name: SETH LOW HOUSES
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION UNIT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/31/2008

Site Id: 20888
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 707-5900
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: bkfalvey
Date Last Modified: 6/1/2009

Site Id: 20888
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/19/2010

SETH LOW HOUSES (Continued) **A100295998**

Site Id:	20888
Affiliation Type:	Owner
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	FUEL OIL REMEDIATION COORDINATOR
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F06 - Pipe External Protection - Wrapped
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
C01 - Pipe Location - Aboveground
L08 - Piping Leak Detection - Tank Top Sump
F05 - Pipe External Protection - Jacketed
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction
E10 - Piping Secondary Containment - Impervious Underlayment
L09 - Piping Leak Detection - Exempt Suction Piping
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B09 - Tank External Protection - Urethane

SETH LOW HOUSES (Continued) **A100295998**

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
D11 - Pipe Type - Flexible Piping
K00 - Spill Prevention - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Info:

Tank Number:	W/O 1
Tank Id:	208302
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	201
Pipe Model:	Not reported
Install Date:	1/4/1997
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008

M121 **FORMER GARAGE FACILITY** **UST** **U003065908**
East **403-19 SNEDIKER AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.053 mi.
278 ft. **Site 7 of 8 in cluster M**

Relative:
Lower

Actual:
35 ft.

UST:

Facility Id:	2-602615
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592996.54700999998
UTM Y:	4502103.5405700002

Affiliation Records:

Site Id:	24572
Affiliation Type:	Mail Contact
Company Name:	CA RICH CONSULTANTS, INC.
Contact Type:	Not reported
Contact Name:	RICHARD IZZO
Address1:	404 GLEN COVE AVENUE
Address2:	Not reported
City:	SEA CLIFF
State:	NY
Zip Code:	11579
Country Code:	001
Phone:	(516) 674-3889
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported

FORMER GARAGE FACILITY (Continued) **U003065908**

Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	24572
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY HOUSING PRESERVATION DEPARTMENT
Contact Type:	Not reported
Contact Name:	BEVERLY REITH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 386-6451
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	24572
Affiliation Type:	On-Site Operator
Company Name:	FORMER GARAGE FACILITY
Contact Type:	Not reported
Contact Name:	BEVERLY REITH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 386-6451
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	24572
Affiliation Type:	Owner
Company Name:	NEW YORK CITY HOUSING PRESERVATION DEPARTMENT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	100 GOLD STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 386-6451
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

FORMER GARAGE FACILITY (Continued) **U003065908**

Equipment Records:

B00 - Tank External Protection - None
J02 - Dispenser - Suction
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
I00 - Overfill - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
I00 - Overfill - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

Tank Info:

Site ID:	24572
Tank Number:	001
Tank ID:	50727
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	2/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	24572
Tank Number:	002
Tank ID:	50728
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported

FORMER GARAGE FACILITY (Continued) **U003065908**

Capacity Gallons:	1000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	2/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	24572
Tank Number:	003
Tank ID:	50729
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	2/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-602615
SPDES Number:	Not reported
Emergency Contact:	BEVERLY REITH
Emergency Telephone:	(212) 386-6451
Operator:	BEVERLY REITH
Operator Telephone:	(212) 386-6451
Owner Name:	NEW YORK CITY HOUSING PRESERVATION DEPARTMENT
Owner Address:	100 GOLD STREET
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Telephone:	(212) 386-6451
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	CA RICH CONSULTANTS, INC.
Mailing Address:	404 GLEN COVE AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SEA CLIFF, NY 11579
Mailing Contact:	RICHARD IZZO
Mailing Telephone:	(516) 674-3889
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported

FORMER GARAGE FACILITY (Continued) **U003065908**

Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	02/13/2001
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	02/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	None

FORMER GARAGE FACILITY (Continued) **U003065908**

Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	02/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	None
Pipe Type:	NONE
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	02/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

M122 **403-19 SNEDIKER AVE** **LTANKS** **S104276775**
East **403-19 SNEDIKER AVE** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
278 ft. **Site 8 of 8 in cluster M**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	100094
Spill No:	9602568
Spill Date:	3/1/1996
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/18/2005

403-19 SNEDIKER AVE (Continued) **S104276775**

Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	TLDiaz
Referred To:	Not reported
Reported to Dept:	5/23/1996
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/23/1996
Spill Record Last Update:	9/7/2005
Spiller Name:	NYC HOUSING
Spiller Company:	403-19 SNEDIKER AVE
Spiller Address:	403-19 SNEDIKER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	NYC HOUSING
Spiller Phone:	(212) 386-6400
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	88914
Remarks:	caller removed tank, and found contamination.

Material:

Site ID:	100094
Operable Unit ID:	1030114
Operable Unit:	01
Material ID:	352387
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

403-19 SNEDIKER AVE (Continued) **S104276775**

HIST LTANKS:

Region of Spill:	2
Spill Number:	9602568
Spill Date:	03/01/1996
Spill Time:	12:00
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	TIBBE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	05/23/96
Reported to Department Time:	08:49
SWIS:	61
Spiller Contact:	NYC HOUSING
Spiller Phone:	(212) 386-6400
Spiller Extention:	Not reported
Spiller Name:	403-19 SNEDIKER AVE
Spiller Address:	403-19 SNEDIKER AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Cleanup Date:	/ /
Facility Contact:	NYC HOUSING
Facility Phone:	(212) 386-6400
Facility Extention:	Not reported
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	05/23/96
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	06/27/96
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported

403-19 SNEDIKER AVE (Continued) **S104276775**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: caller removed tank, and found contamination.

Z123 **VAULT VS6788** **NY Spills** **S106470437**
WSW **BLAKE AVE/POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
278 ft. **Site 1 of 2 in cluster Z**

Relative:
Lower

Actual:
38 ft.

NY Spills:
Site ID: 213525
Facility Addr2: Not reported
Facility ID: 0403292
Spill Number: 0403292
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 6/26/2004
Reported to Dept: 6/26/2004
CID: 64
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 9/23/2004
Remediation Phase: 0
Date Entered In Computer: 6/26/2004
Spill Record Last Update: 9/23/2004
Spiller Name: ERT DESK
Spiller Company: CON ED
Spiller Address: 1 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Region: 2

VAULT VS6788 (Continued) **S106470437**

DER Facility ID: 176902
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" e2mis no. 154054: TRANSFORMER TOP OF VS6788 EXPLODED CAUSING APPROX 5-GALLONS OF OIL TO SPILL ONTO SIDEWALK, 6 FEET BY 6 FEET AREA OF GRASS, SIDE OF BUILDING AND TREE IN FRONT OF 420 BLAKE AVE. RECORDS SHOW 10PPM DATED 3/31/95. FIRE DEPT WAS ON LOCATION WHEN CREW ARRIVED, BUT NO FIRE OR SMOKE. UNABLE TO TAKE SAMPLE AND PLACE ENVIR TAG DUE TO HIGH VOLTAGE ON FEEDER. 6/26/04 07:30HRS A. WALKER REPORTS CLEANING OF SIDEWALK AND FENCE IN PROGRESS. Lab Sequence Number: 04-04999-001 PCB <1 ppm. Several limbs were cut from a tree near the transformer that had oil on them. The side of the building was washed with slicks. About an 8' x 8' square of sod was removed from the area between the transformer and the side of the building. Env. Ops. removed 8 barrels of Non-Hazardous material to 3rd Avenue yard via the rack body truck. VS 6788 was partially cleaned and the oil was drained from the transformer. VS 6788 was found to have a concrete sump. THE MFG TAG STATES UNIT HOLDS 290 GAL AND 200 GAL WERE DRAINED FROM THE UNIT, WHICH LEAVES 90 GAL SPILLED. TAG REMAINS IN PLACE PENDING REMOVAL OF UNIT. Update - 7/6/04 - 1220hrs An additional 10 gallons of oil removed from unit. Unit has been removed from structure and env. ops on location performing clean up of structure. UPDATE: 7/6/04 - 1350 C. LABARBERA - ENV. OPS., REPORTS TRANSFORMER REMOVED BY TRANSFORMER GANG. STRUCTURE DOUBLE WASHED WITH BIO GEN 760. SUMP FOUND CEMENTED.
Remarks: Top of transformer exploded. Tree,land,bldg were effected. Update 6/26/04 @ 1722hrs: Transformer holds 290 - drained 200 so there is an 85 gallon descrepancy. An additional 85 gallons was spilled.

Material:
Site ID: 213525
Operable Unit ID: 886706
Operable Unit: 01
Material ID: 490883
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Y124 **VAULT 4506** **NY Spills** **S103938268**
WSW **DUMONT AVE / POWELL ST** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
279 ft. **Site 8 of 8 in cluster Y**

Relative:
Lower

Actual:
35 ft.

NY Spills:

Site ID:	221189
Facility Addr2:	Not reported
Facility ID:	9902828
Spill Number:	9902828
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	6/11/1999
Reported to Dept:	6/11/1999
CID:	312
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/15/2002
Remediation Phase:	0
Date Entered In Computer:	6/11/1999
Spill Record Last Update:	4/15/2002
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	182928
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" e2mis no. 125-512: IT11JUN-1999 0950HRS VAVALLO O/S EQUIPT GP REPORTS FOUND 20 GALLONS OF OIL IN VS 4506 NO SEWERS OR WATERWAYS AFFECTED DOES NOT SEE SEWER CONECTION IN HOLE . CAN NOT SEE PUMP. HE WILL DO PRESSURE TEST AND TAKE SAMPLE SHORTLY. HE DID HANG A TAG #06801. FOUND WHILE DOING RETRO FILL. UPDATE:11-JUN-1999 1102HRS THERE IS DIRT IN THE HOLE AND THE OIL IS SOAKED INTO IT.THE WALLS ARE STAINED. HISTORICAL RECORDS SHOW 52PPM AS PER V.VAVALLO.THERE IS A SOIL DRAIN IN THIS STRUCTURE. THIS IS ON FEEDER 3B87. V.VAVALLO IS WAITING TO GET INTO HOLE. TO DO SAMPLE AND PRESSURE TEST. UPDATE:11JUNE1999 1215HRS ZALLOUGHI REPORTS, MR VALLAVO IS TAKING SAMPLES AND WILL SEND TO CHEM LAB AT THIS TIME.PLAN TO CALL POLICE DEPT TO MOVE CARS. ONE FROM PENN AND ONE FROM CONN. CAR FROM GEORGIA WAS MOVED. ESTIMATE THERE IS 100 GALLONS OIL IN STRUCTURE. UNIT FAILED PRESSURE TEST. THERE IS A SOIL DRAIN IN STRUCTURE AS PER DRAWINGS. WILL ATTEMPT TO VERIFY IF CEMENTED OR EXISTING. MR ZALLOUGH WILL ADVISE ERT. UPDATE: 6/11/99 16:00HRS-V. VAVALLO CALLED AND

VAULT 4506 (Continued) **S103938268**

STATED PUMPED OUT 405 GALLONS OF OIL FROM TRANSFORMER-UPDATE GALLONS LOST TO 195. UNIT COMPLETELY DRAINED. UPDATE: 6/11/99 19:25HRS-LAB SEQ# 99-06065-RESULTS 57 PPM. UPDATE - 6/12/99 0440HRS - A. HOWELL, OS, PARTIAL CLEANUP COMPLETED . COMPLETION OF C/U PENDING REMOVAL OF VS.TAG LEF INT PLACE. REMOVED 1 FT OF SOIL FROM SUMP AND CHEM LAB TOOK SAMPLE . SUMP HAS BEEN PROTECTED PENDING RESULTS OF SOIL SAMPLE. REMOVED 4 BARRELS OF DEBRIS. UPDATE K. KAVANAGH OS FLUSH REPORTS IN VS4506 THE UNIT WAS REMOVED THAT THERE IS A CEMENT FLOOR AND THEY REMOVED 8 BARRELS OF DEBRIS AND 150 GALLONS OF LIQUID FROM STRUCTURE. A SUMP SAMPLE WAS TAKEN ON 3-11 (2100 HRS) SHIFT 6-11-99. DOUBLE WASH HOLE AND REMOVED E.S.TAG #06801. CLEANUP IS COMPLETED 1330 HRS 6-12-99. UPDATE 6/13/99-16:45HRS- LAB SEQ 99-06093-SOIL-SUMP PIT. RESULTS 1PPM. 2 SOIL SAMPLE RESULTS RECEIVED BOTH PASSED @ 0700 6/15 ENVIRO OPS TO GO OUT TO CEMENT SUMP & PULL TAG.

Remarks: 52PPM HISTORICAL DATA - SAMPLE TO BE TAKEN - CLEANUP PENDING RESULTS - CASE #125512

Material:

Site ID:	221189
Operable Unit ID:	1077433
Operable Unit:	01
Material ID:	302757
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9902828
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	06/11/1999 09:50
Reported to Dept Date/Time:	06/11/99 10:49

VAULT 4506 (Continued) **S103938268**

SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/11/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/11/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 20
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: 52PPM HISTORICAL DATA - SAMPLE TO BE TAKEN - CLEANUP PENDING RESULTS - CASE 125512

R125 **SETH LOW HOUSES -NYCHA** **NY Spills** **S104194168**
WSW **180 POWELL STREET** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
281 ft. **Site 2 of 5 in cluster R**

Relative:
Higher

Actual:
41 ft.

NY Spills:

Site ID:	139972
Facility Addr2:	Not reported
Facility ID:	9906013
Spill Number:	9906013
Facility Type:	ER
SWIS:	2401
Investigator:	jkkann
Referred To:	WP UNDER REVIEW, QRTLY RECVD 1/6/11
Spill Date:	8/19/1999
Reported to Dept:	8/19/1999
CID:	389
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	8/19/1999
Spill Record Last Update:	3/7/2011
Spiller Name:	LEWIS PONCE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	204278
DEC Memo:	11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski. 9/22/06: Spill transferred from Kraszewski to Kann. 9/21/10: J.Kann - Quarterly Report recieved on 9/1/10. 3/7/11: J.Kann - Qrtly Rpt rcvd 1/6/11
Remarks:	CALLER STATES THAT A MALFUNCTION IN THE TANK PIPING CAUSED AN UNKNOWN AMOUNT SPILL CLEAN UP IS IN THE PROCESS AND TANK WILL BE REPLACED NO CALLBACK NECESSARY

Material:

Site ID:	139972
Operable Unit ID:	1084451
Operable Unit:	01
Material ID:	302286
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0

SETH LOW HOUSES -NYCHA (Continued) **S104194168**

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9906013
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 08/19/1999 12:00
Reported to Dept Date/Time: 08/19/99 12:33
SWIS: 61
Spiller Name: NYC HOUSING AUTHORITY
Spiller Contact: LEWIS PONCE
Spiller Phone: (212) 306-8894
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: MANHATTAN, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/19/99

SETH LOW HOUSES -NYCHA (Continued) **S104194168**

Date Spill Entered In Computer Data File: Not reported
Update Date: 02/08/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Remark: CALLER STATES THAT A MALFUNCTION IN THE TANK PIPING CAUSED AN UNKNOWN AMOUNT SPILL CLEAN UP IS IN THE PROCESS AND TANK WILL BE REPLACED NO CALLBACK NECESSARY

R126 **SETH LOW HOUSES** **HIST UST** **U001840688**
WSW **230 POWELL STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.053 mi.
281 ft. **Site 3 of 5 in cluster R**

Relative:
Higher

Actual:
41 ft.

HIST UST:
PBS Number: 2-474185
SPDES Number: Not reported
Emergency Contact: EMERGENCY SERVICE DEPT.
Emergency Telephone: (718) 289-3940
Operator: LUIS PONCE
Operator Telephone: (718) 707-5725
Owner Name: NEW YORK CITY HOUSING AUTHORITY
Owner Address: 23-02 49TH AVENUE
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (718) 707-5725
Owner Type: Local Government
Owner Subtype: 51
Mailing Name: NEW YORK CITY HOUSING AUTH.
Mailing Address: 23-02 49TH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: LUIS PONCE
Mailing Telephone: (718) 707-5725
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 180 POWELL STREET (MANAGEMENT OFFICE)

SETH LOW HOUSES (Continued) **U001840688**

SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	01/05/2001
Expiration Date:	03/28/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	15000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19671201
Capacity (gals):	20000
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1999
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19671201
Capacity (gals):	20000
Product Stored:	EMPTY

SETH LOW HOUSES (Continued) **U001840688**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1999
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	NEW TK#1
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19991101
Capacity (gals):	15000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Fiberglass coated steel
Tank Internal:	Not reported
Tank External:	Fiberglass
Pipe Location:	Underground
Pipe Type:	FIBERGLASS REINFORCED PLASTIC
Pipe Internal:	Other
Pipe External:	Other
Second Containment:	Vault (w/access)
Leak Detection:	14
Overfill Prot:	Float Vent Valve, High Level Alarm
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

R127 **NYCHA - SETH LOW** **RCRA-NonGen** **1001224049**
WSW **232 POWELL ST** **FINDS** **NYR000052654**
< 1/8 **BROOKLYN, NY 11212**
0.053 mi.
281 ft. **Site 4 of 5 in cluster R**

Relative:
Higher

Actual:
41 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCHA - SETH LOW
Facility address:	232 POWELL ST BROOKLYN, NY 112128135

NYCHA - SETH LOW (Continued) **1001224049**

EPA ID: NYR000052654
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: Not reported
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - SETH LOW
Classification: Not a generator, verified

NYCHA - SETH LOW (Continued) **1001224049**

Date form received by agency: 07/08/1999
Facility name: NYCHA - SETH LOW
Classification: Not a generator, verified

Date form received by agency: 03/30/1998
Facility name: NYCHA - SETH LOW
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004541611

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

R128 **NYC HOUSING AUTHORITY** **MANIFEST** **1010182287**
WSW **232 POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.053 mi.
281 ft. **Site 5 of 5 in cluster R**

Relative:
Higher

Actual:
41 ft.

NY MANIFEST:
EPA ID: NYR000052654
Country: USA
Mailing Name: NYC HOUSING AUTHORITY
Mailing Contact: RAFAEL PELEZ
Mailing Address: 250 BROADWAY
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10007
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-306-3142

NY MANIFEST:
No Manifest Records Available

Z129 **NYCHA - VAN DYKE HOUSES** **RCRA-NonGen** **1005905755**
WSW **330 POWELL ST** **FINDS** **NYR000108399**
< 1/8 **BROOKLYN, NY 11212**
0.054 mi.
283 ft. **Site 2 of 2 in cluster Z**

Relative:
Lower

Actual:
38 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - VAN DYKE HOUSES
Facility address: 330 POWELL ST

NYCHA - VAN DYKE HOUSES (Continued) **1005905755**

BROOKLYN, NY 11212
EPA ID: NYR000108399
Mailing address: 49TH AVE
LONG ISLAND CITY, NY 111014528
Contact: ANTHONY SOLOMITA
Contact address: 49TH AVE
LONG ISLAND CITY, NY 111014528
Contact country: US
Contact telephone: (718) 707-5731
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK CITY HOUSING AUTHORITY
Owner/operator address: 23-02 49TH AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 707-5731
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY HOUSING AUTHORITY
Owner/operator address: 23-02 49TH AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 707-5731
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - VAN DYKE HOUSES
Classification: Not a generator, verified

NYCHA - VAN DYKE HOUSES (Continued) **1005905755**

Date form received by agency: 08/02/2002
Facility name: NYCHA - VAN DYKE HOUSES
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110012567775

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AA130 **PEREY TURNSTILES** **UST** **U003652029**
NE **2490 ATLANTIC AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.054 mi.
284 ft. **Site 1 of 5 in cluster AA**

Relative:
Higher

Actual:
64 ft.

UST:
Facility Id: 2-603884
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 592765.63095999998
UTM Y: 4503287.4950599996

Affiliation Records:
Site Id: 25781
Affiliation Type: Emergency Contact
Company Name: PEREY MANUFACTURING COMPANY, INC.
Contact Type: Not reported
Contact Name: ED HENDRICKSON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (203) 961-8444
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25781
Affiliation Type: Owner
Company Name: PEREY MANUFACTURING COMPANY, INC.
Contact Type: Not reported
Contact Name: Not reported

PEREY TURNSTILES (Continued) **U003652029**

Address1:	45 CHURCH STREET
Address2:	Not reported
City:	STAMFORD
State:	CT
Zip Code:	06906-1710
Country Code:	001
Phone:	(203) 961-8444
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25781
Affiliation Type:	On-Site Operator
Company Name:	PEREY TURNSTILES
Contact Type:	Not reported
Contact Name:	ED HENDRICKSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 498-6320
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25781
Affiliation Type:	Mail Contact
Company Name:	PEREY TURNSTILES
Contact Type:	Not reported
Contact Name:	JOE TARNOWSKI
Address1:	45 CHURCH STREET
Address2:	Not reported
City:	STAMFORD
State:	CT
Zip Code:	06906
Country Code:	001
Phone:	(203) 961-8444
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground

PEREY TURNSTILES (Continued) **U003652029**

C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:

Site ID:	25781
Tank Number:	001
Tank ID:	55858
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	500
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	25781
Tank Number:	002
Tank ID:	55859
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	25781

PEREY TURNSTILES (Continued) **U003652029**

Tank Number:	003
Tank ID:	55860
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	12/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-603884
SPDES Number:	Not reported
Emergency Contact:	ED HENDRICKSON
Emergency Telephone:	(203) 961-8444
Operator:	ED HENDRICKSON
Operator Telephone:	(718) 498-6320
Owner Name:	PEREY MANUFACTURING COMPANY, INC.
Owner Address:	45 CHURCH STREET
Owner City,St,Zip:	STAMFORD, CT 06906-1710
Owner Telephone:	(203) 961-8444
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	PEREY TURNSTILES
Mailing Address:	45 CHURCH STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STAMFORD, CT 06906
Mailing Contact:	JOE TARNOWSKI
Mailing Telephone:	(203) 961-8444
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	Not reported
Expiration Date:	01/11/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0

PEREY TURNSTILES (Continued) **U003652029**

Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	500
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	12/01/1998
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported
Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	Diking
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	12/01/1998
Test Method:	Not reported
Deleted:	False

PEREY TURNSTILES (Continued) **U003652029**

Updated: True
Lat/long: Not reported

Tank Id: 003
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: Diking
Leak Detection: None
Overfill Prot: None
Dispenser: 0
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 12/01/1998
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AA131 **DRUM RUN** **NY Spills** **S106722295**
NE **2509 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.056 mi.
296 ft. **Site 2 of 5 in cluster AA**

Relative:
Higher

Actual:
64 ft.

NY Spills:
Site ID: 332572
Facility Addr2: Not reported
Facility ID: 0407976
Spill Number: 0407976
Facility Type: ER
SWIS: 2401
Investigator: TJDEMEO
Referred To: Not reported
Spill Date: 10/18/2004
Reported to Dept: 10/18/2004
CID: 73
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known

DRUM RUN (Continued) **S106722295**

release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/1/2004
Remediation Phase: 0
Date Entered In Computer: 10/19/2004
Spill Record Last Update: 11/1/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: 2 PETTICOAT LA
Spiller City,St,Zip: TOWN OF BRUNSWICK, NY
Spiller Company: 001
Contact Name: JOSEPH MCGOVERN
Contact Phone: (347) 539-0559
DEC Region: 2
DER Facility ID: 267780
DEC Memo: 11/1/04 TJD Drum emptied as part of Drum Run on 10/29/04. Spill closed
Not reported
Remarks: 5 DRUMS VARYING SIZE CONTAINING WASTE OIL FOUND ABANDONED. NO LEAK AT THIS TIME. FD IS PACKING THE DRUMS.

Material:
Site ID: 332572
Operable Unit ID: 1094804
Operable Unit: 01
Material ID: 574936
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 150
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AA132
NE
< 1/8
0.058 mi.
304 ft.

ACCURATE FORMING / VENTURE METAL PRODUCT — **ICIS** — **1011511594**
2523 ATLANTIC AVENUE BROOKLYN NY 11207 — **N/A**
BROOKLYN, NY 11207

Site 3 of 5 in cluster AA

Relative:
Higher

Actual:
64 ft.

ICIS:

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Program ID:	FIS 2-6105-00241
Action Name:	VENTURE METALS
Facility Name:	ACCURATE FORMING / VENTURE METAL PRODUCT
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN NY 11207 BROOKLYN, New York 11207
Enforcement Action Type:	CAA 113 Notice Of Violation
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Program ID:	AIRS/AFS 3604700243
Action Name:	VENTURE METALS
Facility Name:	VENTURE METAL PRODUCTS CORP
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN NY 11207 BROOKLYN, New York 11207
Enforcement Action Type:	CAA 113 Notice Of Violation
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Program ID:	RCRAINFO NYD053563219
Action Name:	VENTURE METALS
Facility Name:	VENTURE METAL PRODUCTS CORP
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN NY 11207 BROOKLYN, New York 11207
Enforcement Action Type:	CAA 113 Notice Of Violation
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Program ID:	FRS 110001571503
Action Name:	VENTURE METALS
Facility Name:	VENTURE METAL PRODUCTS CORP
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN NY 11207 BROOKLYN, New York 11207
Enforcement Action Type:	CAA 113 Notice Of Violation
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Program ID:	FIS 2-6105-00170
Action Name:	VENTURE METALS
Facility Name:	VENTURE METAL PRODUCTS CORP
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN NY 11207 BROOKLYN, New York 11207
Enforcement Action Type:	CAA 113 Notice Of Violation

ACCURATE FORMING / VENTURE METAL PRODUCT (Continued) **1011511594**

Facility County: Kings
EPA Region #: 3

Program ID: AIRS/AFS 3604700243
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Program ID: AIRS/AFS 3604700243
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Program ID: FIS 2-6105-00170
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Program ID: FIS 2-6105-00170
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Program ID: FIS 2-6105-00241
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Program ID: FIS 2-6105-00241
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Program ID: FRS 110001571503
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No

ACCURATE FORMING / VENTURE METAL PRODUCT (Continued) **1011511594**

NAIC Code: Not reported
SIC Code: 3471

Program ID: FRS 110001571503
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Program ID: RCRAINFO NYD053563219
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Program ID: RCRAINFO NYD053563219
Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

AA133 **VENTURE METAL PRODUCTS CORP** **RCRA-NonGen** **1001405076**
NE **2523 ATLANTIC AVE** **FINDS** **NYD053563219**
< 1/8 **BROOKLYN, NY 11207** **MANIFEST**
0.058 mi.
305 ft. **Site 4 of 5 in cluster AA**

Relative:
Higher

Actual:
64 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: VENTURE METAL PRODUCTS CORP
Facility address: 2523 ATLANTIC AVE
BROOKLYN, NY 11207
EPA ID: NYD053563219
Mailing address: ATLANTIC AVE
BROOKLYN, NY 11207
Contact: Not reported
Contact address: ATLANTIC AVE
BROOKLYN, NY 11207
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: VENTURE METAL PRODUCTS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Owner/operator telephone: (212) 555-1212
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: VENTURE METAL PRODUCTS
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: County
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VENTURE METAL PRODUCTS CORP
Classification: Not a generator, verified

Date form received by agency: 12/17/1998
Facility name: VENTURE METAL PRODUCTS CORP
Classification: Not a generator, verified

Date form received by agency: 06/17/1988
Facility name: VENTURE METAL PRODUCTS CORP
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/20/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Registry ID: 110001571503

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

NY MANIFEST:

EPA ID:	NYD053563219
Country:	USA
Mailing Name:	VENTURE METAL
Mailing Contact:	VENTURE METAL
Mailing Address:	2525 ATLANTIC AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-346-0596

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Document ID:	NYB6773148
Manifest Status:	Completed copy
Trans1 State ID:	NYPD1011
Trans2 State ID:	Not reported
Generator Ship Date:	960613
Trans1 Recv Date:	960613
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	960613
Part A Recv Date:	Not reported
Part B Recv Date:	960624
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	96

Document ID:	NYB4018311
Manifest Status:	Completed copy
Trans1 State ID:	PD1011
Trans2 State ID:	Not reported
Generator Ship Date:	930202
Trans1 Recv Date:	930202
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	930202
Part A Recv Date:	930211
Part B Recv Date:	930219
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	93

Document ID:	NYB2147004
Manifest Status:	Completed copy
Trans1 State ID:	PD1011
Trans2 State ID:	Not reported
Generator Ship Date:	931021
Trans1 Recv Date:	931021
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	931021
Part A Recv Date:	Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Part B Recv Date:	931109
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00200
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	93

Document ID:	SCA1124980
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	11/24/1998
Trans1 Recv Date:	11/24/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/07/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	SCD036275626
Trans2 EPA ID:	Not reported
TSDF ID:	NJDEP5005
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F003 - UNKNOWN
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	98

O134 **CON EDISON** **RCRA-CESQG** **1014397162**
NNW **ATLANTIC AVE & HAVENS PL** **NYP004194809**
< 1/8 **BROOKLYN, NY 11233**
0.065 mi.
342 ft. **Site 7 of 7 in cluster O**

Relative:
Higher

Actual:
69 ft.

RCRA-CESQG:

Date form received by agency:	09/18/2009
Facility name:	CON EDISON
Facility address:	ATLANTIC AVE & HAVENS PL BROOKLYN, NY 11233
EPA ID:	NYP004194809
Mailing address:	4 IRVING PL, RM 828

CON EDISON (Continued) **1014397162**

NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 666-4714
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

P135 **NYCTA POWELL STREET GARDEN** **MANIFEST** **1009244439**
SW **LIVONIA AVE & POWELL ST** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.066 mi.
347 ft. **Site 6 of 7 in cluster P**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:
EPA ID: NYR000811257
Country: USA
Mailing Name: NYCTA POWELL STREET GARDEN
Mailing Contact: BERNARD JENS
Mailing Address: 370 JAY STREET RM 819
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY

NYCTA POWELL STREET GARDEN (Continued) **1009244439**

Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-243-4227

Document ID:	NJA4070457
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2003
Trans1 Recv Date:	06/02/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000811257
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	H10376
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	03

P136 **NYCT - POWELL STREET GARDEN** **RCRA-CESQG** **1004762589**
SW **COR OF LIVONIA AVE &** **FINDS** **NYR000098475**
< 1/8 **BROOKLYN, NY 11212** **MANIFEST**
0.066 mi. **MANIFEST**
347 ft. **Site 7 of 7 in cluster P**

Relative:
Lower

Actual:
32 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	NYCT - POWELL STREET GARDEN
Facility address:	COR OF LIVONIA AVE & POWELL ST BROOKLYN, NY 11212
EPA ID:	NYR000098475
Mailing address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact:	JAMES CRANDALL
Contact address:	JAY ST ROOM 819 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	(718) 243-4581
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	370 JAY ST ROOM 819 BROOKLYN, NY 11201
Owner/operator country:	US
Owner/operator telephone:	(718) 243-4581
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Facility name:	NYCT - POWELL STREET GARDEN
Classification:	Conditionally Exempt Small Quantity Generator

Date form received by agency:	06/11/2001
Facility name:	NYCT - POWELL STREET GARDEN
Classification:	Conditionally Exempt Small Quantity Generator

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Violation Status: No violations found

FINDS:

Registry ID: 110007905259

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

Manifest Code:	NJA5077706
EPA ID:	NYR000098475
Date Shipped:	20040406
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040406
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040406
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	05030425
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5077685
EPA ID:	NYR000098475
Date Shipped:	20040323

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040323
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040323
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04280421
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code: Not reported	
Manifest Year: Not reported	
Quantity: Not reported	
Unit: Not reported	
Hand Code: Not reported	

Manifest Code:	NJA5314301
EPA ID:	NYR000098475
Date Shipped:	20060420
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060420
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060420
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 06140622
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5212762
EPA ID: NYR000098475
Date Shipped: 20050421
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050421
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050422
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 06150521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5212751
EPA ID: NYR000098475
Date Shipped: 20050418

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050418
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050418
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	05270522
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5081933
EPA ID:	NYR000098475
Date Shipped:	20050902
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050902
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050902
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	10170521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

NY MANIFEST:

EPA ID:	NYR000098475
Country:	USA
Mailing Name:	NYCTA
Mailing Contact:	BERNARD JENS
Mailing Address:	370 JAY STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-243-4227

Document ID:	NJA4110475
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/17/2003
Trans1 Recv Date:	11/17/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/17/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098475
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	S5811
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	03

Document ID:	NJA5081933
Manifest Status:	Not reported

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/02/2005
Trans1 Recv Date: 09/02/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/02/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA5212751
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/18/2005
Trans1 Recv Date: 04/18/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/18/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA5212762
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/21/2005
Trans1 Recv Date: 04/21/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/22/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: Not reported

Document ID: NJA5077685
Manifest Status: Not reported
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 03/23/2004
Trans1 Recv Date: 03/23/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/23/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 04

Document ID: NJA5077706
Manifest Status: Not reported
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2004
Trans1 Recv Date: 04/06/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/06/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00010
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Specific Gravity: 01.00
Year: 04

Document ID: NJA5212762
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/21/2005
Trans1 Recv Date: 04/21/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/22/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2005

Document ID: NJA5081933
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/02/2005
Trans1 Recv Date: 09/02/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/02/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000098475
Trans1 EPA ID: S5811
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2005

Document ID: NJA5212751
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/18/2005

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

Trans1 Recv Date:	04/18/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/18/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098475
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	2005

Document ID:	06
Manifest Status:	NJA5314301
Trans1 State ID:	NYR000098475
Trans2 State ID:	Not reported
Generator Ship Date:	NJD002200046
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJ0000027193
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	5
Handling Method:	G
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported

Document ID:	NJA5314301
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/20/2006
Trans1 Recv Date:	04/20/2006
Trans2 Recv Date:	Not reported

NYCT - POWELL STREET GARDEN (Continued) **1004762589**

TSD Site Recv Date:	04/20/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098475
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	NJA4106463
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/16/2002
Trans1 Recv Date:	04/16/2002
Trans2 Recv Date:	04/22/2002
TSD Site Recv Date:	04/22/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000098475
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	H10376
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	02

N137 **PVT RESIDENCE** **NY Spills** **S110138598**
WSW **1713 EAST NEW YORK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.066 mi.
348 ft. **Site 7 of 7 in cluster N**

Relative:
Higher

Actual:
64 ft.

NY Spills:

Site ID:	422477
Facility Addr2:	Not reported
Facility ID:	0909750
Spill Number:	0909750
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	12/3/2009
Reported to Dept:	12/3/2009
CID:	Not reported

PVT RESIDENCE (Continued) **S110138598**

Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/24/2010
Remediation Phase:	0
Date Entered In Computer:	12/3/2009
Spill Record Last Update:	2/24/2010
Spiller Name:	JAMES BEDARY
Spiller Company:	UNKNOWN
Spiller Address:	1713 EAST NEW YORK AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	JAMES BEDARY
Contact Phone:	(516) 250-8065
DEC Region:	2
DER Facility ID:	371412
DEC Memo:	12/04/09 Inspected the tank room on 12/03/09.The house was evicted yesterday.Now its owned by Bank.Tom Marco Real Estate is the bank's representative.A 275 gal old AST in the basement, leaked out few gallons of oil.Unsure, the tank has oil in it or not.Oil mixed with sewage in the basement.Spill clean up required letter was sent out to(via facsimile as well) Tom Marco Real Estate Ph:(718)998-7100, Fax:(718)998-4005 18-01 Stillwell Avenue Brooklyn, NY 11223 Attn: Tom Marco(sr) 02/24/10 Rec'd pictures and email from Boro Fuel Oil confirming the spill was cleaned up and it was a minor spill. Pictures in edocs.Case closed.(sr)
Remarks:	oil leak into basement - 15 x 20 x 1 1/2 deep mixed with water - cleanup is pending - steve is familiar - scirice will meet at property

Material:

Site ID:	422477
Operable Unit ID:	1178316
Operable Unit:	01
Material ID:	2171604
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported

PVT RESIDENCE (Continued) **S110138598**

Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

V138 **ROADWAY** **NY Spills** **S102560539**
East **515 BLAKE AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.073 mi.
384 ft. **Site 3 of 3 in cluster V**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	271738
Facility Addr2:	Not reported
Facility ID:	9700235
Spill Number:	9700235
Facility Type:	ER
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported
Spill Date:	4/4/1997
Reported to Dept:	4/4/1997
CID:	252
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/4/1997
Remediation Phase:	0
Date Entered In Computer:	4/4/1997
Spill Record Last Update:	4/7/1997
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, ZZ
Spiller Company:	999
Contact Name:	DISP 381
Contact Phone:	(718) 965-8300
DEC Region:	2
DER Facility ID:	221153
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT" SPOKE TO 381- ON STREET SANITATION WAS CALLED.
Remarks:	FIRE DEPT ON SCENE-SPILL IN PROCESS OF BEING CLEANED UP

Material:

Site ID:	271738
Operable Unit ID:	1043072
Operable Unit:	01

ROADWAY (Continued) **S102560539**

Material ID:	336853
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9700235
Investigator:	MARTINKAT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	04/04/1997 11:30
Reported to Dept Date/Time:	04/04/97 12:02
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	UNKNOWN
Spiller Phone:	(000) 000-0000
Spiller Contact:	DISP 381
Spiller Phone:	(718) 965-8300
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Fire Department
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /

ROADWAY (Continued) **S102560539**

Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/04/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/04/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 04/07/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 50
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: SPOKE TO 381- ON STREET SANITATION WAS CALLED.
Remark: FIRE DEPT ON SCENE-SPILL IN PROCESS OF BEING CLEANED UP

AA139 **CARLOS GATES & IRON WORK INC** **FINDS** **1012278719**
ENE **2533 ATLANTIC AVE, SIDE B** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.073 mi.
387 ft. **Site 5 of 5 in cluster AA**

Relative:
Higher

Actual:
60 ft.

FINDS:

Registry ID: 110040178330

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

140
WSW
< 1/8
0.076 mi.
401 ft.

DRUM RUN
6 POWELL ST
BROOKLYN, NY

NY Spills **S110488183**
N/A

Relative:
Higher

Actual:
63 ft.

NY Spills:

Site ID:	438284
Facility Addr2:	ON SIDEWALK
Facility ID:	1004989
Spill Number:	1004989
Facility Type:	ER
SWIS:	2401
Investigator:	HRAHMED
Referred To:	Not reported
Spill Date:	8/3/2010
Reported to Dept:	8/3/2010
CID:	Not reported
Spill Cause:	Abandoned Drums
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/13/2010
Remediation Phase:	0
Date Entered In Computer:	8/3/2010
Spill Record Last Update:	8/13/2010
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	KATHY GRINLEY
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	393276
DEC Memo:	Drum run 8/13/10-HRAHMED-One white color 55 gal plastic drum was pumped out during drum run today. NYC DEP and Sanitation were notified. This case is closed.
Remarks:	white 55gal plastic drum/no leaks/approx. 5 gals in drum

Material:

Site ID:	438284
Operable Unit ID:	1188947
Operable Unit:	01
Material ID:	2183879
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported

DRUM RUN (Continued) **S110488183**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

141
WSW
< 1/8
0.080 mi.
423 ft.

NYCHA - WOODSON VAN DYKE II
430 DUMONT AVE
BROOKLYN, NY 11212

RCRA-NonGen **1001224055**
FINDS **NYR000052712**
MANIFEST

Relative:
Lower

Actual:
35 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - WOODSON VAN DYKE II
Facility address: 430 DUMONT AVE
BROOKLYN, NY 11212
EPA ID: NYR000052712
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: FRANK OCELLO
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: (212) 306-3229
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY 16TH FLOOR
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator

NYCHA - WOODSON VAN DYKE II (Continued) **1001224055**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - WOODSON VAN DYKE II
Classification: Not a generator, verified

Date form received by agency: 03/30/1998
Facility name: NYCHA - WOODSON VAN DYKE II
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004541675

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000052712
Country: USA
Mailing Name: NYC HOUSING AUTHORITY
Mailing Contact: RAFAEL PELEZ
Mailing Address: 250 BROADWAY
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10007
Mailing Zip4: Not reported
Mailing Country: USA

NYCHA - WOODSON VAN DYKE II (Continued) **1001224055**

Mailing Phone: 212-306-3142

Document ID: NJA2787911
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 04/20/1998
Trans1 Recv Date: 04/20/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/21/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000052712
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSDF ID: S5811
Waste Code: U240 - 2,4 D,SALTS + ESTERS
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

AB142 **NYCDOT BRIDGE BIN 2243569** **RCRA-NonGen** **1000912082**
NNW **ATLANTIC AVE OVER LIRR** **FINDS** **NY0000445619**
< 1/8 **BROOKLYN, NY 11233**
0.086 mi.
454 ft. **Site 1 of 8 in cluster AB**

Relative:
Higher

Actual:
71 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCDOT BRIDGE BIN 2243569
Facility address: ATLANTIC AVE OVER LIRR
ATLANTIC AVE
BROOKLYN, NY 11233
EPA ID: NY0000445619
Mailing address: RECTOR ST - 4TH FLOOR
NEW YORK, NY 10006
Contact: ANTHONY GROSSO
Contact address: RECTOR ST - 4TH FLOOR
NEW YORK, NY 10006
Contact country: US
Contact telephone: (212) 788-1705
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCDOT BUREAU OF BRIDGE
Owner/operator address: 2 RECTOR ST
NEW YORK, NY 10006
Owner/operator country: US
Owner/operator telephone: (212) 788-1705

NYCDOT BRIDGE BIN 2243569 (Continued) **1000912082**

Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCDOT BUREAU OF BRIDGE
Owner/operator address: 2 RECTOR ST
NEW YORK, NY 10006
Owner/operator country: US
Owner/operator telephone: (212) 788-1705
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCDOT BRIDGE BIN 2243569
Classification: Not a generator, verified

Date form received by agency: 07/11/1994
Facility name: NYCDOT BRIDGE BIN 2243569
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110007987401

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

143
WSW
< 1/8
0.091 mi.
479 ft.

DRUM RUN
128 LIBERTY AVE
BROOKLYN, NY

NY Spills **S108296307**
N/A

Relative:
Higher

Actual:
56 ft.

NY Spills:

Site ID:	374089
Facility Addr2:	ON SIDEWALK
Facility ID:	0609771
Spill Number:	0609771
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	11/27/2006
Reported to Dept:	11/27/2006
CID:	408
Spill Cause:	Abandoned Drums
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/1/2006
Remediation Phase:	0
Date Entered In Computer:	11/27/2006
Spill Record Last Update:	12/1/2006
Spiller Name:	Not reported
Spiller Company:	UNKOWN.
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	GABRIEL KAPUR
Contact Phone:	(917) 682-3753
DEC Region:	2
DER Facility ID:	323797
DEC Memo:	add to next drum run 12/01/06 Rahman- Two drums were found, were pumped out and NYC sanitation was notified to pick up the empty drums. Not reported
Remarks:	ONE DRUM CONTAINS ABOUT 12 INCHES OF WASTE MOTOR OIL THE OTHER ABOUT AN INCH OF WASTE MOTOR OIL; DRUMS NOT YET REMOVED;

Material:

Site ID:	374089
Operable Unit ID:	1131770
Operable Unit:	01
Material ID:	2121486
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No

DRUM RUN (Continued) **S108296307**

Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AC144 **ARC METAL GROUP, LLC** **UST** **U004046013**
East **156 HINSDALE STREET** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.095 mi.
502 ft. **Site 1 of 7 in cluster AC**

Relative:
Higher

Actual:
43 ft.

UST:
Facility Id: 2-609411
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 592911.62479999999
UTM Y: 4502876.9731099997

Affiliation Records:
Site Id: 31255
Affiliation Type: Emergency Contact
Company Name: ERASMINA & ROSA REALTY CORP.
Contact Type: Not reported
Contact Name: JORDAN GLASER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 922-4505
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31255
Affiliation Type: Mail Contact
Company Name: ARC METAL GROUP, LLC
Contact Type: Not reported
Contact Name: JORDAN GLASER
Address1: 156 HINSDALE STREET
Address2: Not reported

ARC METAL GROUP, LLC (Continued) **U004046013**

City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 922-4505
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	31255
Affiliation Type:	Owner
Company Name:	ARC METAL GROUP
Contact Type:	PRES.
Contact Name:	JORDAN GLASER
Address1:	156 HINSDALE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 922-4505
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2/24/2005

Site Id:	31255
Affiliation Type:	On-Site Operator
Company Name:	ARC METAL GROUP, LLC
Contact Type:	Not reported
Contact Name:	JORDAN GLASER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 922-4505
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C03 - Pipe Location - Aboveground/Underground Combination
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

ARC METAL GROUP, LLC (Continued) **U004046013**

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None

Tank Info:

Site ID:	31255
Tank Number:	1
Tank ID:	67360
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	21
Next Test Date:	Not reported
Date Tank Closed:	1/5/2005
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	12/9/2003
Register:	True
Modified By:	KXTANG
Last Modified:	2/24/2005

T145 **ENCORE RETAIL SYSTEMS INC** **FINDS** **1009650823**
East **138 HINSDALE ST** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.096 mi.
505 ft. **Site 6 of 6 in cluster T**

Relative:
Higher

Actual:
48 ft.

FINDS:

Registry ID: 110027305896

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AD146 **H E L P BROOKLYN HOUSING NEW YORK** **RCRA-NonGen** **1000457372**
East **HINSDALE ST & SNEDIKER AVE** **FINDS** **NYD986925220**
< 1/8 **BROOKLYN, NY 11207**
0.096 mi.
505 ft. **Site 1 of 2 in cluster AD**

Relative:
Higher

Actual:
59 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	H E L P BROOKLYN HOUSING NEW YORK
Facility address:	HINSDALE ST & SNEDIKER AVE BROOKLYN, NY 11207
EPA ID:	NYD986925220
Mailing address:	OLD POST RD EDISON, NY 08817
Contact:	Not reported
Contact address:	OLD POST RD EDISON, NY 08817

H E L P BROOKLYN HOUSING NEW YORK (Continued) **1000457372**

Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: ANDREW CUOMO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: ANDREW CUOMO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: H E L P BROOKLYN HOUSING NEW YORK
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: H E L P BROOKLYN HOUSING NEW YORK
Classification: Not a generator, verified

Date form received by agency: 10/02/1990
Facility name: H E L P BROOKLYN HOUSING NEW YORK

H E L P BROOKLYN HOUSING NEW YORK (Continued) **1000457372**

Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008043786

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AC147 **30 GALLONS OIL IN MANHOLE #65986** **NY Spills** **S108465674**
East **HINSDALE STREET & PITKIN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.096 mi.
506 ft. **Site 2 of 7 in cluster AC**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	376736
Facility Addr2:	Not reported
Facility ID:	0611979
Spill Number:	0611979
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	1/30/2007
Reported to Dept:	1/30/2007
CID:	444
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/16/2007
Remediation Phase:	0
Date Entered In Computer:	1/30/2007
Spill Record Last Update:	2/16/2007
Spiller Name:	ERTS
Spiller Company:	CON EDISON MH #65986
Spiller Address:	INSDALE STR/PICKIN AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERTS
Contact Phone:	(212) 580-8383
DEC Region:	2

30 GALLONS OIL IN MANHOLE #65986 (Continued) **S108465674**

DER Facility ID:	326319
DEC Memo:	02/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 204316. see eDocs
Remarks:	no to 5 questions: clean up pending test results coned # 204316

Material:

Site ID:	376736
Operable Unit ID:	1134300
Operable Unit:	01
Material ID:	2124155
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AC148 **CON EDISON MANHOLE 65986** **RCRA-NonGen** **1010327622**
East **HINSDALE ST & PITKIN AVE** **MANIFEST** **NYP004147856**
< 1/8 **BROOKLYN, NY 11207**
0.096 mi.
506 ft. **Site 3 of 7 in cluster AC**

Relative:
Higher

Actual:
39 ft.

RCRA-NonGen:

Date form received by agency:	04/11/2007
Facility name:	CON EDISON MANHOLE 65986
Facility address:	HINSDALE ST & PITKIN AVE BROOKLYN, NY 11207
EPA ID:	NYP004147856
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL D'AGOSTINO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE 65986 (Continued) **1010327622**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 04/10/2007
- Facility name: CON EDISON MANHOLE 65986
- Site name: CON EDISON
- Classification: Not a generator, verified

- Date form received by agency: 04/09/2007
- Facility name: CON EDISON MANHOLE 65986
- Site name: CON EDISON
- Classification: Unverified

- Violation Status: No violations found

NY MANIFEST:
- EPA ID: NYP004147856
- Country: USA
- Mailing Name: CONSOLIDATED EDISON
- Mailing Contact: FRANKLIN MURRAY
- Mailing Address: 4 IRVING PLACE RM 828
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: 212-460-2808

- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD006982359
- Trans2 State ID: Not reported
- Generator Ship Date: 1/31/2007
- Trans1 Recv Date: 1/31/2007
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 2/1/2007
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004147856
- Trans1 EPA ID: Not reported

CON EDISON MANHOLE 65986 (Continued) **1010327622**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	150
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001450357FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-31
Trans1 Recv Date:	2007-01-31
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147856
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	150.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001450357FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

CON EDISON MANHOLE 65986 (Continued) **1010327622**

Mgmt Method Type Code: H141

AC149 **CON EDISON** **FINDS** **1010462557**
East **HINSDALE ST & PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.096 mi.
506 ft. **Site 4 of 7 in cluster AC**

Relative:
Higher

Actual:
39 ft.

FINDS:

Registry ID: 110031396987

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AE150 **CON EDISON** **FINDS** **1012237331**
East **GLENMORE & HINSDALE ST** **N/A**
< 1/8 **BROOKLYN, NY 11203**
0.097 mi.
512 ft. **Site 1 of 3 in cluster AE**

Relative:
Higher

Actual:
50 ft.

FINDS:

Registry ID: 110039591787

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AE151 **CON EDISON** **RCRA-CESQG** **1012186170**
East **GLENMORE & HINSDALE ST** **NYP004170080**
< 1/8 **BROOKLYN, NY 11203**
0.097 mi.
512 ft. **Site 2 of 3 in cluster AE**

Relative:
Higher

Actual:
50 ft.

RCRA-CESQG:

Date form received by agency:	05/18/2009
Facility name:	CON EDISON
Facility address:	GLENMORE & HINSDALE ST BROOKLYN, NY 11203
EPA ID:	NYP004170080
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL BETO

CON EDISON (Continued) **1012186170**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (917) 337-5519
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AF152 **MANHOLE 5211** **NY Spills** **S106718886**
East **SUTTER AV / HINSDALE AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.099 mi.
522 ft. **Site 1 of 7 in cluster AF**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 118941
Facility Addr2: Not reported
Facility ID: 0204191
Spill Number: 0204191
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 7/22/2002
Reported to Dept: 7/22/2002

MANHOLE 5211 (Continued) **S106718886**

CID:	365
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/24/2003
Remediation Phase:	0
Date Entered In Computer:	7/22/2002
Spill Record Last Update:	4/25/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	103333
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" e2mis no. 144-093: 7-22-02 1135 HRS L. BIBLE # 38673 SPLICER UG REPORTS WHILE MAKING INSPECTION FOR FUTURE FDR. WORK IN MH05211 NWC SUTTER AVE & HINSDALE ST HE FOUND APPROX 3 QUARTS UNKNOWN OIL ON 200 GALLONS WATER. ONLY OIL FILLED EQUIPMENT IN STRUCTURE IS JOINT REGULATOR AND 3C PAPER CABLE, EITHER LOOK TO BE LEAKING AT THIS TIME. HE DOES NOT SEE A SUMP OR SEWER CONNECTION AT THIS TIME, LIQUID SEEMS CONTAINED NO SEWERS OR WATERWAYS AFFECTED. HE TOOK A LIQUID SAMPLE AND REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULTS. CLEANUP PENDING SAMPLE RESULTS. UPDATE 7-22-02 HRS A. GIARRATANO OS UG REPORTS IN MH5211 HE FOUND 3C 350 STR JOINT LEAKING (D-FAULT # 66) THAT LOOKS TO BE ON FDR.3B95 (BY DUCTING) . FDR. 3B95 WILL HAVE TO COME OFF AND JOINT IDENTIFY & TAG AND STRUCTURE MADE SAFE BEFORE CLEANUP CAN BE STARTED. WILL TAKE THIS OFF THE 24 HRS DEMINIMIS PROGRAM DUE TO THE D- FAULT. 9/1/02=0440HRS QUIJIJE ENVIR OPPS REPORTS CLEANUP COMPLETED .DOULBED WASHED STRUCTURE USING BIO-GEN 760.FOUND NO SUMP.REMOVED ENVIR.TAG#37372. Detailed Description:
Remarks:	3 quarts unk oil on 200 gallons of water - has to be reported under the 24 hrs dimminimous - ref #144093

Material:

Site ID:	118941
Operable Unit ID:	855364
Operable Unit:	01
Material ID:	518449
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

MANHOLE 5211 (Continued) **S106718886**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AG153 **GENESIS HOMES LIMITED** **NY Spills** **S102961796**
East **330 HINSDALE ST APT-F138** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.099 mi.
523 ft. **Site 1 of 9 in cluster AG**

Relative:
Lower

Actual:
33 ft.

NY Spills:
Site ID: 227821
Facility Addr2: Not reported
Facility ID: 9709407
Spill Number: 9709407
Facility Type: ER
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Spill Date: 11/13/1997
Reported to Dept: 11/13/1997
CID: 366
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 11/13/1997
Remediation Phase: 0
Date Entered In Computer: 11/13/1997
Spill Record Last Update: 12/9/1997
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: BARBARA JOHNSON-BELLIDO
Contact Phone: (718) 485-4626
DEC Region: 2
DER Facility ID: 188006
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

GENESIS HOMES LIMITED (Continued) **S102961796**

"TIBBE" REFERED TO NYC DEP AND HEALTH DEPT.
Remarks: CALLER REPORTING THAT SHE IS FINDING SEWAGE LEAKING INTO BATHTUB AND TOILETS ONTO THE FLOORS. THIS HAS BEEN OCCURING THE START OF EVERY WINTER FOR THE LAST FIVE YEARS. HAS OCCURED THREE TIMES THIS YEAR. CALLER REQUESTING ASSISTANCE FROM DEC.

Material:
Site ID: 227821
Operable Unit ID: 1052527
Operable Unit: 01
Material ID: 327758
Material Code: 0062A
Material Name: RAW SEWAGE
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9709407
Investigator: TIBBE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/13/1997 06:15
Reported to Dept Date/Time: 11/13/97 07:16
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Contact: BARBARA JOHNSON-BELLIDO
Spiller Phone: (718) 485-4626
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported

GENESIS HOMES LIMITED (Continued) **S102961796**

Spill Source: 09
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt: 11/13/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/13/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/09/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Hazardous Material
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: RAW SEWAGE
Class Type: RAW SEWAGE
Times Material Entry In File: 1993
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: REFERED TO NYC DEP AND HEALTH DEPT.
Remark: CALLER REPORTING THAT SHE IS FINDING SEWAGE LEAKING INTO BATHTUB AND TOILETS ONTO THE FLOORS. THIS HAS BEEN OCCURING THE START OF EVERY WINTER FOR THE LAST FIVE YEARS. HAS OCCURED THREE TIMES THIS YEAR. CALLER REQUESTING ASSISTANCE FROM DEC.

AH154 **FLYING SERVICE BOX COVER** **NY Spills** **S107657547**
WNW **2402 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
526 ft. **Site 1 of 8 in cluster AH**

Relative:
Higher

Actual:
71 ft.

NY Spills:
Site ID: 360779
Facility Addr2: Not reported
Facility ID: 0514131
Spill Number: 0514131
Facility Type: ER
SWIS: 2401

FLYING SERVICE BOX COVER (Continued) **S107657547**

Investigator:	JMKRIMGO
Referred To:	Not reported
Spill Date:	3/9/2006
Reported to Dept:	3/9/2006
CID:	73
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/10/2009
Remediation Phase:	0
Date Entered In Computer:	3/10/2006
Spill Record Last Update:	9/10/2009
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	310961
DEC Memo:	09/10/09 - See eDocs for Con Ed report detailing cleanup and closure. 163273. 3/9/06 2220HRS O.S TINO FERNADEZ #56150 ENVIR OPPS REPORTS ARRIVED ON LOCATION 2402 ATLANTIC AVE AND FOUND THAT A SERVICE BOX COVER F/O 2402 ATLANTIC AVE HIT A TRACTER TRAILER FUEL TANK CAUSING IT TO SPILL APPPROX 100 GALLONS OF DIESEL FUEL ONTO AN AREA OF 400' BY 30' OF ASPHALT .ALSO FOUND APPROX 5-GALLONS OF DIESEL FUEL THAT ENTERED A SB W/O 2402 ATLANTIC AVE.REPORTS 3-CATCH BASINS ALONG THE CURB ALSO AFFECTED WITH FUEL AND 3- PRIVATE VEHICLES THAT WERE PARKED ON LOCATION HAD FUEL ON TIRES . .NYPD ON LOCATION CORDIN AREA OFF STREET .DEPT OF SANITATION ON LOCATION AND PLACED SAND DOWN ON STREET.TINO REPORTS DEP CELEST OKOLI ON LOCATION .ENVIR EH&S RON CONSENTINO WAS NOTIFIED.CIG P MCGUIRE NOTIFIED AT 2240HRS .MORE INFO TO FOLLOW.G DONATONE 3/9/06 UPDATE T.FERNANDEZ REPORTS AREA AFFECTED AT THIS TIME IS 400' BY 15' AND ALSO 2-CATCH BASIN WERE AFFECTED.PLATE # TO TRACTOR -TRAILER IS (253228. INDIANA) THE OWNER OF TRUCK IS (RYAN FARRELL) FERRELL TRUCKING.DRIVER OF TRUCK IS ELVIN MASON.DRIVER WAS TAKEN TO UNKNOWN HOSIPTAL. G DONATONE
Remarks:	EXPLOSION IN A MANHOLE CAUSE COVER TO FLY AND HIT A PARKED VEHICLE WHICH RESULTED IN FUEL LEAK COVERING AN AREA OF 400'X30' AREA. SOME MAY HAVE REACHED A CATCH BASIN (PER DEP). On 3/9/06 at 2340pm Petty Officer 2nd Class of the US Coast Guard called inquiring about this report and asked to have the DEC Rep contact him at 917-439-5919 or 203-577-8898. DEC Rep Ryan Piper advised. 163273.

Material:

Site ID:	360779
Operable Unit ID:	1117898
Operable Unit:	01
Material ID:	2108404

FLYING SERVICE BOX COVER (Continued) **S107657547**

Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AH155 **2402 ATLANTIC AVE** **NY Spills** **S107657546**
WNW **2402 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
526 ft. **Site 2 of 8 in cluster AH**

Relative:
Higher

Actual:
71 ft.

NY Spills:

Site ID:	360778
Facility Addr2:	Not reported
Facility ID:	0514130
Spill Number:	0514130
Facility Type:	ER
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Spill Date:	3/9/2006
Reported to Dept:	3/9/2006
CID:	41
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/10/2006
Remediation Phase:	0
Date Entered In Computer:	3/10/2006
Spill Record Last Update:	3/10/2006
Spiller Name:	Not reported

2402 ATLANTIC AVE (Continued) **S107657546**

Spiller Company:	FARRELL TRUCKING
Spiller Address:	Not reported
Spiller City,St,Zip:	TANNERSVILLE, PA 18372
Spiller Company:	001
Contact Name:	SAME AS ABOVE
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	310961
DEC Memo:	3/9/06- DEC Piper placed call into FDNY. They forwarded me to on site responder. Left message requesting call back. DEC Piper contacted DEP. As per them a truck traveling over a recessed manhole, popped up the manhole and ruptured the saddle tank. Spill to roadway. FDNY pumped catch basin, approx 80 gal. and speedy dried roadway. DEC Piper spoke w/ DEP Celeste on site. No DEC response needed. Under control. Closed.
Remarks:	SUNKEN MANHOLE COVER POPPED UP AND RUPTURED TANK - UNKNOWN QTY WENT INTO STORM DRAIN

Material:

Site ID:	360778
Operable Unit ID:	1117897
Operable Unit:	01
Material ID:	2108403
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AH156 **2402 ATLANTIC HOLDINGS LLC** **AST** **A100300849**
WNW **2402 ATLANTIC AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 10038**
0.100 mi.
526 ft. **Site 3 of 8 in cluster AH**

Relative:
Higher

Actual:
71 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-608095
Program Type:	PBS

2402 ATLANTIC HOLDINGS LLC (Continued) **A100300849**

UTM X: 592492.28127000004
UTM Y: 4503353.46483
Expiration Date: N/A

Affiliation Records:

Site Id: 29947
Affiliation Type: Mail Contact
Company Name: 2402 ATLANTIC HOLDINGS LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 49 WEST 44TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 453-4005
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29947
Affiliation Type: Owner
Company Name: 2402 ATLANTIC HOLDINGS LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 49 WEST 44TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 453-4005
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29947
Affiliation Type: On-Site Operator
Company Name: 2402 ATLANTIC HOLDINGS LLC
Contact Type: Not reported
Contact Name: NA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

2402 ATLANTIC HOLDINGS LLC (Continued) **A100300849**

Site Id:	29947
Affiliation Type:	Emergency Contact
Company Name:	2402 ATLANTIC HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	SUIMMY HORN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 453-4005
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Info:

Tank Number:	001
Tank Id:	64433
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/1/2002
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

AG157 **CONSOLIDATED EDISON** **MANIFEST** **S108980651**
East **HINSDALE ST & BLAKE AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.100 mi.
527 ft. **Site 2 of 9 in cluster AG**

Relative:
Lower

Actual:
33 ft.

NY MANIFEST:

EPA ID:	NYP004155438
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY

CONSOLIDATED EDISON (Continued) **S108980651**

Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2007
Trans1 Recv Date:	12/20/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004155438
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001451332FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AG158 **MANHOLE 3957** **NY Spills** **S104194165**
East **BLAKE AVE & HINSDALE AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
527 ft. **Site 3 of 9 in cluster AG**

Relative:
Lower

Actual:
33 ft.

NY Spills:

Site ID:	145477
Facility Addr2:	Not reported
Facility ID:	0205391
Spill Number:	0205391
Facility Type:	ER
SWIS:	2401

MANHOLE 3957 (Continued) **S104194165**

Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	8/22/2002
Reported to Dept:	8/22/2002
CID:	257
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/29/2002
Remediation Phase:	0
Date Entered In Computer:	8/22/2002
Spill Record Last Update:	10/29/2002
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -
Spiller Company:	001
Contact Name:	ANTHONY NATALE
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	123963
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" Con Ed e2mis #144675: 8/22/02 - 1245hrs - Ralph Cilento # 44214, splicer, Networks , reports while doing an inspection on a condemned unit found VS 5629 - 200 gallons of oil below min and 12" heavily oil saturated dirt in structure. Historical is 47ppm dated 10/99. No sewers or waterways appear to be affected. No private property affected. No fire/smoke involved. Sample taken marked E priority - chain of custody # CC04399. Unit on fdr 9b18. Env. stop tag # 31087 placed. No water involved. W. Alvarado & Env. ops crew advised and being dispatched to proceed with 50-499 cleanup. S. Stathis env. ops mgr advised @ 1250hrs. D. Duke, ERT, advised @ 1254hrs. EPA # NYP004101796 _ >50 tanker ordered and is being dispatched. M. Mastrocinque, Shift Mgr advised @ 1304hrs. 8-22-02 15:00HRS S. STATHIS REPORTS, D.E.P STANLEY BALDWIN ON LOCATION AND TOLD HIM ABOUT PARTIAL CLEANUP THAT UNIT WILL BE DRAINED AND WILL BE REMOVED TOMORROW, HE WAS SATISFIED. SAMPLE LEFT LOCATION AT 14:30HRS AND TANKER ARRIVED AT 14:30HRS. UPDATE: 22-AUG-2002 16:10 HRS. NETWORKS OPER. SUPV. SEDA EDIP EMP# 85210 REPORTS: ASTORIA TANKER REMOVED 80 GAL'S FROM UNIT. UNIT CAPACITY IS 295 GAL'S THERE FOR 215 GAL'S ARE MISSING FROM UNIT. UPDATE : 22-AUG-2002 16:25 HRS. EH&S S.STHATHIS REPORTS: S.BALDWIN OF THE DEP REQUESTED HARD COPY OF SAMPLE RESULTS BE FAXED TO HIS OFFICE WHEN AVAILABLE, ALSO HE WOULD LIKE TO BE NOTIFIED OF ASAP OF DISCOVERY OF AN EARTHEN SUMP. S.BALDWIN LEAVES LOCATION 15:50 HRS. UPDATE : 22-AUG-2002 17:28 HRS. ENVIR. FLUSH DEPT. MECH-A R.QUIJIJE EMP# 19656 REPORTS : WHILE CREW WAS PERFORMING PRELIMINARY CLEANUP AN EARTHEN SUMP WAS DISCOVERED. UPDATE :22-AUG-2002 21:20 HRS. ENVIR. OPER. MECH-A R.QUIJIJE EMP# 19656 REPORTS: ENVIR. CREW REMOVED 3 BARRELLS OF SOLID DEBRIS & PPE

MANHOLE 3957 (Continued) **S104194165**

FROM STRUCTURE AND TRANSPORTED TO 3RD AVE UNDER THE TRIP RULE. SAMPLES TANKEN FROM SUMP AND CEMENTED. TAG LEFT IN PLACE PENDING UNIT REMOVAL. UPDATE: 22-AUG-200 22:23 HRS. LSN# 02-07860-00 MATRIX: OIL, AROCLOR 1260, SAMPLE RESULT: 57 PPM PCB. UPDATE 8-23-02 0715 HRS J. GAGLIO ENVIOR REP REPORTS: HE NOTIFIED DEP S. BALDWIN THAT CHEM LAB RESULTS WAS 57 PPM AND THERE WAS EARTHEN SUMP AND TRANSF TO REMOVED MORNING OF 8-23-02. HE ALSO NOTIFIED ERT M. KESSLER AND HAD HIM FAX CHEM LAB RESULT TO DEP. UPDATE 8-23-02 1300 HRS A. HOWELL OS FLUSH DEPT REPORTS THEY REMOVED 4 DRUMS (OVER 50 PPM DRUMS) OF SOLID WASTE MATERIAL. THEY WILL START TO DOUBLE WASH STRUCTURE. UPDATE - 24-AUG-2002 9:00 HRS.. LSN# 02-07884-002, SUMP WALLS MATRIX : SOIL, AROCLOR: 1260, RESULT: < 1. PPM. UPDATE:-AUG-200 05 HRS. ENVIR. OPER. MECH-A J.MIDDLETON EMP# 13774 REPORTS: ENVIR. TAG# 31087 REMOVED CLEANUP COMPLETE 100%

Remarks: clean up crew has been dispatched clean up as 50-499ppm ref #144675

Material:

Site ID:	145477
Operable Unit ID:	858059
Operable Unit:	01
Material ID:	519590
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9906007
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	08/19/1999 10:30
Reported to Dept Date/Time:	08/19/99 11:15
SWIS:	61

MANHOLE 3957 (Continued) **S104194165**

Spiller Name: CON ED
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Address: 4 IRVING PL
Spiller City,St,Zip: MANHATTEN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/08/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/19/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/30/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: CON ed e2mis notes: A cable joint had leaked approx 3 ounces of dielectric fluil onto concrete floor of MH. A soil sample taken. Seq 99-08693 @1ppm, reports cleanup completed and env tag removed, incident is closed.
Remark: SPILLED 3OZ. CON ED 127317.

AG159 **MANHOLE 3957** **NY Spills** **S107408030**
East **BLAKE AVE & HINSDALE AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
527 ft. **Site 4 of 9 in cluster AG**

Relative:
Lower

Actual:
33 ft.

NY Spills:

Site ID:	310337
Facility Addr2:	Not reported
Facility ID:	9906007
Spill Number:	9906007
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	8/19/1999
Reported to Dept:	8/19/1999
CID:	205
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/8/1999
Remediation Phase:	0
Date Entered In Computer:	8/19/1999
Spill Record Last Update:	5/30/2000
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	250493
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" CON ed e2mis notes: A cable joint had leaked approx 3 ounces of dielectric fluil onto concrete floor of MH. A soil sample taken. Seq #99-08693 @1ppm, reports cleanup completed and env tag removed, incident is closed.
Remarks:	SPILLED 3OZ. CON ED #127317.

Material:

Site ID:	310337
Operable Unit ID:	1080447
Operable Unit:	01
Material ID:	302281
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons

MANHOLE 3957 (Continued) **S107408030**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AI160 **CON EDISON** **RCRA-CESQG** **1014397131**
WSW **SACKMAN ST & PITKIN AVE** **NYP004194494**
< 1/8 **BROOKLYN, NY 11212**
0.100 mi.
528 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
46 ft.

RCRA-CESQG:
Date form received by agency: 09/16/2009
Facility name: CON EDISON
Facility address: SACKMAN ST & PITKIN AVE
BROOKLYN, NY 11212
EPA ID: NYP004194494
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 666-4714
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON (Continued) **1014397131**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

AJ161 **ROAD WAY** **NY Spills** **S102560143**
WSW **SUTTER AVE/SACKMAN ST** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
528 ft. **Site 1 of 6 in cluster AJ**

Relative:
Higher

Actual:
41 ft.

NY Spills:

Site ID:	252442
Facility Addr2:	Not reported
Facility ID:	9612352
Spill Number:	9612352
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	1/13/1997
Reported to Dept:	1/15/1997
CID:	252
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/16/1997
Remediation Phase:	0
Date Entered In Computer:	1/15/1997
Spill Record Last Update:	1/16/1997
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	JOW DEVOTI
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	206815
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ROAD WAY (Continued) **S102560143**

"ENGELHARDT" 1/16/96 - SPILL FROM BLOWN HYDRAULIC LINE ON CABLE PULLING TRUCK. CLEANED BY CON ED WITH PADS, SORB-ALL, SLICKS, AND DRUMS. 1 CU FT OF SOIL REMOVED. MOST OF SPILL WAS ON PAVEMENT.
Remarks: VEH LEAKED HYDRAULIC FLUID ON TO CONCRETE AND BLACK TOP IN PROCESS OF BEING CLEANED UP

Material:
Site ID: 252442
Operable Unit ID: 1040224
Operable Unit: 01
Material ID: 340998
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9612352
Investigator: ENGELHARDT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/13/1997 18:16
Reported to Dept Date/Time: 01/15/97 19:28
SWIS: 61
Spiller Name: CON ED
Spiller Contact: TIM SOILCH
Spiller Phone: (212) 580-6764
Spiller Contact: JOW DEVOTI
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported

ROAD WAY (Continued) **S102560143**

Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 01/16/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/15/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/16/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 30
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: HYDRAULIC OIL
Class Type: HYDRAULIC OIL
Times Material Entry In File: 1846
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: 1/16/96 - SPILL FROM BLOWN HYDRAULIC LINE ON CABLE PULLING TRUCK. CLEANED BY CON ED WITH PADS, SORB-ALL, SLICKS, AND DRUMS. 1 CU FT OF SOIL REMOVED. MOST OF SPILL WAS ON PAVEMENT.
Remark: VEH LEAKED HYDRAULIC FLUID ON TO CONCRETE AND BLACK TOP IN PROCESS OF BEING CLEANED UP

AF162 **SERVICE BOX 42543** **NY Spills** **S104509042**
East **520 SUTTER AVE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
530 ft. **Site 2 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NY Spills:
Site ID: 320849
Facility Addr2: Not reported
Facility ID: 9911860
Spill Number: 9911860
Facility Type: ER

SERVICE BOX 42543 (Continued) **S104509042**

SWIS:	2401
Investigator:	COMENALE
Referred To:	Not reported
Spill Date:	1/12/2000
Reported to Dept:	1/12/2000
CID:	351
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/4/2002
Remediation Phase:	0
Date Entered In Computer:	1/12/2000
Spill Record Last Update:	11/17/2004
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	STEPHEN CRIBBEN
Contact Phone:	(212) 580-8576
DEC Region:	2
DER Facility ID:	258478
DEC Memo:	e2mis no. 129286: 12/13/99 1138 HRS PETTWAY 15204 OF RW REPORTS: A spill of approximatley 5 gallons of an unknown oil mixed with approximately 10 gallons of mud in M59227, 215 W 76 St was found while at that location on an AC burnout job (AC burnouts in structure). No water in structure, no visual movement, no entry to waterway, no smoke, no fire, no foundation cracks, sewer connection verified as per conduit plate 37-D-3. A PCB sample was taken and Tag #18341 was placed. Cleanup will be pending lab report. 12/16/99 12:46 RECEIVED LAB RESULTS, LAB SEQUENCE # 99-12793 AROCLOR - NONE PCB - <1.00 PPM INCIDENT # 129286 , F/O 215 WEST 76 ST , MH.59227 , <1.PPM DATE AND TIME THE CLEANUP COMPLETED : 1/03/00 , 14:00. OPERATING SUPERVISOR : K.MCDOWELL # 77565 CLEANUP PROCEDURE : (NO WATER) MUD REMOVED BY VAC-TRUCK, WAS DOUBLE WASHED WITH BIO-GENESIS SOLUTION,MANHOLE WAS RINSED BY VAC-TRUCK. QUANTITY REMOVED FROM SITE AND TYPE OF CONTAINERS USED : 1 PLASTIC BAG NON-HAZARDOUS WASTE. TRANSPORTATION TO 110 ST YARD MANHATTAN. SPILL TAG REMOVED.
Remarks:	5 gallons unknown oil on 50 gallons of water - sample taken clean up pending results - con ed #129571

Material:

Site ID:	320849
Operable Unit ID:	1090558
Operable Unit:	01
Material ID:	297300
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum

SERVICE BOX 42543 (Continued) **S104509042**

Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9911860
Investigator: COMENALE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 01/12/2000 09:45
Reported to Dept Date/Time: 01/12/00 10:42
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Contact: STEPHEN CRIBBEN
Spiller Phone: (212) 580-8576
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /

SERVICE BOX 42543 (Continued) **S104509042**

Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/12/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/18/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 5
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: 5 gallons unknown oil on 50 gallons of water - sample taken clean up pending results - con ed 129571

AB163 **WROUGHT ORIGINALS INC** **TANKS** **S110772084**
North **38 VAN SINDERIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.100 mi.
530 ft. **Site 2 of 8 in cluster AB**

Relative:
Higher

Actual:
72 ft.

TANKS:
Facility Id: 2-608012
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 592670.61103999999
UTM Y: 4503460.5004799999

AB164 **LTANKS** **S105996747**
North **38 VAN SINDEREN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
530 ft. **Site 3 of 8 in cluster AB**

Relative:
Higher

Actual:
72 ft.

LTANKS:
Site ID: 160781
Spill No: 0206144
Spill Date: 9/13/2002

(Continued) **S105996747**

Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/8/2002
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	9/13/2002
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/13/2002
Spill Record Last Update:	10/8/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	DENNIS MADIGAN
Spiller Phone:	(631) 249-3150
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135751
Remarks:	site is abandoned warehouse - after tanks were removed test results show contamination

Material:

Site ID:	160781
Operable Unit ID:	857676
Operable Unit:	01
Material ID:	516755
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported

(Continued) **S105996747**

Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AK165 **MANHOLE #67171** **NY Spills** **S106004613**
East **HINESDALE ST/DUMONT AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.101 mi.
532 ft. **Site 1 of 7 in cluster AK**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	77186
Facility Addr2:	Not reported
Facility ID:	0202830
Spill Number:	0202830
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	6/17/2002
Reported to Dept:	6/17/2002
CID:	281
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/29/2002
Remediation Phase:	0
Date Entered In Computer:	6/17/2002
Spill Record Last Update:	8/29/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ANDREW MORRIS
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	72050
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" Con Ed e2mis #143394: 6/17/02=1155HRS SILECCHIA #85203 CABLE REPORTS WHILE DOING INSPECTIONS FOUND APPROX 2-PINTS OF UNKNOWN OIL ON CONCRETE FLOOR IN MH67171 .NO SEWERS OR WATERWAYS EFFECTED NO FIRE OR SMOKE OR PRIVATE PROPERTY INVOLVED.1-SAMPLE TAKEN ENVIR TAG#05513 PLACED. INCIDENT ON 24HRS DEC PROGRAM. CLEANUP PENDING TEST RESULTS 6/17/02=1220HRS=CIG K. MCARDLE NOTIFIED. 6/17/02=1250HRS SAMPLE AT CHEM LAB. 6-17-02 20:15HRS D. LICHENSTEIN (ENV OPS) REPORTS, JUST BEFORE DOING CLEANUP HE DISCOVERED OIL TUBING LEAKING. #9 WAS NOTIFIED AND WILL GO TO LOCATION TO MAKE REPAIRS. 6-17-02 20:30HRS D.

MANHOLE #67171 (Continued) **S106004613**

LICHENSTEIN (ENV OPS) REPORTS, FOUND SOIL SUMP AND WILL CONTINUE TO DO CLEANUP, THIS JOB WILL BE TAKEN OFF THE 24HR DIMINIMIS PROGRAM. 6-17-02 20:37HRS CIG MR. MORRIS WAS NOTIFIED. UPDATE 6- 17- 02 0045 HRS AFTER CHECKING C& D PLATES FOUND THAT THE CORRECT STRUCTURE # IS MH66029. CALLED OUT TO D. LICHTENSTEIN TO CHECK E. S. TAG FOR STRUCTURE NUMBER. MANHOLE NUMBER ON TAG IS MH66029. 6/ 18/ 02= 0715HRS LAB RESULTS RETURNED 13PPM LSN-05599 UPDATE 6- 18- 02 0240 HRS D. LICHTENSTEIN MECH "A" FLUSH DEPT REPORTS CLEANUP IS COMPLETED. HE DOUBLE WASH STRUCTURE WITH BIO- JEN 760. HE REMOVED ALL SOLID AND LIQUIDS WITH HIS VACTOR. HE CEMENTED EARTHEN SUMP. SERVICE BUR REPAIRED LEAKING TUBING. THEY PLACED A C-FAULT TAG IN STRUCTURE DUE TO JOINT REGULATOR TANK HAS NO OIL IN IT. UG TO FOLLOW UP. HE REMOVED E. S. TAG # 05513. CLEANUP IS COMPLETED.

Remarks: amount reported as 2 ounces. crew on scene and cleanup is in progress and all material to be recovered. con ed # 143394.

Material:

Site ID:	77186
Operable Unit ID:	855866
Operable Unit:	01
Material ID:	520666
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AJ166 **NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN** **RCRA-NonGen** **1004755805**
WSW **364 SACKMAN ST** **FINDS** **NY0000382259**
< 1/8 **BROOKLYN, NY 11212**
0.101 mi.
533 ft. **Site 2 of 6 in cluster AJ**

Relative:
Higher

Actual:
42 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Facility address:	364 SACKMAN ST BROOKLYN, NY 11212
EPA ID:	NY0000382259
Mailing address:	SACKMAN ST BROOKLYN, NY 11212

NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN (Continued) **1004755805**

Contact: MICHAEL MOSKOWITZ
Contact address: SACKMAN ST
BROOKLYN, NY 11212
Contact country: US
Contact telephone: (212) 727-7676
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 110 LIVINGSTON ST
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 935-5010
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 110 LIVINGSTON ST
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 935-5010
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Classification: Not a generator, verified

Date form received by agency: 06/09/1995
Facility name: NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN (Continued) **1004755805**

Violation Status: No violations found

FINDS:

Registry ID: 110004317105

Environmental Interest/Information System

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

AJ167 **NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN** **ICIS** **1011626815**
WSW **364 SACKMAN ST BROOKLYN NY 11212** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.101 mi.
533 ft. **Site 3 of 6 in cluster AJ**

Relative:
Higher

Actual:
42 ft.

ICIS:

Enforcement Action ID:	02-1994-0052
FRS ID:	110004317105
Program ID:	RCRAINFO NY0000382259
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Facility Address:	364 SACKMAN ST BROOKLYN NY 11212 BROOKLYN, New York 11212
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1994-0052
FRS ID:	110004317105
Program ID:	NCES 360012102542
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	P.S. 150 CHRISTOPHER SCHOOL

NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN (Continued) **1011626815**

Facility Address:	364 SACKMAN ST BROOKLYN NY 11212 BROOKLYN, New York 11212
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3
Enforcement Action ID:	02-1994-0052
FRS ID:	110004317105
Program ID:	FRS 110004317105
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Facility Address:	364 SACKMAN ST BROOKLYN NY 11212 BROOKLYN, New York 11212
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3
Program ID:	FRS 110004317105
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Address:	364 SACKMAN ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	1795
Program ID:	NCES 360012102542
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Address:	364 SACKMAN ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	1795
Program ID:	RCRAINFO NY0000382259
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 150 BKLYN
Address:	364 SACKMAN ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	1795

AJ168 **PUBLIC SCHOOL 150 - BROOKLYN (K150)** **AST** **A100178090**
WSW **364 SACKMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.101 mi.
533 ft. **Site 4 of 6 in cluster AJ**

Relative:
Higher

Actual:
42 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605824
Program Type:	PBS
UTM X:	592583.41261999996
UTM Y:	4502520.1306400001
Expiration Date:	2016/05/03

PUBLIC SCHOOL 150 - BROOKLYN (K150) (Continued) **A100178090**

Affiliation Records:

Site Id:	27691
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5738
Phone Ext:	Not reported
Email:	JMERLO@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	3/25/2011

Site Id:	27691
Affiliation Type:	On-Site Operator
Company Name:	PUBLIC SCHOOL 150 - BROOKLYN (K150)
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	5/16/2006

Site Id:	27691
Affiliation Type:	Owner
Company Name:	NEW YORK CITY DEPT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5738
Phone Ext:	Not reported
Email:	JMERLO@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	3/25/2011

Site Id:	27691
Affiliation Type:	Emergency Contact

PUBLIC SCHOOL 150 - BROOKLYN (K150) (Continued) **A100178090**

Company Name:	NEW YORK CITY DEPT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	5/16/2006

Equipment Records:

L00 - Piping Leak Detection - None
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Info:

Tank Number:	001
Tank Id:	60528
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/2000
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	5/16/2006

AJ169 **PUBLIC SCHOOL 150** **HIST AST** **S107784567**
WSW **364 SACKMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.101 mi.
533 ft. **Site 5 of 6 in cluster AJ**

Relative:
Higher

Actual:
42 ft.

HIST AST:

PBS Number:	2-605824
SWIS Code:	6101
Operator:	PLANT OPERATION
Facility Phone:	(718) 391-6000
Facility Addr2:	Not reported
Facility Type:	SCHOOL
Emergency:	SCHOOL SAFETY
Emergency Tel:	(212) 979-3300
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	N.Y.C. BOARD OF EDUCATION
Owner Address:	28-11 QUEENS PLAZA NORTH
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 391-6832
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	FRANK CARDELLO
Mailing Name:	OFFICE OF BUILDING SERVICES
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 391-6832
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	07/10/2001
Expiration:	05/03/2006
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	7500
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	20000101
Capacity (Gal):	7500
Product Stored:	NOS 1,2, OR 4 FUEL OIL

PUBLIC SCHOOL 150 (Continued) **S107784567**

Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	1
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	1
Tank Containment:	Diking
Leak Detection:	9
Overfill Protection:	24
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

AL170 **UNK** **NY Spills** **S106467963**
South **500 JUNIUS ST** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.104 mi.
549 ft. **Site 1 of 2 in cluster AL**

Relative:
Lower

Actual:
29 ft.

NY Spills:

Site ID:	330532
Facility Addr2:	Not reported
Facility ID:	9401858
Spill Number:	9401858
Facility Type:	ER
SWIS:	2401
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	5/9/1994
Reported to Dept:	5/9/1994
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/3/1997
Remediation Phase:	0
Date Entered In Computer:	12/27/1948
Spill Record Last Update:	10/3/1997
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, ZZ

UNK (Continued) **S106467963**

Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 265867
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "XX" SPILL CLOSED DUE TO INSUFFICIENT DATA.
Remarks: Not reported

Material:
Site ID: 330532
Operable Unit ID: 998951
Operable Unit: 01
Material ID: 385604
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9401858
Investigator: XX
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/09/1994 00:00
Reported to Dept Date/Time: 05/09/94
SWIS: 61
Spiller Name: UNK
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: Air

UNK (Continued) **S106467963**

Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/03/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/27/48
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/03/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Raw Sewage
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN MATERIAL
Class Type: UNKNOWN MATERIAL
Times Material Entry In File: 9140
CAS Number: Not reported
Last Date: 19941109
DEC Remarks: SPILL CLOSED DUE TO INSUFFICIENT DATA.
Remark: Not reported

AM171 **NYCDEP** **MANIFEST** **1009244177**
NNE **30 WILLIAMS PL** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.109 mi.
574 ft. **Site 1 of 6 in cluster AM**

Relative:
Higher

Actual:
69 ft.

NY MANIFEST:
EPA ID: NYP010000214
Country: USA
Mailing Name: NYCDEP
Mailing Contact: LIONEL MACKENNE
Mailing Address: 1 CENTRE ST RM 2444
Mailing Address 2: Not reported
Mailing City: NEW YORK

NYCDEP (Continued) **1009244177**

Mailing State:	NY
Mailing Zip:	10007
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-669-8930

Document ID:	NJA0978075
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPS568
Trans2 State ID:	Not reported
Generator Ship Date:	901130
Trans1 Recv Date:	901130
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901130
Part A Recv Date:	910114
Part B Recv Date:	910103
Generator EPA ID:	NYP010000214
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90

AB172 **NYCTA - 30 HAVENS PLACE** **RCRA-NonGen** **1000890325**
NNW **30 HAVENS PL** **FINDS** **NY0000340430**
< 1/8 **BROOKLYN, NY 11233** **MANIFEST**
0.111 mi.
586 ft. **Site 4 of 8 in cluster AB**

Relative:
Higher

Actual:
73 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCTA - 30 HAVENS PLACE
Facility address:	30 HAVENS PL BROOKLYN, NY 112333408
EPA ID:	NY0000340430
Mailing address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact:	Not reported
Contact address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address: 370 JAY ST ROOM 809
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 330-4581
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address: 370 JAY ST ROOM 809
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: (718) 330-4581
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCTA - 30 HAVENS PLACE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NYCTA - 30 HAVENS PLACE
Classification: Not a generator, verified

Date form received by agency: 06/01/1994
Facility name: NYCTA - 30 HAVENS PLACE
Classification: Large Quantity Generator

Violation Status: No violations found

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

FINDS:

Registry ID: 110004315795

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NY0000340430
Country:	USA
Mailing Name:	NYCTA
Mailing Contact:	OLIVER SHOY
Mailing Address:	370 JAY ST RM 809
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-330-4581

Document ID:	NJA1967995
Manifest Status:	Completed copy
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	940920
Trans1 Recv Date:	940920
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940920
Part A Recv Date:	Not reported
Part B Recv Date:	941005
Generator EPA ID:	NY0000340430
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	16000
Units:	P - Pounds
Number of Containers:	032
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	94

Document ID:	NJA1870656
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPES58
Trans2 State ID:	Not reported

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Generator Ship Date:	940624
Trans1 Recv Date:	940624
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940624
Part A Recv Date:	940708
Part B Recv Date:	940713
Generator EPA ID:	NY0000340430
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	15900
Units:	P - Pounds
Number of Containers:	030
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	94

AB173 **NY Spills** **S105234698**
NNW **30 HAVENS PLACE** **NY Hist Spills** **N/A**
< 1/8 **BROOKLYN, NY**
0.111 mi.
586 ft. **Site 5 of 8 in cluster AB**

Relative:
Higher

Actual:
73 ft.

NY Spills:

Site ID:	289484
Facility Addr2:	Not reported
Facility ID:	0106974
Spill Number:	0106974
Facility Type:	ER
SWIS:	2401
Investigator:	DJEATON
Referred To:	Not reported
Spill Date:	10/5/2001
Reported to Dept:	10/5/2001
CID:	205
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/19/2005
Remediation Phase:	0
Date Entered In Computer:	10/5/2001
Spill Record Last Update:	12/19/2005
Spiller Name:	MIKE HEMLOCK
Spiller Company:	30 HAVENS PLACE
Spiller Address:	30 HAVENS PLACE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	CALLER

(Continued) **S105234698**

Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	234418
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE" 1K, UST, FULL HAS BEEN EXCAVATED FROM SITE. UST WAS FULL OF OLD FUEL (SPENT), WAS VACATED OUT, CLEANED, CUT, AND WILL BE REMOVED FROM SITED TODAY. CALLER THINKS CONTAMINATED SOILS ARE DUE TO LINE LEAKING DURING PAST YEARS OF DELIVERER. SOILS ARE BEING EXCAVATED, NO GW REACHED AND SOILS TO BE SAMPLED VIA 4046 TAGM. PART OF SAMPLES WILL BE TAKEN AND CLOSURE REPORT TO BE SUBMITTED TO TIPPLE FOR REVIEW. SPILLER HAS BEEN HOOKED UP TO NG FOR SOME YEARS?. RS DEC Received a tank closure report dated Nov. 15, 2001, submitted to PBS and transferred to DEC (Tipple) on Dec. 3, 2001. Referenced report is not in files, called Impact Environmental to try to obtain second copy. 12/06/05. (Eaton, Albany) No additional files available, closed spill based on tank closure information indicated above. DE
Remarks:	contaminated soil from leaking u/g tank. cleanup started.

Material:

Site ID:	289484
Operable Unit ID:	845164
Operable Unit:	01
Material ID:	531813
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0106974
Investigator:	TIPPLE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/05/2001 09:09

(Continued) **S105234698**

Reported to Dept Date/Time: 10/05/01 09:09
SWIS: 61
Spiller Name: 30 HAVENS PLACE
Spiller Contact: MIKE HEMLOCK
Spiller Phone: (718) 849-7277
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Address: 30 HAVENS PLACE
Spiller City,St,Zip: BROOKLYN, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/05/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/03/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 1K, UST, FULL HAS BEEN EXCAVATED FROM SITE. UST WAS FULL OF OLD FUEL SPENT), WAS VACATED OUT, CLEANED, CUT, AND WILL BE REMOVED FROM SITED TODAY. CALLER THINKS CONTAMINATED SOILS ARE DUE TO LINE LEAKING DURING PAST YEARS OF DELIVERER. SOILS ARE BEING EXCAVATED, NO GW REACHED AND SOILS TO BE SAMPLED VIA 4046 TAGM. PART OF SAMPLES WILL BE TAKEN AND CLOSURE REPORT TO BE SUBMITTED TO

(Continued) **S105234698**

TIPPLE FOR REVIEW. SPILLER HAS BEEN HOOKED UP TO NG FOR SOME YEARS?. RS DEC
Received a tank closure report dated Nov. 15, 2001, submitted to PBS and
transferred to DEC Tipple) on Dec. 3, 2001.
Remark: contaminated soil from leaking u/g tank. cleanup started.

AG174 **UNITY PLAZA** **LTANKS** **S101103136**
East **371 WILLIAM ST.** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.113 mi.
595 ft. **Site 5 of 9 in cluster AG**

Relative:
Lower

Actual:
33 ft.

LTANKS:

Site ID:	244105
Spill No:	9315469
Spill Date:	12/18/1990
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/7/2005
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	3/30/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/5/1994
Spill Record Last Update:	12/7/2005
Spiller Name:	Not reported
Spiller Company:	NYCHA - JOE MONTELLA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	214155
Remarks:	LEAK RATE OF +0.08 GPH - REPORTED AS PASSED BY TESTER.

Material:

Site ID:	244105
Operable Unit ID:	993570
Operable Unit:	01
Material ID:	387220
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum

UNITY PLAZA (Continued) **S101103136**

Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 244105
Spill Tank Test: 1542575
Tank Number: 001
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 9315469
Spill Date: 12/18/1990
Spill Time: 12:00
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 03/30/94
Reported to Department Time: 14:20
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYCHA - JOE MONTELLA
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (212) 306-3142
Facility Extention: Not reported
Spill Notifier: DEC

UNITY PLAZA (Continued) **S101103136**

PBS Number: 2-474169
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 04/05/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 04/05/94
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: LEAK RATE OF +0.08 GPH - REPORTED AS PASSED BY TESTER.

---

175 SSE < 1/8 0.117 mi. 619 ft. **RABEN DEMOLITION CO.** **SWF/LF** **S105841920**
434 RIVERDALE AVE **N/A**
BROOKLYN, NY 11207

Relative: Lower

Actual: 29 ft.

SWF/LF:
Flag: INACTIVE
Region Code: 2
Phone Number: Not reported
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: (UNKNOWN)
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported

RABEN DEMOLITION CO. (Continued) **S105841920**

Contact Phone:	Not reported
Activity Desc:	C&D processing - registered
Activity Number:	[24W09]
Active:	No
East Coordinate:	592997
North Coordinate:	4501836
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	None
Authorization Date:	Not reported
Expiration Date:	Not reported

176
WNW
< 1/8
0.118 mi.
621 ft.

VACANT LOT **LTANKS** **S107489258**
170-180 SACKMAN ST **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
61 ft.

LTANKS:

Site ID:	356181
Spill No:	0510241
Spill Date:	11/29/2005
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/25/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	11/29/2005
CID:	406
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/30/2005
Spill Record Last Update:	4/25/2006
Spiller Name:	KAY ZIAS
Spiller Company:	VACANT LOT
Spiller Address:	170-180 SACKMAN ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	KAY ZIAS
Spiller Phone:	(212) 312-3752
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	306251
Remarks:	While removing an underground tank found holes in the tank. The contaminated was stock piled and samples have been taken. More clean up will be done depending on the test results. Excavation was lined with plastic then filled in with clean soil.

VACANT LOT (Continued) **S107489258**

Material:

Site ID:	356181
Operable Unit ID:	1113495
Operable Unit:	01
Material ID:	2103553
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	356181
Spill Tank Test:	1549554
Tank Number:	Not reported
Tank Size:	550
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	11/30/2005
Test Method:	Unknown

AI177 **OLD AUTO SHOP** **NY Spills** **S109062554**
WSW **1827-1835 PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.118 mi.
625 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
46 ft.

NY Spills:

Site ID:	397337
Facility Addr2:	Not reported
Facility ID:	0801419
Spill Number:	0801419
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	5/6/2008
Reported to Dept:	5/6/2008
CID:	444
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

OLD AUTO SHOP (Continued) **S109062554**

Spill Closed Dt:	7/2/2008
Remediation Phase:	0
Date Entered In Computer:	5/6/2008
Spill Record Last Update:	7/2/2008
Spiller Name:	YARON ROSENTHAL
Spiller Company:	Not reported
Spiller Address:	1827-1835 PITKIN AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	YASH SAHA
Contact Phone:	(718) 636-0800
DEC Region:	2
DER Facility ID:	346765
DEC Memo:	Point of contact: HydroTech,Riachel Ataman 631.241.7401. 05/13/08 Rec'd RAP without site plan.Need Phase II report.(sr) 07/02/08 Rec'd closure report from HydroTech.Contaminated soil was removed by excavation as per RAP previously submitted to DEC.The excavation was 60'long x 15' wide x 8'-12' deep.192 tons of contaminated soil was disposed of. Two 275 gallon UST were discovered during the excavation. HydroTeck took five end point samples,four from four side walls and one from the bottom.As per HydroTech, no VOC/SVOCs were detected along the sidewalls of the four walls but bottom samples which are within TAGM range.In the Phase II investigation, no vocs were identified above TAGM 4046.HydroTech inspected the excavation for visual and olfactory evidence of contamination before taking the end point samples.PID read 0.0(zero) ppm on all the samples.Report in edocs included photographs, waste disposal manifest.NFA required.(sr)
Remarks:	FOUND CONTAMIANTED SOIL AT ABOVE ADDRESS

Material:

Site ID:	397337
Operable Unit ID:	1154307
Operable Unit:	01
Material ID:	2145097
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AM178 **MTA NYCT BUS PARKING LOT** **RCRA-NonGen** **1001818141**
North **VAN SINDEREN AVE & HERKIMER ST** **FINDS** **NYR000076257**
< 1/8 **BROOKLYN, NY 11233** **MANIFEST**
0.119 mi.
627 ft. **Site 2 of 6 in cluster AM**

Relative:
Higher

Actual:
73 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT BUS PARKING LOT
Facility address:	VAN SINDEREN AVE & HERKIMER ST BROOKLYN, NY 11233
EPA ID:	NYR000076257
Mailing address:	COLUMBUS CIR 25TH FLOOR NEW YORK, NY 10019
Contact:	WILLIAM JEHLE
Contact address:	COLUMBUS CIR 25TH FLOOR NEW YORK, NY 10019
Contact country:	US
Contact telephone:	(212) 307-6010
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	10 COLUMBUS CIR 25TH FLOOR NEW YORK, NY 10019
Owner/operator country:	US
Owner/operator telephone:	(212) 307-6010
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	10 COLUMBUS CIR 25TH FLOOR NEW YORK, NY 10019
Owner/operator country:	US
Owner/operator telephone:	(212) 307-6010
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

MTA NYCT BUS PARKING LOT (Continued) **1001818141**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: MTA NYCT BUS PARKING LOT
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Facility name: MTA NYCT BUS PARKING LOT
Site name: NYC TRANSIT AUTHORITY
Classification: Large Quantity Generator

Date form received by agency: 09/02/1999
Facility name: MTA NYCT BUS PARKING LOT
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008109590

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000076257
Country: USA
Mailing Name: NYCTA
Mailing Contact: N/S
Mailing Address: 10 COLUMBUS CIRCLE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10019
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-307-5589

Document ID: NYG1003491
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 10/22/1999
Trans1 Recv Date: 10/22/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/25/1999
Part A Recv Date: Not reported

MTA NYCT BUS PARKING LOT (Continued) **1001818141**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99

Document ID:	NYG2608209
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2000
Trans1 Recv Date:	07/28/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/01/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01800
Units:	P - Pounds
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00

Document ID:	NYG1059228
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/2000
Trans1 Recv Date:	03/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002

MTA NYCT BUS PARKING LOT (Continued) **1001818141**

Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00

Document ID:	NYG1812906
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2000
Trans1 Recv Date:	10/20/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PP5193NY
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00

Document ID:	NYG2568537
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	05/05/2000
Trans1 Recv Date:	05/05/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1010
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00020
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00

AM179 **CON EDISON** **RCRA-NonGen** **1010327678**
North **HERKIMER 60 FEET E OF VAN** **MANIFEST** **NYP004148136**
< 1/8 **BROOKLYN, NY 11203**
0.119 mi.
627 ft. **Site 3 of 6 in cluster AM**

Relative:
Higher

Actual:
73 ft.

RCRA-NonGen:

Date form received by agency:	04/11/2007
Facility name:	CON EDISON
Facility address:	HERKIMER 60 FEET E OF VAN SINDEREN AVE BROOKLYN, NY 11203
EPA ID:	NYP004148136
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL DAUGHTREY
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/10/2007
Facility name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	04/09/2007
Facility name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004148136
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PL RM 828

CON EDISON (Continued) **1010327678**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2/13/2007
Trans1 Recv Date:	2/13/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148136
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001436016FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-02-13
Trans1 Recv Date:	2007-02-13
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148136
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **1010327678**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001436016FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AM180 **CON EDISON MANHOLE 65390** **RCRA-NonGen** **1010327680**
North **HERKIMER ST 160 FEET W OF VAN** **MANIFEST** **NYP004148144**
< 1/8 **BROOKLYN, NY 11203**
0.119 mi.
627 ft. **Site 4 of 6 in cluster AM**

Relative:
Higher

Actual:
73 ft.

RCRA-NonGen:

Date form received by agency:	04/11/2007
Facility name:	CON EDISON MANHOLE 65390
Facility address:	HERKIMER ST & VAN SINDEREN AVE 160 FT W OF VAN SINDEREN AVE BROOKLYN, NY 11203
EPA ID:	NYP004148144
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL DAUGHTREY
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON MANHOLE 65390 (Continued) **1010327680**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/10/2007
Facility name: CON EDISON MANHOLE 65390
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 04/09/2007
Facility name: CON EDISON MANHOLE 65390
Site name: CON EDISON
Classification: Unverified

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYP004148144
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2/13/2007
Trans1 Recv Date: 2/13/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004148144
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 50
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1

CON EDISON MANHOLE 65390 (Continued) **1010327680**

Year:	07
Manifest Tracking Num:	001436014FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-02-13
Trans1 Recv Date:	2007-02-13
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148144
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001436014FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AH181 **INSTITUTE FOR COMMUNITY LIVING, INC.** **UST** **U002170635**
WNW **2384 ATLANTIC AVENUE** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.119 mi.
628 ft. **Site 4 of 8 in cluster AH**

Relative:
Higher

Actual:
72 ft.

UST:

Facility Id:	2-602054
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592455.01815999998
UTM Y:	4503311.1852000002

Affiliation Records:

Site Id:	24013
Affiliation Type:	Owner
Company Name:	EASTERN INDUSTRIAL DEVELOPMENT CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	655 PELHAM PARKWAY NORTH
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10467
Country Code:	001
Phone:	(718) 654-5959
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/22/2010

Site Id:	24013
Affiliation Type:	Mail Contact
Company Name:	INSTITUTE FOR COMMUNITY LIVING, INC.
Contact Type:	Not reported
Contact Name:	PAT VALERIO
Address1:	40 RECTOR STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10006
Country Code:	001
Phone:	(212) 385-3030
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/22/2010

Site Id:	24013
Affiliation Type:	Emergency Contact
Company Name:	EASTERN INDUSTRIAL DEVELOPMENT CORPORATION
Contact Type:	Not reported
Contact Name:	CHRISTOPHER HEIGHTER
Address1:	Not reported
Address2:	Not reported

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **U002170635**

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 219-8991
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/22/2010

Site Id: 24013
Affiliation Type: On-Site Operator
Company Name: INSTITUTE FOR COMMUNITY LIVING, INC.
Contact Type: Not reported
Contact Name: CHRISTOPHER HEIGHTER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 219-8991
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/22/2010

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
J02 - Dispenser - Suction

Tank Info:
Site ID: 24013

Tank Number: 001
Tank ID: 48948
Tank Status: Closed - Removed
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1080
Tightness Test Method: 21
Next Test Date: Not reported
Date Tank Closed: 10/19/2006
Tank Location: 5
Tank Type: Steel/carbon steel

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **U002170635**

Date Test: 3/22/2001
Register: True
Modified By: NRLOMBAR
Last Modified: 1/22/2010

HIST UST:
PBS Number: 2-602054
SPDES Number: Not reported
Emergency Contact: DEAN PETERSON
Emergency Telephone: (718) 442-3643
Operator: DEAN PETERSON
Operator Telephone: (718) 234-0073
Owner Name: EASTERN INDUSTRIAL DEVELOPMENT CORPORATION
Owner Address: 655 PELHAM PARKWAY NORTH
Owner City,St,Zip: BRONX, NY 10467
Owner Telephone: (718) 654-5959
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: INSTITUTE FOR COMMUNITY LIVING, INC.
Mailing Address: 40 RECTOR ST.
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10006
Mailing Contact: ROBERT TURRENTINE
Mailing Telephone: (212) 385-3030
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: Not reported
SWIS ID: 6101
Old PBS Number: Not reported
Facility Type: MANUFACTURING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 07/21/2000
Expiration Date: 01/07/2005
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 3000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **U002170635**

Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge, Vent Whistle
Dispenser:	Suction
Date Tested:	07/01/1994
Next Test Date:	07/01/1999
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

AH182 **2384 ATLANTIC AVE** **LTANKS** **S101174394**
WNW **2384 ATLANTIC AVE** **HIST LTANKS** **N/A**
< 1/8 **BROOKLYN, NY**
0.119 mi.
628 ft. **Site 5 of 8 in cluster AH**

Relative:
Higher

Actual:
72 ft.

LTANKS:

Site ID:	69637
Spill No:	9402632
Spill Date:	5/23/1994
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/18/2003
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	5/23/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/8/1994
Spill Record Last Update:	2/18/2003
Spiller Name:	Not reported
Spiller Company:	APT BLDG - HOWIE
Spiller Address:	2384 ATLANTIC AVE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller County:	001

2384 ATLANTIC AVE (Continued) **S101174394**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 66192
Remarks: PUMPING TANK OUT TODAY. (TANK NOT REGISTERED)

Material:
Site ID: 69637
Operable Unit ID: 999695
Operable Unit: 01
Material ID: 553954
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 69637
Spill Tank Test: 1542768
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 9402632
Spill Date: 05/23/1994
Spill Time: 12:30
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: MARTINKATXX
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported

2384 ATLANTIC AVE (Continued) **S101174394**

Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 05/23/94
Reported to Department Time: 15:42
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: APT BLDG - HOWIE
Spiller Address: 2384 ATLANTIC AVE
Spiller City,St,Zip: BROOKLYN
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (718) 346-4327
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 06/08/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/06/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: INSUFFICIENT INFORMATION
Spill Cause: PUMPING TANK OUT TODAY. TANK NOT REGISTERED)

AH183 **INSTITUTE FOR COMMUNITY R** **LTANKS** **S107523505**
WNW **2384 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.119 mi.
628 ft. **Site 6 of 8 in cluster AH**

Relative:
Higher

Actual:
72 ft.

LTANKS:

Site ID:	358824
Spill No:	0512499
Spill Date:	1/27/2006
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/6/2006
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	1/27/2006
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/27/2006
Spill Record Last Update:	10/6/2006
Spiller Name:	BOB TURRENTINE
Spiller Company:	INSTITUTE FOR COMMUNITY R
Spiller Address:	2384 ATLANTIC AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001
Spiller Contact:	BOB TURRENTINE
Spiller Phone:	(212) 385-3030
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	66192
Remarks:	Not reported

Material:

Site ID:	358824
Operable Unit ID:	1116051
Operable Unit:	01
Material ID:	2106175
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

INSTITUTE FOR COMMUNITY R (Continued) **S107523505**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AL184 **PALAGONIA JMP BAKERY CO** **FINDS** **1007810839**
South **508 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.120 mi.
633 ft. **Site 2 of 2 in cluster AL**

Relative:
Lower

Actual:
29 ft.

FINDS:

Registry ID: 110019733797

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AH185 **OUR LADY OF LORETO CHURCH** **UST** **U000402330**
West **124 SACKMAN ST** **HIST UST** **N/A**
< 1/8 **BROOKLYN, NY 11233** **NY Spills**
0.120 mi.
636 ft. **Site 7 of 8 in cluster AH**

Relative:
Higher

Actual:
69 ft.

UST:

Facility Id:	2-237973
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	1992/07/20
UTM X:	592442.38818000001
UTM Y:	4503262.6994500002

Affiliation Records:

Site Id:	8893
Affiliation Type:	Emergency Contact
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	DIOCESE OF BROOKLYN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Country Code:	001
Phone:	(718) 628-5500
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8893
Affiliation Type:	Owner
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	124 SACKMAN ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 385-3740
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/6/2011

Site Id:	8893
Affiliation Type:	On-Site Operator
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	OUR LADY OF LORETO CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 385-3740
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	8893
Affiliation Type:	Mail Contact
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	124 SACKMAN STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 385-3740
Phone Ext:	Not reported

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/6/2011

Equipment Records:

H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I00 - Overfill - None
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction

Tank Info:
Site ID: 8893

Tank Number: 001
Tank ID: 17345
Tank Status: In Service
Tank Model: Not reported
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4800
Tightness Test Method: 00
Next Test Date: 12/27/1987
Date Tank Closed: Not reported
Tank Location: 5
Tank Type: Steel/carbon steel
Date Test: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 3/4/2004

HIST UST:
PBS Number: 2-237973
SPDES Number: Not reported
Emergency Contact: DIOCESE OF BROOKLYN
Emergency Telephone: (718) 628-5500
Operator: OUR LADY OF LORETO CHURCH
Operator Telephone: (718) 385-3740
Owner Name: OUR LADY OF LORETO CHURCH
Owner Address: 124 SACKMAN ST
Owner City,St,Zip: BROOKLYN, NY 11233
Owner Telephone: (718) 385-3740
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: OUR LADY OF LORETO CHURCH
Mailing Address: 124 JACKMAN ST
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11233
Mailing Contact: Not reported
Mailing Telephone: (718) 385-3740
Owner Mark: First Owner

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	124 SACKMAN ST
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/20/1987
Expiration Date:	07/20/1992
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	4800
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	4800
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	12/27/1987
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

NY Spills:

Site ID:	444009
Facility Addr2:	Not reported

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Facility ID:	1010406
Spill Number:	1010406
Facility Type:	ER
SWIS:	2401
Investigator:	HRAHMED
Referred To:	Not reported
Spill Date:	1/5/2011
Reported to Dept:	1/5/2011
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	1/5/2011
Spill Record Last Update:	1/6/2011
Spiller Name:	MOHAMMED AHMED
Spiller Company:	OUR LADY OF LORETO CHURCH
Spiller Address:	124 SACKMAN ST
Spiller City,St,Zip:	BROOKLYN, NY 11233
Spiller Company:	999
Contact Name:	MOHAMMED AHMED
Contact Phone:	(212) 675-3225
DEC Region:	2
DER Facility ID:	8881
DEC Memo:	1/6/11-Vought-Primary off hours responder. Vought called FLS (Mohammed Ahmed 212-675-3225) and left message to return call to DEC Vought. As per PBS #2-237973 tank has 5000-gallon #2 fuel oil UST and site is owned by: Our Lady Of Loreto Church 124 Sackman Street Brooklyn, NY 11233 Ph: (718)387-3740 Vought spoke to RSE and spill assigned to DEC Ahmed as secondary off-hours responder. Vought to send out CSL with possible additional requirements upon callback from FLS Ahmed. Vought received callback from and spoke to FLS Ahmed who noted that he was hired by property developer (Reese & Sons) and that the property was to be developed for affordable housing units. They were onsite to remove an abandoned 4,800-gallon fuel oil UST (See PBS #2-237973) and noted contaminated soil around "and below" the tank. Vought noted that DEC Ahmed was the project manager and that CSL would be drafted by Vought and signed by Ahmed. Vought drafted CSL with one month due date and the following requirements: 1)delineation of soil and groundwater (if applicable) contamination 2)collection of endpoint samples 3)strong recommendation for installation of SSDS and VB 4)Updating PBS Registration 2-237973 to reflect current closed status of UST (as per DEC Falvey this was required, PBS registration also expired as of 7/20/92). 5)cc to FLS Ahmed 6)advisement that site should not be developed until RAP approved by DEC. Vought sent letter with above requirements to address provided by FLS Ahmed: Our Lady of Loreto Catholic Church c/o Progress of Peoples Development Corporation 191 Joralemon Street Brooklyn, NY 11201 Attention: Claire Hilger

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Remarks: Contaminated soil found at construction site. Cleanup pending assessment and pre-plan.

Material:
Site ID: 444009
Operable Unit ID: 1194454
Operable Unit: 01
Material ID: 2190280
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AC186 **DLX INDUSTRIES INC** **FINDS** **1010012901**
East **1970 PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.123 mi.
650 ft. **Site 5 of 7 in cluster AC**

Relative: Higher

Actual: 39 ft.

FINDS:

Registry ID: 110028280508

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AC187 **D L X INDUSTRIES** **RCRA-SQG** **1010327963**
East **1970 INDUSTIAL PARK RD** **MANIFEST** **NYR000140855**
< 1/8 **BROOKLYN, NY 11207**
0.123 mi.
650 ft. **Site 6 of 7 in cluster AC**

Relative:
Higher

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	D L X INDUSTRIES
Facility address:	1970 INDUSTIAL PARK RD BROOKLYN, NY 11207
EPA ID:	NYR000140855
Mailing address:	INDUSTIAL PARK RD BROOKLYN, NY 11207
Contact:	PHIL STERN
Contact address:	INDUSTIAL PARK RD BROOKLYN, NY 11207
Contact country:	US
Contact telephone:	(718) 522-6630
Contact email:	Not reported
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	D L X INDUSTRIES
Owner/operator address:	INDUSTRIAL PARK RD BROOKLYN, NY 11207
Owner/operator country:	US
Owner/operator telephone:	(718) 522-6630
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/30/2006
Owner/Op end date:	Not reported

Owner/operator name:	MARK STEWART
Owner/operator address:	INDUSTRIAL PARK RD BROOKLYN, NY 11207
Owner/operator country:	US
Owner/operator telephone:	(718) 522-6630
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/30/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

D L X INDUSTRIES (Continued) **1010327963**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/30/2006
Facility name: D L X INDUSTRIES
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/29/2006
Facility name: D L X INDUSTRIES
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000140855
Country: USA
Mailing Name: DLX INDUSTRIES
Mailing Contact: PHILIP STERN
Mailing Address: 1970 INDUSTRIAL PARK ROAD
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-522-6630

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAC300001617
Trans2 State ID: NYD982792814
Generator Ship Date: 4/9/2007
Trans1 Recv Date: 4/9/2007
Trans2 Recv Date: 4/13/2007
TSD Site Recv Date: 4/17/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000140855
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: IND000646943
Waste Code: Not reported
Quantity: 275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 5
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 07
Manifest Tracking Num: 100040968CTN

D L X INDUSTRIES (Continued) **1010327963**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300001617
Trans2 State ID:	NYD982792814
Generator Ship Date:	2008-01-21
Trans1 Recv Date:	2008-01-21
Trans2 Recv Date:	2008-01-23
TSD Site Recv Date:	2008-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000140855
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	IND000646943
Waste Code:	Not reported
Quantity:	1375.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	002662958JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300001617
Trans2 State ID:	NYD982792814
Generator Ship Date:	2008-01-21
Trans1 Recv Date:	2008-01-21
Trans2 Recv Date:	2008-01-23
TSD Site Recv Date:	2008-01-28

D L X INDUSTRIES (Continued) **1010327963**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000140855
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	IND000646943
Waste Code:	Not reported
Quantity:	1375.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	002662958JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	NYG1921626
Manifest Status:	Not reported
Trans1 State ID:	MAC300001617
Trans2 State ID:	NYD982792814
Generator Ship Date:	07/24/2006
Trans1 Recv Date:	07/24/2006
Trans2 Recv Date:	07/27/2006
TSD Site Recv Date:	07/31/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000140855
Trans1 EPA ID:	MA66068
Trans2 EPA ID:	AK39287NY
TSDF ID:	IND000646943
Waste Code:	F003 - UNKNOWN
Quantity:	00560
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300001617
Trans2 State ID:	NYD982792814
Generator Ship Date:	2008-01-21

D L X INDUSTRIES (Continued) **1010327963**

Trans1 Recv Date:	2008-01-21
Trans2 Recv Date:	2008-01-23
TSD Site Recv Date:	2008-01-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000140855
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	IND000646943
Waste Code:	Not reported
Quantity:	1375.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	002662958JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H020

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300001617
Trans2 State ID:	NYD982792814
Generator Ship Date:	2007-04-09
Trans1 Recv Date:	2007-04-09
Trans2 Recv Date:	2007-04-13
TSD Site Recv Date:	2007-04-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000140855
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	IND000646943
Waste Code:	Not reported
Quantity:	275.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	5.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	100040968CTN
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

D L X INDUSTRIES (Continued) **1010327963**

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

AC188 **DISPLAY CREATIONS-1970 INDUSTRIAL PK RD** **FINDS** **1005900346**
East **1970 INDUSTRIAL PARK ROAD** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.123 mi.
650 ft. **Site 7 of 7 in cluster AC**

Relative:
Higher

Actual:
39 ft.

FINDS:

Registry ID: 110012158930

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AF189 **JUNIORS CLEANERS** **RCRA-NonGen** **1004758995**
East **531 SUTTER AVE** **FINDS** **NYD987035011**
< 1/8 **BROOKLYN, NY 11208**
0.125 mi.
660 ft. **Site 3 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: JUNIORS CLEANERS
Facility address: 531 SUTTER AVE
BROOKLYN, NY 11208
EPA ID: NYD987035011
Mailing address: SUTTER AVE
BROOKLYN, NY 11208
Contact: FREDDY DIAZ
Contact address: SUTTER AVE
BROOKLYN, NY 11208
Contact country: US
Contact telephone: (718) 647-3421

JUNIORS CLEANERS (Continued) **1004758995**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: FREDDY DIAZ
Owner/operator address: 531 SUTTER AVE
BROOKLYN, NY 11208
Owner/operator country: US
Owner/operator telephone: (718) 647-3421
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FREDDY DIAZ
Owner/operator address: 531 SUTTER AVE
BROOKLYN, NY 11208
Owner/operator country: US
Owner/operator telephone: (718) 647-3421
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: JUNIORS CLEANERS
Classification: Not a generator, verified

Date form received by agency: 06/02/1993
Facility name: JUNIORS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

JUNIORS CLEANERS (Continued) **1004758995**

Registry ID: 110004505296

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AB190 **E B C HIGH SCHOOL FOR PUBLIC SAFETY** **FINDS** **1011460310**
NNW **1495 HERKIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.127 mi.
668 ft. **Site 6 of 8 in cluster AB**

Relative: Higher

Actual: 74 ft.

FINDS:

Registry ID: 110036081557

Environmental Interest/Information System
NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

AM191 **HERKIMER STREET YARD** **RCRA-NonGen** **1000270478**
NNE **HERKIMER & WILLIAMS ST** **FINDS** **NYD982183287**
1/8-1/4 **BROOKLYN, NY 11207** **MANIFEST**
0.127 mi.
668 ft. **Site 5 of 6 in cluster AM**

Relative: Higher

Actual: 71 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCT HERKIMER STREET YARD
Facility address:	HERKIMER & WILLIAMS ST BROOKLYN, NY 11207
EPA ID:	NYD982183287
Mailing address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact:	Not reported
Contact address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYC TRANSIT AUTHORITY
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999

HERKIMER STREET YARD (Continued) **1000270478**

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC TRANSIT AUTHORITY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCT HERKIMER STREET YARD
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NYCT HERKIMER STREET YARD
Classification: Not a generator, verified

Date form received by agency: 05/12/1987
Facility name: NYCT HERKIMER STREET YARD
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008024814

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

HERKIMER STREET YARD (Continued) **1000270478**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD982183287
Country:	USA
Mailing Name:	NYCTA
Mailing Contact:	N/S
Mailing Address:	370 JAY ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-852-4134

Document ID:	NJA0293567
Manifest Status:	Completed copy
Trans1 State ID:	NJWSASX30
Trans2 State ID:	Not reported
Generator Ship Date:	870612
Trans1 Recv Date:	870612
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870612
Part A Recv Date:	870623
Part B Recv Date:	870624
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00825
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	015
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110

HERKIMER STREET YARD (Continued) **1000270478**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	87

Document ID:	NJA0571044
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	890317
Trans1 Recv Date:	890317
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890317
Part A Recv Date:	890324
Part B Recv Date:	890324
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	X910 - NJ UNKNOWN
Quantity:	04800
Units:	P - Pounds
Number of Containers:	016
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	03600
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

HERKIMER STREET YARD (Continued) **1000270478**

Waste Code:	Not reported
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89

Document ID:	NJA0571115
Manifest Status:	Completed copy
Trans1 State ID:	NJSWA3002
Trans2 State ID:	Not reported
Generator Ship Date:	890331
Trans1 Recv Date:	890331
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890331
Part A Recv Date:	890410
Part B Recv Date:	890407
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	X721 - WASTE OIL FROM GAS STATION (NJ ONLY)
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00385
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels

HERKIMER STREET YARD (Continued) **1000270478**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89

Document ID:	NJA0453469
Manifest Status:	Completed copy
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	890414
Trans1 Recv Date:	890414
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890414
Part A Recv Date:	890421
Part B Recv Date:	890427
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89

AM192 **NYC TRANSIT CPM ENV-MTA NYT BUS PKG LOT** **MANIFEST** **S108933828**
NNE **WILLIAMS PL & HERKIMER** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.127 mi.
668 ft. **Site 6 of 6 in cluster AM**

Relative:
Higher

Actual:
71 ft.

NY MANIFEST:

EPA ID:	NYD000076257
Country:	USA
Mailing Name:	NYC TRANSIT CPM ENV-MTA NYT BUS PKG LOT
Mailing Contact:	LOU DEFORTE
Mailing Address:	2 BROADWAY 2ND FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	646-252-3500

NY MANIFEST:

No Manifest Records Available

AN193 **NYCHA - SETH LOW HOUSES** **RCRA-NonGen** **1001493632**
WSW **131 BELMONT AVE** **FINDS** **NYR000075234**
1/8-1/4 **BROOKLYN, NY 11212** **MANIFEST**
0.127 mi.
669 ft. **Site 1 of 2 in cluster AN**

Relative:
Higher

Actual:
43 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYCHA - SETH LOW HOUSES
Facility address:	131 BELMONT AVE BROOKLYN, NY 112122516
EPA ID:	NYR000075234
Mailing address:	BROADWAY NEW YORK, NY 100072516
Contact:	FRANK OCELLO
Contact address:	BROADWAY NEW YORK, NY 100072516
Contact country:	US
Contact telephone:	(212) 306-3229
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYCHA
Owner/operator address:	250 BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	(212) 306-3229
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NYCHA
Owner/operator address:	250 BROADWAY NEW YORK, NY 10007
Owner/operator country:	US
Owner/operator telephone:	(212) 306-3229
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

NYCHA - SETH LOW HOUSES (Continued) **1001493632**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - SETH LOW HOUSES
Classification: Not a generator, verified

Date form received by agency: 08/12/1999
Facility name: NYCHA - SETH LOW HOUSES
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004555525

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000075234
Country: USA
Mailing Name: SETH LOW HOUSES
Mailing Contact: V DIVIRILIO
Mailing Address: 131 BELMONT AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11211
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 718-498-9229

Document ID: NYG1710009
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 12/15/1999
Trans1 Recv Date: 12/15/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/16/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000075234
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: PD1011NY

NYCHA - SETH LOW HOUSES (Continued) **1001493632**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	99

Document ID:	NYG1711935
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2000
Trans1 Recv Date:	02/10/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075234
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00

AB194 **NY Spills** **S104790043**
NNW **1 HAVENS PL** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.128 mi.
677 ft. **Site 7 of 8 in cluster AB**

Relative:
Higher

Actual:
75 ft.

NY Spills:

Site ID:	263609
Facility Addr2:	Not reported
Facility ID:	0007586
Spill Number:	0007586

(Continued) **S104790043**

Facility Type:	ER
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Spill Date:	9/28/2000
Reported to Dept:	9/28/2000
CID:	312
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt:	9/10/2002
Remediation Phase:	0
Date Entered In Computer:	9/28/2000
Spill Record Last Update:	9/10/2002
Spiller Name:	IRA TURRET
Spiller Company:	CARAVAN TRANSPORTATION
Spiller Address:	141 PILING STR
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	214893
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE" LOT WAS A REPAIR SHOP. ACCORDING TO NYCT, LOT CONTAINED APPROX. 20 DRUMS OF WASTE OIL. NYCT WAS SUPPOSED TO START USING THE LOT TODAY TO STORE BUSES, WHEN THEY NOTICED THAT MOST OF THE DRUMS WERE GONE EXCEPT FOR A FEW CRUSHED ONES. THERE APPEARED TO BE STAINING AROUND THE STORM WATER DRAIN ON THE PROERTY. NYCT (SANJIV'S PAGER # 917-651-4670) OBSERVED SERVERAL INCHES OF WASTE OIL IN THE STORM WATER DRAIN. DEP NOTIFIED. DEP REQUESTED THAT I NOTIFY ENCON POLICE. 9/29/00 SITE VISIT. MET WITH SANJIV KURAY (NYCT), CECIL MORRIS (CARAVAN TRANSPORTATION), ALDO VASAPOLLI (CONTRACTOR), MARK TIBBE (DEC). MR. VASAPOLLI INFORMED TIBBE THAT THERE WERE SEVERAL DRUMS ONSITE THAT HIS COMPANY TOOK DURING THE CLEANING OF THE LOT. MOST OF THEM WERE EMPTY AND WERE TAKEN BACK TO HIS YARD. ONE CONTAINED WATER, ONE CONTAINED ANTI-FREEZE, ONE CONTAINED WINDSHIELD WASHER FLUID, ONE CONTAINED A LITTLE WASTE OIL AND TWO CONTAINED WHAT APPEARED TO HYDRALIC OR TRANSMISSION FLUID. NONE OF THE DRUMS WERE FULL. ACCORDING TO MR. VASAPOLLI, ALL BUT THE HYDRALIC FLUID WERE DUMPED IN THE STORM WATER DRAIN ON THE PROPERTY. THE HYDRALIC OIL DRUMS WERE PUNCTURED BY THE BACKHOE WHILE IT WAS CLEANING SOME DEBRIS. THE RESULTING SPILL WAS SWEPT INTO THE SAME DRAIN. TIBBE PLACED A CALL TO IRA TURRET (OWNERS ATTORNEY) AND INFORMED HIM THE THE SPILL AND THE DRAIN WOULD HAVE TO BE CLEANED. HE INFORMED TIBBE THAT HE WAS ALREADY WORKING ON GETTING A CONTRACTOR, BUT HE WOULD LIKE A LETTER DIRECTING THEM WHAT TO DO. THE OWNER OF THE PROPERTY IS LAWRENCE GREEN. As per 10/19/00 letter from Ira Turret, the spill was cleaned by Dola Construction.

(Continued) **S104790043**

Remarks: PARKING LOT - NYC TRANSIT WAS SUPPOSED TO OCCUPY THIS TODAY, BUT THERE A LOT OF DRUMS ON SITE - SUBJ MAY HAVE DUMPED THE OIL INTO SEWER

Material:
Site ID: 263609
Operable Unit ID: 828340
Operable Unit: 01
Material ID: 545120
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0007586
Investigator: TIBBE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/28/2000 09:10
Reported to Dept Date/Time: 09/28/00 09:46
SWIS: 61
Spiller Name: Not reported
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False

(Continued) **S104790043**

Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/28/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/28/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927
DEC Remarks: LOT WAS A REPAIR SHOP. ACCORDING TO NYCT, LOT CONTAINED APPROX. 20 DRUMS OF WASTE OIL. NYCT WAS SUPPOSED TO START USING THE LOT TODAY TO STORE BUSES, WHEN THEY NOTICED THAT MOST OF THE DRUMS WERE GONE EXCEPT FOR A FEW CRUSHED ONES. THERE APPEAREDTO BE STAINING AROUND THE STORM WATER DRAIN ON THE PROERTY. NYCT SANJIV S PAGER 917-651-4670) OBSERVED SERVERAL INCHES OF WASTE OIL IN THE STORM WATER DRAIN. DEP NOTIFIED. DEP REQUESTED THAT I NOTIFY ENCON POLICE. 9/29/00 SITE VISIT. MET WITH SANJIV KURAY NYCT), CECIL MORRIS CARAVAN TRANSPORTATION), ALDO VASAPOLLI CONTRACTOR), MARK TIBBE DEC). MR. VASAPOLLI INFORMED TIBBE THAT THERE WERE SEVERAL DRUMS ONSITE THAT HIS COMPANY TOOK DURING THE CLEANING OF THE LOT. MOST OF THEM WEREEMPTY AND WERE TAKEN BACK TO HIS YARD. ONE CONTAINED WATER, ONE CONTAINED ANTI-FREEZE, ONE CONTAINED WINDSHIELD WASHER FLUID, ONE CONTAINED A LITTLE WASTE OIL AND TWO CONTAINED WHAT APPEARED TO HYDRALIC OR TRANSMISSION FLUID. NONE OF THE DRUMS WEREFULL. ACCORDING TO MR. VASAPOLLI, ALL BUT THE HYDRALIC FLUID WERE DUMPED IN THE STORM WATER DRAIN ON THE PROPERTY. THE HYDRALIC OIL DRUMS WERE PUNCTURED BY THE BACKHOE WHILE IT WAS CLEANING SOME DEBRIS. THE RESULTING SPILL WAS SWEPT INTO THE SAME DRAIN. TIBBE PLACED A CALL TO IRA TURRET OWNERS ATTORNEY) AND INFORMED HIM THE THE SPILL AND THE DRAIN WOULD HAVE TO BE CLEANED. HE INFORMED TIBBE THAT HE WAS ALREADY WORKING ON GETTING A CONTRACTOR, BUT HE WOULD LIKE A LETTER DIRECTING THEM WHAT TO DO. THE OWNER OF THE PROPERTY IS LAWRENCE GREEN.
Remark: PARKING LOT - NYC TRANSIT WAS SUPPOSED TO OCCUPY THIS TODAY, BUT THERE A LOT OF DRUMS ON SITE - SUBJ MAY HAVE DUMPED THE OIL INTO SEWER

AB195 **CON EDISON** **RCRA-NonGen** **1010327676**
NNW **INT OF HERKIMER & HAVENS PL** **MANIFEST** **NYP004148128**
1/8-1/4 **BROOKLYN, NY 11203**
0.131 mi.
690 ft. **Site 8 of 8 in cluster AB**

Relative:
Higher

Actual:
75 ft.

RCRA-NonGen:

Date form received by agency:	04/11/2007
Facility name:	CON EDISON
Facility address:	INT OF HERKIMER & HAVENS PL BROOKLYN, NY 11203
EPA ID:	NYP004148128
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	MICHAEL DAUGHTREY
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	(212) 580-8383
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/10/2007
Facility name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	04/09/2007
Facility name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004148128
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PL RM 828
Mailing Address 2:	Not reported

CON EDISON (Continued) **1010327676**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2/13/2007
Trans1 Recv Date:	2/13/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148128
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001436015FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-02-13
Trans1 Recv Date:	2007-02-13
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148128
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **1010327676**

TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	001436015FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AO196 **MANHOLE 3896** **NY Spills** **S104283081**
WSW **392 BLAKE AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.137 mi.
725 ft. **Site 1 of 4 in cluster AO**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	366758
Facility Addr2:	Not reported
Facility ID:	0603908
Spill Number:	0603908
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	7/9/2006
Reported to Dept:	7/9/2006
CID:	71
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/21/2006
Remediation Phase:	0
Date Entered In Computer:	7/10/2006
Spill Record Last Update:	12/21/2006
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE

MANHOLE 3896 (Continued) **S104283081**

Spiller City,St,Zip:	NEW YORK, NY 10038
Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	61380
DEC Memo:	12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. 201010. see eDocs.
Remarks:	1 PT UNKN OIL ON 500 GAL WATER - OLFF 72 HR. CLOCK. CON ED REF 201010

Material:

Site ID:	366758
Operable Unit ID:	1124689
Operable Unit:	01
Material ID:	2114185
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	63566
Facility Addr2:	Not reported
Facility ID:	9908606
Spill Number:	9908606
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	10/15/1999
Reported to Dept:	10/15/1999
CID:	211
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended

MANHOLE 3896 (Continued) **S104283081**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/21/2002
Remediation Phase:	0
Date Entered In Computer:	10/15/1999
Spill Record Last Update:	2/22/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MARK SCHLAGEL
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	61380
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"
Remarks:	1 pint of product on 200 gals water - clean up pending lab results con ed 128450

Material:

Site ID:	63566
Operable Unit ID:	1082877
Operable Unit:	01
Material ID:	555924
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	9908606
Investigator:	ENGELHARDT
Caller Name:	Not reported

MANHOLE 3896 (Continued) **S104283081**

Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/15/1999 09:40
Reported to Dept Date/Time:	10/15/99 10:44
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported
Spiller Phone:	( ) -
Spiller Contact:	MARK SCHLAGEL
Spiller Phone:	(212) 580-6763
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	10/15/99
Date Spill Entered In Computer Data File:	Not reported
Update Date:	10/18/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	1
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	UNKNOWN PETROLEUM
Class Type:	UNKNOWN PETROLEUM
Times Material Entry In File:	16414
CAS Number:	Not reported

MANHOLE 3896 (Continued) **S104283081**

Last Date: 19940929
DEC Remarks: Not reported
Remark: 1 pint of product on 200 gals water - clean up pending lab results con ed 128450

AO197 **CON EDISON MANHOLE 3896** **RCRA-NonGen** **1010327336**
WSW **392 BLAKE AVE** **MANIFEST** **NYP004145868**
1/8-1/4 **BROOKLYN, NY 11208**
0.139 mi.
734 ft. **Site 2 of 4 in cluster AO**

Relative:
Higher

Actual:
39 ft.

RCRA-NonGen:
Date form received by agency: 01/11/2007
Facility name: CON EDISON MANHOLE 3896
Facility address: 392 BLAKE AVE
BROOKLYN, NY 11208
EPA ID: NYP004145868
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: PAUL WALSH
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/10/2007
Facility name: CON EDISON MANHOLE 3896
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 01/09/2007
Facility name: CON EDISON MANHOLE 3896
Site name: CON EDISON
Classification: Unverified

CON EDISON MANHOLE 3896 (Continued) **1010327336**

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004145868
Country:	USA
Mailing Name:	CONED
Mailing Contact:	CONED
Mailing Address:	31-01 20TH AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11105
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-204-4090

NY MANIFEST:

No Manifest Records Available

AO198 **CON EDISON** **FINDS** **1010499564**
WSW **392 BLAKE AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.139 mi.
734 ft. **Site 3 of 4 in cluster AO**

Relative:
Higher

Actual:
39 ft.

FINDS:

Registry ID: 110031433884

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AD199 **NYC FACILITY** **NY Spills** **S109206465**
East **72 WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.143 mi.
754 ft. **Site 2 of 2 in cluster AD**

Relative:
Higher

Actual:
57 ft.

NY Spills:

Site ID:	401576
Facility Addr2:	Not reported
Facility ID:	0804634
Spill Number:	0804634
Facility Type:	ER
SWIS:	2401
Investigator:	smsanges
Referred To:	Not reported
Spill Date:	7/23/2008
Reported to Dept:	7/23/2008
CID:	444

NYC FACILITY (Continued) **S109206465**

Spill Cause:	Other
Water Affected:	SEWER
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Spill Closed Dt:	7/28/2008
Remediation Phase:	0
Date Entered In Computer:	7/23/2008
Spill Record Last Update:	7/28/2008
Spiller Name:	KEITH WILLIAMS
Spiller Company:	NYC FACILITY
Spiller Address:	72 WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	KEITH WILLIAMS
Contact Phone:	(347) 672-6075
DEC Region:	2
DER Facility ID:	350797
DEC Memo:	Not reported
Remarks:	DUMPING WASTE WATER INTO SEWER AND LAND

Material:

Site ID:	401576
Operable Unit ID:	1158363
Operable Unit:	01
Material ID:	2149423
Material Code:	0060A
Material Name:	WASTEWATER
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AP200 **NYC DHS WOMENS SHELTER** **RCRA-NonGen** **1004760619**
East **116 WILLIAMS AVE** **FINDS** **NYR000052530**
1/8-1/4 **BROOKLYN, NY 11207** **MANIFEST**
0.143 mi.
755 ft. **Site 1 of 4 in cluster AP**

Relative:
Higher

Actual:
53 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NYC DHS WOMENS SHELTER
Facility address:	116 WILLIAMS AVE BLOCK 3699 LOT 1 BROOKLYN, NY 11207
EPA ID:	NYR000052530
Mailing address:	WILLIAM ST 17TH FLOOR NEW YORK, NY 10038
Contact:	ALVIS STERNS
Contact address:	WILLIAM ST 17TH FLOOR NEW YORK, NY 10038
Contact country:	US
Contact telephone:	(212) 630-9318
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CITY OF NY DEPT OF HOMELESS SERVICES
Owner/operator address:	161 WILLIAM ST 18TH FLOOR NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	(212) 788-9446
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	CITY OF NY DEPT OF HOMELESS SERVICES
Owner/operator address:	161 WILLIAM ST 18TH FLOOR NEW YORK, NY 10038
Owner/operator country:	US
Owner/operator telephone:	(212) 788-9446
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

NYC DHS WOMENS SHELTER (Continued) **1004760619**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC DHS WOMENS SHELTER
Classification: Not a generator, verified

Date form received by agency: 03/27/1998
Facility name: NYC DHS WOMENS SHELTER
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110009486662

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000052530
Country: USA
Mailing Name: NYC DEPT OF HOMELESS SVCS
Mailing Contact: AL STERNS
Mailing Address: 161 WILLIAMS ST
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10038
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-630-9318

Document ID: NYB6717555
Manifest Status: Not reported
Trans1 State ID: NY0000148163
Trans2 State ID: Not reported
Generator Ship Date: 10/08/1998
Trans1 Recv Date: 10/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/10/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000052530
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported

NYC DHS WOMENS SHELTER (Continued) **1004760619**

TSDF ID:	NYDEC1A37
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	98

AP201 **MANHOLE# 65890** **NY Spills** **S106722233**
East **WILLIAMS AVE./LIBERTY AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.144 mi.
760 ft. **Site 2 of 4 in cluster AP**

Relative:
Higher

Actual:
54 ft.

NY Spills:

Site ID:	164947
Facility Addr2:	Not reported
Facility ID:	0407221
Spill Number:	0407221
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	9/28/2004
Reported to Dept:	9/29/2004
CID:	406
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/29/2004
Remediation Phase:	0
Date Entered In Computer:	9/29/2004
Spill Record Last Update:	11/29/2004
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	139057
DEC Memo:	e2mis no. 155587: 9-28-04 19:20HRS T. SCOURCSIS 10471 (FOD) FOUND FOUR GALLONS OF UNKNOWN OIL ON 200 GALLONS OF WATER IN MH 65890. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS AFFECTED. MR. SCOURCSIS IS UNABLE TO DETERMINE IF JOINT IS LEAKING DUE TO AMOUNT OF WATER IN HOLE. ONE LIQUID SAMPLE WAS TAKEN ON A E

MANHOLE# 65890 (Continued) **S106722233**

PRIORTY AND CLEANUP PENDING LAB RESULTS. 9/28/04 22:21 HRS. -- RECEIVED PCB RESULTS < 1.0 PPM, LSN 04-07774. UPDATE 29-SEP-2004 22:05 HRS. ENVIR. OPER. S.ROSENKING MECH-A EMP# 61951 REPORTS: DBL. WASHED STRUCTURE WITH BIO-GEN 760, FOUND SUMP SEALED. ENVIR. TAG WILL REMAIN IN PLACE PENDING REPAIR OF BLOWN JOINT. UPDATE 10/1/04 18:15 HRS D. THOMPSON #65890 U/G REPORTS THE BLOWN JOINT HAS BEEN REPAIRED, AND HE REMOVED ENV TAG# 42406.

Remarks: 4 gal of material on 200gal of water. Unable to clean last night because of the rain. Will not have it cleaned up by 19:00 hrs. taking it off the 24 hr. program No to the 5 questions. ConED # 155587

Material:

Site ID:	164947
Operable Unit ID:	889820
Operable Unit:	01
Material ID:	485060
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AH202 **92 SACKMAN ST** **NY Spills** **S107488316**
NW **92 SACKMAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.144 mi.
762 ft. **Site 8 of 8 in cluster AH**

Relative:
Higher

Actual:
76 ft.

NY Spills:

Site ID:	355429
Facility Addr2:	Not reported
Facility ID:	0509622
Spill Number:	0509622
Facility Type:	ER
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Spill Date:	11/10/2005
Reported to Dept:	11/10/2005
CID:	64
Spill Cause:	Unknown

92 SACKMAN ST (Continued) **S107488316**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/15/2005
Remediation Phase:	0
Date Entered In Computer:	11/11/2005
Spill Record Last Update:	10/23/2009
Spiller Name:	JOANNE NOWLIN
Spiller Company:	Not reported
Spiller Address:	92 SACKMAN ST
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	JOANNE NOWLIN
Contact Phone:	(718) 495-6106
DEC Region:	2
DER Facility ID:	305458
DEC Memo:	11.15.05 Sharif- I spoke with home owner Ms. Edwards,718-495-6106 several times.She called the oil company back and they cleaned up the spill. It was an overfill.The oil company washed the basement and the tenant Ms. Joe Ann confirmed the odor went away.
Remarks:	Not reported

Material:

Site ID:	355429
Operable Unit ID:	1112789
Operable Unit:	01
Material ID:	2102832
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AE203 **INTERSECTION/EMIS 220526** **NY Spills** **S110539987**
East **WILLIAMS AVE AND GLENMORE AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.145 mi.
763 ft. **Site 3 of 3 in cluster AE**

Relative:
Higher

Actual:
49 ft.

NY Spills:

Site ID:	440706
Facility Addr2:	Not reported
Facility ID:	1007305
Spill Number:	1007305
Facility Type:	ER
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Spill Date:	10/7/2010
Reported to Dept:	10/7/2010
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/22/2010
Remediation Phase:	0
Date Entered In Computer:	10/7/2010
Spill Record Last Update:	10/22/2010
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	395739
DEC Memo:	10/7/10 - Raphael Ketani. The spill consisted of the release of 1 quart of dielectric oil to soil. The site location is Williams Avenue and Glenmore Avenue in Brooklyn. According to Paul Walsh of the Con Ed environmental desk (212) 580-8383, the Con Ed crew was removing an old transformer when they discovered an earthen sump. Typically, in the past, earthen sumps were dug for transformers that were placed below the ground. So, the crew dug out the soil. The oil contained 47.9 ppm of PCBs, but was completely removed. They "popped" the cover of the earthen sump and vacuumed it out. 10/22/10 - Austin - Source of spill was a leaking joint regulator tank - Con Ed contained and cleaned up the release - see eDocs documents for more information - closed - end
Remarks:	1 qt to soil - cleanup pending

Material:

Site ID:	440706
Operable Unit ID:	1191310
Operable Unit:	01

INTERSECTION/EMIS 220526 (Continued) **S110539987**

Material ID:	2186436
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0.25
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AQ204 **CON ED - TM 718** **RCRA-NonGen** **1007206172**
East **WILLIAMS AVE & PITKIN AVE** **MANIFEST** **NYP004004966**
1/8-1/4 **BROOKLYN, NY 11207**
0.146 mi.
772 ft. **Site 1 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

RCRA-NonGen:

Date form received by agency:	02/28/1998
Facility name:	CON ED - TM 718
Facility address:	WILLIAMS AVE & PITKIN AVE BROOKLYN, NY 112070000
EPA ID:	NYP004004966
Mailing address:	CONSOLIDATED EDISON INC 4 IRVING PL RM 310 NEW YORK, NY 100030000
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC NEW YORK, NY 100030000
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

CON ED - TM 718 (Continued) **1007206172**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/27/1998
Facility name:	CON ED - TM 718
Classification:	Not a generator, verified

Date form received by agency:	02/26/1998
Facility name:	CON ED - TM 718
Classification:	Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004004966
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYG0123291
Manifest Status:	Completed copy
Trans1 State ID:	80416AD
Trans2 State ID:	Not reported
Generator Ship Date:	970224
Trans1 Recv Date:	970224
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970225
Part A Recv Date:	970310
Part B Recv Date:	970307
Generator EPA ID:	NYP004004966
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	01182
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	97

CON ED - TM 718 (Continued) **1007206172**

Document ID: NYB8468046
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: SM1860
Trans2 State ID: 80336AB
Generator Ship Date: 970206
Trans1 Recv Date: 970206
Trans2 Recv Date: 970207
TSD Site Recv Date: 970207
Part A Recv Date: 970220
Part B Recv Date: 970331
Generator EPA ID: NYP004004966
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00002
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97

Document ID: NYB8468343
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 80336AB
Trans2 State ID: Not reported
Generator Ship Date: 970224
Trans1 Recv Date: 970224
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970225
Part A Recv Date: 970313
Part B Recv Date: 970327
Generator EPA ID: NYP004004966
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00002
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00001
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 97

Document ID: NYB8468856
Manifest Status: Completed copy

CON ED - TM 718 (Continued) **1007206172**

Trans1 State ID:	20854AD
Trans2 State ID:	Not reported
Generator Ship Date:	970206
Trans1 Recv Date:	970206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970210
Part A Recv Date:	970221
Part B Recv Date:	970220
Generator EPA ID:	NYP004004966
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	05570
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	97

AQ205 **CONSOLIDATED EDISON** **MANIFEST** **S110709266**
East **PITKIN AVE & WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.146 mi.
772 ft. **Site 2 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:

EPA ID:	NYP004218166
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-3770

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2010-10-17
Trans1 Recv Date:	2010-10-17
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2010-10-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004218166
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	Not reported
Quantity:	250.0

CONSOLIDATED EDISON (Continued) **S110709266**

Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	001438970FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AQ206 **MANHOLE 65840** **NY Spills** **S103574127**
East **PITKIN AV & WILLIAMS AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.146 mi.
772 ft. **Site 3 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	127590
Facility Addr2:	Not reported
Facility ID:	9810060
Spill Number:	9810060
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	11/10/1998
Reported to Dept:	11/10/1998
CID:	211
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/7/2002
Remediation Phase:	0
Date Entered In Computer:	11/10/1998
Spill Record Last Update:	11/7/2002
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	LISA PRIMEGGIA

MANHOLE 65840 (Continued) **S103574127**

Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	110157
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" E2MIS NOTES 121175 11/10/98-09:35-M. PANTALEO-37922-O.S. U.G. WHILE ON SCHEDULE WORK -REPORTS FD APPROX 1 1/2 GAL OF OIL ON APPROX 200 GALLONS OF WATER-NO SEWERS OR WATERWAYS EFFECTED AND IS CONTAINED. SAMPLE TAKEN W/4-6 HOUR PRIORITY TURNAROUND-PLACED ENV TAG# 12507. **UPDATE** 11/10 LAB RESULTS <1.0PPM SEQ # 98- UPDATE: 11/11/98 - 1230 G. KERN - 50632 - ENV. OPS., REPORTS <1.0 PPM CLEANUP COMPLETE WITH SLIX AND TAG #12507 REMOVED. INCIDENT IS CLOSED.
Remarks:	CON ED #121175 - SAMPLE TAKEN CLEAN UP PENDING LAB RESULTS

Material:

Site ID:	127590
Operable Unit ID:	1067331
Operable Unit:	01
Material ID:	313943
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9810060
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/10/1998 09:15
Reported to Dept Date/Time:	11/10/98 10:08
SWIS:	61
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported
Spiller Phone:	Not reported

MANHOLE 65840 (Continued) **S103574127**

Spiller Contact: LISA PRIMEGGIA
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/10/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/17/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: CON ED 121175 - SAMPLE TAKEN CLEAN UP PENDING LAB RESULTS

AQ207 **MANHOLE 65838** **NY Spills** **S106868472**
East **WILLIAMS AVE./PITKIN AVE.** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.146 mi.
772 ft. **Site 4 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	344214
Facility Addr2:	Not reported
Facility ID:	0501078
Spill Number:	0501078
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	4/25/2005
Reported to Dept:	4/26/2005
CID:	406
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/13/2005
Remediation Phase:	0
Date Entered In Computer:	4/26/2005
Spill Record Last Update:	7/13/2005
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 ERVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	290853
DEC Memo:	158277. 4/25/05 - 1745. J. SONTAG - 17813 - FOD, WHILE TROUBLE SHOOTING FDR 3B85, REPORTS FINDING APPROX 3 GALS OF AN UNKNOWN OIL ON APPROX 300 GALS OF WATER IN MH65838. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES. NO PRIVATE PROPERTY AFFECTED. NO MOVEMENT IN THE WATER. NO OIL FILLED EQUIP IN THE STRUC. CANNOT VERIFY THE EXISTENCE OF ANY SEWER CONNECTIONS OR SUMPS. NO PARKING 0300 - 0600 MON & THURS. TAG # 26199 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # DD03556 FILLED OUT AND MARKED 'E' PRIORITY. CLEANUP PENDING LAB RESULT. LAB RESULT RECEIVED 4/26/05 - 0056 HRS. 05-03841. 101 PPM. EPA # ISSUED 4/26/05 - 0210. NYP 004 130 951. UPDATE 4/26/05 14:45 HRS DUE TO TWO SEPARATE D-FAULTS ON FDR 3B85 AND 9B02 A LEAKING 3c500 STRAIGHT AND A SWOLLEN JOINT, D-FAULT TAG#02032 HAS BEEN PLACED, AND THIS INCIDENT IS BEING REMOVED FROM THE 24 HOUR PROGRAM. UPDATE 4/26/05 14:56 HRS CIG R. ELLIOTT NOTIFIED OF REMOVAL FROM 24 HOUR PROGRAM. UPDATE 4/26/05 16:20 ENV OPS A. WALKER REPORTS THAT 1 DRUM OF PPE AND ZONE MATERIAL WERE TAKEN BACK TO THE YARD ON THE ONE TRIP

MANHOLE 65838 (Continued) **S106868472**

RULE. UPDATE 4/28/05 07:58 HRS SUPV G. WILLIAMS REPORTS AN EARTHEN SUMP. NOTIFIED CIG SHIKARIDES, HOWEVER NOTIFICATIONS ALREADY MADE WHEN INCIDENT REMOVED FROM THE 24 HOUR PROGRAM. UPDATE 4/28/05 10:30 HRS AS PER ENV SUPV G. WILLIAMS ENV OPS CREW OF GLODOWSKI, ROSADO, AND RYAN REMOVED ALL DEBRIS FROM STRUCTURE AND DOUBLE WASHED THE STRUCTURE WITH BIO-GEN 760 AND SAFE WASH. FOUR DRUMS OF DEBRIS AND PPE ZONE MATERIAL WERE GENERATED AND BROUGHT BACK BY AN ASTORIA TANKER. THE EARTHEN SUMP WAS SEALED AFTER TAKING 2 SAMPLES FROM IT WHICH WILL BE SENT TO CHEM LAB VIA COURIER. THE TANKER REMOVED 450 GALS OF LIQUID. THE ENV TAG REMAINS IN PLACE PENDING SUMP SAMPLES. U/G TO SET ZONES AND REMOVE THE D-FAULT AND BRING THE GENERATED PPE AND ZONE MATERIAL BACK TO THE YARD VIA ONE TRIP RULE. UPDATE 4/29/05 06:39 HRS FCR C. MONTANA REPORTS U/G REMOVED THE LEAKING JOINT D-FAULT, ENV TAG REMAINS IN PLACE PENDING SUMP SAMPLE RESULTS. update 29-apr-2008 1800 Lab Sequence Number: 05-03947-001 Total PCB <1 PPM UPDATE: 4/30/05 - 1945 D. RODRIGUEZ - ENV. OPS., REPORTS TAG # 26199 REMOVED. INCIDENT IS CLOSED.

Remarks: 3 gal. of unknown oil on 300 gal of water in a manhole. Just came off the 24hour program. Spill is 30ft. south of Pitkin Ave. Feeders need to be deenergized before clean up can begin. No to the five questions. ConEd #158277.

Material:

Site ID:	344214
Operable Unit ID:	1102868
Operable Unit:	01
Material ID:	583089
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AQ208 **CON ED - TM 718** **FINDS** **1005630406**
East **WILLIAMS AVE & PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.146 mi.
772 ft. **Site 5 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

FINDS:

Registry ID: 110017249351

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AQ209 **MANHOLE #65838** **NY Spills** **S107409413**
East **WILLIAMS AVE NEAR PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.146 mi.
772 ft. **Site 6 of 6 in cluster AQ**

Relative:
Higher

Actual:
39 ft.

NY Spills:

Site ID:	353537
Facility Addr2:	Not reported
Facility ID:	0508024
Spill Number:	0508024
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	10/4/2005
Reported to Dept:	10/5/2005
CID:	444
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/3/2007
Remediation Phase:	0
Date Entered In Computer:	10/5/2005
Spill Record Last Update:	5/3/2007
Spiller Name:	ERT DESK’
Spiller Company:	MANHOLE #65838
Spiller Address:	WILLIAMS/PITKIN
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	ERT DESK’
Contact Phone:	(212) 580-8383
DEC Region:	2

MANHOLE #65838 (Continued) **S107409413**

DER Facility ID: 300877
DEC Memo: 05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. 161360. 10/4/05 - 0901hrs - Ken Nixon # 29766 Splicer, UG, reports while doing pre-inspections for Fdr 5B27 using acct # C7515 found 1/2 pt unknown oil on 50 gallons water in MH65838. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample taken marked E priority - 72 hr program - chain of custody # CC16143. Env. stop tag #36312 placed. Structure on swk - access anytime. Clean up pending test results. cn#19661 UPDATE 04-OCT-2005 17:57 HRS. LSN-05-10384-001 226 PPM C.HOGAN 07511 UPDATE 10/5/05 09:05 HRS ENV SUPV WILLIAMS REPORTS THE STRUCTURE WAS DOUBLE WASHED WITH BIO-GEN 760, ALL LIQUIDS REMOVED, UG SUPV VELEZ ON LOCATION AND VERIFIED A LEAKING 3c JOINT AT THE "L" FITTING AND D-FAULTED THIS STRUCTURE WITH TAG# 01696. THIS INCIDENT TO BE REMOVED FROM THE 72 HOUR PROGRAM AND ENV TAG REMAINS IN PLACE PENDING D-FAULT CORRECTION. J ANDERSON
Remarks: LEAKING JOINT: TAKEN OFF 72 HOUR LIST DUE TO A DEFAULT: CONED # 161360: NO TO 5 QUESTIONS;

Material:
Site ID: 353537
Operable Unit ID: 1110995
Operable Unit: 01
Material ID: 2101034
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AR210 **BROWNVILLES SUB STATION** **NY Spills** **S102239935**
East **247 WILLIAMS ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.146 mi.
773 ft. **Site 1 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 128454
Facility Addr2: Not reported
Facility ID: 0108050
Spill Number: 0108050

BROWNVILLES SUB STATION (Continued) **S102239935**

Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	8/6/2001
Reported to Dept:	11/7/2001
CID:	282
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/6/2006
Remediation Phase:	0
Date Entered In Computer:	11/7/2001
Spill Record Last Update:	9/7/2006
Spiller Name:	BILL MURPHY
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -
Spiller Company:	001
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" 11-8-01 Foley inspected transformer vault #2. Barksdale switch is bagged. Pete Sudol requested that the equipment be rebagged. Bluestone in vault has been partially removed as part of remediation of historical contamination. Bluestone appears clean. No active leaks. (KMF) 5/30/03 Inspected substation. Repairs pending. (KMF) 9/6/06 - See e-docs for spill closure documentation. (JHO)
Remarks:	38B02 C PAHSE POTHEAD LEAK 1 PINT WAS SPILLED OLD SPILL PICKED UP ON AN AUDIT CON ED 138710

Material:

Site ID:	128454
Operable Unit ID:	845289
Operable Unit:	01
Material ID:	529303
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

BROWNVILLES SUB STATION (Continued) **S102239935**

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	312510
Facility Addr2:	Not reported
Facility ID:	0001682
Spill Number:	0001682
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	5/9/2000
Reported to Dept:	5/9/2000
CID:	281
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/7/2003
Remediation Phase:	0
Date Entered In Computer:	5/9/2000
Spill Record Last Update:	10/7/2003
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	JIM FOX
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" 5/30/03 Inspected substation. Repair and cleanup completed. (KMF) Con Ed e2mis #131326: 5/9/00 1835hrs A sweaty film on "A" phase oil pump control wiring, transformer #2, feeder 38B02. Stain approx 2'X2' on concrete pad. Diapers and bolognies placed. 5/9/00 2005hrs Cleanup completed as 50-499ppm. 5/22/03 Maximo #209291 was created to capture repair work on "A phase oi pump control wiring." 5/29/03 The previous maximo has been voided since Transformer Group had already done the repair under a different maximo. They repacked the fitting and replaced the end fitting to the

BROWNVILLES SUB STATION (Continued) **S102239935**

control wiring. There were no signs of anything leaking and the spot is being monitored, containment was left as a precautionary measure.

Remarks: ABOVE MATERIAL DISCOVERED AS A SHEEN ON CONCRETE AT ABOVE LOCATION. CLEANUP IN PROGRESS. MATERIAL BEING TREATED AS 50/499 PPM. CON ED # 131326.

Material:

Site ID:	312510
Operable Unit ID:	823212
Operable Unit:	01
Material ID:	289898
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	0108070
Investigator:	FOLEY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/08/2001 10:50
Reported to Dept Date/Time:	11/08/01 11:34
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	SAME
Spiller Phone:	(212) 580-6763
Spiller Contact:	SEAN MCKEEVER
Spiller Phone:	(212) 580-6763
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -

BROWNVILLES SUB STATION (Continued) **S102239935**

Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/08/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/09/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Con Ed e2mis 140167 Notes: 11-8-01 Transformer 5 leaked 6o transformer oil from drain plug onto bluestone covering an area of 8 X8 . Station crew to start repairs and start cleanup. DEC Inspector Notes: 11-9-01 Foley inspected Brownsville substation on 11/8/01. Accompanied by station supervisor Martin Watt and SSO EH S Pete Sudol. Could not determine if drain plugs were actively leaking but looked greasy. Requested that they be called in to address possible repair of equipment. Also has contaminated soil/bluestone in vault but will be adressed separately.
Remark: no sewers or waterways - transformer leaked - dec inspector on scene - no clean up - transformer tr5 feeder 38b05

Region of Spill: 2
Spill Number: 0108071
Investigator: FOLEY

BROWNVILLES SUB STATION (Continued) **S102239935**

Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/08/2001 10:55
Reported to Dept Date/Time:	11/08/01 11:37
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	SAME
Spiller Phone:	(212) 580-6763
Spiller Contact:	SEAN MCKEEVER
Spiller Phone:	(212) 580-6763
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	11/08/01
Date Spill Entered In Computer Data File:	Not reported
Update Date:	11/09/01
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	1
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	TRANSFORMER OIL
Class Type:	TRANSFORMER OIL
Times Material Entry In File:	533

BROWNVILLES SUB STATION (Continued) **S102239935**

CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Con Ed e2mis 140168 Notes: 11-8-01 Transformer 6 leaked 6o transformer oil from drain plug onto bluestone covering an area of 8 X8 . Station crew to start repairs and start cleanup. DEC Inspector Notes: 11-9-01 Foley inspected Brownsville substation on 11/8/01. Accompanied by station supervisor Martin Watt and SSO EH S Pete Sudol. Could not determine if drain plugs were actively leaking but looked greasy. Requested that they be called in to address possible repair of equipment. Also has contaminated soil/bluestone in vault but will be adressed separately.
Remark: tranformer tr-6 feeder 38b02 - 6 o leaked from transformer on blue stone - dec inspector on site

Region of Spill: 2
Spill Number: 0108072
Investigator: FOLEY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/08/2001 11:00
Reported to Dept Date/Time: 11/08/01 11:40
SWIS: 61
Spiller Name: CON ED
Spiller Contact: SAME
Spiller Phone: (212) 580-6763
Spiller Contact: SEAN MCKEEVER
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/08/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/09/01
Is Updated: False

Tank:
PBS Number: Not reported

BROWNVILLES SUB STATION (Continued) **S102239935**

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Con Ed e2mis 140169 Notes: 11-8-01 Transformer 10 leaked 6o transformer oil from drain plug onto bluestone covering an area of 8 X8 . Station crew to start repairs and start cleanup. DEC Inspector Notes: 11-9-01 Foley inspected Brownsville substation on 11/8/01. Accompanied by station supervisor Martin Watt and SSO EH S Pete Sudol. Could not determine if drain plugs were actively leaking but looked greasy. Requested that they be called in to address possible repair of equipment. Also has contaminated soil/bluestone in vault but will be adressed separately.
Remark: tr 10 feeder 38b05 - 6o s product leaked onto blue stone - no clean up - dec inspector on scene

Region of Spill: 2
Spill Number: 0108073
Investigator: FOLEY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/08/2001 11:05
Reported to Dept Date/Time: 11/08/01 11:41
SWIS: 61
Spiller Name: CON ED
Spiller Contact: SAME
Spiller Phone: (212) 580-6763
Spiller Contact: SEAN MCKEEVER
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended

BROWNVILLES SUB STATION (Continued) **S102239935**

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/08/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/09/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Con Ed e2mis 140170 Notes: 11-8-01 Transformer 8 leaked 6o transformer oil from drain plug onto bluestone covering an area of 8 X8 . Station crew to start repairs and start cleanup. DEC Inspector Notes: 11-9-01 Foley inspected Brownsville substation on 11/8/01. Accompanied by station supervisor Martin Watt and SSO EH S Pete Sudol. Could not determine if drain plugs were actively leaking but looked greasy. Requested that they be called in to address possible repair of equipment. Also has contaminated soil/bluestone in vault but will be adressed separately.
Remark: tr 8 feeder 38b04 - 6 o s product onto blue stone - no clean up dec inspector on scene

Region of Spill: 2
Spill Number: 0108074
Investigator: FOLEY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/08/2001 11:10
Reported to Dept Date/Time: 11/08/01 11:43
SWIS: 61
Spiller Name: CON ED

BROWNVILLES SUB STATION (Continued) **S102239935**

Spiller Contact: SAME
Spiller Phone: (212) 580-6763
Spiller Contact: SEAN MCKEEVER
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/08/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/09/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Con Ed e2mis 140171 Notes: 11-8-01 Transformer 9 leaked 6o transformer oil from drain plug onto bluestone covering an area of 8 X8 . Station crew to start repairs and start cleanup. DEC Inspector Notes: 11-9-01 Foley inspected Brownsville substation on 11/8/01. Accompanied by station supervisor Martin Watt and SSO EH S Pete Sudol. Could not determine if drain plugs were actively leaking but looked greasy. Requested that they be called in to address possible repair of equipment. Also has contaminated soil/bluestone in vault but will be adressed separately.

BROWNVILLES SUB STATION (Continued) **S102239935**

Remark: transformer tr9 feeder 38b01 6 o prodcut onto blue stone no clean up - dec inspector on scene

---

AR211 **PUMP HOUSE #1** **NY Spills** **S104195544**
East **WILLIAMS & BELMONT AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 2 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	140365
Facility Addr2:	Not reported
Facility ID:	9907656
Spill Number:	9907656
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	9/24/1999
Reported to Dept:	9/24/1999
CID:	389
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/4/2004
Remediation Phase:	0
Date Entered In Computer:	9/24/1999
Spill Record Last Update:	5/17/2004
Spiller Name:	CALLER
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	119878
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" 9/27/99: ERT Kessler - found 6:30 Friday evening in a manhole on Glenmore Avenue/Stone Avenue, Brooklyn. PCBs <1 ppm. 9/27/99: Leon Paretsky - 2nd leak over weekend - contractor cut through feeder Saturday morning at 11:55. Leaked about 400+ gallons at 64th St./4th Avenue (spill # 9907692). As for spill # 9907656, contained in manhole. 9/29/99: John Hegerty - he is to call back with onfo on spill volume. (CAE) ~~~~~~~~~~~~~~~~~~~~ e2mis no. 127990: BROWNSVILLE S/S PUMPHOUSE #1 TANK LEVEL DESCREPANCY OF 485 GALS ON FDRS 38B02/38B04. DROP CHECKS BEING DONE TO DETERMINE WHICH FEEDER. LEAK COMMITTEE CONVENED. T.O. AND GAS CORROSION CREWS CHECKING SURFACE RUN AND MANHOLES. FEEDER RUNS FROM BROWNSVILLE S/S (WILLIAMS AND BELMONT AVE) AND FARRAGUT S/S (89 JOHN ST.) IN BROOKLYN. At 18:0

PUMP HOUSE #1 (Continued) **S104195544**

Remarks: CGO crew found +/- 500 gallons of fresh dielectric fluid leaking from 38B02 in MH 65361 @ Glenmore Ave. 150' e/o Christopher St. Chem lab took samples. Temp clamp installed at 03:00 9/25/99. Barrel installation completed at 06:00 9/26/99. ETI performed weld inspection. Chem lab reports 99-10068 <1.0 ppm PCBs. Removed 5659 kilograms of liquids and 159 kilograms of solids. Chem Lab reports 1.2 ppm benzene #99-10096. CSD reports total loss as 785 gallons - all contained in manhole. Cleanup completed on 9/25/99 at 10:00. possible leak discrepency in readings in their pump house unsure if a spill has occurred con ed#127990 involves 32b02 or 32b04 runs from browville to faragett station incident is being investigated

Material:

Site ID:	140365
Operable Unit ID:	1086235
Operable Unit:	01
Material ID:	300350
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	485
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9907656
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	09/24/1999 13:30
Reported to Dept Date/Time:	09/24/99 14:36
SWIS:	61
Spiller Name:	CON EDISON
Spiller Contact:	CALLER
Spiller Phone:	(212) 580-6763
Spiller Address:	4 IRVING PLACE

PUMP HOUSE #1 (Continued) **S104195544**

Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/24/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/27/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 485
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: possible leak discrepency in readings in their pump house unsure if a spill has occurred con ed 127990 involves 32b02 or 32b04 runs from browville to faragett station incident is being investigated

AR212 **BROWNSVILLE UNIT SUB-STAT** **NY Spills** **S102402115**
East **WILLIAMS AV & BELMONT ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 3 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	289780
Facility Addr2:	Not reported
Facility ID:	9608417
Spill Number:	9608417
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	10/7/1996
Reported to Dept:	10/7/1996
CID:	266
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/17/2006
Remediation Phase:	0
Date Entered In Computer:	10/7/1996
Spill Record Last Update:	2/17/2006
Spiller Name:	PAT MCHUGH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	234637
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" 5/30/03 Inspected substation. Con Ed provided old tracking system report #2079 which states the following: Brownsville #1, Transformer #2 leak found at base of sound enclosure at east side of transformer. Discovered approx 16oz on transformer pad with some quantity running off pad onto bluestone. Upon further inspection, also discovered puddle within confines of sound enclosure in same proximity. Amount and identity of liquid "unknown". At this time origin of leak undeterminable. Proper containment followed. 5/30/03 Incident remains open. Requested Con Ed enter this info into e2mis for followup. (KMF) 11/18/05 Transformer inspected by Con ed personnel - no leaks. Transformer pad and bluestone clean. Close out. (JHO)
Remarks:	PCB'S < 10 PPM. UNKNOWN CAUSE. 1 PINT ONTO CONCRETE AND BLUESTONE. CLEAN UP IN PROGRESS.

Material:

Site ID:	289780

BROWNSVILLE UNIT SUB-STAT (Continued) **S102402115**

Operable Unit ID: 1039457
Operable Unit: 01
Material ID: 344155
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9608417
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 10/07/1996 09:45
Reported to Dept Date/Time: 10/07/96 11:19
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: PAT MCHUGH
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /

BROWNSVILLE UNIT SUB-STAT (Continued) **S102402115**

Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/07/96
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/18/96
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 1
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Not reported
Remark: PCB S < 10 PPM. UNKNOWN CAUSE. 1 PINT ONTO CONCRETE AND BLUESTONE. CLEAN UP IN PROGRESS.

AS213 **LONG ISLAND BAPTIST** **UST** **U001840681**
East **340 WILLIAMS AVE** **HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.147 mi.
775 ft. **Site 1 of 2 in cluster AS**

Relative:
Lower

Actual:
35 ft.

UST:
Facility Id: 2-474118
Region: STATE
DEC Region: 2
Site Status: Unregulated
Program Type: PBS
Expiration Date: N/A
UTM X: 593095.93111
UTM Y: 4502394.8791899998

Affiliation Records:
Site Id: 20881
Affiliation Type: On-Site Operator
Company Name: LONG ISLAND BAPTIST
Contact Type: Not reported
Contact Name: JOHN COLLINS
Address1: Not reported

LONG ISLAND BAPTIST (Continued) **U001840681**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 306-3129
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	20881
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN COLLINS
Address1:	250 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10007
Country Code:	001
Phone:	(212) 306-3129
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	20881
Affiliation Type:	Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011

Site Id:	20881
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE SQUAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

LONG ISLAND BAPTIST (Continued) **U001840681**

Zip Code:	Not reported
Country Code:	001
Phone:	(212) 686-9597
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
F06 - Pipe External Protection - Wrapped
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Info:

Site ID:	20881
Tank Number:	001
Tank ID:	37594
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	6/1/1981
Capacity Gallons:	3000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	4/1/1995
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-474118
SPDES Number:	Not reported
Emergency Contact:	EMERGENCY SERVICE SQUAD
Emergency Telephone:	(212) 289-3940
Operator:	JOHN COLLINS
Operator Telephone:	(212) 306-3129
Owner Name:	NYC HOUSING AUTHORITY
Owner Address:	250 BROADWAY
Owner City,St,Zip:	NEW YORK, NY 10007
Owner Telephone:	(212) 306-3129
Owner Type:	Local Government
Owner Subtype:	51
Mailing Name:	NYC HOUSING AUTHORITY
Mailing Address:	250 BROADWAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10007

LONG ISLAND BAPTIST (Continued) **U001840681**

Mailing Contact:	JOHN COLLINS
Mailing Telephone:	(212) 306-3129
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	06/06/1994
Expiration Date:	03/28/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19810601
Capacity (gals):	3000
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AR214 **MANHOLE # 65799** **NY Spills** **S107408517**
East **WILLIAMS AVE/BELMONT** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 4 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	351737
Facility Addr2:	Not reported
Facility ID:	0506507
Spill Number:	0506507
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	8/26/2005
Reported to Dept:	8/26/2005
CID:	444
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/3/2007
Remediation Phase:	0
Date Entered In Computer:	8/26/2005
Spill Record Last Update:	5/3/2007
Spiller Name:	ERT DESK'
Spiller Company:	MANHOLE # 65799
Spiller Address:	WILLAIMS AVE/BELMONT
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	299004
DEC Memo:	05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. 160738 26-AUG-2005 10:56 HRS. UNDERGROUND DEPT.SR. ELECT. TECH. MARK SATIRA EMP# 43600 REPORTS: WHILE ON LOCATION M65779 TO PRE-INSPECT (FEEDER 3B91) (ACCT# C7515) FOUND: 1PT OF DIELECTRIC FEEDER FLUID (2' X 2' PATCH) FROM A LEAKING RESERVOIR TANK TUBING ON SOIL IN A CONCRETE STRUCTURE. NO WATER . D-FAULT TAG# 03998 HAS BEEN HUNG. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THE SPILL APPEARS TO BE CONTAINED. THERE IS NO FIRE INVOLVEMENT. NO SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS CONED. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 47729 PLACED. 1 OIL/SOIL SAMPLE TAKEN FROM SPILL & MARKED PRIORITY " E ". 72 HR DEMINIMIS PROGRAM ON A CHAIN OF CUSTODY# DD-21853. SAMPLE TO BE TAKEN TO ASTORIA CHEM. LAB. C.HOGAN
Remarks:	LEAKED FROM A RESOVOIR TANK: DEFAULT NEED TO TAKE FEEDER OUT OF SERVICE: CONED # 160738: NO TO 5 QUESTIONS;

MANHOLE # 65799 (Continued) **S107408517**

Material:

Site ID:	351737
Operable Unit ID:	1109242
Operable Unit:	01
Material ID:	2099233
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AR215 **BROWNSVILL SUB STA** **NY Spills** **S104192376**
East **247 WILLIAMS ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 5 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	312521
Facility Addr2:	Not reported
Facility ID:	9903999
Spill Number:	9903999
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	7/6/1999
Reported to Dept:	7/6/1999
CID:	270
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

BROWNSVILL SUB STA (Continued) **S104192376**

Spill Closed Dt:	10/8/2003
Remediation Phase:	0
Date Entered In Computer:	7/6/1999
Spill Record Last Update:	10/8/2003
Spiller Name:	MIKE CESARE
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" 5/30/03 Inspected and found repaired and cleaned up. (KMF) Con Ed e2mis #126163: 7/6/99 1gal DF leaked from transformer #9 B-phase flange main body onto concrete. Absorbant pads placed and area roped off. 8/2/99 Cleanup completed on 7/6/99 at 2100hrs. Absorbant materials were used to removed residual fluid and large drip container was placed under leaking point to contain leak. Lab results indicate PCB count <1ppm. 5/19/03 1451hrs As per Maximo # 54898, "oil leaking from B phase flange between main body and radiator"was completed and repaired on 5/22/01 0818hrs.
Remarks:	TRANSFORMER 9 1256163

Material:

Site ID:	312521
Operable Unit ID:	1082926
Operable Unit:	01
Material ID:	303895
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9903999
Investigator:	O'CONNELL

BROWNSVILL SUB STA (Continued) **S104192376**

Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	07/06/1999 19:00
Reported to Dept Date/Time:	07/06/99 21:04
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	MIKE CESARE
Spiller Phone:	(212) 580-6763
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003-
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	07/06/99
Date Spill Entered In Computer Data File:	Not reported
Update Date:	07/07/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	1
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	TRANSFORMER OIL
Class Type:	TRANSFORMER OIL
Times Material Entry In File:	533

BROWNSVILL SUB STA (Continued) **S104192376**

CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Not reported
Remark: TRANSFORMER 9 1256163

AR216 **BELMONT & WILLIAMS ST** **ERNS** **2005610451**
East **BELMONT & WILLIAMS ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 6 of 17 in cluster AR**

Relative:
Lower

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual:
37 ft.

AR217 **BROWNSVILLE SUBSTATION TR #1** **NY Spills** **S104511259**
East **247 WILLIAMS STREET** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 7 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	312522
Facility Addr2:	Not reported
Facility ID:	9914635
Spill Number:	9914635
Facility Type:	ER
SWIS:	2401
Investigator:	JMOCONNE
Referred To:	Not reported
Spill Date:	3/27/2000
Reported to Dept:	3/27/2000
CID:	390
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	3/27/2000
Spill Record Last Update:	6/21/2010
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller City,St,Zip:	NEW YORK, NY
Spiller Company:	001
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was

BROWNSVILLE SUBSTATION TR #1 (Continued) **S104511259**

"O'CONNELL" 5/30/03 Substation inspected. Vault #1 remediation complete. Open for repair of transformer. (KMF) Con Ed e2mis #130579: 3/27/00 1155hrs 1/2 pint dielectric fluid spilled from main body of TR#1 on fdr 38B01. Contained to concrete pad. Has not reached bluestone. PCB count as of 10/15/98 was 10ppm. 3/28/00 0746hrs LSN 00-02903, 8ppm PCB 3/28/00 1805hrs Cleanup completed at 1630hrs. 12/17/01 1540hrs This report is being updated as per direction of NYSDEC to include historical contamination of bluestone as reported by NYSDEC# 9601831 on 5/6/96. 3/25/02 1500hrs AllState Power Vac reported on site and removed all stained bluestone/soil around bank #1. Excavation took place between 3/6/02 and 3/12/02. Waste removed by vactor. On 3/12/02, a site inspection was performed by NYSDEC Jane O'Connell and Kerry Foley. They gave OK to backfill with clean bluestone. Waste disposal results are on file. 6/21/10 - changed Lead DEC to JMOCONNE (JOC)

Remarks: 1/2 PT OF FLUID LEAKED - LEAK WAS FROM SAMPLE PIPING FROM TRANSFORMER HEATER 38 B. CON ED #130579 PCB TEST ON 10/15/98 - WAS 10 PPM

Material:

Site ID:	312522
Operable Unit ID:	1092623
Operable Unit:	01
Material ID:	292928
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9914635
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/27/2000 11:55

BROWNSVILLE SUBSTATION TR #1 (Continued) **S104511259**

Reported to Dept Date/Time: 03/27/00 12:51
SWIS: 61
Spiller Name: CON ED
Spiller Contact: CALLER
Spiller Phone: (212) 580-6763
Spiller Contact: BILL MURPHY
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PL
Spiller City,St,Zip: NEW YORK, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/27/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/27/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: 1/2 PT OF FLUID LEAKED - LEAK WAS FROM SAMPLE PIPING FROM TRANSFORMER HEATER 38 B. CON ED 130579 PCB TEST ON 10/15/98 - WAS 10 PPM

AR218 **BROWNSVILLE SUB STA** **NY Spills** **S104192375**
East **247 WILLIAMS STREET** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
775 ft. **Site 8 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	128456
Facility Addr2:	Not reported
Facility ID:	9903998
Spill Number:	9903998
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	7/6/1999
Reported to Dept:	7/6/1999
CID:	282
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/19/1999
Remediation Phase:	0
Date Entered In Computer:	7/6/1999
Spill Record Last Update:	6/2/2000
Spiller Name:	MIKE CESARE
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	MIKE CESARE
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" SEE 9904000. con ed e2mis notes: Found approx 1 qt dielectric fluid, onto concrete floor. Spill is contained. Cleanup was completed on 6-Jul-1999. Absorbent materials were used to remove residual fluids and the flange bolts were retorqued. Thus stopping the leak. Indicate a pcb count of 15ppm. 1 qt dielectric fluid leaked from Transformer#6 tap changer contact flange onto concrete floor. Spill is contained. No sewers or waterways affected. Absorbent pads placed and area roped off. Cleanup is pending arrival of Substation crew.
Remarks:	tranformer failed con ed 126162 1 quart was spilled

Material:

Site ID:	128456
Operable Unit ID:	1082924
Operable Unit:	01
Material ID:	303894
Material Code:	0541A

BROWNSVILLE SUB STA (Continued) **S104192375**

Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	342687
Facility Addr2:	Not reported
Facility ID:	0413556
Spill Number:	0413556
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	3/29/2005
Reported to Dept:	3/29/2005
CID:	64
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	7/29/2005
Remediation Phase:	0
Date Entered In Computer:	3/30/2005
Spill Record Last Update:	7/29/2005
Spiller Name:	ERT DESK
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	110821
DEC Memo:	157837. 3/29/05 18:20 HRS M. RAMDIN #14875 SUB STA OPER REPORTS

BROWNSVILLE SUB STA (Continued) **S104192375**

FINDING AN UNKNOWN AMOUNT OF INSULATUM LEAKED FROM THE C PHASE POT HEAD OF CAPACITOR TANK#5 ONTO A GRATING AND THEN ONTO ASPHALT. THIS WAS OBSERVED WHILE WALKING BY. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. M. RAMDIN HAS PLACED PADS UNDER THE GRATING AND ON THE 2' X 4' AFFECTED AREA OF THE ASPHALT. HE IS ALSO QUALIFIED TO CLEAN THE SPILL AND IS IN THE PROCESS OF DOING SO. ALSO THEY WILL ATTEMPT TO SHUT DOWN THIS CAPACITOR. HE IS ALSO CONTACTING CHEM LAB TO GO TO LOCATION SO THEY CAN OBTAIN A SAMPLE. UPDATE 3/29/05 20:01 AS PER ERT KINDBERG WHO WAS IN CONTACT WITH BROWNSVILLE SUB-STA, THE SPILL WAS APPROX 2 OZ OF INSULATUM DROPS SPREAD OVER A 2' X 4' AREA. THE SPILL AMOUNT WAS CHANGED ON THE DESCRIPTION, AND ON THE MATERIAL HISTORY. Lab Sequence Number: 05-02883-001 - PCBs < 1 ppm Operator M. Ramdin #14875 notified me that underground came in Substation 3/31/05 at 12:00 and made a visual of Cap Bank #5 potheads to see about repairs. They also wipped down the pothead and cleaned up the area a 15 gallon drum of non-hazards oils debris was generated. Waiting for Underground to come back and make repairs. Supervisor for Brownsville F. Kennedy sent me E-Mail which he recived a letter from A. Lubrano #72765, stating that (UG Suprvisor) A. Scarpa went to Brownsville on 3/30/2005 to look at Cap Bank #5. They had cleaned up insulatum that had leaked. Based on their inspection, they deemed both the cable and the pothead to be good. No further work is required from UG at this time. No further problems were found and Cap Bank can be used for service.

Remarks: Unknown amount of Insulatum spilled on asphalt - cleanup is in progress. No to five questions. 157837.

Material:

Site ID:	342687
Operable Unit ID:	1101408
Operable Unit:	01
Material ID:	581574
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

BROWNSVILLE SUB STA (Continued) **S104192375**

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	0010736
Investigator:	FOLEY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	12/27/2000 13:15
Reported to Dept Date/Time:	12/27/00 14:49
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	SAME
Spiller Phone:	(212) 580-6763
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	12/27/00
Date Spill Entered In Computer Data File:	Not reported
Update Date:	12/28/00
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum

BROWNSVILLE SUB STA (Continued) **S104192375**

Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: 50-499 ppm no smoke or fire not private property no transformer. dashpot oil is material con ed 134901

Region of Spill: 2
Spill Number: 9903998
Investigator: ENGELHARDT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/06/1999 18:40
Reported to Dept Date/Time: 07/06/99 20:47
SWIS: 61
Spiller Name: CON ED
Spiller Contact: MIKE CESARE
Spiller Phone: (212) 580-6763
Spiller Contact: MIKE CESARE
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/19/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/06/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/02/00
Is Updated: False

BROWNSVILLE SUB STA (Continued) **S104192375**

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: SEE 9904000. con ed e2mis notes: Found approx 1 qt dielectric fluid, onto concrete floor. Spill is contained. Cleanup was completed on 6-Jul-1999. Absorbent materials were used to remove residual fluids and the flange bolts were retorqued.Thus stopping the leak. Indicate a pcb count of 15ppm. 1 qt dielectric fluid leaked from Transformer 6 tap changer contact flange onto concrete floor. Spill is contained. No sewers or waterways affected. Absorbent pads placed and area roped off. Cleanup is pending arrival of Substation crew.
Remark: tranformer failed con ed 126162 1 quart was spilled

AR219 **BROWNSVILLE SUBSTATION** **NY Spills** **S107658133**
East **274 WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
776 ft. **Site 9 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 361763
Facility Addr2: Not reported
Facility ID: 0514920
Spill Number: 0514920
Facility Type: ER
SWIS: 2401
Investigator: GDBREEN
Referred To: Not reported
Spill Date: 3/29/2006
Reported to Dept: 3/29/2006
CID: 444
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

BROWNSVILLE SUBSTATION (Continued) **S107658133**

	Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/14/2006
Remediation Phase:	0
Date Entered In Computer:	3/29/2006
Spill Record Last Update:	7/17/2006
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	274 WILLIAM AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	311998
DEC Memo:	06/14/06 - See e-docs for Con Ed report detailing cleanup and closure. 163569. 29-MAR-09:50 EMP. J. BLEVINS # 55304 REPORTS THAT WHILE CHECKING INSPECTION OF AN ALARM. FOUND 4 OZ. OF DIELECTRIC FLUID LEAKING FROM PRIMARY POTHEAD A PHASE. TRANSMISSION #4. FDR # 38B04 ONTO BLUESTONE. NO SMOKE/FIRE INVOLVED. NO SEWER/WATERWAYS AFFECTED. NO INJURES INVOLVED. NO PRIVATE PROPERTY AFFECTED. WILL CALL CHEMLAB TO TAKE SAMPLE. TRAMISSION OPS. FOR REPAIR TO STOP LEAK. CR-84446
Remarks:	6 OUNCES AND IS CONTAINED AND NO TO 5 QUESTIONS: CONED# 163569

Material:

Site ID:	361763
Operable Unit ID:	1119877
Operable Unit:	01
Material ID:	2109339
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AT220 **89-91 SACKMAN STREET** **NY Spills** **S104495928**
NW **89-91 SACKMAN STREET** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
777 ft. **Site 1 of 4 in cluster AT**

Relative:
Higher

Actual:
76 ft.

NY Spills:

Site ID:	245140
Facility Addr2:	Not reported
Facility ID:	9414554
Spill Number:	9414554
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	2/3/1995
Reported to Dept:	2/3/1995
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/22/2005
Remediation Phase:	0
Date Entered In Computer:	2/13/1995
Spill Record Last Update:	7/22/2005
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	128 WEST END AVENUE
Spiller City,St,Zip:	NEW YORK, NY 10023
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	201370
DEC Memo:	Update 7/22/05 Service box 44238 was inspected on 5/26/05 and no oil or tag was found.
Remarks:	OIL/WATER MIXTURE CONTAINED IN MANHOLE MATERIAL BEING ANALYZED FOR IDENTIFICATION.

Material:

Site ID:	245140
Operable Unit ID:	1012118
Operable Unit:	01
Material ID:	373290
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	70
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

89-91 SACKMAN STREET (Continued) **S104495928**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9414554
Investigator: ENGLEHARDT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 02/03/1995 15:58
Reported to Dept Date/Time: 02/03/95 19:23
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: (718) 802-5150
Spiller Address: 128 WEST END AVENUE
Spiller City,St,Zip: NEW YORK, NY 10023
Spill Cause: Unknown
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/13/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/13/98
Is Updated: False

89-91 SACKMAN STREET (Continued) **S104495928**

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 70
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: OIL/WATER MIXTURE CONTAINED IN MANHOLE MATERIAL BEING ANALYZED FOR IDENTIFICATION.

AF221 **NY Spills** **S104650254**
East **541 SUTTER AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.147 mi.
778 ft. **Site 4 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NY Spills:
Site ID: 217014
Facility Addr2: Not reported
Facility ID: 9912618
Spill Number: 9912618
Facility Type: ER
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Spill Date: 2/4/2000
Reported to Dept: 2/4/2000
CID: 270
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 7/29/2003
Remediation Phase: 0
Date Entered In Computer: 2/4/2000
Spill Record Last Update: 7/29/2003
Spiller Name: WORK 718-345-7200

(Continued) **S104650254**

Spiller Company: PRICI QUEVEDO
Spiller Address: 541 SUTTER AVE
Spiller City,St,Zip: BROOKLYN, NY
Spiller Company: 001
Contact Name: PRICI QUEVEDO
Contact Phone: (718) 495-1301
DEC Region: 2
DER Facility ID: 179673
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND" sangesland spoke to Mike Shaw at Petro (516-686-2031) He said the problem appears minor, but they will know more next week when Petro opens up the sidewalk and replaces the fill line. 7/29/2003 administrative closure
Remarks: FILL LINE DEVELOPED LEAK FOR AN UNKNOW REASON

Material:
Site ID: 217014
Operable Unit ID: 1091317
Operable Unit: 01
Material ID: 294500
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9912618
Investigator: SANGESLAND
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 02/04/2000 14:29
Reported to Dept Date/Time: 02/04/00 14:50
SWIS: 61
Spiller Name: PRICI QUEVEDO

(Continued) **S104650254**

Spiller Contact: WORK 718-345-7200
Spiller Phone: (718) 495-1301
Spiller Contact: PRICI QUEVEDO
Spiller Phone: (718) 495-1301
Spiller Address: 541 SUTTER AVE
Spiller City,St,Zip: BROOKLYN, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/04/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/07/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: sangesland spoke to Mike Shaw at Petro 516-686-2031) He said the problem appears minor, but they will know more next week when Petro opens up the sidewalk and replaces the fill line.
Remark: FILL LINE DEVELOPED LEAK FOR AN UNKNOW REASON

AG222 **MANHOLE #66462** **NY Spills** **S107788596**
East **WILLIAMS AVE & BLAKE AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
779 ft. **Site 6 of 9 in cluster AG**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	364693
Facility Addr2:	Not reported
Facility ID:	0602262
Spill Number:	0602262
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	5/30/2006
Reported to Dept:	5/31/2006
CID:	27
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/21/2006
Remediation Phase:	0
Date Entered In Computer:	5/31/2006
Spill Record Last Update:	12/21/2006
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Company:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	314889
DEC Memo:	12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. 200295. see eDocs.
Remarks:	Caller reports 1 gal unk oil in manhole. No to the 5 questions. 200295 is the Coned ref number.

Material:

Site ID:	364693
Operable Unit ID:	1122714
Operable Unit:	01
Material ID:	2112191
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

MANHOLE #66462 (Continued) **S107788596**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AG223 **CONSOLIDATED EDISON** **MANIFEST** **S108980610**
East **WILLIAMS AVE & BLAKE AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.148 mi.
779 ft. **Site 7 of 9 in cluster AG**

Relative:
Lower

Actual:
34 ft.

NY MANIFEST:
EPA ID: NYP004154977
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2802

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/13/2007
Trans1 Recv Date: 11/13/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/15/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004154977
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 50
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1

CONSOLIDATED EDISON (Continued) **S108980610**

Year:	07
Manifest Tracking Num:	001437194FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AG224 **ONE PINT OIL IN MANHOLE #M66457** **NY Spills** **S108295684**
East **WILLIAMS AVE & BLAKE AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
779 ft. **Site 8 of 9 in cluster AG**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	372978
Facility Addr2:	Not reported
Facility ID:	0608905
Spill Number:	0608905
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	11/2/2006
Reported to Dept:	11/2/2006
CID:	406
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/21/2006
Remediation Phase:	0
Date Entered In Computer:	11/2/2006
Spill Record Last Update:	12/21/2006
Spiller Name:	UNKNOWN NAME
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	999
Contact Name:	ERT DESK' MIKE DAUGHTERY
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	322701
DEC Memo:	12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. 203152. see eDocs

ONE PINT OIL IN MANHOLE #M66457 (Continued) **S108295684**

Remarks: One pint of unknown oil found in a manhole. Coming off 72hr. clock @ 16:05 because they discovered earth and sump in the manhole. Con Ed#203152 No to the five questions.

Material:

Site ID:	372978
Operable Unit ID:	1130707
Operable Unit:	01
Material ID:	2120380
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AG225 **MANHOLE 66461** **NY Spills** **S103572994**
East **BLAKE AVE/WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
779 ft. **Site 9 of 9 in cluster AG**

Relative:
Lower

Actual:
34 ft.

NY Spills:

Site ID:	236857
Facility Addr2:	Not reported
Facility ID:	9808804
Spill Number:	9808804
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	10/15/1998
Reported to Dept:	10/15/1998
CID:	252
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended

MANHOLE 66461 (Continued) **S103572994**

UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/28/2002
Remediation Phase:	0
Date Entered In Computer:	10/15/1998
Spill Record Last Update:	10/28/2002
Spiller Name:	BILL MURPHY
Spiller Company:	MANHOLE 66461
Spiller Address:	BLAKE AVE/WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller Company:	001
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	195125
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" Con Ed e2mis #120533: L.QUINTANA #01754 UNDERGROUND SPLICER REPORTS WHILE INSPECTING MH66461 FOR SCHEDULED FEEDER WORK DISCOVERED TUBING FROM A JOINT REGULATOR LEAKING OIL ONTO FLOOR OF HOLE. TUBING CONNECTED TO CABLE JOINT ON FDR3B85. APPROX 4 GALLONS OF DIELECTRIC FLUID MIXED WITH APPROX 5 GALLONS OF WATER IN MH. HE SEES OIL & DEBRIS IN DRAIN NOT SURE IF DRAIN IS WORKING. NOTIFIED HIS SUPERVISOR P.BROGNA @ 10:45 HRS. HE IS RESPONDING TO LOCATION TO INVESTAGATE. SAMPLE TO BE TAKEN FROM EQUIPMENT IN QUESTION, & STOP TAG #11269 PLACED. R.COSENTINO NOTIFIED @ 10:15 HRS ALSO RESPONDING TO LOCATION. update @ 1137 HRS R.COSENTINO ON LOCATION REPORTS NO SEWERS OR WATERWAYS AFFECTED, HOLE HAS A SUMP. SPLICER IS TAKING SAMPLE FROM TUBING AT THIS TIME MARKED 4-6 HR TURNAROUND. CIG NOTIFIED 1156 HRS. 10-15-98 16:15HRS PETE BROGNA REPORTS, BULLET NEVER SHOWED UP TO PICK UP SAMPLE FROM LOC AT 12:10 HRS THIS AFTERNOON. CREW WAITED FOR PICKUP. P. BROGNA CALLED BULLET AGAIN AT 16:00HRS AND SAID THEY SHOULD BE THERE IN 20MIN. BULLET CLAIMS THEY GOT LOST. UPDATE 10-15 98 CHEM LAB RESULTS 98-11114 < 1PPM UPDATE 10-23-98 0500HRS S.ROSENKING FLUSH REPORTS CLEANUP INCOMPLETE NEEDS SODA BLAST TRUCK. UPDATE: 10/23/98 - 1515 N. SAVOCA - 17932 - ENV. OPS., REPORTS U/G REPAIRED LEAKING TUBING AND THE <1.0 PPM CLEANUP IS COMPLETE WITH SLIX AND TAG #11269 REMOVED.
Remarks:	CABLE JOINT REGULATOR TUBING FAILURE CAUSED SPILL-SAMPLES TAKEN AND UPON REULTS CLEANUP WILL BEGIN. #CON ED 120533

Material:

Site ID:	236857
Operable Unit ID:	1069992
Operable Unit:	01
Material ID:	316290
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

MANHOLE 66461 (Continued) **S103572994**

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9808804
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/15/1998 09:35
Reported to Dept Date/Time:	10/15/98 12:10
SWIS:	61
Spiller Name:	MANHOLE 66461
Spiller Contact:	BILL MURPHY
Spiller Phone:	(212) 580-6763
Spiller Contact:	BILL MURPHY
Spiller Phone:	(212) 580-6763
Spiller Address:	BLAKE AVE/WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	10/15/98
Date Spill Entered In Computer Data File:	Not reported
Update Date:	10/16/98
Is Updated:	False

Tank:

MANHOLE 66461 (Continued) **S103572994**

PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 4
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: CABLE JOINT REGULATOR TUBING FAILURE CAUSED SPILL-SAMPLES TAKEN AND UPON REULTS CLEANUP WILL BEGIN. CON ED 120533

AR226 **BROWNSVILLE SUBSTATION** **NY Spills** **S106014474**
East **247 WILLIAMS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 10 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 165627
Facility Addr2: Not reported
Facility ID: 0302127
Spill Number: 0302127
Facility Type: ER
SWIS: 2401
Investigator: SKARAKHA
Referred To: Not reported
Spill Date: 5/30/2003
Reported to Dept: 5/30/2003
CID: 422
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 9/26/2003
Remediation Phase: 0
Date Entered In Computer: 5/30/2003
Spill Record Last Update: 9/29/2003
Spiller Name: Not reported
Spiller Company: SAME

BROWNSVILLE SUBSTATION (Continued) **S106014474**

Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	001
Contact Name:	TOM MARCINEK
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	139569
DEC Memo:	E2MIS 148531 5/30/03 - 1020 M. WATT - 14868 - S.S.O, REPORTS A LEAK OF APPROX 1 PT OF NON PCB DIEL FLUID FROM THE POTHEAD VALVES OF A & C PHASE OF FDR 38B01 ONTO BLUESTONE. SPILL IS CONTAINED WITH MARRIAGE ROLL. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO PRIVATE PROPERTY AFFECTED. CLEANUP IS UNDER WAY USING A SHOVEL TO REMOVE THE AFFECTED BLUESTONE. A PHASE IS NOT DRIPPING. C PHASE IS DRIPPING APROX 1 DROP EVERY 30 SECONDS. MARRIAGE ROLL WILL STAY UNDER C PHASE TO CATCH THE DRIPPING UNTIL FDR IS TAKEN OFF FOR PERMANENT REPAIRS. TJ - 50495 6/19/03 10:14 As per M. Watt, the station supervisor, on 5/30/03 from 10:30 to 11:15 station maintenance wiped down the phases, picked up the bluestone, and placed containment down as a precaution until TO will be able to come on site and make the repairs. As per written confirmation from V. Schaefer, on 6/17/03 TO went to the site and retourqued the potheads and tightened the packing glands on the valves that were leaking during an outage. The incident may be closed and submitted to the DEC. UPDATE 7/22/03 1430 Hours Additional info from E McQueen. SPILL CLEANUP CHECKLIST Completing Checklist: N RUSSELL SPLICER, 16232 Location of spill: BROWNSVILLE SUBSTATION Source of spill: A & C PHASE POTHEADS Affected by spill: POTHEADS & STRUCTURE Cleanup Activities: SEALED LEAK, REMOVED/RECOVED LIQUID/SOLIDS, WASHED STAINED AREAS RETOQUED Con Edison personnel: TRANSMISSION OPERATIONS, N. RUSSELL AND C SAMAROO Cleanup complete: 06-17-03 @ 17:30 Directing cleanup: D. HUGGINS SUPERVISOR, 14205 CLEANUP COMPLETE, SUBMITTED TO NYSDEC FOR APPROVAL.U
Remarks:	LEAKING VALVE 1 PHASE IS STILL LEAKING 1 DROP EVERY 30 SECONDS MARRIAGE ROLL UNDERNEATH TO CATCH DRIPPING NO SMOKE/FIRE/WATERWAYS/INJURIES/PRIVATE PROPERTY

Material:

Site ID:	165627
Operable Unit ID:	870019
Operable Unit:	01
Material ID:	506612
Material Code:	0016A
Material Name:	NON PCB OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported

BROWNSVILLE SUBSTATION (Continued) **S106014474**

Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AR227 **BROWNSVILLE S/S. XFMR # 4 CIRC PUMP** **NY Spills** **S109061035**
East **247 WILLIAMS AVE. SUBSTATION** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 11 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	395483
Facility Addr2:	Not reported
Facility ID:	0713689
Spill Number:	0713689
Facility Type:	ER
SWIS:	2401
Investigator:	gdbreen
Referred To:	Not reported
Spill Date:	3/27/2007
Reported to Dept:	3/27/2008
CID:	77
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/12/2008
Remediation Phase:	0
Date Entered In Computer:	3/27/2008
Spill Record Last Update:	5/12/2008
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ 10003
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	345008
DEC Memo:	05/12/08 - See eDocs for Con Ed report detailing cleanup and closure. 210565. see eDocs
Remarks:	spill onto concrete and blue stone, contained. spill of 2 drops per min. clean-up pending. con ed ref #210565.

Material:

Site ID:	395483
Operable Unit ID:	1152420
Operable Unit:	01

BROWNSVILLE S/S. XFMR # 4 CIRC PUMP (Continued) **S109061035**

Material ID: 2143196
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AR228 **BROWNSVILLE SUB STATION** **NY Spills** **S103936744**
East **247 WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 12 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 226750
Facility Addr2: Not reported
Facility ID: 0104424
Spill Number: 0104424
Facility Type: ER
SWIS: 2401
Investigator: AERODRIG
Referred To: Not reported
Spill Date: 7/25/2001
Reported to Dept: 7/25/2001
CID: 252
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/9/2001
Remediation Phase: 0
Date Entered In Computer: 7/25/2001
Spill Record Last Update: 11/8/2002

BROWNSVILLE SUB STATION (Continued) **S103936744**

Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	JIMMY FOX
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ" Con Ed e2mis #138481 Notes: 7-25-01 Area of 10'X20' of contaminated bluestone within Transformer vault #2. Vendor will cleanup and replace bluestone where needed. 4-samples for PCB TCLP will be taken of soil. On 10/23/01 Clean Harbors completed excavating 3-4ft of bluestone from around entire perimeter of the transformer pad. Upon completion, the area was inspected for any visible contamination. None was detected. A glass jar was filled with water and soil from around the pad was taken from random areas. It was inspected for an oil sheen (none was present) and exhibited no odor. Disposal characterized by LSN 01-10347-001. Bluestone grab from roll-off container returned <1ppm PCB. 10-31-01 Results of post-excavation sampling of soil taken from 4 test pits around the perimeter at a depth of 4ft are as follows: THC modified method 8100-(north side) grab 34.8ppm (south side) grab 28.3ppm (east side) grab 1660ppm (west side) grab 144ppm PCB analysis on all four sides returned <1ppm. Clean Harbors will be on-site to backfill the week of Nov. 5th. DEC Inspector Notes: 11-8-01 Based upon visual inspection and post-ex results, Foley instructed SSO EH&S Pete Sudol to backfill bluestone. All areas of bluestone and soil appeared to be clean. e2mis notes: 11/13/01 1530 hours Kerry Foley NYSDEC conducted inspection of Brownsville substation on 11/08/01 at 0930 hours. She OKed cleanup of Bank #2. Backfill is in progress. 11/20/01 Allstate Power Vac completed backfill of vault 2. Incident can be closed. P Sudol #80493 7/25/02 This incident has been closed and submitted to DEC. C.Koehler 84220
Remarks:	SAMPLES TAKEN-CONTRACTOR TO DO THE CLEANUP. CON ED #138481.

Material:

Site ID:	226750
Operable Unit ID:	841056
Operable Unit:	01
Material ID:	565963
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported

BROWNSVILLE SUB STATION (Continued) **S103936744**

Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	226753
Facility Addr2:	Not reported
Facility ID:	0301459
Spill Number:	0301459
Facility Type:	ER
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Spill Date:	5/9/2003
Reported to Dept:	5/9/2003
CID:	322
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/17/2003
Remediation Phase:	0
Date Entered In Computer:	5/9/2003
Spill Record Last Update:	6/17/2003
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY" Refer to spill #0108073, e2mis #140170. Con Ed e2mis #148306: J.RIVERA #86361 ENGENERING AID EH&S REPORTS END CAP TO RADIATOR DRAIN VAVLE LEAKED APPROX 1 PINT OF DIELECTRIC FLUID ONTO A 4"X4" AREA OF BLUESTONE UNDER DRAIN. LAD SEQ#99-07355-001 @ 15 PPM PCB. DRAIN VALVE CLEANED UP WITH ABSORBANT PADS VALVE REPAIRED. BLUESTONE REMAINS TO BE REPLACED. MAINT TO BE NOTIFIED. 5/9/03 1944hrs Bluestone removed approx 2 shovels full. Valve remains tagged pending maintenance for repairs. Cleanup completed. 5/30/03 1522hrs As per inspection on 5/30/03 with K. Foley of the NYSDEC, this spill will be closed and all information will be captured under e2mis #140170.
Remarks:	end cap radiator valve failed causing spill to blue stone - con ed #148306 - 15 ppm pcb count - clean up in progress

BROWNSVILLE SUB STATION (Continued) **S103936744**

Material:

Site ID:	226753
Operable Unit ID:	869475
Operable Unit:	01
Material ID:	505952
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	0104424
Investigator:	RODRIGUEZ
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	07/25/2001 14:00
Reported to Dept Date/Time:	07/25/01 15:03
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Contact:	JIMMY FOX
Spiller Phone:	(212) 580-6763
Spiller Address:	UNK
Spiller City,St,Zip:	UNK
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Other

BROWNSVILLE SUB STATION (Continued) **S103936744**

PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/09/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/25/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/13/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con Ed e2mis 138481 Notes: 7-25-01 Area of 10 X20 of contaminated bluestone within Transformer vault 2. Vendor will cleanup and replace bluestone where needed. 4-samples for PCB TCLP will be taken of soil. On 10/23/01 Clean Harbors completed excavating 3-4ft of bluestone from around entire perimeter of the transformer pad. Upon completion, the area was inspected for any visible contamination. None was detected. A glass jar was filled with water and soil from around the pad was taken from random areas. It was inspected for an oil sheen none was present) and exhibited no odor. Disposal characteri ed by LSN 01-10347-001. Bluestone grab from roll-off container returned <1ppm PCB. 10-31-01 Results of post-excavation sampling of soil taken from 4 test pits around the perimeter at a depth of 4ft are as follows: THC modified method 8100- north side) grab 34.8ppm
south side) grab 28.3ppm
east side) grab 1660ppm west side) grab
144ppm PCB analysis on all four sides returned <1ppm. Clean Harbors will be on-site to backfill the week of Nov. 5th. DEC Inspector Notes: 11-8-01 Based upon visual inspection and post-ex results, Foley instructed SSO EH S Pete Sudol to backfill bluestone. All areas of bluestone and soil appeared to be clean.

BROWNSVILLE SUB STATION (Continued) **S103936744**

Remark: SAMPLES TAKEN-CONTRACTOR TO DO THE CLEANUP. CON ED 138481.

Region of Spill: 2
Spill Number: 0001683
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/08/2000 17:10
Reported to Dept Date/Time: 05/09/00 19:07
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: (212) 580-6763
Spiller Contact: JIM FOX
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/09/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/10/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons

BROWNSVILLE SUB STATION (Continued) **S103936744**

Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: ABOVE MATERIAL DISCOVERED ABOVE LOCATION AS A SHEEN CONCRETE. CLEANUP IS IN PROGRESS. MATERIAL BEING TREATED AS 50/499 PPM. CON ED 131327.

Region of Spill: 2
Spill Number: 9901103
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/29/1999 04:15
Reported to Dept Date/Time: 04/29/99 05:14
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: FRAANK MASSERIA
Spiller Phone: (212) 580-6762
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/06/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/29/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/14/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported

BROWNSVILLE SUB STATION (Continued) **S103936744**

Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 4
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: con ed e2mis notes: Approx 3 1/2 gallons leaking from a oil pump on transf 4 brownsville 1 on pad mond, oil contained to mond, no sewers or waterways affected, records show 2 - records 1-10ppm - 2-22 ppm , waiting for O.S. to take sample and start cleanup. 4/29/99 Blevins 55304 reports clean up complete. Documentation received from supervisor Anthoney Lubrano indicates that the clean up was completed on 29-APR 1999 @ 10:30 hrs. Absorbents were used to remove residual fluids and the stained areas were washed. The oil is known to have a pcb count of <50 ppm. The leak was sealed but the transformer group is awaiting parts to complete the repairs. Con ed shows the PCB result of oi lin the Selector Compartment of Transformer 4 to be less than 10 ppm. The oil in the main body to be 22 ppm. When the Central Maintenance assessed the pump leak situation, they determined the leak was coming from the tap changer fill lines oil from selector compartment). Another lab sample taken on 12/16/98 showed PCB to be less than 1ppm. The e2mis report will be updated to reflect this information.
Remark: SPILL FROM OIL PUMP. SAMPLE TAKEN. CLEAN UP PENDING PCB TEST. CON ED SPILL NUMBER 124526. NO CALL BACK NEEDED.

AR229 **BROWNSVILLE SUBSTATION** **NY Spills** **S103937122**
East **247 WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 13 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 184091
Facility Addr2: Not reported
Facility ID: 0406421
Spill Number: 0406421
Facility Type: ER
SWIS: 2401
Investigator: GDBREEN
Referred To: Not reported
Spill Date: 9/11/2004
Reported to Dept: 9/11/2004
CID: 38
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/12/2004
Remediation Phase:	0
Date Entered In Computer:	9/11/2004
Spill Record Last Update:	11/12/2004
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON 151710
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	139569
DEC Memo:	155306 Employee reports that while doing inspections of mh in Brownsville S/S for 138kv fdr 38B04 found 1 gallon transmission fdr oil on fdr cable under it and on concrete floor of MH65455. No fire/smoke involved. No sewers or waterways affected. No private property affected. Substance owned by Coned. Leak is dripping approx 1 drop per minute. Generator knowledge of transmission fdr oil is <50 ppm pcb. Structure is being treated as 50-499 to perform clean up and to do maintenance work on the fdr line. Will not be hanging an env. stop tag since work is proceeding as 50-499. structure inside Station. Will notify if chem lab will be taking samples. UPDATE 11-SEP-2004 16:25 HRS. TRANSMISSION OPS. SPLICER A. O'CONNELL EMP# 11949 REPORTS: REPAIRED VALVE ON OIL LINE. SPILL WAS WIPED UP ABSORBENT PADS THEN AREA WAS WASHED WITH SIMPLE GREEN. ALL PADS BAGGED FOR DISPOSAL AS 50-499. CLEANUP COMPLETE 100%.
Remarks:	feeder line 38b04 cable was leaking, cleanup pending sample test con ed ref # 155306

Material:

Site ID:	184091
Operable Unit ID:	889013
Operable Unit:	01
Material ID:	487489
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	226751
Facility Addr2:	Not reported
Facility ID:	0105487
Spill Number:	0105487
Facility Type:	ER
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Spill Date:	8/21/2001
Reported to Dept:	8/21/2001
CID:	382
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/18/2009
Remediation Phase:	0
Date Entered In Computer:	8/21/2001
Spill Record Last Update:	9/10/2009
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	JIMMY FOX
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	09/10/09 - See eDocs for Con Ed report detailing cleanup and closure. 06/18/09 - See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ" 6/22/07: spill submitted for closure by Con Ed. Request rejected, with comment: "Post-remediation report was never submitted to NYSDEC for review and approval (only report for vaults 5 and 6 at Brownsville were submitted)." (JHO) ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ Con Ed e2mis #139037: 8/21/01 0955hrs 1oz dielectric fluid leaked from base of B phase pothead oil sampling valve of Transformer #3 on feeder 38B03 onto bluestone. 8/21/01 1125hrs Cleanup completed by using oil absorb and diapers. Bluestone dug up and placed into barrel. Valve wrapped in absorbant padding to stop leak. 9/24/01 1945hrs As per Watt, the cleanup supervisor, on 8/21/01 from 1020 to 1130, crew removed all visible traces of oil and excavated the contaminated soil/bluestone. 12/17/01 1535hrs Historical oil

BROWNSVILLE SUBSTATION (Continued) **S103937122**

contamination was reported in NYSDEC #9601831 on 5/6/96. 4/3/02 1500hrs AllState Power Vac reported on site and removed stained bluestone/soil around bank #3. Excavation took place between 3/12/02 and 3/22/02. Removed with vactor truck into roll off containers. On 3/29/02, a site inspection was performed by NYSDEC Kerry Foley. Gave OK to backfill with clean bluestone. Waste disposal results are on file. 5/29/03 1753hrs Maximo #125433 capture all repair work to be done on "38B03 bank #3 B phase pothead oil sample valve.

Remarks: LEAK FROM OIL VALVE CAUSED 1 OZ SPILL ONTO BLUESTONE. CLEAN UP PENDING CREWS AT LOCATION. LEAK RATE OF 1 DROP EVERY 15 MIN. CON ED 139-037

Material:

Site ID:	226751
Operable Unit ID:	843841
Operable Unit:	01
Material ID:	533952
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	9911282
Investigator:	COMENALE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	12/27/1999 04:30
Reported to Dept Date/Time:	12/27/99 06:28
SWIS:	61
Spiller Name:	CON EDISON
Spiller Contact:	Not reported

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Spiller Phone: ( ) -
Spiller Contact: STEVE ROMERO
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/27/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/17/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: Not reported
Remark: 2 QTS SPILLED TO CONCRETE PAD FROM TRANSFORMER 4 - CONTAINED

Region of Spill: 2
Spill Number: 0105487
Investigator: RODRIGUEZ
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 08/21/2001 09:55
Reported to Dept Date/Time: 08/21/01 10:29
SWIS: 61
Spiller Name: CON ED
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: JIMMY FOX
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/21/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/23/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Remark: LEAK FROM OIL VALVE CAUSED 1 OZ SPILL ONTO BLUESTONE. CLEAN UP PENDING CREWS AT LOCATION. LEAK RATE OF 1 DROP EVERY 15 MIN. CON ED 139-037

Region of Spill: 2
Spill Number: 0105499
Investigator: RODRIGUEZ
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 08/21/2001 11:55
Reported to Dept Date/Time: 08/21/01 12:49
SWIS: 61
Spiller Name: CON ED
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: JIMMY FOX
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: -
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 08/21/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/23/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: leak from flange caused 1 o spill onto bluestone. clean up in progress. leak rate of 1 drop per hr. con ed 139-044

Region of Spill: 2
Spill Number: 9901573
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/10/1999 23:30
Reported to Dept Date/Time: 05/11/99 01:16
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/06/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/11/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/14/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: con ed e2mis notes: Found 1 pt unknown oil on floor in brownsville S/S 2 F/O switch gear 7 apx. 40 sq feet area. There is no equipment that contains oil in area. Can not tell where oil came from. Oil pads were put down on top of oil and areawas taped off. No sewers or waterways were affected. Blivin reports oil residue due to washing out salt spreader, was told relief operator of Mr. Blevins and janitor, outside contractor, of faulties they are the ones that washed spreader, Mr. Blivin was suggested to call ERT, wheather to take sample, update Mr. Blevin called 5-16-99 at 11:45 hrs and said he talk to Mr. P.Sudol and this is not a envoronmental incident. Incident closed as of 5-14-99 1100hrs. After conferring with the janitor who had performed the cleanup of the salt spreader the previous day, Substation Operator J.Blevins was informerd that the material on the floor was the soap w/ water used clean the salt spreader, no oil as had been initially reported.
Remark: 1 pint of unknown oil on concrete floor. sample will be taken. clean up pending results.

Region of Spill: 2
Spill Number: 0011821
Investigator: OKWUOHA
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 02/01/2001 18:30
Reported to Dept Date/Time: 02/01/01 20:04
SWIS: 61
Spiller Name: CON ED
Spiller Contact: SAME
Spiller Phone: (212) 580-6763
Spiller Contact: SEAN MCKEEVER
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY
Spill Cause: Human Error
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False

BROWNSVILLE SUBSTATION (Continued) **S103937122**

Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/17/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 02/01/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/17/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 1
Unkonwn Quantity Recovered: False
Material: LUBRICATING OIL
Class Type: LUBRICATING OIL
Times Material Entry In File: 292
CAS Number: Not reported
Last Date: Not reported
Material: LUBE OIL
Class Type: LUBE OIL
Times Material Entry In File: 295
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: E2MIS Notes 2/1/01: Pothead in cubicle 71 fot causing debri and approx 4 o of insulatium spilled onto concrete. No sewers or waterways affected. Will clean as 50-499. No smoke or fire. 2/1/01 2025 hrs: H. Watt will do a spot cleanup 50-499. 2/7/01 14:15: Cleanup completed on 2/2/001 at 6:35 am by removing/recovering solids/liquids. pot head was replaced. Incident closed. ARS
Remark: THEY WERE WORKING ON A POT HEAD AND THE MATERIAL SPILLED.

AR230 **BROWNSVILLE SUBSTATION TR #1** **NY Spills** **S106018061**
East **247 WILLIAMS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 14 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	165628
Facility Addr2:	Not reported
Facility ID:	0306243
Spill Number:	0306243
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	9/12/2003
Reported to Dept:	9/12/2003
CID:	266
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/10/2008
Remediation Phase:	0
Date Entered In Computer:	9/12/2003
Spill Record Last Update:	1/10/2008
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	NEW YORK, NY 10003
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	139569
DEC Memo:	01/10/08 - See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ" E2MIS 150317 9/12/03 - 1219 J. BLEVINS - 55304 - SSO, REPORTS FINDING APPROX 4 OZ OF NON-PCB DIELECTRIC FLUID THAT LEAKED FROM THE PIPING & VALVES ON THE A & B PHASE POTHEADS OF TRANSFORMER #1 ON FDR 38B01. THE VALVES & PIPING ARE BARELY LEAKING. SPILL IS CONTAINED TO BLUESTONE. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO PRIVATE PROPERTY AFFECTED. CLEANUP TO BE DONE ON THE 3 - 11 SHIFT. MARRIAGE ROLL HAS BEEN PLACED UNDER THE SLIGHT DRIP TO CONTAIN. FDR IS SCHEDULED TO COME OFF ON SUNDAY - 9/14. THE PIPING & VALVES WILL BE REPAIRED AT THAT TIME.
Remarks:	LEAK FROM PIPING AND VALVES ON POTHEADS A & B ATTACHED TO TRANSFORMER 1. 4 OUNCES SPILLED ONTO BLUESTONE. NON-PCB. CLEAN UP PENDING LINE DEENERGIZATION. CON EDISON REFERENCE NUMBER 150317.

Material:

Site ID:	165628

BROWNSVILLE SUBSTATION TR #1 (Continued) **S106018061**

Operable Unit ID:	872821
Operable Unit:	01
Material ID:	503480
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AR231 **MANHOLE 69357** **NY Spills** **S104195554**
East **247 WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 15 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:

Site ID:	226758
Facility Addr2:	Not reported
Facility ID:	9907667
Spill Number:	9907667
Facility Type:	ER
SWIS:	2401
Investigator:	COMENALE
Referred To:	Not reported
Spill Date:	9/24/1999
Reported to Dept:	9/24/1999
CID:	371
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/23/2003
Remediation Phase:	0

MANHOLE 69357 (Continued) **S104195554**

Date Entered In Computer:	9/24/1999
Spill Record Last Update:	11/8/2004
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	FRANK MASSERIA
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	e2mis no. 127995: J. BLEVINS # 55304 SSO BROWNSVILLE S.S. 247 WILLIAMS AVE REPORTS IN STATION MH69357 HE FOUND APPROX 25 GALLONS OF UNKNOWN OIL, NO WATER IN HOLE. HE FOUND UNKNOWN OIL WHILE DOING INSPECTION. 138 KV HI-FDR 38B02 & 38B02-T RUNS THRU HOLE. HE DOES NOT SEE ANY SUMP OR SEWER CONNECTION IN HOLE. NO SEWER OR WATERWAYS AFFECTED. THERE IS NO OTHER OIL FILLED EQUIPMENT IN HOLE. CHEM LAB TO TAKE A LIQUID SAMPLE. E.S.TAG #044-0068 WAS PLACED. O.S. H.WATSON TRANSMISSION OPERATOR PHONE# 204-4488 REQUESTED CLEAN HARBORS TO START CLEANUP AS 50- 499 RIGHT AWAY. WILL LEAVE E.S.TAG IN PLACED UNTIL SAMPLE RESULTS COME BACK. NYS DEC # 99-07667. CGO crew found 25 gallons of old fluid in manhole 69357. Feeders 38B05 and 38B02T run through this manhole. No leak found. Clean Harbors notified to clean up manhole. Chem lab took samples. Clean Harbors cleaned manhole treating as if it was 50-499 PCB's. Temp EPA ID # NYP004033254 received for cleanup. Clean Harbors finished cleanup at 9/25 at 18:30. They removed 800 gallons of liquid from manhole and shipped as 50-499 ppm PCB's. Chem lab reported 99-10068 <1.0 ppm PCB's. Chem lab reports 99-10097 <0.013 ppm benzene. CLEANUP CHECKLIST Location of spill. MANHOLE 69357 BROWNSVILLE S/S Source/cause of spill. OLD OIL FOUND IN MANHOLE X Removed/recovered liquid/solids. X Washed stained areas. X Name of contractor CLEAN HARBORS X Recovered oil/water 800 GALLONS amount Cleanup completed on Date 09/25/99 Time 18:30
Remarks:	found 25 gal unknown petroleum in manhole - sample taken - clean up pending results -- no con ed number yet.

Material:

Site ID:	226758
Operable Unit ID:	1086245
Operable Unit:	01
Material ID:	563472
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported

MANHOLE 69357 (Continued) **S104195554**

Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9907667
Investigator: COMENALE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 09/24/1999 16:23
Reported to Dept Date/Time: 09/24/99 17:37
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: FRANK MASSERIA
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/17/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/24/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/12/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported

MANHOLE 69357 (Continued) **S104195554**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 25
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: e2mis notes: Approx. 9 gallons oil and 6 gallons water in P-Box. Source unknown at this time. Liquid sample taken. Update 1155hrs 9/25/99: Underground reports D-fault tag. Update 16:15hrs: Results 2ppm PCBs. Update 9/26/99: Cleanup completed. Update 9/27/99: Incident closed.
Remark: found 25 gal unknown petroleum in manhole - sample taken - clean up pending results -- no con ed number yet.

AR232 **BROWNSVILL SUBJ STATION** **NY Spills** **S103482743**
East **247 WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.148 mi.
780 ft. **Site 16 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

NY Spills:
Site ID: 226756
Facility Addr2: Not reported
Facility ID: 9804649
Spill Number: 9804649
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 7/14/1998
Reported to Dept: 7/14/1998
CID: 270
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 8/11/1998
Remediation Phase: 0
Date Entered In Computer: 7/14/1998
Spill Record Last Update: 6/26/2000
Spiller Name: FRAANK MASSERIA
Spiller Company: CON ED
Spiller Address: 247 WILLIAMS AVE
Spiller City,St,Zip: BROOKLYN, NY

BROWNSVILL SUBJ STATION (Continued) **S103482743**

Spiller Company:	001
Contact Name:	FRAANK MASSERIA
Contact Phone:	(212) 580-6762
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" 8/11/98: Update from ERT Lukeshides - Spill report indicates dielectric fluid spilled. Actual material spilled: transformer oil. Final spill amount 1 pint. PCB count 10 ppm based on historical data. Cleanup/repair date 7/15/98 @ 1015. Leaking plug tightened.
Remarks:	MECHANICAL FAILURE ON A TRANSFORMER

Material:

Site ID:	226756
Operable Unit ID:	1062564
Operable Unit:	01
Material ID:	319368
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	226754
Facility Addr2:	Not reported
Facility ID:	0307334
Spill Number:	0307334
Facility Type:	ER
SWIS:	2401
Investigator:	SKARAKHA
Referred To:	Not reported
Spill Date:	10/12/2003
Reported to Dept:	10/12/2003
CID:	233
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

BROWNSVILL SUBJ STATION (Continued) **S103482743**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/14/2004
Remediation Phase:	0
Date Entered In Computer:	10/12/2003
Spill Record Last Update:	5/10/2007
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY -
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	187164
DEC Memo:	e2mis no. 150715: APPROX 1/2 PINT OF TRANSORMER FLUID FROM A WEEPING BLEED VALVE ON MAIN BODY OF TRANSFORMER. LEAK CONTAINED WITH PADS. 2 STOP TAGS 044-0071 OF 'C' PHASE & 044-0070 ON 'A' PHASE PLACED. RECORDS INDICATE LESS THAN 10 PPM. MAINT NOTIFIED TO DO CLEANUP & MAKE REPAIRS TO VALVE. 10/12/03 05:40 HRS. -- J.CHOMIUK REPORTS CLEANUP COMPLETE, LEAKS WERE STOPPED AND ENV. STOP TAGS REMOVED.
Remarks:	CON ED # 150715 WEEPING BLEED VALVE HAS CAUSED THIS SPILL SPILL IS CONTAINED AND CLEAN UP IS PENDING CREW SPILL IS TO CONCRETE

Material:

Site ID:	226754
Operable Unit ID:	876057
Operable Unit:	01
Material ID:	500878
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

BROWNSVILL SUBJ STATION (Continued) **S103482743**

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	9804649
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	07/14/1998 09:00
Reported to Dept Date/Time:	07/14/98 10:58
SWIS:	61
Spiller Name:	CON ED
Spiller Contact:	FRAANK MASSERIA
Spiller Phone:	(212) 580-6762
Spiller Contact:	FRAANK MASSERIA
Spiller Phone:	(212) 580-6762
Spiller Address:	247 WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	08/11/98
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	07/14/98
Date Spill Entered In Computer Data File:	Not reported
Update Date:	06/26/00
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum

BROWNSVILL SUBJ STATION (Continued) **S103482743**

Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: 8/11/98: Update from ERT Lukeshides - Spill report indicates dielectric fluid spilled. Actual material spilled: transformer oil. Final spill amount 1 pint. PCB count 10 ppm based on historical data. Cleanup/repair date 7/15/98 @ 1015. Leaking plug tightened.
Remark: MECHANICAL FAILURE ON A TRANSFORMER

233
SE
1/8-1/4
0.148 mi.
780 ft.

504 HINSDALE STREET **AST** **A100292467**
504 HINSDALE STREET **N/A**
NEW YORK, NY 11207

Relative:
Lower

Actual:
28 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-607672
Program Type: PBS
UTM X: 593119.91847999999
UTM Y: 4501885.03125
Expiration Date: 2007/04/18

Affiliation Records:
Site Id: 29524
Affiliation Type: Mail Contact
Company Name: NYC/HPD/DPM
Contact Type: Not reported
Contact Name: ASST. COMMISSIONER/DPM
Address1: 100 GOLD ST
Address2: #6Z1
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 863-7087
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29524
Affiliation Type: Emergency Contact
Company Name: NYC/HPD/DPM
Contact Type: Not reported
Contact Name: ASST. COMMISSIONER/DPM
Address1: Not reported
Address2: Not reported

504 HINSDALE STREET (Continued) **A100292467**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	8/19/2004

Site Id:	29524
Affiliation Type:	On-Site Operator
Company Name:	504 HINSDALE STREET
Contact Type:	Not reported
Contact Name:	ASST. COMMISSIONER/ DPM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	29524
Affiliation Type:	Owner
Company Name:	NYC/HPD/DPM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	100 GOLD STREET #6Z1
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 863-7087
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

J02 - Dispenser - Suction
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

504 HINSDALE STREET (Continued) **A100292467**

Tank Info:

Tank Number:	001
Tank Id:	63355
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

AU234 **NYC-HA GLENMORE PLAZA** **FINDS** **1007820774**
WSW **89 CHRISTOPHER AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.148 mi.
784 ft. **Site 1 of 9 in cluster AU**

Relative:
Higher

Actual:
48 ft.

FINDS:

Registry ID: 110019833340

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AU235 **GLENMORE PLAZA -NYCHA** **LTANKS** **S102147380**
WSW **108 CHRISTOPHER AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY** **NY Spills**
0.148 mi. **NY Hist Spills**
784 ft. **Site 2 of 9 in cluster AU**

Relative:
Higher

Actual:
48 ft.

LTANKS:

Site ID:	272843
Spill No:	9413245
Spill Date:	1/4/1995
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

GLENMORE PLAZA -NYCHA (Continued) **S102147380**

Spill Closed Dt:	Not reported
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	SOME RESIDUAL CONTAM, IWP RCVD 3/3/11
Reported to Dept:	1/4/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	1/5/1995
Spill Record Last Update:	3/10/2011
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Remarks:	CONTRACTOR DOING BORINGS AT LOCATION FOUND CONTAMINATED SOIL.

Material:

Site ID:	272843
Operable Unit ID:	1010793
Operable Unit:	01
Material ID:	371991
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

GLENMORE PLAZA -NYCHA (Continued) **S102147380**

HIST LTANKS:

Region of Spill:	2
Spill Number:	9413245
Spill Date:	01/04/1995
Spill Time:	15:30
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	01/04/95
Reported to Department Time:	15:34
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(212) 306-3142
Facility Extention:	Not reported
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	01/05/95
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	03/17/95
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported

GLENMORE PLAZA -NYCHA (Continued) **S102147380**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL.
Spill Cause: CONTRACTOR DOING BORINGS AT LOCATION FOUND CONTAMINATED SOIL.

NY Spills:
Site ID: 225508
Facility Addr2: Not reported
Facility ID: 9310506
Spill Number: 9310506
Facility Type: ER
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Spill Date: 11/30/1993
Reported to Dept: 11/30/1993
CID: Not reported
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 12/15/1993
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/15/1993
Remediation Phase: 0
Date Entered In Computer: 12/1/1993
Spill Record Last Update: 12/28/1993
Spiller Name: Not reported
Spiller Company: MYSTIC TRANSPORT
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 186158
DEC Memo: Not reported
Remarks: NOTIFIED BY FUEL SUPLIER. FITTING POPPED OUT OF GROUND - CREW ON WAY - CONTAINED BY DRIVER W/SPEEDY DRY.

GLENMORE PLAZA -NYCHA (Continued) **S102147380**

Material:

Site ID:	225508
Operable Unit ID:	989316
Operable Unit:	01
Material ID:	393112
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9310506
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/30/1993 12:45
Reported to Dept Date/Time:	11/30/93 12:58
SWIS:	61
Spiller Name:	MYSTIC TRANSPORT
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	12/15/93
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended

GLENMORE PLAZA -NYCHA (Continued) **S102147380**

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/15/93
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/01/93
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/28/93
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 7
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
DEC Remarks: Not reported
Remark: NOTIFIED BY FUEL SUPLIER. FITTING POPPED OUT OF GROUND - CREW ON WAY - CONTAINED BY DRIVER W/SPEEDY DRY.

AU236 **NYCHA - GLENMORE PLZ** **RCRA-NonGen** **1000550121**
WSW **89 CHRISTOPHER AVE** **NYD986870939**
1/8-1/4 **BROOKLYN, NY 11212**
0.148 mi.
784 ft. **Site 3 of 9 in cluster AU**

Relative:
Higher

Actual:
48 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - GLENMORE PLZ
Facility address: 89 CHRISTOPHER AVE
BROOKLYN, NY 11212
EPA ID: NYD986870939
Mailing address: BROADWAY
NEW YORK, NY 10007
Contact: Not reported
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02

NYCHA - GLENMORE PLZ (Continued) **1000550121**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - GLENMORE PLZ
Classification: Not a generator, verified

Date form received by agency: 04/03/1998
Facility name: NYCHA - GLENMORE PLZ
Classification: Not a generator, verified

Date form received by agency: 02/27/1998
Facility name: NYCHA - GLENMORE PLZ
Classification: Small Quantity Generator

Violation Status: No violations found

AV237 **P.S. 332** **AST** **U003394312**
WSW **51 CHRISTOPHER AVE** **HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.149 mi.
785 ft. **Site 1 of 3 in cluster AV**

Relative:
Higher

Actual:
53 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355747
Program Type:	PBS
UTM X:	592423.20904999995
UTM Y:	4502921.1703599999
Expiration Date:	2013/06/28

Affiliation Records:

Site Id:	17742
Affiliation Type:	Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JAMES A. MERLO
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5738
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/30/2011

Site Id:	17742
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/30/2011

Site Id:	17742
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JAMES A. MERLO
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD

P.S. 332 (Continued) **U003394312**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5738
Phone Ext:	Not reported
Email:	JMERLO@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	9/2/2008

Site Id:	17742
Affiliation Type:	On-Site Operator
Company Name:	PUBLIC SCHOOL 332 - BROOKLYN
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	5/19/2008

Equipment Records:

L00 - Piping Leak Detection - None
L00 - Piping Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Info:

Tank Number:	001
Tank Id:	34734

P.S. 332 (Continued) **U003394312**

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	2/2/1967
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	dxliving
Last Modified:	5/19/2008

Tank Number:	002
Tank Id:	34735
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	2/2/1967
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	dxliving
Last Modified:	5/19/2008

HIST AST:

PBS Number:	2-355747
SWIS Code:	6101
Operator:	PLANT OPERATION
Facility Phone:	(718) 391-6000
Facility Addr2:	51 CHRISTOPHER AVE
Facility Type:	SCHOOL
Emergency:	SCHOOL SAFETY
Emergency Tel:	(212) 979-3300
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CITY OF NEW YORK C/O BOARD OF EDUCATION
Owner Address:	28-11 QUEENS PLAZA NORTH
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 391-6832
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	FRANK CARDELLO NTROL
Mailing Name:	BOARD OF EDUCATION
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	95TH FLOOR

P.S. 332 (Continued) **U003394312**

Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 391-6832
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	09/02/1998
Expiration:	06/28/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	20000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	10000
Product Stored:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

Tank ID:	002
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	10000
Product Stored:	NOS 5 OR 6 FUEL OIL

P.S. 332 (Continued) **U003394312**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

AV238 **P.S. 332 CHARLES H. HOUSTON SCHOOL** **FINDS** **1011460002**
WSW **51 CHRISTOPHER AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.149 mi.
785 ft. **Site 2 of 3 in cluster AV**

Relative:
Higher

Actual:
53 ft.

FINDS:

Registry ID: 110036073904

Environmental Interest/Information System
NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

AF239 **BROWNVILLE SUB STATION** **NY Spills** **S103575634**
East **SUTTER AVE & WILLIAMS ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
786 ft. **Site 5 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NY Spills:

Site ID:	195417
Facility Addr2:	Not reported
Facility ID:	9811793
Spill Number:	9811793
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	12/18/1998
Reported to Dept:	12/18/1998
CID:	257

BROWNVILLE SUB STATION (Continued) **S103575634**

Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	2/14/2003
Remediation Phase:	0
Date Entered In Computer:	12/18/1998
Spill Record Last Update:	2/20/2003
Spiller Name:	RICHARD ROACH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City,St,Zip:	MANHATTAN, NY 10003
Spiller Company:	001
Contact Name:	TONY CONSTANTINE
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	162824
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" E2MIS 122035 18-DEC-1998 1200HRS J MILLER REPORTS THAT BACK HOE #C90878 LEAKED HYDRAULIC FLUID ON TO BLUE STONE AND TRUCK AT THE BROWNVILLE SUBSTATION PARKING LOT THE AMOUNT IS UNKNOWN AT THIS TIME . HUGH TATE OF CONST MGMT SUPERVISOR IS GOING TO LOCATION AT THIS TIME TO REPORT HOW MUCH LEAKED. WILL NOTIFY CIG OF QUANITY, WHEN WE KNOW THIS INFO. NO SEWERS OR WATERWAYS AFFECTED . UPDATE-18-DEC-1998 13:38 CALLED CIG LET KNOW 2 GALLONS WAS THE AMOUNT OF LEAK UPDATE:18-DEC-1998 1547HRS HUGH TATE SUPV CONST MGMT REPORTS CLEANUP COMPLETE AT THIS TIME WITH DIAPERS, ABSORBANTS. BLUE STONE ALSO REMOVED. INCIDENT IS CLOSED. TJ - 50495
Remarks:	hose from backup leaked into blue stone - ref #122035

Material:

Site ID:	195417
Operable Unit ID:	1072567
Operable Unit:	01
Material ID:	312077
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported

BROWNVILLE SUB STATION (Continued) **S103575634**

Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9811793
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 12/18/1998 12:00
Reported to Dept Date/Time: 12/18/98 13:31
SWIS: 61
Spiller Name: CON ED
Spiller Contact: RICHARD ROACH
Spiller Phone: (212) 580-6763
Spiller Contact: TONY CONSTANTINE
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/18/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/11/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported

BROWNVILLE SUB STATION (Continued) **S103575634**

Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: HYDRAULIC OIL
Class Type: HYDRAULIC OIL
Times Material Entry In File: 1846
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: hose from backup leaked into blue stone - ref 122035

AF240 **MANHOLE 5209** **NY Spills** **S103573901**
East **SUTTER AVE & WILLIAMS ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
786 ft. **Site 6 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NY Spills:
Site ID: 195416
Facility Addr2: Not reported
Facility ID: 9809833
Spill Number: 9809833
Facility Type: ER
SWIS: 2401
Investigator: CAENGELH
Referred To: Not reported
Spill Date: 11/4/1998
Reported to Dept: 11/4/1998
CID: 322
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/6/2002
Remediation Phase: 0
Date Entered In Computer: 11/4/1998
Spill Record Last Update: 11/7/2002
Spiller Name: Not reported
Spiller Company: UNK SOURCE
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported

MANHOLE 5209 (Continued) **S103573901**

DEC Region: 2
DER Facility ID: 162824
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" 11/19/98 - Saccacio - General Info: No water. How spill was discovered: Discovered while marking phases for scheduled work on feeder 3B84. Containment: Yes, no sewers or waterways affected. Oil containing equipment in manhole: Primary 27kv cable (PILC). Cleanup Plan: Sample taken and sent to lab with a 4-6 hour turnaround. If the result are not back by the soon the spill will be cleaned up 50-499 ppm PCBs. -sps E2MIS NOTES 121051 buivibas#07974 of fod reports found 5 gallons oil & no water in mh5209 at the nec sutter ave & williams ave. no sewers or waterways affected. sample taken & e.s.tag#08860 placed. mr buivibas was at this location to mark phases for scheduled feeder 3b84. --- mr buivibas cannot see where oil is coming from. taking sample to chemlab and marking 4-6 hour turnaround. cig constantine notified at 1914hrs. 11/4/98 - 2150. R. COSENTINO ON LOC. MET WITH ELIE ST. JOHN OF DEP. MR. ST. JOHN OBSERVED MANHOLE AND IS REQUESTING A SPLIT SAMPLE. 11/4/98 - 2319. DEP HAS SPLIT SAMPLE AND IS SATISFIED WITH PROGRESS OF JOB. 11/4/98 - 2234. BULLITT NOTIFIED TO PICK UP SAMPLE 11/4/98 - 2305. ORIGINAL TEST RESULTS RECIEVED. <1.0 PPM LAB RESULT RECEIVED 11/5/98 - 0045. 98-12118. <1.0 PPM. UPDATE: 11/5/98 - 0108 V. DELLACROCE CALLED CIG AND REPORTED CLEANUP STARTED AT 2130 ON 11/4 AS 50-499. ERT LUKESHIDES NOTIFIED AT 0112 HRS 11/5/98. UPDATE: 11/5/98 - 0345 E. DAVIS - 03732 - ENV. OPS., REPORTS <1.0 PPM CLEANUP INCOMPLETE AND TAG #08860 REMAINS. LAB RESULT RECEIVED 11/5/98 - 0555. 98-12141. <1.0 PPM. UPDATE 07-NOV-1998 15:10 CASTRO FLUSH REPORTS CLEANUP COMPLETE WITH SLIX STOP TAG #08860 WAS REMOVED
Remarks: aprox 5 gal of unk type oil found in manhole

Material:
Site ID: 195416
Operable Unit ID: 1070915
Operable Unit: 01
Material ID: 313728
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

MANHOLE 5209 (Continued) **S103573901**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9809833
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/04/1998 17:00
Reported to Dept Date/Time:	11/04/98 19:24
SWIS:	61
Spiller Name:	UNK SOURCE
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	In Sewer
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	/ /
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	11/04/98
Date Spill Entered In Computer Data File:	Not reported
Update Date:	12/01/98
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	5
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	UNKNOWN PETROLEUM
Class Type:	UNKNOWN PETROLEUM

MANHOLE 5209 (Continued) **S103573901**

Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 11/19/98 - Saccacio - General Info: No water. How spill was discovered: Discovered while marking phases for scheduled work on feeder 3B84. Containment: Yes, no sewers or waterways affected. Oil containing equipment in manhole:Primary 27kv cable PILC). Cleanup Plan: Sample taken and sent to lab with a 4-6 hour turnaround. If the result are not back by the soon the spill will be cleaned up 50-499 ppm PCBs. -sps
Remark: aprox 5 gal of unk type oil found in manhole

AF241 **BROWNSVILLE SUBSTATION** **NY Spills S104880049**
East **SUTTER AV / WILLIAMS AV** **NY Hist Spills N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
786 ft. **Site 7 of 7 in cluster AF**

Relative:
Lower

Actual:
36 ft.

NY Spills:
Site ID: 85549
Facility Addr2: Not reported
Facility ID: 0008746
Spill Number: 0008746
Facility Type: ER
SWIS: 2401
Investigator: OKWUOHA
Referred To: Not reported
Spill Date: 10/27/2000
Reported to Dept: 10/27/2000
CID: 312
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/9/2002
Remediation Phase: 0
Date Entered In Computer: 10/27/2000
Spill Record Last Update: 5/20/2003
Spiller Name: SAME
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 78582
DEC Memo: Not reported
Remarks: VEH LEAKED GAS - NOT CLEANED UP - CLEAN UP COMP WAS CONTACTED

Material:
Site ID: 85549

BROWNSVILLE SUBSTATION (Continued) **S104880049**

Operable Unit ID: 831201
Operable Unit: 01
Material ID: 546246
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 3
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0008746
Investigator: OKWUOHA
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 10/27/2000 08:30
Reported to Dept Date/Time: 10/27/00 10:14
SWIS: 61
Spiller Name: CON EDISON
Spiller Contact: SAME
Spiller Phone: (212) 580-6763
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /

BROWNSVILLE SUBSTATION (Continued) **S104880049**

Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/27/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/06/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 3
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: VEH LEAKED GAS - NOT CLEANED UP - CLEAN UP COMP WAS CONTACTED

AN242 **NYC DEP** **RCRA-NonGen** **1014395414**
WSW **CHRISTOPHER AVE & BELMONT AVE** **NYP003663085**
1/8-1/4 **BROOKLYN, NY 11212**
0.149 mi.
787 ft. **Site 2 of 2 in cluster AN**

Relative:
Higher

Actual:
43 ft.

RCRA-NonGen:
Date form received by agency: 08/25/2006
Facility name: NYC DEP
Facility address: CHRISTOPHER AVE & BELMONT AVE
BROOKLYN, NY 11212
EPA ID: NYP003663085
Mailing address: JUNCTION BLVD
FLUSHING, NY 11373
Contact: JOANNE NURSE
Contact address: JUNCTION BLVD
FLUSHING, NY 11373
Contact country: US
Contact telephone: (718) 595-4675
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

NYC DEP (Continued) **1014395414**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

AW243 **UNITY PLAZA HOUSES** **LTANKS** **U001840687**
East **371 WILLIAMS AVENUE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **UST**
0.149 mi. **HIST UST**
788 ft. **Site 1 of 6 in cluster AW** **AST**
HIST AST
Relative: **NY Spills**
Lower **NY Hist Spills**

Actual: **34 ft.**

LTANKS:

Site ID:	75311
Spill No:	9904855
Spill Date:	7/23/1999
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/7/2005
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	7/23/1999
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/23/1999
Spill Record Last Update:	12/7/2005
Spiller Name:	SEBASTIAN LOREFICE
Spiller Company:	UNITY PLAZA NYCHA
Spiller Address:	371 WILLIAMS AV
Spiller City,St,Zip:	BROOKLYN, NY
Spiller County:	001

UNITY PLAZA HOUSES (Continued) **U001840687**

Spiller Contact: SEBASTIAN LOREFICE
Spiller Phone: (212) 306-3229
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 214155
Remarks: isolate and retest system

Material:
Site ID: 75311
Operable Unit ID: 1079294
Operable Unit: 01
Material ID: 555964
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 75311
Spill Tank Test: 1547410
Tank Number: 1
Tank Size: 30000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

HIST LTANKS:
Region of Spill: 2
Spill Number: 9904855
Spill Date: 07/23/1999
Spill Time: 13:00
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported

UNITY PLAZA HOUSES (Continued) **U001840687**

Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 07/23/99
Reported to Department Time: 14:16
SWIS: 61
Spiller Contact: SEBASTIAN LOREFICE
Spiller Phone: (212) 306-3229
Spiller Extention: Not reported
Spiller Name: UNITY PLAZA
Spiller Address: 371 WILLIAMS AV
Spiller City,St,Zip: BROOKLYN, NY
Spiller Cleanup Date: / /
Facility Contact: SEBASTIAN LOREFICE
Facility Phone: (212) 306-3229
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: 4-74215
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 07/23/99
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/26/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 1
Tank Size: 30000
Test Method: Horner EZ Check
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: isolate and retest system

UST:
Facility Id: 2-474169
Region: STATE
DEC Region: 2
Site Status: Active

UNITY PLAZA HOUSES (Continued) **U001840687**

Program Type: PBS
Expiration Date: 2014/03/28
UTM X: 593114.14015999995
UTM Y: 4502295.4762599999

Affiliation Records:

Site Id: 20886
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 707-5900
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/13/2011

Site Id: 20886
Affiliation Type: On-Site Operator
Company Name: UNITY PLAZA HOUSES
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION UNIT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/31/2008

Site Id: 20886
Affiliation Type: Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: \\
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

UNITY PLAZA HOUSES (Continued) **U001840687**

Date Last Modified: 4/19/2011

Site Id: 20886
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/19/2010

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F05 - Pipe External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I04 - Overfill - Product Level Gauge (A/G)
B09 - Tank External Protection - Urethane
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
L08 - Piping Leak Detection - Tank Top Sump
H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
C01 - Pipe Location - Aboveground
H05 - Tank Leak Detection - In-Tank System (ATG)
I03 - Overfill - Automatic Shut-Off
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

UNITY PLAZA HOUSES (Continued) **U001840687**

F00 - Pipe External Protection - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
I03 - Overfill - Automatic Shut-Off
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:

Site ID:	20886
Tank Number:	1
Tank ID:	179323
Tank Status:	In Service
Tank Model:	108
Pipe Model:	E
Install Date:	6/1/2004
Capacity Gallons:	30000
Tightness Test Method:	21
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	0
Date Test:	7/20/2004
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008
Site ID:	20886
Tank Number:	OLD 2
Tank ID:	37613
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/1/1975
Capacity Gallons:	30000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	9/1/2003
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	nrlombar
Last Modified:	7/6/2004

HIST UST:

PBS Number:	2-474169
SPDES Number:	Not reported
Emergency Contact:	EMERGENCY SERVICE SQUAD
Emergency Telephone:	(212) 289-3940
Operator:	MR. LUIS PONCE
Operator Telephone:	(718) 707-5725
Owner Name:	NYC HOUSING AUTHORITY

UNITY PLAZA HOUSES (Continued) **U001840687**

Owner Address:	23-02 49TH AVENUE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 707-5725
Owner Type:	Local Government
Owner Subtype:	51
Mailing Name:	NYC HOUSING AUTHORITY
Mailing Address:	23-02 49TH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Contact:	MR. LUIS PONCE
Mailing Telephone:	(718) 707-5725
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	578 BLAKE AVENUE (MGT OFFICE)
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	04/20/2001
Expiration Date:	03/28/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	36000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Temporarily Out Of Service
Install Date:	19750901
Capacity (gals):	30000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Product Level Gauge
Dispenser:	Suction

UNITY PLAZA HOUSES (Continued) **U001840687**

Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-474169
Program Type: PBS
UTM X: 593114.14015999995
UTM Y: 4502295.4762599999
Expiration Date: 2014/03/28

Affiliation Records:
Site Id: 20886
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICES DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 707-5900
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/13/2011

Site Id: 20886
Affiliation Type: On-Site Operator
Company Name: UNITY PLAZA HOUSES
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION UNIT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/31/2008

Site Id: 20886

UNITY PLAZA HOUSES (Continued) **U001840687**

Affiliation Type:	Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011

Site Id:	20886
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/19/2010

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F05 - Pipe External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I04 - Overfill - Product Level Gauge (A/G)
B09 - Tank External Protection - Urethane
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
L08 - Piping Leak Detection - Tank Top Sump

UNITY PLAZA HOUSES (Continued) **U001840687**

H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
C01 - Pipe Location - Aboveground
H05 - Tank Leak Detection - In-Tank System (ATG)
I03 - Overfill - Automatic Shut-Off
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
I03 - Overfill - Automatic Shut-Off
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:

Tank Number:	T1
Tank Id:	172763
Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/2003
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	7/1/2004
Register:	True
Modified By:	nrlombar
Last Modified:	7/6/2004

Tank Number:	T1-A
Tank Id:	172765
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	8/1/2002
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	5/1/2003

UNITY PLAZA HOUSES (Continued) **U001840687**

Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-474169
SWIS Code:	6101
Operator:	MR. LUIS PONCE
Facility Phone:	(718) 707-5725
Facility Addr2:	578 BLAKE AVENUE (MGT OFFICE)
Facility Type:	APARTMENT BUILDING
Emergency:	EMERGENCY SERVICE SQUAD
Emergency Tel:	(212) 289-3940
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	NYC HOUSING AUTHORITY
Owner Address:	23-02 49TH AVENUE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 707-5725
Owner Type:	Local Government
Owner Subtype:	51
Mailing Contact:	MR. LUIS PONCE
Mailing Name:	NYC HOUSING AUTHORITY
Mailing Address:	23-02 49TH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 707-5725
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	04/20/2001
Expiration:	03/28/2004
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	36000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	T-1
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	19990101
Capacity (Gal):	6000
Product Stored:	NOS 1,2, OR 4 FUEL OIL

UNITY PLAZA HOUSES (Continued) **U001840687**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Epoxy Liner
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	Not reported
Overfill Protection:	34
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

NY Spills:

Site ID:	75310
Facility Addr2:	Not reported
Facility ID:	9900066
Spill Number:	9900066
Facility Type:	ER
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Spill Date:	4/2/1999
Reported to Dept:	4/2/1999
CID:	211
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/8/2006
Remediation Phase:	0
Date Entered In Computer:	4/2/1999
Spill Record Last Update:	3/8/2006
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	NEW YORK, NY 10007-
Spiller Company:	001
Contact Name:	ED MALONE
Contact Phone:	(212) 306-8480
DEC Region:	2
DER Facility ID:	214155

UNITY PLAZA HOUSES (Continued) **U001840687**

DEC Memo: 11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski.
02/02/06: This spill transferred from S.Kraszewski to Q.Abidi.
03/08/06: This spill deemed as no immediate threat to the environment or public health and safety. This spill closed out. - SK
Remarks: hydraulic line from compactor leaked - spill contained with pads and cleaned up

Material:
Site ID: 75310
Operable Unit ID: 1078843
Operable Unit: 01
Material ID: 307206
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9900066
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 04/02/1999 08:15
Reported to Dept Date/Time: 04/02/99 11:08
SWIS: 61
Spiller Name: NYC HOUSING AUTHORITY
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Contact: ED MALONE
Spiller Phone: (212) 306-8480
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NEW YORK, NY 10007-
Spill Cause: Unknown
Reported to Dept: On Land

UNITY PLAZA HOUSES (Continued) **U001840687**

Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: -474169
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 04/02/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 06/03/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 1
Unkonwn Quantity Recovered: False
Material: HYDRAULIC OIL
Class Type: HYDRAULIC OIL
Times Material Entry In File: 1846
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: hydraulic line from compactor leaked - spill contained with pads and cleaned up

---

AW244 **NYCHA - UNITY PLAZA** **RCRA-NonGen** **1001223893**
East **371 WILLIAMS AVE** **FINDS** **NYR000051094**
1/8-1/4 **BROOKLYN, NY 11207**
0.149 mi.
788 ft. **Site 2 of 6 in cluster AW**

Relative:
Lower

Actual:
34 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - UNITY PLAZA
Facility address: 371 WILLIAMS AVE
BROOKLYN, NY 11207
EPA ID: NYR000051094
Mailing address: BROADWAY
NEW YORK, NY 10007

NYCHA - UNITY PLAZA (Continued) **1001223893**

Contact: Not reported
Contact address: BROADWAY
NEW YORK, NY 10007
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC HOUSING AUTHORITY
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - UNITY PLAZA
Classification: Not a generator, verified

Date form received by agency: 04/03/1998
Facility name: NYCHA - UNITY PLAZA
Classification: Not a generator, verified

NYCHA - UNITY PLAZA (Continued) **1001223893**

Date form received by agency: 02/27/1998
Facility name: NYCHA - UNITY PLAZA
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004540845

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AW245 **UNITY PROJECT** **LTANKS** **S104278465**
East **371 WILLIAMS AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
788 ft. **Site 3 of 6 in cluster AW**

Relative:
Lower

Actual:
34 ft.

LTANKS:

Site ID:	262314
Spill No:	9908775
Spill Date:	10/19/1999
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/30/2009
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9102328
Reported to Dept:	10/19/1999
CID:	252

UNITY PROJECT (Continued) **S104278465**

Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	10/19/1999
Spill Record Last Update:	12/30/2009
Spiller Name:	ED MALONE
Spiller Company:	UNITY PROJECT NYCHA
Spiller Address:	371 WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller County:	001
Spiller Contact:	ED MALONE
Spiller Phone:	(212) 306-8480
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	214155
Remarks:	WILL INVESTIGATE AND LATER RE-TEST.

Material:

Site ID:	262314
Operable Unit ID:	1083052
Operable Unit:	01
Material ID:	297875
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	262314
Spill Tank Test:	1547750
Tank Number:	1
Tank Size:	30000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

Site ID:	262313
Spill No:	0403571
Spill Date:	7/2/2004
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/6/2009

UNITY PROJECT (Continued) **S104278465**

Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9908775
Reported to Dept:	7/2/2004
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/2/2004
Spill Record Last Update:	7/6/2009
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller County:	999
Spiller Contact:	JOHN RIGGUSO
Spiller Phone:	(646) 529-6531
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	214155
Remarks:	Air leak, non liquid leak.

Material:

Site ID:	Not reported
Operable Unit ID:	Not reported
Operable Unit:	Not reported
Material ID:	Not reported
Material Code:	Not reported
Material Name:	Not reported
Case No.:	Not reported
Material FA:	Not reported
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	262313
Spill Tank Test:	1529410
Tank Number:	Not reported
Tank Size:	30000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

UNITY PROJECT (Continued) **S104278465**

HIST LTANKS:

Region of Spill:	2
Spill Number:	9908775
Spill Date:	10/19/1999
Spill Time:	13:00
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	10/19/99
Reported to Department Time:	15:49
SWIS:	61
Spiller Contact:	ED MALONE
Spiller Phone:	(212) 306-8480
Spiller Extention:	Not reported
Spiller Name:	UNITY PROJECT
Spiller Address:	371 WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN
Spiller Cleanup Date:	/ /
Facility Contact:	ED MALONE
Facility Phone:	(212) 306-8480
Facility Extention:	Not reported
Spill Notifier:	Local Agency
PBS Number:	4-74215
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	10/19/99
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	10/20/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	1
Tank Size:	30000
Test Method:	Horner EZ Check
Leak Rate Failed Tank:	0.00

UNITY PROJECT (Continued) **S104278465**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: WILL INVESTIGATE AND LATER RE-TEST.

246
ENE
1/8-1/4
0.149 mi.
788 ft.

Relative:
Higher

Actual:
65 ft.

MH 55133
17 WILLIAMS AVE
BROOKLYN, NY

NY Spills **S104283735**
NY Hist Spills **N/A**

NY Spills:
Site ID: 114219
Facility Addr2: Not reported
Facility ID: 9909505
Spill Number: 9909505
Facility Type: ER
SWIS: 2401
Investigator: JHOCONNE
Referred To: Not reported
Spill Date: 11/4/1999
Reported to Dept: 11/4/1999
CID: 270
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/2/1999
Remediation Phase: 0
Date Entered In Computer: 11/4/1999
Spill Record Last Update: 5/15/2000
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, NY
Spiller Company: 001
Contact Name: CALLER
Contact Phone: Not reported
DEC Region: 2

MH 55133 (Continued) **S104283735**

DER Facility ID: 99637
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"
Remarks: UNK OIL ON 300 GALS WATER IN MANHOLE SAMPLE TAKEN CLEAN UP PENDING 128863

Material:
Site ID: 114219
Operable Unit ID: 1084276
Operable Unit: 01
Material ID: 555935
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9909505
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/04/1999 14:00
Reported to Dept Date/Time: 11/04/99 14:41
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: UNKNOWN
Spiller Phone: ( ) -
Spiller Contact: CALLER
Spiller Phone: ( ) -
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported

MH 55133 (Continued) **S104283735**

Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/02/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/04/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/15/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: UNK OIL ON 300 GALS WATER IN MANHOLE SAMPLE TAKEN CLEAN UP PENDING 128863

AW247 **NYCHA - UNITY PLAZA HOUSES** **RCRA-NonGen** **1001493639**
East **375 WILLIAMS AVE** **FINDS** **NYR000075309**
1/8-1/4 **BROOKLYN, NY 11207**
0.149 mi.
789 ft. **Site 4 of 6 in cluster AW**

Relative:
Lower

Actual:
33 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - UNITY PLAZA HOUSES
Facility address: 375 WILLIAMS AVE
BROOKLYN, NY 112072516
EPA ID: NYR000075309
Mailing address: BROADWAY
NEW YORK, NY 100072516
Contact: FRANK OCELLO

NYCHA - UNITY PLAZA HOUSES (Continued) **1001493639**

Contact address: BROADWAY
NEW YORK, NY 100072516
Contact country: US
Contact telephone: (212) 306-3229
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - UNITY PLAZA HOUSES
Classification: Not a generator, verified

Date form received by agency: 08/12/1999
Facility name: NYCHA - UNITY PLAZA HOUSES
Classification: Small Quantity Generator

NYCHA - UNITY PLAZA HOUSES (Continued) **1001493639**

Violation Status: No violations found

FINDS:

Registry ID: 110004555598

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AW248 **MH3953** **NY Spills** **S104653622**
East **375 WILLIAMS AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
789 ft. **Site 5 of 6 in cluster AW**

Relative:
Lower

Actual:
33 ft.

NY Spills:

Site ID:	179796
Facility Addr2:	Not reported
Facility ID:	0003134
Spill Number:	0003134
Facility Type:	ER
SWIS:	0301
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	6/13/2000
Reported to Dept:	6/13/2000
CID:	270
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/26/2001
Remediation Phase:	0
Date Entered In Computer:	6/13/2000
Spill Record Last Update:	10/10/2001
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	001
Contact Name:	CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	150890
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was

MH3953 (Continued) **S104653622**

"O'CONNELL" Con Ed e2mis Notes: 6/13/00 1qt unknown oil on 50gal water in manhole. Sample returned <1ppm PCB. 7/25/00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump.

Remarks: SAMPLE TAKEN CLEAN UP PENDING

Material:

Site ID:	179796
Operable Unit ID:	825344
Operable Unit:	01
Material ID:	551463
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0003134
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	06/13/2000 13:19
Reported to Dept Date/Time:	06/13/00 13:27
SWIS:	60
Spiller Name:	UNKNOWN
Spiller Contact:	Not reported
Spiller Phone:	( ) -
Spiller Contact:	CALLER
Spiller Phone:	( ) -
Spiller Address:	Not reported
Spiller City,St,Zip:	-
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported

MH3953 (Continued) **S104653622**

Spill Source: 12
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 09/26/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 06/13/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/10/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con Ed e2mis Notes: 6/13/00 1qt unknown oil on 50gal water in manhole. Sample returned <1ppm PCB. 7/25/00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump.
Remark: SAMPLE TAKEN CLEAN UP PENDING

AV249 **219315; LIBERTY AV AND CHRISTOPHER AVE** **NY Spills** **S110307562**
WSW **LIBERTY AV AND CHRISTOPHER AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.149 mi.
789 ft. **Site 3 of 3 in cluster AV**

Relative:
Higher

Actual:
56 ft.

NY Spills:
Site ID: 433270
Facility Addr2: Not reported
Facility ID: 0914631
Spill Number: 0914631
Facility Type: ER

219315; LIBERTY AV AND CHRISTOPHER AVE (Continued) **S110307562**

SWIS:	2401
Investigator:	DMPOKRZY
Referred To:	Not reported
Spill Date:	11/18/2009
Reported to Dept:	12/31/2009
CID:	Not reported
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/28/2009
Remediation Phase:	0
Date Entered In Computer:	4/16/2010
Spill Record Last Update:	4/16/2010
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller City,St,Zip:	New York, NY
Spiller Company:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	388200
DEC Memo:	Not reported
Remarks:	Not reported

Material:

Site ID:	433270
Operable Unit ID:	1184181
Operable Unit:	01
Material ID:	2178416
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported

219315; LIBERTY AV AND CHRISTOPHER AVE (Continued) **S110307562**

Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AU250 **CON EDISON MANHOLE 65361** **RCRA-NonGen** **1010327594**
WSW **GLENMORE AVE & CHRISTOPHER ST** **MANIFEST** **NYP004147443**
1/8-1/4 **BROOKLYN, NY 11212**
0.150 mi.
790 ft. **Site 4 of 9 in cluster AU**

Relative:
Higher

Actual:
49 ft.

RCRA-NonGen:
Date form received by agency: 04/11/2007
Facility name: CON EDISON MANHOLE 65361
Facility address: GLENMORE AVE & CHRISTOPHER ST
BROOKLYN, NY 11212
EPA ID: NYP004147443
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL D'AGOSTINO
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/10/2007
Facility name: CON EDISON MANHOLE 65361
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 04/09/2007
Facility name: CON EDISON MANHOLE 65361
Site name: CON EDISON
Classification: Unverified

CON EDISON MANHOLE 65361 (Continued) **1010327594**

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004147443
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	LUIS MERCADO
Mailing Address:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-204-4090

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	1/10/2007
Trans1 Recv Date:	1/10/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	1/11/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147443
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000331365FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-10

CON EDISON MANHOLE 65361 (Continued) **1010327594**

Trans1 Recv Date:	2007-01-10
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-11
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147443
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000331365FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AU251 **CON EDISON** **FINDS** **1010440005**
WSW **GLENMORE AVE & CHRISTOPHER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.150 mi.
790 ft. **Site 5 of 9 in cluster AU**

Relative:
Higher

Actual:
49 ft.

FINDS:

Registry ID: 110031368874

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AK252 **CON ED - MH 66476** **RCRA-NonGen** **1007206440**
East **WILLIAMS AVE & DUMONT AVE** **MANIFEST** **NYP004009866**
1/8-1/4 **BROOKLYN, NY 11207**
0.150 mi.
791 ft. **Site 2 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

RCRA-NonGen:

Date form received by agency:	02/28/1998
Facility name:	CON ED - MH 66476
Facility address:	WILLIAMS AVE & DUMONT AVE BROOKLYN, NY 112070000
EPA ID:	NYP004009866
Mailing address:	CONSOLIDATED EDISON INC 4 IRVING PL RM 300 NEW YORK, NY 100030000
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC NEW YORK, NY 100030000
Contact country:	US
Contact telephone:	(212) 460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/27/1998
Facility name:	CON ED - MH 66476
Classification:	Not a generator, verified

Date form received by agency:	02/26/1998
Facility name:	CON ED - MH 66476
Classification:	Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID:	NYP004009866
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address:	4 IRVING PLACE RM 828

CON ED - MH 66476 (Continued) **1007206440**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	NYG0914562
Manifest Status:	Completed copy
Trans1 State ID:	20854AD
Trans2 State ID:	Not reported
Generator Ship Date:	970730
Trans1 Recv Date:	970730
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970731
Part A Recv Date:	970819
Part B Recv Date:	970815
Generator EPA ID:	NYP004009866
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity:	01109
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	97

Document ID:	NYG0914751
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	80680AE
Trans2 State ID:	Not reported
Generator Ship Date:	970730
Trans1 Recv Date:	970730
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970731
Part A Recv Date:	970825
Part B Recv Date:	970827
Generator EPA ID:	NYP004009866
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00001
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	97

AK253 **MANHOLE #3952** **NY Spills** **S104790255**
East **WILLIAMS AV & DUMONT AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
791 ft. **Site 3 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

NY Spills:

Site ID:	282676
Facility Addr2:	Not reported
Facility ID:	0007876
Spill Number:	0007876
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	10/4/2000
Reported to Dept:	10/4/2000
CID:	390
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/14/2001
Remediation Phase:	0
Date Entered In Computer:	10/4/2000
Spill Record Last Update:	12/14/2001
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller City,St,Zip:	UNKNOWN, NY
Spiller Company:	999
Contact Name:	JIMMIE FOX
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	229490
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Con Ed e2mis #133787 Notes: 10-4-00 1qt unknown oil on 1000gal water in manhole. PCB sample taken. Sample returned <1ppm PCBs. 10-10-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking company equipment.
Remarks:	1 qt oil on 1000 gals of water - sample taken - clean up pending lab results con ed #133787

Material:

Site ID:	282676
Operable Unit ID:	828525
Operable Unit:	01
Material ID:	545400
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1

MANHOLE #3952 (Continued) **S104790255**

Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	0007876
Investigator:	O'CONNELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/04/2000 13:00
Reported to Dept Date/Time:	10/04/00 13:32
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Contact:	JIMMIE FOX
Spiller Phone:	(212) 580-6763
Spiller Address:	UNK
Spiller City,St,Zip:	UNK
Spill Cause:	Unknown
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Local Agency
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/14/01
Corrective Action Plan Submitted:	/ /

MANHOLE #3952 (Continued) **S104790255**

Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/04/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 12/14/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con Ed e2mis 133787 Notes: 10-4-00 1qt unknown oil on 1000gal water in manhole. PCB sample taken. Sample returned <1ppm PCBs. 10-10-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking company equipment.
Remark: 1 qt oil on 1000 gals of water - sample taken - clean up pending lab results con ed 133787

AK254 **CONSOLIDATED EDISON** **MANIFEST** **S108980613**
East **WILLIAMS AVE & DUMONT AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.150 mi.
791 ft. **Site 4 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:
EPA ID: NYP004155008
Country: USA
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/14/2007

CONSOLIDATED EDISON (Continued) **S108980613**

Trans1 Recv Date:	11/14/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/15/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004155008
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001451342FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AK255 **CONSOLIDATED EDISON** **MANIFEST** **S110709226**
East **DUMONT AVE & WILLIAMS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
791 ft. **Site 5 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

NY MANIFEST:

EPA ID:	NYP004217448
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-3770

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2010-10-08
Trans1 Recv Date:	2010-10-08
Trans2 Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S110709226**

TSD Site Recv Date:	2010-10-13
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004217448
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD980593636
Waste Code:	Not reported
Quantity:	150.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2010
Manifest Tracking Num:	001438640FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

AK256 **ONE QUART OIL IN MANHOLE 66368** **NY Spills** **S108956591**
East **WILLIAMS AVENUE & DUMONT AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
791 ft. **Site 6 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

NY Spills:

Site ID:	389680
Facility Addr2:	Not reported
Facility ID:	0708729
Spill Number:	0708729
Facility Type:	ER
SWIS:	2401
Investigator:	gdbreen
Referred To:	Not reported
Spill Date:	11/10/2007
Reported to Dept:	11/10/2007
CID:	72
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/28/2007

ONE QUART OIL IN MANHOLE 66368 (Continued) **S108956591**

Remediation Phase:	0
Date Entered In Computer:	11/10/2007
Spill Record Last Update:	12/28/2007
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ -
Spiller Company:	999
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	339268
DEC Memo:	12/28/07 - See eDocs for Con Ed report detailing cleanup and closure. 208869. see eDocs
Remarks:	1 quart unknown oil in manhole. An earthen sump was found. 208869

Material:

Site ID:	389680
Operable Unit ID:	1146813
Operable Unit:	01
Material ID:	2137200
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AK257 **CON ED - MH 66476** **FINDS** **1005630197**
East **WILLIAMS AVE & DUMONT AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.150 mi.
791 ft. **Site 7 of 7 in cluster AK**

Relative:
Lower

Actual:
32 ft.

FINDS:

Registry ID: 110017252453

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON ED - MH 66476 (Continued) **1005630197**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AW258 **SERVICE BOX 53154** **NY Spills** **S104652811**
East **IFO 395 WILLIAMS AV** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
793 ft. **Site 6 of 6 in cluster AW**

Relative:
Lower

Actual:
32 ft.

NY Spills:

Site ID:	268215
Facility Addr2:	Not reported
Facility ID:	0001955
Spill Number:	0001955
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	5/16/2000
Reported to Dept:	5/16/2000
CID:	211
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/24/2001
Remediation Phase:	0
Date Entered In Computer:	5/16/2000
Spill Record Last Update:	11/7/2001
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	MIKE CESARE
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	218477
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL" Con Ed e2mis #131424 Notes: 5-16-00 1qt unknown oil on 60gal water in service box. Liquid sample returned <1ppm PCB. 5-30-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump.
Remarks:	1 qt unk oil on 60 gals water / sample taken clean up pending results - con ed 131424

Material:

Site ID:	268215
Operable Unit ID:	823870

SERVICE BOX 53154 (Continued) **S104652811**

Operable Unit: 01
Material ID: 550337
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0001955
Investigator: O'CONNELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/16/2000 10:05
Reported to Dept Date/Time: 05/16/00 10:40
SWIS: 61
Spiller Name: UNKNOWN
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Contact: MIKE CESARE
Spiller Phone: (212) 580-6763
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 12
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /

SERVICE BOX 53154 (Continued) **S104652811**

Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 09/24/01
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/16/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/07/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Con Ed e2mis 131424 Notes: 5-16-00 1qt unknown oil on 60gal water in service box. Liquid sample returned <1ppm PCB. 5-30-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment.No sump.
Remark: 1 qt unk oil on 60 gals water / sample taken clean up pending results - con ed 131424

AU259 **GLENMORE PLAZA** **LTANKS** **U001840698**
WSW **108 CHRISTOPHER STREET** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY 11212** **UST**
0.150 mi. **HIST UST**
793 ft. **Site 6 of 9 in cluster AU** **NY Spills**
NY Hist Spills

Relative:
Higher

Actual:
48 ft.

LTANKS:
Site ID: 110612
Spill No: 9602447
Spill Date: 5/21/1996
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 7/24/1996
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

GLENMORE PLAZA (Continued) **U001840698**

SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	5/21/1996
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/21/1996
Spill Record Last Update:	7/24/1996
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	WILLY NEGRON
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Remarks:	old tank removed - contaminated soil found

Material:

Site ID:	110612
Operable Unit ID:	1033927
Operable Unit:	01
Material ID:	352269
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	2
Spill Number:	9602447

GLENMORE PLAZA (Continued) **U001840698**

Spill Date:	05/21/1996
Spill Time:	10:42
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	07/24/96
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	05/21/96
Reported to Department Time:	11:46
SWIS:	61
Spiller Contact:	WILLY NEGRON
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	FRANK OCELLO
Facility Phone:	(212) 306-3229
Facility Extention:	Not reported
Spill Notifier:	Other
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	05/21/96
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	07/24/96
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum

GLENMORE PLAZA (Continued) **U001840698**

Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
DEC Remarks: 7/11/96: spill transferred from KO D to JNH. 7/24/96: old tank removeds. Some contaminated soil found and removed. Site investigation found little subsurface contamination to soil, no groundwater contam. Close out.
Spill Cause: old tank removed - contaminated soil found

UST:
Facility Id: 2-474320
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2014/03/28
UTM X: 592456.82782000001
UTM Y: 4502749.2999700001

Affiliation Records:
Site Id: 20901
Affiliation Type: Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: \\
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/19/2011

Site Id: 20901
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: FUEL OIL REMEDIATION COORDINATOR
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported

GLENMORE PLAZA (Continued) **U001840698**

Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/19/2010

Site Id:	20901
Affiliation Type:	On-Site Operator
Company Name:	GLENMORE PLAZA
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	11/10/2008

Site Id:	20901
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/13/2011

Equipment Records:

H04 - Tank Leak Detection - Groundwater Well
L00 - Piping Leak Detection - None
F06 - Pipe External Protection - Wrapped
A01 - Tank Internal Protection - Epoxy Liner
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground

GLENMORE PLAZA (Continued) **U001840698**

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction

Tank Info:

Site ID:	20901
Tank Number:	1
Tank ID:	37649
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	10/1/1985
Capacity Gallons:	25000
Tightness Test Method:	21
Next Test Date:	2/20/2013
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Fiberglass coated steel
Date Test:	2/20/2008
Register:	True
Modified By:	NRLOMBAR
Last Modified:	11/10/2008
Site ID:	20901
Tank Number:	OLD 1
Tank ID:	37648
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	10/1/1967
Capacity Gallons:	25000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	8/1/1996
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-474320
SPDES Number:	Not reported
Emergency Contact:	EMERGENCY SERVICE SQUAD
Emergency Telephone:	(212) 289-3940
Operator:	RAFAEL VELEZ
Operator Telephone:	(212) 306-3142
Owner Name:	NYC HOUSING AUTHORITY
Owner Address:	250 BROADWAY
Owner City,St,Zip:	NEW YORK, NY 10007
Owner Telephone:	(212) 306-3142

GLENMORE PLAZA (Continued) **U001840698**

Owner Type:	Local Government
Owner Subtype:	51
Mailing Name:	REMEDITAION SECTION-16TH FLOOR
Mailing Address:	NEW YORK HOUSING AUTHORITY
Mailing Address 2:	250 BROADWAY 16TH FLOOR
Mailing City,St,Zip:	NEW YORK, NY 10007
Mailing Contact:	FRANK OCELLO
Mailing Telephone:	(212) 306-3142
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	11/08/1999
Expiration Date:	03/28/2004
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	25000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19671001
Capacity (gals):	25000
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	Groundwater Well
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data

GLENMORE PLAZA (Continued) **U001840698**

Date Closed:	08/01/1996
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19851001
Capacity (gals):	25000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	Groundwater Well
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	04/01/1997
Next Test Date:	04/01/2002
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Horner EZ Check
Deleted:	False
Updated:	True
Lat/long:	Not reported

NY Spills:

Site ID:	110613
Facility Addr2:	Not reported
Facility ID:	9608161
Spill Number:	9608161
Facility Type:	ER
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Spill Date:	9/30/1996
Reported to Dept:	9/30/1996
CID:	282
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/7/1996

GLENMORE PLAZA (Continued) **U001840698**

Remediation Phase:	0
Date Entered In Computer:	9/30/1996
Spill Record Last Update:	10/7/1996
Spiller Name:	DECLAN POWER
Spiller Company:	KELLY TANK
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	FRANCIS FIELDS
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	96846
DEC Memo:	Not reported
Remarks:	PIPING BROKE IN THE BOILER ROOM CAUSING THE SPILL SPILL IS BEING CLEANED UPS

Material:

Site ID:	110613
Operable Unit ID:	1036429
Operable Unit:	01
Material ID:	343901
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9608161
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	09/30/1996 13:00
Reported to Dept Date/Time:	09/30/96 16:51
SWIS:	61

GLENMORE PLAZA (Continued) **U001840698**

Spiller Name: KELLY TANK
Spiller Contact: DECLAN POWER
Spiller Phone: (718) 366-8300
Spiller Contact: FRANCIS FIELDS
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 02
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/07/96
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/30/96
Date Spill Entered In Computer Data File: Not reported
Update Date: 10/07/96
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 10
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
DEC Remarks: Not reported
Remark: PIPING BROKE IN THE BOILER ROOM CAUSING THE SPILL SPILL IS BEING CLEANED UPS

AU260 **GLENMORE HOUSES** **LTANKS** **S104073503**
WSW **108 CHRISTOPHER ST** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY** **NY Spills**
0.150 mi. **NY Hist Spills**
793 ft. **Site 7 of 9 in cluster AU**

Relative:
Higher

Actual:
48 ft.

LTANKS:

Site ID:	120585
Spill No:	9611221
Spill Date:	12/11/1996
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/13/1996
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	12/11/1996
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/11/1996
Spill Record Last Update:	12/13/1996
Spiller Name:	TINA HANSEN
Spiller Company:	CLASSIC OIL
Spiller Address:	9 WYTHE AV
Spiller City,St,Zip:	BROOKLYN, NY 11211-
Spiller County:	001
Spiller Contact:	RAY VELEZ
Spiller Phone:	(212) 306-3142
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Remarks:	THE SUPVSR AT THE NYC HOUSING AUTHORITY ORDERED THE OIL BUT NEVER STUCK THE TANK FOR THE LEVEL - WHEN THE DRIVER FILLED THE TANK, IT OVERFILLED - THE OIL COMPANY IS REFUSING TO CLEAN THE SPILL

Material:

Site ID:	120585
Operable Unit ID:	1039245
Operable Unit:	01
Material ID:	343418
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	100
Resource Affected:	Not reported
Oxygenate:	False

GLENMORE HOUSES (Continued) **S104073503**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	2
Spill Number:	9611221
Spill Date:	12/11/1996
Spill Time:	14:00
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/13/96
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	12/11/96
Reported to Department Time:	14:35
SWIS:	61
Spiller Contact:	RAY VELEZ
Spiller Phone:	(212) 306-3142
Spiller Extention:	Not reported
Spiller Name:	CLASSIC OIL
Spiller Address:	9 WYTHE AV
Spiller City,St,Zip:	BROOKLYN, NY 11211-
Spiller Cleanup Date:	/ /
Facility Contact:	TINA HANSEN
Facility Phone:	(718) 384-3712
Facility Extention:	Not reported
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False

GLENMORE HOUSES (Continued) **S104073503**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 12/11/96
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/13/96
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 100
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 100
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: SEE SPILL 9611220 DUPLICATE SPILL NUMBER)
Spill Cause: THE SUPVSR AT THE NYC HOUSING AUTHORITY ORDERED THE OIL BUT NEVER STUCK THE TANK FOR THE LEVEL - WHEN THE DRIVER FILLED THE TANK, IT OVERFILLED - THE OIL COMPANY IS REFUSING TO CLEAN THE SPILL

NY Spills:
Site ID: 110615
Facility Addr2: Not reported
Facility ID: 9614301
Spill Number: 9614301
Facility Type: ER
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Spill Date: 3/10/1997
Reported to Dept: 3/10/1997
CID: 297
Spill Cause: Human Error
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 8/15/1997
Remediation Phase: 0

GLENMORE HOUSES (Continued) **S104073503**

Date Entered In Computer: 3/10/1997
Spill Record Last Update: 11/5/2002
Spiller Name: ED MALONE
Spiller Company: NYC HOUSING
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: NY, NY 10007-
Spiller Company: 001
Contact Name: ED MALONE
Contact Phone: (212) 306-8480
DEC Region: 2
DER Facility ID: 96846
DEC Memo: Not reported
Remarks: FUEL COMPANY DID NOT OPEN ALL THE COMPARTMENTS IN THE FUEL OIL TANK AND IT CREATED BACKPRESSURE WHICH PUSHED THE OIL BACK OUT THE TANK - DEC ON SITE - WINSTON CONTRACTING CALLED IN FOR THE CLEAN UP

Material:
Site ID: 110615
Operable Unit ID: 1045726
Operable Unit: 01
Material ID: 339403
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 110614
Facility Addr2: Not reported
Facility ID: 9611220
Spill Number: 9611220
Facility Type: ER
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Spill Date: 12/11/1996
Reported to Dept: 12/11/1996
CID: 257
Spill Cause: Human Error
Water Affected: Not reported

GLENMORE HOUSES (Continued) **S104073503**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/13/1996
Remediation Phase:	0
Date Entered In Computer:	12/11/1996
Spill Record Last Update:	9/16/2002
Spiller Name:	TINA
Spiller Company:	CLASSIC OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	WILLIE NEGRON
Contact Phone:	(718) 498-0882
DEC Region:	2
DER Facility ID:	96846
DEC Memo:	Not reported
Remarks:	PROBLEM WITH VENT CLEANUP CREW FINISHING CLEAN UP NOW

Material:

Site ID:	110614
Operable Unit ID:	1039243
Operable Unit:	01
Material ID:	561130
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100
Units:	Gallons
Recovered:	100
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

GLENMORE HOUSES (Continued) **S104073503**

NY Hist Spills:

Region of Spill:	2
Spill Number:	9611220
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	12/11/1996 13:00
Reported to Dept Date/Time:	12/11/96 14:32
SWIS:	61
Spiller Name:	CLASSIC OIL
Spiller Contact:	TINA
Spiller Phone:	(718) 384-3712
Spiller Contact:	WILLIE NEGRON
Spiller Phone:	(718) 498-0882
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Human Error
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/13/96
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	12/11/96
Date Spill Entered In Computer Data File:	Not reported
Update Date:	12/13/96
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	100
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	100

GLENMORE HOUSES (Continued) **S104073503**

Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: PROJECT ORDERED 5,000 GALLONS FOR DELIVERY TO 6,500 GALLON TEMPORARY TANK. HAD 274 GALLONS ON-HAND. DRIVER WAS DELIVERING OIL AT TOO FAST A RATE FOR OIL TO EQUILIBRATE INSIDE THREE COMPARTMENTS OF TANK. SPILLED OUT THROUGH VENT CAP ON TOP OF TANK. WINSTON CONTRACTING PERFORMED CLEAN UP.
Remark: PROBLEM WITH VENT CLEANUP CREW FINISHING CLEAN UP NOW

Region of Spill: 2
Spill Number: 9614301
Investigator: HEALY
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/10/1997 09:30
Reported to Dept Date/Time: 03/10/97 12:05
SWIS: 61
Spiller Name: NYC HOUSING
Spiller Contact: ED MALONE
Spiller Phone: (212) 306-8480
Spiller Contact: ED MALONE
Spiller Phone: (212) 306-8480
Spiller Address: 250 BROADWAY
Spiller City,St,Zip: MANHATTAN, NY 10007-
Spill Cause: Human Error
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 02
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/15/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/10/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/15/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported

GLENMORE HOUSES (Continued) **S104073503**

Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 100
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Remark: FUEL COMPANY DID NOT OPEN ALL THE COMPARTMENTS IN THE FUEL OIL TANK AND IT CREATED BACKPRESSURE WHICH PUSHED THE OIL BACK OUT THE TANK - DEC ON SITE - WINSTON CONTRACTING CALLED IN FOR THE CLEAN UP

AU261 **NYCHA - GLENMORE PLAZA** **RCRA-NonGen** **1004762087**
WSW **108 CHRISTOPHER ST** **FINDS** **NYR000093401**
1/8-1/4 **BROOKLYN, NY 11212** **MANIFEST**
0.150 mi.
793 ft. **Site 8 of 9 in cluster AU**

Relative:
Higher

Actual:
48 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - GLENMORE PLAZA
Facility address: 108 CHRISTOPHER ST
BROOKLYN, NY 11212
EPA ID: NYR000093401
Mailing address: 49TH AVE
LONG ISLAND CITY, NY 111014528
Contact: ANTHONY SOLOMITA
Contact address: 49TH AVE
LONG ISLAND CITY, NY 111014528
Contact country: US
Contact telephone: (718) 707-5731
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK CITY HOUSING AUTH
Owner/operator address: 23-02 49TH AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 707-5731
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY HOUSING AUTH

NYCHA - GLENMORE PLAZA (Continued) **1004762087**

Owner/operator address: 23-02 49TH AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 707-5731
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - GLENMORE PLAZA
Classification: Not a generator, verified

Date form received by agency: 01/23/2001
Facility name: NYCHA - GLENMORE PLAZA
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004566675

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYR000093401
Country: USA
Mailing Name: NYCHA GLENMORE PLAZA
Mailing Contact: NYCHA GLENMORE PLAZA
Mailing Address: 108 CHRISTOPHER ST

NYCHA - GLENMORE PLAZA (Continued) **1004762087**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11212
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-498-0882

Document ID:	NYG2932074
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/2001
Trans1 Recv Date:	06/25/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093401
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1011
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01

Document ID:	NYG2935872
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	05/02/2001
Trans1 Recv Date:	05/02/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/03/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000093401
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)

NYCHA - GLENMORE PLAZA (Continued) **1004762087**

Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00300
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	01

AJ262 **MANHOLE 5167** **NY Spills** **S103574006**
WSW **SUTTER AVE/CHRISTOPHER ST** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
793 ft. **Site 6 of 6 in cluster AJ**

Relative:
Higher

Actual:
41 ft.

NY Spills:

Site ID:	219994
Facility Addr2:	Not reported
Facility ID:	9809934
Spill Number:	9809934
Facility Type:	ER
SWIS:	2401
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	11/6/1998
Reported to Dept:	11/6/1998
CID:	312
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/8/2002
Remediation Phase:	0
Date Entered In Computer:	11/6/1998
Spill Record Last Update:	11/8/2002
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999

MANHOLE 5167 (Continued) **S103574006**

Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	181953
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" E2MIS NOTES 121105 11-06-98 12:30 E. BROGAN REPORTS, FOUND 1/2 GAL OF UNKNOWN OIL ON 1000 GAL OF WATER IN MH 58826. HOLE IS CONTAINED & NO SEWERS OR WATERWAYS WERE AFFECTED. NO OIL FILLED EQUIPMENT IN HOLE. FOUND WHILE WORKING ON FDR 3B84. 1 LIQUID SAMPLE WAS TAKEN ON A 4-6HR TURNAROUND.ENV. STOP TAG # 13572. S.PACE 49874. CIS WAS NOTIFIED AT 13:02HRS.. UPDATE OIL SAMPLE RESULTS 11/6/98 21:35 LAB SEQ. #98-12241 LESS THEN 1 PPM PCB FOR MH58826 11/7/98--RUF, FLUSH, REPORTS CLEANUP COMPLETED WITH SLIX 2045HRS-TAG#13573 REMOVED
Remarks:	1 pint of unk oil on top of 750 gal of water in manhole - sample taken - case #121105

Material:

Site ID:	219994
Operable Unit ID:	1067206
Operable Unit:	01
Material ID:	313824
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	2
Spill Number:	9809934
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/06/1998 13:00
Reported to Dept Date/Time:	11/06/98 13:57

MANHOLE 5167 (Continued) **S103574006**

SWIS: 61
Spiller Name: CON ED
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/06/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/10/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: 1 pint of unk oil on top of 750 gal of water in manhole - sample taken - case 121105

AS263 **LI BAPTIST** **LTANKS** **S100153362**
East **341 WILLIAM AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
794 ft. **Site 2 of 2 in cluster AS**

Relative:
Lower

Actual:
35 ft.

LTANKS:

Site ID:	180611
Spill No:	9105511
Spill Date:	8/21/1991
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not reported
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	jkkann
Referred To:	IWP RCVD 3/3/11
Reported to Dept:	8/21/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	8/29/1991
Spill Record Last Update:	3/10/2011
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	151494
Remarks:	5K HORNER EZ CHECK E,I & R

Material:

Site ID:	180611
Operable Unit ID:	956006
Operable Unit:	01
Material ID:	421301
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

LI BAPTIST (Continued) **S100153362**

Tank Test:
Site ID: 180611
Spill Tank Test: 1538932
Tank Number: 001
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 9105511
Spill Date: 08/21/1991
Spill Time: 14:15
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 08/21/91
Reported to Department Time: 15:14
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYCHA
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (212) 306-3142
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: 2-474118
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False

LI BAPTIST (Continued) **S100153362**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 08/29/91
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/05/94
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 001
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: 5K HORNER EZ CHECK E,I R

AX264 **ELVA MCZEAL** **UST** **U004076253**
East **405 WILLIAMS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.151 mi.
795 ft. **Site 1 of 5 in cluster AX**

Relative:
Lower

Actual:
32 ft.

UST:
Facility Id: 2-095362
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2011/03/24
UTM X: 593132.17150000005
UTM Y: 4502197.8274499997

Affiliation Records:
Site Id: 2636
Affiliation Type: Mail Contact
Company Name: ELVA MCZEAL APARTMENTS C/O ARCO MGMT.
Contact Type: Not reported
Contact Name: MAMIE FREEMAN
Address1: 4 EXECUTIVE BLVD.
Address2: SUITE 100
City: SUFFERN
State: NY
Zip Code: 10901
Country Code: 001

ELVA MCZEAL (Continued) **U004076253**

Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	MFREEMAN@MULTIFAMILYMGMT.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	Emergency Contact
Company Name:	UHAB AAF NEIGHBORHOOD RESTORE HDFC
Contact Type:	Not reported
Contact Name:	MAMIE FREEMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	Owner
Company Name:	UHAB AAF NEIGHBORHOOD RESTORE HDFC
Contact Type:	V.P. ASST. MGMT.DIV.
Contact Name:	MAMIE C. FREEMAN
Address1:	4 EXECUTIVE BLVD, SUITE 100
Address2:	Not reported
City:	SUFFERN
State:	NY
Zip Code:	10901
Country Code:	001
Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	On-Site Operator
Company Name:	ELVA MCZEAL
Contact Type:	Not reported
Contact Name:	CANDI LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 498-7558
Phone Ext:	Not reported
Email:	Not reported

ELVA MCZEAL (Continued) **U004076253**

Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 3/27/2007

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

ELVA MCZEAL (Continued) **U004076253**

B01 - Tank External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping

Tank Info:

Site ID:	2636
Tank Number:	001
Tank ID:	4524
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1972
Capacity Gallons:	4000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	2636
Tank Number:	002
Tank ID:	4525
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1972
Capacity Gallons:	4000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/1998
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

AX265 **ELVA MCZEAL** **HIST UST** **U003127547**
East **405 WILLIAMS AVENUE** **AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **HIST AST**
0.151 mi.
795 ft. **Site 2 of 5 in cluster AX**

Relative:
Lower

Actual:
32 ft.

HIST UST:

PBS Number:	2-095362
SPDES Number:	Not reported
Emergency Contact:	SCOTT LANGAN
Emergency Telephone:	(914) 368-2400
Operator:	SEANETTE MCCRAY

ELVA MCZEAL (Continued) **U003127547**

Operator Telephone:	(718) 498-7558
Owner Name:	JEFFREY P. GOLDSTEIN AS RECEIVER
Owner Address:	113 BON AIRE CIRCLE WEST
Owner City,St,Zip:	SUFFERN, NY 10901
Owner Telephone:	(914) 368-2400
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Name:	ELVA MCZEAL APARTMENTS C/O ARCO MGMT.
Mailing Address:	113 BON AIRE CIRCLE WEST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SUFFERN, NY 10901
Mailing Contact:	MR. SCOTT LANGAN
Mailing Telephone:	(914) 368-2400
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	405 WILLIAMS AVE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	APARTMENT BUILDING
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/23/1999
Expiration Date:	05/07/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	16000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19721201
Capacity (gals):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None

ELVA MCZEAL (Continued) **U003127547**

Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	05/01/1998
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19721201
Capacity (gals):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	05/01/1998
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-095362
Program Type:	PBS
UTM X:	593132.17150000005
UTM Y:	4502197.8274499997
Expiration Date:	2011/03/24

Affiliation Records:

Site Id:	2636
Affiliation Type:	Mail Contact
Company Name:	ELVA MCZEAL APARTMENTS C/O ARCO MGMT.
Contact Type:	Not reported
Contact Name:	MAMIE FREEMAN
Address1:	4 EXECUTIVE BLVD.
Address2:	SUITE 100
City:	SUFFERN

ELVA MCZEAL (Continued) **U003127547**

State:	NY
Zip Code:	10901
Country Code:	001
Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	MFREEMAN@MULTIFAMILYMGMT.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	Emergency Contact
Company Name:	UHAB AAF NEIGHBORHOOD RESTORE HDFC
Contact Type:	Not reported
Contact Name:	MAMIE FREEMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	Owner
Company Name:	UHAB AAF NEIGHBORHOOD RESTORE HDFC
Contact Type:	V.P. ASST. MGMT.DIV.
Contact Name:	MAMIE C. FREEMAN
Address1:	4 EXECUTIVE BLVD, SUITE 100
Address2:	Not reported
City:	SUFFERN
State:	NY
Zip Code:	10901
Country Code:	001
Phone:	(914) 368-2400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Site Id:	2636
Affiliation Type:	On-Site Operator
Company Name:	ELVA MCZEAL
Contact Type:	Not reported
Contact Name:	CANDI LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

ELVA MCZEAL (Continued) **U003127547**

Phone:	(718) 498-7558
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	3/27/2007

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
J02 - Dispenser - Suction
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron

ELVA MCZEAL (Continued) **U003127547**

J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping

Tank Info:

Tank Number:	0010
Tank Id:	54698
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	6/1/1998
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

Tank Number:	0020
Tank Id:	54699
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	6/1/1998
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

Tank Number:	03
Tank Id:	56154
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	5/1/1998
Capacity Gallons:	4000
Tightness Test Method:	NN

ELVA MCZEAL (Continued) **U003127547**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

Tank Number:	04
Tank Id:	56155
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	5/1/1998
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-095362
SWIS Code:	6101
Operator:	SEANETTE MCCRAY
Facility Phone:	(718) 498-7558
Facility Addr2:	405 WILLIAMS AVE
Facility Type:	APARTMENT BUILDING
Emergency:	SCOTT LANGAN
Emergency Tel:	(914) 368-2400
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	JEFFREY P. GOLDSTEIN AS RECEIVER
Owner Address:	113 BON AIRE CIRCLE WEST
Owner City,St,Zip:	SUFFERN, NY 10901
Federal ID:	Not reported
Owner Tel:	(914) 368-2400
Owner Type:	Private Resident
Owner Subtype:	Not reported
Mailing Contact:	MR. SCOTT LANGAN
Mailing Name:	ELVA MCZEAL APARTMENTS C/O ARCO MGMT.
Mailing Address:	113 BON AIRE CIRCLE WEST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SUFFERN, NY 10901
Mailing Telephone:	(914) 368-2400
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	03/23/1999

ELVA MCZEAL (Continued) **U003127547**

Expiration:	05/07/2002
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	16000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	0010
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	19980601
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	01
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	00
Tank Containment:	Diking
Leak Detection:	04
Overfill Protection:	04
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

Tank ID:	0020
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	19980601
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	1
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	01
Tank Containment:	Diking

ELVA MCZEAL (Continued) **U003127547**

Leak Detection:	04
Overfill Protection:	04
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

Tank ID:	03
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	19980501
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	01
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	01
Tank Containment:	Diking
Leak Detection:	00
Overfill Protection:	02
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

Tank ID:	04
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	19980501
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	0
Tank External:	01
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	01
Tank Containment:	Diking
Leak Detection:	00

ELVA MCZEAL (Continued) **U003127547**

Overfill Protection:	02
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

AY266 **NY Spills** **S105234963**
WSW **1812 PITKIN AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.151 mi.
795 ft. **Site 1 of 2 in cluster AY**

Relative:
Higher

Actual:
46 ft.

NY Spills:

Site ID:	197831
Facility Addr2:	Not reported
Facility ID:	0108702
Spill Number:	0108702
Facility Type:	ER
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Spill Date:	11/30/2001
Reported to Dept:	11/30/2001
CID:	257
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/12/2003
Remediation Phase:	0
Date Entered In Computer:	11/30/2001
Spill Record Last Update:	11/12/2003
Spiller Name:	CALLER
Spiller Company:	METRO OIL
Spiller Address:	500 KINGSLAND AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	MARGARET GENTLE
Contact Phone:	(718) 383-1400
DEC Region:	2
DER Facility ID:	164631
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"
Remarks:	broken gauge causing overfill - cleaned up

(Continued) **S105234963**

Material:
Site ID: 197831
Operable Unit ID: 847033
Operable Unit: 01
Material ID: 529939
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: 2
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 0108702
Investigator: TIPPLE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 11/30/2001 10:00
Reported to Dept Date/Time: 11/30/01 10:14
SWIS: 61
Spiller Name: METRO OIL
Spiller Contact: CALLER
Spiller Phone: (718) 383-1400
Spiller Contact: MARGARET GENTLE
Spiller Phone: (718) 383-1400
Spiller Address: 500 KINGSLAND AVE
Spiller City,St,Zip: BROOKLYN, NY
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 07
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False

(Continued) **S105234963**

Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/30/01
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/30/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 2
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Remark: broken gauge causing overfill - cleaned up

AP267 **NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN** **RCRA-NonGen** **1004759513**
East **275 LIBERTY AVE** **FINDS** **NYR000011957**
1/8-1/4 **BROOKLYN, NY 11207** **MANIFEST**
0.151 mi.
798 ft. **Site 3 of 4 in cluster AP**

Relative:
Higher

Actual:
54 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Facility address: 275 LIBERTY AVE
BROOKLYN, NY 11207
EPA ID: NYR000011957
Mailing address: LIBERTY AVE
BROOKLYN, NY 11207
Contact: ROBERT GUASTA
Contact address: LIBERTY AVE
BROOKLYN, NY 11207
Contact country: US
Contact telephone: (718) 349-5590
Contact email: Not reported

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 28-11 QUEENS PLZ N
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 349-5600
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 28-11 QUEENS PLZ N
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 349-5600
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Classification: Not a generator, verified

Date form received by agency: 08/22/1995
Facility name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004517693

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000011957
Country:	USA
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	JACK BRUCCULERI
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-391-6094

Document ID:	NJA2182274
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	50082
Trans2 State ID:	S6993
Generator Ship Date:	950822
Trans1 Recv Date:	950822
Trans2 Recv Date:	951026
TSD Site Recv Date:	951027
Part A Recv Date:	Not reported
Part B Recv Date:	951107
Generator EPA ID:	NYR000011957
Trans1 EPA ID:	NY0000551218
Trans2 EPA ID:	NJD980772768
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00150
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	95

AZ268 **D T SUPPLY CORP** **FINDS** **1007800707**
West **21 CHRISTOPHER AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.152 mi.
802 ft. **Site 1 of 5 in cluster AZ**

Relative:
Higher

Actual:
58 ft.

FINDS:

Registry ID: 110019632272

D T SUPPLY CORP (Continued) **1007800707**

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AT269 **CONSOLIDATED EDISON** **MANIFEST** **S110045771**
WNW **2371 ATLANTIC AVE AND SACKMAN** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.156 mi.
823 ft. **Site 2 of 4 in cluster AT**

Relative:
Higher

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004197497
Country:	USA
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	2009-10-02
Trans1 Recv Date:	2009-10-02
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-10-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004197497
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	300.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000893809GBF
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

CONSOLIDATED EDISON (Continued) **S110045771**

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

AT270 **CON EDISON - MANHOLE 5076** **RCRA-LQG** **1014397429**
WNW **2371 ATLANTIC AVE AND SACKMAN** **NYP004197497**
1/8-1/4 **BROOKLYN, NY 11233**
0.156 mi.
823 ft. **Site 3 of 4 in cluster AT**

Relative:
Higher

Actual:
75 ft.

RCRA-LQG:
Date form received by agency: 03/23/2010
Facility name: CON EDISON - MANHOLE 5076
Facility address: 2371 ATLANTIC AVE AND SACKMAN
ST
BROOKLYN, NY 11233
EPA ID: NYP004197497
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/02/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Owner/Operator Type: Operator
Owner/Op start date: 10/02/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/02/2009
Facility name: CON EDISON - MANHOLE 5076
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

BA271 **WIGIS & WIGIS MGMT CO AVE.** **AST** **U003385159**
East **496 WILLIAMS AVE** **HIST AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.156 mi.
826 ft. **Site 1 of 3 in cluster BA**

Relative:
Lower

Actual:
29 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-097810
Program Type: PBS
UTM X: 593187.16145000001
UTM Y: 4501940.59571
Expiration Date: 1992/05/07

Affiliation Records:
Site Id: 2814
Affiliation Type: Mail Contact
Company Name: CITY OF NEW YORK HPD
Contact Type: Not reported
Contact Name: Not reported
Address1: 75 MODERN LANE
Address2: Not reported
City: NEW YORK

WIGIS & WIGIS MGMT CO AVE. (Continued) **U003385159**

State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 806-8552
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2814
Affiliation Type: Emergency Contact
Company Name: CITY OF NEW YORK HPD
Contact Type: Not reported
Contact Name: MILTON BROWN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 385-8069
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2814
Affiliation Type: On-Site Operator
Company Name: WIGIS & WIGIS MGMT CO AVE.
Contact Type: Not reported
Contact Name: WIGIS & WIGIS MGMT CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 385-8069
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2814
Affiliation Type: Owner
Company Name: CITY OF NEW YORK HPD
Contact Type: Not reported
Contact Name: Not reported
Address1: 75 MODERN LANE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001

WIGIS & WIGIS MGMT CO AVE. (Continued) **U003385159**

Phone:	(212) 806-8552
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

Tank Info:

Tank Number:	001
Tank Id:	5149
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-097810
SWIS Code:	6101
Operator:	WIGIS & WIGIS MGMT CORP
Facility Phone:	(718) 385-8069
Facility Addr2:	496 WILLIAMS AVE
Facility Type:	Not reported
Emergency:	MILTON BROWN
Emergency Tel:	(718) 385-8069
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CITY OF NEW YORK HPD
Owner Address:	75 MODERN LANE
Owner City,St,Zip:	NEW YORK, NY 10038
Federal ID:	Not reported
Owner Tel:	(212) 806-8552
Owner Type:	Not reported

WIGIS & WIGIS MGMT CO AVE. (Continued) **U003385159**

Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	CITY OF NEW YORK HPD
Mailing Address:	75 MODERN LANE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10038
Mailing Telephone:	(212) 806-8552
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	05/07/1987
Expiration:	05/07/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	3000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	9
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

BB272 **VAN DYKE HOUSES** **UST** **U004064927**
WSW **393 DUMONT AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.157 mi.
830 ft. **Site 1 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

UST:

Facility Id:	2-474282
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	2014/03/28
UTM X:	592587.46424
UTM Y:	4502066.7541199997

Affiliation Records:

Site Id:	20897
Affiliation Type:	Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011

Site Id:	20897
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/19/2010

Site Id:	20897
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPARTMENT
Address1:	Not reported
Address2:	Not reported

VAN DYKE HOUSES (Continued) **U004064927**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008

Site Id:	20897
Affiliation Type:	On-Site Operator
Company Name:	VAN DYKE HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E04 - Piping Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
H00 - Tank Leak Detection - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
E10 - Piping Secondary Containment - Impervious Underlayment
I02 - Overfill - High Level Alarm
D11 - Pipe Type - Flexible Piping

VAN DYKE HOUSES (Continued) **U004064927**

A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
F05 - Pipe External Protection - Jacketed
L08 - Piping Leak Detection - Tank Top Sump
I04 - Overfill - Product Level Gauge (A/G)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
J02 - Dispenser - Suction
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
L08 - Piping Leak Detection - Tank Top Sump
I00 - Overfill - None
D11 - Pipe Type - Flexible Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F05 - Pipe External Protection - Jacketed
K00 - Spill Prevention - None
J02 - Dispenser - Suction
I03 - Overfill - Automatic Shut-Off
B09 - Tank External Protection - Urethane
G04 - Tank Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F06 - Pipe External Protection - Wrapped
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:
Site ID: 20897

Tank Number: 1
Tank ID: 62981

VAN DYKE HOUSES (Continued) **U004064927**

Tank Status:	In Service
Tank Model:	108
Pipe Model:	E
Install Date:	2/2/2002
Capacity Gallons:	20000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	0
Date Test:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008
Site ID:	20897
Tank Number:	2
Tank ID:	62982
Tank Status:	In Service
Tank Model:	108
Pipe Model:	E
Install Date:	2/2/2002
Capacity Gallons:	20000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	0
Date Test:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	12/31/2008
Site ID:	20897
Tank Number:	OLD 1
Tank ID:	37638
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1955
Capacity Gallons:	25000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/2001
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	20897
Tank Number:	OLD 2
Tank ID:	37639

VAN DYKE HOUSES (Continued) **U004064927**

Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	10/1/1985
Capacity Gallons:	25000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	5/1/2001
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	20897
Tank Number:	OLD 3
Tank ID:	37640
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	12/1/1955
Capacity Gallons:	50000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	11/1/1992
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

BB273 **HIST LTANKS** **S105055267**
WSW **393 DUMONT AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.157 mi.
830 ft. **Site 2 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

HIST LTANKS:

Region of Spill:	2
Spill Number:	0103847
Spill Date:	07/11/2001
Spill Time:	12:00
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	ROMMEL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported

(Continued) **S105055267**

Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 07/11/01
Reported to Department Time: 12:27
SWIS: 61
Spiller Contact: MARIO MANDELONE
Spiller Phone: (718) 649-7017
Spiller Extention: Not reported
Spiller Name: NYC HOUSING
Spiller Address: 123 WILLIAMS ST
Spiller City,St,Zip: NYC, NY 10038-
Spiller Cleanup Date: / /
Facility Contact: CALLER
Facility Phone: ( ) -
Facility Extention: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 07/11/01
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/12/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #4 FUEL OIL
Class Type: #4 FUEL OIL
Times Material Entry In File: 1751
CAS Number: Not reported
Last Date: 19941205
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0

(Continued) **S105055267**

Unkonwn Quantity Recovered: False
Material: #6 FUEL OIL
Class Type: #6 FUEL OIL
Times Material Entry In File: 2190
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Spill Cause: CONTAMINATED SOIL FOUND DURING THE REMOVAL ON REPLACEMENT OF A 25,000 GAL TANK AT LOCATION.

BB274 **VAN DYKE HOUSING -NYCHA** **LTANKS** **S100145682**
WSW **393 DUMONT AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.157 mi.
830 ft. **Site 3 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

LTANKS:
Site ID: 260222
Spill No: 8907648
Spill Date: 11/1/1989
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 2/9/2006
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 11/1/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/6/1989
Spill Record Last Update: 2/9/2006
Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 258193
Remarks: 25K TANK. OIL COMING IN FROM UST INTO BOILER ROOM. TANK TAKEN OUT OF SERVICE.

Material:
Site ID: 260222
Operable Unit ID: 935265

VAN DYKE HOUSING -NYCHA (Continued) **S100145682**

Operable Unit: 01
Material ID: 444433
Material Code: 0003
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 260222
Spill Tank Test: 1536343
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 2
Spill Number: 8907648
Spill Date: 11/01/1989
Spill Time: 12:00
Spill Cause: Tank Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 11/01/89
Reported to Department Time: 14:20
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NYCHA
Spiller Address: Not reported

VAN DYKE HOUSING -NYCHA (Continued) **S100145682**

Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (718) 345-4532
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: 2-474282
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 11/06/89
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/02/95
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Not reported
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #6 FUEL OIL
Class Type: #6 FUEL OIL
Times Material Entry In File: 2190
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Spill Cause: 25K TANK. OIL COMING IN FROM UST INTO BOILER ROOM. TANK TAKEN OUT OF SERVICE.

BB275 **NYCHA - VAN DYKE HOUSES** **RCRA-NonGen** **1001493637**
WSW **393 DUMONT AVE** **FINDS** **NYR000075283**
1/8-1/4 **BROOKLYN, NY 11212** **MANIFEST**
0.157 mi.
830 ft. **Site 4 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYCHA - VAN DYKE HOUSES
Facility address: 393 DUMONT AVE
BROOKLYN, NY 112122516
EPA ID: NYR000075283
Mailing address: BROADWAY
NEW YORK, NY 100072516
Contact: FRANK OCELLO
Contact address: BROADWAY

NYCHA - VAN DYKE HOUSES (Continued) **1001493637**

NEW YORK, NY 100072516
Contact country: US
Contact telephone: (212) 306-3229
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYCHA
Owner/operator address: 250 BROADWAY
NEW YORK, NY 10007
Owner/operator country: US
Owner/operator telephone: (212) 306-3229
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NYCHA - VAN DYKE HOUSES
Classification: Not a generator, verified

Date form received by agency: 08/12/1999
Facility name: NYCHA - VAN DYKE HOUSES
Classification: Small Quantity Generator

Violation Status: No violations found

NYCHA - VAN DYKE HOUSES (Continued) **1001493637**

FINDS:

Registry ID: 110013793779

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID:	NYR000075283
Country:	USA
Mailing Name:	NYCHA
Mailing Contact:	FRANK OCELLO
Mailing Address:	250 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10007
Mailing Zip4:	2516
Mailing Country:	USA
Mailing Phone:	212-306-3229

Document ID:	NYG3193398
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2001
Trans1 Recv Date:	12/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/07/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075283
Trans1 EPA ID:	NYD077444263

NYCHA - VAN DYKE HOUSES (Continued) **1001493637**

Trans2 EPA ID:	Not reported
TSDF ID:	PA1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	01

Document ID:	NYG3163203
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2001
Trans1 Recv Date:	10/31/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075283
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	NYPD1011
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00135
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	027
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	01

Document ID:	NYG3028347
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2001
Trans1 Recv Date:	08/22/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075283
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

NYCHA - VAN DYKE HOUSES (Continued) **1001493637**

Year:	01
Document ID:	NYG2933982
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	06/01/2001
Trans1 Recv Date:	06/01/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000075283
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00105
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	021
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	01

BB276 **UNK** **NY Spills** **S106467999**
WSW **393 DUMONT AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.157 mi.
830 ft. **Site 5 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

NY Spills:

Site ID:	320462
Facility Addr2:	Not reported
Facility ID:	9505108
Spill Number:	9505108
Facility Type:	ER
SWIS:	2401
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	7/26/1995
Reported to Dept:	7/26/1995
CID:	Not reported
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/3/1997
Remediation Phase:	0
Date Entered In Computer:	12/27/1948

UNK (Continued) **S106467999**

Spill Record Last Update: 10/3/1997
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 2
DER Facility ID: 258193
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "XX" SPILL CLOSED DUE TO INSUFFICIENT DATA.
Remarks: Not reported

Material:
Site ID: 320462
Operable Unit ID: 1019870
Operable Unit: 01
Material ID: 366636
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 320461
Facility Addr2: Not reported
Facility ID: 0103847
Spill Number: 0103847
Facility Type: ER
SWIS: 2401
Investigator: jkkann
Referred To: QRTLY RPT RCVD 1/6/11
Spill Date: 7/11/2001
Reported to Dept: 7/11/2001
CID: 382
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other

UNK (Continued) **S106467999**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	7/11/2001
Spill Record Last Update:	3/7/2011
Spiller Name:	CALLER
Spiller Company:	NYC HOUSING
Spiller Address:	123 WILLIAMS ST
Spiller City,St,Zip:	NYC, NY 10038-
Spiller Company:	001
Contact Name:	MARIO MANDELONE
Contact Phone:	(718) 649-7017
DEC Region:	2
DER Facility ID:	258193
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KOLLEENY" 01/26/04 Transferred from Rommel to Austin 02/17/04: Reassigned from AUSTIN to KRIMGOLD. 05/26/04. Reassigned from Krimgold to Kolleeny. 11/08/05: Reassigned from J.Kolleeny to S.Kraszewski. 03/15/06: This spill reassigned to K.Tang. - SK 9/22/06: Spill transferred from Tang to Kann. -JK 3/7/11: J.Kann - Qrtly report recvd 1/6/11.
Remarks:	CONTAMINATED SOIL FOUND DURING THE REMOVAL ON REPLACEMENT OF A 25,000 GAL TANK AT LOCATION.

Material:

Site ID:	320461
Operable Unit ID:	842368
Operable Unit:	01
Material ID:	535923
Material Code:	0003
Material Name:	#6 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	320461
Operable Unit ID:	842368
Operable Unit:	01
Material ID:	535922
Material Code:	0002
Material Name:	#4 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

UNK (Continued) **S106467999**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	2
Spill Number:	9505108
Investigator:	XX
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	07/26/1995 00:00
Reported to Dept Date/Time:	07/26/95
SWIS:	61
Spiller Name:	UNK
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	Air
Water Affected:	Not reported
Spill Source:	12
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	/ /
Cleanup Meets Std:	False
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/03/97
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	12/27/48
Date Spill Entered In Computer Data File:	Not reported
Update Date:	10/03/97

UNK (Continued) **S106467999**

Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Raw Sewage
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Pounds
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN MATERIAL
Class Type: UNKNOWN MATERIAL
Times Material Entry In File: 9140
CAS Number: Not reported
Last Date: 19941109
DEC Remarks: SPILL CLOSED DUE TO INSUFFICIENT DATA.
Remark: Not reported

BB277 **VAN DYKE HOUSES** **LTANKS** **S101658423**
WSW **393 DUMONT AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.157 mi.
830 ft. **Site 6 of 7 in cluster BB**

Relative:
Lower

Actual:
35 ft.

LTANKS:
Site ID: 216684
Spill No: 9507220
Spill Date: 9/13/1995
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 12/19/2005
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 9/13/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/20/1995
Spill Record Last Update: 12/19/2005
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported

VAN DYKE HOUSES (Continued) **S101658423**

Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	258193
Remarks:	TANK #2 - UNABLE TO HOLD NEGATIVE PRESSURE

Material:

Site ID:	216684
Operable Unit ID:	1018057
Operable Unit:	01
Material ID:	361649
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	216684
Spill Tank Test:	1544143
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	216683
Spill No:	9505107
Spill Date:	7/26/1995
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/20/1995
Facility Addr2:	Not reported
Cleanup Ceased:	9/20/1995
Cleanup Meets Standard:	True
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	7/26/1995
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

VAN DYKE HOUSES (Continued) **S101658423**

Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/26/1995
Spill Record Last Update:	12/19/2005
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	258193
Remarks:	TANK #2 - WOULD NOT HOLD PRESSURE. SEE EPILL # 9507220 (SUBSEQUENT TANK TEST FAILURE)

Material:

Site ID:	216683
Operable Unit ID:	1016022
Operable Unit:	01
Material ID:	366635
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	216683
Spill Tank Test:	1544028
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	320464
Spill No:	9912687
Spill Date:	2/7/2000
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/8/2005
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported

VAN DYKE HOUSES (Continued) **S101658423**

Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	2/7/2000
CID:	207
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/7/2000
Spill Record Last Update:	11/8/2005
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	ED MALONE
Spiller Phone:	(212) 306-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	258193
Remarks:	NO PRODUCT SPILLED

Material:

Site ID:	Not reported
Operable Unit ID:	Not reported
Operable Unit:	Not reported
Material ID:	Not reported
Material Code:	Not reported
Material Name:	Not reported
Case No.:	Not reported
Material FA:	Not reported
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	320464
Spill Tank Test:	1548032
Tank Number:	2
Tank Size:	25000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

HIST LTANKS:

Region of Spill:	2

VAN DYKE HOUSES (Continued) **S101658423**

Spill Number:	9505107
Spill Date:	07/26/1995
Spill Time:	13:40
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	09/20/95
Cleanup Ceased:	09/20/95
Cleanup Meets Standard:	True
Investigator:	HEALY
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	07/26/95
Reported to Department Time:	15:29
SWIS:	61
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(212) 306-3142
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	2-474282
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	07/26/95
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	09/20/95
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	002
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

VAN DYKE HOUSES (Continued) **S101658423**

Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: TANK 2 - WOULD NOT HOLD PRESSURE. SEE EPILL 9507220 SUBSEQUENT TANK TEST FAILURE)

Region of Spill: 2
Spill Number: 9912687
Spill Date: 02/07/2000
Spill Time: 13:30
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 02/07/00
Reported to Department Time: 14:59
SWIS: 61
Spiller Contact: ED MALONE
Spiller Phone: (212) 306-3233
Spiller Extention: Not reported
Spiller Name: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: 4-74282
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False

VAN DYKE HOUSES (Continued) **S101658423**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 02/07/00
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 02/08/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 2
Tank Size: 25000
Test Method: Horner EZ Check
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Not reported
Quantity Spilled: Not reported
Unkonwn Quantity Spilled: Not reported
Units: Not reported
Quantity Recovered: Not reported
Unkonwn Quantity Recovered: Not reported
Material: Not reported
Class Type: Not reported
Times Material Entry In File: Not reported
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Spill Cause: NO PRODUCT SPILLED

Region of Spill: 2
Spill Number: 9507220
Spill Date: 09/13/1995
Spill Time: 10:45
Spill Cause: Tank Test Failure
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: SACCACIO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 09/13/95
Reported to Department Time: 11:25
SWIS: 61
Spiller Contact: Not reported
Spiller Phone: Not reported

VAN DYKE HOUSES (Continued) **S101658423**

Spiller Extention: Not reported
Spiller Name: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (212) 306-3229
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: 2-474282
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 09/20/95
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 002
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: -1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: TANK 2 - UNABLE TO HOLD NEGATIVE PRESSURE

BB278 **VAN DYKE** **LTANKS** **U001840696**
WSW **393 DUMONT AVE** **HIST LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY** **HIST UST**
0.157 mi. **AST**
830 ft. **Site 7 of 7 in cluster BB** **HIST AST**

Relative: Lower

Actual: 35 ft.

LTANKS:
Site ID: 320463
Spill No: 9714309
Spill Date: 3/25/1998
Spill Cause: Tank Test Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release that creates potential for fire or hazard. DEC Response.

VAN DYKE (Continued) **U001840696**

	Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/8/2005
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	3/25/1998
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/25/1998
Spill Record Last Update:	11/8/2005
Spiller Name:	SEBATIAN LOREFICE
Spiller Company:	NYC HOUSING AUTUHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	MANHATTAN, NY
Spiller County:	001
Spiller Contact:	FRANK ROSELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	258193
Remarks:	ISOLATE AND RETEST

Material:

Site ID:	320463
Operable Unit ID:	1057178
Operable Unit:	01
Material ID:	325276
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	320463
Spill Tank Test:	1545704
Tank Number:	1
Tank Size:	25000
Test Method:	03
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Horner EZ Check I or II

VAN DYKE (Continued) **U001840696**

HIST LTANKS:

Region of Spill:	2
Spill Number:	9714309
Spill Date:	03/25/1998
Spill Time:	12:30
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gallons
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	SACCACIO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	03/25/98
Reported to Department Time:	14:22
SWIS:	61
Spiller Contact:	FRANK ROSELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
Spiller Name:	NYC HOUSING AUTUHORITY
Spiller Address:	250 BROADWAY
Spiller City,St,Zip:	MANHATTAN, NY
Spiller Cleanup Date:	/ /
Facility Contact:	SEBATIAN LOREFICE
Facility Phone:	(212) 306-3229
Facility Extention:	Not reported
Spill Notifier:	Affected Persons
PBS Number:	4-74282
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	03/25/98
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	03/26/98
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	1
Tank Size:	25000
Test Method:	Horner EZ Check
Leak Rate Failed Tank:	0.00

VAN DYKE (Continued) **U001840696**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: ISOLATE AND RETEST

HIST UST:
PBS Number: 2-474282
SPDES Number: Not reported
Emergency Contact: EMERGENCY SERVICE DEPARTMENT
Emergency Telephone: (212) 289-3940
Operator: MR. LUIS PONCE
Operator Telephone: (718) 707-5725
Owner Name: NYC HOUSING AUTHORITY
Owner Address: 23-02 49TH AVENUE
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Telephone: (718) 707-5725
Owner Type: Local Government
Owner Subtype: 51
Mailing Name: NYC HOUSING AUTHORITY
Mailing Address: 23-02 49TH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Contact: MR. LUIS PONCE
Mailing Telephone: (718) 707-5725
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 370 BLAKE AVENUE (MGT. OFFICE)
SWIS ID: 6101
Old PBS Number: Not reported
Facility Type: APARTMENT BUILDING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 10/18/2001
Expiration Date: 03/28/2004
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 20000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing

VAN DYKE (Continued) **U001840696**

Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	19551201
Capacity (gals):	50000
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Wrapped (Piping)
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	11/01/1992
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	19551201
Capacity (gals):	25000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	10/01/2001
Test Method:	Not reported

VAN DYKE (Continued) **U001840696**

Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 2
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: 19851001
Capacity (gals): 25000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/2001
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-474282
Program Type: PBS
UTM X: 592587.46424
UTM Y: 4502066.7541199997
Expiration Date: 2014/03/28

Affiliation Records:
Site Id: 20897
Affiliation Type: Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: \\
Contact Name: Not reported
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported

VAN DYKE (Continued) **U001840696**

Modified By:	NRLOMBAR
Date Last Modified:	4/19/2011
Site Id:	20897
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/19/2010
Site Id:	20897
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPARTMENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008
Site Id:	20897
Affiliation Type:	On-Site Operator
Company Name:	VAN DYKE HOUSES
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/31/2008

VAN DYKE (Continued) **U001840696**

Equipment Records:

E04 - Piping Secondary Containment - Double-Walled (Underground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E04 - Piping Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
H00 - Tank Leak Detection - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
E10 - Piping Secondary Containment - Impervious Underlayment
I02 - Overfill - High Level Alarm
D11 - Pipe Type - Flexible Piping
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
F05 - Pipe External Protection - Jacketed
L08 - Piping Leak Detection - Tank Top Sump
I04 - Overfill - Product Level Gauge (A/G)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
J02 - Dispenser - Suction
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
F01 - Pipe External Protection - Painted/Asphalt Coating

VAN DYKE (Continued) **U001840696**

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction
L09 - Piping Leak Detection - Exempt Suction Piping
L08 - Piping Leak Detection - Tank Top Sump
I00 - Overfill - None
D11 - Pipe Type - Flexible Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F05 - Pipe External Protection - Jacketed
K00 - Spill Prevention - None
J02 - Dispenser - Suction
I03 - Overfill - Automatic Shut-Off
B09 - Tank External Protection - Urethane
G04 - Tank Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F06 - Pipe External Protection - Wrapped
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Info:

Tank Number:	T1
Tank Id:	60633
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	2/1/1999
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	3/1/2002
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

Tank Number:	W/O1
Tank Id:	208308
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	201
Pipe Model:	Not reported
Install Date:	10/1/1995
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

VAN DYKE (Continued) **U001840696**

Modified By: NRLOMBAR
Last Modified: 12/31/2008

HIST AST:
PBS Number: 2-474282
SWIS Code: 6101
Operator: MR. LUIS PONCE
Facility Phone: (718) 707-5725
Facility Addr2: 370 BLAKE AVENUE (MGT. OFFICE)
Facility Type: APARTMENT BUILDING
Emergency: EMERGENCY SERVICE DEPARTMENT
Emergency Tel: (212) 289-3940
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: NYC HOUSING AUTHORITY
Owner Address: 23-02 49TH AVENUE
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Federal ID: Not reported
Owner Tel: (718) 707-5725
Owner Type: Local Government
Owner Subtype: 51
Mailing Contact: MR. LUIS PONCE
Mailing Name: NYC HOUSING AUTHORITY
Mailing Address: 23-02 49TH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: LONG ISLAND CITY, NY 11101
Mailing Telephone: (718) 707-5725
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 10/18/2001
Expiration: 03/28/2004
Renew Flag: False
Renew Date: Not reported
Total Capacity: 20000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: T1
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19990201
Capacity (Gal): 20000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

VAN DYKE (Continued) **U001840696**

Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Epoxy Liner
Pipe External:	Not reported
Tank Containment:	Vault (w/access)
Leak Detection:	Not reported
Overfill Protection:	34
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

BA279 **EIGIS EIGIS MGMT CO INC** **AST** **U003384889**
ESE **508 WILLIAMS AVE** **HIST AST** **N/A**
1/8-1/4 **BRKLYN, NY 11207**
0.163 mi.
863 ft. **Site 2 of 3 in cluster BA**

Relative:
Lower

Actual:
30 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-099163
Program Type:	PBS
UTM X:	593193.24291000003
UTM Y:	4501911.97688
Expiration Date:	1992/05/07

Affiliation Records:

Site Id:	2935
Affiliation Type:	Mail Contact
Company Name:	CITY OF NEW YORK HPD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	75 MAIDEN LANE HPD
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 806-8552
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/16/2004

Site Id:	2935
Affiliation Type:	On-Site Operator
Company Name:	EIGIS EIGIS MGMT CO INC

EIGIS EIGIS MGMT CO INC (Continued) **U003384889**

Contact Type:	Not reported
Contact Name:	EIGIS EIGIS MGNT CO INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 385-8069
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	2935
Affiliation Type:	Owner
Company Name:	CITY OF NEW YORK HPD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	75 MAIDEN LANE HPD
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 806-8552
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	12/16/2004

Site Id:	2935
Affiliation Type:	Emergency Contact
Company Name:	CITY OF NEW YORK HPD
Contact Type:	Not reported
Contact Name:	MUETON BROWN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 385-8069
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

EIGIS EIGIS MGMT CO INC (Continued) **U003384889**

B00 - Tank External Protection - None
J02 - Dispenser - Suction
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Info:

Tank Number:	001
Tank Id:	4693
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-099163
SWIS Code:	6101
Operator:	EIGIS EIGIS MGNT CO INC
Facility Phone:	(718) 385-8069
Facility Addr2:	508 WILLIAMS AVE
Facility Type:	Not reported
Emergency:	MUETON BROWN
Emergency Tel:	(718) 385-8069
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CITY OF NEW YORK HPD
Owner Address:	75 MAIDEN LANE HPD
Owner City,St,Zip:	NEW YORK, NY 10038
Federal ID:	Not reported
Owner Tel:	(212) 806-8552
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	CITY OF NEW YORK HPD
Mailing Address:	75 MAIDEN LANE HPD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10038
Mailing Telephone:	(212) 806-8552
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	05/07/1987

EIGIS EIGIS MGMT CO INC (Continued) **U003384889**

Expiration:	05/07/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	4000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	9
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AZ280 **GRAFTON REALTY CORP.** **AST** **A100300594**
WNW **1660 EAST NEW YORK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.167 mi.
882 ft. **Site 2 of 5 in cluster AZ**

Relative:
Higher

Actual:
61 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Facility Id:	2-082570
Program Type:	PBS
UTM X:	592389.14277000003
UTM Y:	4503079.6865800004
Expiration Date:	N/A

GRAFTON REALTY CORP. (Continued) **A100300594**

Affiliation Records:

Site Id:	1796
Affiliation Type:	Owner
Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1478 PITKIN AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	1796
Affiliation Type:	On-Site Operator
Company Name:	GRAFTON REALTY CORP.
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	1796
Affiliation Type:	Mail Contact
Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1478 PITKIN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	1796
Affiliation Type:	Emergency Contact

GRAFTON REALTY CORP. (Continued) **A100300594**

Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	N/AMJR HOLDING CORPORATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Info:

Tank Number:	001
Tank Id:	3008
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

AZ281 **MJR HOLDING CORPORATION** **HIST AST** **U003384101**
WNW **1660 EAST NEW YORK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.167 mi.
882 ft. **Site 3 of 5 in cluster AZ**

Relative:
Higher

Actual:
61 ft.

HIST AST:

PBS Number:	2-082570
SWIS Code:	6101
Operator:	MJR HOLDING CORPORATION
Facility Phone:	(718) 342-2352
Facility Addr2:	1660 EAST NEW YORK AVENUE

MJR HOLDING CORPORATION (Continued) **U003384101**

Facility Type:	OTHER
Emergency:	MJR HOLDING CORPORATION
Emergency Tel:	(718) 342-2352
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	MJR HOLDING CORPORATION
Owner Address:	1660 EAST NEW YORK AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11212
Federal ID:	Not reported
Owner Tel:	(718) 342-2352
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	MJR HOLDING CORPORATION
Mailing Address:	1660 EAST NEW YORK AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11212
Mailing Telephone:	(718) 342-2352
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	02/19/1992
Expiration:	03/24/1997
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4

MJR HOLDING CORPORATION (Continued) **U003384101**

Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AR282 **BELMONT STATION** **Manufactured Gas Plants** **1008407879**
East **BELMONT, WILLIAMS, ALABAMA AND SUTTER AVES.** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.169 mi.
894 ft. **Site 17 of 17 in cluster AR**

Relative:
Lower

Actual:
37 ft.

Manufactured Gas Plants:
No additional information available

---

283 **MANHOLE #04264** **NY Spills** **S107787827**
North **FULTON STREET & VAN SINDEREN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.172 mi.
908 ft.

Relative:
Higher

Actual:
78 ft.

NY Spills:

Site ID:	363385
Facility Addr2:	Not reported
Facility ID:	0601203
Spill Number:	0601203
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	5/2/2006
Reported to Dept:	5/2/2006
CID:	444
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/14/2006
Remediation Phase:	0
Date Entered In Computer:	5/2/2006
Spill Record Last Update:	7/17/2006
Spiller Name:	ERT DESK

MANHOLE #04264 (Continued) **S107787827**

Spiller Company:	CON EDISON MH #04264
Spiller Address:	FULTON STREET/VAN SINDERE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	999
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	313566
DEC Memo:	06/14/06 - See e-docs for Con Ed report detailing cleanup and closure. 164045. 5/2/06 10:25 HRS. V. BAUCCIO #85835 UG REPORTS WHILE ON ROUTINE WORK IN MH04264 (ACCT 14893) FOUND APPROX 1 PT. DIELECTRIC OIL ON 2 GALS OF WATER. NO FIRE/ SMOKE/ INJURIES INVOLVED. NO SEWERS/ WATERWAYS/PVT PROPERTY AFFECTED.NO VISUAL WATER MOVEMENT. PRESENCE OF SUMPS/DRAINS NOT VERIFIED AT THIS TIME. SPILL IS CONTAINED TO THE STRUCTURE & THE SOURCE APPEARS TO COME FROM A LEAKING 3c STRAIGHT JT. MS. BAUCCIO & HER SUPV. REMOVED SOME ARC PROOFING AND SAW THE LEAK. FDR # TO FOLLOW. D-FAULT TAG # 06573 PLACED. ENV. STOP TAG # 48003 PLACED & SAMPLE TAKEN FOR PCB ON CHAIN OF CUSTODY #EE-08285 MARKED E-PRIORITY. CLEANUP PENDING DFAULT REPAIR & TEST RESULTS. CIG TO BE NOTIFIED. J. MASON 5/2/06 11:20 HRS AS PER CCR SHIFT MGR D-FAULT 06573 IS ON DEAD FDR 10225. J. MASON UPDATE 5/2/06 17:05 HRS CHEM LAB RESULTS RETURNED 2PPM LSN 06-04779-001 MATRIX: OIL GRAB LOCATION: S/S FULTON ST 144' E/O VAN SINDEREN AVE, STRUCTURE: MANHOLE 04264. J. MASON
Remarks:	1 pint on 2 gallons of water: no top 5 questions: coned # 164045

Material:

Site ID:	363385
Operable Unit ID:	1121440
Operable Unit:	01
Material ID:	2110937
Material Code:	0541A
Material Name:	DIELECTRIC FLUID
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AX284 **PUBLIC SCHOOL 174 - BROOKLYN** **HIST LTANKS** **1000961272**
East **574 DUMONT AVENUE** **AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **HIST AST**
0.172 mi. **NY Spills**
910 ft. **Site 3 of 5 in cluster AX**

Relative:
Lower

Actual:
31 ft.

HIST LTANKS:

Region of Spill:	2
Spill Number:	9800121
Spill Date:	04/01/1998
Spill Time:	18:00
Spill Cause:	Tank Overfill
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	O'DOWD
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	04/03/98
Reported to Department Time:	10:00
SWIS:	61
Spiller Contact:	ABOVE CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	PS 174K
Spiller Address:	574 DUMONT AVE
Spiller City,St,Zip:	BROOKLYN
Spiller Cleanup Date:	/ /
Facility Contact:	ABOVE CALLER
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	04/03/98
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	04/07/98
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: had an oil sheen on 800 gallons of runoff water, poss from tank overfill, sample taken, believed to be 1 and 10 oil, spill contained and cleaned

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603798
Program Type: PBS
UTM X: 593177.25873999996
UTM Y: 4502180.8088600002
Expiration Date: 2013/12/04

Affiliation Records:
Site Id: 25701
Affiliation Type: Mail Contact
Company Name: NYC DEPT. OF EDUCATION
Contact Type: Not reported
Contact Name: RAYMOND CORREA
Address1: FIELD OPERATIONS - FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5738
Phone Ext: Not reported
Email: RCORREA5@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/31/2009

Site Id: 25701
Affiliation Type: On-Site Operator
Company Name: PUBLICK SCHOOL 174 - BROOKLYN
Contact Type: Not reported
Contact Name: PLANT OPERATIONS
Address1: Not reported
Address2: Not reported
City: Not reported

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	25701
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	6/30/2011

Site Id:	25701
Affiliation Type:	Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	RAYMOND CORREA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5738
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	EJCALIFA
Date Last Modified:	11/16/2009

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction
F04 - Pipe External Protection - Fiberglass
L09 - Piping Leak Detection - Exempt Suction Piping
F05 - Pipe External Protection - Jacketed

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

C01 - Pipe Location - Aboveground

Tank Info:

Tank Number:	1
Tank Id:	55582
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	11/1/1998
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-603798
SWIS Code:	6101
Operator:	PLANT OPERATIONS
Facility Phone:	(718) 391-6000
Facility Addr2:	574 DUMONT AVENUE
Facility Type:	Not reported
Emergency:	SCHOOL SECURITY
Emergency Tel:	(718) 979-3300
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	NYC BOARD OF EDUCATION
Owner Address:	28-11 QUEENS PLAZA NORTH
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Federal ID:	Not reported
Owner Tel:	(718) 391-6832
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Contact:	FRANK CARDELLO.S.CHIEF
Mailing Name:	OFFICE OF BUILDING SERVICES, NYC BD. OF EDUCATION
Mailing Address:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City,St,Zip:	LONG ISLAND CITY, NY 11101
Mailing Telephone:	(718) 391-6832
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	12/21/1998
Expiration:	12/04/2003
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	8000

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 61
Town or City Code: 01
Region: 2

Tank ID: 1
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: 19981101
Capacity (Gal): 8000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 45
Tank Containment: Diking
Leak Detection: 01
Overfill Protection: 02
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

NY Spills:
Site ID: 114826
Facility Addr2: Not reported
Facility ID: 9800121
Spill Number: 9800121
Facility Type: ER
SWIS: 2401
Investigator: kkchanda
Referred To: Not reported
Spill Date: 4/1/1998
Reported to Dept: 4/3/1998
CID: 370
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/6/2008
Remediation Phase:	0
Date Entered In Computer:	4/3/1998
Spill Record Last Update:	11/7/2008
Spiller Name:	ABOVE CALLER
Spiller Company:	PS 174K
Spiller Address:	574 DUMONT AVE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller Company:	001
Contact Name:	ABOVE CALLER
Contact Phone:	Not reported
DEC Region:	2
DER Facility ID:	100124
DEC Memo:	11/15/2005: Lead transferred to Joe White as part of the Spill Initiative Project. 12/08/2005: Joe White spoke with James Merlo, the NYC Schools spill coordinator who will be sending in the closure report for this spill. 1/5/2006: The associated PBS tank is PBS# 2-603798. The tanks is an above ground tank and does not require a new tank test but we need some documentation that the spill from the overfill was addressed. The spill amount was 0 gallons so perhaps a photo of the current situation anda field inspedction would be sufficient. This request will be passed along to James Merlo. ---------- ---------- 02/02/07: Re-assigned to chanda. 04/19/07:Kartik Chanda of DEC reviewed all documents regarding this spill case. On 4/19/07, Chanda sent a letter to James Merlo, Manager, Fuel Division, NYC Department of Education, requiring that the following information be submitted to DEC for review by June 8, 2007: 1. An explanation of the cause of the tank system overfill; 2. Either a description of the work performed to restore the integrity of the tank system (including retesting results), or a description of the work performed to close (decommission) the tank; 3. Information regarding petroleum contamination found at the site and cleanup activities (if any) associated with a release from this tank system; and 4. Any available documentation (i.e., invoices, bills, sampling analysis reports, etc.) pertaining to the work performed at this site associated with this violation. 5/24/07: DEC received a letter from James Merlo, NYC Department of Education on 5/24/07. He indecated that PS174k School facility was a coal fired plant in April of 1998. 5/31/07: Chanda sent a letter and attached with a spill report to James Merlo requiring that the information and documents which mentioned the previous letter(Letter dated 4/19/07) be submitted to DEC for review by July 16, 2007. 7/12/07: Chanda received a letter from James Merlo, NYC Department of Education on 7/12/07. He indecated that his office does not have any further information regarding this spill case. 2/8/08: Chanda called NYCSCA regarding this spill case. NYCSCA Mr. Drew Pardus stated that he will search NYCSCA spill case and call back as soon as possible. 8/7/08: Chanda sent a letter to Ms. Lee Guterman, NYCSCA, requiring that an investigation report be submitted to DEC by 10/7/08 for review. (see eDocs) 10/8/08: Chanda received a letter with several photographs from Ms. Lee guterman, NYCSCA, dated 10/7/2008. The letter stated that NYCSCA has not been able to locate any documentation of the

PUBLIC SCHOOL 174 - BROOKLYN (Continued) **1000961272**

clean-up performed in 1998, and the current custodial staff are not aware of a spill having occured at this location. NYCSCA performed a site inspection on October 2, 2008 and noted that the temporary #2 fuel oil AST is no longer on site. NYCSCA submitted several photographs of the former location of the temporary #2 AST, where the spill reportedly occured. (see eDocs) 10/23/08: A meeting was held on 10/21/08 among DER staff, the NYCSCA representative to discuss the site status and updated information for this site. The meeting's consensus was that a site visit is required with NYCSCA representative. 11/3/08: Chanda visited the spill site with Mr. Drew Pardus and observed that the temporary #2 fuel oil AST is no longer on site. Chanda saw one permenant AST on site. 11/3/08: No significant accumulated product was observed inside the containment. Chanda took several photographs around the #2 fuel oil AST.(see eDocs) 11/5/08: Chanda reviewed the spill related documents and discussed with Mark Tibbe(NYSDEC) regarding the site visit and NYCSCA's letter dated October 7, 2008. Based on the information presented to the Department, DEC closed this spill, dated 11/6/08. 11/7/08: Chanda sent an NFA letter to Ms. Lee Geterman, NYCSCA and copy to Drew Pardus, NYCSCA via regular mail and e-mail.

Remarks: had an oil sheen on 800 gallons of runoff water, poss from tank overfill, sample taken, believed to be 1 and 10% oil, spill contained and cleaned

Material:

Site ID:	114826
Operable Unit ID:	1057525
Operable Unit:	01
Material ID:	325674
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AX285 **PS 174** **ICIS** **1011624152**
East **574 DUMONT AVE BROOKLYN NY 11207-5131** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.172 mi.
910 ft. **Site 4 of 5 in cluster AX**

Relative:
Lower

Actual:
31 ft.

ICIS:

Enforcement Action ID:	02-1994-0052
FRS ID:	110001613497
Program ID:	AIRS/AFS 36047R0124
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	PS 174
Facility Address:	574 DUMONT AVE BROOKLYN NY 11207-5131 BROOKLYN, New York 11207-5131
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1994-0052
FRS ID:	110001613497
Program ID:	GNIS 961430
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	PUBLIC SCHOOL 174
Facility Address:	574 DUMONT AVE BROOKLYN NY 11207-5131 BROOKLYN, New York 11207-5131
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1994-0052
FRS ID:	110001613497
Program ID:	RCRAINFO NY0000382226
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN
Facility Address:	574 DUMONT AVE BROOKLYN NY 11207-5131 BROOKLYN, New York 11207-5131
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1994-0052
FRS ID:	110001613497
Program ID:	FIS 2-6105-00426
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	PS 174
Facility Address:	574 DUMONT AVE BROOKLYN NY 11207-5131 BROOKLYN, New York 11207-5131
Enforcement Action Type:	Civil Judicial Action
Facility County:	Kings
EPA Region #:	3

Enforcement Action ID:	02-1994-0052
FRS ID:	110001613497
Program ID:	NCES 360012002611
Action Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name:	P.S. 174 DUMONT SCHOOL
Facility Address:	574 DUMONT AVE BROOKLYN NY 11207-5131 BROOKLYN, New York 11207-5131
Enforcement Action Type:	Civil Judicial Action

PS 174 (Continued) **1011624152**

Facility County: Kings
EPA Region #: 3

Enforcement Action ID: 02-1994-0052
FRS ID: 110001613497
Program ID: FRS 110001613497
Action Name: NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Facility Name: PS 174 DUMONT
Facility Address: 574 DUMONT AVE BROOKLYN NY 11207-5131
BROOKLYN, New York 11207-5131
Enforcement Action Type: Civil Judicial Action
Facility County: Kings
EPA Region #: 3

Program ID: AIRS/AFS 36047R0124
Facility Name: PS 174 DUMONT
Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

Program ID: FIS 2-6105-00426
Facility Name: PS 174 DUMONT
Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

Program ID: FRS 110001613497
Facility Name: PS 174 DUMONT
Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

Program ID: GNIS 961430
Facility Name: PS 174 DUMONT
Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

Program ID: NCES 360012002611
Facility Name: PS 174 DUMONT
Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

Program ID: RCRAINFO NY0000382226
Facility Name: PS 174 DUMONT

PS 174 (Continued) **1011624152**

Address: 574 DUMONT AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 1795

AX286 **NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN** **RCRA-NonGen** **1004755804**
East **574 DUMONT ST** **FINDS** **NY0000382226**
1/8-1/4 **BROOKLYN, NY 11207** **MANIFEST**
0.172 mi.
910 ft. **Site 5 of 5 in cluster AX**

Relative:
Lower

Actual:
31 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN
Facility address: 574 DUMONT ST
BROOKLYN, NY 11207
EPA ID: NY0000382226
Mailing address: DUMONT ST
BROOKLYN, NY 11207
Contact: ROBERT GUASTA
Contact address: DUMONT ST
BROOKLYN, NY 11207
Contact country: US
Contact telephone: (718) 349-5590
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 28-11 QUEENS PLZ N
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 349-5600
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC BOARD OF EDUCATION
Owner/operator address: 28-11 QUEENS PLZ N
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 349-5600
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No

NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN (Continued) **1004755804**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN
Classification: Not a generator, verified

Date form received by agency: 09/05/1995
Facility name: NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001613497

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

US Geographic Names Information System (GNIS) is the official vehicle for geographic names used by the federal government and the source for applying geographic names to federal maps and other printed and electronic documents.

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department

NYC BD OF ED - PUBLIC SCHOOL 174 BKLYN (Continued) **1004755804**

of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

NY MANIFEST:

EPA ID:	NY0000382226
Country:	USA
Mailing Name:	NYC BOARD OF EDUCATION PS 174 BKLYN
Mailing Contact:	ROBERT GUASTA
Mailing Address:	574 DUMONT STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11207
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	718-349-5590

Document ID:	NJA2182335
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	S50082
Trans2 State ID:	S6993
Generator Ship Date:	950927
Trans1 Recv Date:	950927
Trans2 Recv Date:	951208
TSD Site Recv Date:	951208
Part A Recv Date:	Not reported
Part B Recv Date:	951222
Generator EPA ID:	NY0000382226
Trans1 EPA ID:	NY0000551218
Trans2 EPA ID:	NJD980772768
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00325
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	95

BA287
ESE
1/8-1/4
0.172 mi.
910 ft.

EISIG & EIGIS MGMT CO INC
520 WILLIAMS AVENUE
BROOKLYN, NY 11207

Site 3 of 3 in cluster BA

AST **U003384590**
HIST AST **N/A**

Relative:
Lower

Actual:
29 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-114138
Program Type:	PBS
UTM X:	593199.32438000001
UTM Y:	4501883.3580600005
Expiration Date:	2010/01/11

Affiliation Records:

Site Id:	3713
Affiliation Type:	On-Site Operator
Company Name:	WILLIAMS ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	SAM FRENCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 922-2229
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	1/11/2005

Site Id:	3713
Affiliation Type:	Mail Contact
Company Name:	WILLIAMS ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	GILBERT SANCHEZ
Address1:	C/O NEYUYC
Address2:	539 ALABAMA AVE BSMNT
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 922-2229
Phone Ext:	109
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	1/11/2005

Site Id:	3713
Affiliation Type:	Emergency Contact
Company Name:	WILLIAMS ASSOCIATES LP C/O NEYUYC
Contact Type:	Not reported
Contact Name:	GILBERT SANCHEZ
Address1:	Not reported
Address2:	Not reported

EISIG & EIGIS MGMT CO INC (Continued) **U003384590**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 440-2669
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	1/11/2005

Site Id:	3713
Affiliation Type:	Owner
Company Name:	WILLIAMS ASSOCIATES LP C/O NEYUYC
Contact Type:	PRESIDENT / CEO
Contact Name:	WINCHESTER KEY
Address1:	539 ALABAMA AVE BSMT
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 922-2229
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	1/11/2005

Equipment Records:

L00 - Piping Leak Detection - None
J02 - Dispenser - Suction
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
D02 - Pipe Type - Galvanized Steel
I01 - Overfill - Float Vent Valve
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None

Tank Info:

Tank Number:	001
Tank Id:	4044
Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

EISIG & EIGIS MGMT CO INC (Continued) **U003384590**

Register:	True
Modified By:	KXTANG
Last Modified:	1/11/2005

HIST AST:

PBS Number:	2-114138
SWIS Code:	6101
Operator:	EIGIS & EIGIS MGMT CO INC
Facility Phone:	(718) 385-8069
Facility Addr2:	520 WILLIAMS AVENUE
Facility Type:	Not reported
Emergency:	MILTON BRORON
Emergency Tel:	(718) 385-8069
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CITY OF NEW YORK-HPD
Owner Address:	75 MAIDEN LANE
Owner City,St,Zip:	NEW YORK, NY 10038
Federal ID:	Not reported
Owner Tel:	(212) 806-8552
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	CITY OF NEW YORK-HPD
Mailing Address:	75 MAIDEN LANE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10038
Mailing Telephone:	(212) 806-8552
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	03/24/1987
Expiration:	03/24/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	4000
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2

Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	4000
Product Stored:	NOS 1,2, OR 4 FUEL OIL

EISIG & EIGIS MGMT CO INC (Continued) **U003384590**

Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	Diking
Leak Detection:	9
Overfill Protection:	4
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

AU288 **77-11 GLENMORE AVE/QUEENS** **LTANKS** **S102671484**
WSW **77-11 GLENMORE AVENUE** **HIST LTANKS** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.174 mi.
920 ft. **Site 9 of 9 in cluster AU**

Relative:
Higher

Actual:
50 ft.

LTANKS:

Site ID:	330849
Spill No:	8910343
Spill Date:	1/29/1990
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Spill Closed Dt:	1/30/1990
Facility Addr2:	Not reported
Cleanup Ceased:	1/30/1990
Cleanup Meets Standard:	True
SWIS:	4101
Investigator:	WILSON
Referred To:	Not reported
Reported to Dept:	1/29/1990
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1/31/1990
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

77-11 GLENMORE AVE/QUEENS (Continued) **S102671484**

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 266094
Remarks: 550 GALLON TANK, SPILL NEAR TANK & IN FRONT OF HOUSE, SPEEDY DRY APPLIED, SMALL AMOUNT IN BACKYARD, SPILL TEAM ENROUTE TO CLEAN UP.

Material:
Site ID: 330849
Operable Unit ID: 937357
Operable Unit: 01
Material ID: 443445
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 2
Spill Number: 8910343
Spill Date: 01/29/1990
Spill Time: 09:30
Spill Cause: Tank Overfill
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Class: Not reported
Spill Closed Dt: 01/30/90
Cleanup Ceased: 01/30/90
Cleanup Meets Standard: True
Investigator: WILSON
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported

77-11 GLENMORE AVE/QUEENS (Continued) **S102671484**

Reported to Department Date: 01/29/90
Reported to Department Time: 10:18
SWIS: 63
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (718) 738-2865
Facility Extention: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/31/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 3
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: 550 GALLON TANK, SPILL NEAR TANK IN FRONT OF HOUSE, SPEEDY DRY APPLIED, SMALL AMOUNT IN BACKYARD, SPILL TEAM ENROUTE TO CLEAN UP.

AP289 **METRO STRUCTURAL STEEL MR. RUSSO** **UST** **U001831595**
East **282 LIBERTY AVENUE** **HIST UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11234**
0.175 mi.
923 ft. **Site 4 of 4 in cluster AP**

Relative:
Higher

Actual:
53 ft.

UST:

Facility Id:	2-054895
Region:	STATE
DEC Region:	2
Site Status:	Unregulated
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592996.78457999998
UTM Y:	4503083.7191300001

Affiliation Records:

Site Id:	788
Affiliation Type:	Owner
Company Name:	MR. LUCLANO RUSSO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	282 LIBERTY AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11234-2521
Country Code:	001
Phone:	(718) 241-2501
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	788
Affiliation Type:	Mail Contact
Company Name:	TAKE PRIDE
Contact Type:	Not reported
Contact Name:	HAROLT PITTS
Address1:	76 RUNYON AVENUE
Address2:	Not reported
City:	YONKERS
State:	NY
Zip Code:	10710
Country Code:	001
Phone:	(914) 969-1006
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	788
Affiliation Type:	On-Site Operator
Company Name:	METRO STRUCTURAL STEEL MR. RUSSO
Contact Type:	Not reported
Contact Name:	MR. RUSSO
Address1:	Not reported
Address2:	Not reported

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 241-2501
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	788
Affiliation Type:	Emergency Contact
Company Name:	MR. LUCLANO RUSSO
Contact Type:	Not reported
Contact Name:	HALOID PITTS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 760-3705
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I00 - Overfill - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

I00 - Overfill - None
A00 - Tank Internal Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping

Tank Info:

Site ID:	788
Tank Number:	001
Tank ID:	1971
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	5/1/1972
Capacity Gallons:	2500
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	788
Tank Number:	002
Tank ID:	66151
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Z
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	788
Tank Number:	003
Tank ID:	66152
Tank Status:	Closed - In Place
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	500
Tightness Test Method:	NN

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank Location:	5
Tank Type:	Z
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004
Site ID:	788
Tank Number:	1000UST
Tank ID:	66253
Tank Status:	Closed - Removed
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	1/1/2003
Capacity Gallons:	2500
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	1/1/2003
Tank Location:	5
Tank Type:	Steel/carbon steel
Date Test:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST UST:

PBS Number:	2-054895
SPDES Number:	Not reported
Emergency Contact:	CHRIS FABER NORWOOD ELECTRO
Emergency Telephone:	(718) 345-4300
Operator:	NORWOOD ELECTRO PLATING
Operator Telephone:	(718) 345-4300
Owner Name:	NORWOOD ELECTRO PLATING
Owner Address:	282 LIBERTY AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11207
Owner Telephone:	(718) 345-4300
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	NORWOOD ELECTRO PLATING
Mailing Address:	282 LIBERTY AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11207
Mailing Contact:	Not reported
Mailing Telephone:	(718) 345-4300
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	282 LIBERTY AVENUE
SWIS ID:	6101
Old PBS Number:	Not reported
Facility Type:	MANUFACTURING
Inspected Date:	Not reported
Inspector:	Not reported

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	02/13/1992
Expiration Date:	02/05/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	2500
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City:	01
Region:	2

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	19720501
Capacity (gals):	2500
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	12/27/1987
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

AZ290 **DISCOUNT AUTO REPAIR** **AST** **A100301011**
WNW **1649 EAST NEW YORK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.177 mi.
936 ft. **Site 4 of 5 in cluster AZ**

Relative:
Higher

Actual:
60 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610441
Program Type:	PBS
UTM X:	592362.32077999995

DISCOUNT AUTO REPAIR (Continued) **A100301011**

UTM Y: 4503138.8063200004
Expiration Date: 2012/01/02

Affiliation Records:
Site Id: 375554
Affiliation Type: Mail Contact
Company Name: RICHARD CALABRESE
Contact Type: Not reported
Contact Name: Not reported
Address1: 2220 EAST 71ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11234
Country Code: 001
Phone: (718) 241-9134
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/2/2007

Site Id: 375554
Affiliation Type: Owner
Company Name: RICHARD CALABRESE
Contact Type: OWNER
Contact Name: RICHARD J. CALABRESE
Address1: 2220 E 71ST ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11234
Country Code: 001
Phone: (718) 241-9134
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/2/2007

Site Id: 375554
Affiliation Type: Emergency Contact
Company Name: RICHARD CALABRESE
Contact Type: Not reported
Contact Name: RICHARD CALABRESE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 241-9134
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/2/2007

DISCOUNT AUTO REPAIR (Continued) **A100301011**

Site Id:	375554
Affiliation Type:	On-Site Operator
Company Name:	DISCOUNT AUTO REPAIR
Contact Type:	Not reported
Contact Name:	R. NOVA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 922-7079
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	1/2/2007

Equipment Records:

L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
E00 - Piping Secondary Containment - None
F06 - Pipe External Protection - Wrapped
I04 - Overfill - Product Level Gauge (A/G)

Tank Info:

Tank Number:	L120
Tank Id:	215217
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	201
Pipe Model:	Not reported
Install Date:	8/1/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	1/2/2007

AZ291 **AUTO REPAIR SHOP** **NY Spills** **S108296635**
WNW **1649 EAST NEW YORK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.177 mi.
936 ft. **Site 5 of 5 in cluster AZ**

Relative:
Higher

Actual:
60 ft.

NY Spills:

Site ID:	374640
Facility Addr2:	Not reported
Facility ID:	0610240
Spill Number:	0610240
Facility Type:	ER
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Spill Date:	12/8/2006
Reported to Dept:	12/8/2006
CID:	444
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/5/2007
Remediation Phase:	0
Date Entered In Computer:	12/8/2006
Spill Record Last Update:	1/23/2007
Spiller Name:	LINDA CALABRESE
Spiller Company:	AUTO REPAIR SHOP
Spiller Address:	1649 EAST NEW YORK AVE
Spiller City,St,Zip:	BROOKLYN, NY
Spiller Company:	001
Contact Name:	LINDA CALABRESE
Contact Phone:	(718) 241-9134
DEC Region:	2
DER Facility ID:	324307
DEC Memo:	12/18/06 - Raphael Ketani. Contaminated soil was found on 12/8/06 after the property was sold. The seller, Linda Calabrese (718) 241-9134, was forced to clean up the site. The site is an auto repair shop. There is no PBS case. I received the phase II report on 12/15/06. The report was generated by Vertex Environmental Services, Inc. (781) 952-6000. The report states that the site has been used as an auto repair shop since the 1940s. The 15 borings drilled encountered historical waste just below the concrete floor of the site which consisted of wire, railroad ties, gravel, asphalt, rubber, and brick. The site sits at approximately 65 feet above sea level, according to the Site Locus Map, Figure 1. Groundwater should be at about 10 feet above sea level in this area, according to published reports from the U.S. Geological Survey. However, the site is about 55 feet above the water table. Strong petroleum odors with PID readings of 75 to 487 ppm were encountered in the field at borings B-2, B-5, B-9, B-12, and B-14, with lesser odors at B-13. There were VOCs in the soil samples from B-5 (6) and B-13 (7), but they were

AUTO REPAIR SHOP (Continued) **S108296635**

well below the TAGM RSCO standards. Soil samples from borings B-3, B-9, B-13, and B-14 had many PAH hits ranging from several thousand PPB to a high of 41000 ppb. Most of these hits are the benzo series of PAHs, with anthracene, chrysene, flouranthene, indeno(1,2,3-c,d)pyrene, phenanthrene, and pyrene. The great majority of the PAH hits exceeded the TAGM standards. My analysis of the phase II investigation report is that the analytical environmental impact of car repair work that has taken place at the site is minimal and does not require remediation. The rubber, wire, railroad ties, brick, and asphalt are historical fill that is similar to historical fill that has been buried over the past century in many parts of NYC. During the 1940s, the former owners may have buried junked car parts and debris on site. The site may not have always been paved as it is now. They probably spilled some oil and gas on the ground at that time. Hence the odors from some of the soil samples. However, the water table is 55 feet below the site. Soil samples from sites nearby have indicated that this auto repair shop probably sits atop a thick layer of boulder glacial till. The till consists principally of a mixture of sand, silt, and clay, with some cobbles and boulders. This would explain the drillers hitting refusal at depths of from 3.5 feet to 8.5 feet. The thick glacial till also has good a absorbtive capacity for oil and other contaminants, and so the groundwater is probably not affected by the spillage at this site. Lastly, the high PAH hits at four of the boring sites are probably from buried incinerator ash or coal combustion ash, as most of the analytes are of the benzo series with chrysene and pyrene - all are combustion products. The boring logs B-9 to B-14 even describe blackish soils, which is suggestive of the presence of ash. In summation, the phase II report was found to be adequate for describing the investigation and for serving as a report of the site conditions. The only problem is that the waste oil tank is unregistered. I called up Ms. Calabrese (718) 241-9134 and told her she had to get the tank registered. She asked me to send her the form. I sent the form out today. 1/5/07 - Raphael Ketani. Ms. Calabrese called to ask whether the waste oil tank registration had gone through. I looked it up in the PBS database and found registration #2-610441 for a 275 gal. waste oil tank at the site. I told her the tank registration was in-place. Based upon the phase II investigation report generated by Vertex Environmental Services and the PBS registration, I am closing the spill case. 1/23/07 - Raphael Ketani. I received a call from Diego Pinzon of HSBC Bank (718) 297-4169. He said that the bank was holding money in escrow for Ms. Calabrese and wont release it unless they receive a letter from the Department stating that the site has been cleaned up. I told Mr. Pinzon that I will send an NFA letter. He said that his address was HSBC Bank, 147-02 Hillside Avenue, Jamaica, 11435. Linda Calabrese's address is 2220 E. 71 Street, Brooklyn, 11234. I sent the NFA letter.

Remarks: ON NOVEMBER 7TH CALLER SOLD AUTO SHOP, BUT A TESTING COMPANY DOING SOIL TESTING FOUND CONTAMINATED SOUIL AND CALLER HAS TO HAVE IT TAKEN CARE OF:

Material:

Site ID:	374640
Operable Unit ID:	1132305
Operable Unit:	01
Material ID:	2122041
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM

AUTO REPAIR SHOP (Continued) **S108296635**

Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

AY292 **CHEMICAL BANK** **AST U003396291**
WSW **1797 PITKIN AVENUE** **HIST AST N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.180 mi.
952 ft. **Site 2 of 2 in cluster AY**

Relative:
Higher

Actual:
47 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-601739
Program Type: PBS
UTM X: 592420.27425999998
UTM Y: 4502669.1167099997
Expiration Date: 2008/01/22

Affiliation Records:
Site Id: 23701
Affiliation Type: On-Site Operator
Company Name: JP MORGAN CHASE
Contact Type: Not reported
Contact Name: JACK FUCICH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 242-2828
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23701
Affiliation Type: Emergency Contact

CHEMICAL BANK (Continued) **U003396291**

Company Name:	JP MORGAN CHASE
Contact Type:	Not reported
Contact Name:	JACK FUCICH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 242-2828
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23701
Affiliation Type:	Owner
Company Name:	JP MORGAN CHASE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 METROTECH CENTER
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11254
Country Code:	001
Phone:	(718) 242-8000
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	23701
Affiliation Type:	Mail Contact
Company Name:	CNS MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	CHARLES POWERS
Address1:	245 GREAT NECK ROAD
Address2:	SUITE 216
City:	GREAT NECK
State:	NY
Zip Code:	11021
Country Code:	001
Phone:	(516) 773-0052
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C03 - Pipe Location - Aboveground/Underground Combination
F00 - Pipe External Protection - None

CHEMICAL BANK (Continued) **U003396291**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Info:

Tank Number:	001
Tank Id:	47646
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

HIST AST:

PBS Number:	2-601739
SWIS Code:	6101
Operator:	CHEMICAL BANK
Facility Phone:	(212) 622-0663
Facility Addr2:	1797 PITKIN AVENUE
Facility Type:	OTHER
Emergency:	MR. NICK SAVILLA
Emergency Tel:	(212) 622-8955
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	CHEMICAL BANK
Owner Address:	P.O. BOX 2735
Owner City,St,Zip:	NEW YORK, NY 10163
Federal ID:	Not reported
Owner Tel:	(212) 622-8955
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	MR. NICK SAVILLA BRANCH F
Mailing Name:	C/O CHEMICAL BANK
Mailing Address:	RETAIL FACILITIES MANAGEMENT
Mailing Address 2:	GRAND CENTRAL STATION P.O. BOX 2735
Mailing City,St,Zip:	NEW YORK, NY 10163
Mailing Telephone:	(212) 622-8955
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag:	False
Certification Date:	02/07/1994
Expiration:	02/04/1999

CHEMICAL BANK (Continued) **U003396291**

Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	2000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	NEW YORK CITY
County Code:	61
Town or City Code:	01
Region:	2
Tank ID:	001
Tank Location:	ABOVEGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (Gal):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	1
Tank External:	09
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	Not reported
Pipe External:	00
Tank Containment:	Diking
Leak Detection:	05
Overfill Protection:	06
Dispenser Method:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
SPDES Number:	Not reported
Lat/Long:	Not reported

AT293 **MERIT INDUSTRIES** **AST** **A100295023**
NW **1430 HERKIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.181 mi.
957 ft. **Site 4 of 4 in cluster AT**

Relative:
Higher

Actual:
78 ft.

AST:

Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608733
Program Type:	PBS
UTM X:	592434.27321999997
UTM Y:	4503501.4100599997
Expiration Date:	2008/04/01

Affiliation Records:

MERIT INDUSTRIES (Continued) **A100295023**

Site Id:	30585
Affiliation Type:	Owner
Company Name:	VAN DE WALD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	192 LEXINGTON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 213-0600
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	30585
Affiliation Type:	On-Site Operator
Company Name:	MERIT INDUSTRIES
Contact Type:	Not reported
Contact Name:	BRAD SOBEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 922-6090
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	30585
Affiliation Type:	Emergency Contact
Company Name:	VAN DE WALD
Contact Type:	Not reported
Contact Name:	PETER MERTUCCI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 213-0600
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	30585
Affiliation Type:	Mail Contact
Company Name:	MERIT INDUSTIES

MERIT INDUSTRIES (Continued) **A100295023**

Contact Type:	Not reported
Contact Name:	BRAD SOBEL
Address1:	1430 HERKIMER STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 922-6090
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground

Tank Info:

Tank Number:	001
Tank Id:	65579
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	3/4/2004

AO294 **NYCHA - VAN DYKE HOUSES** **FINDS** **1006246547**
WSW **370 BLAKE AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.181 mi.
958 ft. **Site 4 of 4 in cluster AO**

Relative:
Higher

Actual:
39 ft.

FINDS:

Registry ID: 110001589889

Environmental Interest/Information System
The NEI (National Emissions Inventory) database contains information

NYCHA - VAN DYKE HOUSES (Continued) **1006246547**

on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

BC295 **MANHOLE #66366** **NY Spills** **S104282725**
ESE **529 WILLIAMS AVE** **NY Hist Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.183 mi.
965 ft. **Site 1 of 3 in cluster BC**

Relative:
Lower

Actual:
29 ft.

NY Spills:

Site ID:	100959
Facility Addr2:	Not reported
Facility ID:	9908147
Spill Number:	9908147
Facility Type:	ER
SWIS:	2401
Investigator:	JHOCONNE
Referred To:	Not reported
Spill Date:	10/5/1999
Reported to Dept:	10/5/1999
CID:	252
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/12/2004
Remediation Phase:	0
Date Entered In Computer:	10/5/1999
Spill Record Last Update:	11/12/2004
Spiller Name:	JOE DEVOTI
Spiller Company:	MANHOLE #66366
Spiller Address:	529 WILLIAMS AVE
Spiller City,St,Zip:	BROOKLYN, ZZ
Spiller Company:	001
Contact Name:	JOE DEVOTI
Contact Phone:	(212) 580-6763
DEC Region:	2
DER Facility ID:	89520
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" e2mis no. 128244: 10/5/99 10:15HRS-S. SAGONAS-04781-OS-I&A-WHILE AT LOCATION TO PULL IN NEW SERVICE-FOUND APPROX 1/2 PINT DIELECTRIC FLUID COMING FROM T CONNECTION AND JOINTS ON JOINT REGULATOR IN MH 66366-F/O 529 WILLIAMS AVENUE-APPEARS CONTAINED AT THIS TIME-NO WATER IN STRUCTURE-NO OTHER OIL FILLED EQUIPMENT EXCEPT REGULATOR-NO SUMP-NO SEWER CONNECTIONS OR ANY SEWER OR WATERWAYS AFFECTED-NO OUTSIDE IMPACT-MR. SAGONAS UNABLE TO TAKE SAMPLE-U.G. SUPERVISOR DISPATCHED TO LOCATION TO ASSIST IN TAKING SAMPLE AND TO PLACE ENV TAG-WILL TAKE LIQUID SAMPLE FROM SOURCE, WITH A 4-6 HOUR PRIORITY AND WILL CALL IN "D" FAULT TO FEEDER CONTROL. CLEANUP PENDING LAB RESULTS AND WHEN "D" FAULT CONDITION IS

MANHOLE #66366 (Continued) **S104282725**

CORRECTED. UPDATE: 10/5/99 12:57HRS. M. PANTELEO-OS-UG-FOUND THAT LEAK IS COMING FROM 3C STRAIGHT JOINT AT THE WIPE NOT FROM JOINT REGULATOR-CONTACTED FEEDER CONTROL TO REPORT "D" FAULT AND TOOK A LIQUID SAMPLE WITH A 4-6 HOUR PRIORITY-PLACED ENV TAG 12504. UPDATE 10/05/99 -- SAMPLE RESULTS RECEIVED LAB SEQ#99-10451 PCB=19PPM. UPDATE********** 10-11-99 20:50HRS MR. DAVIS REPORTS, D FAULT CORRECTED AND CLEANUP COMPLETED USING BIO-GEN 760. INCIDENT IS CLOSED.
Not reported
Remarks: EQUIPTMENT FAILURE FROM A LEAKING JOINT REGULATOR-CLEAN UP PENDING LAB RESULTS-CON ED #128244

Material:
Site ID: 100959
Operable Unit ID: 1082437
Operable Unit: 01
Material ID: 300827
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 2
Spill Number: 9908147
Investigator: ENGELHARDT
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 10/05/1999 10:15
Reported to Dept Date/Time: 10/05/99 11:09
SWIS: 61
Spiller Name: MANHOLE #66366
Spiller Contact: JOE DEVOTI
Spiller Phone: (212) 580-6763
Spiller Contact: JOE DEVOTI
Spiller Phone: (212) 580-6763

MANHOLE #66366 (Continued) **S104282725**

Spiller Address: 529 WILLIAMS AVE
Spiller City,St,Zip: BROOKLYN
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/05/99
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/10/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: DIELECTRIC FLUID
Class Type: DIELECTRIC FLUID
Times Material Entry In File: 41
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: EQUIPTMENT FAILURE FROM A LEAKING JOINT REGULATOR-CLEAN UP PENDING LAB RESULTS-CON ED 128244

BC296
ESE
1/8-1/4
0.188 mi.
991 ft.

CONSOLIDATED EDISON
WILLIAMS AVE & RIVERDALE AVE
BROOKLYN, NY

Site 2 of 3 in cluster BC

MANIFEST **S108980623**
N/A

Relative:
Lower

Actual:
29 ft.

NY MANIFEST:

EPA ID:	NYP004155131
Country:	USA
Mailing Name:	consolidated edison
Mailing Contact:	franklyn murray
Mailing Address:	4 irving pl rm 828
Mailing Address 2:	Not reported
Mailing City:	new york
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-460-2808

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/2007
Trans1 Recv Date:	11/22/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/26/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004155131
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	001437247FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

BC297 **MANHOLE 66363** **NY Spills** **S107657589**
ESE **WILLIAMS AVE/RIVERDALE AV** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.188 mi.
991 ft. **Site 3 of 3 in cluster BC**

Relative:
Lower

Actual:
29 ft.

NY Spills:

Site ID:	360842
Facility Addr2:	Not reported
Facility ID:	0514185
Spill Number:	0514185
Facility Type:	ER
SWIS:	2401
Investigator:	GDBREEN
Referred To:	Not reported
Spill Date:	3/8/2006
Reported to Dept:	3/10/2006
CID:	73
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/17/2006
Remediation Phase:	0
Date Entered In Computer:	3/11/2006
Spill Record Last Update:	6/12/2006
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	ERT DESK'
Contact Phone:	(212) 580-8383
DEC Region:	2
DER Facility ID:	311033
DEC Memo:	04/17/06 - See e-docs for Con Ed report detailing cleanup and closure. 04/17/06 - See e-docs for Con Ed report detailing cleanup and closure. 163247. 3-8-06 12:30HRS R. BOCIGNONE 07942 (UG) REPORTS, FOUND TWO GALLONS OF UNKNOWN OIL ON FOUR GALLONS OF WATER. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. OIL WAS DISCOVERED WHILE INSPECTION OF JOINT REGULATORS. NO OTHER OIL FILLED EQUIPMENT IN STRUCTURE APPEARS TO BE LEAKING. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED AND NO INJURIES WERE RELATED TO SPILL WITH NO WEATHER CONDITIONS CONTRIBUTING TO THE HAZARD OF THE SPILL. ENV STOP TAG# 52459 WAS PLACED AND ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORTY AND CLEANUP PENDING LAB SAMPLE. CHAIN OF CUSTODY# DD-12236 AND ACCT# C3255. S. PACE 49874. LAB RESULT RECEIVED 3/8/06 - 2350. 06-02542. 4 PPM. TJ - 50495 UPDATE: 3/10/06 - 0005. W. LONG - ENV. OPS., REPORTS A VEHICLE IS BLOCKING THE STRUCTURE. TJ - 50495 UPDATE 3/10/2006 17:30 HRS ENV OPS ADEDAPO REPORTS CAR ON HOLE, SUPV T. FERNANDEZ WILL PASS BY LATER THIS EVENING. 3/10/06 2310 HRS INCIDENT WILL BE TAKEN OFF 72HR DEC DUE TO VEHICLE OVER STRUCURE

MANHOLE 66363 (Continued) **S107657589**

Remarks:	UNABLE TO LOCATE OWNER NO ACCESS. G DONATONE NO TO ALL 5 QUESTIONS. CLEAN UP PENDING ACCESS TO MANHOLE (CAR BLOCKING IT). CON ED REF #163247.

Material:

Site ID:	360842
Operable Unit ID:	1117957
Operable Unit:	01
Material ID:	2108472
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Count: 20 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	1001224066	NYCHA - PENN WORTMAN	875 PENN AVE	11207	FINDS,RCRA-NLR
BROOKLYN	1004761951	NYC DEPT PARKS & REC - LINDEN PARK	LINDEN BLVD & STANLEY AVE	11207	FINDS,RCRA-NLR
BROOKLYN	1004762588	NYCT - PARKS COUNCIL SUCCESS GARDE	LIVONIA AVE BETW WILLIAMS ST	11207	FINDS,RCRA-NLR
BROOKLYN	1005630363	CON ED - MH 67372	GLENMORE & JEROME AVE	11212	FINDS
BROOKLYN	1005630445	CON ED - MH 3741	LIBERTY AVE & MILFORD	11212	FINDS
BROOKLYN	1005630466	CON ED - V 3742	LIBERTY AVE & LOGAN	11212	FINDS
	1007206113	CONSOLIDATED EDISON CO MH03741	LIBERTY AVENUE MILFORD STREET		RCRA-NLR,MANIFEST
	1007206138	CONSOLIDATED EDISON CO	LIBERTY AND LOGAN TM3742		RCRA-NLR,MANIFEST
QUEENS	1007206226	CONSOLIDATED EDISON	#67372 - GLENMORE & JEROME ST		RCRA-NLR,MANIFEST
QUEENS	1007206743	CONSOLIDATED EDISON	V 3469 - ROCKAWAY AVE		RCRA-NLR,MANIFEST
BROOKLYN	1007207666	CONSOLIDATED EDISON	MH5196-SNEDIKER AVE & PITKIN	11207	RCRA-NLR,MANIFEST
BROOKLYN	1007208397	CONSOLIDATED EDISON	MH38210-KINGS HWY & W 7TH ST		RCRA-NLR,MANIFEST
BROOKLYN	S102142527	E 29TH ST & KINGS HWY	E 29TH ST & KINGS HWY		SPILLS,HIST SPILLS
BROOKLYN	S103938400	BOX 38486	KINGS HIGHWAY/ROCKAWAY PK		SPILLS,HIST SPILLS
BROOKLYN	S106737045	BETW/AVE X &	KINGS HIGHWAY AVE U		SPILLS
BROOKLYN	S107407580	KINGS HIGHWAY MOBIL	KINGS HIGHWAY		SPILLS
BROOKLYN	S109064521	BELL ATLANTIC-NY	E 94 ST/BET CLARKSON AVE KINGS		MANIFEST
	S109207895	205842; KINGS HWY	KINGS HWY		SPILLS
BROOKLYN	S111011715	ROADWAY	KINGS HIGHWAY AND OCEAN PARKWA		SPILLS
BROOKLYN	S111011885	TO ROADWAY	KINGS HWY AND EAST 16TH ST		SPILLS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/31/2011
Date Data Arrived at EDR: 04/13/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPAa??s Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/10/2010
Date Data Arrived at EDR: 01/11/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/09/2011
Date Data Arrived at EDR: 03/15/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 91

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/16/2011
Date Data Arrived at EDR: 03/25/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/16/2011
Date Data Arrived at EDR: 03/25/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 04/05/2011
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 70

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 11/24/2010
Date Made Active in Reports: 12/17/2010
Number of Days to Update: 23

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/26/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/01/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 03/03/2011
Date Data Arrived at EDR: 03/18/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 45

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/31/2011
Date Data Arrived at EDR: 02/01/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 48

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/17/2011
Date Data Arrived at EDR: 05/19/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 26
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 05/20/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 25
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 11/04/2009
Date Data Arrived at EDR: 05/04/2010
Date Made Active in Reports: 07/07/2010
Number of Days to Update: 64
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/16/2011
Date Data Arrived at EDR: 05/17/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 28
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 31
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS UST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage
Registered Aboveground Storage Tanks.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 31

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database
Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing
These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing
These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 01/01/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 68

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 03/03/2011
Date Data Arrived at EDR: 03/18/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 45

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 05/18/2011
Date Data Arrived at EDR: 05/26/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 19

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/16/2011
Date Data Arrived at EDR: 05/17/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 28

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/01/2011
Date Data Arrived at EDR: 06/01/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 13

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/17/2011
Date Data Arrived at EDR: 05/19/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 26

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 05/04/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 41

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/02/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 12/23/2010
Date Made Active in Reports: 02/11/2011
Number of Days to Update: 50

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/29/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 70

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 09/05/2011
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 07/12/2011
Date Data Arrived at EDR: 07/13/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 03/29/2011
Date Data Arrived at EDR: 03/29/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 07/29/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/02/2011
Date Data Arrived at EDR: 03/17/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 46
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/07/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites
A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/24/2011
Date Data Arrived at EDR: 05/25/2011
Date Made Active in Reports: 07/05/2011
Number of Days to Update: 41
Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 02/04/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 87

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/12/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 09/05/2011
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 01/05/2011
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 51

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 07/05/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 07/05/2011
Date Data Arrived at EDR: 07/05/2011
Date Made Active in Reports: 08/01/2011
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/25/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/07/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/12/2011
Date Data Arrived at EDR: 02/11/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 08/09/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 08/12/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 112

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 06/14/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 04/05/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 70

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/16/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 5

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/15/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/21/2010
Date Made Active in Reports: 01/28/2011
Number of Days to Update: 99

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/08/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 09/08/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/17/2010
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 94

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/30/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 08/18/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/07/2011
Date Data Arrived at EDR: 01/21/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 59
Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 06/27/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2010
Date Data Arrived at EDR: 11/10/2010
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 98

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/18/2010
Date Data Arrived at EDR: 04/06/2010
Date Made Active in Reports: 05/27/2010
Number of Days to Update: 51

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/11/2011
Date Data Arrived at EDR: 01/13/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/12/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/14/2010
Date Data Arrived at EDR: 04/16/2010
Date Made Active in Reports: 05/27/2010
Number of Days to Update: 41

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 06/14/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/01/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/13/2011
Date Data Arrived at EDR: 06/15/2011
Date Made Active in Reports: 07/18/2011
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 06/15/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 05/12/2011
Date Made Active in Reports: 05/24/2011
Number of Days to Update: 12

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 08/09/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 06/28/2011
Date Data Arrived at EDR: 06/29/2011
Date Made Active in Reports: 07/05/2011
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/20/2011
Next Scheduled EDR Contact: 10/03/2011
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/19/2011
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 11/02/2010
Date Made Active in Reports: 12/17/2010
Number of Days to Update: 45

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 05/02/2011
Next Scheduled EDR Contact: 08/15/2011
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 06/14/2011
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 20

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/30/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Varies

FINANCIAL ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/31/2008
Date Data Arrived at EDR: 11/25/2008
Date Made Active in Reports: 12/11/2008
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/14/2011
Next Scheduled EDR Contact: 09/26/2011
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 01/01/2008
Date Data Arrived at EDR: 02/18/2009
Date Made Active in Reports: 05/29/2009
Number of Days to Update: 100

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/05/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: Varies

FINANCIAL ASSURANCE 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/10/2011
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Quarterly

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 07/11/2011
Date Data Arrived at EDR: 07/11/2011
Date Made Active in Reports: 08/09/2011
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands
Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: N/A

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 36

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 08/05/2011
Number of Days to Update: 36

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/11/2011
Next Scheduled EDR Contact: 10/24/2011
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 06/17/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 19

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 06/17/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 19

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 05/25/2011
Date Data Arrived at EDR: 05/27/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 05/25/2011
Date Data Arrived at EDR: 05/27/2011
Date Made Active in Reports: 07/06/2011
Number of Days to Update: 40

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/11/2009
Number of Days to Update: 16

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/26/2011
Next Scheduled EDR Contact: 12/05/2011
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 07/20/2011
Date Made Active in Reports: 08/11/2011
Number of Days to Update: 22

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/20/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/15/2011
Next Scheduled EDR Contact: 10/10/2011
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/24/2011
Date Made Active in Reports: 06/30/2011
Number of Days to Update: 6

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/31/2011
Next Scheduled EDR Contact: 12/12/2011
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 05/13/2011
Date Data Arrived at EDR: 05/20/2011
Date Made Active in Reports: 07/08/2011
Number of Days to Update: 49

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/25/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 07/06/2010
Date Made Active in Reports: 07/26/2010
Number of Days to Update: 20

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 10/03/2011
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

EAST NEW YORK - CROSS HARBOR PORTFOLIO
VAN SINDEREN AVE. / SUTTER AVE.
BROOKLYN, NY 11212

TARGET PROPERTY COORDINATES

Latitude (North):	40.66790 - 40° 40' 4.4''
Longitude (West):	73.9021 - 73° 54' 7.6''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	592800.3
UTM Y (Meters):	4502260.0
Elevation:	39 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40073-F8 BROOKLYN, NY
Most Recent Revision:	1995

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 39 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
KINGS, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 360497 - FEMA DFIRM Flood data

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	0.189
Federal FRDS PWS	Nearest PWS within 0.189 miles
State Database	0.189

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found


Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 3164130.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	East New York - Cross Harbor Portfolio	CLIENT:	STV Inc.
ADDRESS:	Van Sinderen Ave. / Sutter Ave. Brooklyn NY 11212	CONTACT:	Doane E. Cafferty
LAT/LONG:	40.6679 / 73.9021	INQUIRY #:	3164130.2s
		DATE:	September 12, 2011 2:28 pm

Copyright © 2011 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

East New York - Cross Harbor Portfolio
Van Sinderen Ave. / Sutter Ave.
Brooklyn, NY 11212

Inquiry Number: 3164130.3
September 16, 2011

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

9/16/11

Site Name:
East New York - Cross Harbor
Van Sinderen Ave. / Sutter Ave.
Brooklyn, NY 11212

Client Name:
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3164130.3

Contact: Doane E. Cafferty

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by STV Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, State, Zip: Brooklyn, NY 11212
Cross Street:
P.O. # 4014403
Project: Cross Harbor - East New York
Certification # E75A-41DD-9B5A

Maps Provided:

2007	2001	1989	1981	1965	1908
2006	1996	1988	1980	1963	1907
2005	1995	1987	1979	1951	1887
2004	1994	1986	1978	1950	
2003	1992	1983	1977	1932	
2002	1991	1982	1966	1928	

Sanborn® Library search results
Certification # E75A-41DD-9B5A

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets


Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11



Volume 7, Sheet 12



Volume 7, Sheet 32

2006 Source Sheets


Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11



Volume 7, Sheet 12



Volume 7, Sheet 32

2005 Source Sheets


Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11



Volume 7, Sheet 12



Volume 7, Sheet 32

2004 Source Sheets


Volume 16, Sheet 7



Volume 16, Sheet 8


Volume 7, Sheet 11



Volume 7, Sheet 12


Volume 7, Sheet 32


2003 Source Sheets




Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32


2002 Source Sheets




Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32


2001 Source Sheets




Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11



Volume 7, Sheet 12



Volume 7, Sheet 32

1996 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1995 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12



Volume 7, Sheet 32



Volume 16, Sheet 7




Volume 16, Sheet 8

1994 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8



Volume 7, Sheet 32




Volume 7, Sheet 11




Volume 7, Sheet 12

1992 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12



Volume 7, Sheet 32




Volume 16, Sheet 7




Volume 16, Sheet 8

1991 Source Sheets




Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 32




Volume 7, Sheet 11




Volume 7, Sheet 12

1989 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12



Volume 7, Sheet 32




Volume 16, Sheet 7




Volume 16, Sheet 8

1988 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1987 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12



Volume 7, Sheet 32




Volume 16, Sheet 7




Volume 16, Sheet 8

1986 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1983 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1982 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1981 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1980 Source Sheets



Volume 7, Sheet 11



Volume 7, Sheet 12



Volume 7, Sheet 32


1979 Source Sheets




Volume 16, Sheet 7



Volume 16, Sheet 8



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1978 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1977 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1966 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1965 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1963 Source Sheets



Volume 7, Sheet 11




Volume 7, Sheet 12




Volume 7, Sheet 32

1951 Source Sheets



Volume 7, Sheet 11



Volume 7, Sheet 12




Volume 7, Sheet 32

1950 Source Sheets




Volume 16, Sheet 7




Volume 16, Sheet 8

1932 Source Sheets



Volume 7, Sheet 11



Volume 7, Sheet 12




Volume 7, Sheet 32

1928 Source Sheets



Volume 16, Sheet 7




Volume 16, Sheet 8

1908 Source Sheets



Volume 7, Sheet 42



Volume 8, Sheet 7



Volume 7, Sheet 20



Volume 7, Sheet 21

1907 Source Sheets



Volume 16, Sheet 2

1887 Source Sheets



Volume 8, Sheet 195



Volume 8, Sheet 196




Volume 8, Sheet 198



Volume 8, Sheet 199

2007 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2006 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2005 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2004 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2003 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2002 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

2001 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1996 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1995 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32
Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1994 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 32
Volume 7, Sheet 11
Volume 7, Sheet 12

0 Feet 165 330 660

N

1992 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32
Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1991 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 32
Volume 7, Sheet 11
Volume 7, Sheet 12

1989 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32
Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1988 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1987 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32
Volume 16, Sheet 7
Volume 16, Sheet 8

N

1986 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 7
Volume 16, Sheet 8

N

1983 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1983

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 7
Volume 16, Sheet 8

N

1982 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1981 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1981

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1980 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1979 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8
Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1978 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1977 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1966 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification #: E75A-41DD-9B5A
Copyright: 1966

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1965 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1963 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1963

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1951 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1950 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 7
Volume 16, Sheet 8

0 Feet 165 330 660

N

1932 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1932

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 11
Volume 7, Sheet 12
Volume 7, Sheet 32

0 Feet 165 330 660

N

1928 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 7
Volume 16, Sheet 8

N

1908 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 42
Volume 8, Sheet 7
Volume 7, Sheet 20
Volume 7, Sheet 21

0 Feet 165 330 660

N

1907 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1907

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 2

N

1887 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E75A-41DD-9B5A

Site Name:	East New York - Cross Harbor Portfolio
Address:	Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP:	Brooklyn NY 11212
Client:	STV Inc.
EDR Inquiry:	3164130.3
Order Date:	9/16/2011 1:52:04 PM
Certification #	E75A-41DD-9B5A
Copyright:	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 8, Sheet 195
Volume 8, Sheet 196
Volume 8, Sheet 198
Volume 8, Sheet 199

N

East New York - Cross Harbor Portfolio
Van Sinderen Ave. / Sutter Ave.
Brooklyn, NY 11212

Inquiry Number: 3164130.3
September 16, 2011

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

9/16/11

Site Name:
East New York - Cross Harbor
Van Sinderen Ave. / Sutter Ave.
Brooklyn, NY 11212

Client Name:
STV Inc.
225 Park Ave S
New York, NY 10003

EDR Inquiry # 3164130.3

Contact: Doane E. Cafferty

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by STV Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, State, Zip: Brooklyn, NY 11212
Cross Street:
P.O. # 4014403
Project: Cross Harbor - East New York
Certification # E75A-41DD-9B5A

Maps Provided:

2007	2001	1989	1979	1888
2006	1996	1988	1977	1887
2005	1995	1987	1966	
2004	1994	1986	1950	
2003	1992	1983	1928	
2002	1991	1981	1908	

Sanborn® Library search results
Certification # E75A-41DD-9B5A

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

STV Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9



Volume 16, Sheet 15


Volume 16, Sheet 16

2006 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9



Volume 16, Sheet 15


Volume 16, Sheet 16

2005 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9



Volume 16, Sheet 15


Volume 16, Sheet 16

2004 Source Sheets



Volume 16, Sheet 8


Volume 16, Sheet 9



Volume 16, Sheet 15


Volume 16, Sheet 16


2003 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


2002 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


2001 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16


1996 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16


1995 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16


1994 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1992 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1991 Source Sheets




Volume 16, Sheet 16



Volume 16, Sheet 8




Volume 16, Sheet 9



Volume 16, Sheet 15


1989 Source Sheets




Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16

1988 Source Sheets


1987 Source Sheets




Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1986 Source Sheets




Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1983 Source Sheets




Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16


1981 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1979 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1977 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1966 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15




Volume 16, Sheet 16


1950 Source Sheets



Volume 16, Sheet 8



Volume 16, Sheet 9




Volume 16, Sheet 15



Volume 16, Sheet 16


1928 Source Sheets



Volume 16, Sheet 15



Volume 16, Sheet 16




Volume 16, Sheet 8




Volume 16, Sheet 9


1908 Source Sheets



Volume 8, Sheet 7



Volume 8, Sheet 8



Volume 8, Sheet 39



Volume 8, Sheet 40

1888 Source Sheets



Volume 7, Sheet 175

1887 Source Sheets



Volume 8, Sheet 198




Volume 8, Sheet 199

2007 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

2006 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

0 Feet 165 330 660

N


2005 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N


2004 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N

2003 Certified Sanborn Map

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification #: E75A-41DD-9B5A
Copyright: 2003


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

E75A-41DD-9B5A Certification #

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16


N

2002 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

2001 Certified Sanborn Map

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 2001

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


E75A-41DD-9B5A

Certification #

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N


1996 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16


N

1995 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16


N

1994 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

1992 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

0 Feet 165 330 660


N

1991 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 16
Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15

0 Feet 165 330 660

N


1989 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N

1988 Certified Sanborn Map


Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification # E75A-41DD-9B5A
Copyright: 1988

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



N


1987 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N


1986 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N


1983 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

N


1981 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16


N

1979 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

0 Feet 165 330 660


N

1977 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

0 Feet 165 330 660

N


1966 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16


N

1950 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 16, Sheet 15
Volume 16, Sheet 16

0 Feet 165 330 660


N

1928 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 15
Volume 16, Sheet 16
Volume 16, Sheet 8
Volume 16, Sheet 9


N

1908 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 8, Sheet 7
Volume 8, Sheet 8
Volume 8, Sheet 39
Volume 8, Sheet 40

0 Feet 165 330 660


N

1888 Certified Sanborn Map




This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 175





1887 Certified Sanborn Map

Site Name: East New York - Cross Harbor Portfolio
Address: Van Sinderen Ave. / Sutter Ave.
City, ST, ZIP: Brooklyn NY 11212
Client: STV Inc.
EDR Inquiry: 3164130.3
Order Date: 9/16/2011 1:52:04 PM
Certification #: E75A-41DD-9B5A
Copyright: 1887


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # E75A-41DD-9B5A

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 8, Sheet 198
Volume 8, Sheet 199

N