

# PAT 024.028A - HARRISON STATION REPLACEMENT AND UPGRADE



PROGRESS PHOTOS  
DATE: 5/16/2016

Photo: Northeast Roof Gravity Ventilators

Northeast Head House CMU Installation for Retail Space Room 102 and Entrance for Corridor NE 107



Contractor installing concrete curb for curtain wall and door entrance to Platform Area



Installation of Electrical and Communication Junction boxes located Underneath Westbound Platform.




Installation of Northeast Head House CMU exterior wall .  
Wall to be covered with a precast stone wall



Lane Closure on Frank E Roger Blvd. for Storm Drain installation.  
Lane return at the end of each shift. Sidewalk remains close during construction



Photo of Southeast Storm Drain excavation. Contractor To remove old existing water main pipes and values in order Install new line on Frank E Rogers Blvd.



# Installation of Fire Proofing on Steel Members



WO#16 – Demolition of Existing Ben Harjay Buildings. Completed installation of RCA material for backfill after removal of concrete slabs



## UPCOMING WORK

- Install Roof Membrane
- Installation of Southeast Irrigation Tank
- Complete installation of Concrete Masonry Units (CMU)
- Sealing and Painting of CMU Walls
- Installation of cast stone wall.
- Installation of Electrical Equipment
- Repair of existing viaduct steel.

